

Stand	Price list B-Class
21/3/2019	CJ 19/1 MY 800 SR 29. April 2019 Package 1 + 2
V3	CJ 19/1 MY 800 SR 29. April 2019 Package 3

● available at extra charge    ○ available at no extra charge    U annotations existing  
S standard equipment    - not available

● available at extra charge   ○ available at no extra charge   ○ annotations existing  
S standard equipment   - not available

[illegible]





Code	Designation	Q	Q	Q	Q	Q	Q	Q	Q	Q	Q	Q	LLP
	i.V.m. Code P55	-	-	-	●	-	-	-	●	●	●	●	840,00
	i.V.m. Code P59	○	○	○	○	○	○	○	○	○	○	○	0,00
	i.V.m. Code PYF	●	●	●	●	●	●	●	●	●	●	●	840,00
05B	Owner's Manual and Service Booklet - English	○	○	○	○	○	○	○	○	○	○	○	0,00
05Z	Power supply of taxi functions for 4 h 1_only in conjunction with Code 965 2_not in conjunction with Code 06Z 3_not valid, only for Code 017	U	○	○	U	U	U	U	U	U	U	U	0,00
		★			★	★	★	★	★	★	★	★	
06B	Owner's Manual and Service Booklet - Italian	○	○	○	○	○	○	○	○	○	○	○	0,00
06Z	Power supply of taxi functions, unrestricted 1_only in conjunction with Code 965 2_not in conjunction with Code 05Z 3_not valid, only for Code 017	U	○	○	U	U	U	U	U	U	U	U	0,00
		★			★	★	★	★	★	★	★	★	
07B	Owner's Manual and Service Booklet - French	○	○	○	○	○	○	○	○	○	○	○	0,00
08B	Owner's Manual and Service Booklet - Spanish	○	○	○	○	○	○	○	○	○	○	○	0,00
08U	Preinstallation for Vehicle Setup 1_only in conjunction with Code 09U, 362 2_only in conjunction with PBI or certain in countries i.V.m. Code PBI	●	●	●	●	●	●	●	●	●	●	●	52,50
		○	○	○	○	○	○	○	○	○	○	○	0,00
09B	Owner's Manual and Service Booklet - Portuguese	○	○	○	○	○	○	○	○	○	○	○	0,00
09U	Preinstallation for Vehicle Monitoring 1_only in conjunction with Code 08U, 362 2_only in conjunction with PBI or certain in countries i.V.m. Code PBI	●	●	●	●	●	●	●	●	●	●	●	52,50
		○	○	○	○	○	○	○	○	○	○	○	0,00
10B	Owner's Manual and Service Booklet - Swedish	○	○	○	○	○	○	○	○	○	○	○	0,00
11B	Owner's Manual and Service Booklet - Arabic	○	○	○	○	○	○	○	○	○	○	○	0,00
12B	Owner's Manual and Service Booklet - Engl. USA/CAN	○	○	○	○	○	○	○	○	○	○	○	0,00
12U	Preinstallation for Concierge Service 1_for certain countries only	○	○	○	○	○	○	○	○	○	○	○	0,00
13B	Owner's Manual and Service Booklet - Norwegian	○	○	○	○	○	○	○	○	○	○	○	0,00
14B	Owner's Manual and Service Booklet - Greek	○	○	○	○	○	○	○	○	○	○	○	0,00
14U	Smartphone integration 1_only in conjunction with Code 16U, 17U 2_for certain countries only i.V.m. Code PBI	●	●	●	●	●	●	●	●	●	●	●	315,00
		○	○	○	○	○	○	○	○	○	○	○	0,00
15B	Owner's Manual and Service Booklet - Turkish	○	○	○	○	○	○	○	○	○	○	○	0,00
15U	Preinstallation for Mercedes-Benz Link	S	S	S	S	S	S	S	S	S	S	S	0,00
16B	Owner's Manual and Service Booklet - Polish	○	○	○	○	○	○	○	○	○	○	○	0,00
16U	Apple CarPlay 1_only in conjunction with Code 14U	○	○	○	○	○	○	○	○	○	○	○	0,00
17B	Owner's Manual and Service Booklet - Czech	○	○	○	○	○	○	○	○	○	○	○	0,00
17U	Android Auto 1_only in conjunction with Code 14U	○	○	○	○	○	○	○	○	○	○	○	0,00
18B	Owner's Manual and Service Booklet - Engl. S. Am.	○	○	○	○	○	○	○	○	○	○	○	0,00
18U	Baidu Carlife 1_only in conjunction with Code 14U 2_for certain countries only	-	-	-	-	○	○	○	○	-	-	○	0,00
19B	Owner's Manual and Service Booklet - French S. Am.	○	○	○	○	○	○	○	○	○	○	○	0,00
20B	Owner's Manual and Service Booklet - Spanish S. Am.	○	○	○	○	○	○	○	○	○	○	○	0,00
20U	Pre-installation for car sharing 1_only in conjunction with Code 362 2_for certain countries only i.V.m. Code PYA	●	●	●	●	●	●	●	●	●	●	●	52,50
		○	○	○	○	○	○	○	○	○	○	○	0,00
213	Direct-Steer system 1_only in conjunction with Code 459, 486 or 677	○	○	○	○	○	○	○	○	○	○	○	0,00
218	Reversing camera 2_not in conjunction with Code 501 i.V.m. Code P44	●	●	●									

Stand	Price list B-Class
21/3/2019	CJ 19/1 MY 800 SR 29. April 2019 Package 1 + 2
V3	CJ 19/1 MY 800 SR 29. April 2019 Package 3

[illegible]



[illegible]

Stand	Price list B-Class
21/3/2019	CJ 19/1 MY 800 SR 29. April 2019 Package 1 + 2
V3	CJ 19/1 MY 800 SR 29. April 2019 Package 3

● available at extra charge   ○ available at no extra charge   ◐ annotations existing  
S standard equipment   - not available

[illegible]

<b>Code</b>	<b>Description</b>	NL	LUX	BEL	FRA	GER	GRC	HUN	CZE	POL	SLOVAKIA	ITA	ESP.	PTG	LLP
<b>513</b>	Traffic Sign Assist 1_only in conjunction with Code 365 2_not in conjunction with Code 504 3_for certain countries only	*	*	*	*	*	*	*	*	*	*	*	*	*	<b>309,75</b>
<b>517</b>	HD digital radio standard 1_for certain countries only	-	-	O	O	O	O	O	O	O	O	O	O	O	<b>0,00</b>
<b>518</b>	Media Interface Cable kit 1_for certain countries only	*	*	*	*	*	*	*	*	*	*	*	*	*	<b>52,50</b>
<b>51B</b>	Rating, country group EURO-NCAP 1_only in conjunction with Code 258 or 239, 243 or 233, 504 or 513 2_for certrain countries only	O	O	O	O	O	O	O	O	O	O	O	O	O	<b>0,00</b>
<b>51U</b>	Roof liner in black fabric	O	O	O	O	O	O	O	O	O	O	O	O	O	<b>0,00</b>
<b>524</b>	Transport protection (full body cover) 1_only in conjunction with Code 662U 2_for certain countries only 3_not in conjunction with Code 820, 14P, 15P, 16P	*	*	*	*	*	*	*	*	*	*	*	*	*	<b>168,00</b>
<b>537</b>	Digital radio 1_only in conjunction with Code 79B 2_for certain countries only	*	*	*	*	*	*	*	*	*	*	*	*	*	<b>210,00</b>
<b>539</b>	Digital radio standard 1_for certain countries only	*	*	*	*	*	*	*	*	*	*	*	*	*	<b>210,00</b>
<b>543</b>	Sun visor with illuminated vanity mirror	S	S	S	S	S	S	S	S	S	S	S	S	S	<b>0,00</b>
<b>545</b>	MBUX multimedia system 1_not in conjunction with Code 355, 859, 77B, PBF, PBP, PBR, 21U, U19  2_for certain countries only	S	S	S	S	S	S	S	S	S	S	S	S	S	<b>0,00</b>
<b>546</b>	Active Speed Limit Assist 1_only in conjunction with Code 233 and 513 2_for certain countries only	O	O	O	O	O	O	O	O	O	O	O	O	O	<b>0,00</b>
<b>547</b>	MBUX multimedia system 1_only in conjunction with Code 859 2_not in conjunction with Code 355, 21U, U19, PBP, PBR 3_for certain countries only	O	O	O	O	O	O	O	O	O	O	O	O	O	<b>0,00</b>
<b>548</b>	MBUX multimedia system 1_only in conjunction with Code 355 or 2U0 2_not in conjunction with Code 859, 21U, U19, PBP, PBR 3_for certain countries only	O	O	O	O	O	O	O	O	O	O	O	O	O	<b>0,00</b>
<b>549</b>	MBUX multimedia system 1_only in conjunction with Code 21U, U19, 862, 865, PBP or PBR 2_for certain countries only	O	O	O	O	O	O	O	O	O	O	O	O	O	<b>0,00</b>
<b>550</b>	Trailer coupling with ESP® trailer stabilisation 1_not in conjunction with Code Z97 2_for certain countries only	*	*	*	*	*	*	*	*	*	*	*	*	*	<b>840,00</b>
<b>551</b>	Anti-theft alarm system (ATA) 1_scope of delivery of Code P54 in certain countries 2_for certain countries only i.V.m. Code P54	* O	* O	* O	* O	* O	* O	* O	* O	* O	* O	* O	* O	* O	<b>262,50</b> <b>0,00</b>
<b>552</b>	Anti-theft alarm system (ATA) 2_for certain countries only 2_only in conjunction with Code P54	O	O	O	O	O	O	O	O	O	O	O	O	O	<b>0,00</b>
<b>554</b>	pre-installation for trailer coupling 1_not in conjunction with Code Z97	*	*	*	*	*	*	*	*	*	*	*	*	*	<b>168,00</b>
<b>567</b>	Rear seats with fore/aft adjustment 1_only in conjunction with Code 7U2 oder 7U4 2_not in conjunction with Code 287	*	*	*	*	*	*	*	*	*	*	*	*	*	<b>351,75</b>
<b>580</b>	THERMATIC automatic climate control 1_not in conjunction with Code PBR	O	O	O	O	O	O	O	O	O	O	O	O	O	<b>0,00</b>
<b>581</b>	THERMOTRONIC automatic climate control i.V.m. Code PBR	* O	* O	* O	* O	* O	* O	* O	* O	* O	* O	* O	* O	* O	<b>535,50</b> <b>0,00</b>

● available at extra charge   ○ available at no extra charge   ○ annotations existing  
S standard equipment   - not available

[illegible]

<b>Stand</b>	<b>Price list B-Class</b>
<b>21/3/2019</b>	<b>CJ 19/1 MY 800 SR 29. April 2019 Package 1 + 2</b>
<b>V3</b>	<b>CJ 19/1 MY 800 SR 29. April 2019 Package 3</b>

● available at extra charge    ○ available at no extra charge    U annotations existing  
S standard equipment    - not available

# B Sportstourer

	B 160 d	B 180 d	B 200 d	B 220 d	B 160	B 180	B 200	B 220	B 220 4MATIC	B 250	B 250 4MATIC	
247.002												
247.003												
247.012												
247.014												
247.082												
247.084												
247.087												
247.044												
247.045												
247.046												
247.047												

Code	Designation											LLP
	1_only in conjunction with Code R78, 72R, RVG											
651	Winter complete wheels fitted 1_for certain countries only 2_only in conjunction with Code 3R1, 2R9, 5R4, 8R5, 8R2	○	○	○	○	○	○	○	○	○	○	0,00
652	Summer complete tyres fitted 1_for certain countries only 2_only in conjunction with Code 3R1, 2R9, 5R4, 8R5, 8R2	○	○	○	○	○	○	○	○	○	○	0,00
666	Freight packaging without tie-down hooks 1_not in conjunction with Code 820 2_for certain countries only i.V.m. Code 14P/15P/16P	●	●	●	●	●	●	●	●	●	●	26,25
668	Freight packaging with tie-down hooks 1_not in conjunction with Code 820, 550 2_for certain countries only	○	○	○	○	○	○	○	○	○	○	0,00
66R	45.7 cm (18-inch) 5-twin-spoke light-alloy wheels  1_only in conjunction with Code R1A, R01 or R03 2_not in conjunction with Code 950 3_in conjunction with Code R03 and R1A Code R66 is not possible i.V.m. Code P27	-	-	-	●	-	-	-	●	●	●	1312,50
		●	●	●	-	●	●	-	-	-	-	1627,50
		●	●	●	-	●	●	-	-	-	-	1155,00
		-	-	-	●	-	-	-	●	●	●	840,00
	i.V.m. Code P55	○	○	○	○	○	○	○	○	○	○	0,00
	i.V.m. Code P59	●	●	●	●	●	●	●	●	●	●	840,00
677	Lowered comfort suspension 1_only in conjunction with Code 213 2_for certain countries only i.V.m. Code 950	●	●	●	●	●	●	●	●	●	●	304,50
		○	○	○	○	○	○	○	○	○	○	0,00
682	Fire extinguisher 1_for certain countries only	●	●	●	●	●	●	●	●	●	●	0,00
687	Model year on model plate	○	○	○	○	○	○	○	○	○	○	0,00
690	Collapsible spare wheel 1_only in conjunction with Code B12 2_for certain countries only, for certain countries not in conjunction with Code R66	-	-	○	○	○	○	○	○	○	○	0,00
70B	Fluorescent jacket for driver 1_for certain countries only 2_not in conjunction with Code 71B	●	●	●	●	●	●	●	●	●	●	5,25
71B	Fluorescent jackets for driver and passengers 1_for certain countries only 2_not in conjunction with Code 70B	●	●	●	●	●	●	●	●	●	●	26,25
72R	43.2 cm (17-inch) 10-spoke light-alloy wheels  1_only in conjunction with Code R01 or 645 2_not in conjunction with Code 950, U29, R66 3_for certain countries only i.V.m. Code P27	-	-	-	●	-	-	-	●	●	●	472,50
		●	●	●	-	●	●	-	-	-	-	787,50
		-	-	-	○	-	-	-	○	○	○	0,00
		○	○	○	○	○	○	○	○	○	○	315,00
	i.V.m. Code P59	○	○	○	○	○	○	○	○	○	○	0,00
73B	Stowage compartment in centre console, with retractable cover i.V.m. Code 426 or 429	-	-	●	●	●	-	-	●	●	●	0,00
		●	●				●	●				0,00
	1_only in conjunction with Code 426 or 429 2_for certain countries only											
762	Radio remote control without panic button 1_for certain countries only	○	○	○	○	○	○	○	○	○	○	0,00
763	Radio remote control with panic switch 1_only in conjunction with Code 551 and certain countries only	-	-	○	○	○	○	○	○	○	○	0,00
76R	43.2 cm (17-inch) 5-twin-spoke light-alloy wheels  1_only in conjunction with Code R01	-	-	-	●	-	-	-	●	●	●	472,50
		●	●	●	-	●	●	-	-	-	-	787,50

● available at extra charge   ○ available at no extra charge   ○ annotations existing  
S standard equipment   - not available

Code	Designation	1	2	3	4	5	6	7	8	9	10	LLP
	2_not in conjunction with Code R66, U29 or 950											
	i.V.m. Code P27	-	-	-	○	-	-	-	○	○	○	0,00
	i.V.m. Code P59	●	●	●	-	●	●	-	-	-	-	315,00
	i.V.m. Code PYD	○	○	○	○	○	○	○	○	○	○	0,00
772	AMG bodystyling	○	○	○	○	○	○	○	○	○	○	0,00
	1_only in conjunction with Code 950											
77B	MBUX Interior Assistant	●	●	●	●	●	●	●	●	●	●	315,00
	1_only in conjunction with Code 426 or 429 and 859 and U62											
	2_not in conjunction with Code 336, 337											
	i.V.m. Code PAU	○	○	○	○	○	○	○	○	○	○	0,00
79B	Preinstallation for digital radio	○	○	○	○	○	○	○	○	○	○	0,00
	1_in certain countries only in conjunction with Code 362											
	2_in certain countries only in conjunction with Code 537											
	3_in conjunction with Code 835 with Code 355, 859, 362											
7U1	Manually adjustable front seats	○	○	○	○	○	○	○	○	○	○	0,00
	1_only in conjunction with Code 301A											
	2_not in conjunction with Code 7U2, 7U4											
7U2	Luxury seats	○	○	○	○	○	○	○	○	○	○	0,00
	1_only in conjunction with Code 101A, 105A, 201A, 205A, 311A, 321A, 371A, 372A or 381A and U59 and 286											
	2_not in conjunction with Code 7U1, 7U4											
7U4	Sports seats	●	●	●	●	●	●	●	●	●	●	246,75
	1_only in conjunction with Code 159A, 211A, 257A, 258A or 651A and Code U59 and 286											
	2_not in conjunction with Code 7U1, 7U2											
	i.V.m. Code 950	○	○	○	○	○	○	○	○	○	○	0,00
800	Technical modifications	○	○	○	○	○	○	○	○	○	○	0,00
810	Burmester® surround sound system	●	●	●	●	●	●	●	●	●	●	698,25
	1_only in conjunction with Code 355 or 859											
	2_not in conjunction with Code 965, Z97											
	3_for certain countries only											
	i.V.m. Code PBP/PBR	●	●	●	●	●	●	●	●	●	●	435,75
	i.V.m. Code PYN/PYO	●	●	●	●	●	●	●	●	●	●	435,75
820	Tourist vehicle	○	○	○	○	○	○	○	○	○	○	0,00
	1_not in conjunction with Code 634 or 636											
	2_for certain countries only											
821	Country code Brazil	-	-	-	-	○	○	○	-	-	-	0,00
822	South Africa specification	○	○	○	○	○	○	○	○	○	○	0,00
823	country code Switzerland	○	○	○	○	○	○	○	○	○	○	0,00
824	Additional parts for cold countries (engine air intake screen)	○	○	○	○	○	○	○	○	○	○	0,00
	2_for certain countries only											
829	Taiwan version	○	○	○	○	○	○	○	○	○	○	0,00
830	China specification	-	-	-	-	○	○	○	-	○	-	0,00
831	country code Italia	○	○	○	○	○	○	○	○	○	○	0,00
835	South Korea specification	-	-	-	-	-	-	○	-	-	-	0,00
837	Taxi rubber floor mat	○	●	●	○	○	○	○	○	○	○	189,00
	1_only in conjunction with Code 965											
	2_not in conjunction with Code U40											
	3_not valid, only for Code 017	★			★	★	★	★	★	★	★	
	i.V.m. Code 450	○	○	○	○	○	○	○	○	○	○	0,00
840	Heat-insulating dark-tinted glass	●	●	●	●	●						

● available at extra charge   ○ available at no extra charge   ○ annotations existing  
S standard equipment   - not available

Stand	Price list B-Class
21/3/2019	CJ 19/1 MY 800 SR 29. April 2019 Package 1 + 2
V3	CJ 19/1 MY 800 SR 29. April 2019 Package 3

● available at extra charge    ○ available at no extra charge    U annotations existing  
S standard equipment    - not available

[illegible]

<b>Stand</b>	<b>Price list B-Class</b>
<b>21/3/2019</b>	<b>CJ 19/1 MY 800 SR 29. April 2019 Package 1 + 2</b>
<b>V3</b>	<b>CJ 19/1 MY 800 SR 29. April 2019 Package 3</b>

● available at extra charge    ○ available at no extra charge    U annotations existing  
S standard equipment    - not available

B Sportstourer									
247.002	B 160 d	247.003	B 180 d	247.012	B 200 d	247.014	B 220 d	247.082	B 160
247.084	B 180	247.087	B 200	247.044	B 220	247.045	B 220 4MATIC	247.046	B 250
247.047	B 250 4MATIC								

Code	Designation											LLP
	1_for certain countries only											
B12	<b>Tyre-change toolkit</b> 1_only in conjunction with Code 669, 690 or 623 2_for certain countries only	●	●	●	●	●	●	●	●	●	●	31,50
B18	<b>Spectacles compartment for driver</b> 1_not in conjunction with Code 77B, 336	S	S	S	S	S	S	S	S	S	S	0,00
B24	<b>Remote control for auxiliary heater</b> 1_only in conjunction with Code 228 and 362 (only for certain countries) 2_for certain countries only	●	●	●	●	●	●	●	●	●	●	210,00
B51	<b>TIREFIT</b> 1_for certain countries only 2_not in conjunction with Code R66 (for certain countries only) <b>i.V.m. Code PYA</b>	●	●	●	●	●	●	●	●	●	●	52,50
B59	<b>DYNAMIC SELECT</b>	○	○	○	○	○	○	○	○	○	○	0,00
B63	<b>Sporty engine sound</b> 1_only in conjunction with Code 950 and 355 or 859	-	-	○	○	-	-	○	○	○	○	0,00
H15	<b>wood linden black open-pored trim</b> 1_only in conjunction with Code P50 or 950	●	●	●	●	●	●	●	●	●	●	273,00
H23	<b>Brown open-pore walnut wood trim</b> 1_only in conjunction with Code P34 or P59	●	●	●	●	●	●	●	●	●	●	273,00
H44	<b>Light longitudinal-grain aluminium trim</b> 1_only in conjunction with Code P59 or 950	●	●	●	●	●	●	●	●	●	●	157,50
H59	<b>Carbon-fibre-look trim</b> 1_not in conjunction with Code P27, P59, 950, 877	S	S	S	S	S	S	S	S	S	S	0,00
H60	<b>Spiral-look trim elements</b> 1_only in conjunction with Code P59	○	○	○	○	○	○	○	○	○	○	0,00
H61	<b>Ellipse-look trim</b> 1_only in conjunction with Code P27 <b>2_not in conjunction with Code 877</b>	○	○	○	○	○	○	○	○	○	○	0,00
H62	<b>Carbon-structure trim</b> 1_only in conjunction with Code 950	○	○	○	○	○	○	○	○	○	○	0,00
K32	<b>Active Lane Change Assist</b> 1_only in conjunction with Code 266 and 365 2_for certain countries only	○	○	○	○	○	○	○	○	○	○	0,00
K33	<b>Extended automatic Re-start in traffic jams</b> 1_only in conjunction with Code 233, 235 and 365 2_for certain countries only	○	○	○	○	○	○	○	○	○	○	0,00
K34	<b>Route-based speed adaptation</b> 1_only in conjunction with Code 233 and 365 2_for certain countries only	○	○	○	○	○	○	○	○	○	○	0,00
L3A	<b>Multifunction sports steering wheel</b> 1_only in conjunction with Code 426 or 429 and 428 or 411 2_not in conjunction with Code P27, P59, 950, 233, 239, 443	○	○	○	○	○	○	○	○	○	○	0,00
L3B	<b>Multifunction sports steering wheel in nappa leather</b> 1_only in conjunction with Code 443 and 426 or 429 and 428 2_not in conjunction with Code 950	○	○	○	○	○	○	○	○	○	○	0,00
L3E	<b>Multifunction sports steering wheel in leather</b> 1_only in conjunction with Code 426 or 429 and 428 or 411 2_not in conjunction with Code 443 or 950 <b>i.V.m. Code P27/P59</b>	●	●	●	●	●	●	●	●	●	●	183,75
L5C	<b>Multifunction sports steering wheel in nappa leather</b> 1_only in conjunction with Code 950, 426 or 429 and 431 or 411 2_not in conjunction with Code 443	○	○	○	○	○	○	○	○	○	○	0,00
L5I	<b>Multifunction sports steering wheel in nappa leather / DINAMICA microfibre</b> 1_only in conjunction with Code 950 and 426 or 429 and 431 2_not in conjunction with Code 443	●	●	●	●	●	●	●	●	●	●	241,50
R00	<b>40.6 cm (16-inch) steel wheels with 10-hole trim</b> 1_only in conjunction with Code R01 or R05	S	S	S	-	S	S	-	-	-	-	0,00

[illegible]

● available at extra charge   ○ available at no extra charge   ◐ annotations existing  
S standard equipment   - not available

● available at extra charge   ○ available at no extra charge   ◐ annotations existing  
S standard equipment   - not available

[illegible]