

| | |
|---------------------|--|
| Model year : | 801+051 |
| Sales Release : | 2020-10-06 |
| Production Change : | 2020-12-01 |
| Legend | (*) Available at extra cost (C) available without additional charge (S) standard equipment (-) not available (L) Limited |

| | | | A-Class | A-Class | | | | | | | | | | | | | | | | | | | | | | |
|------|---|--|-------------------|-------------------|--------------------------|-------------------|--------------------------|-----------------|-----------------|--------------------|------------------------|------------------------------------|-----------------|-------------------|--------------------------|-------------------|--------------------------|-----------------|-----------------|------------------------|-----------------|------------------------------------|-------------------------------------|---------------------------|-------------------|----------|
| | | | 17110 A 180 d (L) | 17112 A 200 d (L) | 17113 A 200 d 4MATIC (L) | 17114 A 220 d (L) | 17115 A 220 d 4MATIC (L) | 17116 A 180 (L) | 17117 A 200 (L) | 17118 A 200 4MATIC | 17119 A 250 4MATIC (L) | 17120 Mercedes-AMG A 35 4MATIC (L) | 17121 A 180 (L) | 17122 A 200 d (L) | 17123 A 200 d 4MATIC (L) | 17124 A 220 d (L) | 17125 A 220 d 4MATIC (L) | 17126 A 180 (L) | 17127 A 200 (L) | 17128 A 200 4MATIC (L) | 17129 A 250 (L) | 17130 Mercedes-AMG A 35 4MATIC (L) | 17131 Mercedes-AMG A 45 4MATIC+ (L) | 17132 Mercedes-AMG A 45 S | 17133 A 250 e (L) | LLP |
| Code | equipment | Restrictions | | | | | | | | | | | | | | | | | | | | | | | | |
| 5U6 | AMG-specific radiator grille, darkened | Available only as part of (PAZ) Only in conjunction with PAZ | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | 0,00 |
| 7U8 | Model badge on boot lid and wings in high-gloss black | Available only as part of (PAZ) Only in conjunction with PAZ | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | 0,00 |
| 900 | AMG Exterior Silver Chrome package | Not in conjunction with B26/P60 | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | 577,50 |
| B26 | AMG Aerodynamics package | Not in conjunction with 550/554 Not in conjunction with 666 Not in conjunction with 900 Only in conjunction with P60 | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | 1.627,50 |
| B26 | AMG Aerodynamics package | Not in conjunction with 550/554 Not in conjunction with 666 Not in conjunction with 900 Only in conjunction with P60 | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | 1.627,50 |
| P60 | AMG Night package | Includes codes 840 Not in conjunction with 900 | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | 787,50 |
| PAZ | AMG Night Package II | Includes codes 5U6+7U8 only in conjunction with P60 | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | 420,00 |
| U70 | red-painted brake callipers | Available only as part of (P71) Not in conjunction with 431/486/L5C Only in conjunction with P71+U88 | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | 336,00 |
| 555 | AMG Performance seats | Not in conjunction with 286/U22 Not in conjunction with 7U3 Not in conjunction with 7U4 Only in conjunction with 287+U59 only in conjunction with PBX/PBY/PBZ | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | 0,00 |
| L6G | AMG Performance steering wheel in DINAMICA microfibre | Only in conjunction with U88 | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | 882,00 |
| L6J | AMG Performance steering wheel in nappa leather | i.V.m. Code PYA i.V.m. Code P71 | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | 105,00 |
| L6K | AMG Performance steering wheel in nappa leather / DIN | i.V.m. Code P71 i.V.m. Code PYA | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | 73,50 |
| PBX | AMG Performance Seat Package | Includes codes 555+873 Not in conjunction with 242/275/286/401/409/E83/E84/PBY/PBZ/U22 Not in conjunction with 7U3 Not in conjunction with 7U4 Only in conjunction with [159A/651A]+287+U59 Only in conjunction with [671A] | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | 441,00 |
| PBY | AMG Performance Seat package Advanced | Includes codes 275+555+873 Not in conjunction with 286/401/1/PBX/PBZ/U22 Not in conjunction with 7U3 Not in conjunction with 7U4 Only in conjunction with [159A/651A]+242+287+409+U59 Only in conjunction with [671A] | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | 0,00 |
| PBZ | AMG Performance Seat package High-End | Includes codes 275+555+873 [401] Not in conjunction with 159A/286/651A/PBX/PBY/U22/Y05 Not in conjunction with 671A Not in conjunction with 7U3 Not in conjunction with 7U4 Not in conjunction with H95 Only in conjunction with 242+287+409+U59 | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | 0,00 |
| 250 | AMG Driver's package | i.V.m. Code PYN i.V.m. Code PYO | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | 3.129,00 |
| 339 | AMG Real Performance Sound | i.V.m. Code PYA | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | 2.304,75 |
| 426 | AMG SPEEDSHIFT DCT 8G | | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | 4.641,00 |
| 429 | AMG SPEEDSHIFT DCT 7G | Not in conjunction with 411 invalid | * | * | * | * | * | | | | | | | | | | | | | | | | | | | |

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

| | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
|-----|--|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|------|--------|------|
| U88 | AMG steering wheel buttons | | - | - | - | - | - | - | - | - | - | ● | - | - | - | - | - | - | - | - | - | - | ● | ● | - | - | | 367,50 | |
| | | | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | S | - | | 0,00 | |
| | | Not in conjunction with 431/L5C | - | - | - | - | - | - | - | - | - | * | - | - | - | - | - | - | - | - | - | - | - | * | * | - | | | |
| | | i.V.m. Code L6G | - | - | - | - | - | - | - | - | - | ○ | - | - | - | - | - | - | - | - | - | - | - | ○ | ○ | - | | 0,00 | |
| | | i.V.m. Code P71 | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | ○ | - | | 0,00 | | |
| | | i.V.m. Code PYA | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | ○ | - | | 0,00 | | |
| 301 | Ashtray insert for cup holder with cigarette lighter | | ● | ● | ● | ● | ● | ● | ● | ● | ● | ● | ● | ● | ● | ● | ● | ● | ● | ● | ● | ● | ● | ● | ● | ● | | 47,25 | |
| 310 | Double cup holder | | ● | ● | ● | ● | ● | ● | ● | ● | ● | - | ● | ● | ● | ● | ● | ● | ● | ● | ● | ● | - | - | - | ● | | 26,25 | |
| | | | - | - | - | - | - | - | - | - | S | - | - | - | - | - | - | - | - | - | - | - | S | S | S | - | | 0,00 | |
| | | i.V.m. Code P27/P59/950 | ○ | ○ | ○ | ○ | ○ | ○ | ○ | ○ | ○ | ○ | ○ | ○ | ○ | ○ | ○ | ○ | ○ | ○ | ○ | ○ | ○ | ○ | ○ | - | | 0,00 | |
| | | i.V.m. Code PYA | ○ | ○ | ○ | ○ | ○ | ○ | ○ | ○ | ○ | - | ○ | ○ | ○ | ○ | ○ | ○ | ○ | ○ | ○ | ○ | ○ | ○ | - | - | | 0,00 | |
| 73B | Stowage compartment in centre console with retractable | | ● | ● | ● | ● | ● | ● | ● | ● | ● | ● | ● | ● | ● | ● | ● | ● | ● | ● | ● | ● | ● | ● | ● | ● | | 36,75 | |
| | | Not in conjunction with 411 | * | * | | | * | * | | | | | * | | | | | * | * | | | | | | | | | | |
| | | Not in conjunction with U63/U64/U65/Z83 | | | | | | | | | | | * | * | | | | * | * | | | | | | | | | | |
| | | Only in conjunction with 426 | * | * | | | | | | | | | * | * | | | | | | | | | | | | | | | |
| | | Only in conjunction with 429 | | | | | * | * | | | | | | | | | | * | * | | | | | | | | | | |
| | | only in conjunction with code 426/429 | ● | ● | ● | ● | ● | ● | ● | ● | ● | ● | ● | ● | ● | ● | ● | ● | ● | ● | ● | ● | ● | ● | ● | ● | ● | | 0,00 |
| | | i.V.m. Code PYA | - | - | - | - | - | - | - | - | - | ○ | - | - | - | - | - | - | - | - | - | - | - | ○ | ○ | - | | 0,00 | |
| 842 | Folding front passenger seat | | - | - | - | - | - | - | - | - | - | - | ● | ● | ● | ● | ● | ● | ● | ● | ● | ● | - | - | - | ● | | 157,50 | |
| | | Not in conjunction with 001A/111A/115A/159A/204A/211A/257A/258A/651A | | | | | | | | | | - | ● | ● | ● | ● | ● | ● | ● | ● | ● | ● | - | - | - | ● | | | |
| | | Not in conjunction with 242/409/7U1/7U3/P37/RUG | | | | | | | | | | | * | * | * | * | * | * | * | * | * | * | * | * | * | * | | | |
| | | Not in conjunction with H47/U13/U66 | | | | | | | | | | | * | * | * | * | * | * | * | * | * | * | * | * | * | * | | | |
| | | Only in conjunction with [101A/105A/201A/205A/311A/321A/371A/372A/381A] | | | | | | | | | | | * | * | * | * | * | * | * | * | * | * | * | * | * | * | | | |
| H15 | Black open-pore linden wood trim | | ● | ● | ● | ● | ● | ● | ● | ● | ● | ● | ● | ● | ● | ● | ● | ● | ● | ● | ● | ● | ● | ● | ● | ● | | 273,00 | |
| | | Not in conjunction with 001A/311A/371A/372A/H55/H59/L3A/P27/P37/RUG | * | * | * | * | * | * | * | * | * | * | * | * | * | * | * | * | * | * | * | * | * | * | * | * | * | | |
| | | Not in conjunction with 641A/H47/U13/U66 | * | * | * | * | * | | | | | | | | | | | | | | | | | | | | | | |

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

| | | | | | | | | | | | | | | | | | | | | | | | | | | | |
|-----|--|---|----|----|----|----|----|----|----|----|----|----|---|----|----|----|----|----|----|----|----|----|----|----|----|------|----------|
| B38 | Charging cable for domestic socket, 5 m, straight | | - | - | - | - | - | - | - | - | - | - | ○ | - | - | - | - | - | - | - | - | - | - | - | - | ○ | 0,00 |
| B74 | Charging cable for domestic socket, 8 m, straight | | - | - | - | - | - | - | - | - | - | - | ● | - | - | - | - | - | - | - | - | - | - | - | - | ● | 73,50 |
| B80 | Charging cable for domestic socket, 8 m, straight | | - | - | - | - | - | - | - | - | - | - | ● | - | - | - | - | - | - | - | - | - | - | - | - | ● | 73,50 |
| | | Not in conjunction with B30 | | | | | | | | | | * | - | - | - | - | - | - | - | - | - | - | - | - | - | * | |
| | | Only in conjunction with 63B | | | | | | | | | | * | - | - | - | - | - | - | - | - | - | - | - | - | - | * | |
| B81 | Charging cable for domestic socket, 8 m, straight | | - | - | - | - | - | - | - | - | - | - | ● | - | - | - | - | - | - | - | - | - | - | - | - | ● | 73,50 |
| B82 | Charging cable for industrial socket, 8 m, straight | | - | - | - | - | - | - | - | - | - | - | ● | - | - | - | - | - | - | - | - | - | - | - | - | ● | 283,50 |
| | | Not in conjunction with B32 | | | | | | | | | | * | - | - | - | - | - | - | - | - | - | - | - | - | - | * | |
| | | Only in conjunction with 63B | | | | | | | | | | * | - | - | - | - | - | - | - | - | - | - | - | - | - | * | |
| B83 | Charging cable for wallbox and public charging stations, | | - | - | - | - | - | - | - | - | - | - | ● | - | - | - | - | - | - | - | - | - | - | - | - | ● | 283,50 |
| | | Not in conjunction with B33 | | | | | | | | | | * | - | - | - | - | - | - | - | - | - | - | - | - | - | * | |
| | | Only in conjunction with 63B | | | | | | | | | | * | - | - | - | - | - | - | - | - | - | - | - | - | - | * | |
| | | i.V.m. Code PYA | - | - | - | - | - | - | - | - | - | - | ● | - | - | - | - | - | - | - | - | - | - | - | - | ● | 73,50 |
| 459 | Suspension with Adaptive Damping system | | ● | ● | ● | ● | ● | ● | ● | ● | ● | ● | - | ● | ● | ● | ● | ● | ● | ● | ● | ● | ● | ● | - | - | 1.039,50 |
| | | Not in conjunction with 485/677 | | | | | | | | | | | | | | | | | | * | * | | | | | | |
| | | Not in conjunction with U54 | * | * | | | | * | * | | | | | * | * | | | | | * | * | * | | | | | |
| | | Only in conjunction with 213 | * | * | * | * | * | * | * | * | * | | | * | * | * | * | * | * | * | * | * | * | * | * | * | |
| | | Only in conjunction with U55 | * | * | | | | * | * | | | | | * | * | | | | | * | * | * | | | | | |
| | | i.V.m. Code 950 (ohne PYH/PYI) | ● | ● | ● | ● | ● | ● | ● | ● | ● | ● | - | ● | ● | ● | ● | ● | ● | ● | ● | ● | ● | ● | - | - | 651,00 |
| | | i.V.m. Code PAD | ○ | ○ | ○ | ○ | ○ | ○ | ○ | ○ | ○ | ○ | - | ○ | ○ | ○ | ○ | ○ | ○ | ○ | ○ | ○ | ○ | ○ | - | - | 0,00 |
| 485 | Comfort suspension | | \$ | \$ | \$ | \$ | \$ | \$ | \$ | \$ | \$ | \$ | - | \$ | \$ | \$ | \$ | \$ | \$ | \$ | \$ | \$ | \$ | \$ | \$ | 0,00 | |
| | | Not in conjunction with 159A/213/257A/258A/651A/950/L5C/P37/P39/PAD/RQS/RUG/U28 | * | * | * | * | * | * | * | * | * | * | | * | * | * | * | * | * | * | * | * | * | * | * | * | |
| | | Not in conjunction with 431/L5l | * | * | * | * | * | * | * | * | * | * | | * | * | * | * | * | * | * | * | * | * | * | * | * | |
| | | Not in conjunction with 459/677 | | | | | | | | | | | | | | | | * | * | | | | | | | | |
| | | Not in conjunction with 641A/772/H47/U13/U26/U66 | * | * | * | * | * | * | * | * | * | * | | * | * | * | * | * | * | * | * | * | * | * | * | * | |
| | | Not in conjunction with U55 | | | | | | | | | | | | | | | | * | | | | | | | | | |
| | | Only in conjunction with 428 | | | * | * | * | | | * | * | | | | | * | * | * | * | | | * | * | * | | | |
| | | Only in conjunction with U54 | | | | | | | | | | | | | | | | * | | | | | | | | | |
| 677 | Lowered comfort suspension | </ | | | | | | | | | | | | | | | | | | | | | | | | | |