

**Standard and special equipment**
**Model year :**

801+051

**Sales Release :**

2020-10-13

**Production Change :**

2020-12-01

Legend

(•) Available at extra cost (○) available without additional charge (S) standard equipment (-) not available (L) Left hand drive only (R) Right hand drive  
Please note that central restrictions are displayed. Markets may have specific deviation if any. Codes could be valid for certain countries only.

			213004 E 220 d	
Code	equipment	Restrictions		LLP
5U6	AMG-specific radiator grille, darkened		-	472,50
			○	0,00
		Not in conjunction with 725		
		Only in conjunction with P60		
		Code at these BM not valid	*	
U47	AMG spoiler lip		●	367,50
			-	0,00
		Available only as part of (P31)		
		Not in conjunction with 001A/101A/H56/P23/P75	*	
		Not in conjunction with 82R	*	
		Not in conjunction with B28/U93		
		Only in conjunction with [772/P31]	*	
		Only for left hand drive		
		Available from August 2020 except USA/CAN/WEU incl. Germany	*	
P87	designo interior in macchiato beige / saddle brown		●	5.145,00
		Includes codes 275+287+421+975A+U04+U38	*	
		Not in conjunction with 001A/101A/P75	*	
		Not in conjunction with 248/837	*	
		Not in conjunction with 336	*	
		Not in conjunction with 450/601A/811A/824A/H56/L5C/P29/U26	*	
		Not in conjunction with 51U/P65/U09	*	
		Not in conjunction with U12	*	
		Only in conjunction with P49	*	
		Only in conjunction with U22	*	
		Only for left hand drive		
		i.V.m. Code PWS+P14	●	5.045,25
		i.V.m. Code (PYE/PYG)+PYO	●	4.074,00
		i.V.m. Code P22	●	3.727,50
		i.V.m. Code PWS+P22	●	3.627,75
		i.V.m. Code PYF+PYO	●	2.656,50
P55	Night package		●	1.207,50
		Includes codes 840 [U50]	*	
		Not in conjunction with 01R/R97/RVO/RZI	*	
		Not in conjunction with 22R/RRD	*	
		Not in conjunction with P23	*	
		Not in conjunction with R11	*	
		Not in conjunction with R32	*	
		Not in conjunction with R43	*	
		i.V.m. Code P15+U50	●	997,50
		i.V.m. Code P31+840	●	787,50
		i.V.m. Code P31+U50	●	577,50
		i.V.m. Code PYG/PYH	●	577,50
		i.V.m. Code P15+U50	-	262,50
260	Deletion of model plate on boot lid		○	0,00
		Only for left hand drive		
		Only valid for T-model		
260	Omission of model plate on boot lid		○	0,00
		Only for left hand drive		
		Only valid for Limosine	*	
231	Garage door opener		●	236,25

		Not in conjunction with 337	*	
		Only in conjunction with P49	*	
		Only for left hand drive		
871	HANDS-FREE ACCESS		○	0,00
		Available only as part of (P17)	*	
		Only in conjunction with P17	*	
		Only for left hand drive		
		Available from September 2020	*	
881	Boot lid convenience closing feature		●	551,25
		Only for left hand drive		
		for certain countries only	*	
		i.V.m. Code P17	○	0,00
		i.V.m. Code PYN/PYO	○	0,00
883	Power closing		●	577,50
		Not in conjunction with 001A/101A/P75	*	
		Not in conjunction with H56	*	
		Only for left hand drive		
889	KEYLESS-GO		●	735,00
		Not in conjunction with 978		
		Only for left hand drive		
		i.V.m. Code P17	○	0,00
		i.V.m. Code PYN/PYO	○	0,00
B67	Vehicle key in high-gloss black with ornamental surround		●	105,00
		Not in conjunction with 934	*	
		Not in conjunction with B68	*	
		Not in conjunction with U32	*	
		Only for left hand drive		
B68	Vehicle key in high-gloss white with ornamental surround		●	105,00
		Not in conjunction with 934	*	
		Not in conjunction with B67	*	
		Not in conjunction with U32	*	
		Only for left hand drive		
P17	KEYLESS-GO Comfort package		●	1.270,50
			-	840,00
		Includes codes 871+881+889	*	
		Includes codes 871+889		
		Not in conjunction with 978		
		Only for left hand drive		
		Expected to be available from September 2020	*	
		i.V.m. Code PYN	○	0,00
		i.V.m. Code PYO	○	0,00
U32	Two additional master keys		●	157,50
		Not in conjunction with B67/B68	*	
		Only for left hand drive	*	
297U	designo selenite grey magno		●	2.940,00
		Only in conjunction with 524	*	
		Only for left hand drive		
644U	designo brilliant blue magno		-	2.940,00
		Only in conjunction with 524		
799U	designo diamond white bright		●	1.732,50
		Only for left hand drive		
996U	designo hyacinth red metallic		●	1.291,50
		Only for left hand drive		
197U	obsidian black		●	913,50
		Only for left hand drive		
831U	graphite grey		●	913,50
		Only for left hand drive		
859U	Mojave silver		●	913,50
		Only for left hand drive		
890U	cavansite blue		●	913,50
		Only for left hand drive		
922U	high-tech silver		●	913,50
		Only for left hand drive		
992U	selenite grey		●	913,50
		Only for left hand drive		
040U	black		○	0,00
		Only for left hand drive		

149U	polar white		●	315,00
		Only for left hand drive		
413	Panoramic sliding sunroof		●	1.858,50
		Not in conjunction with 001A/101A/P75		
		Not in conjunction with 05Z/06Z/333/356	*	
		Not in conjunction with 10Z/11Z/12Z/962/Z30	*	
		Not in conjunction with 19U/334/335/337/341/342/344/450/623U/934/938	*	
		Not in conjunction with 248/837	*	
		Not in conjunction with 24Z/414/50Z/B12	*	
		Not in conjunction with 336	*	
		Not in conjunction with 4R3/844		
		Not in conjunction with 651/652		
		Not in conjunction with 965	*	
		Not in conjunction with 970/974/975	*	
		Not in conjunction with 978		
		Not in conjunction with Z87	*	
		Not in conjunction with Z90	*	
		Only in conjunction with B63		
		Only in conjunction with [965]		
		Only for left hand drive		
		i.V.m. Code PYO	○	0,00
414	Sliding sunroof		●	1.181,25
		Not in conjunction with 001A/101A/P75		
		Not in conjunction with 10Z/11Z/12Z/962/Z30/Z90	*	
		Not in conjunction with 24Z/413/50Z/B12	*	
		Not in conjunction with 970/974/975	*	
		Not in conjunction with 978		
		Not in conjunction with Z87	*	
		Only in conjunction with [965/B63]		
		Only for left hand drive	*	
E22	Alustyle Easy-Fix II rail carrier		–	236,25
			●	210,00
		Not in conjunction with 341/342	*	
		Only for left hand drive		
608	Adaptive Highbeam Assist		●	189,00
		Not in conjunction with 628/642/P35	*	
		Only in conjunction with 632	*	
		Only for left hand drive		
		i.V.m. Code P35	–	0,00
		i.V.m. Code PYA	○	0,00
632	LED High Performance headlamps		○	0,00
		Not in conjunction with 628/642/P35	*	
		Only for left hand drive		
E72	Surround lighting with projection of brand logo		●	131,25
		Not in conjunction with 001A/101A/P75	*	
		Not in conjunction with H56	*	
		Only in conjunction with 891	*	
		Only for left hand drive		
P35	MULTIBEAM LED		●	1.365,00
		Includes codes 628+642	*	
		Not in conjunction with 608/632	*	
		Only for left hand drive		
		i.V.m. Code PYN/PYO	○	0,00
550	Trailer coupling with ESP<sup>®</sup> trailer stabilis		●	1.008,00
		Not in conjunction with 19U/337/341/342/344/934/938/965		
		Not in conjunction with 489		
		Not in conjunction with 4R3/844		
		Not in conjunction with 601A/811A/824A/L5C/P29/P31/RRD/U26		
		Not in conjunction with 651/652		
		Not in conjunction with 978		
		Only for left hand drive		
882	Interior monitoring system		○	0,00
		Not in conjunction with 336	*	
		Only for left hand drive		
887	Independent boot locking		●	26,25
		Only for left hand drive		
		not in conjunction with 830		

E16	Rim lock set		●	52,50
		Only for left hand drive		
P54	URBAN GUARD vehicle protection		●	493,50
		Includes codes 551+882	*	
		Not in conjunction with 336	*	
		Not in conjunction with P82	*	
		Only for left hand drive		
P82	URBAN GUARD vehicle protection Plus		●	703,50
		Includes codes 551+882	*	
		Not in conjunction with 336	*	
		Not in conjunction with P54	*	
		Only for left hand drive		
		i.V.m. Code 34U	●	598,50
645	M+S winter tyres, set of 4		●	204,75
		Not in conjunction with 1R7	*	
		Not in conjunction with 4R3		
		Not in conjunction with 4R6/P55/U50		
		Not in conjunction with 651	*	
		Not in conjunction with 652	*	
		Not in conjunction with 720		
		Not in conjunction with 776		
		Not in conjunction with R01	*	
		Not in conjunction with R03	*	
		Not in conjunction with R06	*	
		Not in conjunction with R32	*	
		Not in conjunction with R97/RRD/RSJ/RSK		
		Only in conjunction with 15R		
		Only in conjunction with 725		
		Only in conjunction with R32		
		Only for left hand drive		
R01	Summer tyres		○	0,00
		Not in conjunction with 645	*	
		Not in conjunction with R03	*	
		Not in conjunction with R05/R66		
		Not in conjunction with R06		
		Only for left hand drive		
R03	Sports tyres		○	0,00
		Not in conjunction with 645/R01	*	
		Not in conjunction with R90/RRD		
		Only in conjunction with [22R]	*	
		Only in conjunction with [B2R]		
		Only in conjunction with [R10/R38/RVQ/RVR]	*	
		Only in conjunction with [R32]	*	
		Only in conjunction with [RSJ/RSK]		
		Only for left hand drive		
		only in conjunction with R06 and RQK, RQJ, 22R or R32	*	
R06	Noise reduced tyre with foam absorber		○	0,00
		Not in conjunction with 19U/337/341/342/623U/965		
		Not in conjunction with 248/450		
		Not in conjunction with 250/R05		
		Not in conjunction with 645	*	
		Not in conjunction with 82R	*	
		Not in conjunction with B51		
		Not in conjunction with R01		
		Not in conjunction with R11/R69	*	
		Not in conjunction with R43	*	
		Not in conjunction with R66		
		Not in conjunction with R90/RRD	*	
		Not in conjunction with R97/RSW	*	
		Only in conjunction with [52R/61R/R48/RVQ/RVR]		
		Only for left hand drive		
R66	run-flat tyres		●	294,00
			-	0,00
		Not in conjunction with 250/R01		
		Not in conjunction with 4R3		
		Not in conjunction with 651/652		
		Not in conjunction with 978		

		Not in conjunction with B51	*	
		Not in conjunction with R06		
		Not in conjunction with RSJ		
		Only in conjunction with R05+RTA		
		Only for left hand drive		
		Only for right hand drive		
		Not in conjunction with 998 (WLTP)		
		i.V.m. div Räder+WKR (<19")	●	588,00
		i.V.m. Code PYA	●	241,50
		i.V.m. S-Code PXI	○	0,00
		i.V.m. div Räder (19" /20")	○	0,00
RRC	48.3 cm (19-inch) AMG 10-spoke light-alloy wheels		-	0,00
		Only in conjunction with 776		
RRD	48.3 cm (19-inch) AMG 10-spoke light-alloy wheels		●	577,50
			-	210,00
		Not in conjunction with 001A/101A/H56/P23/P55/P75/U50	*	
		Not in conjunction with 1R7		
		Not in conjunction with 248/337/341/342/485/550/623U/811/934/965		
		Not in conjunction with 645		
		Not in conjunction with 651/652		
		Not in conjunction with 720		
		Not in conjunction with 978		
		Not in conjunction with R03	*	
		Not in conjunction with R06	*	
		Only in conjunction with 725		
		Only in conjunction with 776+R01		
		Only in conjunction with 7U0+P31	*	
		Only in conjunction with U29		
		Only for left hand drive		
RSJ	45.7 cm (18-inch) AMG 5-twin-spoke light-alloy wheels		○	0,00
		Not in conjunction with 001A/101A/645/H56/P23/P55/P75/U50		
		Not in conjunction with R66		
		Only in conjunction with [772/P31]		
RSK	45.7 cm (18-inch) AMG 5-twin-spoke light-alloy wheels		●	346,50
			-	315,00
		Not in conjunction with 001A/101A/645/H56/P23/P75		
		Only in conjunction with [772/P31]		
		Only in conjunction with (P55)		
		i.V.m. Code P31+P55	○	0,00
RSN	45.7 cm (18-inch) AMG 5-twin-spoke light-alloy wheels		○	0,00
RSP	45.7 cm (18-inch) AMG 5-twin-spoke light-alloy wheels		●	315,00
		i.V.m. Code P31+P55	○	0,00
RSW	5-twin-spoke 48.3 cm (19-inch) AMG light-alloy wheels		●	682,50
		Not in conjunction with 001A/101A/H56/P23/P75	*	
		Not in conjunction with R03	*	
		Not in conjunction with R06	*	
		Only in conjunction with U29		
		Only in conjunction with [772/P31]	*	
		Only for left hand drive		
		i.V.m. Code P31+P55	●	367,50
RVQ	50.8 cm (20-inch) AMG multi-spoke alloy wheels		-	3.885,00
			●	2.887,50
			-	2.152,50
			-	945,00
		Not in conjunction with 19U/337/341/342/344/450/623U/934/938/965/B51/P55/U50	*	
		Not in conjunction with 248	*	
		Not in conjunction with 4R3		
		Not in conjunction with 651/652		
		Not in conjunction with 978		
		Not in conjunction with R05/R06/R66		
		Only in conjunction with R01		
		Only in conjunction with R66	*	
		Only in conjunction with U29		
		Only for left hand drive		
		i.V.m. Code P31	●	1.312,50
		i.V.m. Code P31	-	945,00
RVR	50.8 cm (20-inch) AMG multi-spoke alloy wheels		-	3.885,00

			●	3.202,50
			–	2.467,50
			–	1.260,00
		Not in conjunction with 19U/337/341/342/344/450/623U/934/938/965/B51	*	
		Not in conjunction with 248	*	
		Not in conjunction with 4R3		
		Not in conjunction with 651/652		
		Not in conjunction with 978		
		Not in conjunction with R05/R06/R66		
		Only in conjunction with R01		
		Only in conjunction with R66	*	
		Only in conjunction with U29		
		Only for left hand drive		
		i.V.m. Code P55	●	2.467,50
		i.V.m. Code P31	●	1.627,50
		i.V.m. Code P31+P55	●	1.312,50
		i.V.m. Code P31	–	1.260,00
		i.V.m. Code P31+P55	–	945,00
RZ1	48.3 cm (19-inch) AMG 5-twin-spoke light-alloy wheels		●	367,50
			–	0,00
		Not in conjunction with 001A/101A/H56/P23/P55/P75/U50	*	
		Not in conjunction with R03	*	
		Not in conjunction with R06		
		Only in conjunction with U29		
		Only in conjunction with [772/P31]	*	
		Only for left hand drive		
01R	45.7 cm (18-inch) 5-twin-spoke light-alloy wheels		●	735,00
			–	210,00
		Not in conjunction with 601A/811A/824A/L5C/P23/P29/P55/U26/U50	*	
		Not in conjunction with R03	*	
		Not in conjunction with R06		
		Only in conjunction with P15	*	
		Only in conjunction with U29		
		Only for left hand drive		
08R	43.2 cm (17-inch) multi-spoke light-alloy wheels		●	210,00
		Not in conjunction with 001A/101A/601A/811A/824A/H56/L5C/P15/P29/P75/U26/U29	*	
		Not in conjunction with R03	*	
		Not in conjunction with R06		
		Only in conjunction with P23	*	
		Only for left hand drive		
15R	48.3-cm (19-inch) multi-twin-spoke light-alloy wheels		–	0,00
		Available only as part of (P15)		
		Not in conjunction with 720/P55/U50		
		Only in conjunction with 725		
		Only in conjunction with 7U0+P15		
22R	45.7 cm (18-inch) 5-twin-spoke light-alloy wheels		–	1.890,00
			●	892,50
			–	210,00
		Not in conjunction with 776/P55/U50	*	
		Not in conjunction with P29/P31		
		Not in conjunction with R06		
		Only in conjunction with U29		
		Only for left hand drive		
		i.V.m. Code P15	–	1.155,00
25R	43.2 cm (17-inch) 10-spoke light-alloy wheels		–	735,00
			○	0,00
52R	45.7 cm (18-inch) 5-twin-spoke light-alloy wheels		●	735,00
			–	0,00
		Not in conjunction with 001A/101A/601A/811A/824A/H56/L5C/P15/P29/P75/U26	*	
		Not in conjunction with R03	*	
		Only in conjunction with P23	*	
		Only in conjunction with U29		
		Only for left hand drive		
		for certain countries only		
61R	45.7-cm (18-inch) 10-twin-spoke light-alloy wheels		●	472,50
			–	210,00
		Not in conjunction with 001A/101A/601A/811A/824A/H56/L5C/P15/P29/P75/U26	*	

		Not in conjunction with R03	*	
		Only in conjunction with P23	*	
		Only in conjunction with U29		
		Only for left hand drive		
<b>82R</b>	<b>45.7 cm (18-inch) 5-spoke light-alloy wheels</b>		●	<b>1.732,50</b>
			-	<b>1.155,00</b>
			-	<b>997,50</b>
			-	<b>735,00</b>
			-	<b>210,00</b>
		Not in conjunction with 4R3/844		
		Not in conjunction with 601A/811A/824A/L5C/P29/U26	*	
		Not in conjunction with 651/652		
		Not in conjunction with 772	*	
		Not in conjunction with 776/P23/R06	*	
		Not in conjunction with P31		
		Not in conjunction with R03	*	
		Not in conjunction with U47	*	
		Only in conjunction with 7U0+P15	*	
		Only in conjunction with U29		
		Only for left hand drive		
		i.V.m. Code P15	●	<b>735,00</b>
		i.V.m. Code P23	-	<b>735,00</b>
		i.V.m. Code P15	-	<b>210,00</b>
<b>R10</b>	<b>45.7 cm (18-inch) 5-twin-spoke light-alloy wheels</b>		○	<b>0,00</b>
		Not in conjunction with P23	*	
		Not in conjunction with R06		
		Only in conjunction with U29		
		Only for left hand drive		
<b>R11</b>	<b>43.2 cm (17-inch) 5-twin-spoke light-alloy wheels</b>		○	<b>0,00</b>
		Not in conjunction with 601A/811A/824A/L5C/P23/P29/P55/U26/U29/U50	*	
		Not in conjunction with R03	*	
		Not in conjunction with R06	*	
		Only in conjunction with P15	*	
		Only for left hand drive		
<b>R32</b>	<b>45.7 cm (18-inch) 5-twin-spoke light-alloy wheels</b>		-	<b>1.890,00</b>
			●	<b>892,50</b>
			-	<b>210,00</b>
			-	<b>0,00</b>
		Not in conjunction with 601A/776/811A/824A/L5C/P29/P31/U26	*	
		Not in conjunction with 645	*	
		Not in conjunction with P55/U50	*	
		Not in conjunction with R06		
		Only in conjunction with R01		
		Only in conjunction with U29		
		Only for left hand drive		
<b>R38</b>	<b>45.7 cm (18-inch) 5-twin-spoke light-alloy wheels</b>		●	<b>735,00</b>
			-	<b>0,00</b>
		Not in conjunction with 601A/811A/824A/L5C/P23/P29/U26	*	
		Not in conjunction with R06		
		Only in conjunction with P15	*	
		Only in conjunction with U29		
		Only for left hand drive		
<b>R43</b>	<b>43.2 cm (17-inch) 10-spoke light-alloy wheels</b>		-	<b>997,50</b>
			●	<b>210,00</b>
		Not in conjunction with 459	*	
		Not in conjunction with 4R3/844		
		Not in conjunction with 776/P29/P31/P55/R06/U29/U50	*	
		Not in conjunction with R03	*	
		Only for left hand drive		
		i.V.m. Code P15/P23	-	<b>262,50</b>
		i.V.m. Code P23	-	<b>262,50</b>
		i.V.m. Code P31	-	<b>0,00</b>
<b>R48</b>	<b>43.2 cm (17-inch) 5-twin-spoke light-alloy wheels</b>		●	<b>210,00</b>
		Not in conjunction with 601A/811A/824A/L5C/P23/P29/U26/U29	*	
		Not in conjunction with R03	*	
		Only in conjunction with P15	*	
		Only for left hand drive		

R69	43.2 cm (17-inch) 5-spoke light-alloy wheels		○	0,00
		Not in conjunction with 001A/101A/601A/811A/824A/H56/L5C/P15/P29/P75/U26/U29	*	
		Not in conjunction with R03	*	
		Not in conjunction with R06	*	
		Only in conjunction with P23	*	
		Only for left hand drive		
R90	48.3 cm (19-inch) 5-twin-spoke light-alloy wheels		●	1.732,50
			-	997,50
			-	840,00
		Not in conjunction with 601A/811A/824A/L5C/P23/P29/U26	*	
		Not in conjunction with 776		
		Not in conjunction with R03	*	
		Not in conjunction with R06	*	
		Only in conjunction with P15	*	
		Only in conjunction with U29		
		Only for left hand drive		
		Only in conjunction with P55		
		i.V.m. Code P55	●	997,50
R97	48.3 cm (19") 10-spoke light-alloy wheels		-	2.730,00
			●	1.732,50
			-	997,50
			-	840,00
		Not in conjunction with 601A/811A/824A/L5C/P29/P31/P55/U26/U50	*	
		Not in conjunction with 645		
		Not in conjunction with 978		
		Not in conjunction with R03	*	
		Not in conjunction with R06	*	
		Only in conjunction with R01		
		Only in conjunction with U29		
		Only for left hand drive		
B51	TIREFIT		●	52,50
		Not in conjunction with R05		
		Not in conjunction with R06		
		Not in conjunction with R66	*	
		Not in conjunction with RVQ/RVR	*	
		Only for left hand drive		
		i.V.m. Code PYA	○	0,00
249	interior mirror and driver's exterior mirror automatic		○	0,00
		Available only as part of (P49)	*	
		Only in conjunction with P49	*	
		Only for left hand drive		
313	Roller sunblinds in left and right rear doors		○	0,00
		Available only as part of (P09)	*	
		Not in conjunction with 840	*	
		Only in conjunction with P09	*	
		Only for left hand drive		
		for certain countries only		
500	Electrically folding exterior mirrors		○	0,00
		Available only as part of (P49)	*	
		Only in conjunction with P49	*	
		Only for left hand drive		
540	Electric sunblind for rear window		●	404,25
		Not in conjunction with 840	*	
		Only for left hand drive		
		i.V.m. Code P09	○	0,00
597	Windscreen, heated		●	609,00
		Not in conjunction with 228/B24		
		Not in conjunction with 865/U19	*	
		Only for left hand drive		
840	Heat-insulating dark-tinted glass		●	409,50
		Not in conjunction with 540/61U/65U/P09	*	
		Not in conjunction with PAF/U50	*	
		Only for left hand drive		
		i.V.m. Code P55/P60	○	0,00
		i.V.m. Code P55	-	0,00
		i.V.m. Code PYC/PYG/PYH	○	0,00
875	Heated windscreen washer system		●	178,50



		Only for left hand drive		
		for certain countries only	*	
P09	Sun Protection package		●	588,00
			-	388,50
		Includes codes 313+540+543	*	
		Includes codes 313+543		
		Not in conjunction with 840	*	
		Only for left hand drive		
P49	Mirror package		●	577,50
			-	0,00
		Includes codes 249+500	*	
		Only for left hand drive		
		i.V.m. Code PWS	○	0,00
		i.V.m. Code PYM/PYN/PYO	○	0,00
PAF	Acoustic Comfort package		●	1.039,50
		Includes codes 596	*	
		Not in conjunction with 840	*	
		Only for left hand drive		
U50	Omission of heat-insulating dark-tinted glass		○	0,00
		Not in conjunction with 001A/101A/P75		
		Not in conjunction with 01R/R97/RVQ/RZI	*	
		Not in conjunction with 15R/645		
		Not in conjunction with 22R/RRD	*	
		Not in conjunction with 341/342		
		Not in conjunction with 725		
		Not in conjunction with 840	*	
		Not in conjunction with 978		
		Not in conjunction with P23	*	
		Not in conjunction with R11	*	
		Not in conjunction with R32	*	
		Not in conjunction with R43	*	
		Not in conjunction with RSJ		
		Only in conjunction with P55	*	
		Only in conjunction with P60		
		Only in conjunction with U29		
		Only in conjunction with [R32/R90/RSK/RSW]		
		Only for left hand drive		
518	Media interface cable kit		●	52,50
		Only for left hand drive		
		not in conjunction with 460 or 494		
U82	2 USB ports in the rear		●	47,25
		Not in conjunction with U67	*	
		Only for left hand drive		
		i.V.m. Code PYA	○	0,00
01U	Preinstallation for Navigation Services		○	0,00
		Only in conjunction with 365	*	
		Only in conjunction with PBF	*	
		Only for left hand drive		
		for certain countries only	*	
355	Extended MBUX functions		○	0,00
		Only for left hand drive		
365	Hard-disc navigation		●	577,50
		Only for left hand drive		
		i.V.m. Code PBF	○	0,00
367	Preinstallation for Live Traffic Information		○	0,00
		Only for left hand drive		
PBF	Navigation Connectivity package		●	682,50
		Includes codes 362	*	
		Only in conjunction with 01U	*	
		Only in conjunction with 365	*	
		Only for left hand drive		
		i.V.m. Code PYA	○	0,00
537	Digital radio		-	346,50
			○	0,00
		Only for left hand drive		
		Available from November 2020 (except Korea)	*	
79B	Preinstallation for digital radio		○	0,00

		Only for left hand drive		
865	TV receiver		●	1.039,50
		Not in conjunction with 335	*	
		Not in conjunction with 548	*	
		Not in conjunction with 597	*	
		Not in conjunction with 978		
		Only in conjunction with 549+868	*	
		Only for left hand drive		
		for certain countries only	*	
866	Preinstallation for entertainment and comfort features		●	178,50
		Not in conjunction with 555/PBX		
		Not in conjunction with PBZ		
		Only for left hand drive		
810	Burmester® surround sound system		●	892,50
		Not in conjunction with 001A/101A/P75		
		Not in conjunction with 05Z/06Z/333/356		
		Not in conjunction with 10Z/11Z/12Z/962/Z30/Z90	*	
		Not in conjunction with 24Z/50Z/B12	*	
		Not in conjunction with 336		
		Not in conjunction with 811	*	
		Not in conjunction with 970/974/975	*	
		Not in conjunction with 978		
		Not in conjunction with Z87	*	
		Only in conjunction with [965/B63]		
		Only for left hand drive		
		i.V.m. Code PYO	○	0,00
811	Burmester® high-end 3D surround sound system		●	5.145,00
		Not in conjunction with 001A/05Z/06Z/101A/19U/333/334/335/337/341/342/344/356/450/623U/934/	*	
		Not in conjunction with 10Z/11Z/12Z/962/Z30	*	
		Not in conjunction with 248/336/837	*	
		Not in conjunction with 24Z/50Z/77B/810/970/974/975/B12	*	
		Not in conjunction with 489		
		Not in conjunction with 601A/811A/824A/L5C/P29/P31/RRD/U26		
		Not in conjunction with 965	*	
		Not in conjunction with Z87	*	
		Not in conjunction with Z90	*	
		Only in conjunction with Z87	*	
		Only in conjunction with B63		
		Only for left hand drive		
		i.V.m. Code PYO	●	4.252,50
14U	Smartphone Integration		●	420,00
		Only in conjunction with 16U+17U	*	
		Only for left hand drive		
		for certain countries only	*	
		i.V.m. Code PWS	○	0,00
380	Car telephony		●	619,50
		Only in conjunction with 274		
		Code at these BM not valid	*	
897	Wireless charging system for mobile devices in the front		●	210,00
		Not in conjunction with 274	*	
		Not in conjunction with 301/899	*	
		Not in conjunction with 333	*	
		Not in conjunction with Z30	*	
		Only for left hand drive		
		for certain countries only	*	
		i.V.m. Code PYB	○	0,00
899	Multifunction telephony		●	514,50
		Not in conjunction with 301/897	*	
		Not in conjunction with 333	*	
		Not in conjunction with Z30	*	
		Only in conjunction with 274	*	
		Only for left hand drive		
		for certain countries only	*	
		i.V.m. Code PYB	●	304,50
21U	Dash cam		●	210,00
543	Pull-out sun visor		●	99,75
		Available only as part of (P09)	*	

		Not in conjunction with 840	*	
		Only in conjunction with P09	*	
		Only for left hand drive		
		only in conjunction with 460 or 494		
		<b>i.V.m. Code P09</b>	○	0,00
<b>730</b>	<b>Centre console in light brown open-pore ash wood</b>		●	157,50
		Not in conjunction with 001A/101A/P75	*	
		Not in conjunction with 656/728/736/737/764/H06/H16/H29/H32/H41/H64/H78	*	
		Not in conjunction with 732/H73	*	
		Not in conjunction with 784	*	
		Not in conjunction with H56	*	
		Not in conjunction with L2D	*	
		Only in conjunction with H09	*	
		Only for left hand drive		
		<b>i.V.m. Code PYC/PYE/PYG/PYH</b>	●	52,50
		<b>i.V.m. Code PYF</b>	○	0,00
<b>U09</b>	<b>Dashboard and door beltlines in ARTICO man-made leather</b>		●	630,00
			-	0,00
		Available only as part of (P29)		
		Not in conjunction with 001A/101A/P75	*	
		Not in conjunction with 975A/P87	*	
		Not in conjunction with H56	*	
		Not in conjunction with U04		
		Not in conjunction with U38		
		Only in conjunction with U12		
		Only for left hand drive		
		<b>i.V.m. Code P22/P29/P86</b>	○	0,00
<b>U17</b>	<b>Omission of coloured seat belts</b>		-	0,00
		Not in conjunction with Y04		
		Not in conjunction with Y05		
<b>U38</b>	<b>Dashboard and door beltlines in nappa leather</b>		-	997,50
			○	0,00
		Available only as part of (P87)	*	
		Not in conjunction with 001A/101A/P75	*	
		Not in conjunction with 248/837	*	
		Not in conjunction with 336	*	
		Not in conjunction with 450/601A/811A/824A/H56/L5C/P29/U26	*	
		Not in conjunction with 51U/P65	*	
		Not in conjunction with PBX		
		Not in conjunction with U09	*	
		Not in conjunction with U12	*	
		Only in conjunction with P49+P87	*	
		Only in conjunction with U22	*	
		Only for left hand drive		
<b>U67</b>	<b>230 V socket in rear</b>		●	126,00
		Not in conjunction with 301/U82	*	
		Only for left hand drive		
		for certain countries only	*	
<b>228</b>	<b>Auxiliary heater</b>		●	1.438,50
		Not in conjunction with 597		
		Only in conjunction with 875		
		Only in conjunction with 916	*	
		Only for left hand drive	*	
		<b>i.V.m. Code 362</b>	●	1.281,00
<b>443</b>	<b>Steering wheel heating</b>		●	273,00
		Not in conjunction with 001A/101A/P75	*	
		Not in conjunction with H56	*	
		Not in conjunction with L6G		
		Not in conjunction with P65	*	
		Not in conjunction with PBX		
		Only in conjunction with 275	*	
		Only in conjunction with P49	*	
		Only in conjunction with U22	*	
		Only for left hand drive		
		Available from October 2020	*	
<b>580</b>	<b>THERMATIC automatic climate control</b>		S	0,00
		Not in conjunction with 581	*	

		Not in conjunction with 670		
		Only for left hand drive		
581	THERMOTRONIC automatic climate control		●	892,50
		Not in conjunction with 580	*	
		Only in conjunction with 670	*	
		Only for left hand drive		
B24	Remote control for auxiliary heating		○	0,00
		Not in conjunction with 597		
		Only in conjunction with 228	*	
		Only in conjunction with 875		
		Only in conjunction with 916	*	
		Only for left hand drive	*	
		i.V.m. Code 362	●	210,00
P21	AIR-BALANCE package		●	351,75
		Not in conjunction with 001A/101A/P75	*	
		Not in conjunction with 334	*	
		Not in conjunction with H56	*	
		Only for left hand drive		
		i.V.m. Code PBP/PBR	○	0,00
P68	Warmth Comfort package		●	829,50
			-	451,50
		Includes codes 902+906	*	
		Not in conjunction with 001A/101A/P75	*	
		Not in conjunction with 555/621A/PBX		
		Not in conjunction with 873/P65	*	
		Not in conjunction with H56	*	
		Not in conjunction with PBZ		
		Only in conjunction with 275	*	
		Only in conjunction with P49	*	
		Only in conjunction with U22	*	
		Only for left hand drive		
		i.V.m. Code PBP	●	451,50
		i.V.m. Code PYN/PYO	●	451,50
		i.V.m. Code PBR	○	0,00
E69	EASY-PACK boot box		●	231,00
		Only for left hand drive		
U35	Socket		-	0,00
		Only for left hand drive		
656	Centre console in high-gloss brown ash wood		●	157,50
		Not in conjunction with 001A/101A/P75	*	
		Not in conjunction with 728/730/736/737/764/H09/H16/H29/H32/H41/H64/H78	*	
		Not in conjunction with 732/H73	*	
		Not in conjunction with 784	*	
		Not in conjunction with H56	*	
		Not in conjunction with L2D	*	
		Only in conjunction with H06	*	
		Only for left hand drive		
		i.V.m.Code PYC/PYE/PYF/PYG/PYH	●	52,50
728	Centre console in black piano-lacquer look		○	0,00
		Not in conjunction with 656/730/737/764	*	
		Not in conjunction with 732/H73	*	
		Not in conjunction with 784	*	
		Only for left hand drive		
732	AMG carbon-fibre centre console		●	997,50
		Not in conjunction with 001A/101A/H56/P75	*	
		Not in conjunction with 656/728/730/736/737/764/H06/H09/H16/H29/H32/H64/H78	*	
		Not in conjunction with 784	*	
		Not in conjunction with 978		
		Only in conjunction with 891	*	
		Only for left hand drive		
		i.V.m.Code PYC/PYE/PYF/PYG/PYH	●	840,00
		i.V.m. Code H73	○	0,00
737	Centre console in black open-pored ash wood		●	157,50
		Not in conjunction with 001A/101A/P75	*	
		Not in conjunction with 656/728/730/764/H06/H09/H16/H29/H32/H64	*	
		Not in conjunction with 732/H73	*	
		Not in conjunction with 784	*	

		Not in conjunction with H56	*	
		Only for left hand drive		
		i.V.m. Code PYF	●	52,50
		i.V.m. Code PYC/PYE/PYG/PYH	○	0,00
		i.V.m. Code PYJ	—	0,00
764	Centre console in grey open-pore ash wood		●	157,50
		Not in conjunction with 001A/101A/P75	*	
		Not in conjunction with 656/728/730/736/737/H06/H09/H16/H29/H41/H64/H78	*	
		Not in conjunction with 732/H73	*	
		Not in conjunction with 784	*	
		Not in conjunction with H56	*	
		Not in conjunction with L2D	*	
		Only in conjunction with H32	*	
		Only for left hand drive		
		i.V.m. Code PYC/PYE/PYF/PYG/PYH	●	52,50
784	Centre console in high-gloss burr walnut wood		●	157,50
		Not in conjunction with 001A/101A/P75	*	
		Not in conjunction with 656/730/736/737/764/H06/H09/H16/H32/H41/H78	*	
		Not in conjunction with 732/H73	*	
		Not in conjunction with H56	*	
		Only in conjunction with H29	*	
		Only for left hand drive		
		i.V.m. Code PYC/PYE/PYF/PYG/PYH	●	52,50
H16	designo piano lacquer, black flowing lines		●	1.044,75
		Not in conjunction with 001A/101A/P75	*	
		Not in conjunction with 656/730/736/737/764/H06/H09/H29/H32/H41/H64/H78	*	
		Not in conjunction with 732/H73	*	
		Not in conjunction with 784	*	
		Not in conjunction with H56	*	
		Only in conjunction with 728	*	
		Only for left hand drive		
		i.V.m. Code PYC/PYH	●	792,75
PBP	ENERGIZING package		●	939,75
			—	561,75
		Includes codes 355+873 [401/902]+891+P21+P68	*	
		Not in conjunction with 001A/101A/P75	*	
		Not in conjunction with 334	*	
		Not in conjunction with 548	*	
		Not in conjunction with H56	*	
		Not in conjunction with PBR	*	
		Only in conjunction with 549+868	*	
		Only for left hand drive		
		i.V.m. Code PYO	○	0,00
PBR	ENERGIZING package Plus		●	4.593,75
			—	4.215,75
		Includes codes 355+401+891+P21+P68	*	
		Not in conjunction with 334	*	
		Not in conjunction with 4R3/844		
		Not in conjunction with 548	*	
		Not in conjunction with 555/621A/PBX		
		Not in conjunction with 651/652		
		Not in conjunction with 873/P65/PBP	*	
		Not in conjunction with H56/L5C/P29/U26	*	
		Not in conjunction with P75	*	
		Not in conjunction with PBZ		
		Only in conjunction with 275+432+902+906	*	
		Only in conjunction with 549+868+P49	*	
		Only in conjunction with U22	*	
		Only in conjunction with [201A/208A/214A/215A/801A/804A/805A/975A]+436	*	
		Only for left hand drive		
		i.V.m. Code PYO	●	3.654,00
U12	Velour floor mats		●	99,75
			—	0,00
		Not in conjunction with 450/601A/811A/824A/L5C/P29/U26	*	
		Not in conjunction with 837	*	
		Not in conjunction with P87	*	
		Not in conjunction with U04/U38		

		Only for left hand drive		
		i.V.m. Code PWS	○	0,00
		i.V.m. Code PYA	○	0,00
U25	AMG door sill panels with »AMG« lettering, illuminated		-	178,50
		i.V.m. Code PYJ	-	0,00
		i.V.m.Code PYC/PYE/PYF/PYG/PYH	-	0,00
U25	Illuminated door sill panels with "Mercedes-Benz" lettering		●	178,50
		Not in conjunction with 978		
		Only for left hand drive		
		i.V.m. Code PYJ	-	0,00
		i.V.m.Code PYC/PYE/PYF/PYG/PYH	○	0,00
U26	AMG floor mats		○	0,00
		Available only as part of (P29)		
		Not in conjunction with 01R/52R/61R/82R/R38		
		Not in conjunction with 1R7		
		Not in conjunction with 248/837	*	
		Not in conjunction with 337/341/342/485/550/623U/811/934/965		
		Not in conjunction with 432/436/450/55U/65U/88U/H56/L2B/P23/P87/PBR/U12	*	
		Not in conjunction with 651/652		
		Not in conjunction with 978		
		Not in conjunction with R32		
		Not in conjunction with R90/R97		
		Only in conjunction with 7U0+876+P29+P31	*	
		Only in conjunction with U29		
		Only for left hand drive		
463	Head-up Display		●	1.039,50
		Only for left hand drive		
868	Widescreen cockpit		●	787,50
			-	0,00
		Only for left hand drive		
		i.V.m. Code PYM	○	0,00
		i.V.m. Code PYN/PYO	○	0,00
		i.V.m. S-Code 108	○	0,00
U19	MBUX augmented reality for navigation		●	409,50
		Not in conjunction with 548	*	
		Not in conjunction with 597	*	
		Only in conjunction with 365+549+868	*	
		Only for left hand drive		
		i.V.m. Code PYN/PYO	○	0,00
891	Ambient lighting		○	0,00
		Available only as part of (P29)		
		Not in conjunction with 001A/101A/P75	*	
		Not in conjunction with H56	*	
		Only for left hand drive		
51U	Roof liner in black fabric		●	367,50
			-	0,00
		Not in conjunction with 105A/208A/55U/805A/88U/975A/P87	*	
		Not in conjunction with 308A	*	
		Not in conjunction with 336	*	
		Not in conjunction with 61U/65U	*	
		Not in conjunction with U04/U38		
		Only in conjunction with U12		
		Only for left hand drive		
		i.V.m. Code 601A	○	0,00
		i.V.m. Code 621A/811A	○	0,00
		i.V.m. Code 824A/851A/854A	○	0,00
		i.V.m. Code 830+(5/6/8*A)	○	0,00
		i.V.m. Code P29	○	0,00
55U	Roof liner in macchiato beige fabric		○	0,00
		Not in conjunction with 001A/101A/P75	*	
		Not in conjunction with 121A	*	
		Not in conjunction with 131A/208A/301A/51U/61U/65U/801A/88U	*	
		Not in conjunction with 201A		
		Not in conjunction with 248	*	
		Not in conjunction with 308A	*	
		Not in conjunction with 336	*	
		Not in conjunction with 601A/811A/824A/H56/L5C/P29/U26	*	

		Only for left hand drive		
61U	designo roof lining in black DINAMICA microfibre		●	1.680,00
		Not in conjunction with 248	*	
		Not in conjunction with 336	*	
		Not in conjunction with 450/H56	*	
		Not in conjunction with 51U/65U	*	
		Not in conjunction with 55U/88U	*	
		Not in conjunction with 840	*	
		Not in conjunction with P14	*	
		Not in conjunction with P75	*	
		Not in conjunction with PBX		
		Only in conjunction with 540	*	
		Only in conjunction with [105A/131A/134A/801A/804A/805A/975A]	*	
		Only in conjunction with [201A/601A/811A/824A]	*	
		Only in conjunction with [P22]		
		Only for left hand drive		
65U	designo roof liner in macchiato beige DINAMICA micro		●	1.680,00
		Not in conjunction with 001A/101A/P75	*	
		Not in conjunction with 121A	*	
		Not in conjunction with 131A/208A/301A/55U/801A/88U	*	
		Not in conjunction with 201A		
		Not in conjunction with 248	*	
		Not in conjunction with 308A	*	
		Not in conjunction with 336	*	
		Not in conjunction with 450/601A/811A/824A/H56/L5C/P29/U26	*	
		Not in conjunction with 51U/61U	*	
		Not in conjunction with 588A		
		Not in conjunction with 840	*	
		Not in conjunction with 898A/PBX/Y05		
		Only in conjunction with 540	*	
		Only for left hand drive		
88U	Roof liner in neva grey fabric		○	0,00
		Not in conjunction with 51U/55U/61U/65U	*	
		Not in conjunction with 601A/811A/824A/L5C/P29/U26	*	
		Only for left hand drive		
P65	Seat Comfort package		○	0,00
		Includes codes U22	*	
		Not in conjunction with 275/432/443/902/E83/E84/P68/PBR	*	
		Not in conjunction with 436/L2D/P87	*	
		Not in conjunction with PBZ		
		Not in conjunction with U04/U38		
		Only in conjunction with U12		
		Only for left hand drive		
		i.V.m. Code P75	●	241,50
		i.V.m. Code PYA	○	0,00
275	Memory package		●	1.071,00
		Not in conjunction with 001A/101A/P75	*	
		Not in conjunction with H56	*	
		Not in conjunction with P65	*	
		Not in conjunction with PBX		
		Only in conjunction with P49	*	
		Only in conjunction with U22	*	
		Only for left hand drive		
		i.V.m. Code PBZ	-	0,00
		i.V.m. Code PYO	○	0,00
401	Climatised front seats		●	1.155,00
			-	777,00
		Not in conjunction with 621A/PBX		
		Not in conjunction with 873	*	
		Not in conjunction with H56	*	
		Not in conjunction with P75	*	
		Only in conjunction with [201A/208A/214A/215A/801A/804A/805A/975A]	*	
		Only for left hand drive		
		i.V.m. Code P68/432	●	777,00
		i.V.m. Code PBP	●	777,00
		i.V.m. Code PYM/PYN/PYO	●	777,00
		i.V.m. Code PBR	○	0,00

432	Active Multicontour Seat package		●	2.047,50
		Not in conjunction with 001A/101A/P75	*	
		Not in conjunction with 4R3/844		
		Not in conjunction with 555/621A/PBX		
		Not in conjunction with 601A/811A/824A/H56/L5C/P29/U26	*	
		Not in conjunction with 651/652		
		Not in conjunction with 873/P65	*	
		Not in conjunction with PBZ		
		Only in conjunction with 275+902	*	
		Only in conjunction with 401		
		Only in conjunction with 436	*	
		Only in conjunction with P49	*	
		Only in conjunction with U22	*	
		Only for left hand drive		
		i.V.m. Code PBP	●	1.669,50
		i.V.m. Code PYN/PYO	●	1.669,50
		i.V.m. Code PBR	○	0,00
436	Comfort front head restraints		○	0,00
		Not in conjunction with 001A/101A/P75	*	
		Not in conjunction with 4R3/844		
		Not in conjunction with 601A/811A/824A/H56/L5C/P29/U26	*	
		Not in conjunction with 651/652		
		Not in conjunction with 873/P65	*	
		Only in conjunction with 275+432+902+P49	*	
		Only in conjunction with U22	*	
		Only for left hand drive		
873	Heated front seats		●	378,00
			-	0,00
		Not in conjunction with 401/432/902/P68/PBR	*	
		Not in conjunction with 436	*	
		Only for left hand drive		
		i.V.m. Code PBR/PBP	○	0,00
		i.V.m. Code PYM/PYN/PYO	○	0,00
902	Seat heating Plus for driver and front passenger seats		○	0,00
		Not in conjunction with 001A/101A/P75	*	
		Not in conjunction with 555/621A/PBX		
		Not in conjunction with 873/P65	*	
		Not in conjunction with H56	*	
		Not in conjunction with PBZ		
		Only in conjunction with 275	*	
		Only in conjunction with P49	*	
		Only in conjunction with U22	*	
		Only for left hand drive		
		With 275+(421/P68) added	*	
U10	Automatic front passenger airbag deactivation		○	0,00
		Only for left hand drive		
U22	4-way lumbar support		○	0,00
		Only in conjunction with P65/275	*	
287	Folding rear seat backrests		●	456,75
			-	0,00
		Only for left hand drive		
		i.V.m. Code PWS	○	0,00
		i.V.m. Code PYB	○	0,00
872	Heated rear seats		●	378,00
		Not in conjunction with 248	*	
		Not in conjunction with 978		
		Only in conjunction with [201A/208A/214A/215A/801A/804A/805A/975A]	*	
		Only in conjunction with [811A/824A]	*	
		Only for left hand drive		
446	Touchpad without Controller		○	0,00
		Not in conjunction with 448	*	
		Only for left hand drive		
448	Touchpad with Controller		●	63,00
		Not in conjunction with 446/77B	*	
		Only for left hand drive		
		Available from September 2020	*	



77B	MBUX Interior Assistant		●	315,00
		Not in conjunction with 336	*	
		Not in conjunction with 337	*	
		Not in conjunction with 448	*	
		Not in conjunction with 811	*	
		Only in conjunction with 446	*	
		Only for left hand drive		
L2B	Multifunction steering wheel in nappa leather		○	0,00
		Not in conjunction with 601A/811A/824A/P29/U26	*	
		Not in conjunction with L2D		
		Only for left hand drive		
L2D	Multifunction steering wheel in wood/leather		●	619,50
		Not in conjunction with 001A/101A/P75	*	
		Not in conjunction with 656/730/736/764/H06/H09/H32/H41/H78/P65	*	
		Not in conjunction with H56/H73	*	
		Not in conjunction with L2B		
		Only in conjunction with 275+443+P49	*	
		Only in conjunction with U22	*	
		Only for left hand drive		
		Expected to be available from October 2020	*	
		Only in conjunction with H18/H29	*	
L5C	Multifunction sports steering wheel in nappa leather		○	0,00
		Not in conjunction with 01R/52R/61R/82R/R38		
		Not in conjunction with 1R7		
		Not in conjunction with 248/837	*	
		Not in conjunction with 337/341/342/485/550/623U/811/934/965		
		Not in conjunction with 432/436/450/55U/65U/88U/H56/P23/P75/P87/PBR/U12	*	
		Not in conjunction with 651/652		
		Not in conjunction with 978		
		Not in conjunction with R32		
		Not in conjunction with R90/R97		
		Only in conjunction with 7U0+876+P29+P31	*	
		Only in conjunction with U29		
		Only for left hand drive		
		At these Baumuster not valid		
301	Front and rear ashtray inserts in the stowage compartment		●	47,25
		Not in conjunction with 274	*	
		Not in conjunction with 333	*	
		Not in conjunction with 336	*	
		Not in conjunction with 897/899/U67	*	
		Only for left hand drive		
30P	Stowage facility package		—	183,75
			●	99,75
		Includes codes 309	*	
		Not in conjunction with 333		
		Only for left hand drive		
		i.V.m. Code PWS	○	0,00
		i.V.m. Code PYA	○	0,00
736	Open-pore black ash wood trim		●	252,00
		Not in conjunction with 001A/101A/P75	*	
		Not in conjunction with 656/730/764/H06/H09/H16/H29/H32/H41/H64/H78	*	
		Not in conjunction with 732/H73	*	
		Not in conjunction with 784	*	
		Not in conjunction with H56	*	
		Not in conjunction with L2D	*	
		Only for left hand drive		
		i.V.m. Code P22/P87	●	199,50
		i.V.m. Code PYC/PYH	○	0,00
H06	brown high-gloss ash wood trim		●	252,00
		Not in conjunction with 001A/101A/P75	*	
		Not in conjunction with 730/736/737/764/H09/H16/H29/H32/H41/H64/H78	*	
		Not in conjunction with 732/H73	*	
		Not in conjunction with 784	*	
		Not in conjunction with H56	*	
		Not in conjunction with L2D	*	
		Only for left hand drive		
		i.V.m. Code P22/P87	●	199,50

		i.V.m. Code PYC/PYH	●	52,50
H09	Open-pore light brown ash wood trim		●	252,00
		Not in conjunction with 001A/101A/P75	*	
		Not in conjunction with 656/736/737/764/H06/H16/H29/H32/H41/H64/H78	*	
		Not in conjunction with 732/H73	*	
		Not in conjunction with 784	*	
		Not in conjunction with H56	*	
		Not in conjunction with L2D	*	
		Only for left hand drive		
		i.V.m. Code P87	●	199,50
		i.V.m. Code PYC/PYH	●	52,50
		i.V.m. Code P22	○	0,00
		i.V.m. Code PYF	○	0,00
H29	High-gloss brown burr walnut wood trim		●	252,00
		Not in conjunction with 001A/101A/P75	*	
		Not in conjunction with 656/730/736/737/764/H06/H09/H16/H32/H41/H78	*	
		Not in conjunction with 732/H73	*	
		Not in conjunction with H56	*	
		Only in conjunction with 728		
		Only for left hand drive		
		i.V.m. Code P22	●	199,50
		i.V.m. Code PYC/PYH	●	52,50
		i.V.m. Code P87	○	0,00
H32	Grey open-pore ash wood trim		●	252,00
		Not in conjunction with 001A/101A/P75	*	
		Not in conjunction with 656/730/736/737/764/H06/H09/H16/H29/H41/H64/H78	*	
		Not in conjunction with 732/H73	*	
		Not in conjunction with 784	*	
		Not in conjunction with H56	*	
		Not in conjunction with L2D	*	
		Only for left hand drive		
		i.V.m. Code P22/P87	●	199,50
		i.V.m. Code PYC/PYH	●	52,50
H41	Light longitudinal-grain aluminium trim		●	304,50
		Available only as part of (P29)	-	0,00
		Not in conjunction with 656/730/736/764/H06/H09/H16/H29/H32/H64/H78	*	
		Not in conjunction with 784	*	
		Not in conjunction with H56	*	
		Not in conjunction with H73	*	
		Not in conjunction with L2D	*	
		Only for left hand drive		
		i.V.m. Code PYC/PYH/PYF	●	52,50
		i.V.m. Code P14/P29	○	0,00
		i.V.m. Code P22/P87	○	0,00
		i.V.m. Code PYE/PYG/PYJ	○	0,00
		i.V.m. Code PYE/PYG	-	0,00
H56	Silver special-effect paint trim		○	0,00
		Not in conjunction with 08R/R69	*	
		Not in conjunction with 23U/275/292/401/432/436/443/55U/61U/656/65U/730/732/736/737/764/78	*	
		Not in conjunction with 52R/61R/RSW/RZI	*	
		Not in conjunction with 772	*	
		Not in conjunction with 776		
		Not in conjunction with 811/U47	*	
		Not in conjunction with P31		
		Not in conjunction with RRD	*	
		Not in conjunction with RSJ/RSK		
		Only in conjunction with 728+7U0+L2B+P15+P75	*	
		Only in conjunction with R32		
		Only for left hand drive		
H64	Metal-weave trim		●	472,50
		Not in conjunction with 001A/101A/P75	*	
		Not in conjunction with 656/730/736/737/764/H06/H09/H16/H32/H41/H78	*	
		Not in conjunction with 732/H73	*	
		Not in conjunction with H56	*	
		Only in conjunction with 728		
		Only for left hand drive		

		i.V.m. Code P22/P87	●	420,00
		i.V.m. Code PYC/PYH	●	220,50
H73	AMG carbon-fibre trim		●	3.097,50
		Not in conjunction with 001A/101A/H56/L2D/P75	*	
		Not in conjunction with 656/728/730/736/737/764/H06/H09/H16/H29/H32/H41/H64/H78	*	
		Not in conjunction with 784	*	
		Not in conjunction with 978		
		Only in conjunction with 732	*	
		Only in conjunction with 891	*	
		Only for left hand drive		
		i.V.m. Code PYC/PYH	●	2.845,50
H78	Light carbon-grain aluminium trim		●	304,50
			-	0,00
		Not in conjunction with 001A/101A/P75	*	
		Not in conjunction with 656/730/736/764/H06/H09/H16/H29/H32/H41/H64	*	
		Not in conjunction with 732/H73	*	
		Not in conjunction with 784	*	
		Not in conjunction with H56	*	
		Not in conjunction with L2D	*	
		Only for left hand drive		
		i.V.m. Code PYC/PYF/PYH	●	52,50
		i.V.m. Code PYE/PYG	○	0,00
			●	525,00
101A	black			
		Not in conjunction with 08R/R69	*	
101A		Not in conjunction with 19U/337/341/342/344/413/414/720/810/934/938/965/974/975/L2D/P55/RTG/U04		
101A		Not in conjunction with 23U/275/292/401/432/436/443/55U/61U/656/65U/730/736/737/764/784/87	*	
101A		Not in conjunction with 52R/61R/RSW/RZl	*	
101A		Not in conjunction with 732/H73/P23/U26	*	
101A		Not in conjunction with 772	*	
101A		Not in conjunction with 776		
101A		Not in conjunction with 811/U47	*	
101A		Not in conjunction with P31		
101A		Not in conjunction with RRD	*	
101A		Not in conjunction with RSJ/RSK		
101A		Only in conjunction with 725+873+970+P65+U12+Z90		
101A		Only in conjunction with 7U0+P15	*	
101A		Only in conjunction with L2B+P75	*	
101A		Only in conjunction with R32		
101A		Only for left hand drive		
101A		i.V.m. Code 450	○	0,00
105A	macchiato beige / magma grey		●	210,00
		Not in conjunction with 248	*	
		Not in conjunction with 336	*	
		Not in conjunction with 401/51U/872/PBR	*	
		Not in conjunction with 450/H56/L5C/U26	*	
		Not in conjunction with P14		
		Not in conjunction with P75	*	
		Only in conjunction with 876	*	
		Only in conjunction with P22	*	
		Only for left hand drive		
131A	black		○	0,00
		Not in conjunction with 248	*	
		Not in conjunction with 401/55U/65U/872/PBR	*	
		Not in conjunction with 450/H56/L5C/U26	*	
		Not in conjunction with P14		
		Not in conjunction with P75	*	
		Only in conjunction with 876	*	
		Only in conjunction with P22	*	
		Only for left hand drive		
134A	nut brown / black		-	472,50
			●	210,00
		Not in conjunction with 248	*	
		Not in conjunction with 336	*	
		Not in conjunction with 401/872/PBR	*	
		Not in conjunction with 450/H56/L5C/U26	*	
		Not in conjunction with P14		
		Not in conjunction with P75	*	

		Only in conjunction with 876	*	
		Only in conjunction with P22	*	
		Only for left hand drive		
601A	black		○	0,00
		Not in conjunction with 01R/52R/61R/82R/R38		
		Not in conjunction with 1R7		
		Not in conjunction with 248/336/837	*	
		Not in conjunction with 337/341/342/485/550/623U/811/934/965		
		Not in conjunction with 401/432/436/450/55U/65U/872/88U/H56/L2B/P23/P75/P87/PBR/U12	*	
		Not in conjunction with 651/652		
		Not in conjunction with 978		
		Not in conjunction with R32		
		Not in conjunction with R90/R97		
		Only in conjunction with 7U0+876+P29+P31	*	
		Only in conjunction with U29		
		Only for left hand drive		
301A	black		○	0,00
		Available only as part of (P14)		
		Not in conjunction with 248	*	
		Not in conjunction with 401/55U/61U/65U/872/PBR	*	
		Not in conjunction with 450/H56/L5C/U26	*	
		Not in conjunction with P22		
		Not in conjunction with P75	*	
		Only in conjunction with 7U0+P15		
		Only in conjunction with P14	*	
		Only for left hand drive		
308A	neva grey / magma grey		—	472,50
			●	210,00
		Not in conjunction with 248	*	
		Not in conjunction with 401/51U/55U/61U/65U/872/PBR	*	
		Not in conjunction with 450/H56/L5C/U26	*	
		Not in conjunction with P22		
		Not in conjunction with P75	*	
		Only in conjunction with 7U0+P15		
		Only in conjunction with 88U+P14	*	
		Only for left hand drive		
314A	nut brown / black		●	210,00
		Not in conjunction with 248	*	
		Not in conjunction with 336	*	
		Not in conjunction with 401/61U/872/PBR	*	
		Not in conjunction with 450/H56/L5C/U26	*	
		Not in conjunction with P22		
		Not in conjunction with P75	*	
		Only in conjunction with 7U0+P15		
		Only in conjunction with P14	*	
		Only for left hand drive		
315A	macchiato beige / black		●	210,00
		Not in conjunction with 248	*	
		Not in conjunction with 336	*	
		Not in conjunction with 401/61U/872/PBR	*	
		Not in conjunction with 450/H56/L5C/U26	*	
		Not in conjunction with P22		
		Not in conjunction with P75	*	
		Only in conjunction with 7U0+P15		
		Only in conjunction with P14	*	
		Only for left hand drive		
975A	macchiato beige / saddle brown		○	0,00
		Not in conjunction with 248	*	
		Not in conjunction with 336	*	
		Not in conjunction with 450/H56/L5C/P29/U26	*	
		Not in conjunction with 51U/U09	*	
		Not in conjunction with P75	*	
		Only for left hand drive		
201A	black		●	1.816,50
		Not in conjunction with 248	*	
		Not in conjunction with 55U/61U/65U		
		Not in conjunction with H56	*	

		Not in conjunction with P22	*	
		Not in conjunction with P75	*	
		Only in conjunction with 7U0+P15		
		Only in conjunction with P14		
		Only for left hand drive		
208A	neva grey / magma grey		●	2.026,50
		Not in conjunction with 248	*	
		Not in conjunction with 450/H56/L5C/U26	*	
		Not in conjunction with 51U/55U/61U/65U	*	
		Not in conjunction with P22		
		Not in conjunction with P75	*	
		Only in conjunction with 7U0+P15		
		Only in conjunction with 88U+P14	*	
		Only for left hand drive		
214A	nut brown / black		●	2.026,50
		Not in conjunction with 248	*	
		Not in conjunction with 336	*	
		Not in conjunction with 61U	*	
		Not in conjunction with H56/L5C/U26	*	
		Not in conjunction with P22		
		Not in conjunction with P75	*	
		Only in conjunction with 7U0+P15		
		Only in conjunction with P14	*	
		Only for left hand drive		
215A	macchiato beige / black		●	2.026,50
		Not in conjunction with 248	*	
		Not in conjunction with 336	*	
		Not in conjunction with 61U	*	
		Not in conjunction with H56/L5C/U26	*	
		Not in conjunction with P22		
		Not in conjunction with P75	*	
		Only in conjunction with 7U0+P15		
		Only in conjunction with P14	*	
		Only for left hand drive		
001A	black		○	0,00
		Not in conjunction with 08R/R69	*	
		Not in conjunction with 19U/337/341/342/344/413/414/720/810/934/938/965/974/975/L2D/P55/RTG/U04		
		Not in conjunction with 23U/275/292/401/432/436/443/55U/61U/656/65U/730/736/737/764/784/87	*	
		Not in conjunction with 248	*	
		Not in conjunction with 450/732/H73/P23/U26	*	
		Not in conjunction with 52R/61R/RSW/RZI	*	
		Not in conjunction with 772	*	
		Not in conjunction with 776		
		Not in conjunction with 811/U47	*	
		Not in conjunction with P31		
		Not in conjunction with RRD	*	
		Not in conjunction with RSJ/RSK		
		Only in conjunction with 725+873+970+P65+U12+Z90		
		Only in conjunction with 7U0+P15	*	
		Only in conjunction with L2B+P75	*	
		Only in conjunction with R32		
		Only for left hand drive		
801A	black		●	2.310,00
		Not in conjunction with 248	*	
		Not in conjunction with 450/H56/L5C/U26	*	
		Not in conjunction with 55U/65U	*	
		Not in conjunction with P14		
		Not in conjunction with P75	*	
		Only in conjunction with 876	*	
		Only in conjunction with P22	*	
		Only for left hand drive		
804A	nut brown / black		●	2.520,00
		Not in conjunction with 248	*	
		Not in conjunction with 336	*	
		Not in conjunction with 450/H56/L5C/U26	*	
		Not in conjunction with P14		
		Not in conjunction with P75	*	

		Only in conjunction with 876	*	
		Only in conjunction with P22	*	
		Only for left hand drive		
805A	macchiato beige / magma grey		●	2.520,00
		Not in conjunction with 248	*	
		Not in conjunction with 336	*	
		Not in conjunction with 450/H56/L5C/U26	*	
		Not in conjunction with 51U	*	
		Not in conjunction with P14		
		Not in conjunction with P75	*	
		Only in conjunction with 876	*	
		Only in conjunction with P22	*	
		Only for left hand drive		
811A	black		●	2.310,00
		Not in conjunction with 01R/52R/61R/82R/R38		
		Not in conjunction with 1R7		
		Not in conjunction with 248/336/837	*	
		Not in conjunction with 337/341/342/485/550/623U/811/934/965		
		Not in conjunction with 401/432/436/450/55U/65U/88U/H56/L2B/P23/P75/P87/PBR/U12	*	
		Not in conjunction with 651/652		
		Not in conjunction with 978		
		Not in conjunction with R32		
		Not in conjunction with R90/R97		
		Only in conjunction with 7U0+876+P29+P31	*	
		Only in conjunction with U29		
		Only for left hand drive		
824A	saddle brown / black		●	2.520,00
		Not in conjunction with 01R/52R/61R/82R/R38		
		Not in conjunction with 1R7		
		Not in conjunction with 248/336/837	*	
		Not in conjunction with 337/341/342/485/550/623U/811/934/965		
		Not in conjunction with 401/432/436/450/55U/65U/88U/H56/L2B/P23/P75/P87/PBR/U12	*	
		Not in conjunction with 651/652		
		Not in conjunction with 978		
		Not in conjunction with R32		
		Not in conjunction with R90/R97		
		Only in conjunction with 7U0+876+P29+P31	*	
		Only in conjunction with U29		
		Only for left hand drive		
P14	AVANTGARDE interior		●	1.386,00
			-	0,00
		Includes codes 301A [201A/214A/215A/308A/314A/315A/975A]+876+891+H78 [736/H06/H09/H16/H64]		
		Includes codes 301A [201A/214A/215A/308A/314A/315A/975A]+876+891	*	
		Includes codes 301A [201A/214A/215A/314A/315A/975A]+876+891+H78 [736/H06/H09/H16/H64]		
		Includes codes 301A [201A/214A/215A/314A/315A/975A]+876+891		
		Not in conjunction with 001A/101A	*	
		Not in conjunction with 105A/131A/134A/61U/801A/804A/805A	*	
		Not in conjunction with 248	*	
		Not in conjunction with 601A/811A/824A/H56/L5C	*	
		Not in conjunction with P22		
		Only in conjunction with 7U0+P15		
		Only for left hand drive		
		i.V.m. Code PWS	●	1.144,50
		i.V.m. Code PYE/PYG/PYJ	○	0,00
		i.V.m. Code PYE/PYG	-	0,00
P15	AVANTGARDE exterior		-	1.155,00
			○	0,00
		Includes codes 15R [RRR/RTG]+489+725 [720]		
		Includes codes 485 [489]		
		Includes codes 485+725 [720]		
		Includes codes 677 [459/482/485/489]	*	
		Includes codes 677 [459/485/489]		
		Includes codes 677 [485/489]+725 [720]		
		Not in conjunction with 08R/R69	*	
		Not in conjunction with 52R/61R/RSW/RZI	*	
		Not in conjunction with 601A/811A/824A/L5C/P29/U26	*	
		Not in conjunction with 776		

		Not in conjunction with RRD	*	
		Not in conjunction with RSJ/RSK		
		Not in conjunction with U47	*	
		Only in conjunction with 7U0	*	
		Only in conjunction with [22R/R90/R97]		
		Only in conjunction with [R32]		
		Only for left hand drive		
P15	AVANTGARDE exterior		-	1.155,00
			○	0,00
		Includes codes 15R [RRR/RTG]+489+725 [720]		
		Includes codes 485 [489]		
		Includes codes 485+725 [720]		
		Includes codes 677 [459/482/485/489]	*	
		Includes codes 677 [459/485/489]		
		Includes codes 677 [485/489]+725 [720]		
		Not in conjunction with 08R/R69	*	
		Not in conjunction with 52R/61R/RSW/RZI	*	
		Not in conjunction with 601A/811A/824A/L5C/P29/U26	*	
		Not in conjunction with 776		
		Not in conjunction with RRD	*	
		Not in conjunction with RSJ/RSK		
		Not in conjunction with U47	*	
		Only in conjunction with 7U0	*	
		Only in conjunction with [22R/R90/R97]		
		Only in conjunction with [R32]		
		Only for left hand drive		
P22	EXCLUSIVE interior		-	2.803,50
			●	2.289,00
			-	1.081,50
		Includes codes 891+H09 [736/H06/H16/H29/H32/H41/H64/H78]+U09		
		Includes codes 891+H09 [736/H06/H16/H32/H41/H64/H73/H78]+U09	*	
		Not in conjunction with 450/H56/L5C	*	
		Not in conjunction with P14		
		Only in conjunction with 876	*	
		Only in conjunction with [105A/131A/134A/801A/804A/805A/975A]	*	
		Only for left hand drive		
		i.V.m. Code PWS	●	2.047,50
		i.V.m. Code PYF	○	0,00
P23	EXCLUSIVE exterior		-	1.155,00
			●	210,00
		Includes codes 485 [459/482/489/677]	*	
		Includes codes 485 [459/489/677]		
		Includes codes 485 [489/677]+725		
		Includes codes 485 [489]		
		Includes codes 485+725		
		Not in conjunction with 001A/101A/601A/7U0/811A/824A/H56/L5C/P29/P55/P75/U26/U50	*	
		Not in conjunction with 01R/R10/R38/R90/RRD/RSW/RZI	*	
		Not in conjunction with 720		
		Not in conjunction with 776		
		Not in conjunction with 82R	*	
		Not in conjunction with R11/R48	*	
		Not in conjunction with U47	*	
		Only in conjunction with U29		
		Only in conjunction with [08R/R43/R69]		
		Only in conjunction with [22R/R97]		
		Only in conjunction with [52R/61R/RVQ/RVR]		
		Only in conjunction with [R32]		
		Only for left hand drive		
		i.V.m. Code PYF	○	0,00
P29	AMG Line interior		●	2.121,00
		Includes codes 601A [811A/824A]+891+H41 [736/H06/H09/H16/H64/H73]+L5C+U09+U26	*	
		Not in conjunction with 1R7		
		Not in conjunction with 248/837	*	
		Not in conjunction with 337/341/342/485/550/623U/811/934/965		
		Not in conjunction with 432/436/450/55U/65U/88U/H56/L2B/P23/P87/PBR/U12	*	
		Not in conjunction with 651/652		
		Not in conjunction with 978		

		Not in conjunction with R32		
		Not in conjunction with R90/R97		
		Only in conjunction with 7U0+876+P31	*	
		Only in conjunction with U29		
		Only for left hand drive		
		i.V.m. Code PWS+498	●	1.879,50
		i.V.m. Code PWS ohne 498	●	1.779,75
		i.V.m. Code PYH	○	0,00
P31	AMG Line exterior		-	2.940,00
			●	2.677,50
			-	2.205,00
		Includes codes 485 [489]+772		
		Includes codes 677 [459/482/485/489]+772	*	
		Includes codes 677 [459/485/489]+772		
		Includes codes 677 [485/489]+725 [720]+772		
		Includes codes 725 [720]+772		
		Includes codes 772		
		Not in conjunction with 001A/101A/H56/P75	*	
		Not in conjunction with 1R7		
		Not in conjunction with 248/337/341/342/485/550/623U/811/934/965		
		Not in conjunction with 651/652		
		Not in conjunction with 978		
		Not in conjunction with R32		
		Not in conjunction with R90/R97		
		Only in conjunction with 7U0	*	
		Only in conjunction with U29		
		Only in conjunction with [22R]	*	
		Only in conjunction with [R10/RRD/RSW/RVQ/RVR/RZI]	*	
		Only for left hand drive		
		i.V.m. Code PYG/PYH/PYJ	○	0,00
		i.V.m. Code PYG/PYH	-	0,00
P75	Standard interior equipment and appointments		S	0,00
		Includes codes 001A [101A]+H56 [H41]	*	
		Includes codes 001A [101A]		
		Not in conjunction with 08R/R69	*	
		Not in conjunction with 19U/337/341/342/344/413/414/720/810/934/938/965/974/975/L2D/P55/RTG/U04		
		Not in conjunction with 23U/275/292/401/432/436/443/55U/61U/656/65U/730/736/737/764/784/87	*	
		Not in conjunction with 52R/61R/RSW/RZI	*	
		Not in conjunction with 732/H73/P23	*	
		Not in conjunction with 772	*	
		Not in conjunction with 776		
		Not in conjunction with 811/U47	*	
		Not in conjunction with P31		
		Not in conjunction with RRD	*	
		Not in conjunction with RSJ/RSK		
		Only in conjunction with 725+873+970+P65+U12+Z90		
		Only in conjunction with 7U0+P15	*	
		Only in conjunction with L2B	*	
		Only in conjunction with R32		
		Only for left hand drive		
362	Communications module (LTE) for the use of Mercedes		○	0,00
		Only for left hand drive		
00U	Remote Services		●	105,00
13U	Preinstallation for Remote and Navigation Services		-	0,00
20U	Pre-installation for car sharing		●	52,50
		Only for left hand drive		
		i.V.m. Code PYA	○	0,00
33U	Remote Services Plus		●	157,50
		Not in conjunction with 34U	*	
		Not in conjunction with 38U		
		Only for left hand drive		
		i.V.m. Code PYA	○	0,00
34U	Remote Services Premium		●	262,50
		Not in conjunction with 33U	*	
		Only for left hand drive		
351	Mercedes-Benz emergency call system		○	0,00
		Only for left hand drive		



38U	Remote and Charging Services Plus		-	252,00
		Not in conjunction with 33U		
		Only in conjunction with 365		
		i.V.m. Code PYA	-	0,00
000U	paintwork not yet finalised		○	0,00
		Only in conjunction with 524	*	
		Only for left hand drive		
00B	Owner's Manual and Service Booklet - Danish		○	0,00
		Only for left hand drive		
01B	Owner's Manual and Service Booklet - Dutch		○	0,00
		Only for left hand drive		
02B	Owner's Manual and Service Booklet - German		○	0,00
		Only for left hand drive		
03B	Owner's Manual and Service Booklet - Russian		○	0,00
		Only for left hand drive		
04B	Owner's Manual and Service Booklet - Finnish		○	0,00
		Only for left hand drive		
05B	Owner's Manual and Service Booklet - English		○	0,00
		Only for left hand drive		
05Z	Run-on times MPM 4 hours		○	0,00
		Not in conjunction with 06Z	*	
		Not in conjunction with 413	*	
		Not in conjunction with 810		
		Not in conjunction with 811	*	
		Not in conjunction with B63		
		Not in conjunction with Z97	*	
		Only for left hand drive		
06B	Owner's Manual and Service Booklet - Italian		○	0,00
		Only for left hand drive		
06Z	Run-on times MPM w/o time limit		○	0,00
		Not in conjunction with 05Z	*	
		Not in conjunction with 413	*	
		Not in conjunction with 810		
		Not in conjunction with 811	*	
		Not in conjunction with B63		
		Not in conjunction with Z97	*	
		Only for left hand drive		
07B	Owner's Manual and Service Booklet - French		○	0,00
		Only for left hand drive		
08B	Owner's Manual and Service Booklet - Spanish		○	0,00
		Only for left hand drive		
09B	Owner's Manual and Service Booklet - Portuguese		○	0,00
		Only for left hand drive		
10B	Owner's Manual and Service Booklet - Swedish		○	0,00
		Only for left hand drive		
10Z	High-beam flashing, daytime, for emerg. vehicle		○	0,00
		Not in conjunction with 19U/337/341/342/344/934/938/965	*	
		Not in conjunction with 19U/965		
		Not in conjunction with 248/344/450/934/938		
		Not in conjunction with 248	*	
		Not in conjunction with 337/341/342/623U		
		Not in conjunction with 413/414/810/Z97		
		Not in conjunction with 413/414/810	*	
		Not in conjunction with 450/623U	*	
		Not in conjunction with 811	*	
		Not in conjunction with 837		
		Not in conjunction with B63		
		Not in conjunction with Z97	*	
		Only in conjunction with Z90	*	
		Only for left hand drive		
11B	Owner's Manual and Service Booklet - Arabic		○	0,00
		Only for left hand drive		
11Z	Dayt. run. lamps flashing, daytime, emerg. veh.		○	0,00
		Not in conjunction with 19U/337/341/342/344/934/938/965	*	
		Not in conjunction with 19U/965		
		Not in conjunction with 248/344/450/934/938		
		Not in conjunction with 248	*	

		Not in conjunction with 337/341/342/623U		
		Not in conjunction with 413/414/810/Z97		
		Not in conjunction with 413/414/810	*	
		Not in conjunction with 450/623U	*	
		Not in conjunction with 811	*	
		Not in conjunction with 837		
		Not in conjunction with B63		
		Not in conjunction with Z97	*	
		Only in conjunction with Z90	*	
		Only for left hand drive		
121A	black ARTICO man-made leather		●	262,50
			–	0,00
		Not in conjunction with 248	*	
		Not in conjunction with 401/55U/61U/65U/872/PBR	*	
		Not in conjunction with 450/H56/L5C/U26	*	
		Not in conjunction with P22		
		Not in conjunction with P75	*	
		Only in conjunction with 7U0+P15		
		Only in conjunction with P14	*	
		Only for left hand drive		
124A	ARTICO man-made leather hazelnut brown / black		●	472,50
			–	0,00
		Not in conjunction with 248	*	
		Not in conjunction with 336	*	
		Not in conjunction with 401/61U/872/PBR	*	
		Not in conjunction with 450/H56/L5C/U26	*	
		Not in conjunction with P22		
		Not in conjunction with P75	*	
		Only in conjunction with 7U0+P15		
		Only in conjunction with P14	*	
		Only for left hand drive		
125A	ARTICO man-made leather macchiato beige / black		●	472,50
			–	0,00
		Not in conjunction with 248	*	
		Not in conjunction with 336	*	
		Not in conjunction with 401/61U/872/PBR	*	
		Not in conjunction with 450/H56/L5C/U26	*	
		Not in conjunction with P22		
		Not in conjunction with P75	*	
		Only in conjunction with 7U0+P15		
		Only in conjunction with P14	*	
		Only for left hand drive		
12Z	Dayt. run. lamps flashing, night-time, emerg. veh.		○	0,00
		Not in conjunction with 19U/337/341/342/344/934/938/965	*	
		Not in conjunction with 19U/965		
		Not in conjunction with 248/344/450/934/938		
		Not in conjunction with 248	*	
		Not in conjunction with 337/341/342/623U		
		Not in conjunction with 413/414/810/Z97		
		Not in conjunction with 413/414/810	*	
		Not in conjunction with 450/623U	*	
		Not in conjunction with 811	*	
		Not in conjunction with 837		
		Not in conjunction with B63		
		Not in conjunction with Z97	*	
		Only in conjunction with Z90	*	
		Only for left hand drive		
13B	Owner's Manual and Service Booklet - Norwegian		○	0,00
		Only for left hand drive		
14B	Owner's Manual and Service Booklet - Greek		○	0,00
		Only for left hand drive		
15B	Owner's Manual and Service Booklet - Turkish		○	0,00
		Only for left hand drive		
16B	Owner's Manual and Service Booklet - Polish		○	0,00
		Only for left hand drive		
16U	Smartphone integration (Apple CarPlay™)		○	0,00
		Only in conjunction with 14U+17U	*	

		Only for left hand drive		
17B	Owner's Manual and Service Booklet - Czech		○	0,00
		Only for left hand drive		
17U	Smartphone integration (Android Auto)		○	0,00
		Only in conjunction with 14U+16U	*	
		Only for left hand drive		
19B	Owner's Manual and Service Booklet - French S. Am.		○	0,00
19U	Smartphone integration mirrorlink (Mercedes-Benz Lin		●	157,50
		Not in conjunction with 001A/101A/P75		
		Not in conjunction with 10Z/11Z/12Z/24Z/50Z/96Z/970/974/975/B12/Z30	*	
		Not in conjunction with 356	*	
		Not in conjunction with 413/811	*	
		Not in conjunction with 489		
		Not in conjunction with 550		
		Not in conjunction with 978		
		Not in conjunction with R06		
		Not in conjunction with RVQ/RVR	*	
		Not in conjunction with Z87	*	
		Not in conjunction with Z90	*	
		Not in conjunction with Z97	*	
		Only in conjunction with 965	*	
		Only for left hand drive		
1R7	7-twin-spoke alloy wheel w. winter tyre 43.2 cm ( 17")		●	1.837,50
		Not in conjunction with 459	*	
		Not in conjunction with 4R3/844/978		
		Not in conjunction with 601A/811A/824A/L5C/P29/P31/RRD/U26		
		Not in conjunction with 645/U29	*	
		Only for left hand drive		
20B	Owner's Manual and Service Booklet - Spanish S. Am.		○	0,00
21B	Owner's Manual and Service Booklet - Portug. S. Am.		○	0,00
22B	Owner's Manual and Service Booklet - Japanese		○	0,00
233	DISTRONIC PLUS		○	0,00
		Not in conjunction with 22P/234	*	
		Not in conjunction with 258		
		Only in conjunction with 513+546+K34		
		Only in conjunction with P49	*	
		Only for left hand drive		
23B	Owner's Manual and Service Booklet - simpl. Chinese		—	0,00
23U	Active traffic-assist		○	0,00
		Not in conjunction with 001A/101A/P75	*	
		Not in conjunction with 220/22P/234	*	
		Not in conjunction with 258/PBZ		
		Not in conjunction with 555/PBX		
		Not in conjunction with H56	*	
		Only in conjunction with 235+513+546+K33+K34+P20	*	
		Only in conjunction with 365+P49	*	
		Only for left hand drive		
248	Rear seats with integrated child seats		●	819,00
		Not in conjunction with 10Z/11Z/12Z/55U/61U/65U/87Z/970/974/975/L5C/P14/P29/P87/U26/Z87	*	
		Not in conjunction with 24Z/96Z/P31/RRD/Z30		
		Not in conjunction with 356/50Z/B12	*	
		Not in conjunction with 413/811	*	
		Not in conjunction with 489		
		Not in conjunction with 978		
		Not in conjunction with R06		
		Not in conjunction with RVQ/RVR	*	
		Not in conjunction with Z90	*	
		Not in conjunction with Z97	*	
		Only in conjunction with 101A	*	
		Only in conjunction with [965]		
		Only for left hand drive		
24B	Owner's Manual and Service Booklet - trad. Chinese		○	0,00
24Z	Pre-installation for TETRA mobile radio, Sepura		●	147,00
		Not in conjunction with 19U/341/342/934/965	*	
		Not in conjunction with 248/623U		
		Not in conjunction with 337		
		Not in conjunction with 344/938		

		Not in conjunction with 413/414/810	*	
		Not in conjunction with 450	*	
		Not in conjunction with 811	*	
		Not in conjunction with 837		
		Not in conjunction with B63		
		Not in conjunction with Z97	*	
		Only in conjunction with Z90		
		Only for left hand drive	*	
26B	Owner's Manual and Service Booklet - Chinese Taiwan		○	0,00
270	Aerial for GPS		○	0,00
		Only for left hand drive		
274	Telephone aerial		○	0,00
		Not in conjunction with 301/333/897	*	
		Not in conjunction with Z30		
		Only for left hand drive		
27B	Owner's Manual and Service Booklet - Spanish Mexico		—	0,00
309	Double cup holder		○	0,00
		Available only as part of (30P)	*	
		Not in conjunction with 333/938	*	
		Only in conjunction with 30P	*	
		Only for left hand drive		
30B	Owner's Manual and Service Booklet - Slovenian		○	0,00
		Only for left hand drive		
31B	Owner's Manual and Service Booklet - Hungarian		○	0,00
		Only for left hand drive		
32B	Owner's Manual and Service Booklet - Bulgarian		○	0,00
		Only for left hand drive		
333	Special instrument panel		●	84,00
		Not in conjunction with 274	*	
		Not in conjunction with 301/309/897/899	*	
		Not in conjunction with 30P/810		
		Not in conjunction with 413	*	
		Not in conjunction with 811	*	
		Not in conjunction with B63		
		Not in conjunction with Z97	*	
		Only for left hand drive		
334	Preinstallation for two-way radio in glove compartment		●	94,50
334		Not in conjunction with 335/P21/PBP/PBR	*	
334		Not in conjunction with 413/811	*	
334		Not in conjunction with B63		
334		Not in conjunction with Z97	*	
334		Only for left hand drive	*	
334		i.V.m. Code 450	○	0,00
335	Preinstallation for two-way radio in boot		●	94,50
		Not in conjunction with 334/865	*	
		Not in conjunction with 413/811	*	
		Not in conjunction with B63		
		Not in conjunction with Z97	*	
		Only for left hand drive	*	
		i.V.m. Code 450	○	0,00
336	Preinstallation for taximeter		●	57,75
336		Not in conjunction with 301/51U/551/55U/61U/65U/77B/882/P54/P82/P87	*	
336		Not in conjunction with 413	*	
336		Not in conjunction with 810		
336		Not in conjunction with 811	*	
336		Not in conjunction with B63		
336		Not in conjunction with U04/U38		
336		Not in conjunction with Z97	*	
336		Only in conjunction with [001A/101A]	*	
336		Only in conjunction with [121A]	*	
336		Only in conjunction with [131A/201A/208A/301A/801A]	*	
336		Only in conjunction with [308A]	*	
336		Only for left hand drive		
336		i.V.m. Code 450	○	0,00
337	Taximeter integrated in the rear-view mirror		●	1.039,50
		Not in conjunction with 001A/101A/P75		
		Not in conjunction with 10Z/11Z/12Z/231/77B/970/974/975	*	

		Not in conjunction with 24Z/962/Z30		
		Not in conjunction with 356	*	
		Not in conjunction with 413/811	*	
		Not in conjunction with 489		
		Not in conjunction with 50Z/B12	*	
		Not in conjunction with 550		
		Not in conjunction with 601A/811A/824A/L5C/P29/P31/RRD/U26		
		Not in conjunction with 978		
		Not in conjunction with R06		
		Not in conjunction with RVQ/RVR	*	
		Not in conjunction with Z87	*	
		Not in conjunction with Z90	*	
		Not in conjunction with Z97	*	
		Only in conjunction with 965		
		Only for left hand drive		
33B	Owner's Manual and Service Booklet - Romanian		○	0,00
		Only for left hand drive		
341	Taxi single arm roof sign		●	257,25
		Not in conjunction with 001A/101A/P75		
		Not in conjunction with 10Z/11Z/12Z/24Z/50Z/962/970/974/975/B12/E22/Z30	*	
		Not in conjunction with 356	*	
		Not in conjunction with 413/811	*	
		Not in conjunction with 489		
		Not in conjunction with 550		
		Not in conjunction with 601A/811A/824A/L5C/P29/P31/RRD/U26		
		Not in conjunction with 720/P55/U50		
		Not in conjunction with 978		
		Not in conjunction with R06		
		Not in conjunction with RTG		
		Not in conjunction with RVQ/RVR	*	
		Not in conjunction with Z87	*	
		Not in conjunction with Z90	*	
		Not in conjunction with Z97	*	
		Only in conjunction with 342	*	
		Only in conjunction with 725		
		Only in conjunction with 965		
		Only for left hand drive		
342	Connection, taxi roof sign		●	73,50
		Not in conjunction with 001A/101A/P75		
		Not in conjunction with 10Z/11Z/12Z/24Z/50Z/962/970/974/975/B12/E22/Z30	*	
		Not in conjunction with 356	*	
		Not in conjunction with 413/811	*	
		Not in conjunction with 489		
		Not in conjunction with 550		
		Not in conjunction with 601A/811A/824A/L5C/P29/P31/RRD/U26		
		Not in conjunction with 720/P55/U50		
		Not in conjunction with 978		
		Not in conjunction with R06		
		Not in conjunction with RTG		
		Not in conjunction with RVQ/RVR	*	
		Not in conjunction with Z87	*	
		Not in conjunction with Z90	*	
		Not in conjunction with Z97	*	
		Only in conjunction with 725		
		Only in conjunction with 965		
		Only for left hand drive		
344	Antenna pre-installation for taxi		●	162,75
		Not in conjunction with 001A/101A/P75		
		Not in conjunction with 10Z/11Z/12Z/356/970/974/975	*	
		Not in conjunction with 24Z/50Z/962/B12/Z30		
		Not in conjunction with 413/811	*	
		Not in conjunction with 489		
		Not in conjunction with 550		
		Not in conjunction with 978		
		Not in conjunction with RVQ/RVR	*	
		Not in conjunction with Z87	*	
		Not in conjunction with Z90	*	

		Not in conjunction with Z97	*	
		Only in conjunction with 274	*	
		Only in conjunction with 965		
		Only for left hand drive	*	
34B	Owner's Manual and Service Booklet - Croatian		○	0,00
		Only for left hand drive		
356	Roof-mounted radio aerial		●	204,75
		Not in conjunction with 19U	*	
		Not in conjunction with 248	*	
		Not in conjunction with 337/341/342/965	*	
		Not in conjunction with 344	*	
		Not in conjunction with 413	*	
		Not in conjunction with 623U	*	
		Not in conjunction with 810		
		Not in conjunction with 811	*	
		Not in conjunction with 934		
		Not in conjunction with B63		
		Not in conjunction with Z97	*	
		Only for left hand drive		
35B	Owner's Manual and Service Booklet - Latvian		○	0,00
		Only for left hand drive		
36B	Owner's Manual and Service Booklet - Lithuanian		○	0,00
		Only for left hand drive		
37B	Owner's Manual and Service Booklet - Slovakian		○	0,00
		Only for left hand drive		
38B	Owner's Manual and Service Booklet - Estonian		○	0,00
		Only for left hand drive		
39B	Owner's Manual and Service Booklet - Serbian		○	0,00
		Only for left hand drive		
3R6	10-spoke alloy wheel w. winter tyre 48.3 cm (19")		●	2.992,50
		Not in conjunction with 844	*	
40B	Owner's Manual and Service Booklet - ukrainian		○	0,00
		Only for left hand drive		
41B	Owner's Manual and Service Booklet - hebrew		○	0,00
42B	Owner's Manual and Service Booklet - Indonesian		○	0,00
431	Galvanised steering-wheel gearshift paddles		○	0,00
		Only for left hand drive		
43B	Owner's Manual and Service Booklet - Thai		○	0,00
450	Taxi version, international		●	0,00
		Not in conjunction with 10Z/11Z/12Z/24Z/50Z/61U/65U/960/962/970/974/975/B12/L5C/P22/P29/P87	*	
		Not in conjunction with 413/811	*	
		Not in conjunction with 489		
		Not in conjunction with 978		
		Not in conjunction with R06		
		Not in conjunction with RVQ/RVR	*	
		Not in conjunction with Z87	*	
		Not in conjunction with Z90	*	
		Not in conjunction with Z97	*	
		Only in conjunction with 670+965	*	
		Only in conjunction with 837	*	
		Only in conjunction with [101A/201A/214A/215A]	*	
		Only for left hand drive	*	
		i.V.m. Code PWS	●	897,75
		Only for left hand drive		
4R7	Complete winter wheel, 5-spoke, 18-inch, light-alloy		●	2.362,50
		Not in conjunction with 844	*	
501	360° camera		○	0,00
		Available only as part of (P47)	*	
		Not in conjunction with 218/220	*	
		Not in conjunction with 978		
		Not in conjunction with P44	*	
		Only in conjunction with P47	*	
		Only in conjunction with P49	*	
		Only for left hand drive		
50Z	Conversion parts for emergency vehicles		○	0,00
		Not in conjunction with 19U/341/342/934/965	*	
		Not in conjunction with 248	*	

		Not in conjunction with 337	*	
		Not in conjunction with 344/938		
		Not in conjunction with 413/414/810	*	
		Not in conjunction with 450	*	
		Not in conjunction with 623U	*	
		Not in conjunction with 811	*	
		Not in conjunction with 837		
		Not in conjunction with B63		
		Not in conjunction with Z97	*	
		Only in conjunction with Z90		
		Only for left hand drive		
524	Transport protection (full body cover)		●	168,00
		Only for left hand drive		
		with 000U, 044U, 049U, Z01, Z02 or Z98 added	*	
548	MBUX multimedia system		○	0,00
		Not in conjunction with 256		
		Not in conjunction with 549/865/PBP/PBR/U19	*	
		Not in conjunction with Z87	*	
		Only for left hand drive		
549	MBUX multimedia system		○	0,00
		Not in conjunction with 548	*	
		Only for left hand drive		
551	Anti-theft alarm system with preinstallation for collision		○	0,00
		Not in conjunction with 336	*	
		Only for left hand drive		
596	Tinted and IR-reflecting laminated glass		○	0,00
		Available only as part of (PAF)	*	
		Not in conjunction with 840	*	
		Only in conjunction with PAF	*	
		Only for left hand drive		
623	Gulf States specification		-	0,00
623U	light ivory		○	0,00
		Not in conjunction with 10Z/11Z/12Z/970/974/975	*	
		Not in conjunction with 24Z/601A/811A/824A/962/L5C/P29/P31/RRD/U26/Z30		
		Not in conjunction with 356/50Z/B12	*	
		Not in conjunction with 413/811	*	
		Not in conjunction with 489		
		Not in conjunction with 978		
		Not in conjunction with R06		
		Not in conjunction with RVQ/RVR	*	
		Not in conjunction with Z87	*	
		Not in conjunction with Z90	*	
		Not in conjunction with Z97	*	
		Only in conjunction with 965		
		Only for left hand drive		
625	Australia specification		○	0,00
628	Adaptive Highbeam Assist Plus		○	0,00
		Available only as part of (P35)	*	
		Not in conjunction with 608/632	*	
		Only in conjunction with P35	*	
		Only for left hand drive		
634	Omission of first-aid kit		○	0,00
		Only for left hand drive		
636	Omission of warning triangle		○	0,00
		Only for left hand drive		
63B	Charging socket for electric and plug-in hybrid vehicle		-	0,00
642	LED Intelligent Light System (LHD)		○	0,00
		Available only as part of (P35)	*	
		Not in conjunction with 608/632	*	
		Only in conjunction with P35	*	
		Only for left hand drive		
651	Winter complete wheels fitted		○	0,00
		Not in conjunction with 413/432/436/550/82R/942/PBR/RVQ/RVR		
		Not in conjunction with 459/U29	*	
		Not in conjunction with 601A/811A/824A/L5C/P29/P31/RRD/U26		
		Not in conjunction with 645	*	
		Not in conjunction with 652	*	

		Not in conjunction with 978		
		Not in conjunction with R66		
		Only in conjunction with 1R7	*	
		Only in conjunction with 4R3		
		Only in conjunction with 4R6		
		Only in conjunction with 844		
		Only in conjunction with 9R2		
		Only in conjunction with 9R3		
		Only for left hand drive		
652	Summer complete tyres fitted		○	0,00
		Not in conjunction with 413/432/436/550/82R/94Z/PBR/RVQ/RVR		
		Not in conjunction with 459/U29	*	
		Not in conjunction with 601A/811A/824A/L5C/P29/P31/RRD/U26		
		Not in conjunction with 645	*	
		Not in conjunction with 651	*	
		Not in conjunction with 978		
		Not in conjunction with R66		
		Only in conjunction with 1R7	*	
		Only in conjunction with 4R3		
		Only in conjunction with 4R6		
		Only in conjunction with 844		
		Only in conjunction with 9R2		
		Only in conjunction with 9R3		
		Only for left hand drive		
666	Freight packaging without tie-down hooks		●	0,00
670	Residual engine heat utilisation		○	0,00
		Not in conjunction with 580		
		Only in conjunction with 581		
		Only for left hand drive		
687	Type plate with model year		○	0,00
		Only for left hand drive		
6U7	BlueTEC diesel emission control system including gen		○	0,00
772	AMG bodystyling		○	0,00
		Available only as part of (P31)		
		Not in conjunction with 001A/101A/H56/P75	*	
		Not in conjunction with 773		
		Not in conjunction with 82R	*	
		Not in conjunction with 978		
		Only for left hand drive		
776	Wider wheel arch for AMG wheels		○	0,00
		Not in conjunction with 001A/101A/H56/P23/P75		
		Not in conjunction with 22R	*	
		Not in conjunction with 645		
		Not in conjunction with 82R	*	
		Not in conjunction with R32	*	
		Not in conjunction with R43	*	
		Not in conjunction with R90		
		Only in conjunction with [772/P31]		
		Only for left hand drive		
7U0	Powerdome on bonnet		○	0,00
		Not in conjunction with P23	*	
		Only for left hand drive		
		At these Baumuster not valid		
801	Technical modifications		○	0,00
		Only for left hand drive		
822	South Africa specification		○	0,00
829	Taiwan version		○	0,00
830	China specification		-	0,00
834	New Zealand specification		○	0,00
835	South Korea specification		○	0,00
837	Boot liner - rubber mat		●	189,00
837		Not in conjunction with 001A/101A/P75/Z90		
837		Not in conjunction with 10Z/11Z/12Z/24Z/50Z/96Z/970/974/975/812/Z30/Z87		
837		Not in conjunction with 413/811	*	
837		Not in conjunction with 601A/811A/824A/L5C/P29/P87/U12/U26	*	
837		Not in conjunction with B63		
837		Not in conjunction with Z97	*	



837		Only in conjunction with 965		
837		Only for left hand drive	*	
837		i.V.m. Code PWS	●	89,25
837		i.V.m. Code 450	○	0,00
876	Interior Light package		○	0,00
		Not in conjunction with 001A/101A/P75	*	
		Not in conjunction with H56	*	
		Only for left hand drive		
879	Removable ashtray insert		○	0,00
		Only for left hand drive		
906	Armrest heating for driver and front passenger		○	0,00
		Available only as part of (P68)	*	
		Not in conjunction with 001A/101A/P75	*	
		Not in conjunction with 555/621A/PBX		
		Not in conjunction with 873/P65	*	
		Not in conjunction with H56	*	
		Not in conjunction with PBZ		
		Only in conjunction with 275+P68	*	
		Only in conjunction with P49	*	
		Only in conjunction with U22	*	
		Only for left hand drive		
926	Emission control system with EU4 technology		○	0,00
927	EU6 emissions standard		○	0,00
		Only for left hand drive		
934	Taxi/hire car emergency alarm system		●	257,25
		Not in conjunction with 001A/101A/P75		
		Not in conjunction with 10Z/11Z/12Z/24Z/50Z/962/970/974/975/B12/B67/B68/Z30	*	
		Not in conjunction with 356/601A/811A/824A/L5C/P29/P31/RRD/U26		
		Not in conjunction with 413/811	*	
		Not in conjunction with 489		
		Not in conjunction with 550		
		Not in conjunction with 978		
		Not in conjunction with RVQ/RVR	*	
		Not in conjunction with Z87	*	
		Not in conjunction with Z90	*	
		Not in conjunction with Z97	*	
		Only in conjunction with 965		
		Only for left hand drive	*	
938	Preinst. for 2-way radio hands-free system		●	157,50
		Not in conjunction with 001A/101A/P75		
		Not in conjunction with 10Z/11Z/12Z/309/970/974/975	*	
		Not in conjunction with 24Z/50Z/962/B12/Z30		
		Not in conjunction with 413/811	*	
		Not in conjunction with 489		
		Not in conjunction with 550		
		Not in conjunction with 978		
		Not in conjunction with RVQ/RVR	*	
		Not in conjunction with Z87	*	
		Not in conjunction with Z90	*	
		Not in conjunction with Z97	*	
		Only in conjunction with 965		
		Only for left hand drive	*	
945	Emission Control China Stage 6B		—	0,00
		Only for left hand drive		
947	Pennant holder and pennant staff left		●	997,50
		Only for left hand drive		
948	Pennant holder and pennant staff right		●	997,50
		Only for left hand drive		
960	Government version		○	0,00
		Not in conjunction with 450	*	
		Not in conjunction with 974/975	*	
		Only for left hand drive	*	
961	Petrol particulate filter		—	0,00
		Only for right hand drive		
962	Preparation for signal unit (light bar)		●	168,00
		Not in conjunction with 19U/341/342/934/965	*	
		Not in conjunction with 248/623U		

		Not in conjunction with 337		
		Not in conjunction with 344/938		
		Not in conjunction with 413/414/810	*	
		Not in conjunction with 450	*	
		Not in conjunction with 811	*	
		Not in conjunction with 837		
		Not in conjunction with B63		
		Not in conjunction with Z97	*	
		Only in conjunction with 260	*	
		Only in conjunction with Z90		
		Only for left hand drive	*	
965	Taxi and hire car		●	519,75
965		Not in conjunction with 001A/101A/P75		
965		Not in conjunction with 10Z/11Z/12Z/24Z/50Z/962/B12/Z30	*	
965		Not in conjunction with 356	*	
965		Not in conjunction with 413/811	*	
965		Not in conjunction with 489		
965		Not in conjunction with 550		
965		Not in conjunction with 601A/811A/824A/L5C/P29/P31/RRD/U26		
965		Not in conjunction with 970/974/975/Z90	*	
965		Not in conjunction with 978		
965		Not in conjunction with R06		
965		Not in conjunction with RVQ/RVR	*	
965		Not in conjunction with Z87	*	
965		Not in conjunction with Z97	*	
965		Only for left hand drive		
965		L.V.m. Code 450	○	0,00
970	Preparation for police vehicle		●	656,25
		Not in conjunction with 19U/337/341/342/344/934/938	*	
		Not in conjunction with 248	*	
		Not in conjunction with 413/414/810	*	
		Not in conjunction with 450/623U	*	
		Not in conjunction with 811	*	
		Not in conjunction with 837		
		Not in conjunction with 965	*	
		Not in conjunction with 974/975	*	
		Not in conjunction with Z97	*	
		Only in conjunction with Z90	*	
		Only for left hand drive		
971	Diesel particulate filter		○	0,00
972	Exhaust system with DPF Generation 2.0		○	0,00
973	Designation as owner-driver rental vehicle		○	0,00
		Only for left hand drive		
974	Preparation for fire service command vehicle		●	656,25
		Not in conjunction with 001A/101A/P75		
		Not in conjunction with 19U/337/341/342/344/934/938	*	
		Not in conjunction with 248	*	
		Not in conjunction with 413/414/810/960	*	
		Not in conjunction with 450/623U	*	
		Not in conjunction with 811	*	
		Not in conjunction with 837		
		Not in conjunction with 965	*	
		Not in conjunction with 970/975	*	
		Not in conjunction with Z97	*	
		Only in conjunction with Z90	*	
		Only for left hand drive		
975	Preparation for emergency doctor vehicle		●	656,25
		Not in conjunction with 001A/101A/P75		
		Not in conjunction with 19U/337/341/342/344/934/938	*	
		Not in conjunction with 248	*	
		Not in conjunction with 413/414/810/960	*	
		Not in conjunction with 450/623U	*	
		Not in conjunction with 811	*	
		Not in conjunction with 837		
		Not in conjunction with 965	*	
		Not in conjunction with 970/974	*	
		Not in conjunction with Z97	*	

		Only in conjunction with Z90	*	
		Only for left hand drive		
986	Identification no. (US-VIN)		○	0,00
		Only for left hand drive		
989	Identification label under windshield		○	0,00
		Only for left hand drive		
E02	Kleiderbügel		○	0,00
		Not in conjunction with 555/PBX		
		Not in conjunction with PBZ		
		Only in conjunction with 866	*	
		Only for left hand drive		
E07	Positioning and Tracking System		–	336,00
E08	Approval documentation for driving aids		●	115,50
		Only for left hand drive	*	
E09	Entrance guard		●	178,50
		Only for left hand drive	*	
E65	Steering wheel knob, left		●	420,00
		Only in conjunction with E08	*	
		Only for left hand drive	*	
E66	Steering wheel knob, right		●	420,00
		Only in conjunction with E08	*	
		Only for left hand drive	*	
E83	"Easy speed" leather-covered hand control unit		●	2.940,00
		Not in conjunction with 001A/101A/P75	*	
		Not in conjunction with E84/E92/E94/E96/P65	*	
		Not in conjunction with H56	*	
		Not in conjunction with PBX		
		Only in conjunction with 275+E08	*	
		Only in conjunction with P49	*	
		Only in conjunction with U22	*	
		Only for left hand drive	*	
E84	"Easy speed" hand control unit		●	2.310,00
		Not in conjunction with 001A/101A/P75	*	
		Not in conjunction with E83/E92/E94/E96/P65	*	
		Not in conjunction with H56	*	
		Not in conjunction with PBX		
		Only in conjunction with 275+E08	*	
		Only in conjunction with P49	*	
		Only in conjunction with U22	*	
		Only for left hand drive	*	
E85	Belt buckle opener		●	183,75
		Only for left hand drive	*	
E87	Pedal cover		●	525,00
		Only in conjunction with E08	*	
		Only for left hand drive	*	
E88	Combination switch moved to the right		●	241,50
		Only in conjunction with E08	*	
		Only for left hand drive	*	
E89	Accelerator pedal moved to the left (electronic)		●	1.680,00
		Only in conjunction with E08	*	
		Only for left hand drive	*	
E92	Pedal extenders (2)		●	630,00
		Not in conjunction with E83/E84	*	
		Only in conjunction with E08	*	
		Only for left hand drive	*	
E94	Left seat repositioning to the rear		●	651,00
		Not in conjunction with E83/E84/E96	*	
		Only in conjunction with E08	*	
		Only for left hand drive	*	
E95	Right seat repositioning to the rear		●	651,00
		Not in conjunction with E97	*	
		Only in conjunction with E08	*	
		Only for left hand drive	*	
E96	Seat raising on left		●	525,00
		Not in conjunction with E83/E84/E94	*	
		Only in conjunction with E08	*	
		Only for left hand drive	*	

E97	Seat raising on right		●	525,00
		Not in conjunction with E95	*	
		Only in conjunction with E08	*	
		Only for left hand drive	*	
K11	Adaptive brake lights		S	0,00
		Only for left hand drive		
K33	Extended automatic Re-start in traffic jams		○	0,00
		Not in conjunction with 220/22P/234	*	
		Not in conjunction with 239	*	
		Not in conjunction with 258	*	
		Only in conjunction with 233+235+513+546+K34	*	
		Only in conjunction with 365+P49	*	
		Only for left hand drive		
K34	Route-based speed adaptation		○	0,00
		Not in conjunction with 22P/234	*	
		Not in conjunction with 239	*	
		Not in conjunction with 258	*	
		Only in conjunction with 233+513+546	*	
		Only in conjunction with 365+P49	*	
		Only for left hand drive		
L	Left-hand drive		○	0,00
PWS	Standard equipment package		●	3.045,00
			-	2.992,50
			-	2.672,25
			-	2.651,25
			-	2.619,75
			-	2.331,00
			-	2.278,50
			-	1.884,75
			-	1.512,00
			-	1.307,25
			-	934,50
		i.V.m. Code 498	●	2.945,25
		i.V.m. Code 498	-	2.892,75
		i.V.m. Code 498	-	2.572,50
		i.V.m. Code 498	-	2.520,00
PYA	Base package		●	0,00
PYB	SE Package		●	0,00
PYE	Avantgarde Line		●	1.470,00
PYF	EXCLUSIVE Line		-	
			●	2.530,00
PYG	AMG/AVANTGARDE Line		●	4.660,00
PYH	AMG Line		●	5.540,00
PYM	Advantage Package		-	
			●	2.342,00
PYN	Premium Package		-	
			●	4.892,00
PYO	Premium Plus package		-	
			●	7.718,00
R	Right-hand drive		●	1.905,75
R05	Summer tyres		-	0,00
		Not in conjunction with 250/B51/R01/R06		
		Only in conjunction with R66+RTA		
R26	48.3 cm (19") 10-spoke light-alloy wheels		-	1.575,00
			-	840,00
R31	45.7 cm (18-inch) 5-spoke light-alloy wheels		●	735,00
			-	210,00
			-	0,00
RUG	48.3 (19-inch) AMG multi-spoke light-alloy wheels		-	577,50
U01	Status display for rear seat belts in instrument cluster		○	0,00
		Only for left hand drive		

U04	designo floor mats		○	0,00
		Available only as part of (P87)	*	
		Not in conjunction with 001A/101A/P75	*	
		Not in conjunction with 248/837	*	
		Not in conjunction with 336	*	
		Not in conjunction with 450/601A/811A/824A/H56/L5C/P29/U26	*	
		Not in conjunction with 51U/P65/U09	*	
		Not in conjunction with U12	*	
		Only in conjunction with P49+P87	*	
		Only in conjunction with U22	*	
		Only for left hand drive		
U13	Badge for special model		○	0,00
U16	Exhaust system with acoustic flap		-	0,00
		Only for left hand drive		
U41	Fuel/water separator and lubrication package		○	0,00
U60	Pedestrian protection		○	0,00
		Only for left hand drive		
U66	Floor mats for special model		○	0,00
U79	BlueTEC diesel emission control system including AdB		●	0,00
U80	115 V socket		-	126,00
U93	AMG spoiler lip in carbon fibre on boot lid		-	0,00
		Not in conjunction with U47		
		Only in conjunction with B28		
Z01	Paint not feat.on standard sample card		○	0,00
		Not in conjunction with Z02/Z98	*	
		Only in conjunction with 000U+524	*	
		Only for left hand drive		
Z02	Paint not feat.on standard sample card		○	0,00
		Not in conjunction with Z01/Z98	*	
		Only in conjunction with 000U+524	*	
		Only for left hand drive		
Z30	Motor continuity circuit		○	0,00
		Not in conjunction with 19U/341/342/934/965	*	
		Not in conjunction with 248/623U		
		Not in conjunction with 274		
		Not in conjunction with 337		
		Not in conjunction with 344/938		
		Not in conjunction with 413/414/810/897/899	*	
		Not in conjunction with 450	*	
		Not in conjunction with 811	*	
		Not in conjunction with 837		
		Not in conjunction with B63		
		Not in conjunction with Z97	*	
		Only in conjunction with Z90	*	
		Only for left hand drive	*	
Z87	Monitor activation in special-purpose vehicles		●	63,00
		Not in conjunction with 19U/337/341/342/344/934/938/965	*	
		Not in conjunction with 248/450/623U	*	
		Not in conjunction with 413/414/548/810	*	
		Not in conjunction with 811	*	
		Not in conjunction with 837		
		Not in conjunction with B63		
		Not in conjunction with Z97	*	
		Only in conjunction with Z90	*	
		Only for left hand drive		
Z88	Deactivation of ext. lights, sp-purpose vehicles		○	0,00
Z90	Multifunction control unit for special functions		●	399,00
		Not in conjunction with 19U/337/341/342/344/934/938	*	
		Not in conjunction with 248	*	
		Not in conjunction with 413/414/810	*	
		Not in conjunction with 450/623U	*	
		Not in conjunction with 811	*	
		Not in conjunction with 837		
		Not in conjunction with 965	*	
		Not in conjunction with Z97	*	
		Only for left hand drive		
Z97	Electronic interface for remote control		●	399,00

		Not in conjunction with 001A/101A/P75		
		Not in conjunction with 05Z/06Z/19U/333/334/335/337/341/342/344/356/934/938	*	
		Not in conjunction with 10Z/11Z/12Z/962/Z30	*	
		Not in conjunction with 248	*	
		Not in conjunction with 24Z/50Z/970/974/975/B12	*	
		Not in conjunction with 336/837	*	
		Not in conjunction with 450/623U	*	
		Not in conjunction with 965	*	
		Not in conjunction with Z87	*	
		Not in conjunction with Z90	*	
		Only in conjunction with B63		
		Only for left hand drive	*	
<b>Z98</b>	<b>Paint not feat.on standard sample card</b>		○	<b>0,00</b>
		Not in conjunction with Z01/Z02	*	
		Only in conjunction with 000U+524	*	
		Only for left hand drive		
<b>B12</b>	<b>Tyre-change toolkit</b>		○	<b>0,00</b>
		Not in conjunction with 19U/341/342/934/965	*	
		Not in conjunction with 248	*	
		Not in conjunction with 337	*	
		Not in conjunction with 344/938		
		Not in conjunction with 413/414/810	*	
		Not in conjunction with 450	*	
		Not in conjunction with 623U	*	
		Not in conjunction with 811	*	
		Not in conjunction with 837		
		Not in conjunction with B63		
		Not in conjunction with Z97	*	
		Only in conjunction with Z90		
		Only for left hand drive		
		<b>i.V.m. Code 970/974/975</b>	●	<b>31,50</b>
<b>682</b>	<b>Fire extinguisher</b>		●	<b>0,00</b>
<b>682</b>		Only for left hand drive		
<b>70B</b>	<b>Fluorescent jacket for driver</b>		●	<b>5,25</b>
		Not in conjunction with 71B	*	
		Only for left hand drive		
<b>71B</b>	<b>Safety vests for driver and passengers</b>		●	<b>26,25</b>
		Not in conjunction with 70B	*	
		Only for left hand drive		
<b>293</b>	<b>Sidebags in rear</b>		●	<b>399,00</b>
		Not in conjunction with 978		
		Only for left hand drive		
<b>294</b>	<b>Kneebag</b>		S	<b>0,00</b>
		Only for left hand drive		
<b>258</b>	<b>Active Brake Assist</b>		○	<b>0,00</b>
<b>258</b>		Not in conjunction with 233		
<b>258</b>		Not in conjunction with 23U/546/K33/K34	*	
<b>258</b>		Not in conjunction with 266		
<b>258</b>		Only for left hand drive		
<b>292</b>	<b>PRE-SAFE® impulse side</b>		○	<b>0,00</b>
		Available only as part of (P20)	*	
		Not in conjunction with 001A/101A/P75	*	
		Not in conjunction with 22P/234	*	
		Not in conjunction with 555/PBX		
		Not in conjunction with H56	*	
		Not in conjunction with PBZ		
		Only in conjunction with 513+546+K34		
		Only in conjunction with P20	*	
		Only in conjunction with P49	*	
		Only for left hand drive		
<b>299</b>	<b>PRE-SAFE® system</b>		S	<b>0,00</b>
		Only for left hand drive		
<b>266</b>	<b>Active Steering Assist</b>		○	<b>0,00</b>
		Not in conjunction with 22P/234	*	
		Not in conjunction with 258		
		Only in conjunction with [233/23P/292/P20]		
		Only for left hand drive		

22P	Lane Tracking package		●	819,00
		Includes codes 234+243	*	
		Not in conjunction with 233/23U/266/546/K33/K34	*	
		Not in conjunction with 23P	*	
		Not in conjunction with 292	*	
		Not in conjunction with 978		
		Not in conjunction with P20	*	
		Only in conjunction with 258		
		Only in conjunction with P49	*	
		Only in conjunction with [239]		
		Only for left hand drive		
		i.V.m. Code PYM/PYN/PYO	●	346,50
234	Blind Spot Assist		●	472,50
		Not in conjunction with 233/23U/266/546/K33/K34	*	
		Not in conjunction with 23P	*	
		Not in conjunction with 292	*	
		Not in conjunction with 978		
		Not in conjunction with P20	*	
		Only in conjunction with 258		
		Only in conjunction with P49	*	
		Only in conjunction with [239]		
		Only for left hand drive		
		i.V.m. Code 22P	○	0,00
		i.V.m. Code PYM/PYN/PYO	○	0,00
239	Active Distance Assist DISTRONIC		●	945,00
			-	630,00
		Not in conjunction with 23U/546/K33/K34	*	
		Not in conjunction with 266		
		Only for left hand drive		
23P	Driving Assistance package		●	2.026,50
		Includes codes 233+266	*	
		Not in conjunction with 22P/234/23U	*	
		Only in conjunction with 513+546+K34		
		Only in conjunction with P49	*	
		Only for left hand drive		
		i.V.m. Code PYM/PYN/PYO	●	1.554,00
243	Active Lane Keeping Assist		○	0,00
		Available only as part of (22P)	*	
		Not in conjunction with 233/23U/266/546/K33/K34	*	
		Not in conjunction with 23P	*	
		Not in conjunction with 292	*	
		Not in conjunction with 978		
		Not in conjunction with P20	*	
		Only in conjunction with 22P	*	
		Only in conjunction with 258		
		Only in conjunction with P49	*	
		Only in conjunction with [239]		
		Only for left hand drive		
243	Active Lane Keeping Assist		○	0,00
		Available only as part of (22P)	*	
		Not in conjunction with 233/23U/266/546/K33/K34	*	
		Not in conjunction with 23P	*	
		Not in conjunction with 292	*	
		Not in conjunction with 978		
		Not in conjunction with P20	*	
		Only in conjunction with 22P	*	
		Only in conjunction with 258		
		Only in conjunction with P49	*	
		Only in conjunction with [239]		
		Only for left hand drive		
475	Tyre pressure monitoring system		●	320,25
			-	0,00
		Only for left hand drive		
		i.V.m. S-Code 6P5	○	0,00
513	Traffic Sign Assist		●	309,75
		Only in conjunction with 365	*	
		Only for left hand drive		

		i.V.m. Code PYA	○	0,00
513	Traffic Sign Assist		●	309,75
		Only in conjunction with 365	*	
		Only for left hand drive		
		i.V.m. Code PYA	○	0,00
546	Active Speed Limit Assist		○	0,00
		Not in conjunction with 22P/234	*	
		Not in conjunction with 239	*	
		Not in conjunction with 258	*	
		Only in conjunction with 233	*	
		Only in conjunction with 513+K34		
		Only in conjunction with P49	*	
		Only for left hand drive		
P20	Driving Assistance package Plus		●	2.551,50
		Includes codes 233+266+292	*	
		Not in conjunction with 001A/101A/P75	*	
		Not in conjunction with 22P/234	*	
		Not in conjunction with 555/PBX		
		Not in conjunction with H56	*	
		Not in conjunction with PBZ		
		Only in conjunction with 513+546+K34		
		Only in conjunction with P49	*	
		Only for left hand drive		
		i.V.m. Code PYM/PYN/PYO	●	2.079,00
218	Reversing camera		●	420,00
			-	0,00
		Not in conjunction with 220/P47	*	
		Only for left hand drive		
		i.V.m. Code P44	○	0,00
		i.V.m. Code PYA	○	0,00
220	Parking Assist PARKTRONIC		●	682,50
		Not in conjunction with 218/P47	*	
		Not in conjunction with 235/23U/K33/P44	*	
		Only for left hand drive		
235	Active Parking Assist with PARKTRONIC		○	0,00
		Not in conjunction with 220	*	
		Not in conjunction with 978		
		Only for left hand drive		
P44	Parking package with reversing camera		●	1.097,25
			-	330,75
		Includes codes 218+235	*	
		Not in conjunction with 220/P47	*	
		Not in conjunction with 501		
		Not in conjunction with 978		
		Only for left hand drive		
		i.V.m. Code PWS	○	0,00
		i.V.m. Code PYM	○	0,00
P47	Parking Package with 360-degree camera		●	1.580,25
			-	813,75
		Includes codes 235+501	*	
		Not in conjunction with 218/220	*	
		Not in conjunction with 978		
		Not in conjunction with P44	*	
		Only in conjunction with P49	*	
		Only for left hand drive		
		for certain countries only	*	
		i.V.m. Code PWS	●	483,00
		i.V.m. Code PYM	●	483,00
		i.V.m. Code PYN/PYO	○	0,00
915	Fuel tank with a capacity of 80 litres		-	105,00
		Not in conjunction with 916		
		i.V.m. Code PYA	-	0,00
916	Fuel tank with a capacity of 66 litres		●	52,50
			-	0,00
		Not in conjunction with 915		
		Only for left hand drive		
		i.V.m. Code PWS	○	0,00



		i.V.m. Code PYA	○	0,00
916	Fuel tank with a capacity of 60 litres		-	52,50
			-	0,00
		Not in conjunction with Ccode 998 (WLTP)		
		i.V.m. Code PWS	-	0,00
		i.V.m. Code PYA	-	0,00
B59	DYNAMIC SELECT		○	0,00
		Only for left hand drive		
U29	Braking system with larger brake discs on the front ax		●	262,50
			-	0,00
		Not in conjunction with 08R/R48/R69	*	
		Not in conjunction with 1R7	*	
		Not in conjunction with 651/652	*	
		Not in conjunction with R11	*	
		Not in conjunction with R43	*	
		Only for left hand drive		
		i.V.m. Code PYG/PYH	○	0,00
U85	AdBlue® tank with 23.5-litre capacity		○	0,00
459	DYNAMIC BODY CONTROL suspension with adjustable		●	997,50
		Not in conjunction with 1R7/651/652	*	
		Not in conjunction with R43	*	
		Only for left hand drive		
482	Suspension with higher ground clearance		○	0,00
		Only for left hand drive		
485	AGILITY CONTROL suspension with selective damping		○	0,00
		Not in conjunction with 489		
		Not in conjunction with 601A/811A/824A/L5C/P29/P31/RRD/U26		
		Only for left hand drive		
489	AIR BODY CONTROL		●	1.995,00
			-	1.575,00
			-	0,00
		Not in conjunction with 19U/248/337/341/342/344/450/485/550/623U/811/934/938/965		
		Not in conjunction with 677		
		Only for left hand drive		
489	AMG RIDE CONTROL+		-	1.995,00
			-	1.575,00
			-	0,00
489	AIR BODY CONTROL		●	1.995,00
			-	1.575,00
			-	0,00
		Not in conjunction with 19U/248/337/341/342/344/450/485/550/623U/811/934/938/965		
		Not in conjunction with 677		
		Only for left hand drive		
677	AGILITY CONTROL suspension with selective damping		○	0,00
		Not in conjunction with 489		
		Only for left hand drive		
		i.V.m. Code P23	●	441,00
481	Underguard		●	0,00
481		Only for left hand drive		
421	9G-TRONIC		S	0,00
		Only for left hand drive		
B53	Acoustic ambient protection		-	0,00