

Standard

Model year :

Sales Release :

Production Change :

Legend

802+052

2021-10-12

2021-12-01

(•) Available at extra cost (○) available without additional charge (S) standard equipment (-) not available (L) Left hand drive only (R) Right hand drive only (Please note that central restrictions are displayed. Markets may have specific deviation if any. Codes could be valid for certain countries only.)

Ap.Πρωτ 309

213004 E 220 d

N/A	Code	equipment	Restrictions		Local price excl. VAT
	NST				
	5U6	AMG-specific radiator grille, darkened		-	472,50
				○	0,00
			Not in conjunction with 725		
			Only in conjunction with P60		
			Not valid for MB type	*	
	773	AMG Exterior Carbon-Fibre package I		-	3.097,50
			Not in conjunction with 772		
	B14	AMG carbon-fibre engine cover		-	787,50
	B28	AMG Exterior Carbon-Fibre package II		-	1.837,50
				-	1.260,00
			Not in conjunction with U47		
			Only in conjunction with U93		
	P31	Mercedes-AMG exterior		-	0,00
			Includes codes 725 [720]+772		
			Includes codes 772+U47		
			i.V.m. Code PYG/PYH/PYJ	-	0,00
	P60	AMG Night package		-	997,50
			Includes codes 720+840 [U50]		
			Includes codes 840 [U50]		
			Not in conjunction with 725		
			i.V.m. Code PYC	-	787,50
			i.V.m. Code U50	-	787,50
	P60	AMG Night package		-	997,50
			Includes codes 720+840 [U50]		
			Includes codes 840 [U50]		
			Not in conjunction with 725		
			i.V.m. Code PYC	-	787,50
			i.V.m. Code U50	-	787,50
	P90	Mercedes-AMG exterior		-	0,00
	P90	Mercedes-AMG exterior		-	0,00
	U47	AMG spoiler lip		●	367,50
				-	0,00
			Not in conjunction with 001A/101A/H56/P23/P75	*	
			Not in conjunction with B28/U93		
			Only in conjunction with 772+P31	*	
	U70	red-painted brake callipers		-	0,00
			Available only as part of (P71)		
			Not in conjunction with B07		
			Only in conjunction with 3U0		
			Only in conjunction with P71		
	555	AMG Performance seats		-	0,00
			Available only as part of (PBZ)		
			Not in conjunction with 23U/432/902/P20/P68/PBR		
			Not in conjunction with 292		
			Not in conjunction with P65		
			Only in conjunction with PBZ		
	L6J	AMG Performance steering wheel in nappa leather		-	0,00
			Not in conjunction with L6K		

	L6K	AMG Performance steering wheel in nappa leather / DIN		-	441,00
			Not in conjunction with L6J	-	0,00
			i.V.m. Code P71	-	0,00
P29		Mercedes-AMG interior		-	0,00
			Includes codes 891+H41 [736/H06/H09/H16/H64/H73]+U09+U26		
			i.V.m. Code PYH	-	0,00
P86		Mercedes-AMG interior		-	0,00
P86		Mercedes-AMG interior		-	0,00
PBX		AMG Performance Seat Package		-	2.047,50
			Includes codes 555+873		
			Not in conjunction with 23U/275/401/432/443/61U/65U/902/E67/E68/E83/E84/P20/P68/PBR/PBZ/U38		
			Not in conjunction with 292		
			Only in conjunction with 51U+P65+U09		
			Only in conjunction with 621A		
PBZ		AMG Performance Seat package High-End		-	5.922,00
				-	3.538,50
			Includes codes 275+555+873 [401]		
			Not in conjunction with 23U/432/902/P20/P65/P68/PBR		
			Not in conjunction with 292		
			Not in conjunction with 621A/PBX		
			Only in conjunction with P49		
			i.V.m. Code 898A	-	6.132,00
			i.V.m. Code PYO	-	4.851,00
			i.V.m. Code 554A/555A/588A	-	3.748,50
			i.V.m. Code PYO	-	2.467,50
U88		AMG steering wheel buttons		-	0,00
250		AMG Driver's package		-	1.995,00
				-	0,00
			Not in conjunction with R05/R06/R66		
250		AMG Driver's package		-	1.995,00
				-	0,00
			Not in conjunction with R05/R06/R66		
250		AMG Driver's package		-	1.995,00
			Not in conjunction with R05/R06/R66		
3U0		AMG high-performance compound brake system		-	0,00
			Not in conjunction with B07		
			Only in conjunction with U70		
421		AMG SPEEDSHIFT MCT 9G		-	0,00
421		AMG SPEEDSHIFT TCT 9G		-	0,00
467		AMG electronic rear-axle limited-slip differential		-	0,00
B07		AMG high-performance ceramic composite braking system		-	7.560,00
			Not in conjunction with 3U0/U70		
B59		AMG DYNAMIC SELECT		-	0,00
P71		AMG DYNAMIC PLUS package		-	2.142,00
P71		AMG DYNAMIC PLUS package		-	1.575,00
			Includes codes U70+U88		
U78		AMG performance exhaust system, selectable		-	1.470,00
			i.V.m. Code PYC	-	0,00
			i.V.m. S-Code 3P8	-	0,00
E08		Approval documentation for driving aids		●	126,00
			Only in conjunction with E5P	*	
			Only for left hand drive	*	
E09		Entrance guard		●	199,50
			Only in conjunction with E5P	*	
			Only for left hand drive	*	
E65		Steering wheel knob, left		●	441,00
			Only in conjunction with E08+E5P	*	
			Only for left hand drive	*	
E66		Steering wheel knob, right		●	441,00
			Only in conjunction with E08+E5P	*	
			Only for left hand drive	*	
E67		"Classic" hand control unit		●	2.205,00
			Not in conjunction with 001A/101A/P75	*	
			Not in conjunction with E68/E83/E84/E92/E94/E96/P65	*	
			Not in conjunction with H56	*	
			Not in conjunction with PBX		

		Only in conjunction with 275+E08+E5P	*	
		Only in conjunction with P49	*	
		Only in conjunction with U22	*	
		Only for left hand drive	*	
E68	"Classic" leather-covered hand control unit		●	2.835,00
		Not in conjunction with 001A/101A/P75	*	
		Not in conjunction with E67/E83/E84/E92/E94/E96/P65	*	
		Not in conjunction with H56	*	
		Not in conjunction with PBX		
		Only in conjunction with 275+E08+E5P	*	
		Only in conjunction with P49	*	
		Only in conjunction with U22	*	
		Only for left hand drive	*	
E83	"Easy speed" leather-covered hand control unit		●	3.045,00
		Not in conjunction with 001A/101A/P75	*	
		Not in conjunction with E67/E68/E84/E92/E94/E96/P65	*	
		Not in conjunction with H56	*	
		Not in conjunction with PBX		
		Only in conjunction with 275+E08+E5P	*	
		Only in conjunction with P49	*	
		Only in conjunction with U22	*	
		Only for left hand drive	*	
E84	"Easy speed" hand control unit		●	2.415,00
		Not in conjunction with 001A/101A/P75	*	
		Not in conjunction with E67/E68/E83/E92/E94/E96/P65	*	
		Not in conjunction with H56	*	
		Not in conjunction with PBX		
		Only in conjunction with 275+E08+E5P	*	
		Only in conjunction with P49	*	
		Only in conjunction with U22	*	
		Only for left hand drive	*	
E85	Belt buckle opener for the driver		●	183,75
		Only in conjunction with E5P	*	
		Only for left hand drive	*	
E87	Pedal cover		●	525,00
		Only in conjunction with E08+E5P	*	
		Only for left hand drive	*	
E88	Combination switch moved to the right		●	262,50
		Only in conjunction with E08+E5P	*	
		Only for left hand drive	*	
E89	Accelerator pedal moved to the left (electronic)		●	1.785,00
		Only in conjunction with E08+E5P	*	
		Only for left hand drive	*	
E92	Pedal extenders (2)		●	756,00
		Not in conjunction with E67/E68/E83/E84	*	
		Only in conjunction with E08+E5P	*	
		Only for left hand drive	*	
E94	Left seat repositioning to the rear		●	787,50
		Not in conjunction with E67/E68/E83/E84/E96	*	
		Only in conjunction with E08+E5P	*	
		Only for left hand drive	*	
E95	Right seat repositioning to the rear		●	787,50
		Not in conjunction with E97	*	
		Only in conjunction with E08+E5P	*	
		Only for left hand drive	*	
E96	Seat raising on left		●	787,50
		Not in conjunction with E67/E68/E83/E84/E94	*	
		Only in conjunction with E08+E5P	*	
		Only for left hand drive	*	
E97	Seat raising on right		●	787,50
		Not in conjunction with E95	*	
		Only in conjunction with E08+E5P	*	
		Only for left hand drive	*	
P55	Night package		●	1.207,50
			-	997,50
			-	787,50
			-	472,50

			Includes codes 720+840 [U50]		
			Includes codes 840 [U50]	*	
			Not in conjunction with 001A/ 101A/P75		
			Not in conjunction with 01R/22R/R11/R97/RRD/RVQ/RZl		
			Not in conjunction with 15R		
			Not in conjunction with 341/342		
			Not in conjunction with 645		
			Not in conjunction with 725		
			Not in conjunction with P23	*	
			Not in conjunction with RSJ		
			Only in conjunction with [52R/61R/R10/R38/R48/RSW/RVR]	*	
			Only in conjunction with [52R/61R/R10/R38/RSW/RVR]		
			Only in conjunction with [R32/RSK/RSW]		
			i.V.m. Code P15+U50	●	997,50
			i.V.m. Code P31+840	●	787,50
			i.V.m. Code P31+U50	●	577,50
			i.V.m. Code PYG/PYH	●	577,50
			i.V.m. Code P15+U50	-	262,50
	260	Omission of model plate on boot lid		○	0,00
	260	Deletion of model plate on boot lid		-	0,00
	261	Omission of badge on the wings		-	0,00
	871	HANDS-FREE ACCESS		○	0,00
			Only in conjunction with P17	*	
	881	Boot lid convenience closing feature		●	551,25
			i.V.m. Code P17	○	0,00
			i.V.m. Code PYN/PYO	○	0,00
	883	Power closing		●	577,50
			Not in conjunction with 001A/ 101A/P75	*	
			Not in conjunction with H56	*	
	889	KEYLESS-GO		●	735,00
			i.V.m. Code P17	○	0,00
			i.V.m. Code PBH	○	0,00
			i.V.m. Code PYN/PYO	○	0,00
	B67	Vehicle key in high-gloss black with ornamental surround		●	105,00
			Not in conjunction with 934	*	
			Not in conjunction with U32	*	
	P17	KEYLESS-GO Comfort package		●	1.270,50
				-	840,00
			Includes codes 881+889	*	
			Includes codes 889		
			Only in conjunction with 871	*	
	U32	Two additional master keys		●	157,50
			Not in conjunction with B67	*	
			Only for left hand drive	*	
	197U	obsidian black		●	913,50
	595U	nautic blue		●	913,50
	831U	graphite grey		●	913,50
	859U	Mojave silver		●	913,50
	922U	high-tech silver		●	913,50
	992U	selenite grey		●	913,50
	040U	black		○	0,00
	149U	polar white		●	315,00
	297U	MANUFAKTUR selenite grey magno		●	2.940,00
			Only in conjunction with 524	*	
	593U	MANUFAKTUR spectral blue magno		-	2.940,00
			Only in conjunction with 524		
	799U	MANUFAKTUR diamond white bright		●	1.732,50
	996U	MANUFAKTUR hyacinth red metallic		●	1.291,50
	413	Panoramic sliding sunroof		●	1.858,50
			Not in conjunction with 001A/ 101A/P75		
			Not in conjunction with 05Z/06Z/356	*	
			Not in conjunction with 10Z/11Z/12Z	*	
			Not in conjunction with 248/837	*	
			Not in conjunction with 24Z	*	
			Not in conjunction with 333/334/335/337/341/342/344/450/623U/934/938	*	
			Not in conjunction with 336	*	
			Not in conjunction with 414/50Z/812	*	

			Not in conjunction with 4R3/844		
			Not in conjunction with 651/652		
			Not in conjunction with 962/Z30	*	
			Not in conjunction with 965	*	
			Not in conjunction with 970/974/975	*	
			Not in conjunction with Z87	*	
			Not in conjunction with Z90	*	
			Only in conjunction with 30P	*	
			Only in conjunction with B63		
			Only in conjunction with [965/B63]		
			i.V.m. Code PYO	○	0,00
	414	Sliding sunroof		●	1.181,25
			Not in conjunction with 001A/101A/P75		
			Not in conjunction with 05Z/06Z/356		
			Not in conjunction with 10Z/11Z/12Z/Z90	*	
			Not in conjunction with 24Z	*	
			Not in conjunction with 336		
			Not in conjunction with 413/50Z/B12	*	
			Not in conjunction with 962/Z30	*	
			Not in conjunction with 970/974/975	*	
			Not in conjunction with Z87	*	
			Only in conjunction with [965/B63]		
	720	Roof rails in black		—	0,00
			Available only as part of (P55)		
			Available only as part of (P60)		
			Not in conjunction with 001A/101A/P75		
			Not in conjunction with 15R		
			Not in conjunction with 341/342		
			Not in conjunction with 645		
			Not in conjunction with 725		
			Not in conjunction with P23		
			Not in conjunction with RRD		
			Not in conjunction with RSJ		
			Only in conjunction with P55		
			Only in conjunction with P60		
	725	Polished aluminium roof rails		—	0,00
			Not in conjunction with 5U6/P60		
			Not in conjunction with 720/U50		
			Not in conjunction with P55		
			Not in conjunction with RSK		
			Not in conjunction with RTG		
	E22	Alustyle Easy-Fix II rail carrier		—	236,25
				●	210,00
			Not in conjunction with 341/342	*	
	608	Adaptive Highbeam Assist		●	189,00
			Not in conjunction with 628/642/P35	*	
			Only in conjunction with 632	*	
			i.V.m. Code P35	—	0,00
			i.V.m. Code PYA	○	0,00
	632	LED High Performance headlamps		○	0,00
			Not in conjunction with 628/642/P35	*	
	E28	Surround lighting with projection of AMG brand logo		—	152,25
	E72	Surround lighting with projection of brand logo		●	131,25
			Not in conjunction with 001A/101A/P75	*	
			Not in conjunction with H56	*	
			Only in conjunction with 891	*	
	P35	MULTIBEAM LED		●	1.365,00
			Includes codes 628+642	*	
			Not in conjunction with 608/632	*	
			i.V.m. Code PBA	●	1.139,25
			i.V.m. Code PBB/PBC	○	0,00
	550	Trailer coupling with ESP<sup>®</sup> trailer stabilis		●	1.008,00
			Not in conjunction with 333/337/341/342/344/934/938/965		
			Not in conjunction with 489		
			Not in conjunction with 4R3/844		
			Not in conjunction with 651/652		
			Only in conjunction with 30P		

			Only for left hand drive		
	882	Interior monitoring system		○	0,00
			Not in conjunction with 336	*	
	887	Independent boot locking		●	26,25
	E16	Rim lock set		●	52,50
	P54	URBAN GUARD vehicle protection		●	493,50
				—	0,00
			Includes codes 551+882	*	
			Not in conjunction with 336	*	
			Not in conjunction with P82	*	
	P82	URBAN GUARD vehicle protection Plus		●	703,50
				—	210,00
			Includes codes 551+882	*	
			Not in conjunction with 336	*	
			Not in conjunction with P54	*	
			i.V.m. Code 34U	●	598,50
	645	M+S winter tyres, set of 4		●	204,75
			Not in conjunction with 1R7	*	
			Not in conjunction with 22R/R32	*	
			Not in conjunction with 4R3		
			Not in conjunction with 4R6/P55/U50		
			Not in conjunction with 651/652	*	
			Not in conjunction with 720		
			Not in conjunction with R01	*	
			Not in conjunction with R03/R06/R97/RRD/RVQ/RVR	*	
			Only in conjunction with 15R		
			Only in conjunction with 725		
	R01	Summer tyres		○	0,00
			Not in conjunction with 645	*	
			Not in conjunction with R03	*	
			Not in conjunction with R05/R66		
			Not in conjunction with R06		
	R03	Sports tyres		○	0,00
			Not in conjunction with 645	*	
			Not in conjunction with R01	*	
			Not in conjunction with R97/RRD/RSW/RZI		
			Only in conjunction with [22R/R32/RVQ]	*	
			Only in conjunction with [22R/RVQ]		
			Only for left hand drive		
	R06	Noise reduced tyre with foam absorber		○	0,00
			Not in conjunction with 01R/R38		
			Not in conjunction with 248/337/341/342/623U/965		
			Not in conjunction with 250/R05		
			Not in conjunction with 645	*	
			Not in conjunction with B51		
			Not in conjunction with R01		
			Not in conjunction with R66		
			Not in conjunction with R97/RRD/RSW/RZI		
			Only in conjunction with [22R/R32/RVQ/RVR/RZI]	*	
			Only in conjunction with [22R/RVQ/RVR/RZI]		
			Only for left hand drive		
	R66	run-flat tyres		●	294,00
				—	0,00
			Not in conjunction with 250/R01		
			Not in conjunction with 4R3		
			Not in conjunction with 651/652		
			Not in conjunction with B51	*	
			Not in conjunction with R06		
			Only in conjunction with R05		
			Only in conjunction with RTA		
			i.V.m. div Räder+WKR (<19")	●	588,00
			i.V.m. Code PYA	●	241,50
			i.V.m. S-Code PXI	○	0,00
			i.V.m. div Räder (19"/20")	○	0,00
	RRC	48.3 cm (19-inch) AMG 10-spoke light-alloy wheels		—	0,00
			Only in conjunction with 776		
	RRD	48.3 cm (19-inch) AMG 10-spoke light-alloy wheels		●	577,50

		Not in conjunction with 001A/101A/H56/P23/P55/P75/R03/U50	*	
		Not in conjunction with 1R7		
		Not in conjunction with 645	*	
		Not in conjunction with 651/652		
		Not in conjunction with 720		
		Not in conjunction with 978	*	
		Not in conjunction with R06	*	
		Only in conjunction with 725		
		Only in conjunction with 772+776+7U0+R01	*	
		Only in conjunction with P31	*	
	RRR	50.8 cm (20-inch) AMG 5-twin-spoke light-alloy wheels	-	1.312,50
		Not in conjunction with 645		
		Only in conjunction with 7U0+P15		
		Only in conjunction with R01		
		i.V.m. Code P55	-	787,50
	RSJ	45.7 cm (18-inch) AMG 5-twin-spoke light-alloy wheels	○	0,00
		Not in conjunction with 001A/101A/H56/P23/P55/P75/U50		
		Not in conjunction with 720		
		Only in conjunction with 725		
		Only in conjunction with 772+7U0		
		Only in conjunction with P31		
	RSK	45.7 cm (18-inch) AMG 5-twin-spoke light-alloy wheels	●	315,00
		Not in conjunction with 001A/101A/H56/P23/P75		
		Not in conjunction with 341/342/725		
		Only in conjunction with 772+7U0+P55		
		Only in conjunction with P31		
		i.V.m. Code P31+P55	○	0,00
	RSW	5-twin-spoke 48.3 cm (19-inch) AMG light-alloy wheels	●	682,50
		Not in conjunction with 001A/101A/H56/P23/P75/R03	*	
		Not in conjunction with 978	*	
		Not in conjunction with R06	*	
		Only in conjunction with 772+P31	*	
		Only in conjunction with 776+R01		
		i.V.m. Code P31+P55	●	367,50
	RTA	48.3 cm (19-inch) AMG 5-twin-spoke light-alloy wheels	-	0,00
		Not in conjunction with R06		
	RTG	48.3 cm (19-inch) AMG 5-twin-spoke light-alloy wheels	-	0,00
		Not in conjunction with 001A/101A/P75		
		Not in conjunction with 341/342/725		
		Not in conjunction with 645		
		Only in conjunction with P55		
		Only in conjunction with R01		
	RTR	50.8 cm (20-inch) AMG cross-spoke forged wheels	-	2.415,00
			-	1.365,00
		Only in conjunction with 776		
	RTS	50.8 cm (20-inch) AMG cross-spoke forged wheels	-	2.940,00
			-	1.890,00
		Only in conjunction with 776		
	RVQ	50.8 cm (20-inch) AMG multi-spoke alloy wheels	●	2.887,50
			-	2.152,50
			-	945,00
		Not in conjunction with 248	*	
		Not in conjunction with 333/337/341/342/344/450/623U/934/938/965	*	
		Not in conjunction with 4R3		
		Not in conjunction with 645/B51/P55/U50	*	
		Not in conjunction with 651/652		
		Not in conjunction with R05/R06/R66		
		Only in conjunction with 30P+R66	*	
		Only in conjunction with R01		
		i.V.m. Code P15/P23	●	2.152,50
		i.V.m. Code P23	-	2.152,50
		i.V.m. Code P31	●	1.312,50
	RVR	50.8 cm (20-inch) AMG multi-spoke alloy wheels	●	3.202,50
			-	2.467,50
			-	1.260,00
		Not in conjunction with 248	*	
		Not in conjunction with 333/337/341/342/344/450/623U/934/938/965	*	

			Not in conjunction with 4R3/844		
			Not in conjunction with 645/B51/R03	*	
			Not in conjunction with 651/652		
			Not in conjunction with R05/R06/R66		
			Only in conjunction with 30P+776+R06+R66	*	
			Only in conjunction with R01	*	
			i.V.m. Code P23	●	2.467,50
			i.V.m. Code P55	●	2.467,50
			i.V.m. Code P31	●	1.627,50
			i.V.m. Code P31+P55	●	1.312,50
	RZ1	48.3 cm (19-inch) AMG 5-twin-spoke light-alloy wheels		●	367,50
			Not in conjunction with 001A/101A/H56/P23/P55/P75/R03/U50	*	
			Not in conjunction with 978	*	
			Not in conjunction with R06		
			Only in conjunction with 772+P31	*	
			Only in conjunction with 776+R01		
	RZS	50.8 cm (20-inch) AMG 5-twin-spoke light-alloy wheels		-	1.680,00
			Not in conjunction with R05/R06/R66		
			Only in conjunction with R01		
	RZT	50.8 cm (20-inch) AMG 5-twin-spoke light-alloy wheels		-	1.155,00
			Not in conjunction with R05/R06/R66		
			Only in conjunction with R01		
	RZU	50.8 cm (20-inch) AMG 5-twin-spoke light-alloy wheels		-	945,00
				-	0,00
			Only in conjunction with 776		
	RZX	50.8 cm (20-inch) AMG 5-twin-spoke light-alloy wheels		-	1.260,00
				-	315,00
			Only in conjunction with 776		
	01R	45.7 cm (18-inch) 5-twin-spoke light-alloy wheels		●	735,00
				-	210,00
			Not in conjunction with 4R3/844		
			Not in conjunction with 601A/776/811A/824A/L5C/P23/P29/P55/R03/R06/U26/U50	*	
			Not in conjunction with 651/652		
			Not in conjunction with 772	*	
			Not in conjunction with 978	*	
			Not in conjunction with P31		
			Only in conjunction with P15	*	
	15R	48.3-cm (19-inch) multi-twin-spoke light-alloy wheels		-	0,00
			Not in conjunction with 720/P55/U50		
			Only in conjunction with 725		
			Only in conjunction with 7U0+P15		
	22R	45.7 cm (18-inch) 5-twin-spoke light-alloy wheels		●	892,50
				-	210,00
			Not in conjunction with 645	*	
			Not in conjunction with 772/P29/P31	*	
			Not in conjunction with 776/P55/U50	*	
			Not in conjunction with 978	*	
			Not in conjunction with R06		
			i.V.m. Code P15	-	1.155,00
			i.V.m. Code P23	●	157,50
	52R	45.7 cm (18-inch) 5-twin-spoke light-alloy wheels		○	0,00
			Not in conjunction with 001A/101A/601A/811A/824A/H56/L5C/P29/P75/R03/U26	*	
			Not in conjunction with 772	*	
			Not in conjunction with 978	*	
			Not in conjunction with P31		
			Not in conjunction with R06	*	
			Only in conjunction with P23	*	
	61R	45.7-cm (18-inch) 10-twin-spoke light-alloy wheels		○	0,00
			Not in conjunction with 001A/101A/601A/811A/824A/H56/L5C/P29/P75/R03/U26	*	
			Not in conjunction with 772	*	
			Not in conjunction with 978	*	
			Not in conjunction with P31		
			Not in conjunction with R06	*	
			Only in conjunction with P23	*	
	R10	45.7 cm (18-inch) 5-twin-spoke light-alloy wheels		○	0,00
			Not in conjunction with 978	*	
			Not in conjunction with P23/R03	*	



			Not in conjunction with R06	*	
	R11	43.2 cm (17-inch) 5-twin-spoke light-alloy wheels		○	0,00
			Not in conjunction with 601A/811A/824A/L5C/P23/P29/P55/R03/U26/U29/U50	*	
			Not in conjunction with 772	*	
			Not in conjunction with 978	*	
			Not in conjunction with P31		
			Not in conjunction with R06	*	
			Only in conjunction with P15	*	
	R32	45.7 cm (18-inch) 5-twin-spoke light-alloy wheels		●	892,50
				–	210,00
				–	0,00
			Not in conjunction with 601A/772/776/811A/824A/L5C/P29/P31/U26	*	
			Not in conjunction with 645	*	
			Not in conjunction with 978	*	
			Not in conjunction with P55/U50	*	
			Not in conjunction with R06		
			i.V.m. Code P23	●	157,50
	R38	45.7 cm (18-inch) 5-twin-spoke light-alloy wheels		●	735,00
				–	0,00
			Not in conjunction with 4R3/844		
			Not in conjunction with 601A/776/811A/824A/L5C/P23/P29/R03/R06/U26	*	
			Not in conjunction with 651/652		
			Not in conjunction with 772	*	
			Not in conjunction with 978	*	
			Not in conjunction with P31		
			Only in conjunction with P15	*	
	R48	43.2 cm (17-inch) 5-twin-spoke light-alloy wheels		●	210,00
			Not in conjunction with 601A/811A/824A/L5C/P23/P29/R03/U26/U29	*	
			Not in conjunction with 772	*	
			Not in conjunction with 978	*	
			Not in conjunction with P31		
			Not in conjunction with R06	*	
			Only in conjunction with P15	*	
	R97	48.3 cm (19") 10-spoke light-alloy wheels		●	997,50
				–	840,00
			Not in conjunction with 601A/772/811A/824A/L5C/P29/P31/P55/R03/U26/U50	*	
			Not in conjunction with 645	*	
			Not in conjunction with 978	*	
			Not in conjunction with R06	*	
			Only in conjunction with R01	*	
			i.V.m. Code P15	●	1.732,50
			i.V.m. Code P23	●	997,50
	B51	TIREFIT		●	52,50
			Not in conjunction with 978	*	
			Not in conjunction with R05		
			Not in conjunction with R06		
			Not in conjunction with R66	*	
			Not in conjunction with RVQ/RVR	*	
			i.V.m. Code PYA	○	0,00
	1R7	Complete set of 4 M+S winter wheels		●	1.837,50
			Not in conjunction with 4R3/844		
			Not in conjunction with 601A/772/811A/824A/L5C/P29/P31/RRD/U26		
			Not in conjunction with 645/U29	*	
	3R6	Complete set of 4 M+S winter wheels		●	2.992,50
	4R3	Complete set of 4 M+S winter wheels		–	2.520,00
			Not in conjunction with 01R/413/432/436/550/553/645/PBR/R38/RVQ/RVR		
			Not in conjunction with 1R7		
			Not in conjunction with R66		
			Only in conjunction with 844		
	4R6	Complete set of 4 M+S winter wheels		–	2.625,00
			Not in conjunction with 645		
	4R7	Complete set of 4 M+S winter wheels		●	2.362,50
	9R2	Complete set of 4 M+S winter wheels		–	3.675,00
	9R3	Complete set of 4 M+S winter wheels		–	3.675,00
	249	interior mirror and driver's exterior mirror automaticall		○	0,00
			Available only as part of (P49)	*	
			Only in conjunction with P49	*	

	313	Roller sunblinds in left and right rear doors		○	0,00
			Available only as part of (P09)	*	
			Not in conjunction with 840	*	
			Only in conjunction with P09	*	
	500	Electrically folding exterior mirrors		○	0,00
			Available only as part of (P49)	*	
			Only in conjunction with P49	*	
	540	Electric sunblind for rear window		●	404,25
			Not in conjunction with 840	*	
			i.V.m. Code P09	○	0,00
	840	Heat-insulating dark-tinted glass		●	409,50
			Not in conjunction with 540/61U/65U/P09	*	
			Not in conjunction with PAF/U50	*	
			i.V.m. Code P55/P60	○	0,00
			i.V.m. Code P55	-	0,00
			i.V.m. Code PYC/PYG/PYH	○	0,00
	875	Heated windscreen washer system		●	178,50
			i.V.m. Code P10	○	0,00
	P09	Sun Protection package		●	588,00
				-	388,50
			Includes codes 313+540+543	*	
			Includes codes 313+543		
			Not in conjunction with 840	*	
	P49	Mirror package		●	577,50
				-	0,00
			Includes codes 249+500	*	
			i.V.m. Code PBA/PBB/PBC	○	0,00
			i.V.m. Code PYM/PYN/PYO	○	0,00
	PAF	Acoustic Comfort package		●	1.039,50
			Includes codes 596	*	
			Not in conjunction with 840	*	
	U50	Omission of heat-insulating dark-tinted glass		○	0,00
			Not in conjunction with 001A/101A/P75		
			Not in conjunction with 01R/22R/R11/R97/RRD/RVQ/RZI		
			Not in conjunction with 15R		
			Not in conjunction with 341/342		
			Not in conjunction with 645		
			Not in conjunction with 725		
			Not in conjunction with 840	*	
			Not in conjunction with P23	*	
			Not in conjunction with RSJ		
			Only in conjunction with P55	*	
			Only in conjunction with P60		
			Only in conjunction with [52R/61R/R10/R38/R48/RSW/RVR]	*	
			Only in conjunction with [52R/61R/R10/R38/RSW/RVR]		
			Only in conjunction with [R32/RSK/RSW]		
	U82	2 USB ports in the rear		●	47,25
			i.V.m. Code PYA	○	0,00
	01U	Preinstallation for Navigation Services		○	0,00
			Only in conjunction with 365+PBF	*	
	355	Extended MBUX functions		○	0,00
	365	Hard-disc navigation		●	577,50
			i.V.m. Code PBF	○	0,00
	367	Preinstallation for Live Traffic Information		○	0,00
	PBF	Navigation Connectivity package		●	682,50
			Includes codes 362	*	
			Only in conjunction with 01U+365	*	
			i.V.m. Code PYA	○	0,00
	537	Digital radio		○	0,00
	79B	Preinstallation for digital radio		○	0,00
	810	Burmester® surround sound system		●	971,25
			Not in conjunction with 001A/101A/P75		
			Not in conjunction with 05Z/06Z/356		
			Not in conjunction with 10Z/11Z/12Z/Z90	*	
			Not in conjunction with 24Z	*	
			Not in conjunction with 336		
			Not in conjunction with 50Z/B12	*	

			Not in conjunction with 962/Z30	*	
			Not in conjunction with 970/974/975	*	
			Not in conjunction with Z87	*	
			Only in conjunction with [965/B63]		
			i.V.m. Code PYO	○	0,00
	14U	Smartphone Integration		●	420,00
			Only in conjunction with 16U+17U	*	
	897	Wireless charging system for mobile devices in the front		●	210,00
			Not in conjunction with 274	*	
			Not in conjunction with 301/899	*	
			Not in conjunction with 333	*	
			Not in conjunction with Z30	*	
			i.V.m. Code PBC	○	0,00
			i.V.m. Code PYB	○	0,00
	899	Multifunction telephony		●	514,50
			Not in conjunction with 301/897	*	
			Not in conjunction with 333	*	
			Not in conjunction with Z30	*	
			Only in conjunction with 274	*	
			i.V.m. Code PBC	●	304,50
			i.V.m. Code PYB	●	304,50
	21U	Dash cam		●	210,00
	543	Pull-out sun visor		●	99,75
			Available only as part of (P09)	*	
			Not in conjunction with 840	*	
			Only in conjunction with P09	*	
			i.V.m. Code P09	○	0,00
	730	Centre console in light brown open-pore ash wood		●	157,50
			Not in conjunction with 001A/101A/P75	*	
			Not in conjunction with 656/728/736/737/764/784/H06/H16/H29/H32/H41/H64/H78	*	
			Not in conjunction with 732/H73	*	
			Not in conjunction with H56	*	
			Not in conjunction with L2D	*	
			Only in conjunction with H09	*	
			i.V.m. Code PYC/PYE/PYG/PYH	●	52,50
			i.V.m. Code PYF	○	0,00
	U09	Dashboard and door beltlines in ARTICO man-made leather		●	630,00
				-	0,00
			Not in conjunction with 001A/101A/P75	*	
			Not in conjunction with H56	*	
			Not in conjunction with U38	*	
			i.V.m. Code P22/P29/P86	○	0,00
	U17	Omission of coloured seat belts		-	0,00
			Not in conjunction with Y04		
			Not in conjunction with Y05		
	U38	Dashboard and door beltlines in nappa leather		-	997,50
				○	0,00
			Not in conjunction with PBX/U09		
			i.V.m. Code PYC	-	0,00
	Y04	Seat belts in crystal grey		-	0,00
			Not in conjunction with U17		
			Only in conjunction with 561A+U38		
	Y05	Red seat belts		-	0,00
			Not in conjunction with 65U/U17		
			Only in conjunction with [621A/898A]		
	228	Auxiliary heater		●	1.438,50
			Only in conjunction with 875		
			Only in conjunction with 916	*	
			Only for left hand drive	*	
			i.V.m. Code 362	●	1.281,00
	443	Steering wheel heating		●	273,00
			Not in conjunction with 001A/101A/P75	*	
			Not in conjunction with H56	*	
			Not in conjunction with P65	*	
			Not in conjunction with PBX		
			Only in conjunction with 275	*	
			Only in conjunction with P49	*	

			Only in conjunction with U22	*	
580	THERMATIC automatic climate control			S	0,00
			Not in conjunction with 581	*	
			Not in conjunction with 670		
581	THERMOTRONIC automatic climate control			●	892,50
			Not in conjunction with 580	*	
			Only in conjunction with 670	*	
P21	AIR-BALANCE package			●	351,75
			Not in conjunction with 001A/ 101A/P75	*	
			Not in conjunction with 334	*	
			Not in conjunction with H56	*	
			i.V.m. Code PBP/PBR	○	0,00
P68	Warmth Comfort package			●	829,50
				-	451,50
			Includes codes 902+906	*	
			Not in conjunction with 001A/ 101A/P75	*	
			Not in conjunction with 555/621A/PBX		
			Not in conjunction with 873/P65	*	
			Not in conjunction with H56	*	
			Not in conjunction with PBZ		
			Only in conjunction with 275	*	
			Only in conjunction with P49	*	
			Only in conjunction with U22	*	
			i.V.m. Code PBP	●	451,50
			i.V.m. Code PYN/PYO	●	451,50
			i.V.m. Code PBR	○	0,00
844	folding bench seat in load compartment			-	1.312,50
			Not in conjunction with 01R/413/432/436/550/553/PBR/R38/RVR		
			Not in conjunction with 1R7		
890	EASY-PACK tailgate			-	0,00
E69	EASY-PACK boot box			●	231,00
U35	Socket			-	0,00
656	Centre console in high-gloss brown ash wood			●	157,50
			Not in conjunction with 001A/ 101A/P75	*	
			Not in conjunction with 728/730/736/737/764/784/H09/H16/H29/H32/H41/H64/H78	*	
			Not in conjunction with 732/H73	*	
			Not in conjunction with H56	*	
			Not in conjunction with L2D	*	
			Only in conjunction with H06	*	
			i.V.m.Code PYC/PYE/PYF/PYG/PYH	●	52,50
728	Centre console in black piano-lacquer look			○	0,00
			Not in conjunction with 656/730/737/764/784	*	
			Not in conjunction with 732/H73	*	
732	AMG carbon-fibre centre console			●	997,50
			Not in conjunction with 001A/101A/H56/P75	*	
			Not in conjunction with 656/728/730/736/737/764/784/H06/H09/H16/H29/H32/H64/H78	*	
			Only in conjunction with 891	*	
			i.V.m.Code PYC/PYE/PYF/PYG/PYH	●	840,00
			i.V.m. Code H73	○	0,00
737	Centre console in black open-pored ash wood			●	157,50
			Not in conjunction with 001A/ 101A/P75	*	
			Not in conjunction with 656/728/730/764/784/H06/H09/H16/H29/H32/H64	*	
			Not in conjunction with 732/H73	*	
			Not in conjunction with H56	*	
			i.V.m. Code PYF	●	52,50
			i.V.m. Code PYC/PYE/PYG/PYH	○	0,00
			i.V.m. Code PYJ	-	0,00
764	Centre console in grey open-pore ash wood			●	157,50
			Not in conjunction with 001A/ 101A/P75	*	
			Not in conjunction with 656/728/730/736/737/784/H06/H09/H16/H29/H41/H64/H78	*	
			Not in conjunction with 732/H73	*	
			Not in conjunction with H56	*	
			Not in conjunction with L2D	*	
			Only in conjunction with H32	*	
			i.V.m.Code PYC/PYE/PYF/PYG/PYH	●	52,50
784	Centre console in high-gloss burr walnut wood			●	157,50
			Not in conjunction with 001A/101A/P75	*	

			Not in conjunction with 656/728/730/736/737/764/H06/H09/H16/H32/H41/H78	*	
			Not in conjunction with 732/H73	*	
			Not in conjunction with H56	*	
			Only in conjunction with H29	*	
			i.V.m.Code PYC/PYE/PYF/PYG/PYH	●	52,50
	PBP	ENERGIZING package		●	939,75
				-	561,75
			Includes codes 355+873 [401/902]+891+P21	*	
			Not in conjunction with 001A/101A/P75	*	
			Not in conjunction with 334	*	
			Not in conjunction with 548/PBR	*	
			Not in conjunction with H56	*	
			Only in conjunction with 549	*	
			Only in conjunction with 868	*	
	PBR	ENERGIZING package Plus		●	4.593,75
				-	4.215,75
			Includes codes 355+401+891+P21+P68	*	
			Not in conjunction with 121A/124A/125A/128A/131A/134A/301A		
			Not in conjunction with 334	*	
			Not in conjunction with 4R3/844		
			Not in conjunction with 548/873/P65/PBP	*	
			Not in conjunction with 555/621A/PBX		
			Not in conjunction with 651/652		
			Not in conjunction with H56	*	
			Not in conjunction with P75	*	
			Not in conjunction with PBZ		
			Only in conjunction with 275+432+549+902+906	*	
			Only in conjunction with 436	*	
			Only in conjunction with 868+P49	*	
			Only in conjunction with U22	*	
			Only in conjunction with [201A/208A/214A/215A/801A/804A/805A]	*	
	U12	Velour floor mats		○	0,00
			Not in conjunction with 450	*	
			Not in conjunction with 601A/811A/824A/L5C	*	
			Not in conjunction with 837	*	
			Not in conjunction with P29/U26	*	
	U25	AMG door sill panels with »AMG« lettering, illuminated		-	178,50
			i.V.m. Code PYJ	-	0,00
			i.V.m.Code PYC/PYE/PYF/PYG/PYH	-	0,00
	U25	Illuminated door sill panels with "Mercedes-Benz" lettering		●	178,50
			i.V.m. Code PYJ	-	0,00
			i.V.m.Code PYC/PYE/PYF/PYG/PYH	○	0,00
	U26	AMG floor mats		○	0,00
			Not in conjunction with 01R/52R/61R/R38		
			Not in conjunction with 1R7		
			Not in conjunction with 248	*	
			Not in conjunction with 450	*	
			Not in conjunction with 55U/65U/88U/H56/L2B/P23	*	
			Not in conjunction with 651/652		
			Not in conjunction with R11/R48		
			Not in conjunction with R32		
			Not in conjunction with R97		
			Not in conjunction with U12	*	
			Only in conjunction with 772+7U0+876+P29	*	
			Only in conjunction with P31	*	
			Only in conjunction with [201A/601A/811A/824A]	*	
			Only in conjunction with [22R/R10/RRD/RSW/RVQ/RVR/RZl]	*	
	256	AMG Track Pace		-	262,50
				-	0,00
			Not in conjunction with 548		
			Only in conjunction with 365+549		
	463	Head-up Display		●	1.102,50
			i.V.m. Code PBC	○	0,00
	868	Widescreen cockpit		●	787,50
				-	0,00
			i.V.m. Code PYM/PYN/PYO	○	0,00
			i.V.m. S-Code 108	○	0,00

	U19	MBUX augmented reality for navigation		●	409,50
			Not in conjunction with 548	*	
			Only in conjunction with 365+549	*	
			Only in conjunction with 868	*	
	891	Ambient lighting		○	0,00
			Not in conjunction with 001A/101A/P75	*	
			Not in conjunction with H56	*	
	H16	MANUFATUR piano lacquer, black flowing lines		●	1.044,75
			Not in conjunction with 001A/101A/P75	*	
			Not in conjunction with 656/730/736/737/764/784/H06/H09/H29/H32/H41/H64/H78	*	
			Not in conjunction with 732/H73	*	
			Not in conjunction with H56	*	
			Only in conjunction with 728	*	
			i.V.m. Code PYC/PYH	●	792,75
	51U	Roof liner in black fabric		●	367,50
				-	0,00
			Not in conjunction with 128A/208A/55U/805A/88U	*	
			Not in conjunction with 336	*	
			Not in conjunction with 61U/65U	*	
			i.V.m. Code 601A	○	0,00
			i.V.m. Code 621A/811A	○	0,00
			i.V.m. Code 824A	○	0,00
			i.V.m. Code 830+(5/6/8*A)	○	0,00
			i.V.m. Code P29	○	0,00
	55U	Roof liner in macchiato beige fabric		○	0,00
			Not in conjunction with 121A/128A/131A/201A/208A/301A/801A		
			Not in conjunction with 248	*	
			Not in conjunction with 336	*	
			Not in conjunction with 51U/61U/65U/88U	*	
			Not in conjunction with H56/L5C/P29/U26	*	
			Not in conjunction with P75	*	
			Only in conjunction with [124A/125A/134A/201A/214A/215A/804A/805A]	*	
			Only in conjunction with [124A/125A/134A/214A/215A/804A/805A]		
	61U	MANUFATUR roof liner in black DINAMICA microfibre		●	1.680,00
			Not in conjunction with 001A/101A/124A/125A/128A/208A/214A/215A/301A		
			Not in conjunction with 248	*	
			Not in conjunction with 336	*	
			Not in conjunction with 450	*	
			Not in conjunction with 51U/65U	*	
			Not in conjunction with 55U/88U	*	
			Not in conjunction with 840	*	
			Not in conjunction with H56	*	
			Not in conjunction with P14	*	
			Not in conjunction with P75	*	
			Not in conjunction with PBX		
			Only in conjunction with 540	*	
			Only in conjunction with P22		
			Only in conjunction with [131A/134A/201A/601A/801A/804A/805A/811A/824A]	*	
			Only in conjunction with [131A/134A/801A/804A/805A]		
	65U	MANUFATUR roof liner in macchiato beige DINAMICA		●	1.680,00
			Not in conjunction with 248	*	
			Not in conjunction with 336	*	
			Not in conjunction with 450	*	
			Not in conjunction with 51U/61U	*	
			Not in conjunction with 55U/88U	*	
			Not in conjunction with 588A		
			Not in conjunction with 840	*	
			Not in conjunction with 898A/PBX/Y05		
			Not in conjunction with H56/L5C/P29/U26	*	
			Not in conjunction with P14		
			Not in conjunction with P75	*	
			Only in conjunction with 540	*	
			Only in conjunction with P22	*	
			Only in conjunction with U12		
			Only in conjunction with [134A/201A/804A/805A]	*	
			Only in conjunction with [134A/804A/805A]		
	88U	Roof liner in neva grey fabric		○	0,00

		Not in conjunction with 51U/55U/61U/65U	*	
		Not in conjunction with 601A/811A/824A/L5C/P29/U26	*	
P65	Seat Comfort package		○	0,00
		Includes codes U22	*	
		Not in conjunction with 275/432/443/902/P68/PBR	*	
		Not in conjunction with 436/L2D	*	
		Not in conjunction with E67/E68/E83/E84	*	
		Not in conjunction with PBZ		
		i.V.m. Code P75	●	241,50
275	Memory package		●	1.071,00
		Not in conjunction with 001A/101A/P75	*	
		Not in conjunction with H56	*	
		Not in conjunction with P65	*	
		Not in conjunction with PBX		
		Only in conjunction with P49	*	
		Only in conjunction with U22	*	
		i.V.m. Code PBZ	-	0,00
401	Climatised front seats		●	1.155,00
			-	777,00
		Not in conjunction with 121A/124A/125A/128A/131A/134A/301A		
		Not in conjunction with 621A/PBX		
		Not in conjunction with 873	*	
		Not in conjunction with H56	*	
		Not in conjunction with P75	*	
		Only in conjunction with [201A/208A/214A/215A/801A/804A/805A]	*	
		i.V.m. Code P10	●	777,00
		i.V.m. Code P68/432	●	777,00
		i.V.m. Code PBP	●	777,00
		i.V.m. Code PYM/PYN/PYO	●	777,00
		i.V.m. Code PBR	○	0,00
432	Active Multicontour Seat package		●	2.047,50
		Not in conjunction with 001A/101A/P75	*	
		Not in conjunction with 4R3/844		
		Not in conjunction with 555/621A/PBX		
		Not in conjunction with 651/652		
		Not in conjunction with 873/P65	*	
		Not in conjunction with H56	*	
		Not in conjunction with PBZ		
		Only in conjunction with 275+902	*	
		Only in conjunction with 401		
		Only in conjunction with 436	*	
		Only in conjunction with P49	*	
		Only in conjunction with U22	*	
		i.V.m. Code PBP	●	1.669,50
		i.V.m. Code PYN/PYO	●	1.669,50
		i.V.m. Code PBR	○	0,00
436	Comfort front head restraints		○	0,00
		Not in conjunction with 001A/101A/P75	*	
		Not in conjunction with 4R3/844		
		Not in conjunction with 651/652		
		Not in conjunction with 873/P65	*	
		Not in conjunction with H56	*	
		Only in conjunction with 275+432+902+P49	*	
		Only in conjunction with U22	*	
873	Heated front seats		●	378,00
			-	0,00
		Not in conjunction with 401/432/902/P68/PBR	*	
		Not in conjunction with 436	*	
		i.V.m. Code P10	○	0,00
		i.V.m. Code PBR/PBP	○	0,00
		i.V.m. Code PYM/PYN/PYO	○	0,00
902	Seat heating Plus for driver and front passenger seats		○	0,00
		Not in conjunction with 001A/101A/P75	*	
		Not in conjunction with 555/621A/PBX		
		Not in conjunction with 873/P65	*	
		Not in conjunction with H56	*	
		Not in conjunction with PBZ		

		Only in conjunction with 275	*	
		Only in conjunction with P49	*	
		Only in conjunction with U22	*	
U10	Automatic front passenger airbag deactivation		○	0,00
U22	4-way lumbar support		○	0,00
287	Folding rear seat backrests		●	456,75
			-	0,00
		i.V.m. Code PYB	○	0,00
872	Heated rear seats		●	378,00
		Not in conjunction with 001A/101A/601A		
		Not in conjunction with 121A		
		Not in conjunction with 124A/125A/128A/131A/134A/301A		
		Not in conjunction with 248	*	
		Only in conjunction with [201A/208A/214A/215A/801A/804A/805A/811A/824A]	*	
		Only in conjunction with [201A/208A/214A/215A/801A/804A/805A]		
446	Touchpad without Controller		○	0,00
		Not in conjunction with 448	*	
448	Touchpad with Controller		●	63,00
		Not in conjunction with 446/778	*	
77B	MBUX Interior Assistant		●	315,00
		Not in conjunction with 336	*	
		Not in conjunction with 337	*	
		Not in conjunction with 448	*	
		Only in conjunction with 446	*	
L2B	Multifunction steering wheel in nappa leather		○	0,00
		Not in conjunction with 601A/811A/824A/P29/U26	*	
		Not in conjunction with L2D		
L2D	Multifunction steering wheel in wood/leather		●	619,50
		Not in conjunction with 001A/101A/P75	*	
		Not in conjunction with 656/730/736/764/H06/H09/H32/H41/H78/P65	*	
		Not in conjunction with H56/H73	*	
		Not in conjunction with L2B		
		Only in conjunction with 275+443+P49	*	
		Only in conjunction with U22	*	
L5C	Multifunction sports steering wheel in nappa leather		○	0,00
		Not in conjunction with 01R/52R/61R/R38		
		Not in conjunction with 1R7		
		Not in conjunction with 248	*	
		Not in conjunction with 450	*	
		Not in conjunction with 55U/65U/88U/H56/P23/P75	*	
		Not in conjunction with 651/652		
		Not in conjunction with 837		
		Not in conjunction with P14/P22	*	
		Not in conjunction with R11/R48		
		Not in conjunction with R32		
		Not in conjunction with R97		
		Not in conjunction with U12	*	
		Only in conjunction with 772+U26+7U0+876	*	
		Only in conjunction with P29+P31	*	
		Only in conjunction with [201A/601A/811A/824A]	*	
		Only in conjunction with [22R/R10/RRD/RSW/RVQ/RVR/RZl]	*	
301	Ashtray inserts at front and rear in the stowage compartment		●	47,25
		Not in conjunction with 274	*	
		Not in conjunction with 333	*	
		Not in conjunction with 336	*	
		Not in conjunction with 897/899	*	
30P	Stowage facility package		○	0,00
		Includes codes 309	*	
736	Open-pore black ash wood trim		●	252,00
		Not in conjunction with 001A/101A/P75	*	
		Not in conjunction with 656/730/764/784/H06/H09/H16/H29/H32/H41/H64/H78	*	
		Not in conjunction with 732/H73	*	
		Not in conjunction with H56	*	
		Not in conjunction with L2D	*	
		i.V.m. Code P22	●	199,50
		i.V.m. Code PYC/PYH	○	0,00
H06	brown high-gloss ash wood trim		●	252,00



			Not in conjunction with 001A/101A/P75	*	
			Not in conjunction with 730/736/737/764/784/H09/H16/H29/H32/H41/H64/H78	*	
			Not in conjunction with 732/H73	*	
			Not in conjunction with H56	*	
			Not in conjunction with L2D	*	
			i.V.m. Code P22	●	199,50
			i.V.m. Code PYC/PYH	●	52,50
H09	Open-pore light brown ash wood trim			●	252,00
			Not in conjunction with 001A/101A/P75	*	
			Not in conjunction with 656/736/737/764/784/H06/H16/H29/H32/H41/H64/H78	*	
			Not in conjunction with 732/H73	*	
			Not in conjunction with H56	*	
			Not in conjunction with L2D	*	
			i.V.m. Code PYC/PYH	●	52,50
			i.V.m. Code P22	○	0,00
			i.V.m. Code PYF	○	0,00
H29	High-gloss brown burr walnut wood trim			●	252,00
			Not in conjunction with 001A/101A/P75	*	
			Not in conjunction with 656/730/736/737/764/H06/H09/H16/H32/H41/H78	*	
			Not in conjunction with 732/H73	*	
			Not in conjunction with H56	*	
			i.V.m. Code P22	●	199,50
			i.V.m. Code PYC/PYH	●	52,50
H32	Grey open-pore ash wood trim			●	252,00
			Not in conjunction with 001A/101A/P75	*	
			Not in conjunction with 656/730/736/737/784/H06/H09/H16/H29/H41/H64/H78	*	
			Not in conjunction with 732/H73	*	
			Not in conjunction with H56	*	
			Not in conjunction with L2D	*	
			i.V.m. Code P22	●	199,50
			i.V.m. Code PYC/PYH	●	52,50
H41	Light longitudinal-grain aluminium trim			●	357,00
				—	0,00
			Not in conjunction with 656/730/736/764/784/H06/H09/H16/H29/H32/H64/H78	*	
			Not in conjunction with H56	*	
			Not in conjunction with H73	*	
			Not in conjunction with L2D	*	
			Not in conjunction with P22		
			i.V.m. Code PYC/PYH/PYF	●	52,50
			i.V.m S-Code PVG	○	0,00
			i.V.m. Code P14/P29	○	0,00
			i.V.m. Code P22	○	0,00
			i.V.m. Code PYE/PYG/PYJ	○	0,00
			i.V.m. Code PYE/PYG	—	0,00
H56	Silver special-effect paint trim			○	0,00
			Not in conjunction with 23U/275/401/432/436/443/55U/61U/656/65U/730/732/736/737/764/784/876/	*	
			Not in conjunction with 292		
			Not in conjunction with 52R/61R/RRD/RSW/RZI	*	
			Not in conjunction with 772	*	
			Not in conjunction with 776		
			Not in conjunction with E67/E68/E83/E84	*	
			Not in conjunction with P31		
			Not in conjunction with U47	*	
			Only in conjunction with L2B+P15+P75	*	
			Only in conjunction with R32		
			Only in conjunction with [001A/101A]+728+7U0	*	
			Only in conjunction with [22R/R32/R97]		
H73	AMG carbon-fibre trim			●	3.097,50
			Not in conjunction with 001A/101A/H56/L2D/P75	*	
			Not in conjunction with 656/728/730/736/737/764/784/H06/H09/H16/H29/H32/H41/H64/H78	*	
			Only in conjunction with 732	*	
			Only in conjunction with 891	*	
			i.V.m. Code PYC/PYH	●	2.845,50
H78	Light carbon-grain aluminium trim			●	357,00
				—	0,00
			Not in conjunction with 001A/101A/P75	*	
			Not in conjunction with 656/730/736/764/784/H06/H09/H16/H29/H32/H41/H64	*	

			Not in conjunction with 732/H73	*	
			Not in conjunction with H56	*	
			Not in conjunction with L2D	*	
			i.V.m. Code PYC/PYF/PYH	●	52,50
			i.V.m. Code PYE/PYG	○	0,00
	554A	nut brown / black		-	283,50
			Only in conjunction with U38		
			i.V.m. Code PBZ	-	0,00
	555A	macchiato beige / black		-	283,50
			Only in conjunction with U38		
			i.V.m. Code PBZ	-	0,00
	561A	black		-	0,00
			Only in conjunction with U38		
	861A	black		-	2.383,50
			Not in conjunction with PBX/Y05		
			Only in conjunction with U17		
			i.V.m. Code PBZ	-	0,00
	864A	nut brown / black		-	2.593,50
			Not in conjunction with PBX/Y05		
			Only in conjunction with U17		
			i.V.m. Code PBZ	-	0,00
	865A	macchiato beige / black		-	2.593,50
			Not in conjunction with PBX/Y05		
			Only in conjunction with U17		
			i.V.m. Code PBZ	-	0,00
	898A	titanium grey pearl / black		-	2.593,50
			Not in conjunction with 65U/PBX		
			i.V.m. Code PBZ	-	0,00
	134A	nut brown / black		●	210,00
			Not in conjunction with 248	*	
			Not in conjunction with 336	*	
			Not in conjunction with 401/872/PBR	*	
			Not in conjunction with 450	*	
			Not in conjunction with H56/L5C/P29/U26	*	
			Not in conjunction with P14		
			Not in conjunction with P75	*	
			Only in conjunction with 876	*	
			Only in conjunction with P22	*	
			Only in conjunction with U12		
	601A	black		○	0,00
			Not in conjunction with 01R/52R/61R/R38		
			Not in conjunction with 1R7		
			Not in conjunction with 248	*	
			Not in conjunction with 336	*	
			Not in conjunction with 401/55U/65U/872/88U/H56/L2B/P23/P75/PBR	*	
			Not in conjunction with 450	*	
			Not in conjunction with 651/652		
			Not in conjunction with 837		
			Not in conjunction with P14/P22	*	
			Not in conjunction with R11/R48		
			Not in conjunction with R32		
			Not in conjunction with R97		
			Not in conjunction with U12	*	
			Only in conjunction with 772+U26+7U0+876	*	
			Only in conjunction with P29+P31	*	
			Only in conjunction with [22R/R10/RRD/RSW/RVQ/RVR/RZl]	*	
	621A	black		-	0,00
			Not in conjunction with 401/432/902/P68/PBR/PBZ		
			Only in conjunction with 873		
	101A	black		●	525,00
			Not in conjunction with 23U/275/401/432/436/443/55U/61U/656/65U/730/736/737/764/784/872/876/	*	
			Not in conjunction with 292		
			Not in conjunction with 333/337/341/342/344/413/414/720/810/837/934/938/965/974/975/L2D/P55/RTG/L		
			Not in conjunction with 52R/61R/RRD/RSW/RZl	*	
			Not in conjunction with 732/H73/P23/P29/U26	*	
			Not in conjunction with 772	*	
			Not in conjunction with 776		

			Not in conjunction with E67/E68/E83/E84	*	
			Not in conjunction with P31		
			Not in conjunction with U47	*	
			Only in conjunction with 30P+725+873+970+P65+U12+Z90		
			Only in conjunction with 7U0	*	
			Only in conjunction with L2B	*	
			Only in conjunction with P15	*	
			Only in conjunction with P75	*	
			Only in conjunction with R32		
			Only in conjunction with [22R/R32/R97]		
			<b>i.V.m. Code 450</b>	<b>LS</b>	<b>0,00</b>
	<b>301A</b>	<b>black</b>		○	<b>0,00</b>
			Available only as part of (P14)		
			Not in conjunction with 248	*	
			Not in conjunction with 401/55U/61U/65U/872/PBR	*	
			Not in conjunction with 450	*	
			Not in conjunction with H56/L5C/P29/U26	*	
			Not in conjunction with P22		
			Not in conjunction with P75	*	
			Only in conjunction with 7U0+P15		
			Only in conjunction with P14	*	
			Only in conjunction with U12		
	<b>131A</b>	<b>black</b>		○	<b>0,00</b>
			Not in conjunction with 248	*	
			Not in conjunction with 401/55U/65U/872/PBR	*	
			Not in conjunction with 450	*	
			Not in conjunction with H56/L5C/P29/U26	*	
			Not in conjunction with P14		
			Not in conjunction with P75	*	
			Only in conjunction with 876	*	
			Only in conjunction with P22	*	
			Only in conjunction with U12		
	<b>588A</b>	<b>titanium grey pearl / black</b>		—	<b>283,50</b>
			Not in conjunction with 65U		
			Only in conjunction with U38		
			<b>i.V.m. Code PBZ</b>	—	<b>0,00</b>
	<b>201A</b>	<b>black</b>		●	<b>1.890,00</b>
			Not in conjunction with 248	*	
			Not in conjunction with 55U/61U/65U		
			Not in conjunction with H56	*	
			Not in conjunction with P22	*	
			Not in conjunction with P75	*	
			Only in conjunction with 7U0+P15		
			Only in conjunction with P14		
	<b>208A</b>	<b>neva grey / magma grey</b>		●	<b>2.100,00</b>
			Not in conjunction with 248	*	
			Not in conjunction with 450	*	
			Not in conjunction with 51U/55U/61U/65U	*	
			Not in conjunction with H56/L5C/P29/U26	*	
			Not in conjunction with P22		
			Not in conjunction with P75	*	
			Only in conjunction with 7U0+P15		
			Only in conjunction with 88U	*	
			Only in conjunction with P14	*	
			Only in conjunction with U12		
	<b>214A</b>	<b>nut brown / black</b>		●	<b>2.100,00</b>
			Not in conjunction with 248	*	
			Not in conjunction with 336	*	
			Not in conjunction with 61U/65U	*	
			Not in conjunction with H56/L5C/P29/U26	*	
			Not in conjunction with P22		
			Not in conjunction with P75	*	
			Only in conjunction with 7U0+P15		
			Only in conjunction with P14	*	
	<b>215A</b>	<b>macchiato beige / black</b>		●	<b>2.100,00</b>
			Not in conjunction with 248	*	
			Not in conjunction with 336	*	

			Not in conjunction with 61U/65U	*	
			Not in conjunction with H56/L5C/P29/U26	*	
			Not in conjunction with P22		
			Not in conjunction with P75	*	
			Only in conjunction with 7U0+P15		
			Only in conjunction with P14	*	
	001A	black		○	0,00
			Not in conjunction with 23U/275/401/432/436/443/55U/61U/656/65U/730/736/737/764/784/872/876/	*	
			Not in conjunction with 248	*	
			Not in conjunction with 292		
			Not in conjunction with 333/337/341/342/344/413/414/720/810/837/934/938/965/974/975/L2D/P55/RTG/L		
			Not in conjunction with 450	*	
			Not in conjunction with 52R/61R/RRD/RSW/RZI	*	
			Not in conjunction with 732/H73/P23/P29/U26	*	
			Not in conjunction with 772	*	
			Not in conjunction with 776		
			Not in conjunction with E67/E68/E83/E84	*	
			Not in conjunction with P31		
			Not in conjunction with U47	*	
			Only in conjunction with 30P+725+873+970+P65+Z90		
			Only in conjunction with 7U0	*	
			Only in conjunction with L2B	*	
			Only in conjunction with P15	*	
			Only in conjunction with P75	*	
			Only in conjunction with R32		
			Only in conjunction with U12		
			Only in conjunction with [22R/R32/R97]		
	801A	black		●	2.383,50
			Not in conjunction with 248	*	
			Not in conjunction with 450	*	
			Not in conjunction with 55U/65U	*	
			Not in conjunction with H56/L5C/P29/U26	*	
			Not in conjunction with P14		
			Not in conjunction with P75	*	
			Only in conjunction with 876	*	
			Only in conjunction with P22	*	
			Only in conjunction with U12		
	804A	nut brown / black		●	2.593,50
			Not in conjunction with 248	*	
			Not in conjunction with 336	*	
			Not in conjunction with 450	*	
			Not in conjunction with H56/L5C/P29/U26	*	
			Not in conjunction with P14		
			Not in conjunction with P75	*	
			Only in conjunction with 876	*	
			Only in conjunction with P22	*	
			Only in conjunction with U12		
	805A	macchiato beige / magma grey		●	2.593,50
			Not in conjunction with 248	*	
			Not in conjunction with 336	*	
			Not in conjunction with 450	*	
			Not in conjunction with 51U	*	
			Not in conjunction with H56/L5C/P29/U26	*	
			Not in conjunction with P14		
			Not in conjunction with P75	*	
			Only in conjunction with 876	*	
			Only in conjunction with P22	*	
			Only in conjunction with U12		
	811A	black		●	2.383,50
			Not in conjunction with 01R/52R/61R/R38		
			Not in conjunction with 1R7		
			Not in conjunction with 248	*	
			Not in conjunction with 336	*	
			Not in conjunction with 401/55U/65U/88U/H56/L2B/P23/P75/PBR	*	
			Not in conjunction with 450	*	
			Not in conjunction with 651/652		
			Not in conjunction with 837		

		Not in conjunction with P14/P22	*	
		Not in conjunction with R11/R48		
		Not in conjunction with R32		
		Not in conjunction with R97		
		Not in conjunction with U12	*	
		Only in conjunction with 772+U26+7U0+876	*	
		Only in conjunction with P29+P31	*	
		Only in conjunction with [22R/R10/RRD/RSW/RVQ/RVR/RZI]	*	
824A	saddle brown / black		●	2.593,50
		Not in conjunction with 01R/52R/61R/R38		
		Not in conjunction with 1R7		
		Not in conjunction with 248	*	
		Not in conjunction with 336	*	
		Not in conjunction with 401/55U/65U/88U/H56/L2B/P23/P75/PBR	*	
		Not in conjunction with 450	*	
		Not in conjunction with 651/652		
		Not in conjunction with 837		
		Not in conjunction with P14/P22	*	
		Not in conjunction with R11/R48		
		Not in conjunction with R32		
		Not in conjunction with R97		
		Not in conjunction with U12	*	
		Only in conjunction with 772+U26+7U0+876	*	
		Only in conjunction with P29+P31	*	
		Only in conjunction with [22R/R10/RRD/RSW/RVQ/RVR/RZI]	*	
P14	AVANTGARDE interior		●	1.386,00
			-	0,00
		Includes codes 301A [201A/214A/215A]+876+891+H78 [736/H06/H09/H16/H64]		
		Includes codes 301A [201A/214A/215A]+876+891	*	
		Not in conjunction with 001A/101A		
		Not in conjunction with 131A/134A/801A/804A/805A		
		Not in conjunction with 248	*	
		Not in conjunction with 61U/65U	*	
		Not in conjunction with H56/L5C	*	
		Not in conjunction with P22		
		Only in conjunction with 7U0+P15		
		Only in conjunction with [121A/124A/125A/128A/201A/208A/214A/215A/301A]	*	
		Only in conjunction with [124A/125A/128A/201A/208A/214A/215A/301A]		
		i.V.m. Code PYE/PYG/PYJ	○	0,00
		i.V.m. Code PYE/PYG	-	0,00
P15	AVANTGARDE exterior		-	0,00
		Not in conjunction with 52R/61R/RRD/RSW/RZI		
		Not in conjunction with 601A/811A/B24A/L5C/P29/U26		
		Not in conjunction with 776		
		Only in conjunction with 7U0		
		Only in conjunction with R32		
P15	AVANTGARDE exterior		○	0,00
		Not in conjunction with 52R/61R/RRD/RSW/RZI	*	
		Not in conjunction with 601A/811A/B24A/L5C/P29/U26	*	
		Not in conjunction with 776		
		Not in conjunction with U47	*	
		Only in conjunction with 7U0	*	
		Only in conjunction with [22R/R32/R97]		
P22	EXCLUSIVE interior		●	2.289,00
			-	1.081,50
		Includes codes 891+H09 [736/H06/H09/H16/H64/H73]+U09	*	
		Includes codes 891+H78 [736/H06/H09/H16/H64]+U09		
		Includes codes 891+U09		
		Not in conjunction with 450	*	
		Not in conjunction with H41		
		Not in conjunction with H56/L5C	*	
		Not in conjunction with P14		
		Only in conjunction with 876	*	
		Only in conjunction with U12		
		Only in conjunction with [131A/134A/801A/804A/805A]	*	
		i.V.m. Code PYF	○	0,00
P23	EXCLUSIVE exterior		●	945,00

				-	210,00
			Not in conjunction with 001A/101A/601A/7U0/811A/824A/H56/L5C/P29/P55/P75/U26/U50	*	
			Not in conjunction with 01R/R10/R38/RRD/RSW/RZI		
			Not in conjunction with 720		
			Not in conjunction with 776		
			Not in conjunction with U47	*	
			Only in conjunction with 725		
			Only in conjunction with R32		
			Only in conjunction with [22R/52R/61R/R32/R97/RVQ/RVR]	*	
			Only in conjunction with [22R/52R/61R/R97/RVQ/RVR]		
			Only in conjunction with [22R/R32/R97]		
			i.V.m. Code PYF	○	0,00
P29	AMG Line interior			●	2.121,00
			Includes codes 601A [811A/824A]+891+H41 [736/H06/H09/H16/H64/H73]+L5C+U09+U26	*	
			Not in conjunction with 1R7		
			Not in conjunction with 248	*	
			Not in conjunction with 450	*	
			Not in conjunction with 55U/65U/88U/H56/L2B/P23	*	
			Not in conjunction with 651/652		
			Not in conjunction with R32		
			Not in conjunction with R97		
			Not in conjunction with U12	*	
			Only in conjunction with 772+7U0+876	*	
			Only in conjunction with P31	*	
			Only in conjunction with [201A/601A/811A/824A]	*	
			Only in conjunction with [R10/RRD/RSW/RVQ/RVR/RZI]	*	
			i.V.m. Code PYH	○	0,00
P31	AMG Line exterior			●	2.677,50
				-	2.205,00
			Includes codes 485 [489]+772		
			Includes codes 677 [482/485/489]+772	*	
			Includes codes 677 [485/489]+725 [720]+772		
			Includes codes 677 [485/489]+772		
			Includes codes 725 [720]+772		
			Includes codes 772		
			Not in conjunction with 001A/101A/H56/P75	*	
			Not in conjunction with 1R7		
			Not in conjunction with 651/652		
			Not in conjunction with R32		
			Not in conjunction with R97		
			Only in conjunction with 7U0	*	
			Only in conjunction with [R10/RRD/RSW/RVQ/RVR/RZI]	*	
			i.V.m. Code PYG/PYH/PYJ	○	0,00
			i.V.m. Code PYG/PYH	-	0,00
P75	Standard interior equipment and appointments			S	0,00
			Includes codes 001A [101A]+H56	*	
			Includes codes 001A [101A]		
			Not in conjunction with 23U/275/401/432/436/443/55U/61U/656/65U/730/736/737/764/784/876/883/	*	
			Not in conjunction with 292		
			Not in conjunction with 333/337/341/342/344/413/414/720/810/837/934/938/965/974/975/L2D/P55/RTG/U		
			Not in conjunction with 52R/61R/RRD/RSW/RZI	*	
			Not in conjunction with 732/H73/P23	*	
			Not in conjunction with 772	*	
			Not in conjunction with 776		
			Not in conjunction with E67/E68/E83/E84	*	
			Not in conjunction with P31		
			Not in conjunction with U47	*	
			Only in conjunction with 30P+725+873+970+P65+U12+Z90		
			Only in conjunction with 7U0	*	
			Only in conjunction with L2B	*	
			Only in conjunction with P15	*	
			Only in conjunction with R32		
			Only in conjunction with [001A/101A]	*	
			Only in conjunction with [22R/R32/R97]		
362	Communications module (LTE) for the use of Mercedes			○	0,00
00U	Remote Services			●	105,00
13U	Preinstallation for Remote and Navigation Services			-	0,00

	20U	Preinstallation for digital key transfer		●	52,50
			i.V.m. Code PYA	○	0,00
	33U	Remote Services Plus		●	157,50
			Not in conjunction with 34U	*	
			Not in conjunction with 38U		
			i.V.m. Code PYA	○	0,00
	34U	Remote Services Premium		●	262,50
			Not in conjunction with 33U	*	
	35 I	Mercedes-Benz emergency call system		○	0,00
	38U	Remote and Charging Services Plus		-	262,50
			Not in conjunction with 33U		
			Only in conjunction with 365		
			i.V.m. Code PYA	-	0,00
	000U	paintwork not yet finalised		○	0,00
			Only in conjunction with 524	*	
	00B	Owner's Manual and service information - Danish		○	0,00
			Not in conjunction with 01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/13B/14B/15B/16B/17B/30B/	*	
	01B	Owner's Manual and service information - Dutch		○	0,00
			Not in conjunction with 00B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/13B/14B/15B/16B/17B/30B/	*	
	02B	Owner's Manual and service information - German		○	0,00
			Not in conjunction with 00B/01B/03B/04B/05B/06B/07B/08B/09B/10B/11B/13B/14B/15B/16B/17B/30B/	*	
	03B	Owner's Manual and service information - Russian		○	0,00
			Not in conjunction with 00B/01B/02B/04B/05B/06B/07B/08B/09B/10B/11B/13B/14B/15B/16B/17B/30B/	*	
	04B	Owner's Manual and service information - Finnish		○	0,00
			Not in conjunction with 00B/01B/02B/03B/05B/06B/07B/08B/09B/10B/11B/13B/14B/15B/16B/17B/30B/	*	
	05B	Owner's Manual and Service Booklet - English		○	0,00
			Not in conjunction with 00B/01B/02B/03B/04B/06B/07B/08B/09B/10B/11B/13B/14B/15B/16B/17B/30B/	*	
	05Z	Run-on times MPM 4 hours		○	0,00
			Not in conjunction with 06Z	*	
			Not in conjunction with 413	*	
			Not in conjunction with 414/810		
			Not in conjunction with B63		
			Not in conjunction with Z97	*	
	06B	Owner's Manual and service information - Italian		○	0,00
			Not in conjunction with 00B/01B/02B/03B/04B/05B/07B/08B/09B/10B/11B/13B/14B/15B/16B/17B/30B/	*	
	06Z	Run-on times MPM w/o time limit		○	0,00
			Not in conjunction with 05Z	*	
			Not in conjunction with 413	*	
			Not in conjunction with 414/810		
			Not in conjunction with B63		
			Not in conjunction with Z97	*	
	07B	Owner's Manual and service information - French		○	0,00
			Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/08B/09B/10B/11B/13B/14B/15B/16B/17B/30B/	*	
	08B	Owner's Manual and service information - Spanish		○	0,00
			Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/09B/10B/11B/13B/14B/15B/16B/17B/30B/	*	
	09B	Owner's Manual and service information - Portuguese		○	0,00
			Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/10B/11B/13B/14B/15B/16B/17B/30B/	*	
	10B	Owner's Manual and service information - Swedish		○	0,00
			Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/11B/13B/14B/15B/16B/17B/30B/	*	
	10Z	High-beam flashing, daytime, for emergency vehicles		○	0,00
			Not in conjunction with 248	*	
			Not in conjunction with 333/337/341/342/344/934/938/965	*	
			Not in conjunction with 413/414/810	*	
			Not in conjunction with 450/623U	*	
			Not in conjunction with 837		
			Not in conjunction with B63		
			Not in conjunction with Z97	*	
			Only in conjunction with 30P	*	
			Only in conjunction with Z90	*	
	11B	Owner's Manual and service information - Arabic		○	0,00
			Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/13B/14B/15B/16B/17B/30B/	*	
	11Z	Dayt. run. lamps flashing, daytime, emerg. veh.		○	0,00
			Not in conjunction with 248	*	
			Not in conjunction with 333/337/341/342/344/934/938/965	*	
			Not in conjunction with 413/414/810	*	
			Not in conjunction with 450/623U	*	
			Not in conjunction with 837		

			Not in conjunction with B63		
			Not in conjunction with Z97	*	
			Only in conjunction with 30P	*	
			Only in conjunction with Z90	*	
	12 1A	black ARTICO man-made leather		●	262,50
				—	0,00
			Not in conjunction with 248	*	
			Not in conjunction with 401/55U/61U/65U/872/PBR	*	
			Not in conjunction with 450	*	
			Not in conjunction with H56/L5C/P29/U26	*	
			Not in conjunction with P22		
			Not in conjunction with P75	*	
			Only in conjunction with 7U0+P15		
			Only in conjunction with P14	*	
			Only in conjunction with U12		
	124A	ARTICO man-made leather hazelnut brown / black		●	472,50
				—	0,00
			Not in conjunction with 248	*	
			Not in conjunction with 336	*	
			Not in conjunction with 401/61U/65U/872/PBR	*	
			Not in conjunction with 450	*	
			Not in conjunction with H56/L5C/P29/U26	*	
			Not in conjunction with P22		
			Not in conjunction with P75	*	
			Only in conjunction with 7U0+P15		
			Only in conjunction with P14	*	
			Only in conjunction with U12		
	125A	ARTICO man-made leather macchiato beige / black		●	472,50
				—	0,00
			Not in conjunction with 248	*	
			Not in conjunction with 336	*	
			Not in conjunction with 401/61U/65U/872/PBR	*	
			Not in conjunction with 450	*	
			Not in conjunction with H56/L5C/P29/U26	*	
			Not in conjunction with P22		
			Not in conjunction with P75	*	
			Only in conjunction with 7U0+P15		
			Only in conjunction with P14	*	
			Only in conjunction with U12		
	128A	ARTICO man-made leather alpaca grey		●	472,50
			Not in conjunction with 248	*	
			Not in conjunction with 401/51U/55U/61U/65U/872/PBR	*	
			Not in conjunction with 450	*	
			Not in conjunction with H56/L5C/P29/U26	*	
			Not in conjunction with P22		
			Not in conjunction with P75	*	
			Only in conjunction with 7U0+P15		
			Only in conjunction with 88U	*	
			Only in conjunction with P14	*	
			Only in conjunction with U12		
	12B	Owner's Manual and service information - English USA/		○	0,00
	12U	Preinstallation for Concierge Service		●	105,00
	12Z	Dayt. run. lamps flashing, night-time, emerg. veh.		○	0,00
			Not in conjunction with 248	*	
			Not in conjunction with 333/337/341/342/344/934/938/965	*	
			Not in conjunction with 413/414/810	*	
			Not in conjunction with 450/623U	*	
			Not in conjunction with 837		
			Not in conjunction with B63		
			Not in conjunction with Z97	*	
			Only in conjunction with 30P	*	
			Only in conjunction with Z90	*	
	13B	Owner's Manual and service information - Norwegian		○	0,00
			Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/14B/15B/16B/17B/30B/	*	
	144A	ARTICO man-made leather hazelnut brown / espresso b		○	0,00
	145A	ARTICO man-made leather macchiato beige / espresso		○	0,00
	14B	Owner's Manual and service information - Greek		○	0,00



			Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/13B/15B/16B/17B/30B/	*	
	15B	Owner's Manual and service information - Turkish		○	0,00
			Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/13B/14B/16B/17B/30B/	*	
	15U	Pre-installation for Mercedes-Benz Link		S	0,00
	16B	Owner's Manual and service information - Polish		○	0,00
			Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/13B/14B/15B/17B/30B/	*	
	16U	Smartphone integration (Apple CarPlay™)		○	0,00
			Only in conjunction with 14U+17U	*	
	17B	Owner's Manual and service information - Czech		○	0,00
			Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/13B/14B/15B/16B/30B/	*	
	17U	Smartphone integration (Android Auto)		○	0,00
			Only in conjunction with 14U+16U	*	
	18B	Owner's Manual and service information - English South		○	0,00
	18U	Baidu Carlife		-	0,00
	233	DISTRONIC PLUS		○	0,00
			Not in conjunction with 22P/234/258	*	
			Only in conjunction with P49	*	
	23U	Active traffic-assist		○	0,00
			Not in conjunction with 001A/101A/P75	*	
			Not in conjunction with 22P/234/258	*	
			Not in conjunction with 23P	*	
			Not in conjunction with 555/PBX	*	
			Not in conjunction with H56	*	
			Not in conjunction with PBZ	*	
			Only in conjunction with 235+365+513+546+K33+K34	*	
			Only in conjunction with 292	*	
			Only in conjunction with P20	*	
			Only in conjunction with P49	*	
	248	Rear seats with integrated child seats		●	819,00
			Not in conjunction with 10Z/11Z/12Z/24Z/50Z/55U/61U/65U/872/962/970/974/975/B12/L5C/P14/P29/	*	
			Not in conjunction with 356	*	
			Not in conjunction with 413	*	
			Not in conjunction with 489	*	
			Not in conjunction with 978	*	
			Not in conjunction with R06	*	
			Not in conjunction with RVO/RVR	*	
			Not in conjunction with Z90	*	
			Not in conjunction with Z97	*	
			Only in conjunction with 101A	*	
			Only in conjunction with 965	*	
			Only for left hand drive	*	
			i.V.m. Code P10	○	0,00
	24Z	Pre-installation for TETRA mobile radio, Sepura		●	147,00
			Not in conjunction with 248	*	
			Not in conjunction with 337/344/938	*	
			Not in conjunction with 341/342/934/965	*	
			Not in conjunction with 413/414/810	*	
			Not in conjunction with 450	*	
			Not in conjunction with 837	*	
			Not in conjunction with B63	*	
			Not in conjunction with Z97	*	
			Only in conjunction with Z90	*	
			Only for left hand drive	*	
	251	Increase in top speed, USA		-	0,00
	25B	Owner's Manual and service information - Korean		○	0,00
	263	Number plate mounting for Asia / Mexico		○	0,00
	264	Number plate mounting for America		○	0,00
	26B	Owner's Manual and service information - Chinese Taiwan		○	0,00
	26U	Preinstallation for engine remote start		●	105,00
			i.V.m. S-Code PZG	●	52,50
	270	Aerial for GPS		○	0,00
	274	Telephone aerial		○	0,00
			Not in conjunction with 301/897	*	
			Not in conjunction with 333	*	
			Not in conjunction with Z30	*	
	309	Double cup holder		○	0,00
			Available only as part of (30P)	*	

		Not in conjunction with 333/938	*	
		Only in conjunction with 30P	*	
30B	Owner's Manual and service information - Slovenian		○	0,00
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/13B/14B/15B/16B/17B/	*	
31B	Owner's Manual and service information - Hungarian		○	0,00
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/13B/14B/15B/16B/17B/	*	
32B	Owner's Manual and service information - Bulgarian		○	0,00
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/13B/14B/15B/16B/17B/	*	
333	Special instrument panel		●	84,00
		Not in conjunction with 001A/101A/P75		
		Not in conjunction with 10Z/11Z/12Z/301/309/897/899/970/974/975	*	
		Not in conjunction with 274/356	*	
		Not in conjunction with 413	*	
		Not in conjunction with 489		
		Not in conjunction with 550/553		
		Not in conjunction with RVQ/RVR	*	
		Not in conjunction with Z87	*	
		Not in conjunction with Z90	*	
		Not in conjunction with Z97	*	
		Only in conjunction with 965		
		Only for left hand drive		
334	Preinstallation for two-way radio in glove compartment		●	94,50
		Not in conjunction with 335/P21/PBP/PBR	*	
		Not in conjunction with 413	*	
		Not in conjunction with B63		
		Not in conjunction with Z97	*	
		Only for left hand drive	*	
		i.V.m. Code 450	LS	0,00
		i.V.m. Code P10	○	0,00
335	Preinstallation for two-way radio in boot		●	94,50
		Not in conjunction with 334	*	
		Not in conjunction with 413	*	
		Not in conjunction with B63		
		Not in conjunction with Z97	*	
		Only for left hand drive	*	
		i.V.m. Code 450	○	0,00
		i.V.m. Code P10	○	0,00
336	Preinstallation for taximeter		●	57,75
		Not in conjunction with 124A/125A/134A/214A/215A/804A/805A		
		Not in conjunction with 301/51U/551/55U/61U/65U/77B/88Z/P54/P82	*	
		Not in conjunction with 413	*	
		Not in conjunction with 414/810		
		Not in conjunction with B63		
		Not in conjunction with Z97	*	
		Only in conjunction with [001A/101A/121A/128A/131A/201A/208A/301A/801A]	*	
		Only in conjunction with [001A/101A/128A/131A/201A/208A/301A/801A]		
		Only for left hand drive		
		i.V.m. Code 450	LS	0,00
		i.V.m. Code P10	○	0,00
337	Taximeter integrated in the rear-view mirror		●	1.039,50
		Not in conjunction with 001A/101A/P75		
		Not in conjunction with 10Z/11Z/12Z/77B/970/974/975	*	
		Not in conjunction with 24Z/962/Z30		
		Not in conjunction with 356	*	
		Not in conjunction with 413	*	
		Not in conjunction with 489		
		Not in conjunction with 50Z/B12	*	
		Not in conjunction with 550/553		
		Not in conjunction with R06		
		Not in conjunction with RVQ/RVR	*	
		Not in conjunction with Z87	*	
		Not in conjunction with Z90	*	
		Not in conjunction with Z97	*	
		Only in conjunction with 965		
		Only for left hand drive		
33B	Owner's Manual and service information - Romanian		○	0,00
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/13B/14B/15B/16B/17B/	*	

	341	Taxi single arm roof sign		●	257,25
			Not in conjunction with 001A/101A/P75		
			Not in conjunction with 10Z/11Z/12Z/24Z/50Z/96Z/970/974/975/B12/E22/Z30	*	
			Not in conjunction with 356	*	
			Not in conjunction with 413	*	
			Not in conjunction with 489		
			Not in conjunction with 550/553		
			Not in conjunction with 720/P55/U50		
			Not in conjunction with R06		
			Not in conjunction with RSK		
			Not in conjunction with RTG		
			Not in conjunction with RVQ/RVR	*	
			Not in conjunction with Z87	*	
			Not in conjunction with Z90	*	
			Not in conjunction with Z97	*	
			Only in conjunction with 342	*	
			Only in conjunction with 725		
			Only in conjunction with 965		
			Only for left hand drive		
			i.V.m. Code P10	○	0,00
	342	Connection, taxi roof sign		●	73,50
			Not in conjunction with 001A/101A/P75		
			Not in conjunction with 10Z/11Z/12Z/24Z/50Z/96Z/970/974/975/B12/E22/Z30	*	
			Not in conjunction with 356	*	
			Not in conjunction with 413	*	
			Not in conjunction with 489		
			Not in conjunction with 550/553		
			Not in conjunction with 720/P55/U50		
			Not in conjunction with R06		
			Not in conjunction with RSK		
			Not in conjunction with RTG		
			Not in conjunction with RVQ/RVR	*	
			Not in conjunction with Z87	*	
			Not in conjunction with Z90	*	
			Not in conjunction with Z97	*	
			Only in conjunction with 725		
			Only in conjunction with 965		
			Only for left hand drive		
			i.V.m. Code P10	○	0,00
	344	Antenna pre-installation for taxi		●	162,75
			Not in conjunction with 001A/101A/P75		
			Not in conjunction with 10Z/11Z/12Z/356/970/974/975	*	
			Not in conjunction with 24Z/50Z/96Z/B12/Z30		
			Not in conjunction with 413	*	
			Not in conjunction with 489		
			Not in conjunction with 550/553		
			Not in conjunction with RVQ/RVR	*	
			Not in conjunction with Z87	*	
			Not in conjunction with Z90	*	
			Not in conjunction with Z97	*	
			Only in conjunction with 274	*	
			Only in conjunction with 965		
			Only for left hand drive	*	
			i.V.m. Code P10	○	0,00
	34B	Owner's Manual and service information - Croatian		○	0,00
			Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/13B/14B/15B/16B/17B/	*	
	356	Roof-mounted radio aerial		●	204,75
			Not in conjunction with 248	*	
			Not in conjunction with 333/337/341/342/965	*	
			Not in conjunction with 344	*	
			Not in conjunction with 413	*	
			Not in conjunction with 414/810		
			Not in conjunction with 623U	*	
			Not in conjunction with B63		
			Not in conjunction with Z97	*	
			i.V.m. Code P10	○	0,00
	35B	Owner's Manual and service information - Latvian		○	0,00

		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/13B/14B/15B/16B/17B/	*	
36B	Owner's Manual and service information - Lithuanian		○	0,00
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/13B/14B/15B/16B/17B/	*	
37B	Owner's Manual and service information - Slovak		○	0,00
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/13B/14B/15B/16B/17B/	*	
38B	Owner's Manual and service information - Estonian		○	0,00
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/13B/14B/15B/16B/17B/	*	
39B	Owner's Manual and service information - Serbian		○	0,00
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/13B/14B/15B/16B/17B/	*	
40B	Owner's Manual and service information - Ukrainian		○	0,00
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/13B/14B/15B/16B/17B/	*	
431	Galvanised steering-wheel gearshift paddles		S	0,00
450	Taxi version, international		LS	997,50
		Not in conjunction with 10Z/11Z/12Z/24Z/50Z/61U/65U/960/962/970/974/975/B12/L5C/P22/Z30	*	
		Not in conjunction with 413	*	
		Not in conjunction with 489		
		Not in conjunction with 978	*	
		Not in conjunction with P29/U26	*	
		Not in conjunction with RVQ/RVR	*	
		Not in conjunction with Z87	*	
		Not in conjunction with Z90	*	
		Not in conjunction with Z97	*	
		Only in conjunction with 837	*	
		Only in conjunction with 965	*	
		Only in conjunction with [101A/201A/214A/215A]+670	*	
		Only for left hand drive	*	
		i.V.m. Code P10	○	0,00
461	Instrument display in miles with English lettering		○	0,00
469	Increased tyre pressure		○	0,00
494	USA specification		-	0,00
498	Japan specification		○	0,00
488	USB adapter cable		○	0,00
501	360° camera		○	0,00
		Available only as part of (P47)	*	
		Not in conjunction with 218/P44	*	
		Only in conjunction with P47	*	
		Only in conjunction with P49	*	
503	Preinstallation for Remote Parking Assist		○	0,00
502	Conversion parts for emergency vehicles		○	0,00
		Not in conjunction with 248	*	
		Not in conjunction with 337	*	
		Not in conjunction with 341/342/934/965	*	
		Not in conjunction with 344/938		
		Not in conjunction with 413/414/810	*	
		Not in conjunction with 450	*	
		Not in conjunction with 623U	*	
		Not in conjunction with 837		
		Not in conjunction with B63		
		Not in conjunction with Z97	*	
		Only in conjunction with Z90		
524	Transport protection (full body cover)		●	168,00
536	Sirius satellite radio		-	708,75
548	MBUX multimedia system		○	0,00
		Not in conjunction with 256		
		Not in conjunction with 549/PBP/PBR/U19	*	
		Not in conjunction with Z87	*	
549	MBUX multimedia system		○	0,00
		Not in conjunction with 548	*	
551	Anti-theft alarm system with preinstallation for collision		○	0,00
		Not in conjunction with 336	*	
552	Anti-theft alarm system with preinstallation for collision		○	0,00
58U	Roof liner in crystal grey fabric		○	0,00
596	Tinted and IR-reflecting laminated glass		○	0,00
		Available only as part of (PAF)	*	
		Not in conjunction with 840	*	
		Only in conjunction with PAF	*	
602	CKD vehicles for Russia		-	0,00

	623	Gulf States specification		-	0,00
	623U	light ivory		○	0,00
		Not in conjunction with 10Z/11Z/12Z/970/974/975		*	
		Not in conjunction with 356/50Z/B12		*	
		Not in conjunction with 413		*	
		Not in conjunction with 489			
		Not in conjunction with R06			
		Not in conjunction with RVO/RVR		*	
		Not in conjunction with Z87		*	
		Not in conjunction with Z90		*	
		Not in conjunction with Z97		*	
		Only in conjunction with 965			
		Only for left hand drive			
	625	Australia specification		○	0,00
	628	Adaptive Highbeam Assist Plus		○	0,00
		Available only as part of (P35)		*	
		Not in conjunction with 608/632		*	
		Only in conjunction with P35		*	
	631	LED High Performance headlamps		○	0,00
	634	Omission of first-aid kit		○	0,00
	636	Omission of warning triangle		○	0,00
	63B	Charging socket for electric and plug-in hybrid vehicles		-	0,00
	640	LED Intelligent Light System (LHD)		-	0,00
	641	LED Intelligent Light System (RHD)		○	0,00
	642	LED Intelligent Light System (LHD)		○	0,00
		Available only as part of (P35)		*	
		Not in conjunction with 608/632		*	
		Only in conjunction with P35		*	
	64B	Vehicle socket		-	0,00
	651	Winter complete wheels fitted		○	0,00
		Not in conjunction with 01R/413/432/436/550/553/PBR/R38/RVQ/RVR			
		Not in conjunction with 601A/772/811A/824A/L5C/P29/P31/RRD/U26			
		Not in conjunction with 645		*	
		Not in conjunction with 652		*	
		Not in conjunction with R66			
		Not in conjunction with U29		*	
		Only in conjunction with 1R7		*	
		Only in conjunction with 4R3			
		Only in conjunction with 4R6			
		Only in conjunction with 844			
		Only in conjunction with 9R2			
		Only in conjunction with 9R3			
	652	Summer complete tyres fitted		○	0,00
		Not in conjunction with 01R/413/432/436/550/553/PBR/R38/RVQ/RVR			
		Not in conjunction with 601A/772/811A/824A/L5C/P29/P31/RRD/U26			
		Not in conjunction with 645		*	
		Not in conjunction with 651		*	
		Not in conjunction with R66			
		Not in conjunction with U29		*	
		Only in conjunction with 1R7		*	
		Only in conjunction with 4R3			
		Only in conjunction with 4R6			
		Only in conjunction with 844			
		Only in conjunction with 9R2			
		Only in conjunction with 9R3			
	670	Residual engine heat utilisation		○	0,00
		Not in conjunction with 580			
		Only in conjunction with 581			
	687	Type plate with model year		○	0,00
	6U7	BlueTEC diesel emission control system including gene		○	0,00
	6U8	Location and tracking system		-	336,00
	762	Key with radio remote control		○	0,00
	772	AMG bodystyling		○	0,00
		Available only as part of (P31)		*	
		Not in conjunction with 001A/101A/H56/P75		*	
		Not in conjunction with 1R7			
		Not in conjunction with 651/652			

		Not in conjunction with 773		
		Not in conjunction with R32		
		Not in conjunction with R97		
		Only in conjunction with 7U0+P31	*	
		Only in conjunction with [R10/RRD/RSW/RVQ/RVR/RZ1]	*	
776	Wider wheel arch for AMG wheels		○	0,00
		Not in conjunction with 001A/101A/H56/P23/P75		
		Not in conjunction with 01R/R38	*	
		Not in conjunction with 22R	*	
		Not in conjunction with R32	*	
		Only in conjunction with 772+P31		
7U0	Powerdome on bonnet		○	0,00
		Not in conjunction with P23	*	
802	Technical modifications		○	0,00
820	Tourist vehicle		○	0,00
821	Country code Brazil		-	0,00
822	South Africa specification		○	0,00
823	Indicator plate fixing Switzerland		○	0,00
824	Additional parts for cold countries		○	0,00
829	Taiwan version		○	0,00
830	China specification		-	0,00
831	Indicator plate fixing Italia		○	0,00
834	New Zealand specification		○	0,00
835	South Korea specification		○	0,00
837	Boot liner - rubber mat		●	189,00
		Not in conjunction with 001A/101A/P75/Z90		
		Not in conjunction with 10Z/11Z/12Z/24Z/50Z/96Z/970/974/975/B12/U12/Z30/Z87		
		Not in conjunction with 413	*	
		Not in conjunction with 601A/811A/824A/L5C	*	
		Not in conjunction with B63		
		Not in conjunction with Z97	*	
		Only in conjunction with 965		
		Only for left hand drive	*	
		i.V.m. Code 450	LS	0,00
		i.V.m. Code P10	○	0,00
838	Direct current charging system (DC charging)		-	525,00
852	Sensor system for anti-theft alarm system		-	0,00
876	Interior Light package		○	0,00
		Not in conjunction with 001A/101A/P75	*	
		Not in conjunction with H56	*	
879	Removable ashtray insert		○	0,00
885	Increased anti-theft protection		●	63,00
906	Armrest heating for driver and front passenger		○	0,00
		Available only as part of (P68)	*	
		Not in conjunction with 001A/101A/P75	*	
		Not in conjunction with 555/621A/PBX		
		Not in conjunction with 873/P65	*	
		Not in conjunction with H56	*	
		Not in conjunction with PBZ		
		Only in conjunction with 275+P68	*	
		Only in conjunction with P49	*	
		Only in conjunction with U22	*	
913	Engine pre-installation for climate control system		○	0,00
922	Reduced power version		○	0,00
927	EU6 emissions standard		○	0,00
934	Taxi/hire car emergency alarm system		●	257,25
		Not in conjunction with 001A/101A/P75		
		Not in conjunction with 10Z/11Z/12Z/24Z/50Z/96Z/970/974/975/B12/B67/Z30	*	
		Not in conjunction with 413	*	
		Not in conjunction with 489		
		Not in conjunction with 550/553		
		Not in conjunction with RVQ/RVR	*	
		Not in conjunction with Z87	*	
		Not in conjunction with Z90	*	
		Not in conjunction with Z97	*	
		Only in conjunction with 965		
		Only for left hand drive	*	

			i.V.m. Code P10	○	0,00
937	Reinforcement package			○	0,00
938	Preinst. for 2-way radio hands-free system			●	157,50
		Not in conjunction with 001A/101A/P75			
		Not in conjunction with 10Z/11Z/12Z/309/970/974/975	*		
		Not in conjunction with 24Z/50Z/96Z/B12/Z30			
		Not in conjunction with 413	*		
		Not in conjunction with 489			
		Not in conjunction with 550/553			
		Not in conjunction with RVQ/RVR	*		
		Not in conjunction with Z87	*		
		Not in conjunction with Z90	*		
		Not in conjunction with Z97	*		
		Only in conjunction with 30P			
		Only in conjunction with 965			
		Only for left hand drive	*		
		i.V.m. Code P10	○		0,00
942	EASY-PACK load securing kit		-		309,75
943	Toll payment system		●		210,00
945	Emission Control China Stage 6B		-		0,00
947	pennant holder and pennant staff		●		997,50
948	Pennant holder and pennant staff right		●		997,50
960	Government version		○		0,00
		Not in conjunction with 450	*		
		Not in conjunction with 974/975	*		
		Only for left hand drive	*		
961	Petrol particulate filter		-		0,00
962	Preparation for signal unit (light bar)		●		168,00
		Not in conjunction with 248	*		
		Not in conjunction with 337/344/938			
		Not in conjunction with 341/342/934/965	*		
		Not in conjunction with 413/414/810	*		
		Not in conjunction with 450	*		
		Not in conjunction with 837			
		Not in conjunction with B63			
		Not in conjunction with Z97	*		
		Only in conjunction with 260	*		
		Only in conjunction with Z90			
		Only for left hand drive	*		
965	Taxi and hire car		●		519,75
		Not in conjunction with 001A/101A/P75			
		Not in conjunction with 10Z/11Z/12Z/24Z/50Z/96Z/B12/Z30	*		
		Not in conjunction with 356	*		
		Not in conjunction with 413	*		
		Not in conjunction with 489			
		Not in conjunction with 550/553			
		Not in conjunction with 970/974/975/Z90	*		
		Not in conjunction with 978	*		
		Not in conjunction with R06			
		Not in conjunction with RVQ/RVR	*		
		Not in conjunction with Z87	*		
		Not in conjunction with Z97	*		
		Only for left hand drive			
		i.V.m. Code 450	LS		0,00
		i.V.m. Code P10	○		0,00
968	COC document EU6 without registration certificate part		○		0,00
969	COC document EU6 with registration certificate part II		○		0,00
970	Preparation for police vehicle		●		656,25
		Not in conjunction with 248	*		
		Not in conjunction with 333/337/341/342/344/934/938	*		
		Not in conjunction with 413/414/810	*		
		Not in conjunction with 450/623U	*		
		Not in conjunction with 837			
		Not in conjunction with 965	*		
		Not in conjunction with 974/975	*		
		Not in conjunction with Z97	*		
		Only in conjunction with 30P	*		

			Only in conjunction with Z90	*	
971	Diesel particulate filter			○	0,00
972	Exhaust system with DPF Generation 2.0			○	0,00
973	Designation as owner-driver rental vehicle			○	0,00
974	Preparation for fire service command vehicle			●	656,25
			Not in conjunction with 001A/ 101A/P75		
			Not in conjunction with 248	*	
			Not in conjunction with 333/337/341/342/344/934/938	*	
			Not in conjunction with 413/414/810	*	
			Not in conjunction with 450/623U	*	
			Not in conjunction with 837		
			Not in conjunction with 960	*	
			Not in conjunction with 965	*	
			Not in conjunction with 970/975	*	
			Not in conjunction with Z97	*	
			Only in conjunction with 30P	*	
			Only in conjunction with Z90	*	
975	Preparation for emergency doctor vehicle			●	656,25
			Not in conjunction with 001A/ 101A/P75		
			Not in conjunction with 248	*	
			Not in conjunction with 333/337/341/342/344/934/938	*	
			Not in conjunction with 413/414/810	*	
			Not in conjunction with 450/623U	*	
			Not in conjunction with 837		
			Not in conjunction with 960	*	
			Not in conjunction with 965	*	
			Not in conjunction with 970/974	*	
			Not in conjunction with Z97	*	
			Only in conjunction with 30P	*	
			Only in conjunction with Z90	*	
978	Vehicle for bodybuilder			○	0,00
			Not in conjunction with 248	*	
			Not in conjunction with 450/965/B51	*	
			Only in conjunction with [RVQ/RVR]	*	
981	Omission of vehicle registration document			○	0,00
986	Identification no. (US-VIN)			○	0,00
989	Identification label under windshield			○	0,00
997	Exhibition vehicle			○	0,00
999	Petrol particulate filter			-	0,00
99P	Versandsteuerung			○	0,00
9B2	Charging cable for wallbox and public charging station,			-	252,00
			Not in conjunction with 9B3/9B6/9B7		
9B3	Charging cable for wallbox and public charging station,			-	283,50
			Not in conjunction with 9B2/9B6/9B7		
9B6	Charging cable for wallbox and public charging station,			-	252,00
			Not in conjunction with 9B2/9B3/9B7		
9B7	Charging cable for wallbox and public charging station,			-	283,50
			Not in conjunction with 9B2/9B3/9B6		
B01	EQ Boost starter-alternator			○	0,00
B08	Electronic fanfare			○	0,00
B21	Charging cable for domestic socket, 5 m, straight			-	0,00
B48	Charging cable for domestic socket, 5 m, straight			-	0,00
B63	Sporty engine sound			-	0,00
			Not in conjunction with 05Z/06Z/10Z/11Z/12Z/336/356/50Z/B12/Z87		
			Not in conjunction with 248		
			Not in conjunction with 24Z/333/334/335/337/341/342/344/837/934/938/962/Z30		
			Not in conjunction with 450/623U		
			Not in conjunction with Z90		
			Only in conjunction with 30P		
B70	Charging cable for domestic socket, 5 m, straight			-	0,00
B71	Charging cable for domestic socket, 5 m, straight			-	0,00
B73	Charging cable for domestic socket, 5 m, straight			-	0,00
B75	Charging cable for domestic socket, 8 m, straight			-	73,50
B77	Charging cable for domestic socket, 8 m, straight			-	73,50
B84	Charging cable for domestic socket, 8 m, straight			-	73,50
B85	Charging cable for domestic socket, 8 m, straight			-	73,50
B86	Charging cable for domestic socket, 8 m, straight			-	0,00



	B88	Charging cable for domestic socket, 8 m, straight		-	73,50
	B89	Charging cable for domestic socket, 8 m, straight		-	73,50
	B92	Charging cable for domestic socket, 8 m, straight		-	73,50
	B93	Charging cable for domestic socket, 8 m, straight		-	73,50
	B94	Charging cable for domestic socket, 8 m, straight		-	0,00
	B96	Charging cable for domestic socket, 8 m, straight		-	73,50
	B98	Charging cable for domestic socket, 8 m, straight		-	73,50
	B99	Charging cable for domestic socket, 8 m, straight		-	73,50
	E07	Positioning and Tracking System		-	336,00
	E5P	Installation of driving aids		○	0,00
		Only for left hand drive		*	
	E79	Spoiler lip on boot lid		-	0,00
	H64	Metal-weave trim		●	472,50
		Not in conjunction with 001A/101A/P75		*	
		Not in conjunction with 656/730/736/737/764/H06/H09/H16/H32/H41/H78		*	
		Not in conjunction with 732/H73		*	
		Not in conjunction with H56		*	
		i.V.m. Code P22		●	420,00
		i.V.m. Code PYC/PYH		●	220,50
	K11	Adaptive brake lights		S	0,00
	K32	Active Lane Change Assist		○	0,00
	K33	Extended automatic Re-start in traffic jams		○	0,00
		Not in conjunction with 22P/234/258		*	
		Only in conjunction with 233+235+365+513+546+K34		*	
		Only in conjunction with P49		*	
	K34	Route-based speed adaptation		○	0,00
		Not in conjunction with 22P/234/258		*	
		Only in conjunction with 233+365+513+546		*	
		Only in conjunction with P49		*	
	L	Left-hand drive		○	0,00
	P10	Special model "Taxi"		●	6.536,25
	P53	Fine particle sensor		-	0,00
	PBA	Mercedes-Benz Intelligent Drive Experience		●	2.882,25
				-	1.207,50
				-	630,00
	PBB	Mercedes-Benz Intelligent Drive Advanced		●	7.108,50
				-	4.667,25
				-	4.089,75
	PBC	Mercedes-Benz Intelligent Drive Professional		●	11.644,50
				-	9.077,25
				-	8.757,00
				-	8.499,75
		i.V.m. Code P17		●	10.909,50
		i.V.m. Code P17		-	8.342,25
		i.V.m. Code P17		-	8.022,00
		i.V.m. Code P17		-	7.764,75
	PBG	Preinstallation for Navigation and Comfort Connectivity		●	735,00
	PBH	Remote Parking package		●	2.362,50
				-	1.596,00
		i.V.m. Code P17		●	1.627,50
		i.V.m. Code PYM		●	1.281,00
		i.V.m. Code P17		-	861,00
		i.V.m. Code PYN		●	798,00
		i.V.m. Code PYO		●	63,00
	PYA	Base package		LS	0,00
	PYB	SE Package		LS	0,00
	PYE	Avantgarde Line		●	1.470,00
	PYF	EXCLUSIVE Line		●	3.230,00
	PYG	AMG/AVANTGARDE Line		●	4.660,00
	PYH	AMG Line		●	5.540,00
	PYM	Advantage Package		●	2.342,00
	PYN	Premium Package		●	3.552,00
	PYO	Premium Plus package		●	5.351,00
	R	Right-hand drive		●	1.905,75
	R05	Summer tyres		-	0,00
		Not in conjunction with 250/B51/R01/R06			
		Only in conjunction with R66			

			Only in conjunction with RTA		
U01	Status display for rear seat belts in instrument cluster			○	0,00
U16	Exhaust system with acoustic flap			-	0,00
U41	Fuel/water separator and lubrication package			○	0,00
U60	Pedestrian protection			○	0,00
U79	BlueTEC diesel emission control system including AdBlue			LS	0,00
U80	115 V socket			-	126,00
U93	AMG spoiler lip in carbon fibre on boot lid			-	0,00
		Not in conjunction with U47			
		Only in conjunction with B28			
Z01	Paint not feat.on standard sample card			○	0,00
		Not in conjunction with Z02/Z98		*	
		Only in conjunction with 000U+524		*	
Z02	Paint not feat.on standard sample card			○	0,00
		Not in conjunction with Z01/Z98		*	
		Only in conjunction with 000U+524		*	
Z30	Engine run-on feature			○	0,00
		Not in conjunction with 248		*	
		Not in conjunction with 274			
		Not in conjunction with 337/344/938			
		Not in conjunction with 341/342/934/965		*	
		Not in conjunction with 413/414/810/897/899		*	
		Not in conjunction with 450		*	
		Not in conjunction with 837			
		Not in conjunction with B63			
		Not in conjunction with Z97		*	
		Only in conjunction with Z90			
		Only for left hand drive		*	
Z87	Activation for monitor for special-purpose vehicles			●	63,00
		Not in conjunction with 248		*	
		Not in conjunction with 333/337/341/342/344/934/938/965		*	
		Not in conjunction with 413/414/548/810		*	
		Not in conjunction with 450/623U		*	
		Not in conjunction with 837			
		Not in conjunction with B63			
		Not in conjunction with Z97		*	
		Only in conjunction with 30P		*	
		Only in conjunction with 365+549+868+U19		*	
		Only in conjunction with Z90		*	
Z88	Shut-off of exterior lighting for special-purpose vehicles			○	0,00
Z90	Multifunction control unit for special functions			●	399,00
		Not in conjunction with 248		*	
		Not in conjunction with 333/337/341/342/344/934/938		*	
		Not in conjunction with 413/414/810		*	
		Not in conjunction with 450/623U		*	
		Not in conjunction with 837			
		Not in conjunction with 965		*	
		Not in conjunction with B63			
		Not in conjunction with Z97		*	
		Only in conjunction with 30P		*	
Z97	Electronic interface for remote control			●	399,00
		Not in conjunction with 001A/101A/P75			
		Not in conjunction with 05Z/06Z/333/334/335/337/341/342/344/356/934/938		*	
		Not in conjunction with 10Z/11Z/12Z/962/Z30		*	
		Not in conjunction with 248		*	
		Not in conjunction with 24Z/50Z/970/974/975/B12		*	
		Not in conjunction with 336/837		*	
		Not in conjunction with 450/623U		*	
		Not in conjunction with 965		*	
		Not in conjunction with Z87		*	
		Not in conjunction with Z90		*	
		Only in conjunction with 30P		*	
		Only in conjunction with B63			
		Only for left hand drive		*	
Z98	Paint not feat.on standard sample card			○	0,00
		Not in conjunction with Z01/Z02		*	
		Only in conjunction with 000U+524		*	

	B12	Tyre-change toolkit		○	0,00
			Not in conjunction with 248	*	
			Not in conjunction with 337	*	
			Not in conjunction with 341/342/934/965	*	
			Not in conjunction with 344/938		
			Not in conjunction with 413/414/810	*	
			Not in conjunction with 450	*	
			Not in conjunction with 623U	*	
			Not in conjunction with 837		
			Not in conjunction with B63		
			Not in conjunction with Z97	*	
			Only in conjunction with Z90		
			i.V.m. Code 970/974/975	●	31,50
	682	Fire extinguisher		LS	0,00
	70B	Fluorescent jacket for driver		●	5,25
	293	Sidebags in rear		●	399,00
	294	Kneebag		S	0,00
	258	Active Brake Assist		LS	0,00
			Not in conjunction with 233/23U/266/546/K33/K34	*	
			Not in conjunction with 23P/P20	*	
	292	PRE-SAFE® impulse side		○	0,00
			Available only as part of (P20)	*	
			Not in conjunction with 001A/101A/P75	*	
			Not in conjunction with 22P/234	*	
			Not in conjunction with 23P/258	*	
			Not in conjunction with 555/PBX		
			Not in conjunction with H56	*	
			Not in conjunction with PBZ		
			Only in conjunction with P20	*	
			Only in conjunction with P49	*	
	299	PRE-SAFE® system		S	0,00
	22P	Lane Tracking package		●	819,00
			Includes codes 234+243	*	
			Not in conjunction with 233/23U/266/546/K33/K34/P20	*	
			Not in conjunction with 23P	*	
			Only in conjunction with 258		
			Only in conjunction with P49	*	
			i.V.m. Code PBA	●	346,50
			i.V.m. Code PYM/PYN/PYO	●	346,50
	234	Blind Spot Assist		●	472,50
			Not in conjunction with 233/23U/266/546/K33/K34/P20	*	
			Not in conjunction with 23P	*	
			Only in conjunction with 258		
			Only in conjunction with P49	*	
			i.V.m. Code 22P	-	0,00
			i.V.m. Code PBA/22P	○	0,00
			i.V.m. Code PYM/PYN/PYO	○	0,00
	23P	Driving Assistance package		●	2.026,50
			Includes codes 233+266	*	
			Not in conjunction with 22P/234/23U	*	
			Not in conjunction with 258/P20	*	
			Only in conjunction with 365+513+546+K34	*	
			Only in conjunction with P49	*	
			i.V.m. Code PYM/PYN/PYO	●	1.554,00
			i.V.m. Code PBA	●	1.522,50
			i.V.m. Code PBB	○	0,00
	243	Active Lane Keeping Assist		○	0,00
			Available only as part of (22P)	*	
			Not in conjunction with 233/23U/266/546/K33/K34/P20	*	
			Not in conjunction with 23P	*	
			Only in conjunction with 22P	*	
			Only in conjunction with 258		
			Only in conjunction with P49	*	
	266	Active Steering Assist		○	0,00
			Not in conjunction with 22P/234/258	*	
	475	Tyre pressure monitoring system		●	320,25
				-	0,00

			i.V.m. S-Code 6P5	○	0,00
513	Traffic Sign Assist		Only in conjunction with 365	●	309,75
				*	
			i.V.m. Code PYA	○	0,00
546	Active Speed Limit Assist			○	0,00
			Not in conjunction with 22P/234/258	*	
			Only in conjunction with 233	*	
			Only in conjunction with P49	*	
P20	Driving Assistance package Plus			●	2.551,50
			Includes codes 233+266+292	*	
			Not in conjunction with 001A/101A/P75	*	
			Not in conjunction with 22P/234	*	
			Not in conjunction with 23P/258	*	
			Not in conjunction with 555/PBX		
			Not in conjunction with H56	*	
			Not in conjunction with PBZ		
			Only in conjunction with P49	*	
			i.V.m. Code PYM/PYN/PYO	●	2.079,00
			i.V.m. Code PBA	●	2.047,50
			i.V.m. Code PBB	●	525,00
			i.V.m. Code PBC	○	0,00
218	Reversing camera			●	420,00
				-	0,00
			Not in conjunction with 553/P47	*	
			i.V.m. Code P44	○	0,00
			i.V.m. Code PYA	○	0,00
235	Active Parking Assist with PARKTRONIC			○	0,00
553	Trailer Manoeuvring Assist			●	367,50
			Not in conjunction with 218/P44	*	
			Not in conjunction with 333/337/341/342/344/934/938/965		
			Not in conjunction with 489		
			Not in conjunction with 4R3/844		
			Not in conjunction with 651/652		
			Only in conjunction with 30P		
			Only in conjunction with 550+P47	*	
			Only in conjunction with P49	*	
			Only for left hand drive		
P44	Parking package with reversing camera			●	1.097,25
				-	330,75
			Includes codes 218+235	*	
			Not in conjunction with 553/P47	*	
			i.V.m. Code PBA/PBB	●	672,00
			i.V.m. Code PBC	○	0,00
			i.V.m. Code PYM	○	0,00
P47	Parking Package with 360-degree camera			●	1.580,25
				-	813,75
			Includes codes 235+501	*	
			Not in conjunction with 218/P44	*	
			Only in conjunction with P49	*	
			i.V.m. Code PYM	●	483,00
			i.V.m. Code PYN/PYO	○	0,00
915	Fuel tank with a capacity of 80 litres			-	105,00
			Not in conjunction with 916		
			i.V.m. Code PYA	-	0,00
916	Fuel tank with a capacity of 66 litres			●	52,50
				-	0,00
			Not in conjunction with 915		
			i.V.m. Code PYA	○	0,00
916	Fuel tank with a capacity of 60 litres			-	52,50
				-	0,00
			i.V.m. Code PYA	-	0,00
B59	DYNAMIC SELECT			○	0,00
U29	Braking system with larger brake discs on the front axle			●	262,50
				-	0,00
			Not in conjunction with 1R7/R11/R48	*	
			Not in conjunction with 651/652	*	
			i.V.m. Code PYG/PYH	○	0,00

	U85	AdBlue® tank with 23.5-litre capacity		○	0,00
	76B	Alternating current charging system (AC charging)		-	0,00
	B30	Charging cable for domestic socket, 5 m, straight		-	0,00
		Not in conjunction with B80			
	B31	Charging cable for domestic socket, 5 m, straight		-	0,00
	B32	Charging cable for industrial socket, 5 m, straight		-	252,00
		Not in conjunction with B82			
	B38	Charging cable for domestic socket, 5 m, straight		-	0,00
	B80	Charging cable for domestic socket, 8 m, straight		-	73,50
		Not in conjunction with B30			
	B82	Charging cable for industrial socket, 8 m, straight		-	283,50
		Not in conjunction with B32			
	482	Suspension with higher ground clearance		○	0,00
	485	AGILITY CONTROL suspension with selective damping s		○	0,00
		Not in conjunction with 489			
		Only for left hand drive			
	489	AIR BODY CONTROL		●	1.995,00
				-	1.575,00
		Not in conjunction with 248/333/337/341/342/344/450/485/550/553/623U/934/938/965			
		Not in conjunction with 677			
		Only in conjunction with 30P			
		i.V.m. S-Code PVF		○	0,00
	489	AMG RIDE CONTROL+		-	0,00
		i.V.m. S-Code PVF		-	0,00
	489	AIR BODY CONTROL		●	1.995,00
				-	1.575,00
				-	0,00
		Not in conjunction with 248/333/337/341/342/344/450/485/550/553/623U/934/938/965			
		Not in conjunction with 677			
		Only in conjunction with 30P			
		i.V.m. S-Code PVF		○	0,00
	677	AGILITY CONTROL suspension with selective damping s		○	0,00
		Not in conjunction with 489			
		i.V.m. Code P23		●	441,00
	481	Underguard		●	115,50
	421	9G-TRONIC		S	0,00
	B53	Acoustic ambient protection		-	0,00



















































































