

| N/A | Code | Equipment  | Restrictions   | EQ<br>A            | Local price excl. VAT |
|-----|------|--|--|--------------------|-----------------------|
|     | NST  |  |  | 243701 EQA 250 (L) |                       |
|     | E08  | Approval documentation for driving aids          |  | ●                  | 126,00                |
|     |      |  | Only in conjunction with E5P   | *                  |                       |
|     | E09  | Entrance guard                                   |  | ●                  | 199,50                |
|     |      |  | Only in conjunction with E5P   | *                  |                       |
|     | E5P  | Installation of driving aids                     |  | ○                  | 0,00                  |
|     | E65  | Steering wheel knob, left                        |  | ●                  | 441,00                |
|     |      |  | Only in conjunction with E08+E5P   | *                  |                       |
|     | E66  | Steering wheel knob, right                       |  | ●                  | 441,00                |
|     |      |  | Only in conjunction with E08+E5P   | *                  |                       |
|     | E67  | "Classic" hand control unit                      |  | ●                  | 2.205,00              |
|     |      |  | Not in conjunction with E68/E83/E84/E89/E92  | *                  |                       |
|     |      |  | Only in conjunction with 275+E08+E5P   | *                  |                       |
|     | E68  | "Classic" leather-covered hand control unit      |  | ●                  | 2.835,00              |
|     |      |  | Not in conjunction with E67/E83/E84/E89/E92  | *                  |                       |
|     |      |  | Only in conjunction with 275+E08+E5P   | *                  |                       |
|     | E83  | "Easy speed" leather-covered hand control unit   |  | ●                  | 3.045,00              |
|     |      |  | Not in conjunction with E67/E68/E84/E92  | *                  |                       |
|     |      |  | Only in conjunction with 275+E08+E5P   | *                  |                       |
|     | E84  | "Easy speed" hand control unit                   |  | ●                  | 2.415,00              |
|     |      |  | Not in conjunction with E67/E68/E83/E92  | *                  |                       |
|     |      |  | Only in conjunction with 275+E08+E5P   | *                  |                       |
|     | E85  | Belt buckle opener for the driver                |  | ●                  | 183,75                |
|     |      |  | Only in conjunction with E5P   | *                  |                       |
|     | E87  | Pedal cover                                      |  | ●                  | 525,00                |
|     |      |  | Only in conjunction with E08+E5P   | *                  |                       |
|     | E88  | Combination switch moved to the right            |  | ●                  | 262,50                |
|     |      |  | Only in conjunction with E08+E5P   | *                  |                       |
|     | E89  | Accelerator pedal moved to the left (electronic) |  | ●                  | 1.785,00              |
|     |      |  | Not in conjunction with E67/E68  | *                  |                       |
|     |      |  | Only in conjunction with E08+E5P   | *                  |                       |
|     | E92  | Pedal extenders (2)                              |  | ●                  | 756,00                |
|     |      |  | Not in conjunction with E67/E68/E83/E84  | *                  |                       |
|     |      |  | Only in conjunction with E08+E5P   | *                  |                       |
|     | 904  | Supplementary standard equipment                 |  | LS                 | 0,00                  |
|     |      |  | Includes codes 218 [P47]+310+537+608+73B+877+890+942+P59 [950/PTD]+U12 [U26/U66]+U22 [409] | *                  |                       |
|     |      |  | Not in conjunction with PBO  | *                  |                       |
|     | P55  | Night package                                    |  | ●                  | 472,50                |
|     |      |  | Includes codes 720 [B27]+840+97R [48R/R31/R96/RQQ/RTF/RVU]                                 | *                  |                       |
|     |      |  | Not in conjunction with 725/U50  | *                  |                       |
|     |      |  | i.V.m. Code PYH  | ●                  | 210,00                |
|     | PDA  | Advanced package                                 |  | ●                  | 2.268,00              |
|     |      |  | Includes codes 234 [PAY]+458+859+P44 [P47]+P49   | *                  |                       |
|     |      |  | Not in conjunction with PBR/PDB/PDC  | *                  |                       |
|     |      |  | i.V.m. Code P19  | ○                  | 0,00                  |
|     |      |  | i.V.m. Code PYM  | ○                  | 0,00                  |
|     | PDB  | Advanced Plus package                            |  | ●                  | 3.244,50              |
|     |      |  | Includes codes 234 [PAY]+458+581+853+859+897+P17+P44 [P47]+P49                             | *                  |                       |

|  |      |   |  |    |          |
|--|------|---|--|----|----------|
|  |      |   | Not in conjunction with PDA/PDC                          | *  |          |
|  |      |   | i.V.m. Code PBO  | ●  | 2.866,50 |
|  |      |   | i.V.m. Code P19  | ●  | 976,50   |
|  |      |   | i.V.m. Code PYN/PYQ                                      | ○  | 0,00     |
|  | PDC  | Premium package   |  | ●  | 4.903,50 |
|  |      |   | Includes codes 234 [PAY]+458+581+810+859+897+P17+P47+P49 | *  |          |
|  |      |   | Not in conjunction with 580/B27/P44/PDA/PDB              | *  |          |
|  |      |   | available approx. as of Production 2nd Quarter 2022      | *  |          |
|  |      |   | i.V.m. Code P19  | ●  | 2.635,50 |
|  |      |   | i.V.m. Code PBO  | ○  | 0,00     |
|  |      |   | i.V.m. Code PYO  | ○  | 0,00     |
|  | 871  | HANDS-FREE ACCESS   |  | ○  | 0,00     |
|  |      |   | Available only as part of (P17)                          | *  |          |
|  |      |   | Only in conjunction with P17                             | *  |          |
|  | B60  | Vehicle key set   |  | ○  | 0,00     |
|  |      |   | Available only as part of (PTD)                          | *  |          |
|  |      |   | Not in conjunction with 651A/950/P34/RQQ                 | *  |          |
|  |      |   | Only in conjunction with PTD                             | *  |          |
|  | P17  | KEYLESS-GO Comfort package                                  |  | ●  | 378,00   |
|  |      |   | Includes codes 871+889+890                               | *  |          |
|  |      |   | only in conjunction with Code PDB/PDC                    | *  |          |
|  |      |   | i.V.m. Code PDC/PDB                                      | ○  | 0,00     |
|  |      |   | i.V.m. Code PYN/PYO/PYQ                                  | ○  | 0,00     |
|  | 144U | digital white   |  | ●  | 661,50   |
|  | 191U | cosmos black  |  | ●  | 661,50   |
|  | 667U | denim blue  |  | ●  | 661,50   |
|  | 775U | iridium silver  |  | ●  | 661,50   |
|  | 787U | mountain grey   |  | ●  | 661,50   |
|  | 817U | rosé gold   |  | ●  | 661,50   |
|  | 149U | polar white   |  | ●  | 0,00     |
|  | 696U | night black   |  | LS | 0,00     |
|  | 662U | MANUFAKTUR mountain grey MAGNO                              |  | ●  | 1.942,50 |
|  |      |   | Only in conjunction with 524                             | *  |          |
|  | 993U | MANUFAKTUR patagonia red metallic                           |  | ●  | 997,50   |
|  | 413  | Panoramic sliding sunroof                                   |  | ●  | 1.228,50 |
|  |      |   | not in conjunction with B27                              | *  |          |
|  |      |   | only in conjunction with PDB/PDC                         | *  |          |
|  |      |   | i.V.m. Code PDC  | ○  | 0,00     |
|  |      |   | i.V.m. Code PYO  | ○  | 0,00     |
|  | 720  | Roof rails in black   |  | ○  | 0,00     |
|  |      |   | Not in conjunction with 725/B27                          | *  |          |
|  |      |   | only in conjunction with P19/P55                         | *  |          |
|  | 725  | Polished aluminium roof rails                               |  | S  | 0,00     |
|  |      |   | Not in conjunction with 720/B27/P55                      | *  |          |
|  | B27  | Omission of roof rails                                      |  | ○  | 0,00     |
|  |      |   | Not in conjunction with 720/725/PDC                      | *  |          |
|  |      |   | not in conjunction with 413                              | *  |          |
|  | 586  | Surround lighting with projection of brand logo             |  | ●  | 115,50   |
|  |      |   | Only in conjunction with U62                             | *  |          |
|  |      |   | i.V.m. Code PYM/PYN/PYO/PYQ                              | ○  | 0,00     |
|  | 608  | Adaptive Highbeam Assist                                    |  | S  | 0,00     |
|  | 632  | LED High Performance headlamps                              |  | S  | 0,00     |
|  | 550  | Trailer coupling with ESP<sup>®</sup> trailer stabilisation |  | ●  | 840,00   |
|  | P54  | URBAN GUARD vehicle protection                              |  | ●  | 430,50   |
|  |      |   | Includes codes 551+882                                   | *  |          |
|  |      |   | Not in conjunction with P82                              | *  |          |
|  |      |   | i.V.m. Code 362  | ●  | 462,00   |
|  | P82  | URBAN GUARD vehicle protection Plus                         |  | ●  | 640,50   |
|  |      |   | Includes codes 551+882                                   | *  |          |
|  |      |   | Not in conjunction with P54                              | *  |          |
|  |      |   | i.V.m. Code 362  | ●  | 672,00   |
|  |      |   | i.V.m. Code 34U+362                                      | ●  | 567,00   |
|  | R01  | Summer tyres  |  | ○  | 0,00     |
|  | R66  | run-flat tyres  |  | ●  | 231,00   |
|  | RQQ  | 45.7 cm (18-inch) AMG 5-spoke light-alloy wheels            |  | ○  | 0,00     |

|  |     |   |   |    |          |
|--|-----|---|---|----|----------|
|  |     |   | Available only as part of (950)   | *  |          |
|  |     |   | Not in conjunction with 101A/105A/111A/209A/213/321A/325A/391A/428/443/457/48R/55U/618A/698 | *  |          |
|  |     |   | Only in conjunction with 950+R01  | *  |          |
|  | RTF | 48.3 cm (19-inch) AMG 5-twin-spoke light-alloy wheels |   | ●  | 1.102,50 |
|  |     |   | Not in conjunction with 48R/97R/R31/R96/RQQ/RVU/RVV   | *  |          |
|  |     |   | Only in conjunction with R01  | *  |          |
|  |     |   | i.V.m. Code PTD   | ●  | 997,50   |
|  |     |   | i.V.m. Code 950   | ●  | 630,00   |
|  | RVU | 50.8 cm (20-inch) AMG multi-spoke alloy wheels        |   | ●  | 1.732,50 |
|  |     |   | Not in conjunction with 48R/97R/R31/R96/RQQ/RTF/RVV   | *  |          |
|  |     |   | Only in conjunction with R01  | *  |          |
|  |     |   | i.V.m. Code PTD   | ●  | 1.627,50 |
|  |     |   | i.V.m. Code 950   | ●  | 1.260,00 |
|  | RVV | 50.8 cm (20-inch) AMG multi-spoke alloy wheels        |   | ○  | 0,00     |
|  |     |   | Available only as part of (P19)   | *  |          |
|  |     |   | Not in conjunction with 48R/97R/R31/R96/RQQ/RTF/RVU   | *  |          |
|  |     |   | Only in conjunction with P19+R01  | *  |          |
|  | 48R | 48.3 cm (19-inch) 5-spoke light-alloy wheels          |   | ●  | 577,50   |
|  |     |   | Not in conjunction with 651A/950/97R/P34/R31/R96/RQQ/RTF/RVU/RVV                            | *  |          |
|  |     |   | Only in conjunction with R01  | *  |          |
|  |     |   | i.V.m. Code PTD   | ●  | 472,50   |
|  | 97R | 45.7 cm (18-inch) 5-twin-spoke light-alloy wheels     |   | ●  | 210,00   |
|  |     |   | Not in conjunction with 213/457/48R/651A/950/P34/R31/R96/RQQ/RTF/RVU/RVV                    | *  |          |
|  |     |   | Only in conjunction with R01  | *  |          |
|  |     |   | i.V.m. Code PTD   | ●  | 105,00   |
|  |     |   | i.V.m. Code P55   | ○  | 0,00     |
|  | R31 | 45.7 cm (18-inch) 5-spoke light-alloy wheels          |   | S  | 0,00     |
|  |     |   | Not in conjunction with 213/457/48R/651A/950/97R/P34/R96/RQQ/RTF/RVU/RVV                    | *  |          |
|  |     |   | Only in conjunction with R01  | *  |          |
|  | R96 | 45.7 cm (18-inch) 5-spoke light-alloy wheels          |   | ●  | 105,00   |
|  |     |   | Not in conjunction with 213/457/48R/651A/950/97R/P34/R31/RQQ/RTF/RVU/RVV                    | *  |          |
|  |     |   | Only in conjunction with R01  | *  |          |
|  |     |   | i.V.m. Code PTD   | ○  | 0,00     |
|  | 851 | TIREFIT   |   | LS | 0,00     |
|  | 4R5 | Complete set of 4 M+S winter wheels                   |   | ●  | 1.942,50 |
|  | 840 | Heat-insulating dark-tinted glass                     |   | ●  | 315,00   |
|  |     |   | Not in conjunction with U50   | *  |          |
|  |     |   | i.V.m. Code P19/P55   | ○  | 0,00     |
|  |     |   | i.V.m. Code PYH   | ○  | 0,00     |
|  | 875 | Heated windscreen washer system                       |   | ●  | 120,75   |
|  | P49 | Mirror package  |   | ●  | 420,00   |
|  |     |   | Includes codes 249+500+U62  | *  |          |
|  |     |   | only in conjunction with Code PDA/PDB/PDC   | *  |          |
|  |     |   | i.V.m. Code PDA/PDC/PDB   | ○  | 0,00     |
|  |     |   | i.V.m. Code PYM/PYN/PYO/PYQ   | ○  | 0,00     |
|  | 859 | Media display   |   | ●  | 682,50   |
|  |     |   | only in conjunction with Code PDA/PDB/PDC   | *  |          |
|  |     |   | i.V.m. Code PBR/PDA/PDC/PDB   | ○  | 0,00     |
|  |     |   | i.V.m. Code PYM/PYN/PYO/PYQ   | ○  | 0,00     |
|  | 01U | Preinstallation for Navigation Services               |   | ○  | 0,00     |
|  |     |   | Available only as part of (PBF)   | *  |          |
|  |     |   | Only in conjunction with 270+355+PBF  | *  |          |
|  | 355 | Extended MBUX functions                               |   | ○  | 0,00     |
|  |     |   | Only in conjunction with 270+365  | *  |          |
|  | 365 | Hard-disc navigation                                  |   | ○  | 0,00     |
|  |     |   | Only in conjunction with 270+355  | *  |          |
|  | 367 | Preinstallation for Live Traffic Information          |   | ○  | 0,00     |
|  |     |   | Only in conjunction with 270+355+365  | *  |          |
|  | PBF | Navigation Connectivity package                       |   | ●  | 105,00   |
|  |     |   | Includes codes 01U+365  | *  |          |
|  |     |   | Only in conjunction with 270+355  | *  |          |
|  | 537 | Digital radio   |   | ○  | 0,00     |
|  |     |   | Only in conjunction with 79B  | *  |          |
|  | 548 | MBUX multimedia system                                |   | ○  | 0,00     |
|  |     |   | Not in conjunction with 549   | *  |          |

|  |     |  |   |   |          |
|--|-----|--|---|---|----------|
|  | PAU | MBUX Innovation package                                      |   | ● | 1.207,50 |
|  |     |  | Includes codes 463+77B  | * |          |
|  |     |  | Only in conjunction with 859  | * |          |
|  |     |  | only in conjunction with PDA/PDB/PDC  | * |          |
|  |     |  | i.V.m. Code PYO/PYQ   | ○ | 0,00     |
|  | 810 | Burmester® surround sound system                             |   | ● | 761,25   |
|  |     |  | Not in conjunction with 853   | * |          |
|  |     |  | available approx. as of Production 2nd Quarter 2022   | * |          |
|  |     |  | only in conjunction with PDC  | * |          |
|  |     |  | i.V.m. Code PBR/PDB   | ● | 435,75   |
|  |     |  | i.V.m. Code PDC   | ○ | 0,00     |
|  |     |  | i.V.m. Code PYO   | ○ | 0,00     |
|  | 853 | Advanced Sound System  |   | ● | 325,50   |
|  |     |  | Available only as part of (PDB)   | * |          |
|  |     |  | Not in conjunction with 810/PDA/PDC   | * |          |
|  |     |  | Only in conjunction with PDB  | * |          |
|  |     |  | i.V.m. Code PBR/PDB   | ○ | 0,00     |
|  |     |  | i.V.m. Code PYN/PYQ   | ○ | 0,00     |
|  | 14U | Smartphone Integration                                       |   | ● | 315,00   |
|  |     |  | Only in conjunction with 16U+17U  | * |          |
|  |     |  | i.V.m. Code PBO   | ○ | 0,00     |
|  | 897 | Wireless charging system for mobile devices in the front     |   | ● | 210,00   |
|  |     |  | only in conjunction with PDB/PDC  | * |          |
|  |     |  | i.V.m. Code PDC/PDB   | ○ | 0,00     |
|  |     |  | i.V.m. Code PYN/PYQ/PYQ   | ○ | 0,00     |
|  | 21U | Dash cam   |   | ● | 210,00   |
|  |     |  | Only in conjunction with 270+355+365  | * |          |
|  |     |  | available approx. as of Production 2nd Quarter 2022   | * |          |
|  | 443 | Steering wheel heating                                       |   | ● | 168,00   |
|  |     |  | Not in conjunction with 431/651A/950/L3E/L5C/L5I/P34/RQQ                                    | * |          |
|  |     |  | Only in conjunction with 428+L3B  | * |          |
|  | 580 | THERMATIC automatic climate control                          |   | S | 0,00     |
|  |     |  | Not in conjunction with 581/PBR/PDC   | * |          |
|  | 581 | THERMOTRONIC automatic climate control                       |   | ● | 535,50   |
|  |     |  | Not in conjunction with 580   | * |          |
|  |     |  | only in conjunction with PBN/PDB/PDC  | * |          |
|  |     |  | i.V.m. Code PBR/PDC/PDB   | ○ | 0,00     |
|  |     |  | i.V.m. Code PYD/PYH/PYN/PYO   | ○ | 0,00     |
|  |     |  | i.V.m. Code PYQ   | ○ | 0,00     |
|  | 890 | EASY-PACK tailgate   |   | S | 0,00     |
|  | 942 | Load Compartment package                                     |   | ● | 157,50   |
|  |     |  | Only in conjunction with B13+U35  | * |          |
|  |     |  | i.V.m. Code PBO/904   | ○ | 0,00     |
|  | U40 | Partition net  |   | ● | 157,50   |
|  | PBR | ENERGIZING package Plus                                      |   | ● | 2.304,75 |
|  |     |  | Includes codes 409 [950]+581+853 [810]+859+873 [401]+877+P59 [950/PTD]                      | * |          |
|  |     |  | Not in conjunction with 580/PDA   | * |          |
|  |     |  | Only in conjunction with 270+355+365  | * |          |
|  |     |  | available approx. as of Production 2nd Quarter 2022   | * |          |
|  |     |  | only in conjunction with Code PDB/PDC   | * |          |
|  |     |  | i.V.m. Code 7U4   | ● | 1.848,00 |
|  | U12 | Velour floor mats  |   | ● | 84,00    |
|  |     |  | Not in conjunction with 651A/950/P34/RQQ/U66  | * |          |
|  |     |  | i.V.m. Code PBO/904   | ○ | 0,00     |
|  | U26 | AMG floor mats   |   | ○ | 0,00     |
|  |     |  | Available only as part of (950)   | * |          |
|  |     |  | Not in conjunction with 101A/105A/111A/209A/321A/325A/391A/428/443/48R/55U/618A/698A/97R/L3 | * |          |
|  |     |  | Only in conjunction with 950  | * |          |
|  | U45 | Door sills with model-series-specific lettering, illuminated |   | ● | 178,50   |
|  |     |  | only in conjunction with PTD/950  | * |          |
|  |     |  | i.V.m. Code 950/PTD   | ○ | 0,00     |
|  |     |  | i.V.m. Code PYH/PYD   | ○ | 0,00     |
|  | U66 | Floor mats for special model                                 |   | ○ | 0,00     |
|  |     |  | Available only as part of (P19)   | * |          |
|  |     |  | Not in conjunction with U12/U26   | * |          |

|  |     |   |   |   |          |
|--|-----|---|---|---|----------|
|  |     |   | Only in conjunction with P19  | * |          |
|  | 458 | All-digital instrument display                              |   | ● | 472,50   |
|  |     |   | only in conjunction with Code PDA/PDB/PDC+859                               | * |          |
|  |     |   | i.V.m. Code PDA/PDC/PDB   | ○ | 0,00     |
|  |     |   | i.V.m. Code PYM/PYN/PYO/PYQ   | ○ | 0,00     |
|  | 463 | Head-up Display   |   | ● | 1.039,50 |
|  |     |   | only in conjunction with PAU  | * |          |
|  |     |   | i.V.m. Code PAU   | ○ | 0,00     |
|  |     |   | i.V.m. Code PYO/PYQ   | ○ | 0,00     |
|  | U19 | MBUX augmented reality for navigation                       |   | ● | 409,50   |
|  |     |   | Only in conjunction with 270+355+365+859                                    | * |          |
|  |     |   | available approx. as of Production 2nd Quarter 2022                         | * |          |
|  |     |   | i.V.m. Code PYN/PYO/PYQ   | ○ | 0,00     |
|  | 877 | Ambient lighting  |   | S | 0,00     |
|  | U62 | Light and Sight package                                     |   | S | 0,00     |
|  | 51U | Roof liner in black fabric                                  |   | S | 0,00     |
|  |     |   | Not in conjunction with 55U/58U   | * |          |
|  | 55U | Roof liner in macchiato beige fabric                        |   | ○ | 0,00     |
|  |     |   | Not in conjunction with 111A/51U/58U/618A/651A/698A/7U4/950/P34/RQQ         | * |          |
|  |     |   | only in conjunction with 105A/325A  | * |          |
|  | 58U | Roof liner in crystal grey fabric                           |   | ○ | 0,00     |
|  |     |   | Not in conjunction with 105A/209A/325A/51U/55U                              | * |          |
|  | 7U2 | Comfort Seats   |   | S | 0,00     |
|  |     |   | Not in conjunction with 111A/618A/651A/698A/7U4/P34                         | * |          |
|  |     |   | Only in conjunction with 286+U59  | * |          |
|  | 7U4 | Sports seats  |   | ○ | 0,00     |
|  |     |   | Not in conjunction with 101A/105A/209A/321A/325A/391A/409/55U/7U2           | * |          |
|  |     |   | Only in conjunction with 286+U59  | * |          |
|  | 242 | Power front right seat with memory function                 |   | ● | 299,25   |
|  |     |   | Only in conjunction with 275  | * |          |
|  |     |   | only in conjunction with Code 275+U22/409/PBN/PBO                           | * |          |
|  |     |   | i.V.m. Code PYO/PYQ   | ○ | 0,00     |
|  | 275 | Driver's seat, electrically adjustable with memory function |   | ● | 362,25   |
|  |     |   | only in conjunction with U22/409/PBN/PBO                                    | * |          |
|  |     |   | i.V.m. Code PYO/PYQ   | ○ | 0,00     |
|  | 401 | Climatised front seats                                      |   | ● | 934,50   |
|  |     |   | Not in conjunction with 873   | * |          |
|  |     |   | only in conjunction with 101A/105A/211A                                     | * |          |
|  |     |   | i.V.m. Code PBR/P34   | ● | 630,00   |
|  |     |   | i.V.m. Code PYN/PYO/PYQ   | ● | 630,00   |
|  | 409 | Multicontour Seat package                                   |   | ● | 456,75   |
|  |     |   | Not in conjunction with 111A/209A/321A/325A/391A/618A/651A/698A/7U4/P34/U22 | * |          |
|  |     |   | Only in conjunction with 286+7U2+U59  | * |          |
|  |     |   | i.V.m. Code PBR   | ○ | 0,00     |
|  | 873 | Heated front seats  |   | ● | 304,50   |
|  |     |   | Not in conjunction with 401   | * |          |
|  |     |   | i.V.m. Code PBR/P19/P34   | ○ | 0,00     |
|  |     |   | i.V.m. Code PYN/PYO/PYQ   | ○ | 0,00     |
|  | U22 | 4-way lumbar support  |   | S | 0,00     |
|  |     |   | Not in conjunction with 409   | * |          |
|  |     |   | Only in conjunction with U59  | * |          |
|  | U59 | Seat Comfort package  |   | S | 0,00     |
|  | 446 | Touchpad without Controller                                 |   | S | 0,00     |
|  | 77B | MBUX Interior Assistant                                     |   | ● | 315,00   |
|  |     |   | Available only as part of (PAU)   | * |          |
|  |     |   | Only in conjunction with 859+PAU  | * |          |
|  |     |   | i.V.m. Code PAU   | ○ | 0,00     |
|  |     |   | i.V.m. Code PYO/PYQ   | ○ | 0,00     |
|  | L3B | Multifunction sports steering wheel in nappa leather        |   | ○ | 0,00     |
|  |     |   | Not in conjunction with 431/651A/950/L3E/L5C/L5I/P34/RQQ                    | * |          |
|  |     |   | Only in conjunction with 428+443  | * |          |
|  | L3E | Leather multifunction sports steering wheel                 |   | S | 0,00     |
|  |     |   | Not in conjunction with 431/443/651A/950/L3B/L5C/L5I/P34/RQQ                | * |          |
|  |     |   | Only in conjunction with 428  | * |          |
|  | L5C | Multifunction sports steering wheel in nappa leather        |   | ○ | 0,00     |

|  |      |  |   |   |          |
|--|------|--|---|---|----------|
|  |      |  | Not in conjunction with 428/443/L3B/L3E/L51   | * |          |
|  |      |  | Only in conjunction with 431  | * |          |
|  |      |  | only in conjunction with 950/PTD/P19  | * |          |
|  | L51  | Multifunction sports steering wheel in nappa leather / L |   | ● | 241,50   |
|  |      |  | Not in conjunction with 428/443/L3B/L3E/L5C   | * |          |
|  |      |  | Only in conjunction with 431  | * |          |
|  |      |  | only in conjunction with 950  | * |          |
|  | 310  | Double cup holder  |   | S | 0,00     |
|  | 73B  | Stowage compartment in centre console with retractab     |   | ● | 36,75    |
|  |      |  | i.V.m. Code PBO/904   | ○ | 0,00     |
|  | 331  | Backlit trim   |   | ○ | 0,00     |
|  |      |  | Not in conjunction with H15/H23/H44   | * |          |
|  |      |  | only in conjunction with 54H  | * |          |
|  | 54H  | Spiral-look trim elements, backlit                       |   | ● | 157,50   |
|  |      |  | Not in conjunction with H15/H23/H44/H60   | * |          |
|  |      |  | only in conjunction with 950/PTD  | * |          |
|  |      |  | i.V.m. Code PTD/950   | ○ | 0,00     |
|  |      |  | i.V.m. Code PYD/PYH   | ○ | 0,00     |
|  | H15  | Black open-pore linden wood trim                         |   | ● | 315,00   |
|  |      |  | Not in conjunction with 331/54H/H23/H44/H60   | * |          |
|  |      |  | i.V.m. Code PTD/950   | ● | 157,50   |
|  | H23  | Brown open-pore walnut wood trim                         |   | ● | 315,00   |
|  |      |  | Not in conjunction with 331/54H/H15/H44/H60   | * |          |
|  |      |  | i.V.m. Code 950   | ● | 157,50   |
|  | H44  | Light longitudinal-grain aluminium trim                  |   | ● | 210,00   |
|  |      |  | Not in conjunction with 331/54H/H15/H23/H60   | * |          |
|  |      |  | i.V.m. Code 950   | ● | 52,50    |
|  | H60  | Spiral-look trim elements                                |   | S | 0,00     |
|  |      |  | Not in conjunction with 54H/H15/H23/H44   | * |          |
|  | 101A | black  |   | ● | 152,25   |
|  |      |  | Not in conjunction with 111A/618A/651A/698A/7U4/950/P34/RQQ                                 | * |          |
|  |      |  | Only in conjunction with 286+7U2+P59+U59  | * |          |
|  | 105A | macchiato beige / black                                  |   | ● | 257,25   |
|  |      |  | Not in conjunction with 111A/58U/618A/651A/698A/7U4/950/P34/RQQ                             | * |          |
|  |      |  | Only in conjunction with 286+7U2+P59+U59  | * |          |
|  | 391A | rosé gold / titanium grey pearl                          |   | ○ | 0,00     |
|  |      |  | Not in conjunction with 111A/409/618A/651A/698A/7U4/950/P34/RQQ                             | * |          |
|  |      |  | Only in conjunction with 286+7U2+U59  | * |          |
|  |      |  | only in conjunction with PTD  | * |          |
|  | 651A | black  |   | ○ | 0,00     |
|  |      |  | Available only as part of (950)   | * |          |
|  |      |  | Not in conjunction with 101A/105A/111A/209A/321A/325A/391A/409/428/443/48R/55U/618A/698A/7U | * |          |
|  |      |  | Only in conjunction with 286+7U4+950+U59  | * |          |
|  | 321A | black  |   | ○ | 0,00     |
|  |      |  | Not in conjunction with 111A/409/618A/651A/698A/7U4/950/P34/RQQ                             | * |          |
|  |      |  | Only in conjunction with 286+7U2+U59  | * |          |
|  | 325A | macchiato beige / black                                  |   | ● | 105,00   |
|  |      |  | Not in conjunction with 111A/409/58U/618A/651A/698A/7U4/950/P34/RQQ                         | * |          |
|  |      |  | Only in conjunction with 286+7U2+U59  | * |          |
|  | 209A | neva grey with CYBER CUT blue                            |   | ○ | 0,00     |
|  |      |  | Available only as part of (P19)   | * |          |
|  |      |  | Not in conjunction with 111A/409/58U/618A/651A/698A/7U4/950/P34/RQQ                         | * |          |
|  |      |  | Only in conjunction with 286+7U2+P19+U59  | * |          |
|  | 211A | black  |   | ○ | 0,00     |
|  |      |  | Available only as part of (P34)   | * |          |
|  |      |  | Not in conjunction with 101A/105A/111A/209A/321A/325A/391A/409/428/443/48R/55U/618A/698A/7U | * |          |
|  |      |  | Only in conjunction with 286+7U4+950+P34+U59  | * |          |
|  |      |  | only in conjunction with 873/401  | * |          |
|  | P34  | Leather package  |   | ● | 1.354,50 |
|  |      |  | Includes codes 211A+873 [401]   | * |          |
|  |      |  | Not in conjunction with 101A/105A/111A/209A/321A/325A/391A/409/428/443/48R/55U/618A/698A/7U | * |          |
|  |      |  | Only in conjunction with 286+7U4+950+U59  | * |          |
|  |      |  | i.V.m. Code PBR   | ● | 1.050,00 |
|  |      |  | i.V.m. Code PYN/PYQ/PYQ   | ● | 1.050,00 |
|  | 950  | AMG Line   |   | ● | 3.139,50 |

|      |   |  |   |    |        |
|------|---|--|---|----|--------|
|      |   |  | Includes codes 431+54H [H15/H23/H44]+651A [211A]+725 [720/B27]+772+L5C [L5I]+RQQ [RTF/RVU]+U26+U  | *  |        |
|      |   |  | Not in conjunction with 101A/105A/111A/209A/321A/325A/391A/428/443/48R/55U/618A/698A/97R/L3       | *  |        |
|      |   |  | i.V.m. Code PYH   | ○  | 0,00   |
| P59  | Progressive   |  |   | S  | 0,00   |
|      |   |  | Includes codes 321A [101A/105A/111A/325A]+725 [720/B27]+H60 [H15/H23/H44]+L3E [L3B]+R31 [48R/97R/ | *  |        |
|      |   |  | Not in conjunction with 651A/950/P34/RQQ  | *  |        |
| PTD  | Electric Art  |  |   | ●  | 829,50 |
|      |   |  | Includes codes 391A [209A/618A/698A]+54H [H15/H23]+725 [720/B27]+B60+L5C [L3B]+R96 [48R/97R/RTF/  | *  |        |
|      |   |  | Not in conjunction with 651A/950/P34/RQQ  | *  |        |
|      |   |  | i.V.m. Code P19   | ○  | 0,00   |
|      |   |  | i.V.m. Code PYD   | ○  | 0,00   |
| 362  | Communications module (LTE) for the use of Mercedes   |  |   | ○  | 0,00   |
| 13U  | Preinstallation for Remote and Navigation Services    |  |   | ○  | 0,00   |
| 20U  | Preinstallation for digital key transfer              |  |   | ●  | 52,50  |
|      |   |  | i.V.m. Code PYA   | ○  | 0,00   |
| 34U  | Remote Services Premium                               |  |   | ●  | 262,50 |
| 351  | Mercedes-Benz emergency call system                   |  |   | ○  | 0,00   |
| 36U  | Remote and extended Charging Services Premium         |  |   | ●  | 798,00 |
|      |   |  | Not in conjunction with 38U/39U   | *  |        |
| 38U  | Remote and Charging Services Plus                     |  |   | LS | 0,00   |
|      |   |  | Not in conjunction with 35U/36U/39U   | *  |        |
|      |   |  | only in conjunction with 362+13U+365  | *  |        |
| 39U  | Remote and Charging Services Premium                  |  |   | ●  | 551,25 |
|      |   |  | Not in conjunction with 35U/36U/38U   | *  |        |
|      |   |  | only in conjunction with 362+13U+365  | *  |        |
| 00B  | Owner's Manual and service information - Danish       |  |   | ○  | 0,00   |
|      |   |  | Not in conjunction with 01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/12B/13B/14B/15B/16B/17B/      | *  |        |
| 01B  | Owner's Manual and service information - Dutch        |  |   | ○  | 0,00   |
|      |   |  | Not in conjunction with 00B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/12B/13B/14B/15B/16B/17B/      | *  |        |
| 02B  | Owner's Manual and service information - German       |  |   | ○  | 0,00   |
|      |   |  | Not in conjunction with 00B/01B/03B/04B/05B/06B/07B/08B/09B/10B/11B/12B/13B/14B/15B/16B/17B/      | *  |        |
| 03B  | Owner's Manual and service information - Russian      |  |   | ○  | 0,00   |
|      |   |  | Not in conjunction with 00B/01B/02B/04B/05B/06B/07B/08B/09B/10B/11B/12B/13B/14B/15B/16B/17B/      | *  |        |
| 04B  | Owner's Manual and service information - Finnish      |  |   | ○  | 0,00   |
|      |   |  | Not in conjunction with 00B/01B/02B/03B/05B/06B/07B/08B/09B/10B/11B/12B/13B/14B/15B/16B/17B/      | *  |        |
| 05B  | Owner's Manual and service information - English      |  |   | ○  | 0,00   |
|      |   |  | Not in conjunction with 00B/01B/02B/03B/04B/06B/07B/08B/09B/10B/11B/12B/13B/14B/15B/16B/17B/      | *  |        |
| 06B  | Owner's Manual and service information - Italian      |  |   | ○  | 0,00   |
|      |   |  | Not in conjunction with 00B/01B/02B/03B/04B/05B/07B/08B/09B/10B/11B/12B/13B/14B/15B/16B/17B/      | *  |        |
| 07B  | Owner's Manual and service information - French       |  |   | ○  | 0,00   |
|      |   |  | Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/08B/09B/10B/11B/12B/13B/14B/15B/16B/17B/      | *  |        |
| 08B  | Owner's Manual and service information - Spanish      |  |   | ○  | 0,00   |
|      |   |  | Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/09B/10B/11B/12B/13B/14B/15B/16B/17B/      | *  |        |
| 09B  | Owner's Manual and service information - Portuguese   |  |   | ○  | 0,00   |
|      |   |  | Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/10B/11B/12B/13B/14B/15B/16B/17B/      | *  |        |
| 10B  | Owner's Manual and service information - Swedish      |  |   | ○  | 0,00   |
|      |   |  | Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/11B/12B/13B/14B/15B/16B/17B/      | *  |        |
| 111A | ARTICO man-made leather black                         |  |   | ●  | 152,25 |
|      |   |  | Not in conjunction with 101A/105A/209A/321A/325A/391A/409/55U/651A/7U2/950/P34/RQQ                | *  |        |
|      |   |  | Only in conjunction with 286+7U4+P59+U59  | *  |        |
| 115A | ARTICO man-made leather, sport seat beige             |  |   | ●  | 257,25 |
|      |   |  | for China only  | *  |        |
| 11B  | Owner's Manual and service information - Arabic       |  |   | ○  | 0,00   |
|      |   |  | Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/12B/13B/14B/15B/16B/17B/      | *  |        |
| 12B  | Owner's Manual and service information - English USA/ |  |   | ○  | 0,00   |
|      |   |  | Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/13B/14B/15B/16B/17B/      | *  |        |
| 12U  | Preinstallation for Concierge Service                 |  |   | ○  | 0,00   |
| 13B  | Owner's Manual and service information - Norwegian    |  |   | ○  | 0,00   |
|      |   |  | Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/12B/14B/15B/16B/17B/      | *  |        |
| 14B  | Owner's Manual and service information - Greek        |  |   | ○  | 0,00   |
|      |   |  | Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/12B/13B/15B/16B/17B/      | *  |        |
| 15B  | Owner's Manual and service information - Turkish      |  |   | ○  | 0,00   |
|      |   |  | Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/12B/13B/14B/16B/17B/      | *  |        |
| 15U  | Pre-installation for Mercedes-Benz Link               |  |   | ○  | 0,00   |
| 16B  | Owner's Manual and service information - Polish       |  |   | ○  | 0,00   |

|  |     |  |  |   |        |
|--|-----|--|--|---|--------|
|  |     |  | Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/12B/13B/14B/15B/17B, | * |        |
|  | 16U | Apple CarPlay  |  | ○ | 0,00   |
|  |     |  | Only in conjunction with 14U+17U   | * |        |
|  | 17B | Owner's Manual and service information - Czech             |  | ○ | 0,00   |
|  |     |  | Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/12B/13B/14B/15B/16B, | * |        |
|  | 17U | Android Auto   |  | ○ | 0,00   |
|  |     |  | Only in conjunction with 14U+16U   | * |        |
|  | 18B | Owner's Manual and service information - English South     |  | ○ | 0,00   |
|  |     |  | Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/12B/13B/14B/15B/16B, | * |        |
|  | 18U | Baidu Carlife  |  | ○ | 0,00   |
|  |     |  | for China only   | * |        |
|  | 19B | Owner's Manual and service information - French South      |  | ○ | 0,00   |
|  |     |  | Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/12B/13B/14B/15B/16B, | * |        |
|  | 1P0 | Sonderpreis  |  | ○ | 0,00   |
|  | 20B | Owner's Manual and service information - Spanish South     |  | ○ | 0,00   |
|  |     |  | Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/12B/13B/14B/15B/16B, | * |        |
|  | 213 | Direct-Steer system  |  | ○ | 0,00   |
|  |     |  | Not in conjunction with 485/677/97R/R31/R96/RQQ  | * |        |
|  |     |  | Only in conjunction with 457   | * |        |
|  | 218 | Reversing camera   |  | S | 0,00   |
|  |     |  | Not in conjunction with P47  | * |        |
|  | 21B | Owner's Manual and service information - Portuguese S      |  | ○ | 0,00   |
|  |     |  | Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/12B/13B/14B/15B/16B, | * |        |
|  | 221 | Electrically adjustable front seat, left                   |  | ● | 236,25 |
|  |     |  | for China only   | * |        |
|  | 222 | Electrically adjustable front seat, right                  |  | ● | 236,25 |
|  |     |  | for China only   | * |        |
|  | 22B | Owner's Manual and service information - Japanese          |  | ○ | 0,00   |
|  |     |  | Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/12B/13B/14B/15B/16B, | * |        |
|  | 232 | Garage door opener (frequency range 284-390 MHz)           |  | ● | 236,25 |
|  | 23B | Owner's Manual and service information - simplified Chi    |  | ○ | 0,00   |
|  |     |  | Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/12B/13B/14B/15B/16B, | * |        |
|  | 241 | Power front left seat with memory function                 |  | ● | 299,25 |
|  |     |  | only in conjunction with 275+U22/409   | * |        |
|  |     |  | i.V.m. Code PY0/PYQ  | ○ | 0,00   |
|  | 249 | Interior mirror and driver's exterior mirror automatically |  | ○ | 0,00   |
|  |     |  | Available only as part of (P49)  | * |        |
|  |     |  | Only in conjunction with P49   | * |        |
|  | 24B | Owner's Manual and service information - traditional Ch    |  | ○ | 0,00   |
|  |     |  | Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/12B/13B/14B/15B/16B, | * |        |
|  | 25B | Owner's Manual and service information - Korean            |  | ○ | 0,00   |
|  |     |  | Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/12B/13B/14B/15B/16B, | * |        |
|  | 263 | Number plate mounting for Asia / Mexico                    |  | ○ | 0,00   |
|  |     |  | Not in conjunction with 264/968  | * |        |
|  | 264 | Number plate mounting for America                          |  | ○ | 0,00   |
|  |     |  | Not in conjunction with 263/968  | * |        |
|  | 266 | Active Steering Assist                                     |  | ○ | 0,00   |
|  |     |  | Not in conjunction with 234/243/258/440  | * |        |
|  |     |  | Only in conjunction with 233   | * |        |
|  | 26B | Owner's Manual and service information - Chinese Taiw      |  | ○ | 0,00   |
|  |     |  | Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/12B/13B/14B/15B/16B, | * |        |
|  | 270 | Aerial for GPS   |  | ○ | 0,00   |
|  | 27B | Owner's Manual and Service Booklet - Spanish Mexico        |  | ○ | 0,00   |
|  |     |  | Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/12B/13B/14B/15B/16B, | * |        |
|  | 286 | Luggage net on driver`s and front pass. backrest           |  | S | 0,00   |
|  | 287 | Folding rear-seat backrests                                |  | S | 0,00   |
|  | 30B | Owner's Manual and service information - Slovenian         |  | ○ | 0,00   |
|  |     |  | Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/12B/13B/14B/15B/16B, | * |        |
|  | 31B | Owner's Manual and service information - Hungarian         |  | ○ | 0,00   |
|  |     |  | Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/12B/13B/14B/15B/16B, | * |        |
|  | 32B | Owner's Manual and service information - Bulgarian         |  | ○ | 0,00   |
|  |     |  | Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/12B/13B/14B/15B/16B, | * |        |
|  | 33B | Owner's Manual and service information - Romanian          |  | ○ | 0,00   |
|  |     |  | Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/12B/13B/14B/15B/16B, | * |        |
|  | 33U | Remote Services Plus                                       |  | ● | 157,50 |



|  |      |   |   |   |        |
|--|------|---|---|---|--------|
|  | 345  | Windscreen wipers with rain sensor                    |   | S | 0,00   |
|  | 34B  | Owner's Manual and service information - Croatian     |   | ○ | 0,00   |
|  |      |   | Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/12B/13B/14B/15B/16B | * |        |
|  | 353U | hydro silver metallic                                 |   | ● | 661,50 |
|  |      |   | for China only  | * |        |
|  | 35B  | Owner's Manual and service information - Latvian      |   | ○ | 0,00   |
|  |      |   | Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/12B/13B/14B/15B/16B | * |        |
|  | 35U  | Remote and extended Charging Services Plus            |   | ● | 525,00 |
|  |      |   | Not in conjunction with 38U/39U   | * |        |
|  | 36B  | Owner's Manual and service information - Lithuanian   |   | ○ | 0,00   |
|  |      |   | Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/12B/13B/14B/15B/16B | * |        |
|  | 37B  | Owner's Manual and service information - Slovak       |   | ○ | 0,00   |
|  |      |   | Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/12B/13B/14B/15B/16B | * |        |
|  | 38B  | Owner's Manual and service information - Estonian     |   | ○ | 0,00   |
|  |      |   | Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/12B/13B/14B/15B/16B | * |        |
|  | 390  | Maintenance Service                                   |   | ○ | 0,00   |
|  | 391  | Pick-up and Delivery Service                          |   | ○ | 0,00   |
|  |      |   | Only in conjunction with 390  | * |        |
|  | 392  | Wear Parts package                                    |   | ○ | 0,00   |
|  |      |   | Only in conjunction with 390  | * |        |
|  | 393  | Vehicle warranty extension                            |   | ○ | 0,00   |
|  | 39B  | Owner's Manual and service information - Serbian      |   | ○ | 0,00   |
|  |      |   | Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/12B/13B/14B/15B/16B | * |        |
|  | 400  | Rear armrest  |   | S | 0,00   |
|  | 40B  | Owner's Manual and service information - Ukrainian    |   | ○ | 0,00   |
|  |      |   | Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/12B/13B/14B/15B/16B | * |        |
|  | 41B  | Owner's Manual and service information - Hebrew       |   | ○ | 0,00   |
|  |      |   | Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/12B/13B/14B/15B/16B | * |        |
|  | 428  | Steering wheel shift paddles                          |   | S | 0,00   |
|  |      |   | Not in conjunction with 431/651A/950/L5C/L5I/P34/RQQ  | * |        |
|  | 42B  | Owner's Manual and service information - Indonesian   |   | ○ | 0,00   |
|  |      |   | Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/12B/13B/14B/15B/16B | * |        |
|  | 431  | Galvanised steering-wheel gearshift paddles           |   | ○ | 0,00   |
|  |      |   | Not in conjunction with 428/443/L3B/L3E   | * |        |
|  | 43B  | Owner's Manual and service information - Thai         |   | ○ | 0,00   |
|  |      |   | Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/12B/13B/14B/15B/16B | * |        |
|  | 440  | Cruise control  |   | S | 0,00   |
|  |      |   | Not in conjunction with 233/266/546/K33/K34   | * |        |
|  | 44B  | Owner's Manual and service information - Vietnamese   |   | ○ | 0,00   |
|  |      |   | Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/12B/13B/14B/15B/16B | * |        |
|  | 461  | Instrument display in miles with English lettering    |   | ○ | 0,00   |
|  | 496  | Mexico version  |   | ○ | 0,00   |
|  | 498  | Japan specification                                   |   | ○ | 0,00   |
|  | 500  | Electrically folding exterior mirrors                 |   | ○ | 0,00   |
|  |      |   | Available only as part of (P49)   | * |        |
|  |      |   | Only in conjunction with P49  | * |        |
|  | 501  | 360° camera   |   | ○ | 0,00   |
|  |      |   | Available only as part of (P47)   | * |        |
|  |      |   | Not in conjunction with 218/P44   | * |        |
|  |      |   | Only in conjunction with P47  | * |        |
|  | 517  | HD digital radio standard                             |   | ○ | 0,00   |
|  | 524  | Transport protection (full body cover)                |   | ○ | 0,00   |
|  | 543  | Sun visor with illuminated vanity mirror              |   | S | 0,00   |
|  | 549  | MBUX multimedia system                                |   | ○ | 0,00   |
|  |      |   | Not in conjunction with 548   | * |        |
|  | 551  | Anti-theft alarm system                               |   | ● | 262,50 |
|  |      |   | only in conjunction with P54/P82  | * |        |
|  |      |   | i.V.m. Code P54/P82   | ○ | 0,00   |
|  | 552  | Anti-theft alarm system                               |   | ● | 262,50 |
|  |      |   | for Belgium only  | * |        |
|  | 618A | ARTICO man-made leather / Montfoort fabric crystal gr |   | ● | 105,00 |
|  |      |   | Not in conjunction with 101A/105A/209A/321A/325A/391A/409/55U/651A/7U2/950/P34/RQQ          | * |        |
|  |      |   | Only in conjunction with 286+7U4+U59  | * |        |
|  |      |   | for China only  | * |        |
|  | 623  | Gulf States specification                             |   | ○ | 0,00   |

|      |  |  |   |        |
|------|--|--|---|--------|
| 625  | Australia specification                                  |  | ○ | 0,00   |
| 631  | LED High Performance headlamp                            |  | ● | 0,00   |
| 634  | Omission of first-aid kit                                |  | ○ | 0,00   |
| 636  | Omission of warning triangle                             |  | ○ | 0,00   |
| 63B  | Charging socket  |  | ○ | 0,00   |
|      |  | Not in conjunction with 64B/65B/66B  | * |        |
| 64B  | Vehicle socket   |  | ○ | 0,00   |
|      |  | Not in conjunction with 63B/65B/66B/9B2/9B3/9B6/9B7                                | * |        |
| 651  | Winter complete wheels fitted                            |  | ○ | 0,00   |
|      |  | Not in conjunction with 652  | * |        |
|      |  | Only in conjunction with 4R5   | * |        |
| 652  | Summer complete tyres fitted                             |  | ○ | 0,00   |
|      |  | Not in conjunction with 651  | * |        |
|      |  | Only in conjunction with 4R5   | * |        |
| 65B  | Charging socket  |  | ○ | 0,00   |
|      |  | Not in conjunction with 63B/64B/66B/9B2/9B3/9B6/9B7                                | * |        |
| 666  | Freight packaging without tie-down hooks                 |  | ● | 26,25  |
|      |  | Not in conjunction with 668  | * |        |
| 668  | Prod. prot. f. freight pkging with tie-down hooks        |  | ● | 26,25  |
|      |  | Not in conjunction with 666  | * |        |
| 66B  | Charging socket  |  | ○ | 0,00   |
|      |  | Not in conjunction with 63B/64B/65B/9B2/9B3/9B6/9B7                                | * |        |
| 687  | Type plate with model year                               |  | ○ | 0,00   |
|      |  | Not in conjunction with 968  | * |        |
| 698A | FABRIC / LEATHERETTE / MICROFIBER - GREY                 |  | ● | 105,00 |
|      |  | Not in conjunction with 101A/105A/209A/321A/325A/391A/409/55U/651A/7U2/950/P34/RQQ | * |        |
|      |  | Only in conjunction with 286+7U4+U59   | * |        |
| 700  | Produktionsstandort Fahrzeug China                       |  | ○ | 0,00   |
| 762  | Remote control unit                                      |  | ○ | 0,00   |
| 763  | Key with Radio remote control with panic switch          |  | ○ | 0,00   |
|      |  | für Mexico only  | * |        |
| 772  | AMG bodystyling  |  | ○ | 0,00   |
|      |  | only in conjunction with 950/P19   | * |        |
| 79B  | Preinstallation for digital radio                        |  | ○ | 0,00   |
| 802  | Technical modifications                                  |  | ○ | 0,00   |
| 81B  | Alternating current charging system (AC charging)        |  | ○ | 0,00   |
|      |  | Not in conjunction with 82B  | * |        |
| 820  | Tourist vehicle  |  | ○ | 0,00   |
| 821  | Country code Brazil                                      |  | ○ | 0,00   |
| 822  | South Africa specification                               |  | ○ | 0,00   |
| 823  | Indicator plate fixing Switzerland                       |  | ○ | 0,00   |
| 829  | Taiwan version   |  | ○ | 0,00   |
| 830  | China specification                                      |  | ○ | 0,00   |
| 831  | Indicator plate fixing Italia                            |  | ○ | 0,00   |
| 832  | INDIA SPECIFICATION                                      |  | ○ | 0,00   |
| 834  | New Zealand specification                                |  | ○ | 0,00   |
| 835  | South Korea specification                                |  | ○ | 0,00   |
| 859U | mojave silver metallic                                   |  | ● | 661,50 |
|      |  | for China only   | * |        |
| 865  | TV receiver  |  | ● | 945,00 |
|      |  | for Japan only   | * |        |
| 882  | Interior monitoring system                               |  | ○ | 0,00   |
|      |  | only in conjunction with P54/P82   | * |        |
| 885  | Increased anti-theft protection                          |  | ○ | 0,00   |
|      |  | for 537L only  | * |        |
| 889  | KEYLESS-GO   |  | ● | 420,00 |
|      |  | only in conjunction with PDB/PDC/PBO/PBN   | * |        |
|      |  | i.V.m. Code P17/PBO  | ○ | 0,00   |
| 896U | brillant blue metallic                                   |  | ● | 661,50 |
| 943  | Toll payment system                                      |  | ● | 210,00 |
|      |  | for China only   | * |        |
| 968  | COC document EU6 without registration certificate part I |  | ○ | 0,00   |
|      |  | Not in conjunction with 263/264/687  | * |        |
| 969  | COC document EU6 with registration certificate part II   |  | ○ | 0,00   |
| 973  | Designation as owner-driver rental vehicle               |  | ○ | 0,00   |

|  |     |   |  |   |        |
|--|-----|---|--|---|--------|
|  | 981 | Omission of vehicle registration document               |  | ○ | 0,00   |
|  | 986 | Identification no. (US-VIN)                             |  | ○ | 0,00   |
|  | 989 | Identification label under windshield                   |  | ○ | 0,00   |
|  | 994 | Exhibition vehicle (B-Trade fair)                       |  | ○ | 0,00   |
|  | 997 | Exhibition vehicle                                      |  | ○ | 0,00   |
|  | 9B7 | Charging cable for wallbox and public charging station, |  | ● | 73,50  |
|  |     |   | Not in conjunction with 64B/65B/66B/9B2/9B3/9B6  | * |        |
|  |     |   | Only in conjunction with 63B   | * |        |
|  | B08 | Fanfares for Asia                                       |  | ○ | 0,00   |
|  | B12 | Tyre-change toolkit                                     |  | ● | 52,50  |
|  | B13 | Shoulderline trim strip in chrome-look finish           |  | S | 0,00   |
|  |     |   | Only in conjunction with 942+U35   | * |        |
|  | B21 | Charging cable for domestic socket, 5 m, straight       |  | ● | 252,00 |
|  |     |   | Not in conjunction with B31/B35/B36/B39/B40/B41/B80/B81/B84/B85/B86/B88/B89/B93/B94/B96/B98  | * |        |
|  | B35 | Charging cable for domestic socket, 5 m, straight       |  | ● | 252,00 |
|  |     |   | Not in conjunction with B21/B22/B30/B31/B36/B39/B40/B41/B44/B47/B48/B49/B70/B71/B73/B75/B77, | * |        |
|  | B36 | Charging cable for domestic socket, 5 m, straight       |  | ● | 252,00 |
|  |     |   | Not in conjunction with B21/B22/B30/B31/B35/B39/B40/B41/B44/B47/B48/B49/B70/B71/B73/B75/B77, | * |        |
|  | B37 | Charging cable for domestic socket, 5 m, straight       |  | ○ | 0,00   |
|  |     |   | Not in conjunction with B84/B95  | * |        |
|  | B39 | Charging cable for domestic socket, 5 m, straight       |  | ● | 252,00 |
|  |     |   | Not in conjunction with B21/B22/B30/B31/B35/B36/B40/B41/B44/B47/B48/B49/B70/B71/B73/B75/B77, | * |        |
|  | B40 | Charging cable for domestic socket, 4 m, straight       |  | ○ | 0,00   |
|  |     |   | Not in conjunction with B21/B22/B30/B31/B35/B36/B39/B41/B44/B47/B48/B49/B70/B71/B73/B75/B77, | * |        |
|  | B41 | Charging cable for domestic socket, 5 m, straight       |  | ● | 252,00 |
|  |     |   | Not in conjunction with B21/B22/B30/B31/B35/B36/B39/B40/B44/B47/B48/B49/B70/B71/B73/B75/B77, | * |        |
|  | B44 | Charging cable for domestic socket, 5 m, straight       |  | ● | 252,00 |
|  |     |   | Not in conjunction with B30/B31/B35/B36/B39/B40/B41/B47/B48/B49/B70/B71/B73/B75/B77/B78/B79, | * |        |
|  | B47 | Charging cable for domestic socket, 5 m, straight       |  | ○ | 0,00   |
|  |     |   | Not in conjunction with B30/B31/B35/B36/B39/B40/B41/B44/B48/B49/B70/B71/B73/B75/B77/B78/B79, | * |        |
|  | B48 | Charging cable for domestic socket, 5 m, straight       |  | ● | 252,00 |
|  |     |   | Not in conjunction with B30/B31/B35/B36/B39/B40/B41/B44/B47/B49/B70/B71/B73/B75/B77/B78/B79, | * |        |
|  | B49 | Charging cable for domestic socket, 5 m, straight       |  | ● | 252,00 |
|  |     |   | Not in conjunction with B30/B31/B35/B36/B39/B40/B41/B44/B47/B48/B70/B71/B73/B75/B77/B78/B79, | * |        |
|  | B70 | Charging cable for domestic socket, 5 m, straight       |  | ● | 252,00 |
|  |     |   | Not in conjunction with B30/B31/B35/B36/B39/B40/B41/B44/B47/B48/B49/B71/B73/B75/B77/B78/B79, | * |        |
|  | B71 | Charging cable for domestic socket, 5 m, straight       |  | ● | 252,00 |
|  |     |   | Not in conjunction with B30/B31/B35/B36/B39/B40/B41/B44/B47/B48/B49/B70/B73/B75/B77/B78/B79, | * |        |
|  | B73 | Charging cable for domestic socket, 5 m, straight       |  | ● | 252,00 |
|  |     |   | Not in conjunction with B30/B31/B35/B36/B39/B40/B41/B44/B47/B48/B49/B70/B71/B75/B77/B78/B79, | * |        |
|  | B75 | Charging cable for domestic socket, 8 m, straight       |  | ● | 283,50 |
|  |     |   | Not in conjunction with B30/B31/B35/B36/B39/B40/B41/B44/B47/B48/B49/B70/B71/B73/B77/B78/B79, | * |        |
|  | B77 | Charging cable for domestic socket, 8 m, straight       |  | ● | 283,50 |
|  |     |   | Not in conjunction with B30/B31/B35/B36/B39/B40/B41/B44/B47/B48/B49/B70/B71/B73/B75/B78/B79, | * |        |
|  | B78 | Charging cable for domestic socket, 8 m, straight       |  | ● | 283,50 |
|  |     |   | Not in conjunction with B30/B31/B35/B36/B39/B40/B41/B44/B47/B48/B49/B70/B71/B73/B75/B77/B79, | * |        |
|  | B79 | Charging cable for domestic socket, 8 m, straight       |  | ● | 283,50 |
|  |     |   | Not in conjunction with B30/B31/B35/B36/B39/B40/B41/B44/B47/B48/B49/B70/B71/B73/B75/B77/B78, | * |        |
|  | B83 | Charging cable for wallbox and public charging stations |  | ● | 73,50  |
|  | B84 | Charging cable for domestic socket, 8 m, straight       |  | ● | 73,50  |
|  |     |   | Not in conjunction with B21/B22/B30/B31/B35/B36/B37/B39/B40/B41/B44/B47/B48/B49/B70/B71/B73, | * |        |
|  | B85 | Charging cable for domestic socket, 8 m, straight       |  | ● | 73,50  |
|  |     |   | Not in conjunction with B21/B22/B30/B31/B35/B36/B39/B40/B41/B44/B47/B48/B49/B70/B71/B73/B75, | * |        |
|  | B86 | Charging cable for domestic socket, 8 m, straight       |  | ● | 283,50 |
|  |     |   | Not in conjunction with B21/B22/B30/B31/B35/B36/B39/B40/B41/B44/B47/B48/B49/B70/B71/B73/B75, | * |        |
|  | B88 | Charging cable for domestic socket, 8 m, straight       |  | ● | 283,50 |
|  |     |   | Not in conjunction with B21/B30/B31/B35/B36/B39/B40/B41/B44/B47/B48/B49/B70/B71/B73/B75/B77, | * |        |
|  | B89 | Charging cable for domestic socket, 8 m, straight       |  | ● | 283,50 |
|  |     |   | Not in conjunction with B21/B30/B31/B35/B36/B39/B40/B41/B44/B47/B48/B49/B70/B71/B73/B75/B77, | * |        |
|  | B93 | Charging cable for domestic socket, 8 m, straight       |  | ● | 283,50 |
|  |     |   | Not in conjunction with B21/B30/B31/B35/B36/B39/B40/B41/B44/B47/B48/B49/B70/B71/B73/B75/B77, | * |        |
|  | B94 | Charging cable for domestic socket, 8 m, straight       |  | ● | 283,50 |
|  |     |   | Not in conjunction with B21/B30/B31/B35/B36/B39/B40/B41/B44/B47/B48/B49/B70/B71/B73/B75/B77, | * |        |
|  | B95 | Charging cable for domestic socket, 8 m, straight       |  | ● | 73,50  |
|  |     |   | Not in conjunction with B22/B30/B31/B35/B36/B37/B39/B40/B41/B44/B47/B48/B49/B70/B71/B73/B75, | * |        |

|  |     |   |   |    |               |
|--|-----|---|---|----|---------------|
|  | B96 | Charging cable for domestic socket, 8 m, straight     |   | ●  | 283,50        |
|  |     |   | Not in conjunction with B21/B30/B31/B35/B36/B39/B40/B41/B44/B47/B48/B49/B70/B71/B73/B75/B77,    | *  |               |
|  | B98 | Charging cable for domestic socket, 8 m, straight     |   | ●  | 73,50         |
|  |     |   | Not in conjunction with B21/B30/B31/B35/B36/B39/B40/B41/B44/B47/B48/B49/B70/B71/B73/B75/B77,    | *  |               |
|  | B99 | Charging cable for domestic socket, 8 m, straight     |   | ●  | 283,50        |
|  |     |   | Not in conjunction with B30/B31/B35/B36/B39/B40/B41/B44/B47/B48/B49/B70/B71/B73/B75/B77/B78,    | *  |               |
|  | K32 | Active Lane Change Assist                             |   | ○  | 0,00          |
|  | K33 | Extended automatic Re-start in traffic jams           |   | ○  | 0,00          |
|  |     |   | Not in conjunction with 234/243/258/440   | *  |               |
|  |     |   | Only in conjunction with 233+235  | *  |               |
|  | K34 | Route-based speed adaptation                          |   | ○  | 0,00          |
|  |     |   | Not in conjunction with 234/243/258/440   | *  |               |
|  |     |   | Only in conjunction with 233  | *  |               |
|  | L   | Left-hand drive                                       |   | ○  | 0,00          |
|  | P53 | Fine particle sensor                                  |   | ●  | 157,50        |
|  |     |   | for South Korea and China only  | *  |               |
|  | PBO | Supplementary standard equipment                      |   | ●  | 1.018,50      |
|  |     |   | Includes codes 14U+218 [P47]+310+608+70B+73B+877+889+890+942+P59 [950/PTD]+U12 [U26/U66]+U22 [4 | *  |               |
|  |     |   | Not in conjunction with 904   | *  |               |
|  | PYA | WEU Standard Equipment                                |   | LS | 0,00          |
|  | PYD | Electric Art Interior                                 |   | ●  | 1.300,00      |
|  |     |   | i.V.m. Code PYN/PYO/PYQ   | ●  | 790,00        |
|  | PYH | AMG Line  |   | ●  | 3.800,00      |
|  |     |   | i.V.m. Code PYN/PYO/PYQ   | ●  | 3.290,00      |
|  |     |   | i.V.m. Code PYN/PYO   | ●  | 3.290,00      |
|  | PYM | Advanced Package                                      |   | ●  | 1.875,00      |
|  | PYN | Premium Package                                       |   | ●  | 3.052,00      |
|  |     |   | i.V.m. Code U19   | ●  | 3.364,00      |
|  | PYO | Premium Plus package                                  |   | ●  | not available |
|  |     |   | available approx. as of Production 2nd Quarter 2022   | *  |               |
|  |     |   | i.V.m. Code U19   | ●  | not available |
|  | PYQ | Premium Plus Package II                               |   | ●  | not available |
|  |     |   | i.V.m. Code U19   | ●  | not available |
|  | R   | Right-hand drive                                      |   | ●  | 1.113,00      |
|  | U01 | Rear belt status indication in the instrument display |   | ○  | 0,00          |
|  | U10 | Front passenger seat with seat occupancy sensor       |   | ●  | 99,75         |
|  | U27 | Exterior door handles in chrome                       |   | ●  | 52,50         |
|  | U35 | 12 V socket in load area                              |   | S  | 0,00          |
|  | U50 | Omission of heat-insulating dark-tinted glass         |   | ○  | 0,00          |
|  |     |   | Not in conjunction with 840/P55   | *  |               |
|  | U55 | Multi-link axle                                       |   | S  | 0,00          |
|  | U60 | Pedestrian protection                                 |   | ○  | 0,00          |
|  | U80 | 115 V socket  |   | ●  | 120,75        |
|  |     |   | only in conjunction with PBN  | *  |               |
|  | 682 | Fire extinguisher                                     |   | LS | 0,00          |
|  | 70B | Fluorescent jacket for driver                         |   | ●  | 5,25          |
|  |     |   | i.V.m. Code PBO   | ○  | 0,00          |
|  |     |   | i.V.m. Code PYA   | ○  | 0,00          |
|  | 293 | Sidebags in rear                                      |   | ●  | 393,75        |
|  | 294 | Kneebag   |   | ○  | 0,00          |
|  | 258 | Active Brake Assist                                   |   | ○  | 0,00          |
|  |     |   | Not in conjunction with 233/266/546/K33/K34   | *  |               |
|  | 273 | Exit warning function                                 |   | ○  | 0,00          |
|  |     |   | only in conjunction with 233/234  | *  |               |
|  | 233 | Active Distance Assist DISTRONIC                      |   | ○  | 0,00          |
|  |     |   | Not in conjunction with 234/243/258/440   | *  |               |
|  |     |   | only in conjunction with 23P/PAY  | *  |               |
|  | 234 | Blind Spot Assist                                     |   | ●  | 450,00        |
|  |     |   | Not in conjunction with 233/266/546/K33/K34/PAY   | *  |               |
|  |     |   | Only in conjunction with 243  | *  |               |
|  |     |   | only in conjunction with PDA/PDB/PDC  | *  |               |
|  |     |   | i.V.m. Code P19/PDA/PDC/PDB   | ⚠  | 0,00          |
|  |     |   | i.V.m. Code PYM/PYN/PYO/PYQ   | ⚠  | 0,00          |
|  | 243 | Active Lane Keeping Assist                            |   | ●  | 472,50        |
|  |     |   | Not in conjunction with 233/266/546/K33/K34   | *  |               |

|     |   |  |  |   |          |
|-----|---|--|--|---|----------|
|     |   |  | i.V.m. S-Code 51B  | ○ | 0,00     |
| 475 | Tyre pressure monitoring system                         |  |  | ● | 320,25   |
|     |   |  | i.V.m. S-Code 6P5  | ○ | 0,00     |
| 504 | Speed Limit Assist                                      |  |  | ○ | 0,00     |
|     |   |  | Not in conjunction with 513/546  | * |          |
| 513 | Traffic Sign Assist                                     |  |  | ● | 309,75   |
|     |   |  | Not in conjunction with 504  | * |          |
|     |   |  | Only in conjunction with 270+355+365   | * |          |
| 546 | Active Speed Limit Assist                               |  |  | ○ | 0,00     |
|     |   |  | Not in conjunction with 234/243/258/440/504  | * |          |
|     |   |  | Only in conjunction with 233+270+355+365+513   | * |          |
| PAY | Driving Assistance Package                              |  |  | ● | 1.680,00 |
|     |   |  | Includes codes 233+P49 [275]   | * |          |
|     |   |  | Not in conjunction with 234  | * |          |
|     |   |  | only in conjunction with 275/221/P49   | * |          |
|     |   |  | i.V.m. S-Code 51B  | ● | 1.270,50 |
|     |   |  | i.V.m. Code PDA/PDB/PDC  | ● | 1.207,50 |
|     |   |  | i.V.m. Code PYM/PYN/PYO/PYQ  | ● | 1.191,75 |
|     |   |  | i.V.m. S-Code 51B+PDA/PDB/PDC  | ● | 798,00   |
| 235 | PARKTRONIC Parking Assist                               |  |  | ○ | 0,00     |
|     |   |  | only in conjunction with P44/P47   | * |          |
| P44 | Parking package with reversing camera                   |  |  | ● | 624,75   |
|     |   |  | Includes codes 218+235   | * |          |
|     |   |  | Not in conjunction with P47/PDC  | * |          |
|     |   |  | only in conjunction with Code PDA/PDB  | * |          |
|     |   |  | i.V.m. Code PDA/PDB  | ○ | 0,00     |
|     |   |  | i.V.m. Code PYM/PYN  | ○ | 0,00     |
| P47 | Parking Package with 360-degree camera                  |  |  | ● | 1.055,25 |
|     |   |  | Includes codes 235+501   | * |          |
|     |   |  | Not in conjunction with 218/P44  | * |          |
|     |   |  | only in conjunction with Code PDA/PDB  | * |          |
|     |   |  | i.V.m. Code PDA/PDB  | ● | 430,50   |
|     |   |  | i.V.m. Code PDC  | ○ | 0,00     |
|     |   |  | i.V.m. Code PYO/PYQ  | ○ | 0,00     |
| P19 | Edition 1   |  |  | ● | 7.518,00 |
|     |   |  | Includes codes 209A+720 [B27]+772+840+873+PDA [PDB/PDC]+PTD+RVV+U66                          | * |          |
|     |   |  | not in conjunction with Code P55/817U/993U   | * |          |
|     |   |  | i.V.m. Code PYM  | ● | 5.250,00 |
|     |   |  | i.V.m. Code PYN/PYO/PYQ  | ● | 4.945,50 |
| B59 | DYNAMIC SELECT  |  |  | S | 0,00     |
| 82B | Alternating current charging system (AC charging)       |  |  | ○ | 0,00     |
|     |   |  | Not in conjunction with 81B  | * |          |
| 83B | Direct current charging system (DC charging)            |  |  | S | 0,00     |
| 9B2 | Charging cable for wallbox and public charging station, |  |  | ○ | 0,00     |
|     |   |  | Not in conjunction with 64B/65B/66B/9B3/9B6/9B7  | * |          |
|     |   |  | Only in conjunction with 63B   | * |          |
| 9B3 | Charging cable for wallbox and public charging station, |  |  | ● | 73,50    |
|     |   |  | Not in conjunction with 64B/65B/66B/9B2/9B6/9B7  | * |          |
|     |   |  | Only in conjunction with 63B   | * |          |
| 9B6 | Charging cable for wallbox and public charging station, |  |  | ○ | 0,00     |
|     |   |  | Not in conjunction with 64B/65B/66B/9B2/9B3/9B7  | * |          |
|     |   |  | Only in conjunction with 63B   | * |          |
| B22 | Charging cable for household socket, 5 m, straight      |  |  | ● | 252,00   |
|     |   |  | Not in conjunction with B31/B35/B36/B39/B40/B41/B80/B81/B84/B85/B86/B95                      | * |          |
| B30 | Charging cable for domestic socket, 5 m, straight       |  |  | ● | 252,00   |
|     |   |  | Not in conjunction with B31/B35/B36/B39/B40/B41/B44/B47/B48/B49/B70/B71/B73/B75/B77/B78/B79, | * |          |
|     |   |  | i.V.m. Code PYA  | ○ | 0,00     |
| B31 | Charging cable for domestic socket, 5 m, straight       |  |  | ● | 252,00   |
|     |   |  | Not in conjunction with B21/B22/B30/B35/B36/B39/B40/B41/B44/B47/B48/B49/B70/B71/B73/B75/B77, | * |          |
|     |   |  | i.V.m. Code PYA  | ○ | 0,00     |
| B32 | Charging cable for industrial socket, 5 m, straight     |  |  | ● | 252,00   |
|     |   |  | Not in conjunction with B82  | * |          |
|     |   |  | i.V.m. Code PYA  | ○ | 0,00     |
| B80 | Charging cable for domestic socket, 8 m, straight       |  |  | ● | 283,50   |
|     |   |  | Not in conjunction with B21/B22/B30/B31/B35/B36/B39/B40/B41/B44/B47/B48/B49/B70/B71/B73/B75, | * |          |

|  |     |   |   |   |          |
|--|-----|---|---|---|----------|
|  |     |   | i.V.m. Code PYA   | ● | 31,50    |
|  | B81 | Charging cable for domestic socket, 8 m, straight   |   | ● | 283,50   |
|  |     |   | Not in conjunction with B21/B22/B30/B31/B35/B36/B39/B40/B41/B44/B47/B48/B49/B70/B71/B73/B75 | * |          |
|  |     |   | i.V.m. Code PYA   | ● | 31,50    |
|  | B82 | Charging cable for industrial socket, 8 m, straight |   | ● | 283,50   |
|  |     |   | Not in conjunction with B32   | * |          |
|  |     |   | i.V.m. Code PYA   | ● | 31,50    |
|  | B92 | Charging cable for household socket, 8 m, straight  |   | ● | 283,50   |
|  | 457 | Adjustable damping                                  |   | ● | 1.039,50 |
|  |     |   | Not in conjunction with 485/677/97R/R31/R96/RQQ   | * |          |
|  |     |   | Only in conjunction with 213  | * |          |
|  | 485 | Comfort suspension                                  |   | S | 0,00     |
|  |     |   | Not in conjunction with 213/457/677   | * |          |
|  | 677 | Lowered comfort suspension                          |   | ○ | 0,00     |
|  |     |   | Not in conjunction with 213/457/485   | * |          |
|  | B53 | Acoustic ambient protection                         |   | S | 0,00     |