

N/A	Code	Equipment	Restrictions	247713 GLA 200 d	247715 GLA 200 d 4MATIC	247715 GLA 220 d 4MATIC	247787 GLA 200	247745 GLA 220 4MATIC	247745 GLA 250	247747 GLA 250 4MATIC	247795 GLA 250 e	247795 Mercedes-AMG GLA 35 4MATIC	Local Price excl VAT
	00B	Owner's Manual and service information - Danish		O	O	O	O	O	-	O	O	O	0,00
	00U	Remote Services		LS	LS	LS	LS	LS	-	LS	-	LS	0,00
			Not in conjunction with 33U/34U	*	*	*	*	*	*	*	*	*	0,00
			Not in conjunction with 33U/34U/37U	*	*	*	*	*	*	*	*	*	0,00
			Only in conjunction with 36Z	*	*	*	*	*	*	*	*	*	0,00
			L.V.m. Code PSA/PSD/PSE/PSI	O	O	O	O	O	-	O	-	O	0,00
			L.V.m. Code PSI/PSN/PSQ	-	-	-	-	-	-	-	-	O	0,00
			L.V.m. Code PSI/PSN/PSQ	O	O	O	O	O	O	-	O	-	0,00
	01B	Owner's Manual and service information - Dutch		O	O	O	O	O	O	-	O	-	0,00
	01R	45.7 cm (18-inch) 5-twin-spoke light-alloy wheels		*	*	*	*	*	*	*	*	*	630,00
			Not in conjunction with 950	*	*	*	*	*	*	*	*	*	0,00
			Only in conjunction with R01	*	*	*	*	*	*	*	*	*	0,00
			Only in conjunction with R02						*				0,00
			Only in conjunction with R02/R01						*				0,00
			L.V.m. Code P59	O	O	O	O	O	O	O	-	O	0,00
	01U	Preinstallation for Navigation Services		O	O	O	O	O	O	O	O	O	0,00
			Only in conjunction with 36Z	*	*	*	*	*	*	*	*	*	0,00
			Only in conjunction with PBF/PBG	*	*	*	*	*	*	*	*	*	0,00
			Only in conjunction with PBG						*				0,00
	02B	Owner's Manual and service information - German		O	O	O	O	O	-	O	O	O	0,00
	03B	Owner's Manual and service information - Russian		O	O	O	O	O	-	O	O	O	0,00
	03H	Brown open-pore lime wood trim		*	*	*	*	*	*	*	*	*	273,00
			Only in conjunction with 950/P34/P59	*	*	*	*	*	*	*	*	*	0,00
	04B	Owner's Manual and service information - Finnish		O	O	O	O	O	-	O	O	O	0,00
	05B	Owner's Manual and service information - English		O	O	O	O	O	-	O	O	O	0,00
	06B	Owner's Manual and service information - Italian		O	O	O	O	O	-	O	O	O	0,00
	07B	Owner's Manual and service information - French		O	O	O	O	O	-	O	O	O	0,00
	08B	Owner's Manual and service information - Spanish		O	O	O	O	O	-	O	O	O	0,00
	09B	Owner's Manual and service information - Portuguese		O	O	O	O	O	-	O	O	O	0,00
	101A	ARTICO man-made leather black		*	*	*	*	*	*	*	*	-	153,00
			Only in conjunction with P59+7U2	*	*	*	*	*	*	*	*	-	0,00
	105A	ARTICO man-made leather macchiato beige / black		*	*	*	*	*	*	*	*	-	258,00
			Only in conjunction with P59+7U2	*	*	*	*	*	*	*	*	-	0,00
	10B	Owner's Manual and service information - Swedish		O	O	O	O	O	-	O	O	O	0,00
	111A	ARTICO man-made leather black		-	-	-	*	-	-	-	-	-	153,00
			Only in conjunction with P59+7U4				*						0,00
	114A	twin leather, brown		-	-	-	*	-	-	-	-	-	258,00
			Only in conjunction with P59+7U4				*						0,00
	11B	Owner's Manual and service information - Arabic		O	O	O	O	O	-	O	O	O	0,00
	12B	Owner's Manual and service information - English USA		-	-	-	-	-	O	-	O	O	0,00
	13B	Owner's Manual and service information - Norwegian		O	O	O	O	O	-	O	O	O	0,00
	13U	Preinstallation for Remote and Navigation Services		-	-	-	-	-	-	-	-	-	0,00
	144U	digital white metallic		*	*	*	*	*	*	*	*	*	788,00
	144U			-	-	-	-	-	-	-	-	O	0,00
	149U	polar white		*	*	*	*	*	*	*	*	*	289,00
	144U			-	-	-	-	-	-	-	-	O	0,00
	14B	Owner's Manual and service information - Greek		O	O	O	O	O	-	O	O	O	0,00
	14U	Smartphone integration		*	*	*	*	*	*	*	*	*	315,00
			Only in conjunction with 16U+17U	*	*	*	*	*	*	*	*	*	0,00
	158A	ARTICO man-made leather sage grey / black		*	*	*	*	*	*	*	*	*	153,00
			Only in conjunction with 7U4+(P59/950)	*	*	*	*	*	*	*	*	*	0,00
			Only in conjunction with 7U4/555									*	0,00
			L.V.m. Code 950	O	O	O	O	O	O	O	O	O	0,00
	15B	Owner's Manual and service information - Turkish		O	O	O	O	O	-	O	O	O	0,00
	15U	Pre-installation for Mercedes-Benz Link		O	O	O	O	O	-	O	O	O	0,00
	16B	Owner's Manual and service information - Polish		O	O	O	O	O	-	O	O	O	0,00
	16U	Apple CarPlay		O	O	O	O	O	O	O	O	O	0,00
			Only in conjunction with 14U	*	*	*	*	*	*	*	*	*	0,00
	17B	Owner's Manual and service information - Czech		O	O	O	O	O	-	O	O	O	0,00
	17U	Android Auto		O	O	O	O	O	O	O	O	O	0,00
			Only in conjunction with 14U	*	*	*	*	*	*	*	*	*	0,00
	18B	Owner's Manual and service information - English South Africa		O	-	O	O	O	-	O	-	O	0,00
	191U	cosmos black metallic		*	*	*	*	*	*	*	*	*	788,00
	191U			-	-	-	-	-	-	-	-	O	0,00
	19B	Owner's Manual and service information - French South Africa		O	-	O	O	O	-	O	-	O	0,00
	1P0	Sonderpreis		O	O	O	O	O	O	O	O	O	0,00
	207	Active Distance Assist DISTRONIC		*	*	*	*	*	-	*	*	*	420,00
			Not in conjunction with 239				*	*	*	*	*	*	0,00
			Only in conjunction with 5B0	*	*	*	*	*	*	*	*	*	0,00
			L.V.m. Code 23P	O	O	O	O	O	-	O	O	O	0,00
	20B	Owner's Manual and service information - Spanish South America		O	-	O	O	O	-	O	-	O	0,00
	20U	Preinstallation for digital key transfer		LS	LS	LS	LS	LS	-	LS	LS	LS	0,00
			Only in conjunction with 36Z	*	*	*	*	*	*	*	*	*	0,00
			L.V.m. Code PSA/PSD/PSE	-	-	-	-	-	-	-	-	O	0,00
			L.V.m. Code PSI/PSI/PSN/PSQ	-	O	-	O	-	O	-	O	-	0,00
			L.V.m. Code PSA/PSD/PSE	O	-	O	-	O	-	O	-	O	0,00
			L.V.m. Code PSA/PSD/PSE	O	-	O	-	O	-	O	-	O	0,00
			L.V.m. Code PSA/PSD/PSE	O	-	O	-	O	-	O	-	O	0,00
			L.V.m. Code PSI/PSI/PSN/PSQ	O	-	O	-	O	-	O	-	O	0,00

[illegible]



N/A	Code	Equipment	Restrictions	247712 GLA 200 d	247713 GLA 200 d 4MATIC	247715 GLA 220 d 4MATIC	247717 GLA 200	247718 GLA 220 4MATIC	247716 GLA 250	247717 GLA 250 4MATIC	247715 GLA 250 e	247711 Mercedes-AMG GLA 35 4MATIC	Local Price excl VAT
	33U	Remote Services Plus		*	*	*	*	*	*	*	*	*	158,00
			Not in conjunction with 00U/34U	-	-	-	*	*	*	*	*	*	0,00
			Not in conjunction with 00U/34U/37U	*	*	*	*	*	*	*	*	*	0,00
			Not in conjunction with 34U/38U	*	*	*	*	*	*	*	*	*	0,00
			Only in conjunction with 36Z	*	*	*	*	*	*	*	*	*	0,00
			L.V.m. Code PSA/PSD/PSE/PSI	*	*	*	*	*	*	*	*	*	53,00
			L.V.m. Code PSI/PSN/PSQ	-	-	-	-	-	-	-	-	*	53,00
			L.V.m. Code PSI/PSN/PSQ	*	*	*	*	*	*	*	*	*	53,00
345		Windscreens wipers with rain sensor		S	S	S	S	S	S	S	S	S	0,00
34B		Owner's Manual and service information - Croatian		O	O	O	O	O	O	O	O	O	0,00
34U		Remote Services Premium		*	*	*	*	*	*	*	*	*	263,00
			Not in conjunction with 00U/33U	*	*	*	*	*	*	*	*	*	0,00
			Not in conjunction with 33U	*	*	*	*	*	*	*	*	*	0,00
			Only in conjunction with 36Z	*	*	*	*	*	*	*	*	*	0,00
			L.V.m. Code PSA/PSD/PSE/PSI	*	*	*	*	*	*	*	*	*	0,00
			L.V.m. Code PSI/PSN/PSQ	-	-	-	-	-	-	-	-	*	158,00
			L.V.m. Code PSI/PSN/PSQ	*	*	*	*	*	*	*	*	*	158,00
351		Mercedes-Benz emergency call system		O	O	O	O	O	O	O	O	O	0,00
			Only in conjunction with 36Z	*	*	*	*	*	*	*	*	*	0,00
355		Extended MBUX functions		O	O	O	O	O	O	O	O	O	0,00
35B		Owner's Manual and service information - Latvian		O	O	O	O	O	O	O	O	O	0,00
36Z		Communications module (LTE) for the use of Mercedes		O	O	O	O	O	O	O	O	O	0,00
			Only in conjunction with 34U+351+79B+(37U/00U)								*		0,00
			Only in conjunction with 34U+351+79B+(37U/00U)+(33U/37U)									*	0,00
			Only in conjunction with 351+(33U/34U)+(37U/00U)+79B+(00U/33U/34U)	*	*	*	*	*	*	*	*	*	0,00
			Only in conjunction with 351+(33U/34U)+79B+(00U/33U/34U)	*	*	*	*	*	*	*	*	*	0,00
365		Hard-disc navigation		*	*	*	*	*	*	*	*	*	578,00
			Only in conjunction with PBF/PBG	*	*	*	*	*	*	*	*	*	0,00
			Only in conjunction with PBG	*	*	*	*	*	*	*	*	*	0,00
			L.V.m. Code PBF/PBG	-	-	-	O	-	-	-	-	-	0,00
			L.V.m. Code PBF	O	O	O	-	O	-	O	-	O	0,00
			L.V.m. Code PBF	O	O	O	-	O	-	O	-	O	0,00
			L.V.m. Code PBF/PBG	-	-	-	-	-	O	-	-	-	0,00
			L.V.m. Code PBF/PBG	O	O	O	O	O	O	O	O	O	0,00
367		Preinstallation for Live Traffic Information		O	O	O	O	O	O	O	O	O	0,00
			Only in conjunction with 36Z	*	*	*	*	*	*	*	*	*	0,00
36B		Owner's Manual and service information - Lithuanian		O	O	O	O	O	O	O	O	O	0,00
37B		Owner's Manual and service information - Slovak		O	O	O	O	O	O	O	O	O	0,00
37U		Remote Services Advanced		*	*	*	*	*	*	*	*	*	158,00
			Not in conjunction with 00U/33U	*	*	*	*	*	*	*	*	*	0,00
			Only in conjunction with 36Z	*	*	*	*	*	*	*	*	*	0,00
38B		Owner's Manual and service information - Estonian		O	O	O	O	O	O	O	O	O	0,00
38U		Remote and Charging Services Plus		-	-	-	-	-	-	LS	-	-	0,00
			Not in conjunction with 33U	*	*	*	*	*	*	*	*	*	0,00
			Only in conjunction with (PDA/PDB/PDC/PDD)+13U	*	*	*	*	*	*	*	*	*	0,00
			L.V.m. Code PSA/PSD/PSE/PSI	-	-	-	-	-	-	O	-	-	0,00
			L.V.m. Code PSI/PSN/PSQ	-	-	-	-	-	-	O	-	-	0,00
39B		Owner's Manual and service information - Serbian		O	O	O	O	O	O	O	O	O	0,00
400		Rear armrest		O	O	O	O	O	O	O	O	O	0,00
			Only in conjunction with 567	*	*	*	*	*	*	*	*	*	0,00
401		Climatised front seats		-	-	-	-	-	-	-	*	-	966,00
			Not in conjunction with 873	*	*	*	*	*	*	*	*	*	0,00
			Only in conjunction with 555+(211A/257A/277A)	*	*	*	*	*	*	*	*	*	0,00
			L.V.m. Code PSI/PSN/PSQ	-	-	-	-	-	-	-	*	-	630,00
			L.V.m. Code PBZ	-	-	-	-	-	-	-	*	-	630,00
409		Multicontour Seat Package		-	-	-	-	-	-	-	*	-	620,00
			Only in conjunction with 275+555	*	*	*	*	*	*	*	*	*	0,00
			L.V.m. Code PBX/PBY/PBZ	-	-	-	-	-	-	O	-	O	0,00
40B		Owner's Manual and service information - Ukrainian		O	O	O	O	O	O	O	O	O	0,00
413		Panoramic sliding sunroof		*	*	*	*	*	*	*	*	*	1 260,00
			Not in conjunction with 827	*	*	*	*	*	*	*	*	*	0,00
			Only in conjunction with 720/725	*	*	*	*	*	*	*	*	*	0,00
			L.V.m. Code PDD	-	-	-	O	-	-	O	-	-	0,00
			L.V.m. Code PDD	O	O	O	O	O	O	O	O	O	0,00
41B		Owner's Manual and service information - Hebrew		O	O	O	O	O	O	O	O	O	0,00
426		8G-DCT		S	S	S	-	S	S	S	S	-	0,00
426		AMG SPEEDSHIFT DCT 8G		-	-	-	-	-	-	-	S	-	0,00
428		Steering wheel shift paddles		O	O	O	O	O	O	O	O	-	0,00
			Not in conjunction with 431	*	*	*	*	*	*	*	*	*	0,00
			Not in conjunction with L5C	*	*	*	*	*	*	*	*	*	0,00
429		7G-DCT		-	-	S	-	-	-	-	-	-	0,00
42B		Owner's Manual and service information - Indonesian		O	-	O	O	O	-	O	-	O	0,00
430		Off-Road Engineering Package		-	O	O	-	O	-	O	-	-	0,00
			Includes codes 355/859	*	*	*	*	*	*	*	*	*	0,00
431		Galvanised steering-wheel gearshift paddles		O	O	O	O	O	O	O	O	-	0,00
			Not in conjunction with 428	*	*	*	*	*	*	*	*	*	0,00
			Only in conjunction with L5C	*	*	*	*	*	*	*	*	*	0,00
43B		Owner's Manual and service information - Thai		O	-	O	O	O	-	O	-	O	0,00
440		CRUISE CONTROL		S	S	S	S	S	S	S	S	S	0,00
			Not in conjunction with 233/239	*	*	*	*	*	*	*	*	*	0,00
			Not in conjunction with 233/239/580	*	*	*	*	*	*	*	*	*	0,00
			Not in conjunction with 233/580	*	*	*	*	*	*	*	*	*	0,00

[illegible]

N/A	Code	Equipment	Restrictions									Local Price excl.VAT
				247712 GLA 200 d	247713 GLA 200 d 4MATIC	247715 GLA 220 d 4MATIC	247787 GLA 200	247745 GLA 220 4MATIC	247746 GLA 250	247747 GLA 250 4MATIC	247795 GLA 250 e 4MATIC	
			Only in conjunction with P54/P82	+	+	+	+	+	+	+	+	0,00
			LV.m. Code P82	○	○	○	○	○	○	○	○	0,00
			LV.m. Code P54	○	○	○	○	○	○	○	○	0,00
	552	Anti-theft alarm system with preinstallation for collision		○	○	○	○	-	-	○	○	0,00
			Only in conjunction with P54/P82	+	+	+	+			+	+	0,00
	555	AMG Performance seats		-	-	-	-	-	-	-	○	0,00
			Not in conjunction with 654A/U22								+	0,00
			Only in conjunction with U10+(P81/P82)								+	0,00
	55H	Star Pattern trim elements		○	○	○	○	○	○	○	-	0,00
	55U	Roof liner in macchiato beige fabric		○	○	○	○	○	○	○	-	0,00
			Only in conjunction with 105A	+	+	+	+	+	+	+	+	0,00
	567	Rear seats with fore/aft adjustment		●	●	●	●	●	●	●	●	378,00
			Only in conjunction with (7U2/7U4)+400	+	+	+	+	+	+	+	+	0,00
			Only in conjunction with (7U4/555)+400								+	0,00
	56H	Star Pattern trim		○	○	○	○	○	○	○	○	0,00
			Only in conjunction with (P59/P50)+331						+			0,00
			Only in conjunction with 331								+	0,00
			Only in conjunction with 877+(P59/P50)+331	+	+	+	+	+	+	+	+	0,00
	580	THERMATIC automatic climate control		○	○	○	○	-	○	○	○	0,00
			Not in conjunction with P53				+	+	+	+	+	0,00
	581	THERMOTRONIC automatic climate control		●	●	●	●	●	●	●	●	536,00
			LV.m. Code PDC/PDD	-	-	-	-	○	-	-	-	0,00
			LV.m. Code PDC/PDD	-	-	-	-	-	-	○	-	0,00
			LV.m. Code PDC/PDD	○	○	○	-	○	○	-	○	0,00
	586	Surround lighting with projection of brand logo		○	○	○	○	○	○	○	○	0,00
			Only in conjunction with PDD	+	+	+	+	+	+	+	+	0,00
	58U	Roof liner in crystal grey fabric		○	○	○	○	○	○	○	○	0,00
			Not in conjunction with 105A	+	+	+	+	+	+	+	+	0,00
	580	Pre-installation for DISTRONIC		○	○	○	○	-	○	○	○	0,00
			Only in conjunction with 258							+	+	0,00
			Only in conjunction with 258+(B01/207)				+					0,00
			Only in conjunction with 258+207	+	+	+					+	0,00
	5U6	AMG-specific radiator grille, darkened		-	-	-	-	-	-	-	○	0,00
			Only in conjunction with PAZ								+	0,00
	608	Adaptive Highbeam Assist		●	●	●	●	●	●	●	●	0,00
			Not in conjunction with 628	+	+	+	+	+	+	+	+	0,00
			Only in conjunction with 631/632	+	+	+	+				+	0,00
			Only in conjunction with 631/632/640							+	+	0,00
			LV.m. Code 640	-	-	-	-	●	●	●	●	0,00
	623	Gulf States specification		-	-	-	-	-	-	-	-	158,00
			Only in conjunction with U60+(672+R66/R66)+B12+682+687+986+989							+	+	0,00
			Only in conjunction with U60+B12+682+687+(672/690)+R66/R66)+986+989				+					0,00
	625	Australia specification		-	-	-	○	-	-	○	-	0,00
			Only in conjunction with U60+(258/239/233)+537+827				+			+	+	0,00
	628	Adaptive Highbeam Assist Plus		○	○	○	○	-	○	○	○	0,00
			Not in conjunction with 608	+	+	+	+	+	+	+	+	0,00
			Only in conjunction with 641/642	+	+	+	+	+	+	+	+	0,00
	631	LED High Performance headlamp		●	●	●	●	●	-	●	●	0,00
			Not in conjunction with 632/640/642							+	+	0,00
			Not in conjunction with 632/641/642							+	+	0,00
			Not in conjunction with 632/642	+	+	+	+					0,00
			Not in conjunction with PAD/PDD	+	+	+	+	+	+			0,00
			Not in conjunction with PDD							+	+	0,00
			Only in conjunction with 608	+	+	+	+	+	+	+	+	0,00
			Only in conjunction with R	+	+	+	+	+	+	+	+	0,00
	632	LED High Performance headlamps		●	●	●	●	●	●	●	●	0,00
			Not in conjunction with 631/641	+	+	+	+			+	+	0,00
			Not in conjunction with 631/641/642							+	+	0,00
			Not in conjunction with PAD/PDD	+	+	+	+	+	+	+	+	0,00
			Not in conjunction with PDD							+	+	0,00
			Only in conjunction with 608	+	+	+	+	+	+	+	+	0,00
			Only in conjunction with L	+	+	+	+	+	+	+	+	0,00
	634	Omission of first-aid kit		○	○	○	○	○	○	○	○	0,00
	636	Omission of hazard warning triangle		○	○	○	○	○	○	○	○	0,00
	638	Charging socket		-	-	-	-	-	-	○	-	0,00
	640	MULTIBEAM LED		-	-	-	-	●	●	-	●	305,00
			Not in conjunction with 631/641							+	+	0,00
			Only in conjunction with 608							+	+	0,00
			Only in conjunction with L							+	+	0,00
			LV.m. Code PDD	-	-	-	-	○	○	-	○	0,00
	641	MULTIBEAM LED		●	●	●	●	-	●	●	●	305,00
			Not in conjunction with 631/632/642							+	+	0,00
			Not in conjunction with 632/640/642							+	+	0,00
			Not in conjunction with 632/642	+	+	+	+					0,00
			Only in conjunction with 628	+	+	+	+			+	+	0,00
			Only in conjunction with R	+	+	+	+			+	+	0,00
			LV.m. Code PAD	-	-	-	-	-	○	-	-	0,00
			LV.m. Code PAD	○	○	○	○	-	○	-	-	0,00
			LV.m. Code PDD	-	-	-	-	-	-	○	-	0,00
			LV.m. Code PDD	-	-	-	-	-	-	-	○	0,00
			LV.m. Code PDD	○	○	○	○	-	○	-	-	0,00
	642	MULTIBEAM LED		●	●	●	●	●	●	●	●	305,00
			Not in conjunction with 631/632/641							+	+	0,00
			Not in conjunction with 631/641	+	+	+	+			+	+	0,00

[illegible]

N/A	Code	Equipment	Restrictions									Local Price excl.VAT
				247712 GLA 200 d	247713 GLA 200 d 4MATIC	247715 GLA 220 d 4MATIC	247787 GLA 200	247745 GLA 220 4MATIC	247746 GLA 250	247747 GLA 250 4MATIC	247795 GLA 250 e 4MATIC	
	775U			-	-	-	-	-	-	-	0	0,00
	77B	MBUX Interior Assistant		0	0	0	0	0	0	0	0	0,00
			Only in conjunction with PDD	+	+	+	+	+	+	+	+	0,00
	787U	mountain grey metallic		*	*	*	*	*	*	*	-	788,00
	787U			-	-	-	-	-	-	-	0	0,00
	79B	Preinstallation for digital radio		0	0	0	0	0	0	0	0	0,00
			Only in conjunction with 362/537+362	+	+	+	+	+	+	+	+	0,00
	7U2	Comfort Seats		\$	\$	\$	\$	\$	\$	\$	-	0,00
			Only in conjunction with 101A/105A/311A/318A	+	+	+	+	+	+	+	+	0,00
	7U4	Sports seats		*	*	*	*	*	*	*	*	315,00
			Not in conjunction with 101A/105A/311A/318A	+	+	+	+	+	+	+	+	0,00
			Only in conjunction with 286								+	0,00
			LV.m. Code 950	0	0	0	0	0	0	0	0	0,00
			LV.m. Code P34	0	0	0	0	0	0	0	0	0,00
	7U8	Model badge on boot lid and wings in high-gloss black		-	-	-	-	-	-	-	0	0,00
			Only in conjunction with PAZ								+	0,00
	804	Technical modifications		0	0	0	0	0	0	0	0	0,00
	80B	Alternating current charging system (AC charging)		-	-	-	-	-	-	-	0	0,00
			Not in conjunction with 82B								+	0,00
	810	Burmester® surround sound system		*	*	*	*	*	*	*	*	951,00
			Not in conjunction with 853	+	+	+	+	+	+	+	+	0,00
			Only in conjunction with 22U+32U	+	+	+	+	+	+	+	+	0,00
			LV.m. Code PDC/PDD	*	*	*	*	*	*	*	*	625,00
	817U	rosé gold metallic		*	*	*	*	*	*	*	-	788,00
	817U			-	-	-	-	-	-	-	0	0,00
	820	Tourist vehicle		0	0	0	0	0	0	0	0	0,00
	821	Country code Brazil		-	-	0	-	-	-	-	0	0,00
			Only in conjunction with (258/239/233)+294+827+986+851			+					+	0,00
	822	South Africa specification		0	-	0	-	-	0	-	0	0,00
			Only in conjunction with (233/258)+989	+	+							0,00
			Only in conjunction with (258/239/233)+989			+			+	+		0,00
	823	country code Switzerland		0	0	0	0	-	0	0	0	0,00
			Not in conjunction with 263/264/823/831								+	0,00
			Not in conjunction with 263/827/831									0,00
			Not in conjunction with 263/831		+							0,00
			Not in conjunction with 264/827/831	+	+	+	+	+				0,00
			Not in conjunction with 831								+	0,00
	824	Additional parts for cold countries (engine air intake)		0	0	0	0	-	0	0	0	0,00
	827	Number plate mounting		0	-	0	0	-	0	-	0	0,00
			Not in conjunction with 263/264/823/831								+	0,00
			Not in conjunction with 263/823/831									0,00
			Not in conjunction with 264/823/831	+	+	+	+	+	+			0,00
	829	Taiwan version		-	-	-	0	-	-	-	0	0,00
			Only in conjunction with (233/258)+808+827									0,00
			Only in conjunction with (258/239/233)+808+827			+					+	0,00
	82B	Alternating current charging system (AC charging)		-	-	-	-	-	-	-	*	525,00
			Not in conjunction with 80B								+	0,00
	830	China specification		-	-	-	0	0	-	-	-	0,00
			Only in conjunction with (P44/P47)+275+(401/873)+413+567+840+14U+P60+(U22/555)+70B+(233/239)+634+827+986+985+808+P8F+U12A								+	0,00
			Only in conjunction with 14U+21U+221+413+446+458+500+70B+772+873+877+P55+P59+(U27/889)+(233/239)+634+827+986+988+908+P8F+U112/U12A					+				0,00
			Only in conjunction with 221+413+458+14U+U37+P59+70B+(233/239)+634+U12/U26+827+986+989+808+P8F				+					0,00
	831	country code Italia		0	0	0	0	0	-	0	0	0,00
			Not in conjunction with 263/264/823/827								+	0,00
			Not in conjunction with 263/823		+							0,00
			Not in conjunction with 263/823/827									0,00
			Not in conjunction with 264/823/827	+	+	+	+	+	+			0,00
			Not in conjunction with 823								+	0,00
	832	India specification		-	-	0	0	-	-	-	0	0,00
			Only in conjunction with (672/690)+294+986+808+U60				+					0,00
			Only in conjunction with 294+672+986+808+U60								+	0,00
			Only in conjunction with U41+294+(672/690)+986+808+U60			+						0,00
	834	New Zealand specification		-	-	-	0	-	-	0	-	0,00
			Only in conjunction with U60				+			+	+	0,00
	835	South Korea specification		-	-	-	-	-	0	-	-	0,00
			Only in conjunction with 14U+238+242+294+634+798+873+943+986+808+P53+PAV+U567/287+U(P59/950)						+			0,00
	83B	Direct current charging system (DC charging)		-	-	-	-	-	-	*	-	525,00
			Only in conjunction with 82B								+	0,00
	840	Heat-insulating dark-tinted glass		*	*	*	*	*	*	*	*	315,00
			Not in conjunction with U50	+	+	+	+	+	+	+	+	0,00
			Only in conjunction with P59/950	+	+	+	+	+	+	+	+	0,00
			LV.m. Code P55	0	0	0	0	-	0	0	-	0,00
			LV.m. Code PS/PSN/PSQ	-	-	-	-	0	-	-	-	0,00
			LV.m. Code P60	-	-	-	-	-	-	-	0	0,00
			LV.m. Code PS/PSN/PSQ	-	-	-	-	-	-	0	-	0,00
			LV.m. Code PS/PSN/PSQ	0	0	0	0	-	0	-	0	0,00
	852	Sensor system for anti-theft alarm system		-	-	-	-	*	*	*	*	147,00
			Not in conjunction with 882							+	+	0,00
			Only in conjunction with L							+	+	0,00
			Only in conjunction with P82						+	+	+	0,00
			LV.m. Code 362	-	-	-	-	*	*	-	*	179,00
			LV.m. Code P54/P82	-	-	-	-	0	0	-	0	0,00



[illegible]

[illegible]

N/A	Code	Equipment	Restrictions									Local Price excl.VAT
				247712 GLA 200 d	247713 GLA 200 d 4MATIC	247715 GLA 220 d 4MATIC	247787 GLA 200	247745 GLA 220 4MATIC	247746 GLA 250	247747 GLA 250 4MATIC	247795 GLA 250 e 4MATIC	
			Not in conjunction with 413	+	+	+	+	+	+	+	+	0,00
			Not in conjunction with 720/725	+	+	+	+	+	+	+	+	0,00
			Only in conjunction with P55/P59	+	+	+	+	+	+	+	+	0,00
	B30	Charging cable for domestic socket, 5 m, straight		-	-	-	-	-	-	○	-	0,00
	B31	Charging cable for domestic socket, 5 m, straight		-	-	-	-	-	-	○	-	0,00
	B32	Charging cable for industrial socket, 5 m, straight		-	-	-	-	-	-	+	-	252,00
	B51	TIREFIT		LS	LS	LS	LS	LS	LS	LS	LS	0,00
			Not in conjunction with R66	+	+	+	+	+	+	+	+	0,00
			LV.m. Code PSA/PSD/PSE/PSI	-	-	-	○	-	-	○	-	0,00
			LV.m. Code PSA/PSD/PSE/PSI	○	○	○	-	-	○	-	-	0,00
			LV.m. Code PSI/PSN/PSQ	-	-	-	○	-	-	○	○	0,00
			LV.m. Code PSI/PSN/PSQ	○	○	○	-	-	○	-	-	0,00
	B53	Acoustic presence indicator		-	-	-	-	-	-	S	-	0,00
	B59	AMG DYNAMIC SELECT		-	-	-	-	-	-	-	S	0,00
	B59	DYNAMIC SELECT		S	S	S	S	S	S	S	-	0,00
	B63	Sporty engine sound		○	○	○	○	○	○	○	-	0,00
			Only in conjunction with 950	+	+	+	+	+	+	+	+	0,00
	B71	Charging cable for domestic socket, 5 m, straight		-	-	-	-	-	-	○	-	0,00
	B80	Charging cable for domestic socket, 8 m, straight		-	-	-	-	-	-	+	-	74,00
	B81	Charging cable for domestic socket, 8 m, straight		-	-	-	-	-	-	+	-	74,00
	B82	Charging cable for industrial socket, 8 m, straight		-	-	-	-	-	-	+	-	284,00
	B92	Charging cable for household socket, 8 m, straight		-	-	-	-	-	-	+	-	74,00
	B99	Charging cable for domestic socket, 8 m, straight		-	-	-	-	-	-	+	-	74,00
	E08	Approval documentation for driving aids		+	+	+	+	-	+	+	+	200,00
			Only in conjunction with E5P+;E45/E46/E47/E48/E83/E84/E87/E88/E89/E92/E93/E94/E95/E96/E97	+	+	+	+	-	+	+	+	0,00
			Only in conjunction with L	+	+	+	+	-	+	+	+	0,00
	E09	Entrance guard		+	+	+	+	-	+	+	+	200,00
			Only in conjunction with E5P	+	+	+	+	-	+	+	+	0,00
			Only in conjunction with L	+	+	+	+	-	+	+	+	0,00
	E5P	Installation of driving aids for people with a disability		○	○	○	○	-	○	○	○	0,00
			Only in conjunction with E08/E09/E85	+	+	+	+	-	+	+	+	0,00
			Only in conjunction with L	+	+	+	+	-	+	+	+	0,00
	E65	Steering wheel knob, left		+	+	+	+	-	+	+	+	441,00
			Only in conjunction with E08	+	+	+	+	-	+	+	+	0,00
			Only in conjunction with L	+	+	+	+	-	+	+	+	0,00
	E66	Steering wheel knob, right		+	+	+	+	-	+	+	+	441,00
			Only in conjunction with E08	+	+	+	+	-	+	+	+	0,00
			Only in conjunction with L	+	+	+	+	-	+	+	+	0,00
	E67	"Classic" hand control unit		+	+	+	+	-	+	+	+	2.205,00
			Not in conjunction with E68/E83/E84	+	+	+	+	-	+	+	+	0,00
			Not in conjunction with E89/E94/E96	+	+	+	+	-	+	+	+	0,00
			Only in conjunction with 275+E08	+	+	+	+	-	+	+	+	0,00
			Only in conjunction with L	+	+	+	+	-	+	+	+	0,00
	E68	"Classic" leather-covered hand control unit		+	+	+	+	-	+	+	+	2.835,00
			Not in conjunction with E67/E83/E84	+	+	+	+	-	+	+	+	0,00
			Not in conjunction with E89/E94/E96	+	+	+	+	-	+	+	+	0,00
			Only in conjunction with 275+E08	+	+	+	+	-	+	+	+	0,00
			Only in conjunction with L	+	+	+	+	-	+	+	+	0,00
	E83	"Easy speed" leather-covered hand control unit		+	+	+	+	-	+	+	+	3.045,00
			Not in conjunction with E67/E68/E84	+	+	+	+	-	+	+	+	0,00
			Not in conjunction with E94/E96	+	+	+	+	-	+	+	+	0,00
			Only in conjunction with 275+E08	+	+	+	+	-	+	+	+	0,00
			Only in conjunction with L	+	+	+	+	-	+	+	+	0,00
	E84	"Easy speed" hand control unit		+	+	+	+	-	+	+	+	2.415,00
			Not in conjunction with E67/E68/E83	+	+	+	+	-	+	+	+	0,00
			Not in conjunction with E94/E96	+	+	+	+	-	+	+	+	0,00
			Only in conjunction with 275+E08	+	+	+	+	-	+	+	+	0,00
			Only in conjunction with L	+	+	+	+	-	+	+	+	0,00
	E85	Belt buckle opener for the driver		+	+	+	+	-	+	+	+	184,00
			Only in conjunction with E5P	+	+	+	+	-	+	+	+	0,00
			Only in conjunction with L	+	+	+	+	-	+	+	+	0,00
	E87	Pedal cover		+	+	+	+	-	+	+	+	525,00
			Only in conjunction with E08	+	+	+	+	-	+	+	+	0,00
			Only in conjunction with L	+	+	+	+	-	+	+	+	0,00
	E88	Repositioned combination switch		+	+	+	+	-	+	+	+	263,00
			Only in conjunction with E08	+	+	+	+	-	+	+	+	0,00
			Only in conjunction with L	+	+	+	+	-	+	+	+	0,00
	E89	Repositioned accelerator pedal		+	+	+	+	-	+	+	+	1.785,00
			Not in conjunction with E67/E68	+	+	+	+	-	+	+	+	0,00
			Only in conjunction with E08	+	+	+	+	-	+	+	+	0,00
			Only in conjunction with L	+	+	+	+	-	+	+	+	0,00
	E92	Pedal extenders (2)		+	+	+	+	-	+	+	+	756,00
			Not in conjunction with E67/E68/E83/E84	+	+	+	+	-	+	+	+	0,00
			Only in conjunction with E08	+	+	+	+	-	+	+	+	0,00
			Only in conjunction with L	+	+	+	+	-	+	+	+	0,00
	E93	Turny Evo swivel/lift seat		+	+	+	+	-	+	+	+	10.080,00
			Not in conjunction with 23P/PAY	+	+	+	+	-	+	+	+	0,00
			Only in conjunction with 242+E08	+	+	+	+	-	+	+	+	0,00
			Only in conjunction with L	+	+	+	+	-	+	+	+	0,00
	E94	Left seat repositioning to the rear		+	+	+	+	-	+	+	+	788,00
			Not in conjunction with E96	+	+	+	+	-	+	+	+	0,00
			Only in conjunction with E08	+	+	+	+	-	+	+	+	0,00
			Only in conjunction with L	+	+	+	+	-	+	+	+	0,00
	E95	Right seat repositioning to the rear		+	+	+	+	-	+	+	+	788,00

[illegible]

[illegible]

				247712 GLA 200 d	247713 GLA 200 d 4MATIC	247715 GLA 220 d 4MATIC	247787 GLA 200	247745 GLA 220 4MATIC	247746 GLA 250	247747 GLA 250 4MATIC	247785 GLA 250 e	247751 Mercedes-AMG GLA 35	Local Price excl.VAT
N/A	Code	Equipment	Restrictions										
			Includes codes 890+(P44/P47)+P49+U22	+	+	+	+	+	+	+	+	+	0,00
			Includes codes 890+P44+P49+U22					+					0,00
			Only in conjunction with 20U+38U+890+P49+U22+(P44/P47)								+		0,00
			Only in conjunction with 73B+(P44/P47)+890+P49+U22+20U+(00U/33U/34U/37U)								+		0,00
			Only in conjunction with 890+(P44/P47)+P49+U22+20U+(00U/33U/34U)				*						0,00
			Only in conjunction with 890+(P44/P47)+P49+U22+20U+(00U/33U/34U/37U)	+	+	+	+	+					0,00
			LV.m. Code PSD/PSE	○	○	○	○	○	-	○	○	-	0,00
	PDB	Advanced Plus Package		+	+	+	+	+	+	+	+	+	745,50
				-	-	-	-	-	LS	-	-	-	0,00
				-	-	-	-	-	-	-	-	D	0,00
			Includes codes 458+877+890+897+P17+(P44/P47)+P49+U22	+	+	+	+	+	+	+	+	+	0,00
			Includes codes 458+877+890+897+P17+P44+P49+U22					+					0,00
			Only in conjunction with				*						0,00
			Only in conjunction with (00U/33U/34U/37U)+(P44/P47)+(U22/409)+20U+73B+897								*		0,00
			Only in conjunction with (00U/33U/34U/37U)+458+877+P17+(P44/P47)+P49+(P59/950)+U22+20U+73B+897							*			0,00
			Only in conjunction with	+	+	+	+						0,00
			Only in conjunction with (P44/P47)+(P59/950)					*					0,00
			Only in conjunction with 20U+38U+458+877+897+P17+P49+U22+(P44/P47)+(P59/950)								+		0,00
			LV.m. Code PSI/PSJ	○	○	○	○	○	-	○	○	○	0,00
	PDC	Premium Package		+	+	+	+	+	+	+	+	-	4.583,25
				-	-	-	-	-	-	-	-	-	0,00
			Includes codes 234+458+581+(853/810)+877+890+897+P17+(P44/P47)+P49+(PBG/PBF)+(U19/PBF)+(U22/PBF)+(U45/PBF)	+	+	+	+	+	+	+	+	+	0,00
			Includes codes 234+458+581+(853/810)+877+890+897+P17+(P44/P47)+P49+PBG+U19+U22+U45					*					0,00
			Includes codes 458+877+890+897+P17+P44+P49+PBG+U19+U22+U45					*					0,00
			Only in conjunction with (P44/P47)+(P59/950)+PBG+(853/810)+U45+(233/234)						*				0,00
			Only in conjunction with 20U+38U+458+581+877+897+P17+P49+U19+U22+U45+(P44/P47)+(P59/950)+(PBF/PBG)+(853/810)+(233/234)								*		0,00
			Only in conjunction with 73B+U19+(00U/33U/34U/37U)+458+581+P17+(P44/P47)+P49+(P59/950)+(PBF/PBG)+(853/810)+877+U22+U45+(233/234)							*			0,00
			Only in conjunction with 73B+U19+(00U/33U/34U/37U)+581+(P44/P47)+(PBF/PBG)+(853/810)+(U22/409)+U45+20U+897+(233/234)								*		0,00
			Only in conjunction with U19+(00U/33U/34U/37U)+458+581+P17+(P44/P47)+P49+(P59/950)+(PBF/PBG)+(853/810)+877+U22+U45+(233/234)			*							0,00
			Only in conjunction with U19+(00U/33U/34U/37U)+458+581+P17+(P44/P47)+P49+(P59/950)+(PBF/PBG)+(853/810)+877+U22+U45+(233/234)	+	+	+	+	+					0,00
			LV.m. Code U19	+	+	+	+	+	+	+	+	+	0,00
			LV.m. Code U19	-	-	-	-	-	-	-	-	-	4.930,00
			LV.m. Code PBF+U19	+	+	+	+	+	+	+	+	+	2.258,00
			LV.m. Code PBF+U19	-	-	-	-	-	-	-	-	-	4.841,00
			LV.m. Code PBF	+	+	+	+	+	+	+	+	+	2.169,00
			LV.m. Code PBF	-	-	-	-	-	-	-	-	-	4.494,00
			LV.m. S-Code BP3+PBG	+	+	+	+	+	+	+	+	+	1.822,00
			LV.m. S-Code BP3+PBG	-	-	-	-	-	-	-	-	-	2.378,25
			LV.m. S-Code BP3+PBG	-	-	-	-	-	-	LS	-	-	1.160,25
			LV.m. Code PSN	○	○	○	○	○	○	○	○	○	0,00
	PDD	Premium Plus Package		+	+	+	+	+	+	+	+	+	8.091,00
				-	-	-	-	-	-	-	-	-	5.418,00
			Includes codes 241+275+413+458+463+581+586+628+77B+(853/810)+877+890+897+P17+P47+P49+(PBG/PBF)+(U19/233/234)	+	+	+	+		+	+	+	+	0,00
			Includes codes 275+413+458+463+581+586+628+642+77B+(853/810)+877+890+897+P17+P47+P49+(PBG/PBF)+(U19/233/234)	+	+	+	+	+	+	+	+	+	0,00
			Includes codes 275+413+458+463+581+586+77B+(853/810)+877+890+897+P17+P47+P49+PBG+U19+U22+U45					*					0,00
			Includes codes 458+877+890+897+P17+P49+PBG+U19+U22+U45					*					0,00
			Only in conjunction with (241/242)+458+463+586+950+P17+P49+(PBF/PBG)+581+(640/641/642)+(853/810)+877+77B+U22+20U+(00U/33U/34U/37U)							*			0,00
			Only in conjunction with (241/242)+458+463+586+950+P17+P49+(PBF/PBG)+581+(641/642)+(853/810)+877+77B+U22+20U+(00U/33U/34U/37U)			*							0,00
			Only in conjunction with (241/242)+458+463+586+950+P17+P49+(PBF/PBG)+581+(641/642)+(853/810)+877+77B+U22+20U+(00U/33U/34U/37U)	+	+	+	+	+					0,00
			Only in conjunction with (241/242)+458+463+586+950+P17+P49+(PBF/PBG)+581+(641/642)+(853/810)+77B+(U22/409)+20U+U19+897+877+77B+U45+(00U/33U/34U/37U)							*			0,00
			Only in conjunction with 20U+38U+458+463+581+586+77B+877+897+950+P17+P47+P49+U19+U22+U45+(241/242)+(PBF/PBG)+(U45/233/234)							*			0,00
			Only in conjunction with 463+586+950+PBG+640+(853/810)+77B+U19+P47+U45						*				0,00
			LV.m. Code U19	+	+	+	+	+	+	+	+	+	8.437,00
			LV.m. Code U19	-	-	-	-	-	-	-	-	-	5.765,00
			LV.m. Code PBF+U19	+	+	+	+	+	+	+	+	+	8.548,00
			LV.m. Code PBF+U19	-	-	-	-	-	-	-	-	-	5.676,00
			LV.m. Code PBF	+	+	+	+	+	+	+	+	+	8.001,00
			LV.m. Code PBF	-	-	-	-	-	-	-	-	-	5.329,00
			LV.m. S-Code BP3+PBG	+	+	+	+	+	+	+	+	+	5.885,25
			LV.m. S-Code BP3+PBG	-	-	-	-	-	-	-	-	-	4.667,25
			LV.m. S-Code BP3+PBG	-	-	-	-	-	-	-	-	-	3.507,00
			LV.m. Code PSQ	○	○	○	○	○	○	○	○	○	0,00
N/A	PSA	Entry		+	+	+	+	+	+	+	+	+	1.932,00
				-	-	-	-	-	-	-	-	-	2.163,00
			Includes codes (00U/33U/34U)+(677/459/485)+873+942+(B51/R66)+PBG			*							0,00
			Includes codes (00U/33U/34U/37U)+(677/459/485)+873+942+(B51/R66)+PBG	+	+	+	+						0,00
			Includes codes (00U/33U/34U/37U)+(677/459/485)+B51+PBG					*					0,00
			Includes codes 38U+873+942+(982/983/986/987)+(B51/R66)+PBG								*		0,00
			Only in conjunction with (677/459/485)+873+(B51/R66)+(00U/33U/34U)+PBG+942			*							0,00
			Only in conjunction with (677/459/485)+873+(B51/R66)+(00U/33U/34U/37U)+PBG+942	+	+	+	+						0,00
			Only in conjunction with 873+(B51/R66)+PBG+38U+942+(982/983/986/987)							*			0,00

[illegible]

[illegible]



N/A	Code	Equipment	Restrictions											
		</												