

Valid from 15.06.2012

S standard equipment - not available

Valid from 15.06.2012		A Limousine						
		176.000	176.012	176.001	176.042	176.043	176.044	
		A 180 CDI BlueEFFICIENCY	A 180 CDI BlueEFFICIENCY	A 200 CDI BlueEFFICIENCY	A 180 BlueEFFICIENCY	A 200 BlueEFFICIENCY	A 250 BlueEFFICIENCY	
● available at extra charge ○available at no extra charge U annotations existing S standard equipment - not available								
Code	Designation							CLP EUR
L	Left-hand drive	○	○	○	○	○	○	0,00
R	Right-hand drive	●	●	●	●	●	●	1113,00
162U	south sea blue metallic	●	●	●	●	●	●	577,50
191U	cosmos black metallic	●	●	●	●	●	●	577,50
589U	jupiter red	○	○	○	○	○	○	0,00
650U	cirrus white	○	○	○	○	○	○	0,00
662U	designo mountain grey magno	●	●	●	●	●	●	1837,50
696U	night black	○	○	○	○	○	○	0,00
761U	polar silver metallic	●	●	●	●	●	●	577,50
787U	mountain grey metallic	●	●	●	●	●	●	577,50
893U	monolith grey metallic	●	●	●	●	●	●	577,50
894U	universe blue	●	●	●	●	●	●	577,50
895U	canyon beige metallic	●	●	●	●	●	●	577,50
001A	fabric Venlo black Not in conjunction with Code 400,950,P27,P34,P59 or U59	○	○	○	○	○	○	0,00
021A	fabric Domburg black Not in conjunction with Code 950, P27, P34, P59 Only in conjunction with Code U59	○	○	○	○	○	○	0,00
028A	fabric Domburg grey Not in conjunction with Code 950, P27, P34, P59 Only in conjunction with Code U59	○	○	○	○	○	○	0,00
101A	black ARTICO man-made leather Not in conjunction with Code P34 or 950 Only in conjunction with Code U59 in conjunction with Code P27 oder P59	●	●	●	●	●	●	252,00
		●	●	●	●	●	●	126,00
108A	alpaca grey ARTICO man-made leather Not in conjunction with Code P34 or 950 Only in conjunction with Code U59 in conjunction with Code P27 oder P59	●	●	●	●	●	●	252,00
		●	●	●	●	●	●	126,00
361A	black / anthracite fabric / ARTICO Larochette Not in conjunction with Code P34 Only in conjunction with code P59 and U59	○	○	○	○	○	○	0,00
368A	grey fabric / ARTICO Larochette Not in conjunction with Code P34 Only in conjunction with code P59 and U59	○	○	○	○	○	○	0,00
411	6-speed manual transmission Not in conjunction with Code 239	-	S	S	S	S	-	0,00
429	7G-DCT	S	-	-	-	-	S	0,00
		-	-	●	●	●	-	1911,00
451A	alpaca ARTICO Stoff Messancy black	○	○	○	○	○	○	0,00

	Not in conjunction with Code P34 Only in conjunction with Code P27 and Code U59							
455A	alpaca ARTICO Stoff Messancy black/white Not in conjunction with Code P34 Only in conjunction with Code P27 and Code U59	○	○	○	○	○	○	0,00
651A	DINAMICA/ARTICO man-made leather Not in conjunction with Code P34 Only in conjunction with Code 950 and U59	○	○	○	○	○	○	0,00
801A	black leather Only in conjunction with Code P34 and U59	○	○	○	○	○	○	0,00
804A	nut brown leather Only in conjunction with Code P34 and U59	○	○	○	○	○	○	0,00
808A	leather alpaca grey Only in conjunction with Code P34 and U59	○	○	○	○	○	○	0,00
811A	leather black RED CUT Only in conjunction with Code P39 and U59	○	○	○	○	○	○	0,00
22P	Lane tracking package Certain countries only only in conjunction with Code 234, 476	●	●	●	●	●	●	787,50
30P	Stowage Space package only in conjunction with Code 286, 932 and (939 or 682) and U35 (RHD) only in conjunction with Code 286, 939 and (932 or 682) and U35 (LHD)	●	●	●	●	●	●	173,25
950	AMG Sport 1R2 or 3R7 possible (only Germany) in conjunction with Code P84 Only in conjunction with Code 280,486,51U, 651A or (P39+811A) and 774 or 772,U26; not in conj.w. Code 516,550,1R1,1R2,2R9,3R7 or U37 Not in conjunction with Code P27/P59//516/550 only in conjunction with Code 280,483,51U, 651A, 801A,804A,808A or (P39+811A) and 772 and 646,781,791,794,U26 or U64 in conjunction with Code P84	-	-	-	-	-	○	2110,50
		-	-	○	-	○	-	2478,00
		○	○	-	○	-	-	2635,50
		★	★	★	★	★	★	
		-	-	-	-	-	○	0,00
P27	Style Not in conjunction with Code 950/P59 or P84 Only in conjunction with Code R10/R11/R38/R43 (only A 250) or R48/25R/55R/44R/646/781 or 794 and 51U or 58U (58U not i.conj. w. 455A),101A/108A/451A/455A or 801A/804A/808A	-	-	-	-	-	●	262,50
		-	-	●	-	●	-	677,25
		●	●	-	●	-	-	861,00
P34	Exclusive Package Not in conjunction with Code 516, P84, U12, U26 Only in conjunction with Code 280, 880, 873, U22, 801A/804A(804A n.i.conj.w. 58U) or 808A in conjunction with Code 950 in conjunction with Code P27 in conjunction with Code P59	●	●	●	●	●	●	1942,50
		●	●	●	●	●	●	1102,50
		●	●	●	●	●	●	1627,50
		●	●	●	●	●	●	1522,50
P39	AMG Exclusive package Not in conjunction with Code P34 Only in conjunction with Code 880, 950 and 811A	●	●	●	●	●	●	1102,50
P49	Mirror package only in conjunction with Code 249, 500	●	●	●	●	●	●	309,75
P54	Anti-Theft Protection package Certain countries only Consisting of: Code 551, 882	●	●	●	●	●	●	420,00
P55	Night package	-	-	-	-	-	●	787,50
		○	○	○	○	○	-	945,00

	1R2 or 3R7 possible (only Germany) Not in conjunction with Code 1R1 only in conjunction with Code 840 (Certain countries only), P27/P59 or 950 and R10/R38//646/774/781 or 794 in conjunction with Code 950 in conjunction with Code P59	★	★	★	★	★		409,50 787,50
P59	Urban 1R2, 2R9, 3R7 possible (only Germany) Not in conjunction with Code 950,P27,P84 Only in conjunction with Code 280, R10,R11,R38,R48,25R,44R,646,781 or 794 und 101A,108A,361A,368A,801A,804A,808A	- U -	- U -	U - -	- U -	U - -	- - ●	1128,75 1312,50 546,00
P84	Sport Not in conjunction with Code 213, 483, P27, P34, P59, U37 Only in conjunction with Code 280, 486, 51U, 651A oder (P39+811A), 774, 772	-	-	-	-	-	●	2966,25
U59	Seat Comfort package Not in conjunction with upholstery 001A in conjunction with Code P27, P59, 950, P34, P39	●	●	●	●	●	●	141,75 0,00
U62	Light and Sight package only in conjunction with Code 345, 543, U25 in conjunction with Code P27, P59, 950, P34, P39	●	●	●	●	●	●	304,50 378,00
U63	Driving school package Not in conjunction with Code 310 Only in conjunction with Code U59, U62, 931, 510/512/523 oder 527 only LHD	●	●	●	●	●	●	519,75
494	US version	-	-	-	-	-	●	451,50
498	Japanese version	-	-	-	●	●	●	472,50
709	SKD vehicles for India	○	-	-	○	-	-	0,00
03U	Travel and restaurant guide Certain countries only Only in conjunction with Code 512/527	●	●	●	●	●	●	105,00
202	Literature in German	○	○	○	○	○	○	0,00
205	Literature in English	○	○	○	○	○	○	0,00
206	Literature in Italian	○	○	○	○	○	○	0,00
207	Literature in French	○	○	○	○	○	○	0,00
208	Literature in Spanish	○	○	○	○	○	○	0,00
209	Literature in Portuguese	○	○	○	○	○	○	0,00
210	Swedish literature	○	○	○	○	○	○	0,00
213	Direct-steer system Not in conjunction with Code P84 Only in conjunction with Code 483	○	○	○	○	○	○	0,00
218	Reversing camera Not in conjunction with Code 516	●	●	●	●	●	●	304,50
228	Auxiliary heater only LHD	●	●	●	●	●	●	1312,50
234	Blind Spot Assist Certain countries only Certain countries only in conj. with Code 509 or 512 or 527 Only in conj. with Code 22P	○	○	○	○	○	○	0,00
235	Active Parking Assist	●	●	●	●	●	●	708,75
239	DISTRONIC PLUS Certain countries only Not in conjunction with Code 252 or 440 Only in conjunction with Code 429	●	●	●	●	●	●	903,00
241	Front seat left, elect.adjust.w.mem. switch not in conjunction with Code 001A	●	●	●	●	●	●	294,00

	Only in conjunction with Code 275 Right-hand-drive vehicles only							
242	Front pass. seat, electrically adj. with memory function LHD version Not in conjunction with Code 001A Only in conjunction with Code 275	●	●	●	●	●	●	294,00
249	Automatically dimming int.and ext.mirrors Only in conjunction with Code P49	○	○	○	○	○	○	0,00
252	COLLISION PREVENTION ASSIST Certain countries only Not in conjunction with Code 239	S	S	S	S	S	S	0,00
25R	10-spoke 43.2 cm (17") light-alloy wheels Only in conjunction with Code 645	- - ●	- - ●	- ● -	- - ●	- ● -	○ - -	0,00 693,00 955,50
260	Omission of model plate on boot lid	○	○	○	○	○	○	0,00
263	Number plate mounting for Asia/Mexico	○	○	○	○	○	○	0,00
264	Number plate mounting for America	○	○	○	○	○	○	0,00
275	Driver's seat, electrically adjustable with memory function Not in conjunction with Code 001A Only in conjunction with Code U22, U59	●	●	●	●	●	●	351,75
280	Multifunction steering wheel i.V.m. P59,950,P34,P39	● ○	● ○	● ○	● ○	● ○	● ○	183,75 0,00
286	Luggage net on driver's and front pass. backrest Only in conjunction with Code 30P	○	○	○	○	○	○	0,00
290	windowbags	S	S	S	S	S	S	0,00
293	Sidebags in rear	●	●	●	●	●	●	393,75
294	Kneebag	S	S	S	S	S	S	0,00
299	PRE-SAFE® system	●	●	●	●	●	●	346,50
301	Smoker package	●	●	●	●	●	●	47,25
345	Windscreen wiper with rain sensor Only in conjunction with Code U62	○	○	○	○	○	○	0,00
347	Ecall emergency call system, Europe Certain countries only Only in conjunction with Code 512 or 527	○	○	○	○	○	○	0,00
348	mbrace Only in conjunction with Code 460 or 494	-	-	-	-	-	●	630,00
379	Telephone module with Bluetooth® (SAP profile) Only cert. Countries Only in conjunction with Code 386	●	●	●	●	●	●	462,00
386	Convenience telephony Only in conjunction with Code 510, 512, 523 or 527	●	●	●	●	●	●	367,50
400	Rear armrest Not in conjunction with Code 001A	●	●	●	●	●	●	173,25
413	Automatic panoramic sliding sunroof Not in conjunction with Code 970, 974, 975 Only in conjunction with Code 51U	●	●	●	●	●	●	924,00
428	Steering wheel shift buttons Only in conjunction with Code 429	○	○	○	○	○	○	0,00
440	Cruise control Not in conjunction with Code 239 in conjunction with Code 429	○ - -	- ● ○	- ● ○	- ● ○	- ● ○	S - -	0,00 262,50 0,00
442	Multifunction steering wheel	S	S	S	S	S	S	0,00
44R	43.2 cm (17-inch) 5-twin-spoke light-alloy wheels Not in conjunction with Code 950,P55, P84 Only in conjunction with Code R01	● - -	● - -	- - ●	● - -	- - ●	- ● -	1218,00 189,00 955,50

	in conjunction with Code P27	-	-	-	-	-	●	189,00
		●	●	●	●	●	-	472,50
	in conjunction with Code P59	●	●	●	●	●	●	136,50
460	Canada version/additional parts	-	-	-	-	-	●	551,25
461	Instrument with mileage reading	○	○	○	○	○	○	0,00
462	Instrument cluster with Asian characters Cert. countries only	○	○	○	○	○	○	0,00
474	Diesel particulate filter Part of standard specification in Germany and WEU countries	●	●	●	-	-	-	498,75
476	Lane keeping assist not in conjunction with Code 498 Only in conjunction with Code 22P and Code 280	○	○	○	○	○	○	0,00
477	Tyre pressure loss warning system	S	S	S	S	S	S	0,00
483	dynamic handling package Not in conjunction with Code P84 Only in conjunction with Code 213, 486	●	●	●	●	●	●	288,75
485	Comfort suspension Not in conjunction with Code 950	S	S	S	S	S	S	0,00
486	Sports suspension Only in conjunction with Code 483 (not valid for code P84)	○	○	○	○	○	○	0,00
500	Electrically folding exterior mirrors Only in conjunction with Code P49	○	○	○	○	○	○	0,00
502	3 years of free map updates Certain countries only Only in conjunction with Code 512 or 527	○	○	○	○	○	○	0,00
508	Pre-installation for Becker® MAP PILOT (C. coun. on.); on. in conj. w. Code 510/523 Not in conjunction with Code B56	●	●	●	●	●	●	231,00
509	Becker® MAP PILOT (Certain countries only); only in conjunction with Code 510 or 523 Not in conjunction with Code B56 required with code 22P for certain countries (additional price)	●	●	●	●	●	●	756,00
510	Audio 20 CD with 6-disc CD changer in conjunction with Code P84	●	●	●	●	●	●	525,00
		-	-	-	-	-	●	157,50
512	COMAND Online with 6-disc DVD changer (& in c. c. on. icw Code 513) in conjunction with Code P84	●	●	●	●	●	●	3202,50
		-	-	-	-	-	●	3097,50
513	Road sign recognition system (Certain c. only); only in conj. w. Code 512 /527	○	○	○	○	○	○	0,00
516	Audio 5 USB Not in conjunction with Code 218/234/310/386/498/518/537/810/830/950/22P/P34/B56 oder U63 Only LHD models	S	S	S	S	S	S	0,00
518	Media Interface Not in conjunction with Code B56 only in conjunction with Code 510, 512, 526 or 527	●	●	●	●	●	●	231,00
51U	Headlining in black fabric Only in conjunction with Code 413, 950, P27, P34 or P59	○	○	○	○	○	○	0,00
523	Audio 20 CD Not in conjunction with Code 513,518,537,810,830 Standard Certain countries only (RHD) in conjunction with Code P84	●	●	●	●	●	●	367,50
		-	-	-	-	-	○	0,00
526	Comand DVD (without navigation) Only in conjunction with Code 498	-	-	-	●	●	●	1155,00
527	COMAND Online (cert. c. o. in con. w. Code 513) Certain countries only in conjunction with Code P84	●	●	●	●	●	●	2887,50
		-	-	-	-	-	●	2782,50
537	Digital radio (DAB)	●	●	●	●	●	●	430,50

	(C. c. on.) & not in conj. w. Code Z97 Only in conjunction with Code 510, 512 or 527							
538	ATTENTION ASSIST	S	S	S	S	S	S	0,00
543	Sun visors with illuminated vanity mirrors Only in conj. with Code U62	○	○	○	○	○	○	0,00
550	Trailer coupling Not in conjunction with Code 460,494,772,950	●	●	●	●	●	●	829,50
551	Anti-theft warning system Only in conjunction with Code P54 in conjunction with Code P54 For certain count. scope of delivery of Code P54	○	○	○	○	○	○	262,50 0,00
55R	40.6 cm (16-inch) 10-spoke light-alloy wheels Not in conjunction with Code 950,P55, P59 in conjunction with Code P27	- ●	- ●	● -	- ●	● -	- -	483,00 745,50 0,00
580	Air conditioning system	S	S	S	S	S	S	0,00
581	THERMOTRONIC automatic climate control	●	●	●	●	●	●	535,50
58U	Grey fabric roof liner Not in conjunction with Code 413 or 950 or P27 in conjunction with Code 455A or P34 in conjunction with Code 804A or P59	S	S	S	S	S	S	0,00
600	Headlamp cleaning system Only in conj. w. Code 614 or 618, 621 or 622	○	○	○	○	○	○	0,00
608	Adaptive Main Beam Assist Only in conjunction with Code 621 or 622	○	○	○	○	○	○	0,00
613	Headlamps for RHD vehicles Part of standard specification for LHD countries	○	○	○	○	○	○	0,00
614	Bi-xenon headlamps Only in conjunction with Code 600	●	●	●	●	●	●	887,25
618	Bi-Xenon headlamps for left-hand traffic Only icw Code 600	●	●	●	●	●	●	887,25
621	Intelligent Light System (RHD veh.) Not in conjunction with Code U37 Only in conjunction with Code 600	●	●	●	●	●	●	1470,00
622	Intelligent Light System Not in conjunction with Code U37 Only in conjunction with Code 600	●	●	●	●	●	●	1470,00
625	Australia specification	●	●	●	●	●	●	131,25
634	Omission of first-aid kit Not in conjunction with Code 820	○	○	○	○	○	○	0,00
636	Omission of warning triangle Not in conjunction with Code 820	○	○	○	○	○	○	0,00
643	40.6 cm (16-inch) steel wheels with 10-hole trim Not in conjunction with P27, P59, 950 or P55 in conjunction with Code 483	- ●	- ●	S -	- ●	S -	- -	0,00 262,50 0,00
645	winter (M+S) wheel and tyre assembly x 4 Only in conjunction with Code R00, 643, 55R or 25R	●	●	●	●	●	●	115,50
646	45.7 cm (18-inch) AMG multi-spoke light-alloy wheels Only in conjunction with Code R01 and R66 in conjunction with Code 950 in conjunction with Code P27 in conjunction with Code P55 in conjunction with Code P59	- - ●	- - ●	- ● -	- ● -	- ● -	● - -	1102,50 2005,50 2268,00 367,50 1102,50 1522,50 472,50 1102,50
666	Prod. prot. f. freight pkging w/o tie-down hooks	●	●	●	●	●	●	26,25

	Certain countries only in conjunction with Code 14P, 15P or 16P	○	○	○	○	○	○	0,00
668	Prod. prot. f. freight pkging with tie-down hooks Certain countries only Not in conjunction with Code 820 in conjunction with Code 14P, 15P or 16P	●	●	●	●	●	●	26,25
682	Fire extinguisher Not in conjunction with Code 932 (LHD) or 939 (RHD)	○	○	○	○	○	○	0,00
687	Type plate with model year	○	○	○	○	○	○	0,00
690	Vorrüstung für das Reserverad Certain countries only Only in conjunction with Code E76 and B12	○	○	○	○	○	○	0,00
762	Remote control unit	○	○	○	○	○	○	0,00
763	Radio remote control with panic switch Only in conjunction with Code 551 and Certain countries only	○	○	○	○	○	○	0,00
772	AMG bodystyling Not in conjunction with Code 550, U37 Only in conjunction with Code 950	○	○	○	○	○	○	0,00
774	45.7 cm (18-inch) AMG 5-spoke light-alloy wheels Not in conjunction with Code R66 Only in conjunction with Code P84 and R01	-	-	-	-	-	○	0,00
781	45.7 cm (18-inch) AMG 5-twin-spoke light-alloy wheels Only in conjunction with Code R01 and R66 in conjunction with Code 950 in conjunction with Code P27 in conjunction with Code P55 in conjunction with Code P55 and 950 in conjunction with Code P59	- ● - ● ● - ● ○ ●	- ● - ● ● - ● ○ ●	● - - ● ● - ● ○ ●	- ● - ● ● - ● ○ ●	- - - ● - ● ○ ●	1774,50 2037,00 871,50 262,50 1291,50 871,50 367,50 0,00 871,50	
791	45.7 cm (18-inch) AMG multi-spoke light-alloy wheels Not in conjunction with Code P55 Only in conjunction with Code 950, R01 and R66	○	○	○	○	○	○	0,00
794	45.7 cm (18-inch) AMG 5-twin-spoke light-alloy wheels Only in conjunction with Code R01 and R66 in conjunction with Code 950 in conjunction with Code P27 in conjunction with Code P55 in conjunction with Code P59	- ● - ● ● - ● ● ●	- ● - ● ● - ● ● ●	● - - ● ● - ● ● ●	- ● - ● ● - ● ● ●	- - - ● - ● ○ ●	1774,50 2037,00 871,50 262,50 1291,50 871,50 367,50 871,50	
803	Technical modifications	○	○	○	○	○	○	0,00
810	Harman Kardon® Logic 7® surround sound system not in conjunction with code 970, 974, 975 Only in conj. with Code 510, 512, 526 or 527 or (523 i.c.w. 460/494)	●	●	●	●	●	●	693,00
817	Alarm for anti-theft warning system Only in conjunction with Code P54 and Certain countries only	○	○	○	○	○	○	0,00
820	Tourist vehicles	○	○	○	○	○	○	0,00
822	Addit. parts for South African vehicles	○	○	○	○	○	○	0,00
823	Add.parts for Swiss vehicles	○	○	○	○	○	○	0,00
824	Reduction of power	○	-	○	-	-	-	0,00
829	Taiwan vehicles, additional parts	-	-	○	○	-	○	0,00
830	Vehicles for China, additional parts	-	-	-	○	○	○	0,00
831	Italy vehicles, additional parts	○	○	○	○	○	○	0,00

835	Vehicles for South Korea, additional parts	○	○	○	○	○	○	0,00
840	heat-insulating dark-tinted glass Certain countries only in conjunction with Code P55	●	●	●	●	●	●	231,00
862	Preinstallation for TV Only in conjunction with Code 498 and 526	-	-	-	●	●	●	84,00
873	Heated front seats in conjunction with Code P34, P39	○	○	○	○	○	○	304,50 0,00
875	Heated windscreen washer system	●	●	●	●	●	●	120,75
880	Centr. interlock system w/infrared remote control Only in conjunction with Code P34, P39	○	○	○	○	○	○	0,00
882	Interior motion sensor Only in conjunction with Code P54	○	○	○	○	○	○	0,00
885	Enhanced anti-theft protection only 537L	○	○	○	○	○	○	0,00
912	Special unit for noise and vibration mitigation	○	○	○	○	○	○	0,00
913	Engine fittings for air conditioner Certain countries only	○	○	○	-	-	-	0,00
918	Catalytic converter for leaded fuel Only in conjunction with Code 429	-	-	-	○	○	-	0,00
926	Emission control EU4 technology Certain countries only	-	-	-	○	○	○	0,00
927	Emission control system with EURO 6 technology Certain countries only	-	-	-	S	S	S	0,00 525,00
928	Emission control system with EU5 technology Certain countries only	S	S	S	○	○	○	0,00
931	Tandem interior mirror Only in conjunction with Code U63 (only LHD)	○	○	○	○	○	○	0,00
932	Storage compartment front seat left Not in conjunction with Code 682 (only LHD) Only in conjunction with Code 30P	○	○	○	○	○	○	0,00
939	Storage compartment under right driver's seat Not in conjunction with Code 682 (only RHD) Only in conjunction with Code 30P	○	○	○	○	○	○	0,00
966	CoC document EU5 without Reg. Cert. Part II	○	○	○	○	○	○	0,00
967	COC document EU5 with Reg. Cert. Part II	○	○	○	○	○	○	0,00
968	CoC document EU6 without Reg. Cert. Part II valid from code 804	-	○	-	U ★	U ★	U ★	0,00
969	COC document EU6 with Reg. Cert. Part II valid from Code 804	-	○	-	U ★	U ★	U ★	0,00
981	Omission of German log book and w/o GOP No.	○	○	○	○	○	○	0,00
986	ID no. (US-VIN) Certain countries only	○	○	○	○	○	○	0,00
989	Identification label under windshield	○	○	○	○	○	○	0,00
997	Exhibition vehicle	○	○	○	○	○	○	0,00
B03	ECO start/stop function	S	S	S	S	S	S	0,00
B08	Fanfares for Asia Certain countries only	○	○	○	○	○	○	0,00
B12	Tyre-change tool kit (Certain countries only) not Germany or in conjunction with code 690	●	●	●	●	●	●	31,50
B22	Drive Kit for the Apple® iPhone® 4/4S Only in conjunction with Code 516 Only LHD models	●	●	●	●	●	●	246,75
B24	remote control for auxiliary heater Certain countries only Only in conjunction with Code 228	○	○	○	○	○	○	0,00
B51	TIREFIT (Certain countries only)	S	S	S	S	S	S	0,00

B56	Drive Kit Plus für das Apple® iPhone® Not in conjunction with Code 516, 508, 509 or 518 Only LHD models and Certain countries only	●	●	●	●	●	●	609,00
E76	Spare wheel Certain countries only Only in conjunction with Code 690	●	●	●	●	●	●	240,45
K08	Radio frequencies for South America Certain countries only Only in conjunction with Code 510, 512, 523 or 527	○	○	○	○	○	○	0,00
K10	Software control for the active light function	○	○	○	○	○	○	0,00
K11	Adaptive brake lights Certain countries only	S	S	S	S	S	S	0,00
R00	38.1 cm (15-inch) steel wheels with 10-hole trim Not in conjunction with Code 483,486,R66,950,P27,P55,P59	S	S	-	S	-	-	0,00
R01	Summer tyres Only in conjunction with Code 643, R00, R10, R11, R38,R43, R48, 44R, 55R, 774, 781,791	S	S	S	S	S	S	0,00
R02	All season tyres	●	●	●	●	-	-	115,50
R10	45.7 cm (18-inch) 5-twin-spoke light-alloy wheels Not in conjunction with Code 950 Only in conjunction with Code R01 und R66 in conjunction with Code P27 in conjunction with Code P55 in conjunction with Code P59	-	-	●	-	●	-	1354,50
		●	●	-	●	-	-	1617,00
		-	-	-	-	-	●	525,00
		-	-	-	-	-	●	525,00
		●	●	●	●	●	-	871,50
		○	○	○	○	○	○	0,00
R11	43.2 cm (17-inch) 5-twin-spoke light-alloy wheels Not in conjunction with Code 950 or P55 Only in conjunction with Code R01 in conjunction with Code P27 in conjunction with Code P59	●	●	-	●	-	-	1165,50
		-	-	-	-	-	●	136,50
		-	-	●	-	●	-	903,00
		-	-	-	-	-	●	136,50
		●	●	●	●	●	-	420,00
		○	○	○	○	○	○	0,00
R38	45.7 cm (18-inch) 5-twin-spoke light-alloy wheels Not in conjunction with Code 950 Only in conjunction with Code R01 and R66 in conjunction with Code P27 in conjunction with Code P55 in conjunction with Code P59	-	-	●	-	●	-	1218,00
		●	●	-	●	-	-	1480,50
		-	-	-	-	-	●	315,00
		-	-	-	-	-	●	315,00
		●	●	●	●	●	-	735,00
		●	●	●	●	●	●	136,50
R43	43.2 cm (17-inch) 10-spoke light-alloy wheels Not in conjunction with Code 950,P55,P59 Only in conjunction with Code R01	-	-	-	-	-	S	0,00
		-	-	-	-	-	-	
		-	-	●	-	●	-	
		-	-	-	-	-	●	273,00
		●	●	●	●	●	-	609,00
		●	●	●	●	●	●	189,00
R48	43.2 cm (17-inch) 5-twin-spoke light-alloy wheels Not in conjunction with Code 950 or P55 Only in conjunction with Code R01 in conjunction with Code P27 in conjunction with Code P59	●	●	-	●	-	-	1302,00
		-	-	-	-	-	●	273,00
		-	-	●	-	●	-	1039,50
R66	Tyres with run-flat capability Not in conjunction with Code R00, 774 in conjunction with Code 646, 781, 791 or 794	-	-	-	-	-	-	
		●	●	●	●	●	●	136,50
		○	○	○	○	○	○	0,00
		○	○	○	○	○	○	
		○	○	○	○	○	○	
		○	○	○	○	○	○	0,00

U01	Belt buckle with switch Certain countries only	S	S	S	S	S	S	0,00
U12	Velour floor mats Not in conjunction with Code U64, 950 or P34	●	●	●	●	●	●	84,00
U18	Automatic child seat recognition	●	●	●	●	●	●	52,50
U22	4-way lumbar support Only in conjunction with Code U59 in conjunction with Code P34 oder P39	●	●	●	●	●	●	162,75
		○	○	○	○	○	○	0,00
U25	Illuminated door sill panels Only in conjunction with Code U62	○	○	○	○	○	○	0,00
U26	AMG floor mats Not in conjunction with Code U64, P34, P84 Only in conjunction with Code 950	○	○	○	○	○	○	0,00
U35	12 V socket in load area Only in conjunction with Code 30P	○	○	○	○	○	○	0,00
U37	Front fog lamps Not in conjunction with Code 950,772, 621 or 622	●	●	●	●	●	●	194,25
U60	Pedestrian protection Certain countries only	S	S	S	S	S	S	0,00
U64	Full driving school package including Code U63 Not in conjunction with Code 429 or U12, U26 only LHD	-	●	●	●	●	-	1149,75
U65	Additional exterior mirror Contains: Code U63 only LHD	●	●	●	●	●	●	52,50
Y05	designo seat belts, red Not in conjunction with Code P84 (Scope of delivery of Code P84) in conjunction with Code P84	●	●	●	●	●	●	315,00
		○	○	○	○	○	○	0,00
Z97	Electronic interface not in conjunction with code 537, 965, 970, 974, 975 Only LHD models and Certain countries only	●	●	●	●	●	●	399,00