

**From Price list B-Class TAXI**
**11/11/2016 CY 17/0, MY 808, SR 09. January 2017**
**National Standard**
**Not for Greece**
**Delta to NST**

● available at extra charge    ○ available at no extra charge    U annotations existing  
S standard equipment    - not available

\*BM 246.245 only for South-Korea

Code	Designation	Sportstour			LLP
L	Left-hand drive	○	○	○	0,00
R	Right-hand drive	●	●	-	1113,00
175U	elbaite green metallic	●	●	●	619,50
191U	cosmos black metallic	●	●	●	619,50
589U	jupiter red	○	○	○	0,00
623U	light ivory	○	○	○	0,00
	1_only for certain countries 2_not in conjunction with Code 950				
650U	cirrus white	○	○	○	0,00
662U	designo mountain grey magno	-	-	-	1837,50
696U	night black	○	○	○	0,00
761U	polar silver metallic	●	●	●	619,50
787U	mountain grey metallic	●	●	●	619,50
890U	cavansite blue metallic	●	●	●	619,50
895U	canyon beige metallic	●	●	-	619,50
990U	orient brown metallic	●	●	●	619,50
001A	fabric Venlo	○	○	-	0,00
	1_not in conjunction with Code 248, 400, 950, P27, P34, P39, P59, U57 or U59 3_for certain countries only				
031A	Vianen fabric black	○	○	○	0,00
	1_only in conjunction with Code U59 (except B 250 e) 2_not in conjunction with Code 248, 950, P34, P39, P51, P59 3_Code U59 optional				
038A	Vianen fabric crystal grey / black	○	○	○	0,00
	1_only in conjunction with Code U59 (except B 250 e) 2_not in conjunction with Code 248, 950, P34, P39, P51, P59 3_Code U59 optional				
105A	sahara beige ARTICO man-made leather TAXI - Delta to NST code 105A (260 EUR) 1_only in conjunction with Code U59 2_not in conjunction with Code 58U, 950, P34, P39, P51 3_in conjunction with Code 965: Code 450 only with Code U59 and Code 248 or U57. Not in conjunction with Code 950, P34 or P39 i.V.m. Code P27, P59	●	●	●	0,00
111A	ARTICO man-made leather black National standard 1_only in conjunction with Code U59 2_not in conjunction with Code 950, P34, P39, P51 3_in conjunction with Code 965: Code 450 only with Code 248 or U57. Not in conjunction with Code P34 i.V.m. Code P27, P59	●	●	●	0,00
118A	ARTICO man-made leather crystal grey / black TAXI - Delta to NST code 105A (260 EUR) 1_only in conjunction with Code U59 2_not in conjunction with Code 950, P34, P39, P51 3_in conjunction with Code 965: Code 450 only with Code 248 or U57. Not in conjunction with Code P34 i.V.m. Code P27, P59	●	●	●	0,00
121A	ARTICO man-made leather black 1_only in conjunction with Code P51 and U59 2_in conjunction with Code 965: Code 450 only in conjunction with Code U59. Not in conjunction with Code P34.	-	-	-	0,00
201A	leather black 1_only in conjunction with Code P34 and U59 2_not in conjunction with Code 248	○	○	○	0,00
204A	leather hazelnut brown / black 1_only in conjunction with Code P34 and U59	○	○	○	0,00

**B** Sportstour

246.212 B 180 d

246.208 B 200 d

242.848 B 200 c

	2_not in conjunction with Code 248 or 58U				
<b>207A</b>	<b>Leather cranberry red / black</b> 1_only in conjunction with Code P34 and U59 2_not in conjunction with Code 248 or 58U	○	○	○	<b>0,00</b>
<b>411</b>	<b>6-speed manual transmission</b> 1_not in conjunction with Code 239, 4U3 2_only for certain countries	S	S	-	<b>0,00</b>
<b>420</b>	<b>6-speed manual transmission</b> 1_only in conjunction with Code 4U3 2_not in conjunction with Code 239	U ★	-	S	<b>0,00</b>
<b>429</b>	<b>7G-DCT - dual clutch automatic transmission</b>  1_only in conjunction with Code 428 2_not in conjunction with Code U64, 4U3	- ●	- ●	- ●	<b>0,00</b> <b>1848,00</b>
<b>611A</b>	<b>ARTICO man-made leather / Montfoort fabric black</b> 1_only in conjunction with Code P59 and U59 2_not in conjunction with Code 248, P34 3_for certain countries only	○	○	○	<b>0,00</b>
<b>618A</b>	<b>ARTICO man-made leather / Montfoort fabric crystal grey / black</b> 1_only in conjunction with Code P59 and U59 2_not in conjunction with Code 248, P34 3_for certain countries only	○	○	○	<b>0,00</b>
<b>661A</b>	<b>ARTICO man-made leather / DINAMICA microfibre black</b> 1_only in conjunction with Code 950 and U59 2_not in conjunction with Code 248, P34 or P39	○	○	-	<b>0,00</b>
<b>671A</b>	<b>ARTICO man-made leather / DINAMICA microfibre black with crystal grey topstitching</b> 1_only in conjunction with Code PEK and U59	○	○	-	<b>0,00</b>
<b>821A</b>	<b>leather black RED CUT</b> 1_only in conjunction with Code P39 and U59 2_not in conjunction with Code 248	○	○	-	<b>0,00</b>
<b>22P</b>	<b>Lane Tracking package</b>  1_only in conjunction with Code 234, 476	●	●	●	<b>819,00</b>
<b>30P</b>	<b>Stowage Space package</b> 1_for LHD consisting of Code 286, 939, 932 oder 682 2_for RHD consisting of Code 286, 932, 939 oder 682	●	●	●	<b>199,50</b>
<b>4U3</b>	<b>BlueEFFICIENCY Edition</b>  1_only in conjunction with Code 420, 643, R00, R78, 55R, 677, 927. Not in conjunction with Code 213, 242, 248, 275, 413, 550, 810, 950, B59, P34, P55, P59, U22, U57, 25R 2_only in conjunction with Code 420, 643, R00, R78, 55R, 677, 927. Not in conjunction with Code 213, 830, 950, B59, P55, P59, 25R 3_for certain countries only	U ★	-	-	<b>420,00</b>
<b>950</b>	<b>AMG Line</b>  1_only in conjunction with Upholstery Code: 201A, 204A, 207A, 661A. Code 821A only in conjunction with Code P39 and U59 2_Code 310 or 938 or U63. Code 543, 772, 280. Code 51U or Code 58U (Code 58U only in conjunction with Code P34) Code H74 or 736. Code U26 or with Code P34 U12 3_in conjunction with Code 677 or Code 485. (Code 482 for certain countries only) 4_in conjunction with Code 678 or Code 646, 612 or 791 5_Not in conjunction with Code 623U, 4U3, 965, 450, P27 and P59	- - ●	- ● -	- - -	<b>2409,75</b> <b>2777,25</b> <b>2934,75</b>
<b>P27</b>	<b>Style</b>  1_only in conjunction with Code 031A, 038A, 111A, 115A, 118A. Code 201A, 204A and 207A only in conjunction with Code P34 and U59 2_Code 310, 543. Code 938 or U63. Code H53, 734 or 736. Code 55R or 01R, 25R, 44R, R43, R78, 646, 791, R15 3_not in conjunction with Code 950, P39 or P59 4_only in conjunction with Code R27, U59. Not in conjunction with Code P59  5_only in conjunction with Code 25R. Optional 04R, 69R or 39R (39R only i. c. with Code 645) . Code U59. Not in conjunction with Code P51 or P59 6_not in conjunction with Code 55R, Standard is here Code R43	- - ●	- ● -	- U - ★	<b>614,25</b> <b>850,50</b> <b>850,50</b> <b>1029,00</b> <b>1029,00</b>
<b>P34</b>	<b>Exclusive package</b>  1_consisting of Code 201A, 204A or 207A. Code 280, 873, U22, U59	●	●	●	<b>2215,50</b> <b>2215,50</b>

	2_Code 734, 736 or H74 i.c.w. Code 950. Code 880 or 889, 893. Code U12. Code 837 only in conjunction with Code 965/450. 3_not in conjunction with Code P39, 248 i.V.m. Code 950 i.V.m. Code 950 + R i.V.m. Code P27 i.V.m. Code P27 + R i.V.m. Code P51 i.V.m. Code P51 + R i.V.m. Code P59 i.V.m. Code P59 + R i. c. w. Right Hand Drive	● ● ● ● - - ● ● ●	● ● ● ● - - ● ● ●	- - - - - - - - -	1155,00 987,00 1732,50 1564,50 1155,00 987,00 1575,00 1407,00 2047,50
P39	AMG Exclusive package  1_only in conjunction with Code 950 and Upholstery Code 821A. Code H74 or 736. Code 880 or 889 or 893. Code 873, U22 and U26 or 837 2_not in conjunction with Code P27, P34 or P59 i. c. w. Right Hand Drive	●      ●	●      ●	-      -	1155,00      987,00
P49	Mirror package 1_consisting of Code 249, 500 2_only for certain countries	●	●	●	0,00
P51	Electric Drive package 1_only in conjunction with Code 121A. Code 201A/204A/207A only in conjunction with Code P34 and U59. Code 280, U12, 543, 04R, H81 or 734 or 736, 310 or 938 2_only with painting Code 650U 3_not in conjunction with Code P27 or P59 4_for certain countries only	-     -	-     -	-     -	2037,00
P54	Anti-Theft Protection package 1_consisting of Code 551, 882, 817 certain countries only 2_certain countries only, Standard in certain countries	●   -	●   -	●   -	430,50
P55	Night package  1_consisting of Code 840 (certain countries only), 01R 2_only in conjunction with Code P27, P59 or 950. Code 631 or 632. Code 01R or 646. Code 612 only in conjunction with with Code 950 3_not in conjunction with Code 965, U63, 4U3 i.V.m. Code 950 i.V.m. Code P59	- ●    ● ●	- ●    ● ●	- -    - -	787,50 945,00  409,50 787,50
P58	RANGE PLUS  1_only in conjunction with Code 597 (for certain countries only) or Code 337  2_only in conjunction with Code 840 (certain countries only) 3_not in conjunction with Code 537	-     -	-     -	-     -	787,50
P59	Urban  1_only in conjunction with Code 105A, 111A, 118A, 201A, 204A, 207A, 611A or 618A), 280, (310/938 or U63), 543, (H81/734 or 736) Code 485 or 677 or 482 2_Code R04 or R43, 01R, 25R, 44R, 646, 612 or 791. Not in conjunction with Code 498, 950, P27, P39 3_Code R04 or R43, 01R, R15, 25R or 44R . In case of Code 643 R78 or 55R is Code 645 possible with mentioned tires 4_not in conjunction with Code 950, P27, P39, P51 or 4U3 5_Code 04R, 25R, 69R or 39R i. V. Code 645	- U -   ★	- - U   ★	- - ●   -	829,50 1596,00 1412,25 1412,25 1596,00
PEK	WhiteArt Edition  1_consisting of Upholstery 671A, Paint 650U, 191U, 696U, 761U, 787U. H74 or H81. U66 or U26. U13 or 261. 280 or 277. Code RUT, RUU, 678. In conjunction with Code P55 Code 612, RUT or RUU. 2_only in conjunction with Code 950 3_not in conjunction with Code 58U, P34, P39, P59, 450, 965, 970, 974, 975, U63 4_for certain countries only i.V.m. Rechtslenker	●     ●	●     ●	-     -	945,00     777,00
U59	Seat comfort package  1_not in conjunction with upholstery 001A 2_in conjunction with Code 111A, 115A, 118A, 121A, 201A, 204A, 207A, 611A, 618A, 671A or P27 in scope of delivery i.V.m. Code 950,P27,P34,P39,P59,U63 i.V.m. Code P27,P34,P59,P51	- ●   ○ -	- ●   ○ -	S -   - -	0,00 0,00   0,00 0,00
U62	Light and sight package 1_consisting of Code 345, 543	●	●	●	341,25

	<b>i.V.m. Code U63</b>	-	○	-	<b>0,00</b>
<b>U63</b>	<b>Basic driving school package</b> 1_including Code U59, U62, 931 2_not in conjunction with Code 310, 840, P55, 965, 970, 974, 975 3_for certain countries only	●	●	●	<b>519,75</b>
<b>U66</b>	<b>Floormats special model</b> 1_only in conjunction with Code PEK (Cord floor mats edging in black and crystal grey contrasting topstitching and "EDITION" lettering)	○	○	-	<b>0,00</b>
<b>U90</b>	<b>Low-Line package China</b> 1_only for China	-	-	-	<b>0,00</b>
<b>U91</b>	<b>Mid-Line-package China</b> 1_only for China	-	-	-	<b>0,00</b>
<b>U92</b>	<b>High-Line-package China</b> 1_only for China	-	-	-	<b>0,00</b>
<b>494</b>	<b>USA specification</b>	-	-	-	<b>0,00</b>
<b>498</b>	<b>Japan specification</b> 1_not valid	-	-	-	<b>0,00</b>
<b>00B</b>	<b>Owner's Manual and Service Booklet - Danish</b>	○	○	○	<b>0,00</b>
<b>01B</b>	<b>Owner's Manual and Service Booklet - Dutch</b>	○	○	○	<b>0,00</b>
<b>01R</b>	<b>45.7 cm (18-inch) 5-twin-spoke light-alloy wheels</b>  1_in conjunction with Code R01 is Code R66 possible 2_not in conjunction with Code 645 is Code R66 not possible 3_not in conjunction with Code 950, 965 4_for certain countries only <b>i.V.m. Code P27</b>  <b>i.V.m. Code P55</b> <b>i.V.m. Code P59</b>	- ● - -  - ● ○ ●	● - - -  - ● ○ ●	- - - -  - - - -	<b>1249,50</b> <b>1512,00</b> <b>525,00</b>  <b>525,00</b> <b>892,50</b> <b>0,00</b> <b>525,00</b>
<b>02B</b>	<b>Owner's Manual and Service Booklet - German</b>	○	○	○	<b>0,00</b>
<b>03B</b>	<b>Owner's Manual and Service Booklet - Russian</b>	○	○	○	<b>0,00</b>
<b>04B</b>	<b>Owner's Manual and Service Booklet - Finnish</b>	○	○	○	<b>0,00</b>
<b>04R</b>	<b>45.7 cm (18-inch) multi-spoke light-alloy wheels</b>  1_not in conjunction with Code 965 2_only for certain countries <b>i.V.m. Code P27</b> <b>i.V.m. Code P51</b> <b>i.V.m. Code P59</b>	-  - - -	-  - - -	-  - - -	<b>1039,50</b>  <b>525,00</b> <b>0,00</b> <b>525,00</b>
<b>05B</b>	<b>Owner's Manual and Service Booklet - English</b>	○	○	○	<b>0,00</b>
<b>06B</b>	<b>Owner's Manual and Service Booklet - Italian</b>	○	○	○	<b>0,00</b>
<b>07B</b>	<b>Owner's Manual and Service Booklet - French</b>	○	○	○	<b>0,00</b>
<b>07U</b>	<b>MB apps for Audio 20 without MBCONNECT</b>  1_only in conjunction with Code 505, 520 or 522 2_not in conjunction with Code 11U	●	●	●	<b>52,50</b>
<b>08B</b>	<b>Owner's Manual and Service Booklet - Spanish</b>	○	○	○	<b>0,00</b>
<b>08R</b>	<b>43.2 cm (17-inch) multi-spoke light-alloy wheels</b>  1_only in conjunction with Code P59, R01 or R05	-	-	○	<b>0,00</b>
<b>09B</b>	<b>Owner's Manual and Service Booklet - Portuguese</b>	○	○	○	<b>0,00</b>
<b>10B</b>	<b>Owner's Manual and Service Booklet - Swedish</b>	○	○	○	<b>0,00</b>
<b>11B</b>	<b>Owner's Manual and Service Booklet - Arabic</b>	○	○	○	<b>0,00</b>
<b>11U</b>	<b>Remote Online</b>  1_only in conjunction with Code 360, 362 2_in scope of delivery from Code 531 3_not in conjunction with Code 07U <b>i.V.m. Code 531</b>	- ●  ○	- ●  ○	- ●  ○	<b>0,00</b> <b>157,50</b> <b>0,00</b>
<b>12B</b>	<b>Owner's Manual and Service Booklet - Engl. USA/CAN</b>	○	○	○	<b>0,00</b>
<b>12U</b>	<b>Concierge Service</b> 1_only in conjunction with Code 830, 362. Not in conjunction with Code U90	-	-	-	<b>0,00</b>
<b>13B</b>	<b>Owner's Manual and Service Booklet - Norwegian</b>	○	○	○	<b>0,00</b>
<b>13U</b>	<b>EV-Dienste für PlugIn-Fahrzeuge</b>  1_only in conjunction with Code 360 or 362 2_for certain countries only	-	-	-	<b>0,00</b>
<b>14B</b>	<b>Owner's Manual and Service Booklet - Greek</b>	○	○	○	<b>0,00</b>
<b>14U</b>	<b>Smartphone integration package</b>  1_only in conjunction with Code 16U, 17U 2_for certain countries standard with Code 531, 532 3_in conjunction with Code 531: Smartphone integration 4_for certain countries only <b>i.V.m. Code 531</b>	●  - -	●  - -	●  ○ ○	<b>315,00</b>  <b>0,00</b>

	<b>i.V.m. Code 531/532</b>	○	○	-	0,00
15B	<b>Owner's Manual and Service Booklet - Turkish</b>	○	○	○	0,00
15U	<b>Smartphone integration mirrorlink</b> 1_only in conjunction with Code 19U, 965	○	○	○	0,00
16B	<b>Owner's Manual and Service Booklet - Polish</b>	○	○	○	0,00
16U	<b>Apple CarPlay</b>	○	○	○	0,00
17B	<b>Owner's Manual and Service Booklet - Czech</b>	○	○	○	0,00
17U	<b>Android Auto</b> 1_only in conjunction with Code 14U, 505, 520, 522, 531, 532	○	○	○	0,00
18B	<b>Owner's Manual and Service Booklet - Engl. S. Am.</b>	○	○	-	0,00
18U	<b>Baidu Carlife</b> 1_only in conjunction with Code 830, 14U, 520 or 522	-	-	-	0,00
19B	<b>Owner's Manual and Service Booklet - French S. Am.</b>	○	○	-	0,00
19U	<b>Mercedes-Benz Link Taxi</b> 1_only in conjunction with Code 965 and 15U	●	●	●	157,50
1R1	<b>winter (M+S) wheel and tyre assembly x 4</b> 1_for certain countries only 2_only in conjunction with Code R00. Code 651 or 652 3_not in conjunction with Code 965, 970, 974, 975, P55, P27, P59, 950 or R66	●	-	-	577,50
1R2	<b>winter (M+S) wheel and tyre assembly x 4</b>  1_for certain countries only 2_only in conjunction with Code 651 or 652. 3_not in conjunction with Code 950	●	●	●	840,00
1R3	<b>winter (M+S) wheel and tyre assembly x 8</b>  1_for certain countries only 2_only in conjunction with Code 651 or 652	-	-	●	1323,00
20B	<b>Owner's Manual and Service Booklet - Spanish S. Am.</b>	○	○	-	0,00
213	<b>Sports Direct-Steer system</b> 1_only in conjunction with Code 677 or 459 2_only for certain countries 3_not in conjunction with Code 4U3	⓪	○	-	0,00
218	<b>Reversing camera</b> 2_only for certain countries	●	●	●	351,75
21B	<b>Owner's Manual and Service Booklet - Portug. S. Am.</b>	○	○	-	0,00
228	<b>Auxiliary heater</b>  1_for certain countries only in conjunction with Code B24 2_for certain countries only <b>i.V.m. Code 360/362</b>	-	●	●	1312,50
22B	<b>Owner's Manual and Service Booklet - Japanese</b>	○	○	-	0,00
232	<b>Garage door opener (frequency range 284-390 MHz)</b>  1_only in conjunction with Code P49, U62 2_for certain countries only	-	-	●	236,25
234	<b>Blind Spot Assist</b>  1_for certain countries only <b>i.V.m. Code 22P</b>	●	●	●	472,50
235	<b>Parking Pilot</b> 1_only for certain countries	○	○	○	0,00
239	<b>Distance Pilot DISTRONIC</b> 1_only in conjunction with Code 429 2_not in conjunction with Code 258 or 440 3_Certain countries only	●	●	●	708,75
23B	<b>Owner's Manual and Service Booklet - simpl. Chinese</b>	○	○	-	0,00
23Z	<b>Pre-installation for TETRA mobile radio, Motorola</b> 1_only in conjunction with Code 970, 974 or 975 2_LHD only	●	●	-	903,00
240	<b>LED-daytime running lights</b>	-	-	S	0,00
241	<b>Front seat left, electrically adjustable memory switch</b> 1_only in conjunction with Code 275 2_Right-hand-drive vehicles only 3_Not in conjunction with Code 001A	●	●	-	299,25
242	<b>Front passenger seat, electrically adjustable with memory function</b>  1_only in conjunction with Code 275 2_only for Left Hand Drive 3_not in conjunction with Code U57, 842 or 001A	●	●	●	299,25
245	<b>Compass</b> 1_only in conjunction with Code P49, U62, 460 or 494 2_only in conjunction with Code 249, 494 3_not in conjunction with Code 531	-	-	⓪	110,25
248	<b>Rear seats with integrated child seats</b> 1_only in conjunction with Code 105A, 111A or 118A 2_not in conjunction with Code U57, P34, P39 or 950	⓪	●	-	357,00

	3_not in conjunction with Code 4U3 4_for certain countries only <b>i.V.m. Code 965</b>	★				
		●	●	-		115,50
249	Interior mirror and driver's exterior mirror automatically dimming 1_only in conjunction with Code P49	○	○	○		0,00
24B	<b>Owner's Manual and Service Booklet - trad. Chinese</b>	○	○	-		0,00
24Z	<b>Pre-installation for TETRA mobile radio, Sepura</b> 1_only in conjunction with Code 970, 974 or 975 2_LHD only	●	●	-		147,00
258	<b>Active Brake Assist</b> 2_only for certain countries; Serie in bestimmten Ländern	S	S	S		0,00
25B	<b>Owner's Manual and Service Booklet - Korean</b>	○	○	-		0,00
25R	<b>43.2 cm (17-inch) 10-spoke light-alloy wheels</b>  1_only in conjunction with Code 645 (B 250 e is not possible with Code 645) 2_not in conjunction with Code 950, P51, P55 or 4U3 3_Please notice, that the design is other at the B 250 e <b>i.V.m. Code P27</b>  <b>i.V.m. Code P59</b>	- - - ●	- - ● -	- - - -		0,00 535,50 693,00 955,50
		- ● ○ -	- ● ○ -	- - - -		0,00 535,50 0,00 136,50
260	<b>Deletion of model plate on boot lid</b>  1_only for certain countries 2_Standard in Code 970, 974, 975	○	○	-		0,00
261	<b>Omission of emblem on front wing</b> 1_only in conjunction with Code PEK 2_not in conjunction with Code U13	○	○	-		0,00
263	<b>Number plate mounting for Asia / Mexico</b> 1_only for certain countries 2_not in conjunction with Code 968	○	○	-		0,00
264	<b>Number plate mounting for America</b> 1_only for certain countries 2_not in conjunction with Code 968	○	○	○		0,00
26B	<b>Owner's Manual and Service Booklet - Chinese Taiwan</b>	○	○	-		0,00
275	<b>Driver's seat, electrically adjustable with memory function</b>  1_only in conjunction with Code U22 and U59. Not in conjunction with Code 001A 2_not in conjunction with Code 4U3	U	●	●		362,25
		★				
277	<b>3-spoke multifunction sports steering wheel in leather, with flattened bottom section, perforations</b> 1_only in conjunction with Code PEK	○	○	-		0,00
280	<b>Leather multifunction steering wheel</b> 1_in conjunction with Code 950: Multifunction sports steering wheel in leather  2_in conjunction with Code PEK: 3-spoke multifunction sports steering wheel leather, flattened bottom section, black DINAMICA <b>i.V.m. Code P34, P51, P59</b> <b>i.V.m. P59, 950, P34, P39</b>	●  - ○	●  - ○	●  - ○		183,75  0,00 0,00
286	<b>Luggage net on driver's and front pass. backrest</b>  1_only in conjunction with Code 30P	○	○	○		0,00
290	<b>Windowbags</b>	S	S	S		0,00
293	<b>Sidebags in rear</b> 1_only for certain countries	●	●	●		393,75
294	<b>Kneebag</b> 1_for certain countries only	○	○	○		0,00
299	<b>PRE-SAFE® system</b> 1_for certain countries only	●	●	●		346,50
2R9	<b>Winter (M+S) wheel and tyre assembly x 4</b> 1_for certain countries only 2_only in conjunction with Code 651 or 652 3_not in conjunction with Code 4U3	●	●	-		1533,00
2U0	<b>Car2Go wiring harness and coding</b> 1_not in conjunction with Code 865	●	●	-		15,75
301	<b>Front and rear ashtray inserts including cover in the stowage compartments as well as cigarette light</b> 1_for certain countries only	●	●	●		47,25
309	<b>Cup holder</b> 1_only in conjunction with Code 835 and 429	○	○	-		0,00
30B	<b>Owner's Manual and Service Booklet - Slovenian</b>	○	○	○		0,00
310	<b>Cup holder</b>  1_not in conjunction with Code 938, U63 or P34 2_in case of P34 only available in conjunction with Code 950, P27 or P59	●	●	●		26,25

	i.V.m. Code 950,P27,P59	○	○	○	0,00
	i.V.m. Code P27, P51, P59	-	-	-	0,00
31B	Owner's Manual and Service Booklet - Hungarian	○	○	○	0,00
32B	Owner's Manual and Service Booklet - Bulgarian	○	○	○	0,00
333	Special instrument panel	●	●	●	84,00
	1_Only in conjunction with Code 965, 970, 974 or 975				
334	Two-way radio retainer in glove compartment	●	●	●	63,00
	1_Only in conjunction with Code 965, 970, 974 or 975				
	2_scope of delivery of Code 450 without Code 335 or 941				
	i.V.m. Code 450	○	○	○	0,00
335	Preinstallation for two-way radio in boot	●	●	○	63,00
	1_only in conjunction with Code 965, 970, 974 or 975				
	2_only in conjunction with Code 965			★	
	3_not in conjunction with Code 889 or 893				
336	Preinstallation for taximeter	●	●	●	57,75
	1_only in conjunction with Code 965, 970, 974 or 975				
337	Taximeter integrated in the rear-view mirror	●	●	●	871,50
	1_only in conjunction with Code 965				
	2_not in conjunction with Code 597				
33B	Owner's Manual and Service Booklet - Romanian	○	○	○	0,00
340	Roof sign for driving school	●	●	●	189,00
	1_only in conjunction with Code U63				
	2_LHD only				
341	Taxi roof sign	●	●	●	257,25
	1_only in conjunction with Code 965				
	2_not in conjunction with Code 342				
	3_for certain countries only				
342	Connection, taxi roof sign	●	●	●	73,50
	1_only in conjunction with Code 965				
	2_not in conjunction with Code 341, 413				
345	Windscreen wiper with rain sensor	○	○	○	0,00
	1_only in conjunction with Code U62				
34B	Owner's Manual and Service Booklet - Croatian	○	○	○	0,00
351	Mercedes-Benz emergency call system	○	○	○	0,00
	1_only in conjunction with Code 360, 362				
	2_for certain countries only				
356	Roof-mounted radio aerial	●	●	●	204,75
	1_only in conjunction with Code 965, 970, 974 or 975				
	i.V.m.Code 386,505,522,357,531	●	●	●	120,75
357	Garmin® MAP PILOT	●	●	●	525,00
	1_only in conjunction with Code 522				
	2_for certain countries only				
35B	Owner's Manual and Service Booklet - Latvian	○	○	○	0,00
360	Communications module (UMTS) for the use of Mercedes connect me services	S	S	S	0,00
	1_only in conjunction with Code 505, 520, 522, 531				
	2_for certain countries only				
362	Communications module (LTE) for the use of Mercedes connect me services	●	●	●	157,50
	1_for certain countries only				
367	Live Traffic Information	○	○	○	0,00
	1_only in conjunction with Code 360 and 522 or 531				
	2_for certain countries only				
36B	Owner's Manual and Service Booklet - Lithuanian	○	○	○	0,00
379	Car telephony	●	●	●	735,00
	1_not in conjunction with Code 386				
	2_for certain countries only				
37B	Owner's Manual and Service Booklet - Slovakian	○	○	○	0,00
386	Universal Telephony package	●	●	●	420,00
	1_only in conjunction with Code 505, 520, 522 or 531				
	2_not in conjunction with Code 379, 536, 537, 862 or 865				
	3_for certain countries only				
38B	Owner's Manual and Service Booklet - Estonian	○	○	○	0,00
39B	Owners manual and service record - Serbian	○	○	-	0,00
39R	40.6 cm (16-inch) 10-spoke light-alloy wheels	-	-	-	0,00
	1_in conjunction with Code R01 not in conjunction with Code P27, P51, P59.				
	In conjunction with Code 645 not with Code P51				
	2_not in conjunction with Code R66				
	3_only for certain countries				

3R1	winter (M+S) wheel and tyre assembly x 4 1_for certain countries only 2_only in conjunction with Code 651 or 652 3_not in conjunction with Code 950	●	●	-	1323,00
3R7	Winter (M+S) wheel and tyre assembly x 4 1_for certain countries only 2_only in conjunction with Code 651 or 652 3_only for the B-Class Electric Drive	-	-	-	1323,00
400	Rear armrest 1_not in conjunction with Code 001A in conjunction with Code U57	●	●	●	173,25
40B	Owners manual and service record - ukrainian	○	○	-	0,00
413	Panoramic sliding sunroof 1_only in conjunction with Code 543, 51U 2_not in conjunction with Code 342, 970, 974, 975 or 4U3	●	●	●	1202,25
428	Steering wheel shift paddles 1_nly in conjunction with Code 429	○	○	○	0,00
440	Cruise control 1_not in conjunction with Code 239	S	S	S	0,00
442	Multifunction steering wheel	S	S	S	0,00
450	Taxi version, international 1_only in conjunction with Code 105A, 111A, 118A, 121A, 201A, 204A, 207A, 965, 334 or 335, 837	●	●	●	0,00
459	Suspension with Adaptive Damping system 1_only in conjunction with Code 213, B59 2_not in conjunction with Code 482, 483, 485, 486, 550, 677, 4U3 i.V.m. Code 950	●	●	-	1092,00
460	Canada specification	-	-	-	0,00
461	Instrument cluster with display in miles and English lettering 1_for certain countries only	○	○	○	0,00
462	Instrument cluster with Asian characters 1_for certain countries only	○	○	-	0,00
474	Diesel particulate filter 1_not in conjunction with Code 926 2_Standard in certain countries	S	S	-	0,00
475	Tyre pressure monitoring system 1_Standard in certain countries für bestimmte Länder Serie	-	-	-	0,00
476	Lane Keeping Assist 1_only in conjunction with Code 280 2_not in conjunction with Code 234 i.V.m. Code 22P	●	●	●	472,50
477	Tyre pressure loss warning system 1_for certain countries only	○	○	-	0,00
482	Suspension with higher ground clearance 1_not in conjunction with Code 4U3	U	●	-	105,00
485	Comfort suspension 1_not in conjunction with Code 4U3 2_in conjunction with Code 950 possible, then omission 213	S	S	S	0,00
500	Electrically folding exterior mirrors 1_only in conjunction with Code P49 2_only for certain countries	○	○	○	0,00
505	Audio 20 CD 1_only in conjunction with Code 818 and Code 351 and 360 (for certain countries only)	●	●	●	52,50
513	Traffic Sign Assist 1_only in conjunction with Code 531 2_for certain countries only	○	○	○	0,00
518	Media Interface cable kit 1_not in conjunction with Code 14U with Code 505, 520, 522 2_for certain countries only	●	●	●	52,50
51U	Roof liner in black fabric 1_only in conjunction with Code 413, 950, P27, P34, P39, P51, P59. Or Code 105A or 111A in conjunction with Code 965	○	○	○	0,00
520	Audio 20 USB 1_only in conjunction with Code 351 and 360 (for certain countries only)	S	S	○	0,00
522	Audio 20 CD including preinstallation for Garmin® MAP PILOT	-	-	-	0,00



		●	●	●	315,00
	1_only in conjunction with Code 818				
	<b>i.V.m. Code 367</b>	●	●	●	420,00
524	<b>Transport protection</b>	●	●	●	168,00
	1_for certain countries only, not in conjunction with Code 820				
531	<b>COMAND Online</b>	●	●	●	2845,50
	1_consisting of Code 814 or 815. Code 351, 360, 367, 502, 513, 11U (for certain countries only)				
	<b>i.V.m. Code 367</b>	●	●	●	3108,00
532	<b>COMAND Japan</b>	-	-	-	1365,00
	1_only in conjunction with Code 815, 14U				
	2_for certain countries only				
536	<b>Sirius satellite radio</b>	-	-	●	367,50
	1_for certain countries only				
	2_not in conjunction with Code 386				
537	<b>Digital radio</b>	●	●	●	446,25
	1_only in conjunction with Code 505, 522 or 531				
	2_not in conjunction with Code 386, 597, P58, Z97				
	3_for certain countries only				
538	<b>ATTENTION ASSIST</b>	S	S	S	0,00
543	<b>Sun visor with illuminated vanity mirror</b>	○	○	○	0,00
	1_only in conjunction with Code 413, 950, P27, P51, P59 or U62				
550	<b>Trailer coupling with ESP® trailer stabilisation</b>	U ★	●	●	829,50
	1_not in conjunction with Code 4U3 for the B 180 d (246.212) For the B 180 (246.242) Code 4U3 is Code 550 possible				
	2_for certain countries only				
551	<b>Anti-theft alarm system</b>	●	●	●	262,50
	1_scope of delivery of Code P54 in certain countries				
	2_for certain countries only				
	<b>in Verbindung mit P54</b>	○	○	○	0,00
	For certain count. scope of delivery of Code P54				
552	<b>Anti-theft warning system</b>	-	-	○	0,00
	2_for certain countries only				
	2_only in conjunction with Code P54				
55R	<b>40.6 cm (16-inch) 10-spoke light-alloy wheels</b>	-	●	-	483,00
	<b>NATIONAL STANDARD</b>	●	-	-	745,50
	1_not in conjunction with Code 950, P55 or P59				
	2_in conjunction with Code R02 Code R66 not possible				
	i.V.m. Code P27	○	○	-	0,00
567	<b>Rear seat fore/aft adjustment</b>	○	○	-	0,00
	1_only in conjunction with Code U57				
580	<b>Air conditioning system</b>	S	S	S	0,00
	1_for certain countries only				
581	<b>THERMOTRONIC automatic climate control</b>	-	-	-	0,00
	1_only in conjunction with Code P27, P34, P59 or 950	●	●	U	535,50
	2_only in conjunction with Code P27 or P59			★	
	3_for certain countries only				
58U	<b>Roof liner in crystal grey fabric</b>	○	○	○	0,00
	1_not in conjunction with Code 413, 105A, 204A, 207A, P39, 950. In case of Code 950 only possible with Code P34				
597	<b>Windscreen, heated</b>	-	-	-	0,00
	1_only in conjunction with Code P58				
	2_not in conjunction with Code 537, 337				
5R3	<b>Complete winter (M+S) wheel-and-tyre assembly x 4</b>	●	●	-	2005,50
	1_for certain countries only				
	2_only in conjunction with Code 651 or 652				
	3_not in conjunction with Code R66, 4U3, 965				
600	<b>Headlamp cleaning system</b>	-	-	○	0,00
	1_only in conjunction with Code 614, 618, 621 or 622				
	2_for certain countries only				
608	<b>Adaptive Highbeam Assist</b>	-	-	U	105,00
	1_only in conjunction with Code 631 or 632	●	●	-	189,00
	2_only in conjunction with Code 621 or 622			★	
	3_for certain countries only				
612	<b>45.7 cm (18-inch) AMG 5-twin-spoke light-alloy wheels</b>	-	●	-	1774,50
		●	-	-	2037,00
		-	-	-	871,50
	1_only in conjunction with Code R01 or 645				
	2_in conjunction with Code 645 Code R66 is not possible				
	<b>i.V.m. Code 950</b>	●	●	-	262,50

	i.V.m. Code P27	●	●	-	1291,50
		-	-	-	871,50
	i.V.m. Code P55	●	●	-	367,50
	i.V.m. Code P55+950	○	○	-	0,00
	i.V.m. Code P59	●	●	-	871,50
613	<b>Headlamps for RHD vehicles</b> 1_not in conjunction with Code P55 2_Part of standard specification for LHD countries 3_for certain countries only	○	○	○	0,00
614	<b>Bi-xenon headlamps</b> 1_only in conjunction with Code 240 and 600	-	-	●	887,25
618	<b>Bi-xenon headlamps for left-side traffic</b> 1_only in conjunction with Code 240 and 600	-	-	●	887,25
620	<b>Halogen headlamps with integral LED daytime running lamps</b> 1_not in conjunction with Code P55 2_for certain countries only	○	○	-	0,00
621	<b>INTELLIGENT LIGHT SYSTEM for left-hand traffic</b> 1_only in conjunction with Code 240 and 600 2_for certain countries only	-	-	●	1470,00
622	<b>Intelligent Light System</b> 1_only in conjunction with Code 240 and 600 2_for certain countries only	-	-	●	1470,00
623	<b>Gulf States specification</b>	-	-	-	0,00
625	<b>Australia specification</b>	-	○	-	0,00
631	<b>LED High Performance headlamps</b>	●	●	-	918,75
632	<b>LED High Performance headlamp</b> 2_only for certain countries	●	●	-	918,75
634	<b>Omission of first-aid kit</b> 1_not in conjunction with Code 820 2_for certain countries only	○	○	○	0,00
636	<b>Omission of warning triangle</b> 1_not in conjunction with Code 820 2_for certain countries only	○	○	○	0,00
643	<b>40.6 cm (16-inch) steel wheels with 10-hole trim</b> 1_not in conjunction with Code 950, P27, P55 or P59 i.V.m. Code 450 oder 965	-	S	S	0,00 262,50
		○	-	-	0,00
645	<b>M+S winter tyres, set of 4</b> 1_only in conjunction with Code R00, 643, R78, 55R, 25R, 01R, 646, 612, 791 or 678 2_in case of Code R00, 01R, 612, 646, 678, 791, RUT, RUU not in conjunction with Code R66 3_only in conjunction with Code 643 or R27 4_only in conjunction with Code 39R	●	●	Ⓢ	115,50
				★	
646	<b>45.7 cm (18-inch) AMG multi-spoke light-alloy wheels</b> 1_only in conjunction with Code R01 or 645 2_in conjunction with Code 645 Code R66 not possible 3_not in conjunction with Code 965 i.V.m. Code 950 i.V.m. Code P27 i.V.m. Code P59 in conjunction with Code P55	-	-	-	1102,50 2005,50 2268,00
		●	●	-	367,50
		-	-	-	1102,50
		●	●	-	1522,50
		●	●	-	1102,50
		●	●	-	472,50
651	<b>Winter complete wheels fitted</b> 1_for certain countries only 2_only in conjunction with Code 1R1, 1R2, 2R9, 3R1, 5R3 3_only in conjunction with Code 1R2 or 1R3 4_only in conjunction with Code 3R7	○	○	Ⓢ	0,00
				★	
652	<b>Summer complete tyres fitted</b> 1_for certain countries only 2_only in conjunction with Code 1R1, 1R2, 2R9, 3R1, 5R3 3_only in conjunction with Code 1R2 or 1R3 4_only in conjunction with Code 3R7	○	○	Ⓢ	0,00
				★	
666	<b>Freight packaging without tie-down hooks</b> 1_not in conjunction with Code 820 2_for certain countries only in conjunction with Code 14P, 15P and 16P	●	●	●	0,00 0,00
668	<b>Prod. prot. f. freight pkging with tie-down hooks</b> 1_not in conjunction with Code 820 2_for certain countries only	●	●	●	26,25

	<b>i.V.m. 14P, 15P und 16P</b>	○	○	○	<b>0,00</b>
677	<b>Lowered comfort suspension</b> 1_only in conjunction with Code 213 2_not in conjunction with Code 970, 974, 975 3_in conjunction with 4U3 Code 213 is not possible <b>i.V.m. Code 4U3</b> <b>i.V.m. Code 950</b>	⓪ ★ ○ ○	●  - ○	-  - -	<b>304,50</b>  <b>0,00</b> <b>0,00</b>
678	<b>45.7 cm (18-inch) AMG 5-twin-spoke light-alloy wheels</b> 1_only in conjunction with Code 950 2_in conjunction with Code 645 Code R66 is not possible <b>3_optional in conjunction with Code PEK</b>	○	○	-	<b>0,00</b>
682	<b>Fire extinguisher</b> <b>NATIONAL STANDARD</b> <b>1_not in conjunction with Code 932 or 939</b> <b>2_for certain countries only</b>	●	●	●	<b>0,00</b>
687	<b>Type plate with model year</b>	○	○	○	<b>0,00</b>
690	<b>Collapsible spare wheel</b> 1_only in conjunction with Code E76, B12 2_for certain countries only	○	○	-	<b>0,00</b>
69R	<b>43.2 cm (17-inch) multi-spoke light-alloy wheels</b>  1_not in conjunction with Code P51 2_for certain countries only <b>i.V.m. Code P27</b> <b>i.V.m. Code P59</b>	-  - -	-  - -	-  - -	<b>535,50</b>  <b>136,50</b> <b>0,00</b>
70B	<b>Fluorescent jacket for driver</b>  1_for certain countries only 2_not in conjunction with Code 71B	●	●	●	<b>5,25</b>
71B	<b>Fluorescent jackets for driver and passengers</b> 1_for certain countries only 2_not in conjunction with Code 70B	●	●	●	<b>26,25</b>
723	<b>Retractable load compartment cover</b>	S	S	S	<b>0,00</b>
734	<b>Brown open-pore eucalyptus wood trim</b>  1_not in conjunction with Code 950 <b>i.V.m. Code P34</b>	●  ○	●  ○	●  ○	<b>288,75</b>  <b>0,00</b>
736	<b>black high-gloss ash wood trim</b>  <b>i.V.m. Code P34</b>	●  ○	●  ○	●  ○	<b>288,75</b>  <b>0,00</b>
762	<b>Remote control unit</b> 1_for certain countries only	○	○	-	<b>0,00</b>
763	<b>Key with Radio remote control with panic switch</b> 1_only in conjunction with Code 551 and certain countries only	○	○	○	<b>0,00</b>
772	<b>AMG bodystyling</b> 1_only in conjunction with Code 950	○	○	-	<b>0,00</b>
791	<b>45.7 cm (18-inch) AMG multi-spoke light-alloy wheels</b>  1_in conjunction with Code 645 Code R66 is not possible 2_not in conjunction with Code 965 <b>i.V.m. Code 950</b> <b>i.V.m. Code P27</b> <b>i.V.m. Code P59</b>	- ● - ● ● - ●	● - - ● ● - ●	- - - - - - -	<b>1638,00</b> <b>1900,50</b> <b>735,00</b> <b>136,50</b> <b>1155,00</b> <b>735,00</b> <b>735,00</b>
808	<b>Technical modifications</b>	○	○	○	<b>0,00</b>
810	<b>Harman Kardon® Logic 7® surround sound system</b> 1_only in conjunction with Code 505, 522, 531, 532 2_not in conjunction with Code 4U3 3_for certain countries only	●	●	●	<b>719,25</b>
814	<b>DVD changer</b> 1_only in conjunction with Code 531	●	●	●	<b>315,00</b>
815	<b>DVD player</b> 1_only in conjunction with Code 531 or 532	○	○	○	<b>0,00</b>
818	<b>CD player</b> 1_only in conjunction with Code 505 or 522	○	○	○	<b>0,00</b>
820	<b>Tourist vehicles</b> 1_not in conjunction with Code 634, 636, 666 or 668 2_for certain countries only	○	○	○	<b>0,00</b>
821	<b>Country code Brazil</b>	-	-	-	<b>0,00</b>
822	<b>South Africa specification</b>	○	○	-	<b>0,00</b>
823	<b>Indicator plate fixing Switzerland</b>	○	○	○	<b>0,00</b>
824	<b>Additional parts for cold countries</b> 2_for certain countries only	-	○	-	<b>0,00</b>
829	<b>Taiwan version</b>	○	○	-	<b>0,00</b>
830	<b>China specification</b>	-	-	-	<b>0,00</b>
831	<b>Indicator plate fixing Italia</b>	○	○	○	<b>0,00</b>

835	South Korea specification	-	○	-	0,00
837	Floor mats, rubber	●	●	●	189,00
	1_only in conjunction with Code 965 2_Scope of delivery of 450				
	i.V.m. Code 450	○	○	○	0,00
840	Heat-insulating dark-tinted glass	●	●	●	283,50
	1_only in conjunction with Code P27, P51, P58, P59 or 950 2_for certain countries only 3_scope of delivery from code P55				
	i.V.m. Code P55	○	○	-	0,00
842	Folding front passenger seat backrest	○	○	⚠	0,00
	1_only in conjunction with Code U57 2_only in conjunction with Code U59, not in conjunction with code 242 3_only for LHD models			★	
857	Media-Display	●	●	●	168,00
	1_only in conjunction with code 505 or 520, 522				
862	Preinstallation for TV	●	●	-	84,00
	1_only in conjunction with code 531 or 532 2_not in conjunction with Code 386 3_for certain countries only				
865	TV receiver	●	●	-	1039,50
	1_only in conjunction with Code 531 or 532 2_not in conjunction with Code 386 3_for certain countries only				
873	Heated front seats	●	●	●	304,50
	i.V.m. Code P34/P39	○	○	○	0,00
875	Heated windscreen washer system	●	●	●	120,75
	1_for certain countries only				
877	Ambient lighting	●	●	●	126,00
	1_only in conjunction with Code U62 and P27 or P34, P39, P51, P59 or 950				
880	Enhanced central locking system	○	○	○	0,00
	1_only in conjunction with Code P34 or P39 2_not in conjunction with Code 889 or 893				
882	Interior monitoring system	○	○	○	0,00
	1_only in conjunction with Code P54 2_for certain countries only				
885	Increased anti-theft protection	○	○	-	0,00
	1_for certain countries only				
889	KEYLESS-GO	●	●	●	472,50
	1_not in conjunction with Code 335, 880, 893 oder 965				
893	KEYLESS GO starting function	S	S	S	0,00
	1_not in conjunction with Code 335, 880 oder 889 2_nur für bestimmte Länder				
913	Air conditioning preinstallation for hot countries	○	○	-	0,00
	1_for certain countries only				
918	Catalytic converter for leaded fuel	-	-	○	0,00
	1_for certain countries only				
922	Reduced power version	-	-	-	0,00
	1_for certain countries only				
924	Monovalent natural gas drive Plus	-	-	S	0,00
	1_for certain countries only 2_not in conjunction with Code R00 or 01R				
926	Emission control system with EU4 technology	○	○	-	0,00
	1_for certain countries only				
927	EU6 emissions standard	S	S	S	0,00
	1_for certain countries only				
928	EU5 emission standard	-	-	-	0,00
	1_for certain countries only				
931	Tandem interior mirror	○	○	○	0,00
	1_only in conjunction with Code U63, 970, 974 or 975				
932	Storage compartment front seat left	○	○	○	0,00
	1_only in conjunction with Code 30P 2_only LHD models: not in conjunction with Code 682				
933	Engine for ethanol fuel E100	-	-	-	315,00
	1_for certain countries only				
934	Taxi/hire car emergency alarm system	●	●	●	257,25
	1_only in conjunction with Code 965				
938	Hands-free system	●	●	●	136,50
	1_only in conjunction with Code 965 2_not in conjunction with Code 310				

939	<b>Stowage box under front passenger seat</b> 1_only in conjunction with Code 30P 2_only RHD models: not in conjunction with Code 682	○	○	○	0,00
942	<b>Load compartment package</b> 1_only in conjunction with Code U35 2_scope of delivery Code U57 3_for certain countries only <b>in Verbindung mit U57</b>	●	●	●	68,25
		○	○	-	0,00
960	<b>Government version</b> 1_only LHD	○	○	○	0,00
962	<b>Preparation for signal unit (light bar)</b> 1_only in conjunction with Code 970, 974 or 975 2_for certain countries only	●	●	-	168,00
965	<b>Taxi and hire car</b> 1_not in conjunction with Code 889, U63, P55, R00, 01R, 646, 612, 791, 678, 889 or 950 <b>in conjunction with Code 450</b>	●	●	●	577,50
		○	○	○	0,00
966	<b>COC document EU5 without registration certificate part II</b> 1_only in conjunction with Code 928 2_for certain countries only	○	○	-	0,00
967	<b>COC document EU5 with registration certificate part II</b> 1_only in conjunction with Code 928 2_for certain countries only	○	○	-	0,00
968	<b>COC document EU6 without registration certificate part II</b> 1_only in conjunction with Code 927 2_for certain countries only	○	○	○	0,00
969	<b>COC document EU6 with registration certificate part II</b> 1_only in conjunction with Code 927 2_for certain countries only	○	○	○	0,00
970	<b>Preparation for police vehicle</b> 1_only in conjunction with Code 260 and Z90 2_not in conjunction with Code 413, 830, R00, U63 3_for certain countries only, LHD only 4_for certain countries only in conjunction with Code Z90	●	●	-	1039,50
974	<b>Preparation for fire service command vehicle</b> 1_only in conjunction with code 260 and Z90 2_not in conjunction with Code 413, 830, R00, U63 3_for certain countries only, LHD only 4_for certain countries only in conjunction with Code Z90	●	●	-	1039,50
975	<b>Preparation for emergency doctor vehicle</b> 1_only in conjunction with code 260, Z90 2_not in conjunction with Code 413, 830, R00, U63 3_for certain countries only, LHD only 4_for certain countries only in conjunction with Code Z90	●	●	-	1039,50
981	<b>Omission of vehicle registration document</b> 1_for certain countries only	○	○	○	0,00
986	<b>Identification no. (US-VIN)</b> 1_for certain countries only	○	○	○	0,00
989	<b>Identification label under windshield</b> 1_for certain countries only	○	○	○	0,00
997	<b>Exhibition vehicle</b> 1_only for certain countries	○	○	○	0,00
B02	<b>Fanfare horn, electronic, for India</b>	-	○	-	0,00
B03	<b>ECO start/stop function</b>	S	S	S	0,00
B08	<b>Fanfares for Asia</b> 1_for certain countries only	○	○	-	0,00
B12	<b>Tyre-change toolkit</b> 1_only in conjunction with Code 690/623 2_for certain countries only	●	●	●	31,50
B24	<b>remote control for auxiliary heater</b> 1_only in conjunction with Code 228 2_for certain countries only <b>i.V.m. Code 360/362</b>	-	○	○	0,00
		-	●	●	210,00
B30	<b>Charging cable for E/F-type (Mode 2) domestic plug socket 4 m</b> <b>1_not in conjunction with Code B34 or B90</b> 2_only for certain countries, Standard in certain countries	-	-	-	0,00
B31	<b>Charging cable for Type G (Mode 2) domestic plug socket 4m</b> <b>1_not in conjunction with Code B34 or B91</b> 2_only for certain countries, Standard in certain countries	-	-	-	0,00
B32	<b>Charging cable for 3-pin (IEC 60309 CEE, Mode 2) commercial plug socket 4 m</b> <b>1_not in conjunction with Code B34 oder B92</b> 2_only for certain countries	-	-	-	0,00

B34	<b>Charging cable for wallbox and public charging stations (faster charging, Mode 3)</b> 1_not in conjunction with Code B30, B31, B32, B90, B91 or B92 2_only for certain countries	-	-	-	0,00
B35	<b>120V portable charging cable (level 1, NEMA 5-15) 4m</b> 1_not in conjunction with Code B30, B31, B32 or B40 2_only for certain countries	-	-	-	0,00
B50	<b>Radar-based, recuperative brake system including steering wheel gearshift paddles</b>	-	-	-	367,50
B51	<b>TIREFIT</b> 1_for certain countries only i.V.m. Code 360	○	○	○	0,00
B53	<b>Acoustic ambient protection</b>	-	-	-	105,00
B59	<b>DYNAMIC SELECT</b> 1_not in conjunction with Code 4U3 i.V.m. Code 429/459/677/950	●	●	-	84,00
B90	<b>Combination of charging cable for E/F-type domestic plug socket (Mode 2) and charging cable (mode 3)</b> 1_not in conjunction with Code B30 or B34 2_only for certain countries	-	-	-	262,50
B91	<b>Charging cable BE 1363 incl. 7-PIN ICCA 32A</b> 1_not in conjunction with Code B30, B31, B32, B34, B90 or B92 2_only for certain countries	-	-	-	262,50
B92	<b>Chg. cbl. IEC 60309 CEE 16/3 INCL. 7-PIN ICCA 32A</b> 1_not in conjunction with Code B32 or B34 2_only for certain countries	-	-	-	262,50
E64	<b>ECALL RUSSLAND (GLONASS)</b> 1_for certain countries only	○	○	-	0,00
E76	<b>Spare wheel</b> 1_only in conjunction with Code 690 2_for certain countries only	●	●	-	262,50
H53	<b>Line-pattern trim</b> 1_only in conjunction with Code P27 without P34	○	○	○	0,00
H74	<b>Carbon fibre-look trim</b> 1_only in conjunction with Code 950 2_Standard for Code PEK	○	○	-	0,00
H81	<b>Sail-pattern trim</b> 1_only in conjunction with Code P51 or P59 without P34 2_optional in conjunction with Code PEK	○	○	○	0,00
H88	<b>honeycomb-look trim</b> 1_not in conjunction with Code 950, P27, P34, P39, P51 or P59	S	S	S	0,00
K08	<b>Radio frequencies for South America</b> 1_only in conjunction with Code 505, 520, 522 or 531 2_for certain countries only	○	○	-	0,00
K11	<b>Adaptive brake lights</b> 1_for certain countries only	S	S	S	0,00
K99	<b>Multi-purpose vehicle</b> 1_only in conjunction with Code 966, 967, 968 or 969	○	○	-	0,00
R00	<b>38.1 cm (15-inch) steel wheels with 10-hole</b> 1_not in conjunction with Code R66, 950, P27, P55, P59, 965, 970, 974 or 975 2_for certain countries only	S	-	-	0,00
R01	<b>Summer tyres</b> 1_only in conjunction with Code 01R, 643, R00, R04, R15, R43, R69, R78, 44R or 55R 2_only in conjunction with Code 04R, 25R, 39R, 69R 3_for certain countries only	○	S	○	0,00
R02	<b>All season tyres</b> 1_for certain countries only 2_only in conjunction with Code 494, 04R or 25R	●	●	-	115,50
R04	<b>43.2 cm (17-inch) 5-twin-spoke light-alloy wheels</b> 1_only in conjunction with Code R01, P59 2_only for certain countries	○	○	-	0,00
R05	<b>Tyres with optimised rolling resistance</b> 1_for certain countries only 2_only in conjunction with Code 643, R27, 08R, R00, R04, R15, R43, R69, R78, 26R, 44R or 55R 3_not in conjunction with Code R66	○	○	○	0,00
R15	<b>43.2 cm (17-inch) 5-twin-spoke light-alloy wheels</b>	-	●	-	1071,00

		● - -	1333,50
		- - -	168,00
	1_not in conjunction with Code P55, 950		
	2_for certain countries only		
	i.V.m. Code P27	- - -	168,00
		● ● -	913,50
	i.V.m. Code P59	● ● -	168,00
R27	40.6 cm (16") 7-twin-spoke light-alloy wheels NATIONAL STANDARD	- - ●	0,00
	1_not in conjunction with Code P59		
	i.V.m. Code P27	- - ○	0,00
R43	43.2 cm (17-inch) 10-spoke light-alloy wheels	- - -	0,00
		● - -	1165,50
		- ● -	903,00
	1_only in conjunction with Code R01		
	2_not in conjunction with Code 950 or P55		
	i.V.m. Code P59	○ ○ -	0,00
R66	Run-flat tyres	Ⓢ ● Ⓢ	220,50
	1_not in conjunction with Code R00, 39R		
	2_in conjunction with Code 646, 612, 791, 678 without Code 645	★	★
	i.V.m. 1R2, 1R3, 2R9, 3R7	- - ●	441,00
	i.V.m. 1R2, 2R9, 3R7, 3R1	● ● -	441,00
R69	43.2 cm (17-inch) 5-spoke light-alloy wheels	● - -	1260,00
		- - -	94,50
		- ● -	997,50
	1_not in conjunction with Code 950		
	2_for certain countries only		
	i.V.m. Code P27	● ● -	840,00
		- - -	94,50
	i.V.m. Code P59	● ● -	94,50
R78	40.6 cm (16-inch) 5-twin-spoke light-alloy wheels	- ● -	483,00
		● - -	745,50
	1_not in conjunction with Code 950, P55 or P59		
	i.V.m. Code P27	● ● -	136,50
RUT	45,7 cm (18-inch) AMG multi-spoke light-alloy wheels	○ ○ -	0,00
	1_only in conjunction with Code PEK, R01 or 645 (Serie for PEK)		
	2_in conjunction with Code R01 is Code R66 possible. With Code 645 is Code R66 not possible		
RUU	45,7 cm (18-inch) AMG multi-spoke light-alloy wheels	○ ○ -	0,00
	1_only in conjunction with Code PEK, R01 or 645 (optional for PEK)		
	2_in conjunction with Code R01 is Code R66 possible. With Code 645 is Code R66 not possible		
U01	Status display for rear seat belts in instrument cluster	S S S	0,00
	1_for certain countries only		
U03	Omission of decals for special models	○ ○ -	0,00
	1_only in conjunction with Code PEK		
	2_not in conjunction with Code U15		
U10	Automatic deactivation of front passenger airbag	- - -	0,00
		● ● ●	99,75
	1_for certain countries only		
U12	Velour floor mats	● ● ●	84,00
	1_not in conjunction with Code 450, P39		
	2_in conjunction with Code 950 only possible with Code P34		
	3_for certain countries only		
	i.V.m. Code P51	- - -	0,00
	in Verbindung mit P34	○ ○ ○	0,00
U13	"EDITION" badge on the wing	○ ○ -	0,00
	2_only in conjunction with Code PEK		
U15	Decals in matt white	○ ○ -	0,00
	1_only in conjunction with Code PEK and 650U		
	2_not in conjunction with Code U03		
U22	4-way lumbar support	● ● ●	162,75
	1_only in conjunction with Code U59		
	2_for certain countries only		
	i.V.m. Code P34	○ ○ ○	0,00
	i.V.m. Code P39	○ ○ -	0,00
U25	Door sill panels with "Mercedes-Benz" lettering, illuminated	● ● ●	157,50
	1_only in conjunction with Code U62		
	2_for certain countries only		
U26	AMG floor mats	○ ○ -	0,00

	1_only in conjunction with Code 950 without P34 2_optional in conjunction with Code PEK (Cord floor mats with edging in black and black contrasting topstitching as well as AMG lettering)				
U32	Two addit. keys for special vehicles 1_only in conjunction with Code 965, 970, 974 or 975	●	●	●	157,50
U35	Socket in load compartment  1_only in conjunction with Code 942	○	○	○	0,00
U40	Partition net 1_for certain countries only	●	●	●	204,75
U57	EASY-VARIO-PLUS-system 1_only in conjunction with Code 400, 567, 842, 942, U59 2_not in conjunction with Code 242, 248, 001A, B56 or 4U3 3_for certain countries only	●	●	-	593,25
U64	Full driving school package  1_in conjunction with Code U63 1_not in conjunction with Code 429	●	●	●	1207,50
U65	Additional exterior mirror right and left 1_only in conjunction with Code U63	●	●	●	126,00
Z83	Activation hill-start assist driving school 1_only in conjunction with Code U64	○	○	○	0,00
Z87	Monitor activation in special-purpose vehicles 1_only in conjunction with Code Z90 or 965	○	○	-	0,00
Z88	Deactivation of ext. lights, sp.-purpose vehicles  1_only in conjunction with Code 970	○	○	○	0,00
Z90	Multi-function control unit f.spec.funct.  1_only in conjunction with Code 970, 974 or 975	○	○	-	0,00
Z97	Electronic interface  2_only LHD models only 3_for certain countries only Not in conjunction with Code 537or 965 or 970 or 974 or 975	●	●	●	399,00