

**Valid from 20.05.2020 - MY 800 + 050**

● available at extra charge   ○ available at no extra charge   ◐ annotations existing  
S standard equipment   - not available

[illegible]

## Price list for the GLB

Valid from 20.05.2020 - MY 800 + 050

\* only South Korea

● available at extra charge    ○ available at no extra charge    U annotations existing  
S standard equipment    - not available

		GLB Offroad											
		247.610	247.612	247.613	247.614	247.615	247.684	247.687	247.644	247.646	247.647	247.651	LLP
		GLB 180 d	GLB 200 d	GLB 200 d 4MATIC	GLB 220 d	GLB 220 d 4MATIC	GLB 180	GLB 200	GLB 220 *	GLB 250	GLB 250 4MATIC	Mercedes-AMG GLB 35 4MATIC	
<b>Code</b>	<b>Designation</b>												
311A	<b>ARTICO man-made leather / Bertrix fabric black</b> 1_only in conjunction with code P27 and 7U2 2_not in conjunction with code 830	○	○	○	○	○	○	○	○	○	○	-	0,00
331A	<b>ARTICO man-made leather / Albury fabric black</b> 1_only in conjunction with code P59 and 7U2 2_not in conjunction with code 830	○	○	○	○	○	○	○	○	○	○	-	0,00
335A	<b>ARTICO man-made leather / Albury fabric macchiato beige / black</b> 1_only in conjunction with code P59 and 7U2 2_not in conjunction with code 830	○	○	○	○	○	○	○	○	○	○	-	0,00
379A	<b>ARTICO man-made leather/ Bertrix fabric, two-tone indigo blue / neva white</b> 1_only in conjunction with code P27 and 7U2 2_not in conjunction with code 830	○	○	○	○	○	○	○	○	○	○	-	0,00
384A	<b>ARTICO man-made leather / Albury fabric two-tone black / Bahia brown</b> 1_only in conjunction with code P59 and 7U2 2_not in conjunction with code 830	○	○	○	○	○	○	○	○	○	○	-	0,00
426	<b>8G-DCT</b> 1_AMG SPEEDSHIFT DCT 8 2_not in conjunction with code 429	S	S	S	S	S	-	-	S	S	S	S	0,00
429	<b>7G-DCT</b> 1_not in conjunction with code 426	-	-	-	-	-	S	S	-	-	-	-	0,00
651A	<b>ARTICO man-made leather/DINAMICA microfibre upholstery black</b> 1_only in conjunction with code 950 and 7U4 2_not in conjunction with code 830	○	○	○	○	○	○	○	○	○	○	S	0,00
22P	<b>Lane Tracking package</b> 1_only in conjunction with code 234 and 243 2_not in conjunction with code 23P	●	●	●	●	●	●	●	●	●	●	●	819,00
23P	<b>Driving Assistance package</b> 1_only in conjunction with code 233 and 299 and 275 or 221 or P49 2_not in conjunction with code 22P	●	●	●	●	●	●	●	●	●	●	●	1995,00
	<b>i.V.m. S-Code 51B</b>	●	●	●	●	●	●	●	-	●	●	●	1585,50
430	<b>Off-Road Engineering package</b> 1_only in conjunction with code 355 or 859	-	-	○	-	○	-	-	-	-	○	-	0,00
431	<b>Galvanised steering-wheel gearshift paddles</b> 1_only in conjunction with code 426 or 429 and L5C or L5I 2_not in conjunction with code 428	○	○	○	○	○	○	○	○	○	○	○	0,00
950	<b>AMG line</b> 1_only in conjunction with code H62, H15 or H23, 485 or 457, 725 or 720, 310, 772, code B63, 6U0 or 545 (f. c. engines), RTF, RTG, RVV or RVW, U26 and L3B, L5C or L5L 2_only in conjunction with code H62, H15 or H23, 486 or 459, 725 or 720, 310, 772, code RTH, RVY, RRT, RVZ, RRU, RWX or RWY, code L5C, L6J or L6K, code U26 only in certain country 3_only in conjunction with upholstery code 651A, 159A, 211A, 214A, 257A or 258A 4_not in conjunction with code P27, P59 <b>i.V.m. Code PYH</b>	- ●	- ●	- ●	- ●	- ●	- ●	- ●	- ●	- ●	- ●	S -	0,00 3097,50
P17	<b>KEYLESS-GO Comfort-package</b> 1_consisting code 871, 889 and 890 <b>i.V.m code PYD/PYF/PYH</b> <b>i.V.m. Code PYA</b> <b>i.V.m. Code PAD</b> <b>i.V.m. Code PYD/PYF/PYH</b> <b>i.V.m. Code PYN/PYO</b>	● ● - ● - ○	● ● - ● - ○	● ● - ● - ○	● ● - ● - ○	● ● - ● - ○	● ● - ● - ○	● ● - ● - ○	● ● - ● - ○	● ● - ● - ○	● ● - ● - ○	● ● - ● - ○	787,50 378,00 378,00 378,00 378,00 0,00
P19	<b>Edition 1</b> 1_in conjunction with code 840 or certain countries only in conjunction with upholsterycode 224A and paintcode 144U, 149U, 191U, 696U, 775U, 787U or 859U 2_only for certain countries in conjunction with code P59+P34+(631/632/640/641/642)+H23+29R+U25+U37+U66+(567/847)+720+877+942	●	●	●	●	●	U	U	●	●	●	-	7980,00

**Valid from 20.05.2020 - MY 800 + 050**

● available at extra charge   ○ available at no extra charge   ◐ annotations existing  
S standard equipment   - not available

Code	Description							★	★					LLP
	3_in conjunction with code 830 only in conjunction with code 787U and 224A; code P59+P34+(632/642)+H23+R84+U25+U37+U66+847+720+877+942+P17 <b>i.V.m. Code PYF</b>	●	●	●	●	●	●	●	●	-	●	●	-	4887,75
P27	<b>Style</b> 1_only in conjunction with upholstery code 101A, 311A or 379A 2_only in conjunction with code 725 and H61 and 310, code 643, R11, R26, R38, R43, R84, 52R, 72R, 96R, 97R, RTG, RVV or RVW, code L3E or L3B  3_not in conjunction with code 950, P34, P39, P59, 460, 494, 830 <b>i.V.m. Code PYD</b>	●	●	●	●	●	●	●	●	●	●	●	-	787,50
		○	○	○	○	○	○	○	○	-	○	○	-	0,00
P34	<b>Leather package</b>  1_only in conjunction with code 401 or 873 and code 201A, 205A, 211A, 214A or P19, code 950 or P59 2_not in conjunction with code P39 <b>i.V.m. Code 950</b> <b>i.V.m. Code P19</b>	- ●	- ●	- ●	- ●	- ●	- ●	- ●	- ●	- ●	- ●	- ●	● -	1050,00 1459,50
P39	<b>AMG Leather package</b> 1_only in conjunction with code 950, 401 or 873, code 257A or 258A 2_not in conjunction with code P27, P34 or P59	●	●	●	●	●	●	●	●	●	●	●	●	1050,00
		○	○	○	○	○	○	○	○	○	○	○	-	0,00
P43	<b>AMG Leather package</b> 1_only in conjunction with code 950, 401 or 873, code 257A or 258A 2_not in conjunction with code P27, P34 or P59	●	●	●	●	●	●	●	●	●	●	●	●	1050,00
P44	<b>Parking package with reversing camera</b> 1_only in conjunction with code 235 and 218 2_not in conjunction with code P47 <b>i.V.m. Code PYA</b> <b>i.V.m. Code PYM/PYN/PYO</b>	●	●	●	●	●	●	●	●	●	●	●	●	976,50
P47	<b>Parking Package with 360° camera</b> 1_only in conjunction with code P27, P59 or 950, 234 or 23P and 235 and 501  2_not in conjunction with code P44 <b>i.V.m. Code PYM/PYN/PYO</b>	●	●	●	●	●	●	●	●	●	●	●	●	1407,00
		●	●	●	●	●	●	●	●	-	●	●	●	430,50
P49	<b>Mirror package</b> 1_only in conjunction with code U62, 249, 500 <b>i.V.m. Code PYM/PYN/PYO</b>	●	●	●	●	●	●	●	●	●	●	●	●	420,00
		○	○	○	○	○	○	○	○	-	○	○	○	0,00
P54	<b>Anti-Theft Protection package with preinstallation for parking damage notification</b> 1_only in conjunction with code 551 and 882 2_for certain countries only <b>i.V.m. Code 362</b>	●	●	●	●	●	●	●	●	●	●	●	●	430,50
P55	<b>Night package</b> 1_only in conjunction with code P59 or 950, code 720, 840 2_only in conjunction with code R38, RTG, 52R, 643, 96R, 97R, R11, R26, R43, R84, RVV or RVW 3_not in conjunction with code P19 <b>i.V.m. Code PYH</b>	●	●	●	●	●	●	●	●	●	●	●	●	462,00
		●	●	●	●	●	●	●	●	-	●	●	-	446,25
P59	<b>Progressive</b> 1_only in conjunction with upholstery code 101A, 104A, 105A, 201A, 205A, 211A, 214A, 321A, 325A, 381A or code P19 2_only in conjunction with code 725 or 720, code H60, H61, H62, H15 or H23, code 310, code 29R, 52R, R38, 643, R11, R26, R43, R84, 72R, 96R, 97R, 98R, RTG, RVV or RVW, code L3E or L3B 3_not in conjunction with code P27, 950 <b>i.V.m. Code P19</b> <b>i.V.m. Code PYF</b>	●	●	●	●	●	●	●	●	●	●	●	-	131,25
		○	○	○	○	○	○	○	○	○	○	○	-	0,00
		○	○	○	○	○	○	○	○	-	○	○	-	0,00
P60	<b>AMG Night package</b> 1_in certain countries included in delivery 2_only in conjunction with code 720 and 840 3_for certain countries only <b>i.V.m. Code PYA</b>	-	-	-	-	-	-	-	-	-	-	-	●	787,50
		-	-	-	-	-	-	-	-	-	-	-	●	472,50
PAD	<b>Engineering package</b> 1_only in conjunction with code U29 and 457 and 23P and 889, code 640, 641 or 642 2_not in conjunction with code 460, 494, 498, 830	●	●	●	●	●	●	●	●	●	●	●	-	3108,00
PBF	<b>Navigation Connectivity package</b> 1_ only in conjunction with code 365 and 01U	●	●	●	●	●	●	●	●	●	●	●	●	682,50

**Valid from 20.05.2020 - MY 800 + 050**

● available at extra charge   ○ available at no extra charge   U annotations existing  
S standard equipment   - not available

Code	Designation												LLP
	i.V.m. Code PYM/PYN/PYO	●	●	●	●	●	●	●	-	●	●	●	105,00
PBI	Smartphone Connectivity package	●	●	●	●	●	●	●	-	●	●	●	420,00
	1_only in conjunction with code 08U, 09U, 14U												
	2_for certain countries only												
	i.V.m. Code PYA	●	●	●	●	●	●	●	-	●	●	●	315,00
PBP	ENERGIZING package	●	●	●	●	●	●	●	●	●	●	●	1470,00
	1_only in conjunction with code P59 or 950 and 355, 853 or 810, 859, 877, 873 or 401												
	2_not in conjunction with code PBR												
	i.V.m. Code PYN/PYO	●	●	●	●	●	●	●	-	●	●	●	105,00
PBR	ENERGIZING package Plus	●	●	●	●	●	●	●	●	●	●	●	2625,00
	1_in conjunction with code P59 only in conjunction with code 355, 409, 581, 873 or 401, 853 or 810, 859, 877												
	2_in conjunction with code 950 only in conjunction with code 355, 581, 873 or 401, 853 or 810, 859, 877												
	3_not in conjunction with code PBP												
	i.V.m. Code 7U4	●	●	●	●	●	●	●	●	●	●	●	2005,50
PYA	WEU Standard Equipment	●	●	●	●	●	●	●	-	●	●	-	0,00
	1_for certain countries only	-	-	-	-	-	-	-	-	-	-	●	0,00
PYD	Style Line	●	●	-	-	-	●	●	-	-	-	-	2055,00
	1_for certain countries only				●	●	●	●		●	●	●	0,00
PYF	Progressive Line	●	●	-	-	-	●	●	-	-	-	-	3340,00
	Delta due to PYD	●	●	●	●	●	●	●	●	●	●	●	1010,00
	1_for certain countries only												
PYH	AMG Line	●	●	-	-	-	●	●	-	-	-	-	4660,00
	Delta due to PYD	●	●	●	●	●	●	●	●	●	●	●	2355,00
	1_for certain countries only												
PYM	Advantage Package	●	●	●	●	●	●	●	-	●	●	-	1866,00
	1_for certain countries only	●	●	●	●	●	●	●	●	●	●	●	0,00
PYN	Premium Package	●	●	●	●	●	●	●	-	●	●	●	3192,00
	1_for certain countries only												
	i.V.m. Code P19	●	●	●	●	●	●	●	-	●	●	-	2836,00
PYO	Premium Plus Package	●	●	●	●	●	●	●	-	●	●	-	4774,00
	Delta due to PYD	-	-	-	-	-	-	-	-	-	-	●	3439,00
	1_for certain countries only												
	i.V.m. Code P19	●	●	●	●	●	●	●	-	●	●	-	4440,00
U59	Seat comfort package	○	○	○	○	○	○	○	○	○	○	○	0,00
	1_only in conjunction with code 7U2 or 7U4												
U62	Light and sight package	○	○	○	○	○	○	○	○	○	○	○	0,00
	1_only in conjunction with code B18												
494	USA specification	-	-	-	-	-	-	-	-	○	○	○	0,00
498	Japan specification	○	-	-	-	-	-	-	-	-	○	-	0,00
00B	Owner's Manual and Service Booklet - Danish	○	○	○	○	○	○	○	○	○	○	○	0,00
01B	Owner's Manual and Service Booklet - Dutch	○	○	○	○	○	○	○	○	○	○	○	0,00
01U	Preinstallation for Navigation Services	○	○	○	○	○	○	○	○	○	○	○	0,00
	1_only in conjunction with code PBF												
	2_for certain countries only												
02B	Owner's Manual and Service Booklet - German	○	○	○	○	○	○	○	○	○	○	○	0,00
03B	Owner's Manual and Service Booklet - Russian	○	○	○	○	○	○	○	○	○	○	○	0,00
04B	Owner's Manual and Service Booklet - Finnish	○	○	○	○	○	○	○	○	○	○	○	0,00
05B	Owner's Manual and Service Booklet - English	○	○	○	○	○	○	○	○	○	○	○	0,00
06B	Owner's Manual and Service Booklet - Italian	○	○	○	○	○	○	○	○	○	○	○	0,00
07B	Owner's Manual and Service Booklet - French	○	○	○	○	○	○	○	○	○	○	○	0,00
08B	Owner's Manual and Service Booklet - Spanish	○	○	○	○	○	○	○	○	○	○	○	0,00
08U	Preinstallation for Vehicle Setup	●	●	●	●	●	●	●	●	●	●	●	52,50
	1_standard in certain countries												
	2_only in conjunction with code 09U												
	3_in certain countries only in conjunction with code PBI												
	i.V.m. Code PBI	○	○	○	○	○	○	○	-	○	○	○	0,00
	i.V.m. code PYA	○	○	○	○	○	○	○	-	○	○	○	0,00
09B	Owner's Manual and Service Booklet - Portuguese	○	○	○	○	○	○	○	○	○	○	○	0,00
09U	Preinstallation for Vehicle Monitoring	●	●	●	●	●	●	●	●	●	●	●	52,50

**Valid from 20.05.2020 - MY 800 + 050**

● available at extra charge   ○ available at no extra charge   ◐ annotations existing  
S standard equipment   - not available

[illegible]

## Price list for the GLB

Valid from 20.05.2020 - MY 800 + 050

\* only South Korea

● available at extra charge    ○ available at no extra charge    U annotations existing  
S standard equipment    - not available

		GLB Offroad										LLP
Code	Designation	247.610	247.612	247.613	247.614	247.615	247.684	247.687	247.644	247.646	247.647	
		GLB 180 d	GLB 200 d	GLB 200 d 4MATIC	GLB 220 d	GLB 220 d 4MATIC	GLB 180	GLB 200	GLB 220 *	GLB 250	GLB 250 4MATIC	
											Mercedes-AMG GLB 35 4MATIC	
234	<b>Blind Spot Assist</b> 1_only in conjunction with code P49 or 275, 270 and 273 2_not in conjunction with code 233 3_for certain countries only i.V.m. Code 22P	●	●	●	●	●	●	●	●	●	●	472,50
		○	○	○	○	○	○	○	○	○	○	0,00
235	<b>Active Parking Assist with PARKTRONIC</b> i.V.m. Code P44/P47	●	●	●	●	●	●	●	●	●	●	708,75
		○	○	○	○	○	○	○	○	○	○	0,00
239	<b>Active Distance Assist DISTRONIC</b> 1_only in conjunction with code 426 or 429 2_not in conjunction with code 233, 258, 440 3_for certain countries only	●	●	●	●	●	●	●	●	●	●	630,00
23B	<b>Owner's Manual and Service Booklet - simpl. Chinese</b>	○	○	○	○	○	○	○	○	○	○	0,00
241	<b>Power front left seat with memory function</b> 1_only in conjunction with code 275 and U22 or 409 2_not in conjunction with code 7U1, 221 3_Right-hand-drive vehicles only i.V.m. Code PYO	●	●	●	●	●	●	●	-	●	●	299,25
		○	○	○	○	○	○	○	-	○	○	0,00
242	<b>Power front right seat with memory function</b> 1_only in conjunction with code 275 and U22 or 409 2_not in conjunction with code 842 or 7U1 3_only for Left Hand Drive i.V.m. Code PYO	●	●	●	●	●	●	●	●	●	●	299,25
		○	○	○	○	○	○	○	-	○	○	0,00
243	<b>Active Lane Keeping Assist</b> 1_not in conjunction with code 233 i.V.m. Code 22P i.V.m. S-Code 51B	●	●	●	●	●	●	●	●	●	●	472,50
		○	○	○	○	○	○	○	○	○	○	0,00
		○	○	○	○	○	○	○	○	○	○	0,00
249	<b>Interior mirror and driver's exterior mirror automatically dimming</b> 1_only in conjunction with code P49	○	○	○	○	○	○	○	○	○	○	0,00
24B	<b>Owner's Manual and Service Booklet - trad. Chinese</b>	○	○	○	○	○	○	○	○	○	○	0,00
256	<b>AMG TRACK PACE</b> 1_only in conjunction with code 365 and 549	-	-	-	-	-	-	-	-	-	●	262,50
258	<b>Active Brake Assist</b> 1_standard in certain countries 2_not in conjunction with code 233 or 239 3_for certain countries only	○	○	○	○	○	○	○	○	○	○	0,00
25B	<b>Owner's Manual and Service Booklet - Korean</b>	○	○	○	○	○	○	○	○	○	○	0,00
260	<b>Deletion of model plate on boot lid</b> 1_not in conjunction with code 830, 835	○	○	○	○	○	○	○	○	○	○	0,00
261	<b>Omission of badge</b> 1_not in conjunction with code 830, 835	-	-	-	-	-	-	-	-	-	○	0,00
263	<b>Number plate mounting for Asia / Mexico</b> 1_not in conjunction with code 968 2_for certain countries only	○	○	○	○	○	○	○	○	○	○	0,00
264	<b>Number plate mounting for USA/CAN</b> 1_not in conjunction with code 968 2_for certain countries only	○	○	○	○	○	-	-	-	○	○	0,00
266	<b>Active Steering Assist</b> 1_only in conjunction with code 233 2_for certain countries only	○	○	○	○	○	○	○	○	○	○	0,00
26B	<b>Owner's Manual and Service Booklet - Chinese Taiwan</b>	○	○	○	○	○	○	○	○	○	○	0,00
26U	<b>Preinstallation for engine remote start</b> 1_only in conjunction with code 08U 2_for certain countries only i.V.m. S-Code PZG	●	●	●	●	●	●	●	●	●	●	105,00
		●	●	●	●	●	●	●	●	●	●	157,50
270	<b>GPS aerial</b> 1_only in conjunction with code 233, 234, 355, 362, 501, 899 or B24	○	○	○	○	○	○	○	○	○	○	0,00
273	<b>Exit warning function</b> 1_only in conjunction with code 233 or 234	○	○	○	○	○	○	○	○	○	○	0,00
274	<b>Telephone aerial</b> 1_only in conjunction with code 501, 899 or B24 2_for certain countries only	○	○	○	○	○	○	○	○	○	○	0,00
275	<b>Driver's seat, electrically adjustable with memory function</b> 1_only in conjunction with code U22 or 409 and code 7U2 or 7U4 i.V.m. Code PYO	●	●	●	●	●	●	●	●	●	●	362,25
		○	○	○	○	○	○	○	-	○	○	0,00

**Valid from 20.05.2020 - MY 800 + 050**

\* only South Korea

● available at extra charge    ○ available at no extra charge    U annotations existing  
S standard equipment    - not available

Valid from 20.05.2020 - MY 800 + 050		GLB Offroader											
		247.610	247.612	247.613	247.614	247.615	247.684	247.687	247.644	247.646	247.647	247.651	
		GLB 180 d	GLB 200 d	GLB 200 d 4MATIC	GLB 220 d	GLB 220 d 4 MATIC	GLB 180	GLB 200	GLB 220 *	GLB 250	GLB 250 4MATIC	MERCEDES-AMG GLB 35	
												4MATIC	
Code	Designation												LLP
286	Luggage net on driver's and front pass. backrest 1_only in conjunction with code 7U2 or 7U4	○	○	○	○	○	○	○	○	○	○	○	0,00
287	Folding rear-seat backrests	●	●	●	●	●	●	●	●	●	●	●	0,00
293	Sidebags in rear 1_only in conjunction with code 7U2 or 7U4	●	●	●	●	●	●	●	●	●	●	●	393,75
294	Kneebag 1_for certain countries only	○	○	○	○	○	○	○	○	○	○	○	0,00
299	PRE-SAFE® system 1_for certain countries only i.V.m. Code 23P	●	●	●	●	●	●	●	●	●	●	●	346,50
29R	50.8 cm (20-inch) 5-spoke light-alloy wheels 1_only in conjunction with code P19 and 457 2_not in conjunction with code R66, 950, 460, 494, 830	○	○	○	○	○	○	○	○	○	○	-	0,00
2U0	car2go pre-installation 1_for certain countries only in conjunction with code P54 and 355 or 859 2_in conjunction with code 460 or 494 only in conjunction with code 852, code 355 or 859 3_not in conjunction with code 865	●	●	●	●	●	●	●	-	○	○	●	178,50
301	Ashtray insert for cup holder with cigarette lighter 1_for certain countries only	●	●	●	●	●	●	●	●	●	●	●	47,25
30B	Owner's Manual and Service Booklet - Slovenian	○	○	○	○	○	○	○	○	○	○	○	0,00
310	Double cup holder  i.V.m. Code P27/P59/950 i.V.m. Code PYA	- ● ○ ○	- ● ○ ○	- ● ○ ○	- ● ○ ○	- ● ○ ○	- ● ○ ○	- ● ○ ○	- ● ○ ○	- ● ○ ○	- ● ○ ○	S - - -	0,00 26,25 0,00 0,00
31B	Owner's Manual and Service Booklet - Hungarian	○	○	○	○	○	○	○	○	○	○	○	0,00
32B	Owner's Manual and Service Booklet - Bulgarian	○	○	○	○	○	○	○	○	○	○	○	0,00
33B	Owner's Manual and Service Booklet - Romanian	○	○	○	○	○	○	○	○	○	○	○	0,00
345	Windscreen wiper with rain sensor	S	S	S	S	S	S	S	S	S	S	S	0,00
34B	Owner's Manual and Service Booklet - Croatian	○	○	○	○	○	○	○	○	○	○	○	0,00
351	Mercedes-Benz emergency call system 1_only in conjunction with code 362	○	○	○	○	○	○	○	○	○	○	○	0,00
355	Extended MBUX functions  1_standard equipment for certain countries 2_only in conjunction with code 548 or 549 and 270 and 446 3_for certain countries only i.V.m. Code PYA	- ● ○ ○	- ● ○ ○	- ● ○ ○	- ● ○ ○	- ● ○ ○	- ● ○ ○	- ● ○ ○	- ● ○ ○	- ● ○ ○	- ● ○ ○	○ - ★	0,00 472,50
35B	Owner's Manual and Service Booklet - Latvian	○	○	○	○	○	○	○	○	○	○	○	0,00
362	Communications module (LTE) for the use of Mercedes me connect services 1_standard in certain countries 2_only in conjunction with code 270 and 351 3_only for certain countries not in conjunction with code 08U, 09U 4_for certain countries only	○	○	○	○	○	○	○	○	○	○	○	0,00
365	Hard-disc navigation 1_only in conjunction with code 355 i.V.m. Code PBF i.V.m. Code PYM/PYN/PYO	● ○ ○	● ○ ○	● ○ ○	● ○ ○	● ○ ○	● ○ ○	● ○ ○	● ○ ○	● ○ ○	● ○ ○	● ○ ○	577,50 0,00 0,00
367	Preinstallation for Live Traffic Information 1_only in conjunction with code 355 and 362 2_for certain countries only	○	○	○	○	○	○	○	○	○	○	○	0,00
36B	Owner's Manual and Service Booklet - Lithuanian	○	○	○	○	○	○	○	○	○	○	○	0,00
37B	Owner's Manual and Service Booklet - Slovakian	○	○	○	○	○	○	○	○	○	○	○	0,00
38B	Owner's Manual and Service Booklet - Estonian	○	○	○	○	○	○	○	○	○	○	○	0,00
39B	Owner's Manual and Service Booklet - Serbian	○	○	○	○	○	○	○	○	○	○	○	0,00
400	Rear armrest	S	S	S	S	S	S	S	S	S	S	S	0,00
401	Climatised front seats 1_only in conjunction with upholstery code 101A, 105A, 159A, 201A, 205A, 211A, 214A, 224A, 257A or 258A 2_not in conjunction with code 873, 830 i.V.m. Code P19 i.V.m. Code PBP/PBR i.V.m. Code PYN/PYO	● ● ● ●	● ● ● ●	● ● ● ●	● ● ● ●	● ● ● ●	● ● ● ●	● ● ● ●	● ● ● -	● ● ● ●	● ● ● ●	● - ● ●	934,50 630,00 630,00 630,00
409	Multicontour seat package	●	●	●	●	●	●	●	●	●	●	-	619,50

**Valid from 20.05.2020 - MY 800 + 050**

● available at extra charge   ○ available at no extra charge   ◐ annotations existing  
S standard equipment   - not available

[illegible]



**Valid from 20.05.2020 - MY 800 + 050**

● available at extra charge   ○ available at no extra charge   ◐ annotations existing  
S standard equipment   - not available

Valid from 20.05.2020 - MY 800 + 050		GLB Offroader											
		247.610	247.612	247.613	247.614	247.615	247.684	247.687	247.644	247.646	247.647	247.651	
		GLB 180 d	GLB 200 d	GLB 200 d 4MATIC	GLB 220 d	GLB 220 d 4MATIC	GLB 180	GLB 200	GLB 220 *	GLB 250	GLB 250 4MATIC	GLB 350 4MATIC	
* only South Korea													
● available at extra charge    ○ available at no extra charge    U annotations existing													
S standard equipment    - not available													
Code	Designation												LLP
51U	Roof liner in black fabric	○	○	○	○	○	○	○	○	○	○	S	0,00
524	Transport protection 1_not in conjunction with code 820 2_for certain countries only	●	●	●	●	●	●	●	-	●	●	●	168,00
52R	45.7 cm (18-inch) 5-spoke light-alloy wheels 1_only in conjunction with code R02 and R66, R01 2_not in conjunction with code 950, 830 i.V.m. Code P27 i.V.m. Code P59 i.V.m. Code PYF	● ● ○ ○	● ● ○ ○	● ● ○ ○	● ● ○ ○	● ● ○ ○	● ● ○ ○	● ● ○ ○	● ○ ○ -	● ● ○ ○	● ● ○ ○	- - - -	840,00 630,00 0,00 0,00
536	Radio: SIRIUS/SDARS ex factory 1_only in conjunction with code 355 or 859 2_not in conjunction with code 968, 969 3_for certain countries only	-	-	-	-	-	-	-	-	●	●	●	367,50
537	Digital radio 1_only in conjunction with code 79B i.V.m. Code PYA	● ○	● ○	● ○	● ○	● ○	● ○	● ○	● -	● ○	● ○	● ○	210,00 0,00
543	Sun visor with illuminated vanity mirror	S	S	S	S	S	S	S	S	S	S	S	0,00
545	MBUX multimedia system 1_not in conjunction with code 256, 355, 859, PBF, PBG, PBP, PBR, 21U, U19 2_for certain countries only	S	S	S	S	S	S	S	S	S	S	-	0,00
546	Active Speed Limit Assist 1_only in conjunction with code 233 and 513 2_for certain countries only	○	○	○	○	○	○	○	○	○	○	○	0,00
547	MBUX multimedia system 1_standard in certain countries and only in conjunction with code 859 2_not in conjunction with code 256, 355, 21U, U19, PBP, PBR 3_for certain countries only	○	○	○	○	○	○	○	○	○	○	○	0,00
548	MBUX multimedia system 1_standard in certain countries 2_in certain countries only in conjunction with code 355 or 2U0 3_not in conjunction with code 256, PBP, PBR, 21U, U19 4_for certain countries only	○	○	○	○	○	○	○	○	○	○	○	0,00
549	MBUX multimedia system 1_standard in certain countries 2_only in conjunction with code 256, 21U, U19, PBP or PBR 3_for certain countries only	○	○	○	○	○	○	○	○	○	○	○	0,00
550	Trailer coupling with ESP® trailer stabilisation 1_for certain countries only	●	●	●	●	●	●	●	-	●	●	●	840,00
551	Anti-theft alarm system with preinstallation for parking damage notification 1_in certain countries included in delivery of code P54 2_for certain countries only i.V.m. Code P54	● ○	● ○	● ○	● ○	● ○	● ○	● ○	● ○	● ○	● ○	● ○	262,50 0,00
552	Anti-theft alarm system with preinstallation for parking damage notification 1_only in conjunction with code P54 and 513L	○	○	○	○	○	○	○	○	○	○	○	0,00
554	Pre-installation for trailer coupling 1_for certain countries only	●	●	●	●	●	●	●	-	●	●	●	168,00
55U	Headlining in beige fabric 1_only in conjunction with upholstery code 105A, 205A, 335A	○	○	○	○	○	○	○	○	○	○	○	0,00
567	Rear seats with fore/aft adjustment 1_only in conjunction with code 7U2 or 7U4 2_not in conjunction with code 847 3_for certain countries only i.V.m. Code P19 i.V.m. Code PYA i.V.m. Code PYD/PYF/PYH	● ○ - ○	● ○ - ○	● ○ - ○	● ○ - ○	● ○ - ○	● ○ - ○	● ○ - ○	● ○ - -	● ○ - ○	● ○ - ○	● ○ - ○	378,00 0,00 0,00 0,00
580	THERMATIC automatic climate control 1_not in conjunction with code PBR 2_for certain countries only	○	○	○	○	○	○	○	○	○	○	○	0,00
581	THERMOTRONIC automatic climate control i.V.m. Code PBR i.V.m. Code PYA	● - -	● - -	● - -	● - -	● - -	● - -	● - -	● ○ -	● - -	● - -	● ○ ○	535,50 0,00 0,00

**Valid from 20.05.2020 - MY 800 + 050**

● available at extra charge   ○ available at no extra charge   ◐ annotations existing  
S standard equipment   - not available

[illegible]

**Valid from 20.05.2020 - MY 800 + 050**

● available at extra charge   O available at no extra charge   U annotations existing  
S standard equipment   - not available

Code	Description															LLP
	2_not in conjunction with code R01, R02, R03 3_for certain countries only															
666	<b>Freight packaging without tie-down hooks</b> 1_not in conjunction with code 668 2_for certain countries only	●	●	●	●	●	●	-	●	●	●					26,25
668	<b>Freight packaging with tie-down hooks</b> 1_not in conjunction with code 550, 666 2_for certain countries only	●	●	●	●	●	●	●	●	●	●					0,00
682	<b>Fire extinguisher</b> 1_for certain countries only	●	●	●	●	●	●	●	●	●	●					0,00
687	<b>Model year on model plate</b> 1_not in conjunction with code 969, 968 2_for certain countries only	○	○	○	○	○	○	○	○	○	○					0,00
690	<b>Emergency spare wheel</b> 1_only in conjunction with code B12 2_for certain countries not in conjunction with code R66 3_for certain countries only	○	○	○	○	○	○	○	○	○	○					0,00
70B	<b>Fluorescent jacket for driver</b> 1_not in conjunction with code 71B	●	●	●	●	●	●	●	●	●	●					5,25
71B	<b>Safety vests for driver and passengers</b> 1_not in conjunction with code 70B 2_for certain countries only <b>i.V.m. Code 847</b>	●	●	●	●	●	●	●	●	●	●					26,25
		●	●	●	●	●	●	●	●	●	●					36,75
720	<b>Roof rails in black</b> 1_included in delivery of code P55, P60, P19	○	○	○	○	○	○	○	○	○	○					0,00
725	<b>Polished aluminium roof rails</b>  1_not in conjunction with code P55, P60, P19 <b>i.V.m. Code P27/P59/950</b> <b>i.V.m. Code PYA</b>	- ●	- ●	- ●	- ●	- ●	- ●	- ●	- ●	- ●	- ●	S -				0,00 262,50
		○	○	○	○	○	○	○	○	○	○	-				0,00
		○	○	○	○	○	○	○	○	○	○	-				0,00
72R	<b>43.2 cm (17-inch) 10-spoke light-alloy wheels</b> 1_only in conjunction with code R01 or 645 2_not in conjunction with code R66, U29, 950, 460, 494, 830	○	○	○	○	○	○	○	○	○	○	-				0,00
73B	<b>Stowage compartment in centre console, with retractable cover</b> 1_only in conjunction with code 426 or 429 2_for certain countries only	●	●	●	●	●	●	●	-	●	●	●				0,00
762	<b>Radio remote control without panic button</b> 1_for certain countries only	○	○	○	○	○	○	○	○	○	○	○				0,00
763	<b>Radio remote control with panic switch</b> 1_only in conjunction with code 551 and certain countries 2_not in conjunction with code 762, 968, 969	○	○	○	○	○	○	○	○	○	○	○				0,00
772	<b>AMG bodystyling</b> 1_included in delivery of code 950	○	○	○	○	○	○	○	○	○	○	S				0,00
79B	<b>Preinstallation for digital radio</b> 1_in certain countries only in conjunction with code 362 2_in certain countries only in conjunction with code 537 3_only for certain countries in conjunction with code 355 and 859 and 362	○	○	○	○	○	○	○	○	○	○	○				0,00
7U1	<b>Manually adjustable front seats</b> 1_only in conjunction with upholstery code 301A 2_not in conjunction with code 7U2, 7U4	○	○	○	○	○	○	○	○	○	○	-				0,00
7U2	<b>Comfort Seats</b> 1_only in conjunction with upholstery code 101A, 104A, 105A, 201A, 205A, 311A, 321A, 325A, 379A or 381A, code U59 and 286 2_not in conjunction with code 7U1, 7U4	○	○	○	○	○	○	○	○	○	○	-				0,00
7U4	<b>Sports seats</b>  1_only in conjunction with upholstery code 159A, 211A, 214A, 224A, 257A, 258A or 651A, code U59 and 286 2_not in conjunction with code 7U1, 7U2 <b>i.V.m. Code 950</b> <b>i.V.m. Code P19</b>	- ●	- ●	- ●	- ●	- ●	- ●	- ●	- ●	- ●	- ●	S -				0,00 246,75
		○	○	○	○	○	○	○	○	○	○	-				0,00
		○	○	○	○	○	○	○	○	○	○	-				0,00
800	<b>Technical modifications</b>	○	○	○	○	○	○	○	○	○	○	○				0,00
810	<b>Burmester® surround sound system</b> 1_only in conjunction with code 355 or 859 2_not in conjunction with code 853	●	●	●	●	●	●	●	●	●	●	●				698,25

**Valid from 20.05.2020 - MY 800 + 050**

● available at extra charge   ○ available at no extra charge   ◐ annotations existing  
S standard equipment   - not available

Code	Designation																	LLP
	3_for certain countries only																	
	i.V.m. Code PBP/PBR	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	435,75
	i.V.m. Code PYN	-	-	-	-	-	-	-	-	-	-	-	-	-	-	●	●	435,75
	i.V.m. Code PYN/PYO	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	435,75
	i.V.m. Code PYO	-	-	-	-	-	-	-	-	-	-	-	-	-	-	○	○	0,00
820	Tourist vehicle	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	0,00
	1_not in conjunction with code 634 or 636																	
	2_for certain countries only																	
821	Country code Brazil	-	-	-	-	-	○	○	-	-	-	-	○					0,00
822	South Africa specification	○	○	○	-	○	○	○	-	○	○	○						0,00
823	country code Switzerland	○	○	○	○	○	○	○	-	○	○	○	○	○	○	○	○	0,00
824	Additional parts for cold countries (engine air intake screen)	○	○	○	○	○	○	○	-	○	○	○	○					0,00
	1_for certain countries only																	
829	Taiwan version	○	○	○	-	○	○	○	-	○	○	○	○					0,00
830	China specification	-	-	-	-	-	○	○	-	-	-	-	○					0,00
831	country code Italia	○	○	○	○	○	○	○	-	○	○	○						0,00
834	New Zealand specification	-	-	○	-	○	○	○	-	-	-	○	○	○				0,00
835	South Korea specification	-	○	-	-	-	-	-	○	-	○	○						0,00
840	Heat-insulating dark-tinted glass	●	●	●	●	●	●	●	-	●	●	●						315,00
	1_only in conjunction with code P27, P59 or 950																	
	2_not in conjunction with code U50																	
	3_for certain countries only																	
	i.V.m. Code P19	○	○	○	○	○	○	○	-	○	○	-						0,00
	i.V.m. Code P55	○	○	○	○	○	○	○	-	○	○	-						0,00
	i.V.m. Code P60	-	-	-	-	-	-	-	-	-	-	○						0,00
	i.V.m. Code PYA	-	-	-	-	-	-	-	-	-	-	○						0,00
	i.V.m. Code PYH	○	○	○	○	○	○	○	-	○	○	-						0,00
842	Folding front passenger seat	●	●	●	●	●	●	●	●	●	●	-						157,50
	1_only in conjunction with code 7U2																	
	2_not in conjunction with code 242, 409, 866, 950																	
	3_only for LHD models																	
	4_for certain countries only																	
847	3rd row of seats for 2 people	●	●	○	●	○	●	●	●	●	●	○						1165,50
	1_only in conjunction with code 52R, R38, 97R, R26, R84, 96R, 29R, RTF, RTG, RVV or RVW			★			★											
	2_only for certain countries in conjunction with code 228 or 550															★	★	
	3_only in conjunction with code RRT, RRU, RTH, RVY, RVZ, RWX or RWY																	
	4_not in conjunction with code 567, 690, upholstery code 214A, 301A, 379A																	
	i.V.m. Code P19	●	●	●	●	●	●	●	●	●	●	-						787,50
	i.V.m. Code PYA	-	-	-	-	-	-	-	-	-	-	●						787,50
	i.V.m. code PYD/PYF/PYH	●	●	●	●	●	●	●	-	●	●	-						787,50
852	Sensor system for anti-theft alarm system	-	-	-	-	-	-	-	-	●	●	●						147,00
	1_only in conjunction with code 551 and 460 or 494																	
	2_not in conjunction with code 882																	
	i.V.m. Code 362	-	-	-	-	-	-	-	-	●	●	●						178,50
853	Advanced Sound System	●	●	●	●	●	●	●	●	●	●	●						262,50
	1_not in conjunction with code 810																	
	i.V.m. Code PBP/PBR	○	○	○	○	○	○	○	○	○	○	○						0,00
	i.V.m. Code PYN	-	-	-	-	-	-	-	-	-	-	○						0,00
	i.V.m. Code PYN/PYO	○	○	○	○	○	○	○	-	○	○	-						0,00
859	Media-Display	●	●	●	●	●	●	●	●	●	●	○				○	★	682,50
	1_standard equipment for certain countries																	
	2_only in conjunction with code 547, 548 or 549 and 446																	
	3_for certain countries only																	
	i.V.m. Code PBP/PBR	○	○	○	○	○	○	○	○	○	○	○						0,00
	i.V.m. Code PYM/PYN/PYO	○	○	○	○	○	○	○	-	○	○	○						0,00
862	Pre-installation for digital TV Japan	●	●	●	●	●	●	●	●	●	●	●						94,50
	1_only in conjunction with code 355 and 859																	
	2_not in conjunction with code 865																	
	3_for certain countries only																	
865	TV tuner Japan	●	●	●	●	●	●	●	-	●	●	●						945,00
	1_only in conjunction with code 355 and 859																	
	2_not in conjunction with code 862																	
	3_for certain countries only																	
866	Preinstallation for entertainment and comfort features	●	●	●	●	●	●	●	●	●	●	●						136,50

**Valid from 20.05.2020 - MY 800 + 050**

● available at extra charge   ○ available at no extra charge   ◐ annotations existing  
S standard equipment   - not available

Valid from 20.05.2020 - MY 800 + 050		GLB Offroader											LLP
Code	Designation	247.610	247.612	247.613	247.614	247.615	247.684	247.687	247.644	247.646	247.647	247.651	
		GLB 180 d	GLB 200 d	GLB 200 d 4MATIC	GLB 220 d	GLB 220 d 4MATIC	GLB 180	GLB 200	GLB 220 *	GLB 250	GLB 250 4MATIC	Mercedes-AMG GLB 35 4MATIC	
	* only South Korea												
	● available at extra charge    ○ available at no extra charge    U annotations existing												
	S standard equipment    - not available												
871	HANDS-FREE ACCESS 1_only in conjunction with code 7U2 or 7U4 2_not in conjunction with code 842 3_for certain countries only	○	○	○	○	○	○	○	○	○	○	○	
873	Heated front seats 1_not in conjunction with code 401 i.V.m. Code P19 i.V.m. Code PBP/PBR i.V.m. Code PYN/PYO	●	●	●	●	●	●	●	●	●	●	●	
875	Heated windscreen washer system	●	●	●	●	●	●	●	●	●	●	●	
877	Ambient lighting 1_only in conjunction with code P27, P59 or 950 i.V.m. Code P19 i.V.m. Code PBP/PBR i.V.m. Code PYN/PYO	●	●	●	●	●	●	●	●	●	●	●	
882	Interior monitoring system 1_only in conjunction with code P54 2_not in conjunction with code 852	○	○	○	○	○	○	○	○	○	○	○	
885	Increased anti-theft protection 1_only in conjunction with code 537L	○	○	○	○	○	○	○	-	○	○	○	
889	KEYLESS-GO 1_only in conjunction with code P27, P59 or 950 2_not in conjunction with code U27, paint code 817U i.V.m. Code P17 i.V.m. Code PAD	●	●	●	●	●	●	●	●	●	●	●	
890	EASY-PACK tailgate 1_for certain countries only i.V.m. Code P17 i.V.m. Code PYA i.V.m. Code PYD/PYF/PYH	●	●	●	●	●	●	●	●	●	●	●	
896	Preinstallation for NFC key card 1_only in conjunction with code 897 or 899 and 362 2_for certain countries only	●	●	●	●	●	●	●	●	●	●	●	
897	Wireless charging system for mobile devices 1_only in conjunction with code P27, P59 or 950 2_not in conjunction with code 899 3_for certain countries only	●	●	●	●	●	●	●	●	●	●	●	
899	Multifunction telephony 1_only in conjunction with code P27, P59 or 950 and 270, 274 2_not in conjunction with code 897 3_for certain countries only	●	●	●	●	●	●	●	●	●	●	●	
913	Air conditioning preinstallation for hot countries 1_for certain countries only	○	○	○	○	○	-	-	-	-	-	-	
916	Fuel tank with a capacity of 60 litres 1_for certain countries only	-	-	S	-	S	-	-	-	○	S	S	
922	Reduced output engines 1_for certain countries only (524L/528L/810L)	-	-	-	-	-	○	○	-	-	-	-	
926	Emission control system with EU4 technology 1_not in conjunction with code U79 2_for certain countries only	○	○	○	○	○	○	○	-	○	○	○	
927	EU6 emissions standard 1_for certain countries only	○	○	○	○	○	○	○	-	○	○	○	
933	Engine for ethanol fuel E100 1_not in conjunction with code 968, 969 2_for certain countries only	-	-	-	-	-	-	●	-	-	-	-	
936	Cylinder shut-off 1_for certain countries only	-	-	-	-	-	○	○	-	-	-	-	
942	Load compartment package 1_only in conjunction with code U35 i.V.m. Code P19 i.V.m. Code PYA	●	●	●	●	●	●	●	●	●	●	●	
945	Emission control system China 1_only in conjunction with code 830	-	-	-	-	-	○	○	-	-	-	○	
961	Petrol particulate filter	-	-	-	-	-	○	○	-	○	○	○	

**Valid from 20.05.2020 - MY 800 + 050**

● available at extra charge   ○ available at no extra charge   ◐ annotations existing  
S standard equipment   - not available

[illegible]

**Valid from 20.05.2020 - MY 800 + 050**

● available at extra charge   ○ available at no extra charge   ◐ annotations existing  
S standard equipment   - not available

[illegible]

**Valid from 20.05.2020 - MY 800 + 050**

● available at extra charge   ○ available at no extra charge   ◐ annotations existing  
S standard equipment   - not available

Code	Description																			LLP
	1_only in conjunction with code RTF, RTG, RTH, RVY, RVZ, 52R, 97R, R26, R38 or R84, code R01 or R02 2_not in conjunction with code 29R, 72R, 96R, R11, R43, 643, RVV, RVW, RRT, RRU, RWX, RWY, R03 or 645 3_for certain countries only																			
R84	48.3-cm (19-inch) 5-twin-spoke light-alloy wheels 1_not in conjunction with code 950 i.V.m. Code (P55+P59)/P59 i.V.m. Code P19 i.V.m. Code P27	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	1312,50
		●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	472,50
		-	-	-	-	-	○	○	-	-	-	-	-	-	-	-	-	-	-	0,00
		●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	1102,50
RRT	50.8 cm (20-inch) AMG 5-twin-spoke light-alloy wheels 1_only in conjunction with code 950 and R01	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	●	-	840,00
RRU	50.8 cm (20-inch) AMG 5-twin-spoke light-alloy wheels 1_only in conjunction with code 950 and R01	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	●	-	1207,50
RTF	48.3 cm (19-inch) AMG 5-twin-spoke light-alloy wheels 1_only in conjunction with code 950 i.V.m. Code PYH	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	-	0,00
		○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	-	0,00
RTG	48.3 cm (19-inch) AMG 5-twin-spoke light-alloy wheels i.V.m. Code (P55+P59)/P59 i.V.m. Code 950 i.V.m. Code P27 i.V.m. Code P55+950	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	-	1785,00
		●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	-	945,00
		●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	-	210,00
		●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	-	1575,00
		○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	-	0,00
RTH	48.3 cm (19-inch) AMG 5-twin-spoke light-alloy wheels 1_only in conjunction with code 950, code R02 and R66 or R01	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	S	-	0,00
RVV	50.8 cm (20-inch) AMG multi-spoke alloy wheels 1_only in conjunction with code 457 and R01 2_not in conjunction with code 830, R66 i.V.m. Code (P55+P59)/P59 i.V.m. Code 950 i.V.m. Code P27	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	-	2100,00
		●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	-	1260,00
		●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	-	630,00
		●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	-	1890,00
RVW	50.8 cm (20-inch) AMG multi-spoke light-alloy wheels 1_only in conjunction with code 457 and R01 2_not in conjunction with code 830, R66 i.V.m. Code (P55+P59)/P59 i.V.m. Code 950 i.V.m. Code P27 i.V.m. Code PYH	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	-	2467,50
		●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	-	1627,50
		●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	-	997,50
		●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	-	2257,50
		●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	-	997,50
RVY	48.3 cm (19-inch) AMG 10-spoke light-alloy wheels 1_only in conjunction with code 950, code R02 and R66 or R01	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	●	-	210,00
RVZ	48.3 cm (19-inch) AMG 10-spoke light-alloy wheels 1_only in conjunction with code 950, code R02 and R66 or R01	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	●	-	577,50
RWX	53.3 cm (21-inch) AMG multi-spoke light-alloy wheels 1_only in conjunction with code 950 and R01 2_not in conjunction with code R66	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	●	-	1470,00
RWY	53.3 cm (21-inch) AMG multi-spoke light-alloy wheels 1_only in conjunction with code 950 and R01 2_not in conjunction with code R66	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	●	-	1837,50
U01	Status display for rear seat belts in instrument cluster 1_for certain countries only	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	0,00
U10	Automatic deactivation of front passenger airbag i.V.m. S-Code 51B	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	99,75
		○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	0,00
U12	Velour floor mats 1_not in conjunction with code 498, 830, 950, U26, U66 i.V.m. Code PYA	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	-	84,00
		○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	-	0,00
U17	Omission of designo seat belts in red 1_not in conjunction with code Y05	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	○	-	0,00
U19	MBUX augmented reality for navigation 1_only in conjunction with code 365 and 859 2_for certain countries only	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	409,50
U22	4-way lumbar support 1_only in conjunction with code U59 2_not in conjunction with code 409 i.V.m. Code PYO	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	162,75
		○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	0,00
U25	Illuminated door sill panels with "Mercedes-Benz" lettering 1 AMG door sill panels with »AMG« lettering, illuminated	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	Ⓢ	157,50
																		★		



**Valid from 20.05.2020 - MY 800 + 050**

● available at extra charge   ○ available at no extra charge   ◐ annotations existing  
S standard equipment   - not available

[illegible]