

1/8/2019

## Price list for the GLB

Valid from 13.08.2019 - MY 800

\* only South Korea

\*\* only USA/Canada

● available at extra charge ○ available at no extra charge ⓘ annotations existing

S standard equipment - not available

		GLB						LLP
Code	Designation	247.610	247.612	247.613	247.615	247.687	247.647	
L	Left-hand drive	○	○	○	○	○	○	0,00
R	Right-hand drive	●	●	●	●	●	●	1113,00
144U	digital white metallic	●	●	●	●	-	●	787,50
	1_available from 4th quarter 2019					●		240,00
149U	polar white	●	●	●	●	●	●	0,00
191U	cosmos black metallic	●	●	●	●	-	●	787,50
						●		240,00
662U	designo mountain grey magno	-	-	-	-	●	-	1942,50
	1_only in conjunction with code 830							
	2_available from 4th quarter 2019							
667U	denim blue metallic	●	●	●	●	ⓘ	●	787,50
	1_not in conjunction with code 830					★		
	2_available from 1st quarter 2020					●		240,00
696U	night black	○	○	○	○	ⓘ	○	0,00
	1_not in conjunction with code 830					★		
775U	iridium silver metallic	●	●	●	●	ⓘ	●	787,50
	1_not in conjunction with code 830					★		
	2_available from 4th quarter 2019					●		240,00
787U	mountain grey metallic	●	●	●	●	-	●	787,50
						●		240,00
813U	galaxy blue metallic	●	●	●	●	-	●	787,50
						●		240,00
	1_available from 4th quarter 2019							
993U	designo patagonia red metallic	●	●	●	●	●	●	997,50
	1_available from 1st quarter 2020							
101A	ARTICO man-made leather black	●	●	●	●	●	●	152,25
	1_only in conjunction with code P27 or P59 and 7U2							
104A	ARTICO man-made leather brown	-	-	-	-	●	-	152,25
	1_only in conjunction with code P27 or P59 and 7U2							
	2_only in conjunction with code 830							
105A	ARTICO man-made leather macchiato beige / black	●	●	●	●	●	●	152,25
	1_only in conjunction with code P59 and 7U2							
159A	Two-tone ARTICO man-made leather neva grey / black	○	○	○	○	○	○	0,00
	1_only in conjunction with code 950 and 7U4							
	2_not in conjunction with code 830							
201A	Leather black	○	○	○	○	○	○	0,00
	1_only in conjunction with code P34, P59 and 7U2, code 873 or 401							
	2_not in conjunction with code 830							
205A	Leather macchiato beige / black	○	○	○	○	○	○	0,00
	1_only in conjunction with code P34, P59 and 7U2, code 873 or 401							
	2_not in conjunction with code 830							
211A	Leather black	○	○	○	○	○	○	0,00
	1_only in conjunction with code P34 and P59 or 950 and 7U4, code 873 or 401							
	2_not in conjunction with code 830							

1/8/2019

## Price list for the GLB

Valid from 13.08.2019 - MY 800

\* only South Korea

\*\* only USA/Canada

● available at extra charge ○ available at no extra charge ① annotations existing

S standard equipment - not available

		GLB						LLP
Code	Designation	247.610	247.612	247.613	247.615	247.687	247.647	
		GLB 180 d	GLB 200 d	GLB 200 d 4MATIC	MATIC	GLB 200	GLB 250 4MATIC	
214A	<b>Rough leather / leather Bahia brown / black</b> 1_only in conjunction with code P34 and P59 or 950 and 7U4, code 873 or 401 2_not in conjunction with code 830, 847	○	○	○	○	○	○	0,00
224A	<b>Rough leather / leather Bahia brown / black</b> 1_only in conjunction with code P19 and 7U4, code 873 or 401	○	○	○	○	○	○	0,00
257A	<b>Two-tone leather classic red / black</b> 1_only in conjunction with code P39 and 950 and 7U4, code 873 or 401	○	○	○	○	○	○	0,00
258A	<b>Two-tone leather titanium grey pearl / black</b> 1_only on conjunction with code P39 and 950 and 7U4, code 873 or 401	○	○	○	○	○	○	0,00
301A	<b>ARTICO man-made leather / Tandel fabric black</b> 1_only in conjunction with code 7U1 2_not in conjunction with code 847, 950, P27, P59, 460, 494, 498, 830	○	○	○	○	○	○	0,00
311A	<b>ARTICO man-made leather / Bertrix fabric black</b> 1_only in conjunction with code P27 and 7U2 2_not in conjunction with code 830	○	○	○	○	○	○	0,00
331A	<b>ARTICO man-made leather / Albury fabricblack</b> 1_only in conjunction with code P59 and 7U2 2_not in conjunction with code 830	○	○	○	○	○	○	0,00
335A	<b>ARTICO man-made leather / Albury fabric macchiato beige / black</b> 1_only in conjunction with code P59 and 7U2 2_not in conjunction with code 830	○	○	○	○	○	○	0,00
379A	<b>ARTICO man-made leather/ Bertrix fabric, two-tone indigo blue / neva white</b> 1_only in conjunction with code P27 and 7U2 2_not in conjunction with code 830	○	○	○	○	○	○	0,00
384A	<b>ARTICO man-made leather / Albury fabric two-tone black / Bahia brown</b> 1_only in conjunction with code P59 and 7U2 2_not in conjunction with code 830	○	○	○	○	○	○	0,00
411	<b>6-speed manual transmission</b> 1_not in conjunction with code P53 2_invalid, only in conjunction with code 017	① ★	① ★	-	-	① ★	-	0,00
426	<b>8G-DCT</b> 1_not in conjunction with code 411, 429	○	○	S	S	-	S	0,00
429	<b>7G-DCT</b> 1_not in conjunction with code 411, 426	-	-	-	-	○	-	0,00
651A	<b>ARTICO man-made leather/DINAMICA microfibre upholstery black</b> 1_only in conjunction with code 950 and 7U4 2_not in conjunction with code 830	○	○	○	○	○	○	0,00

1/8/2019

## Price list for the GLB

Valid from 13.08.2019 - MY 800

\* only South Korea

\*\* only USA/Canada

● available at extra charge ○ available at no extra charge U annotations existing

S standard equipment - not available

		GLB						LLP
Code	Designation	247.610	247.612	247.613	247.615	247.687	247.647	
22P	<b>Lane Tracking package</b> 1_only in conjunction with code 234 and 243 2_not in conjunction with code 23P	●	●	●	●	●	●	819,00
23P	<b>Driving Assistance package</b> 1_only in conjunction with code 233 and 299 and 275 or 221 or P49 2_not in conjunction with code 22P <b>i.V.m. S-Code 51B</b>	●	●	●	●	●	●	1995,00
430	<b>Off-Road Engineering package</b> 1_only in conjunction with code 355 or 859	-	-	○	○	-	○	0,00
431	<b>Galvanised steering-wheel gearshift paddles</b> 1_only in conjunction with code 426 or 429 and L5C or L5I 2_not in conjunction with code 428	○	○	○	○	○	○	0,00
950	<b>AMG line</b> 1_only in conjunction with upholstery code 651A, 159A, 211A, 214A, 257A or 258A, code H62, H15 or H23, 485 or 457, 725 or 720, 310, 772, code B63, 6U0 or 545 (f. c. engines), RTF, RTG, RVV or RVW, U26 and L3B, L5C or L5I  2_not in conjunction with code P27, P59 <b>i.V.m. Code PYH</b>	●	●	●	●	●	●	3097,50
P17	<b>KEYLESS-GO Comfort-package</b> 1_consisting code 871, 889 and 890 <b>i.V.m code PYD/PYF/PYH</b> <b>i.V.m. Code PYN/PYO</b>	●	●	●	●	●	●	787,50
P19	<b>Edition 1</b> 1_in conjunction with code 840 or certain countries only in conjunction with upholsterycode 224A and paintcode 144U, 149U, 191U, 696U, 775U, 787U or 859U 2_only for certain countries in conjunction with code P59+P34+(631/632/640/641/642)+H23+29R+U25+U37+U66+(567/847)+720+877+942 3_in conjunction with code 830 only in conjunction with code 787U and 224A; code P59+P34+(632/642)+H23+R84+U25+U37+U66+847+720+877+942+P17	●	●	●	●	U	●	7980,00
	<b>i.V.m. Code PYF</b>	●	●	●	●	●	●	4887,75
P27	<b>Style</b> 1_only in conjunction with upholstery code 101A, 311A or 379A 2_only in conjunction with code 725 and H61 and 310, code 643, R11, R26, R38, R43, R84, 52R, 72R, 96R, 97R, RTG, RVV or RVW, code L3E or L3B  3_not in conjunction with code 950, P34, P39, P59, 460, 494, 830 <b>i.V.m. Code PYD</b>	●	●	●	●	●	●	787,50
		○	○	○	○	○	○	0,00

1/8/2019

## Price list for the GLB

Valid from 13.08.2019 - MY 800

\* only South Korea

\*\* only USA/Canada

● available at extra charge ○ available at no extra charge U annotations existing

S standard equipment - not available

		GLB						LLP
Code	Designation	247.610	247.612	247.613	247.615	247.687	247.647	
		GLB 180 d	GLB 200 d	GLB 200 d 4MATIC	MATIC	GLB 200	GLB 250 4MATIC	
<b>P34</b>	<b>Leather package</b> 1_only in conjunction with code 401 or 873 and code 201A, 205A, 211A, 214A or P19, code 950 or P59 2_not in conjunction with code P39 <b>i.V.m. Code 950</b> <b>i.V.m. Code P19</b>	●	●	●	●	●	●	<b>1459,50</b>
		●	●	●	●	●	●	<b>1050,00</b>
		○	○	○	○	○	○	<b>0,00</b>
<b>P39</b>	<b>AMG Leather package</b> 1_only in conjunction with code 950, 401 or 873, code 257A or 258A 2_not in conjunction with code P27, P34 or P59	●	●	●	●	●	●	<b>1050,00</b>
<b>P44</b>	<b>Parking package with reversing camera</b> 1_only in conjunction with code 235 and 218 2_not in conjunction with code P47 <b>i.V.m. Code PYA</b> <b>i.V.m. Code PYM/PYN/PYO</b>	●	●	●	●	●	●	<b>976,50</b>
		●	●	●	●	●	●	<b>624,75</b>
		○	○	○	○	○	○	<b>0,00</b>
<b>P47</b>	<b>Parking Package with 360° camera</b> 1_only in conjunction with code P27, P59 or 950, 234 or 23P and 235 and 501  2_not in conjunction with code P44 <b>i.V.m. Code PYM/PYN/PYO</b>	●	●	●	●	●	●	<b>1407,00</b>
		●	●	●	●	●	●	<b>430,50</b>
<b>P49</b>	<b>Mirror package</b> 1_only in conjunction with code U62, 249, 500 <b>i.V.m. Code PYM/PYN/PYO</b>	●	●	●	●	●	●	<b>420,00</b>
		○	○	○	○	○	○	<b>0,00</b>
<b>P53</b>	<b>Fine particle sensor</b> <del>1_only in conjunction with code 017</del>	U	U	U	U	U	U	<b>157,50</b>
<b>P54</b>	<b>Anti-Theft Protection package with preinstallation for parking damage notification</b> 1_only in conjunction with code P27, P59 or 950, 551 and 882 <b>i.V.m. Code 362</b>	●	●	●	●	●	●	<b>430,50</b>
		●	●	●	●	●	●	<b>462,00</b>
<b>P55</b>	<b>Night package</b> 1_only in conjunction with code P59 or 950, code 720, 840 2_only in conjunction with code R38, RTG, 52R, 643, 96R, 97R, R11, R26, R43, R84, RVV or RVW 3_not in conjunction with code P19	●	●	●	●	●	●	<b>446,25</b>
	<b>i.V.m. Code PYH</b>	●	●	●	●	●	●	<b>131,25</b>

1/8/2019

## Price list for the GLB

Valid from 13.08.2019 - MY 800

\* only South Korea

\*\* only USA/Canada

● available at extra charge ○ available at no extra charge U annotations existing

S standard equipment - not available

		GLB						LLP
Code	Designation	247.610	247.612	247.613	247.615	247.687	247.647	
		GLB 180 d	GLB 200 d	GLB 200 d 4MATIC	MATIC	GLB 200	GLB 250 4MATIC	
P59	<b>Progressive</b> 1_only in conjunction with upholstery code 101A, 104A, 105A, 201A, 205A, 211A, 214A, 331A, 335A, 384A or code P19 2_only in conjunction with code 725 or 720, code H60, H61, H62, H15 or H23, code 310, code 29R, 52R, R38, 643, R11, R26, R43, R84, 72R, 96R, 97R, 98R, RTG, RVV or RVW, code L3E or L3B 3_not in conjunction with code P27, 950 <b>i.V.m. Code P19</b> <b>i.V.m. Code PYF</b>	●	●	●	●	●	●	1601,25
		○	○	○	○	○	○	0,00
		○	○	○	○	○	○	0,00
PAC	<b>Value package</b>	S	S	S	S	S	S	0,00
PAD	<b>Engineering package</b> 1_only in conjunction with code U29 and 457 and 23P and 889, code 640, 641 or 642 2_not in conjunction with code 460, 494, 498, 830	●	●	●	●	●	●	3108,00
PBF	<b>Navigation Connectivity package</b> 1_only in conjunction with code 365 and 01U <b>i.V.m. Code PYM/PYN/PYO</b>	●	●	●	●	●	●	682,50
		●	●	●	●	●	●	105,00
PBI	<b>Smartphone Connectivity package</b> 1_only in conjunction with code 08U, 09U, 14U 2_for certain countries only	●	●	●	●	●	●	420,00
PBP	<b>ENERGIZING package</b> 1_only in conjunction with code P59 or 950 and 355, 853 or 810, 859, 877, 873 or 401 2_not in conjunction with code PBR <b>i.V.m. Code PYN/PYO</b>	●	●	●	●	●	●	1470,00
		●	●	●	●	●	●	105,00
PBR	<b>ENERGIZING package Plus</b> 1_in conjunction with code P59 only in conjunction with code 355, 409, 581, 873 or 401, 853 or 810, 859, 877 2_in conjunction with code 950 only in conjunction with code 355, 581, 873 or 401, 853 or 810, 859, 877 3_not in conjunction with code PBP <b>i.V.m. Code 7U4</b>	●	●	●	●	●	●	2625,00
		●	●	●	●	●	●	2005,50
PYA	<b>WEU Standard Equipment</b> 1_for certain countries only	●	●	●	●	●	●	0,00
PYD	<b>Style Line</b>	●	●	-	-	●	-	2055,00
				●	●		●	0,00
	1_for certain countries only							
PYF	<b>Progressive Line</b> <b>Delta due to PYD</b> 1_for certain countries only	●	●	-	-	●	-	3340,00
				●	●			1010,00
PYH	<b>AMG Line</b> <b>Delta due to PYD</b> 1_for certain countries only	●	●	-	-	●	-	4660,00
				●	●			2355,00
PYM	<b>Advantage Package</b> 1_for certain countries only	●	●	●	●	●	●	1866,00

1/8/2019

## Price list for the GLB

Valid from 13.08.2019 - MY 800

\* only South Korea

\*\* only USA/Canada

● available at extra charge ○ available at no extra charge U annotations existing

S standard equipment - not available

		GLB						LLP
Code	Designation	247.610	247.612	247.613	247.615	247.687	247.647	
		GLB 180 d	GLB 200 d	4MATIC	MATIC	GLB 200	GLB 250 4MATIC	
PYN	Premium Package 1_for certain countries only	●	●	●	●	●	●	3192,00
PYO	Premium Plus Package 1_for certain countries only	●	●	●	●	●	●	4774,00
U59	Seat comfort package 1_only in conjunction with code 7U2 or 7U4	○	○	○	○	○	○	0,00
U62	Light and sight package 1_only in conjunction with code B18	S	S	S	S	S	S	0,00
494	USA specification	-	-	-	-	-	○	0,00
498	Japan specification	○	-	-	-	-	-	0,00
00B	Owner's Manual and Service Booklet - Danish	○	○	○	○	○	○	0,00
01B	Owner's Manual and Service Booklet - Dutch	○	○	○	○	○	○	0,00
01U	Extended navigation services 1_only in conjunction with code PBF 2_for certain countries only	○	○	○	○	○	○	0,00
02B	Owner's Manual and Service Booklet - German	○	○	○	○	○	○	0,00
03B	Owner's Manual and Service Booklet - Russian	○	○	○	○	○	○	0,00
04B	Owner's Manual and Service Booklet - Finnish	○	○	○	○	○	○	0,00
05B	Owner's Manual and Service Booklet - English	○	○	○	○	○	○	0,00
06B	Owner's Manual and Service Booklet - Italian	○	○	○	○	○	○	0,00
07B	Owner's Manual and Service Booklet - French	○	○	○	○	○	○	0,00
08B	Owner's Manual and Service Booklet - Spanish	○	○	○	○	○	○	0,00
08U	Preinstallation for Vehicle Setup 1_only in conjunction with code 09U 2_only in conjunction with code PBI or certain countries i.V.m. Code PBI i.V.m. code PYA	●	●	●	●	●	●	52,50
		○	○	○	○	○	○	0,00
		○	○	○	○	○	○	0,00
09B	Owner's Manual and Service Booklet - Portuguese	○	○	○	○	○	○	0,00
09U	Preinstallation for Vehicle Monitoring 1_only in conjunction with code 08U 2_only in conjunction with code PBI or certain countries i.V.m. Code PBI i.V.m. Code PYA	●	●	●	●	●	●	52,50
		○	○	○	○	○	○	0,00
		○	○	○	○	○	○	0,00
10B	Owner's Manual and Service Booklet - Swedish	○	○	○	○	○	○	0,00
11B	Owner's Manual and Service Booklet - Arabic	○	○	○	○	○	○	0,00
12B	Owner's Manual and Service Booklet - Engl. USA/CAN	○	○	○	○	○	○	0,00
12U	Preinstallation for Concierge Service 1_only in conjunction with code R01 or R02 2_for certain countries only	○	○	○	○	○	○	0,00
13B	Owner's Manual and Service Booklet - Norwegian	○	○	○	○	○	○	0,00
14B	Owner's Manual and Service Booklet - Greek	○	○	○	○	○	○	0,00

1/8/2019

## Price list for the GLB

Valid from 13.08.2019 - MY 800

\* only South Korea

\*\* only USA/Canada

● available at extra charge ○ available at no extra charge U annotations existing

S standard equipment - not available

Code	Designation	GLB						LLP
		247.610	247.612	247.613	247.615	247.687	247.647	
		GLB 180 d	GLB 200 d	GLB 200 d 4MATIC	MATIC	GLB 200	GLB 250 4MATIC	
14U	Smartphone integration 1_only in conjunction with code 16U and 17U, code 355 or 859 2_for certain countries only i.V.m. Code PBI	●	●	●	●	●	●	315,00
		○	○	○	○	○	○	0,00
15B	Owner's Manual and Service Booklet - Turkish	○	○	○	○	○	○	0,00
15U	Preinstallation for Mercedes-Benz Link	S	S	S	S	S	S	0,00
16B	Owner's Manual and Service Booklet - Polish	○	○	○	○	○	○	0,00
16U	Apple CarPlay 1_only in conjunction with code 14U	○	○	○	○	○	○	0,00
17B	Owner's Manual and Service Booklet - Czech	○	○	○	○	○	○	0,00
17U	Android Auto 1_only in conjunction with code 14U	○	○	○	○	○	○	0,00
18B	Owner's Manual and Service Booklet - Engl. S. Am.	○	○	○	○	○	○	0,00
19B	Owner's Manual and Service Booklet - French S. Am.	○	○	○	○	○	○	0,00
20B	Owner's Manual and Service Booklet - Spanish S. Am.	○	○	○	○	○	○	0,00
20U	Pre-installation for car sharing 1_for certain countries only i.V.m. Code PYA	●	●	●	●	●	●	52,50
		○	○	○	○	○	○	0,00
213	Direct-Steer system 1_only in conjunction with code 457 2_not in conjunction with code 830	○	○	○	○	○	○	0,00
218	Reversing camera 1_not in conjunction with code 501, 498 i.V.m. Code P44 i.V.m. Code PYA	●	●	●	●	●	●	351,75
		○	○	○	○	○	○	0,00
		○	-	○	○	○	○	0,00
21B	Owner's Manual and Service Booklet - Portug. S. Am.	○	○	○	○	○	○	0,00
21U	Dashcam 1_only in conjunction with code 859 and 365 2_for certain countries only (524L, 830)	●	●	●	●	●	●	210,00
221	Electrically adjustable front seat, left 1_only in conjunction with code U22, 830 2_not in conjunction with code 241	-	-	-	-	○	-	0,00
222	Electrically adjustable front seat, right 1_only in conjunction with code U22 and 221, 830 2_not in conjunction with code 242	-	-	-	-	●	-	236,25
228	Auxiliary heater 1_for certain countries only in conjunction with code B24 2_for certain countries only, only for Left Hand Drive	●	●	●	●	●	●	1155,00
22B	Owner's Manual and Service Booklet - Japanese	○	○	○	○	○	○	0,00
231	Garage door opener 1_only in conjunction with code P49 2_for certain countries only	●	●	●	●	●	●	157,50

1/8/2019

## Price list for the GLB

Valid from 13.08.2019 - MY 800

\* only South Korea

\*\* only USA/Canada

● available at extra charge ○ available at no extra charge U annotations existing

S standard equipment - not available

		GLB						LLP
Code	Designation	247.610	247.612	247.613	247.615	247.687	247.647	
		GLB 180 d	GLB 200 d	GLB 200 d 4MATIC	MATIC	GLB 200	GLB 250 4MATIC	
232	Garage door opener (frequency range 284-390 MHz) 1_only in conjunction with code P49 2_for certain countries only	●	●	●	●	●	●	236,25
233	Active Distance Assist DISTRONIC 1_only in conjunction with code 23P, 266, 270, 273, 426 or 429 2_not in conjunction with code 234, 239, 243, 258, 440 3_for certain countries only	○	○	○	○	○	○	0,00
234	Blind Spot Assist 1_only in conjunction with code P49 or 275, 270 and 273 2_not in conjunction with code 233 3_for certain countries only i.V.m. Code 22P	●	●	●	●	●	●	472,50
235	Active Parking Assist with PARKTRONIC i.V.m. Code P44/P47	●	●	●	●	●	●	708,75
239	Active Distance Assist DISTRONIC 1_only in conjunction with code 426 or 429 2_not in conjunction with code 233, 258, 440 3_for certain countries only	●	●	●	●	●	●	630,00
23B	Owner's Manual and Service Booklet - simpl. Chinese	○	○	○	○	○	○	0,00
241	Power front left seat with memory function 1_only in conjunction with code 275 and U22 or 409 2_not in conjunction with code 7U1, 221 3_Right-hand-drive vehicles only i.V.m. Code PYO	●	●	●	●	●	●	299,25
242	Power front right seat with memory function 1_only in conjunction with code 275 and U22 or 409 2_not in conjunction with code 842 or 7U1 3_only for Left Hand Drive i.V.m. Code PYO	●	●	●	●	●	●	299,25
243	Active Lane Keeping Assist 1_not in conjunction with code 233 i.V.m. Code 22P i.V.m. S-Code 51B	●	●	●	●	●	●	472,50
249	Interior mirror and driver's exterior mirror automatically dimming 1_only in conjunction with code P49	○	○	○	○	○	○	0,00
24B	Owner's Manual and Service Booklet - trad. Chinese	○	○	○	○	○	○	0,00
258	Active Brake Assist 1_standard in certain countries 2_not in conjunction with code 233 or 239 3_for certain countries only	○	○	○	○	○	○	0,00
25B	Owner's Manual and Service Booklet - Korean	○	○	○	○	○	○	0,00
260	Deletion of model plate on boot lid	○	○	○	○	○	○	0,00
263	Number plate mounting for Asia / Mexico 1_not in conjunction with code 968 2_for certain countries only	○	○	○	○	○	○	0,00

1/8/2019

## Price list for the GLB

Valid from 13.08.2019 - MY 800

\* only South Korea

\*\* only USA/Canada

● available at extra charge ○ available at no extra charge ⓘ annotations existing

S standard equipment - not available

		GLB						LLP
Code	Designation	247.610	247.612	247.613	247.615	247.687	247.647	
		GLB 180 d	GLB 200 d	GLB 200 d 4MATIC	MATIC	GLB 200	GLB 250 4MATIC	
264	<b>Number plate mounting for USA/CAN</b> 1_not in conjunction with code 968 2_for certain countries only	○	○	○	○	-	○	0,00
266	<b>Active Steering Assist</b> 1_only in conjunction with code 233 2_for certain countries only	○	○	○	○	○	○	0,00
26B	<b>Owner's Manual and Service Booklet - Chinese Taiwan</b>	○	○	○	○	○	○	0,00
26U	<b>Preinstallation for engine remote start</b> 1_only in conjunction with code 08U 2_for certain countries only <b>i.V.m. S-Code PZG</b>	●	●	●	●	●	●	105,00
		●	●	●	●	●	●	157,50
270	<b>GPS aerial</b> 1_only in conjunction with code 233, 234, 355, 362, 501, 899 or B24	○	○	○	○	○	○	0,00
273	<b>Exit warning function</b> 1_only in conjunction with code 233 or 234	○	○	○	○	○	○	0,00
274	<b>Telephone aerial</b> 1_only in conjunction with code 501, 899 or B24 2_for certain countries only	○	○	○	○	○	○	0,00
275	<b>Driver's seat, electrically adjustable with memory function</b> 1_only in conjunction with code U22 or 409 and code 7U2 or 7U4 <b>i.V.m. Code PYO</b>	●	●	●	●	●	●	362,25
		○	○	○	○	○	○	0,00
286	<b>Luggage net on driver's and front pass. backrest</b> 1_only in conjunction with code 7U2 or 7U4	○	○	○	○	○	○	0,00
287	<b>Folding rear-seat backrests</b>	S	S	S	S	S	S	0,00
293	<b>Sidebags in rear</b> 1_only in conjunction with code 7U2 or 7U4	●	●	●	●	●	●	393,75
294	<b>Kneebag</b> 1_for certain countries only	○	○	○	○	○	○	0,00
299	<b>PRE-SAFE® system</b> 1_for certain countries only <b>i.V.m. Code 23P</b>	●	●	●	●	●	●	346,50
		○	○	○	○	○	○	0,00
29R	<b>50.8 cm (20-inch) 5-spoke light-alloy wheels</b> 1_only in conjunction with code P19 and 457 2_not in conjunction with code R66, 950, 460, 494, 830	○	○	○	○	○	○	0,00
2U0	<b>car2go pre-installation</b> 1_for certain countries only in conjunction with code P54 and 355 or 859 2_only in conjunction with code 460 or 494 and 852, code 355 or 859 3_not in conjunction with code 865	●	●	●	●	●	ⓘ	178,50
							★	
301	<b>Ashtray insert for cup holder with cigarette lighter</b> 1_for certain countries only	●	●	●	●	●	●	47,25
30B	<b>Owner's Manual and Service Booklet - Slovenian</b>	○	○	○	○	○	○	0,00
310	<b>Double cup holder</b> <b>i.V.m. Code P27/P59/950</b> <b>i.V.m. Code PYA</b>	●	●	●	●	●	●	26,25
		○	○	○	○	○	○	0,00
		○	○	○	○	○	○	0,00
31B	<b>Owner's Manual and Service Booklet - Hungarian</b>	○	○	○	○	○	○	0,00

1/8/2019

## Price list for the GLB

Valid from 13.08.2019 - MY 800

\* only South Korea

\*\* only USA/Canada

● available at extra charge ○ available at no extra charge U annotations existing

S standard equipment - not available

		GLB						LLP
Code	Designation	247.610	247.612	247.613	247.615	247.687	247.647	
		GLB 180 d	GLB 200 d	4MATIC	MATIC	GLB 200	GLB 250 4MATIC	
32B	Owner's Manual and Service Booklet - Bulgarian	○	○	○	○	○	○	0,00
33B	Owner's Manual and Service Booklet - Romanian	○	○	○	○	○	○	0,00
345	Windscreen wiper with rain sensor	S	S	S	S	S	S	0,00
34B	Owner's Manual and Service Booklet - Croatian	○	○	○	○	○	○	0,00
351	Mercedes-Benz emergency call system 1_only in conjunction with code 362	○	○	○	○	○	○	0,00
355	Extended MBUX functions 1_only in conjunction with code 548 or 549 and 270 and 446 2_for certain countries only i.V.m. Code PYA	●	●	●	●	●	●	472,50
		○	○	○	○	○	○	0,00
35B	Owner's Manual and Service Booklet - Latvian	○	○	○	○	○	○	0,00
362	Communications module (LTE) for the use of Mercedes me connect services 1_standard in certain countries 2_only in conjunction with code 270 and 351 3_for certain countries only	○	○	○	○	○	○	0,00
365	Hard-disc navigation 1_only in conjunction with code 355 i.V.m. Code PBF i.V.m. Code PYM/PYN/PYO	●	●	●	●	●	●	577,50
		○	○	○	○	○	○	0,00
		○	○	○	○	○	○	0,00
367	Preinstallation for Live Traffic Information 1_only in conjunction with code 355 and 362 2_for certain countries only	○	○	○	○	○	○	0,00
36B	Owner's Manual and Service Booklet - Lithuanian	○	○	○	○	○	○	0,00
37B	Owner's Manual and Service Booklet - Slovakian	○	○	○	○	○	○	0,00
38B	Owner's Manual and Service Booklet - Estonian	○	○	○	○	○	○	0,00
39B	Owner's Manual and Service Booklet - Serbian	○	○	○	○	○	○	0,00
400	Rear armrest	S	S	S	S	S	S	0,00
401	Climatised front seats 1_only in conjunction with upholstery code 101A, 105A, 159A, 201A, 205A, 211A, 214A, 224A, 257A or 258A 2_not in conjunction with code 873, 830 i.V.m. Code P19 i.V.m. Code PBP/PBR i.V.m. Code PYN/PYO	●	●	●	●	●	●	934,50
		●	●	●	●	●	●	630,00
		●	●	●	●	●	●	630,00
		●	●	●	●	●	●	630,00
409	Multicontour seat package 1_only in conjunction with Code 7U2 2_not in conjunction with upholstery code 311A, 331A, 335A, 379A, 384A, code U22, 830 i.V.m. Code PBR	●	●	●	●	●	●	619,50
		○	○	○	○	○	○	0,00
40B	Owner's Manual and Service Booklet - ukrainian	○	○	○	○	○	○	0,00
413	Panoramic sliding sunroof 1_only in conjunction with code 720 or 725 and U62 i.V.m. Code PYO	●	●	●	●	●	●	1228,50
		○	○	○	○	○	○	0,00
41B	Owner's Manual and Service Booklet - hebrew	○	○	○	○	○	○	0,00
428	Steering wheel shift paddles 1_only in conjunction with code 426 or 429 and L3B or L3E 2_not in conjunction with code 431	○	○	○	○	○	○	0,00
42B	Owner's Manual and Service Booklet - Indonesian	○	○	○	○	○	○	0,00
43B	Owner's Manual and Service Booklet - Thai	○	○	○	○	○	○	0,00
440	Cruise control 1_not in conjunction with code 233 or 239	S	S	S	S	S	S	0,00
443	Steering wheel heating 1_only in conjunction with code 426 or 429 and L3B	●	●	●	●	●	●	168,00
446	Touchpad without Controller	●	●	●	●	●	●	199,50

1/8/2019

## Price list for the GLB

Valid from 13.08.2019 - MY 800

\* only South Korea

\*\* only USA/Canada

● available at extra charge ○ available at no extra charge U annotations existing

S standard equipment - not available

Code	Designation	GLB						LLP
		247.610	247.612	247.613	247.615	247.687	247.647	
	1_included in delivery of code 355, 859, 498, 830							
	<b>i.V.m. Code PYA</b>	○	○	○	○	○	○	0,00
<b>44B</b>	<b>Owner's Manual and Service Booklet - Vietnamese</b>	○	○	○	○	○	○	0,00
<b>457</b>	<b>Adjustable damping</b>	●	●	●	●	●	●	1039,50
	1_only in conjunction with code 213							
	2_not in conjunction with code 485, 830							
	<b>i.V.m. Code PAD/P19</b>	○	○	○	○	○	○	0,00
<b>458</b>	<b>All-digital instrument display</b>	●	●	●	●	●	●	472,50
	1_only in conjunction with code 859							
	<b>i.V.m. Code PYN/PYO</b>	○	○	○	○	○	○	0,00
<b>460</b>	<b>Canada specification</b>	-	-	-	-	-	○	0,00
<b>461</b>	<b>Instrument display in miles with English lettering</b>	○	○	○	○	○	○	0,00
	1_for certain countries only							
<b>463</b>	<b>Head-up Display</b>	●	●	●	●	●	●	1039,50
	1_only in conjunction with code 355 or 859 and P59 or 950							
<b>475</b>	<b>Tyre pressure monitoring system</b>	●	●	●	●	●	●	320,25
	1_standard in certain countries							
	<b>i.V.m. S-Code 6P5</b>	○	○	○	○	○	○	0,00
<b>477</b>	<b>Tyre pressure loss warning system</b>	○	○	○	○	○	○	0,00
	1_for certain countries only							
<b>485</b>	<b>Comfort suspension</b>	S	S	S	S	S	S	0,00
	1_not in conjunction with code 213							
<b>500</b>	<b>Electrically folding exterior mirrors</b>	○	○	○	○	○	○	0,00
	1_only in conjunction with code P49 or certain countries							
<b>501</b>	<b>360° camera</b>	○	○	○	○	○	○	0,00
	1_included in delivery of code P47							
	2_only in conjunction with code 270 and 274 or 700							
<b>504</b>	<b>Speed Limit Assist</b>	○	○	○	○	○	○	0,00
	1_not in conjunction with code 513							
<b>513</b>	<b>Traffic Sign Assist</b>	●	●	●	●	●	●	309,75
	1_only in conjunction with code 365							
	2_not in conjunction with code 504							
	3_for certain countries only							
<b>517</b>	<b>HD digital radio standard</b>	○	○	○	○	○	○	0,00
	1_for certain countries only							

1/8/2019

## Price list for the GLB

Valid from 13.08.2019 - MY 800

\* only South Korea

\*\* only USA/Canada

● available at extra charge ○ available at no extra charge U annotations existing

S standard equipment - not available

Code	Designation	GLB						LLP
		247.610 GLB 180 d	247.612 GLB 200 d	247.613 4MATIC	247.615 MATIC	247.687 GLB 200	247.647 GLB 250 4MATIC	
518	Media Interface Cable kit 1_for certain countries only	●	●	●	●	●	●	52,50
51U	Roof liner in black fabric	○	○	○	○	○	○	0,00
524	Transport protection 1_not in conjunction with code 820 2_for certain countries only	●	●	●	●	●	●	168,00
52R	45.7 cm (18-inch) 5-spoke light-alloy wheels 1_only in conjunction with code R02 and R66, R01 2_not in conjunction with code 950, 830	●	●	●	●	●	●	840,00
	i.V.m. Code P27	●	●	●	●	●	●	630,00
	i.V.m. Code P59	○	○	○	○	○	○	0,00
	i.V.m. Code PYF	○	○	○	○	○	○	0,00
536	Radio: SIRIUS/SDARS ex factory 1_only in conjunction with code 355 or 859 2_not in conjunction with code 968, 969 3_for certain countries only	-	-	-	-	-	●	367,50
537	Digital radio 1_only in conjunction with code 79B i.V.m. Code PYA	●	●	●	●	●	●	210,00
		○	○	○	○	○	○	0,00
543	Sun visor with illuminated vanity mirror	S	S	S	S	S	S	0,00
545	MBUX multimedia system 1_not in conjunction with code 355, 859, B63, PBF, PBG, PBP, PBR, 21U, U19 2_for certain countries only	S	S	S	S	S	S	0,00
546	Active Speed Limit Assist 1_only in conjunction with code 233 and 513 2_for certain countries only	○	○	○	○	○	○	0,00
547	MBUX multimedia system 1_standard in certain countries and only in conjunction with code 859 2_not in conjunction with code 355, 21U, U19, PBP, PBR 3_for certain countries only	○	○	○	○	○	○	0,00
548	MBUX multimedia system 1_standard in certain countries 2_in certain countries only in conjunction with code 355 or 2U0 3_not in conjunction with code 21U, U19, PBP, PBR 4_for certain countries only	○	○	○	○	○	○	0,00
549	MBUX multimedia system 1_standard in certain countries 2_only in conjunction with code 21U, U19, PBP or PBR 3_for certain countries only	○	○	○	○	○	○	0,00
550	Trailer coupling with ESP® trailer stabilisation 1_for certain countries only	●	●	●	●	●	●	840,00

1/8/2019

## Price list for the GLB

Valid from 13.08.2019 - MY 800

\* only South Korea

\*\* only USA/Canada

● available at extra charge ○ available at no extra charge U annotations existing

S standard equipment - not available

		GLB						LLP
Code	Designation	247.610	247.612	247.613	247.615	247.687	247.647	
		GLB 180 d	GLB 200 d	GLB 200 d 4MATIC	MATIC	GLB 200	GLB 250 4MATIC	
551	Anti-theft alarm system with preinstallation for parking damage notification 1_in certain countries included in delivery of code P54 2_for certain countries only i.V.m. Code P54	●	●	●	●	●	●	262,50
		○	○	○	○	○	○	0,00
552	Anti-theft alarm system with preinstallation for parking damage notification 1_only in conjunction with code P54 and 513L	○	○	○	○	○	○	0,00
554	Pre-installation for trailer coupling 1_for certain countries only	●	●	●	●	●	●	168,00
55U	Headlining in beige fabric 1_only in conjunction with upholstery code 105A, 205A, 335A	○	○	○	○	○	○	0,00
567	Rear seats with fore/aft adjustment 1_only in conjunction with code 7U2 or 7U4 2_not in conjunction with code 847 3_for certain countries only i.V.m. Code P19 i.V.m. Code PYD/PYF/PYH	●	●	●	●	●	●	378,00
		○	○	○	○	○	○	0,00
		○	○	○	○	○	○	0,00
580	THERMATIC automatic climate control 1_not in conjunction with code PBR 2_for certain countries only	○	○	○	○	○	○	0,00
581	THERMOTRONIC automatic climate control i.V.m. Code PBR i.V.m. Code PYF/PYH	●	●	●	●	●	●	535,50
		○	○	○	○	○	○	0,00
		○	○	○	○	○	○	0,00
586	Surround lighting with projection of brand logo	●	●	●	●	●	●	115,50
58U	Roof liner in crystal grey fabric 1_not in conjunction with upholstery code 105A, 159A, 205A, 224A, 335A, 379A	○	○	○	○	○	○	0,00
608	Adaptive Highbeam Assist 1_only in conjunction with code 631 or 632 2_not in conjunction with code 628 3_for certain countries only i.V.m. Code 640	●	●	●	●	●	●	189,00
		○	○	○	○	○	○	0,00
613	Halogen headlamps for left-hand traffic including integral LED daytime running lamps 1_not in conjunction with code PAD, P19 2_for certain countries only	○	○	○	○	○	○	0,00
620	Halogen headlamps including integral LED daytime running lamps 1_not in conjunction with code PAD, P19 2_for certain countries only	○	○	○	○	○	○	0,00
623	Gulf States specification	●	●	●	●	●	●	157,50
625	Australia specification	○	○	○	○	○	○	0,00

1/8/2019

## Price list for the GLB

Valid from 13.08.2019 - MY 800

\* only South Korea

\*\* only USA/Canada

● available at extra charge ○ available at no extra charge U annotations existing

S standard equipment - not available

		GLB						LLP
Code	Designation	247.610	247.612	247.613	247.615	247.687	247.647	
		GLB 180 d	GLB 200 d	GLB 200 d 4MATIC	MATIC	GLB 200	GLB 250 4MATIC	
628	<b>Adaptive Highbeam Assist Plus</b> 1_only in conjunction with code 641 or 642 2_not in conjunction with code 608	○	○	○	○	○	○	0,00
631	<b>LED High Performance headlamp</b> 1_not in conjunction with code PAD 2_for certain countries only <b>i.V.m. Code P19</b> <b>i.V.m. Code PYD/PYF/PYH</b>	●	●	●	●	●	●	871,50
		○	○	○	○	○	○	0,00
		○	○	○	○	○	○	0,00
632	<b>LED High Performance headlamp</b> 1_not in conjunction with code PAD 2_only for certain countries <b>i.V.m. Code P19</b> <b>i.V.m. Code PYD/PYF/PYH</b>	●	●	●	●	●	●	871,50
		○	○	○	○	○	○	0,00
		○	○	○	○	○	○	0,00
634	<b>Omission of first-aid kit</b> 1_not in conjunction with code 820 2_for certain countries only	○	○	○	○	○	○	0,00
636	<b>Omission of hazard warning triangle</b> 1_not in conjunction with code 820 2_for certain countries only	○	○	○	○	○	○	0,00
640	<b>MULTIBEAM LED</b> 1_only in conjunction with code 608 2_for certain countries only <b>i.V.m. Code P19</b>	●	●	●	●	-	●	1312,50
		●	●	●	●	-	●	441,00
641	<b>MULTIBEAM LED</b> 1_only in conjunction with code 628 2_for certain countries only <b>i.V.m. Code P19</b> <b>i.V.m. Code PAD</b> <b>i.V.m. Code PYD/PYF/PYH</b> <b>i.V.m. Code PYO</b>	●	●	●	●	●	●	1312,50
		●	●	●	●	●	●	441,00
		○	○	○	○	○	○	0,00
		●	●	●	●	●	●	441,00
		○	○	○	○	○	○	0,00
642	<b>MULTIBEAM LED</b> 1_only in conjunction with code 628 2_for certain countries only <b>i.V.m. Code P19</b> <b>i.V.m. Code PAD</b> <b>i.V.m. Code PYD/PYF/PYH</b> <b>i.V.m. Code PYO</b>	●	●	●	●	●	●	1312,50
		●	●	●	●	●	●	441,00
		○	○	○	○	○	○	0,00
		●	●	●	●	●	●	441,00
		○	○	○	○	○	○	0,00
643	<b>43.2 cm (17-inch) steel wheels with wheel trims</b> 1_only in conjunction with code R01 2_not in conjunction with code R66, U29, 950, 460, 494, 830	○	○	○	○	○	○	0,00
645	<b>M+S winter tyres, set of 4</b> <b>1_only in conjunction with code 72R, R26, RTF, 29R, 96R</b> 2_not in conjunction with code 651, 652, 460, 494, 498, 830	●	●	●	●	●	●	115,50

1/8/2019

## Price list for the GLB

Valid from 13.08.2019 - MY 800

\* only South Korea

\*\* only USA/Canada

● available at extra charge ○ available at no extra charge U annotations existing

S standard equipment - not available

		GLB						LLP
Code	Designation	247.610 GLB 180 d	247.612 GLB 200 d GLB 200 d 4MATIC	247.613 4MATIC	247.615 MATIC	247.687 GLB 200	247.647 GLB 250 4MATIC	
666	<b>Freight packaging without tie-down hooks</b> 1_not in conjunction with code 668 2_for certain countries only	●	●	●	●	●	●	26,25
668	<b>Freight packaging with tie-down hooks</b> 1_not in conjunction with code 550, 666 2_for certain countries only	●	●	●	●	●	●	0,00
682	<b>Fire extinguisher</b> 1_for certain countries only	●	●	●	●	●	●	0,00
687	<b>Model year on model plate</b> 1_not in conjunction with code 969, 968 2_for certain countries only	○	○	○	○	○	○	0,00
690	<b>Emergency spare wheel</b> 1_only in conjunction with code B12 2_for certain countries not in conjunction with code R66 3_for certain countries only	○	○	○	○	○	○	0,00
700	<b>Produktionsstandort Fahrzeug China</b> 1_only in conjunction with code 830	-	-	-	-	○	-	0,00
70B	<b>Fluorescent jacket for driver</b> 1_not in conjunction with code 71B	●	●	●	●	●	●	5,25
71B	<b>Safety vests for driver and passengers</b> 1_not in conjunction with code 70B 2_for certain countries only	●	●	●	●	●	●	26,25
720	<b>Roof rails in black</b> 1_included in delivery of code P55, P60, P19	○	○	○	○	○	○	0,00
725	<b>Polished aluminium roof rails</b> 1_not in conjunction with code P55, P60, P19 <b>i.V.m. Code P27/P59/950</b> <b>i.V.m. Code PYA</b>	●	●	●	●	●	●	262,50
		○	○	○	○	○	○	0,00
		○	○	○	○	○	○	0,00
72R	<b>43.2 cm (17-inch) 10-spoke light-alloy wheels</b> 1_only in conjunction with code R01 or 645 2_not in conjunction with code R66, U29, 950, 460, 494, 830	○	○	○	○	○	○	0,00
73B	<b>Stowage compartment in centre console, with retractable cover</b> 1_only in conjunction with code 426 or 429 2_for certain countries only	●	●	●	●	●	●	0,00
762	<b>Radio remote control without panic button</b> 1_for certain countries only	○	○	○	○	○	○	0,00
763	<b>Radio remote control with panic switch</b> 1_only in conjunction with code 551 and certain countries 2_not in conjunction with code 762, 968, 969	○	○	○	○	○	○	0,00
772	<b>AMG bodystyling</b> 1_included in delivery of code 950	○	○	○	○	○	○	0,00

1/8/2019

## Price list for the GLB

Valid from 13.08.2019 - MY 800

\* only South Korea

\*\* only USA/Canada

● available at extra charge ○ available at no extra charge U annotations existing

S standard equipment - not available

		GLB						LLP
Code	Designation	247.610	247.612	247.613	247.615	247.687	247.647	
		GLB 180 d	GLB 200 d	GLB 200 d 4MATIC	MATIC	GLB 200	GLB 250 4MATIC	
79B	<b>Preinstallation for digital radio</b> 1_in certain countries only in conjunction with code 362 2_in certain countries only in conjunction with code 537 3_only for certain countries in conjunction with code 355 and 859 and 362	○	○	○	○	○	○	0,00
7U1	<b>Manually adjustable front seats</b> 1_only in conjunction with upholstery code 301A 2_not in conjunction with code 7U2, 7U4	○	○	○	○	○	○	0,00
7U2	<b>Comfort Seats</b> 1_only in conjunction with upholstery code 101A, 104A, 105A, 201A, 205A, 311A, 331A, 335A, 379A or 384A, code U59 and 286 2_not in conjunction with code 7U1, 7U4	○	○	○	○	○	○	0,00
7U4	<b>Sports seats</b> 1_only in conjunction with upholstery code 159A, 211A, 214A, 224A, 257A, 258A or 651A, code U59 and 286 2_not in conjunction with code 7U1, 7U4 <b>i.V.m. Code 950</b> <b>i.V.m. Code P19</b>	●	●	●	●	●	●	246,75
		○	○	○	○	○	○	0,00
		○	○	○	○	○	○	0,00
800	<b>Technical modifications</b>	○	○	○	○	○	○	0,00
810	<b>Burmester® surround sound system</b> 1_only in conjunction with code 355 or 859 2_not in conjunction with code 853 3_for certain countries only <b>i.V.m. Code PBP/PBR</b> <b>i.V.m. Code PYN/PYO</b>	●	●	●	●	●	●	698,25
		●	●	●	●	●	●	435,75
		●	●	●	●	●	●	435,75
820	<b>Tourist vehicle</b> 1_not in conjunction with code 634 or 636 2_for certain countries only	○	○	○	○	○	○	0,00
821	<b>Country code Brazil</b>	-	-	-	-	○	-	0,00
822	<b>South Africa specification</b>	○	○	○	○	○	○	0,00
823	<b>country code Switzerland</b>	○	○	○	○	○	○	0,00
824	<b>Additional parts for cold countries (engine air intake screen)</b> 1_for certain countries only	○	○	○	○	○	○	0,00
829	<b>Taiwan version</b>	○	○	○	○	○	○	0,00
830	<b>China specification</b>	-	-	-	-	○	-	0,00
831	<b>country code Italia</b>	○	○	○	○	○	○	0,00
835	<b>South Korea specification</b>	-	○	-	-	-	○	0,00
840	<b>Heat-insulating dark-tinted glass</b> 1_only in conjunction with code P27, P59 or 950 2_not in conjunction with code U50 3_for certain countries only <b>i.V.m. Code P19</b> <b>i.V.m. Code P55</b> <b>i.V.m. Code PYH</b>	●	●	●	●	●	●	315,00
		○	○	○	○	○	○	0,00
		○	○	○	○	○	○	0,00
		○	○	○	○	○	○	0,00

1/8/2019

## Price list for the GLB

Valid from 13.08.2019 - MY 800

\* only South Korea

\*\* only USA/Canada

● available at extra charge ○ available at no extra charge U annotations existing

S standard equipment - not available

		GLB						LLP
Code	Designation	247.610	247.612	247.613	247.615	247.687	247.647	
		GLB 180 d	GLB 200 d	GLB 200 d 4MATIC	MATIC	GLB 200	GLB 250 4MATIC	
842	<b>Folding front passenger seat</b> 1_only in conjunction with code 7U2 2_not in conjunction with code 242, 409, 866, 494, 830 3_only for LHD models 4_available from 4th quarter 2019	●	●	●	●	●	●	157,50
847	<b>3rd row of seats for 2 people</b> 1_only in conjunction with code 52R, R38, 97R, R26, R84, 96R, 29R, RTF, RTG, RVV or RVW 2_not in conjunction with code 567, 690, upholstery code 214A, 301A, 379A  3_available from 4th quarter 2019	●	●	U	U	●	●	1165,50
	<b>i.V.m. Code P19</b>	●	●	●	●	●	●	787,50
	<b>i.V.m. code PYD/PYF/PYH</b>	●	●	●	●	●	●	787,50
852	<b>Sensor system for anti-theft alarm system</b> 1_only in conjunction with code 551 and 460 or 494 2_not in conjunction with code 882	-	-	-	-	-	●	147,00
	<b>i.V.m. Code 362</b>	-	-	-	-	-	●	178,50
853	<b>Advanced Sound System</b> 1_not in conjunction with code 810	●	●	●	●	●	●	262,50
	<b>i.V.m. Code PBP/PBR</b>	○	○	○	○	○	○	0,00
	<b>i.V.m. Code PYN/PYO</b>	○	○	○	○	○	○	0,00
859	<b>Media-Display</b> 1_only in conjunction with code 547, 548 or 549 and 446 2_for certain countries only	●	●	●	●	●	●	682,50
	<b>i.V.m. Code PBP/PBR</b>	○	○	○	○	○	○	0,00
	<b>i.V.m. Code PYM/PYN/PYO</b>	○	○	○	○	○	○	0,00
862	<b>Pre-installation for digital TV Japan</b> 1_only in conjunction with code 355 and 859 2_not in conjunction with code 865 3_for certain countries only	●	●	●	●	●	●	94,50
865	<b>TV tuner Japan</b> 1_only in conjunction with code 355 and 859 2_not in conjunction with code 862 3_for certain countries only	●	●	●	●	●	●	945,00
866	<b>Preinstallation for entertainment and comfort features</b> 1_only in conjunction with code 7U2 or 7U4 2_not in conjunction with code 842 3_for certain countries only 4_available from 4th quarter 2019	●	●	●	●	●	●	136,50
871	<b>HANDS-FREE ACCESS</b> 1_only in conjunction with code P17	○	○	○	○	○	○	0,00

1/8/2019

## Price list for the GLB

Valid from 13.08.2019 - MY 800

\* only South Korea

\*\* only USA/Canada

● available at extra charge ○ available at no extra charge U annotations existing

S standard equipment - not available

		GLB						LLP
Code	Designation	247.610	247.612	247.613	247.615	247.687	247.647	
		GLB 180 d	GLB 200 d	GLB 200 d 4MATIC	MATIC	GLB 200	GLB 250 4MATIC	
873	<b>Heated front seats</b> 1_not in conjunction with code 401 <b>i.V.m. Code P19</b> <b>i.V.m. Code PBP/PBR</b> <b>i.V.m. Code PYN/PYO</b>	● ○ ○ ○	● ○ ○ ○	● ○ ○ ○	● ○ ○ ○	● ○ ○ ○	● ○ ○ ○	304,50 0,00 0,00 0,00
875	<b>Heated windscreen washer system</b>	●	●	●	●	●	●	120,75
877	<b>Ambient lighting</b> 1_only in conjunction with code P27, P59 or 950 <b>i.V.m. Code PBP/PBR/P19</b> <b>i.V.m. Code PYN/PYO</b>	● ○ ○	● ○ ○	● ○ ○	● ○ ○	● ○ ○	● ○ ○	309,75 0,00 0,00
882	<b>Interior monitoring system</b> 1_only in conjunction with code P54 2_not in conjunction with code 852	○	○	○	○	○	○	0,00
885	<b>Increased anti-theft protection</b> 1_only in conjunction with code 537L	○	○	○	○	○	○	0,00
889	<b>KEYLESS-GO</b> 1_only in conjunction with code P27, P59 or 950 2_not in conjunction with code U27, paint code 817U <b>i.V.m. Code PAD/P17</b>	● ○	● ○	● ○	● ○	● ○	● ○	420,00 0,00
890	<b>EASY-PACK tailgate</b> 1_for certain countries only <b>i.V.m. Code P17</b> <b>i.V.m. Code PYD/PYF/PYH</b>	● ○ ○	● ○ ○	● ○ ○	● ○ ○	● ○ ○	● ○ ○	409,50 0,00 0,00
896	<b>Preinstallation for Digital vehicle key for smartphone</b> 1_only in conjunction with code 897 or 899 and 362 2_for certain countries only	●	●	●	●	●	●	105,00
897	<b>Wireless charging system for mobile devices</b> 1_only in conjunction with code P27, P59 or 950 2_not in conjunction with code 899 3_for certain countries only	●	●	●	●	●	●	210,00
899	<b>Multifunction telephony</b> 1_only in conjunction with code P27, P59 or 950 and 270, 274 2_not in conjunction with code 897 3_for certain countries only	●	●	●	●	●	●	514,50
913	<b>Air conditioning preinstallation for hot countries</b> 1_for certain countries only	○	○	○	○	-	-	0,00
916	<b>Fuel tank with increased capacity</b> 1_for certain countries only	-	-	S	S	-	S	0,00
922	<b>Reduced output engines</b> 1_for certain countries only (524L/528L/810L)	-	-	-	-	○	-	0,00
926	<b>Emission control system with EU4 technology</b> 1_not in conjunction with code U79 2_for certain countries only	○	○	○	○	○	○	0,00
927	<b>EU6 emissions standard</b> 1_for certain countries only	○	○	○	○	○	○	0,00
933	<b>Engine for ethanol fuel E100</b> 1_not in conjunction with code 968, 969 2_for certain countries only	-	-	-	-	●	-	315,00
936	<b>Cylinder shut-off</b> 1_for certain countries only	-	-	-	-	○	-	0,00
942	<b>Load compartment package</b> 1_only in conjunction with code U35 <b>i.V.m. Code P19</b> <b>i.V.m. Code PYA</b>	● ○ ○	● ○ ○	● ○ ○	● ○ ○	● ○ ○	● ○ ○	157,50 0,00 0,00
945	<b>Emission control system China</b>	-	-	-	-	○	-	0,00

## Price list for the GLB

GLB	
247,610	GLB 180 d
247,612	GLB 200 d
247,613	4MATIC
247,615	MATIC
247,687	GLB 200
247,647	GLB 250 4MATIC

● available at extra charge   ○ available at no extra charge   ◐ annotations existing  
S standard equipment   - not available

1/8/2019

## Price list for the GLB

Valid from 13.08.2019 - MY 800

\* only South Korea

\*\* only USA/Canada

● available at extra charge ○ available at no extra charge U annotations existing

S standard equipment - not available

		GLB						LLP
Code	Designation	247.610	247.612	247.613	247.615	247.687	247.647	
		GLB 180 d	GLB 200 d	GLB 200 d 4MATIC	MATIC	GLB 200	GLB 250 4MATIC	
997	Display vehicle for exhibitions (motor show veh.) 1_only for certain countries	○	○	○	○	○	○	0,00
B08	Fanfare horn Asia 1_for certain countries only	○	○	○	○	○	○	0,00
B12	Tyre-change toolkit 1_only in conjunction with code 690 2_for certain countries only	●	●	●	●	●	●	31,50
B18	Spectacles compartment for driver	S	S	S	S	S	S	0,00
B24	Remote control for auxiliary heating 1_only in conjunction with code 228 and 362 (only for certain countries) 2_for certain countries only	●	●	●	●	●	●	210,00
B51	TIREFIT 1_not in conjunction with code R66 (for certain countries only) 2_for certain countries only i.V.m. Code PYA	●	●	●	●	●	●	52,50
B59	DYNAMIC SELECT	S	S	S	S	S	S	0,00
B63	Sporty engine sound 1_only in conjunction with code 950 and 355 or 859	-	○	○	○	○	○	0,00
B68	Vehicle key in high-gloss white with ornamental surround in high-gloss chrome 1_only in conjunction with code P27, P59 or 950 and 890 2_not in conjunction with code 830	●	●	●	●	●	●	105,00
H15	wood linden black open-pored trim 1_only in conjunction with code P59 or 950	●	●	●	●	●	●	273,00
H23	Brown open-pore walnut wood trim 1_only in conjunction with code P34 or P59 i.V.m. Code P19	●	●	●	●	●	●	273,00
H59	Carbon-fibre-look trim 1_not in conjunction with code P27, P59, 950, 877, 498, 830	○	○	○	○	○	○	0,00
H60	Spiral-look trim elements 1_only in conjunction with code P59	S	S	S	S	S	S	0,00
H61	Ellipse-look trim 1_included in delivery of code P27	○	○	○	○	○	○	0,00
H62	Carbon-structure trim 1_included in delivery of code 950	○	○	○	○	○	○	0,00
K32	Active Lane Change Assist 1_only in conjunction with code 266 and 365 2_for certain countries only	○	○	○	○	○	○	0,00

1/8/2019

## Price list for the GLB

Valid from 13.08.2019 - MY 800

\* only South Korea

\*\* only USA/Canada

● available at extra charge ○ available at no extra charge U annotations existing

S standard equipment - not available

		GLB						LLP
Code	Designation	247.610	247.612	247.613	247.615	247.687	247.647	
		GLB 180 d	GLB 200 d	GLB 200 d 4MATIC	MATIC	GLB 200	GLB 250 4MATIC	
K33	<b>Extended automatic Re-start in traffic jams</b> 1_only in conjunction with code 233, 235 and 365 2_for certain countries only	○	○	○	○	○	○	0,00
K34	<b>Route-based speed adaptation</b> 1_only in conjunction with code 233 and 365 2_for certain countries only	○	○	○	○	○	○	0,00
L3B	<b>Multifunction sports steering wheel in nappa leather</b> 1_only in conjunction with code 443, code 428 and 426 or 429 2_in conjunction with code 950 only in conjunction with code 460, 494 3_not in conjunction with code 830	○	○	○	○	○	○	0,00
L3E	<b>Multifunction sports steering wheel in leather</b> 1_only in conjunction with code 411, code 428 and 426 or 429 2_not in conjunction with code 443, 950	S	S	S	S	S	S	0,00
L5C	<b>Multifunction sports steering wheel in nappa leather</b> 1_only in conjunction with code 411, code 431 and 426 or 429 2_in conjunction with code 950 not in conjunction with code 443	○	○	○	○	○	○	0,00
L5I	<b>Multifunction sports steering wheel in nappa leather / DINAMICA microfibre</b> 1_only in conjunction with code 950 and 431 and 426 or 429 2_not in conjunction with code 443	●	●	●	●	●	●	241,50
R01	<b>Summer tyres</b> 1_only in conjunction with code 72R, R11, R43 or 643 for certain countries; code 52R, 97R, R38, R26, R84 or 98R f. c. count. only i.c.w. R66; code 29R, 96R, RVV, RVW, RTF or RTG 2_for certain countries only	○	○	○	○	○	○	0,00
R02	<b>All season tyres</b> 1_only in conjunction with code 460 or 494, code R66 and R26, R38, R84, 52R, 97R, RTF or RTG	●	●	●	●	-	●	115,50
R03	<b>Sports tyres</b> 1_only in conjunction with code R26, R84, 98R, RTF or RTG 2_not in conjunction with code R66 3_for certain countries only	○	○	○	○	○	○	0,00
R11	<b>43.2 cm (17-inch) 5-twin-spoke light-alloy wheels</b> 1_only in conjunction with code R01 2_not in conjunction with code R66, U29, 950, 460, 494, 830	●	●	●	●	●	●	210,00
	<b>i.V.m. Code P27</b>	○	○	○	○	○	○	0,00
	<b>i.V.m. Code PYD</b>	○	○	○	○	○	○	0,00
R26	<b>48.3 cm (19") 10-spoke light-alloy wheels</b> 1_not in conjunction with code 950 2_for certain countries only	●	●	●	●	●	●	1312,50
	<b>i.V.m. Code (P55+P59)/P59</b>	●	●	●	●	●	●	472,50
	<b>i.V.m. Code P27</b>	●	●	●	●	●	●	1102,50
	<b>i.V.m. Code PYF</b>	●	●	●	●	●	●	472,50

1/8/2019

## Price list for the GLB

Valid from 13.08.2019 - MY 800

\* only South Korea

\*\* only USA/Canada

● available at extra charge ○ available at no extra charge ① annotations existing

S standard equipment - not available

		GLB						LLP
Code	Designation	247.610	247.612	247.613	247.615	247.687	247.647	
		GLB 180 d	GLB 200 d	GLB 200 d 4MATIC	MATIC	GLB 200	GLB 250 4MATIC	
R38	45.7 cm (18-inch) 5-twin-spoke light-alloy wheels 1_only in conjunction with code R02 and R66, R01 2_not in conjunction with code 950, 830 i.V.m. Code (P55+P59)/P59 i.V.m. Code P27	● ○ ●	● ○ ●	● ○ ●	● ○ ●	● ○ ●	● ○ ●	840,00  0,00 630,00
R43	43.2 cm (17-inch) 10-spoke light-alloy wheels 1_only in conjunction with code R01 2_not in conjunction with code 950, R66, U29, 460, 494, 830	○	○	○	○	○	○	0,00
R66	Run-flat tyres 1_in conjunction with code R01 only in conjunction with code 52R, 97R or R38 (o. c. countries), code R26, R84, RTF or RTG 2_in conjunction with code R02 only in conjunction with code 460 or 494 3_not in conjunction with code 29R, 72R, 96R, R11, R43, 643, RVV, RVW or R03, code 830	●	●	●	●	●	●	231,00
R84	48.3 cm (19-inch) 5-twin-spoke light-alloy wheels 1_not in conjunction with code 950 i.V.m. Code (P55+P59)/P59 i.V.m. Code P19 i.V.m. Code P27	● ● - ●	● ● - ●	● ● - ●	● ● - ●	● ● ○ ●	● ● - ●	1312,50  472,50 0,00 1102,50
RTF	48.3 cm (19-inch) AMG 5-twin-spoke light-alloy wheels 1_only in conjunction with code 950 i.V.m. Code PYH	○ ○	○ ○	○ ○	○ ○	○ ○	○ ○	0,00 0,00
RTG	48.3 cm (19-inch) AMG 5-twin-spoke light-alloy wheels i.V.m. Code (P55+P59)/P59 i.V.m. Code 950 i.V.m. Code P27 i.V.m. Code P55+950	● ● ● ● ○	● ● ● ● ○	● ● ● ● ○	● ● ● ● ○	● ● ● ● ○	● ● ● ● ○	1785,00 945,00 210,00 1575,00 0,00
RVV	50.8 cm (20-inch) AMG multi-spoke alloy wheels 1_only in conjunction with code 457 and R01 2_not in conjunction with code 700, R66 i.V.m. Code (P55+P59)/P59 i.V.m. Code 950 i.V.m. Code P27	● ● ● ● ●	● ● ● ● ●	● ● ● ● ●	● ● ● ● ●	● ● ● ● ●	● ● ● ● ●	2100,00  1260,00 630,00 1890,00
RVW	50.8 cm (20-inch) AMG multi-spoke light-alloy wheels 1_only in conjunction with code 457 and R01 2_not in conjunction with code 830, R66 i.V.m. Code (P55+P59)/P59 i.V.m. Code 950 i.V.m. Code P27 i.V.m. Code PYH	● ● ● ● ●	● ● ● ● ●	● ● ● ● ●	● ● ● ● ●	● ● ● ● ●	● ● ● ● ●	2467,50  1627,50 997,50 2257,50 997,50
U01	Status display for rear seat belts in instrument cluster 1_for certain countries only	○	○	○	○	○	○	0,00

1/8/2019

## Price list for the GLB

Valid from 13.08.2019 - MY 800

\* only South Korea

\*\* only USA/Canada

● available at extra charge ○ available at no extra charge U annotations existing

S standard equipment - not available

## GLB

Code	Designation	247.610	247.612	247.613	247.615	247.687	247.647	LLP
		GLB 180 d	GLB 200 d	GLB 200 d 4MATIC	MATIC	GLB 200	GLB 250 4MATIC	
U10	Automatic deactivation of front passenger airbag i.V.m. S-Code 51B	● ○	● ○	● ○	● ○	● ○	● ○	99,75 0,00
U12	Velour floor mats 1_not in conjunction with code 498, 830, 950, U26, U66 i.V.m. Code PYA	● ○	● ○	● ○	● ○	● ○	● ○	84,00 0,00
U19	MBUX augmented reality for navigation 1_only in conjunction with code 365 and 859 2_for certain countries only	●	●	●	●	●	●	262,50
U22	4-way lumbar support 1_only in conjunction with code U59 2_not in conjunction with code 409 i.V.m. Code PYO	● ○	● ○	● ○	● ○	● ○	● ○	162,75 0,00
U25	Illuminated door sill panels with "Mercedes-Benz" lettering 1_only in conjunction with code U62 i.V.m. Code P19 i.V.m. Code PYN/PYO	● ○ ○	● ○ ○	● ○ ○	● ○ ○	● ○ ○	● ○ ○	157,50 0,00 0,00
U26	AMG floor mats 1_included in delivery of code 950 2_not in conjunction with code 498, U12, U66	○	○	○	○	○	○	0,00
U27	Exterior door handles in chrome 1_not in conjunction with code 889	-	-	-	-	●	-	52,50
U29	Braking system with larger brake discs on the front axle 1_included in delivery of code PAD	○	○	○	○	○	○	0,00
U35	12 V socket in load area 1_only in conjunction with code 942	○	○	○	○	○	○	0,00
U37	Front fog lamps 1_not in conjunction with code 772, 950 i.V.m. Code P19	● ○	● ○	● ○	● ○	● ○	● ○	194,25 0,00
U40	Partition net 1_not in conjunction with code 830 2_available from 4th quarter 2019	●	●	●	●	●	●	157,50
U41	Water separator and lubrication package 1_only in conjunction with code 927 2_for certain countries only	○	○	○	○	-	-	0,00

1/8/2019

## Price list for the GLB

Valid from 13.08.2019 - MY 800

\* only South Korea

\*\* only USA/Canada

● available at extra charge    ○ available at no extra charge    U annotations existing  
 S standard equipment    - not available

GLB					
247.610	GLB 180 d	247.612	GLB 200 d	247.613	4MATIC
247.615	MATIC	247.687	GLB 200	247.647	GLB 250 4MATIC

Code	Designation	247.610	247.612	247.613	247.615	247.687	247.647	LLP
U50	<b>Omission of heat-insulating dark-tinted glass</b> 1_only in conjunction with code P27, P59 or 950 2_not in conjunction with code P55 or P60 3_for certain countries only	○	○	○	○	○	○	0,00
U55	<b>Multi-link axle</b>	S	S	S	S	S	S	0,00
U60	<b>Pedestrian protection</b> 1_for certain countries only	○	○	○	○	○	○	0,00
U66	<b>Floormats special model</b> 1_included in delivery of code P19 2_not in conjunction with code U12, U26	○	○	○	○	○	○	0,00
U67	<b>230 V socket in the rear</b> 1_not in conjunction with code U80, 460, 494, 498, 830, 835	●	●	●	●	●	●	120,75
U79	<b>BlueTEC diesel emission control system including AdBlue® reservoir</b> 1_not in conjunction with code 926	○	○	○	○	-	-	0,00
U80	<b>115 V socket</b> 1_only in conjunction with code 460, 494, 737L 2_not in conjunction with code U67	●	●	●	●	●	●	120,75