

## 19/3/2019 Optional extras for the GLA

SR 15.04.2018 ÄJ (800) (Package 1)

SR 13.05.2019 ÄJ (800) (Package 2)

GLA

● available at extra charge    ○ available at no extra charge    ⓘ annotations existing  
S standard equipment    - not available -    BM 156.945 nur Indien (RL) or Korea (LL)

Code	Designation	156.908	156.902	156.903	156.905	156.942	156.943	156.944	156.946	156.952	156.945	156.947	LLP
DB1	<b>Progressive Plus Auto package</b> National Package Included: 429-P49-P59-218-14U- 191U/589U/149U/696U/775U/787U/890U/990U/667U						ⓘ						1888,00
DB2	<b>Progressive Plus package</b> National Package Included: P49-P59-218-14U- 175U/191U/589U/149U/696U/761U/787U/890U/895U/990U/667U						ⓘ						1149,00
DB3	<b>Offroad Auto package</b> National Package Included: 429-P27-P49-218-30P-14U-400-482- 175U/191U/589U/149U/696U/761U/787U/890U/895U/990U/667U						ⓘ						1882,00
DB4	<b>Offroad package</b> National Package Included: P27-P49-218-30P-14U-400-482- 175U/191U/589U/149U/696U/761U/787U/890U/895U/990U						ⓘ						1142,00
DB5	<b>Sport package</b> National Package Included: 950-218-14U-P49-857						ⓘ						2760,00
DB6	<b>White Art Plus</b> National Package Included: PEK-950-P49-P55-218-429-632						ⓘ						6144,00
DC1	<b>Advanced Plus Package</b> National Package Included: 429-P49-P59-218-14U-632 - 191U/589U/149U/696U/775U/787U/890U/990U/667U					●	●						3166,00 2647,00

## 19/3/2019 Optional extras for the GLA

SR 15.04.2018 ÄJ (800) (Package 1)

SR 13.05.2019 ÄJ (800) (Package 2)

GLA

● available at extra charge    ○ available at no extra charge    ⓘ annotations existing  
S standard equipment    - not available -    BM 156.945 nur Indien (RL) or Korea (LL)

Code	Designation	156.908	156.902	156.903	156.905	156.942	156.943	156.944	156.946	156.952	156.945	156.947	LLP
DC2	<b>Advanced Package</b> National Package Included: P49-P59-218-14U-632 - 191U/589U/149U/696U/775U/787U/890U/990U/667U						●						1750,00
DC3	<b>Entry Package</b> National Package Included: 218-14U - 191U/589U/149U/696U/775U/787U/890U/990U/667U					●							490,00
L	Left-hand drive					○	○	○	○	○	○	○	0,00
R	Right-hand drive	↓	↓	↓	↓	●	●	●	●	↓	●	●	1113,00
000U	paintwork not yet finalised only in conjunction with code Z98	↓	↓	↓	↓	○	○	○	○	↓	○	○	0,00
149U	polar white	↓	↓	↓	↓	○	○	○	○	↓	○	○	0,00
191U	cosmos black metallic	↓	↓	↓	↓	●	●	●	●	↓	●	●	619,50
589U	jupiter red	↓	↓	↓	↓	○	○	○	○	↓	○	○	0,00
662U	designo mountain grey magno	↓	↓	↓	↓	●	●	●	●	↓	●	●	1837,50
667U	denim blue metallic	↓	↓	↓	↓	●	●	●	●	↓	●	●	619,50
696U	night black	↓	↓	↓	↓	○	○	○	○	↓	○	○	0,00
775U	iridium silver metallic	↓	↓	↓	↓	●	●	●	●	↓	●	●	619,50
787U	mountain grey metallic	↓	↓	↓	↓	●	●	●	●	↓	●	●	619,50
896U	brilliant blue metallic certain countries only	↓	↓	↓	↓	-	●	-	●	-	-	●	619,50
992U	selenite grey metallic certain countries only	↓	↓	↓	↓	●	●	●	●	-	●	●	619,50
996U	designo hyacinth red metallic certain countries only	↓	↓	↓	↓	●	●	●	●	-	●	●	1837,50
021A	Coari fabric black certain countries only not in conjunction with code 950, P27, P34, P59	↓	↓	↓	↓	○	○	○	○	↓	○	○	0,00
105A	ARTICO man-made leather sahara beige not in conjunction with code P34 or 950 only in conjunction with code P27 or P59 only in conjunction with code U59 in conjunction with Code P27 oder P59	↓	↓	↓	↓	●	●	●	●	↓	●	●	273,00
111A	ARTICO man-made leather black not in conjunction with code P34 or 950 only in conjunction with code U59 in conj. W. Code P27 oder P59	↓	↓	↓	↓	●	●	●	●	↓	●	●	136,50
118A	ARTICO man-made leather crystal grey not in conjunction with code P34 or 950 only in conjunction with code U59 in conj. W. Code P27 oder P59	↓	↓	↓	↓	●	●	●	●	↓	●	●	273,00
151A	ARTICO man-made leather sports seat black only in conjunction with Code PEX and U59	↓	↓	↓	↓	○	○	○	○	↓	○	○	0,00
161A	black ARTICO man-made leather certain countries only only in conjunction with code P59; not in conjunction with U10	↓	↓	↓	↓	-	●	●	●	↓	●	●	136,50
165A	almond beige / black ARTICO man-made leather certain countries only only in conjunction with code P59; not in conjunction with U10	↓	↓	↓	↓	-	●	●	●	↓	●	●	136,50

## 19/3/2019 Optional extras for the GLA

SR 15.04.2018 AJ (800) (Package 1)

SR 13.05.2019 AJ (800) (Package 2)

GLA

● available at extra charge    ○ available at no extra charge    ⓘ annotations existing  
S standard equipment    - not available -    BM 156.945 nur Indien (RL) or Korea (LL)

Code	Designation	156.908	156.902	156.903	156.905	156.942	156.943	156.944	156.946	156.952	156.945	156.947	LLP
175A	<b>Kunstleder - beige / schwarz</b> certain countries only not in conjunction with code U10 only in conjunction with code P59	-	-	-	-	-	●	-	-	-	-	●	136,50
378A	<b>ARTICO man-made leather / Maringá fabric crystal grey with white seams</b> certain countries only not in conjunction with code P34 only in conjunction with code P59, U59	-	-	-	-	○	○	○	○	-	○	○	0,00
381A	<b>ARTICO man-made leather / Maringá fabric black with white seams</b> certain countries only not in conjunction with code P34 only in conjunction with code P59, U59	-	-	-	-	○	○	○	○	-	○	○	0,00
411	<b>6-speed manual transmission</b> not in conjunction with code 239 not valid	●	-	-	-	S	S	○	-	-	-	-	0,00
429	<b>7G-DCT - dual clutch automatic transmission</b> AMG SPEEDSHIFT DCT 7-speed sports transmission not in conjunction with code U64 Standard Certain countries only	-	S	S	S	-	●	●	○	S	S	S	0,00 1848,00
621A	<b>ARTICO man-made leather / Macápá fabric black</b> certain countries only only in conjunction with code P27, U59	-	-	-	-	○	○	○	○	-	○	○	0,00
625A	<b>ARTICO man-made leather / Macápá fabric sahara beige / black</b> certain countries only only in conjunction with code P27, U59	-	-	-	-	○	○	○	○	-	○	○	0,00
631A	<b>ARTICO man-made leather / Macápá fabric yellow ochre / black</b> certain countries only only in conjunction with code P27, U59	-	-	-	-	○	○	○	○	-	○	○	0,00
641A	<b>ARTICO man-made leather / DINAMICA microfibre AMG black</b> only in conjunction with Code PEZ and U59	-	-	-	-	-	-	-	-	-	-	-	0,00
651A	<b>ARTICO man-made leather / DINAMICA microfibre black</b> not in conjunction with code P34 only in conjunction with code 950 and U59 Standard	-	-	-	-	○	○	○	○	●	○	○	0,00
801A	<b>Leather black</b> only in conjunction with code P34 and U59 (in conjunction with Code 555 not with Code U59)	-	-	-	-	○	○	○	○	-	○	○	0,00
804A	<b>Leather nut brown</b> only in conjunction with code P34 and U59 (in conjunction with Code 555 not with Code U59) not in conjunction with code 739	-	-	-	-	○	○	○	○	-	○	○	0,00
811A	<b>perforated leather black RED CUT</b> only in conjunction with code P39 and only with 873 and (U22 or 555); not with Code P34	-	-	-	-	○	○	○	○	-	○	○	0,00
831A	<b>Leather upholstery black</b> only in conjunction with code P73	-	-	-	-	○	○	○	○	-	○	○	0,00

## 19/3/2019 Optional extras for the GLA

SR 15.04.2018 AJ (800) (Package 1)		GLA											
SR 13.05.2019 AJ (800) (Package 2)													
Code	Designation	156.908	156.902	156.903	156.905	156.942	156.943	156.944	156.946	156.952	156.945	156.947	LLP
855A	<b>Two-tone leather sahara beige / black</b> only in conjunction with code P34 and U59 (in conjunction with Code 555 not with Code U59)	-	-	-	-	o	o	o	o	-	o	o	0,00
22P	<b>Lane Tracking package</b> certain countries only only in conjunction with code 234, 476	-	-	-	-	•	•	•	•	-	•	•	819,00
30P	<b>Stowage Space package</b> only in conjunction with code 286, 932 and (939 or 682) (RHD); not in conjunction with code 555 only in conjunction with code 286, 939 and (932 or 682) (LHD); not in conjunction with code 555; certain countries only only in conjunction with code 555 but not in conjunction with code 286/932/939; certain countries only	-	-	-	-	•	•	•	•	-	•	•	157,50
430	<b>Off-road functions and presentation in MEDIA DISPLAY</b>	-	S	-	S	-	-	-	S	-	-	S	0,00
950	<b>AMG line</b> certain countries only not in conjunction with code P27/P59/P73/951 or U37 only in conjunction with code (651A/801A/804A/811A/855A), (459/482/486 or 485), (633/635/655/RV/RVJ or 04R) and (498/U26/U66 or P34) only in conjunction with code 280 or 277 and (725 or 720+P55), 772, B59, (H79/H73/H92/739 or (P34 and (H06/H14/H19) or U63	-	-	-	-	•	•	•	•	-	•	•	2331,00
951	<b>Sports package USA</b> only in conjunction with code 460+P59+(635/655/RV/RVJ)+772+(U12/P34); not in conjunction with 486/550/950/P27/U37  only in conjunction with code 494+P59+482+(635/655/RV/RVJ)+772+(U12/P34); not in conjunction with 486/550/950/P27/U37)	-	-	-	-	-	-	•	•	-	•	•	1615,95
B26	<b>AMG Aerodynamics package</b> only in conjunction with code P60 and U47 <b>i.v.m. Code PEZ</b>	-	-	-	-	-	-	-	-	-	-	-	1575,00
P17	<b>KEYLESS-GO Comfort-package</b> only in conjunction with Code 871, 889 and 890	-	-	-	-	•	•	•	•	-	•	•	966,00
P27	<b>Style</b> certain countries only not in conjunction with code 950/951/P59 only in conjunction with (105A/111A/118A/808/621A/625A/631A/801A/804A/811A/855A/831A), 280, 720 and (H54/H06/H14/H19/H73/H79 and P34/739 and P73/U63) and (R31/R48/01R/04R/08R/48R/65R/77R/82R/635/655/RV or RVJ)	-	-	-	-	•	•	•	•	-	•	•	441,00
P34	<b>Exclusive package</b>  not in conjunction with code P39 or PEZ not in conjunction with code PEX/P39/P73/U12 or U26 only in conjunction with code 873 and (889 or 893) and U09 and (H06/H14/H19/H73/H79/H94) and (U22/555) and (498/U26) and (801A/804A/855A) only in conjunction with code 280 and (H06/H14/H19/H73/H79/H54+P27 or (739/H81) and P59 or U63) and U22 and (801A/804A/855A) and (51U/55U but not with 830 or 58U)  in conjunction with Code 950 in conjunction with Code P27 in conjunction with Code P59	-	-	-	-	•	•	•	•	-	•	•	1380,75 2399,25
		-	-	-	-	•	•	•	•	-	•	•	1380,75 1926,75 1884,75

• available at extra charge    o available at no extra charge    U annotations existing  
S standard equipment    - not available -    BM 156.945 nur Indien (RL) or Korea (LL)

## 19/3/2019 Optional extras for the GLA

SR 15.04.2018 AJ (800) (Package 1)

SR 13.05.2019 AJ (800) (Package 2)

GLA

● available at extra charge    ○ available at no extra charge    ⓘ annotations existing  
S standard equipment    - not available -    BM 156.945 nur Indien (RL) or Korea (LL)

Code	Designation	156.908	156.902	156.903	156.905	156.942	156.943	156.944	156.946	156.952	156.945	156.947	LLP
P39	<b>AMG Exclusive package</b> not in conjunction with code PEZ/P34 or (P73 (but not with AMG-Type))  only in conjunction with code 811A and (889/893) and (H19/H73/H79/H90/H92) and U09 and 498/U26) only in conjunction with code 811A, 889 or 893, (H19 and 460/494) or H73/H79 or H92, U09 and (498/U26) only in conjunction with code 950 and 811A and (889/893) and (H73/H79/H92/U63) and U09	-	-	-	-	●	●	●	●	●	●	●	1380,75
P47	<b>Parking Package with 360-degree camera</b> certain countries only not conjunction with code B28 only in conjunction with 235,501 and (P49 or (494,249 and 500)	-	-	-	-	●	●	●	●	-	●	●	1312,50
P49	<b>Mirror package</b> certain countries only comprising: code 249, 500 i.V.m. Code P47	-	-	-	-	●	●	●	●	-	●	●	325,50
		-	-	-	-	○	○	○	○	-	○	○	0,00
P54	<b>Anti-Theft Protection package</b> certain countries only  comprising: code 551, 882, 817 (cert. countries only), 552 (cert.countries only)	-	-	-	-	●	●	●	●	-	●	●	430,50
P55	<b>Night package</b> certain countries only not in conjunction with code P60 only in conjunction with code 950, P27 or P59 and 720, (840 (certain countries only)), (01R04R/48R/65R/655 or RVI; not in conjunction with code U63 only in conjunction with code P59,720,840, and 01R/655 or RVI in conjunction with Code 950 i.V.m. Code P59 i.V.m. Code PEX	-	-	-	-	●	●	●	●	-	●	●	787,50
		-	-	-	-	●	●	●	●	-	●	●	840,00
		-	-	-	-	○	○	○	○	-	○	○	367,50
		-	-	-	-	○	○	○	○	-	○	○	0,00
P59	<b>Urban</b> not in conjunction with code 950, P27 only in conjunction with code 280, R31/R48/01R/04R/48R/77R/65R/82R/635/655/RVI or RVJ and (725 or 720+P55), 105A/111A/118A/161A/165A/168A/175A/381A,378A,801A,804A,811A/831A or 855A and 739/H73/H79/H81/ or (H06/H14/H19 and P34/P73) or U63	-	-	-	-	●	●	●	●	-	●	●	1071,00
P60	<b>AMG Night package</b> only in conjunction with code 840 (cert. countries without 840) i.V.m. Code PEZ	-	-	-	-	-	-	-	-	-	-	-	703,50
		-	-	-	-	-	-	-	-	-	-	-	0,00
P71	<b>AMG DYNAMIC PLUS package</b> consisting of code 281, 459 and 471 (certain countries only) in conjunction with 460/494 only in conjunction with 459, 471, 251 i.V.m. Code PEZ	-	-	-	-	-	-	-	-	-	-	-	2310,00
		-	-	-	-	-	-	-	-	-	-	-	1732,50
P73	<b>Exclusive Comfort package</b> certain countries only  consisting of code 280, 873, (739/H06/H14/H19/H73/H54 and P27/(H79/H81) and P59/U63), U09, U22, 831A and (51U/58U) not in conjunction with code 950/U12/U26/P34 or P39	-	-	-	-	●	●	●	●	-	●	●	2399,25

## 19/3/2019 Optional extras for the GLA

SR 15.04.2018 AJ (800) (Package 1)		GLA											
SR 13.05.2019 AJ (800) (Package 2)													
		156.908	156.902	156.903	156.905	156.942	156.943	156.944	156.946	156.952	156.945	156.947	
		GLA 200 d Sport Utility Vehicle	GLA 200 d 4MATIC Sport Utility Vehicle	GLA 220 d Sport Utility Vehicle	GLA 220 d 4MATIC Sport Utility Vehicle	GLA 180 Sport Utility Vehicle	GLA 200 Sport Utility Vehicle	GLA 250 Sport Utility Vehicle	GLA 250 4MATIC Sport Utility Vehicle	Mercedes-AMG GLA 45 4MATIC Sport Utility Vehicle	GLA 200 Sport Utility Vehicle RL	GLA 220 4MATIC Sport Utility Vehicle	
Code	Designation												LLP
	only in conjunction with code (889 or 893)												
	i.V.m. Code P27												1926,75
	i.V.m. Code P59												1884,75
PAH	AMG DINAMICA Cockpit package only in conjunction with code 651A or 811A, L6G and H92 i.V.m. Code P71												892,50
PEX	Night Edition certain countries only not in conjunction with code (830/951/P34) only in conjunction with code P59 and 151A, H74 and (631/632) and 772 and (633/RVH/RVI/RVJ) and U09, U13 and U66 i.V.m. Code P55 ohne Code P55+633												2467,50
PEZ	AMG Night Edition not in conjunction with (P34/P39) only in conjunction with code P60, B26 and- (149U/191U/662U/696U/775U/787U) and 641A, H73, 555 and (E74/U03) and- L6G, RVX and U26												3045,00
PYR	Europe Night Edition certain countries only												1968,75
PYS	Europe Night Edition Black certain countries only												6720,00
U59	Seat comfort package  not in conjunction with code 555 Standard i.V.m. Code U63/950 i.V.m. P27/P34/P39/P59/P73 i.V.m. Code P27/P34/P39/P59/P73												0,00
U62	Light and sight package certain countries only only in conjunction with Code 345, (543 (but not cert. countries)) and (U25 (but not cert. Countries))												162,75
U63	Driving school package certain countries only  not in conjunction with code 840/P55/739/H06/H14/H19/H54/H73/H79 or H81  only in conjunction with code U59, U62, 931 only LHD in conjunction with Code U64												0,00
U90	Low-Line package China certain countries only												0,00
U92	High-Line-package China certain countries only												0,00
494	USA specification												0,00
498	Japan specification												0,00
709	SKD vehicles for India												0,00
712	CKD delivery scope India only 829L												0,00
713	Omission of SKD parts Brazil												0,00
714	Omission of CKD parts Brazil												0,00

● available at extra charge ○ available at no extra charge U annotations existing  
S standard equipment - not available - BM 156.945 nur Indien (RL) or Korea (LL)

19/3/2019

Optional extras for the GLA

SR 15.04.2018 ÄJ (800) (Package 1)

SR 13.05.2019 ÄJ (800) (Package 2)

## 19/3/2019 Optional extras for the GLA

SR 15.04.2018 AJ (800) (Package 1)

SR 13.05.2019 AJ (800) (Package 2)

GLA

● available at extra charge    ○ available at no extra charge    ⓘ annotations existing  
S standard equipment    - not available -    BM 156.945 nur Indien (RL) or Korea (LL)

Code	Designation	156.908	156.902	156.903	156.905	156.942	156.943	156.944	156.946	156.952	156.945	156.947	LLP
16B	Owner's Manual and Service Booklet - Polish	+	+	+	+	○	○	○	○	+	○	○	0,00
16U	Apple CarPlay only in conjunction with code 14U	+	+	+	+	○	○	○	○	+	○	○	0,00
17B	Owner's Manual and Service Booklet - Czech	+	+	+	+	○	○	○	○	+	○	○	0,00
17U	Android Auto only in conjunction with code 14U and (505/520/522/531/532)	+	+	+	+	○	○	○	○	+	○	○	0,00
18B	Owner's Manual and Service Booklet - Engl. S. Am.	+	+	+	+	○	○	○	○	+	○	○	0,00
18U	Baidu Carlife certain countries only and only in conjunction with code 14U and (520/522)	-	-	-	-	-	○	-	○	+	-	○	0,00
19B	Owner's Manual and Service Booklet - French S. Am.	+	+	+	+	○	○	○	○	+	○	○	0,00
1R0	winter (M+S) wheel and tyre assembly x 4 not in conjunction with code R66 only Germany	-	-	-	-	●	●	●	●	-	●	●	997,50
1R7	winter (M+S) wheel and tyre assembly x 4 not in conjunction with code R66 only Germany	-	-	-	-	●	●	●	●	-	●	●	1480,50
20B	Owner's Manual and Service Booklet - Spanish S. Am.	+	+	+	+	○	○	○	○	+	○	○	0,00
210	Literature in Swedish	+	+	+	+	○	○	○	○	+	○	○	0,00
213	Sports Direct-Steer system certain countries only only in conjunction with code 486/459	-	-	-	-	○	○	○	○	-	○	○	0,00
218	Reversing camera not in conjunction with code 501	+	+	+	+	●	●	●	●	+	●	●	351,75
21B	Owner's Manual and Service Booklet - Portug. S. Am.	+	+	+	+	○	○	○	○	+	○	○	0,00
228	Auxiliary heater certain countries only certain countries only in conjunction with code B24 only LHD i.V.m. Code 362	+	+	+	+	●	●	●	●	-	●	●	1312,50
22B	Owner's Manual and Service Booklet - Japanese	+	+	+	+	○	○	○	○	+	○	○	0,00
232	Garage door opener (frequency range 284-390 MHz) certain countries only only in conjunction with code U62, P49 (cert.countries only)	+	+	+	+	●	●	●	●	+	●	●	236,25
234	Blind Spot Assist certain countries only in conjunction with Code 22P	+	+	+	+	●	●	●	●	+	●	●	472,50
235	Active Parking Assist i.V.m. Code P47	+	+	+	+	○	○	○	○	+	○	○	0,00
239	Active Distance Assist DISTRONIC certain countries only not in conjunction with code 258 or 440 only in conjunction with code 429	+	+	+	+	●	●	●	●	+	●	●	708,75
23B	Owner's Manual and Service Booklet - simpl. Chinese	+	+	+	+	○	○	○	○	+	○	○	0,00
241	Front seat left, elect.adjust.w.mem. switch only in conjunction with code 275 right-hand-drive vehicles only i.V.m. Code 555 i.V.m. Code PEZ	+	+	+	+	●	●	●	●	+	●	●	903,00
242	Front pass. seat, electrically adj. with memory function LHD version not in conjunction with code 842	+	+	+	+	○	○	○	○	+	○	○	0,00
		+	+	+	+	○	○	○	○	+	○	○	299,25
		+	+	+	+	○	○	○	○	+	○	○	493,50
		+	+	+	+	○	○	○	○	+	○	○	0,00
		+	+	+	+	○	○	○	○	+	○	○	299,25

## 19/3/2019 Optional extras for the GLA

SR 15.04.2018 AJ (800) (Package 1)

SR 13.05.2019 AJ (800) (Package 2)

● available at extra charge    ○ available at no extra charge    ⓘ annotations existing  
S standard equipment    - not available -    BM 156.945 nur Indien (RL) or Korea (LL)

Code	Designation	156.908	156.902	156.903	156.905	156.942	156.943	156.944	156.946	156.952	156.945	156.947	LLP
	only in conjunction with code 275 in conjunction with Code 555	+	+	+	+	●	●	●	●	+	●	●	493,50
	i.V.m. Code PEZ	-	-	-	-	-	-	-	-	+	-	-	0,00
245	Compass certain countries only not in conjunction with code 531 only in conjunction with code U62 and P49 (certain countries only)	-	-	-	-	-	-	●	●	+	-	-	110,25
249	interior mirror and driver's exterior mirror automatically dimming certain countries only only in conjunction with code P49	+	+	+	+	○	○	○	○	+	○	○	0,00
24B	Owner's Manual and Service Booklet - trad. Chinese	+	+	+	+	○	○	○	○	+	○	○	0,00
250	AMG Driver's package certain countries only	-	-	-	-	-	-	-	-	+	-	-	1470,00
251	Increase in top speed, USA certain countries only	-	-	-	-	-	-	-	-	+	-	-	1470,00
258	Active Brake Assist certain countries only not in conjunction with code 239	S	S	S	S	S	S	S	S	S	S	S	0,00
25B	Owner's Manual and Service Booklet - Korean	+	+	+	+	○	○	○	○	+	○	○	0,00
260	Deletion of model plate on boot lid certain countries only	+	+	+	+	○	○	○	○	+	○	○	0,00
261	Omission of badge not in conjunction with code U13 not only in conjunction with code 830 not valid	+	+	+	+	ⓘ	ⓘ	ⓘ	ⓘ	+	ⓘ	ⓘ	0,00
263	Number plate mounting for Asia / Mexico	+	+	+	+	○	○	○	○	+	○	○	0,00
264	Number plate mounting for America	+	+	+	+	○	○	○	○	+	○	○	0,00
26B	Owner's Manual and Service Booklet - Chinese Taiwan	+	+	+	+	○	○	○	○	+	○	○	0,00
26U	Preinstallation for engine remote start certain countries only only in conjunction with code 362 and 429 i.V.m. S-Code PZG	-	-	-	-	-	●	●	●	+	-	●	105,00
275	Driver's seat, electrically adjustable with memory function in conjunction with code 555 only in conjunction with code 644A/ 651A/681A/691 or 801A/804A/811A or 855A only in conjunction with code U22, U59 (not conjunction with 555)	+	+	+	+	●	●	●	●	+	●	●	362,25
	i.V.m. Code 555	-	-	-	-	+	+	+	+	+	-	+	551,25
	i.V.m. Code PEZ	-	-	-	-	-	-	-	-	+	-	-	0,00
280	Leather multifunction steering wheel multifunction sports steering wheel leather, flattened bottom section, black DINAMICA in grip area (i.c.w. PEK) multifunction sports steering wheel, leather (i.c.w. P39/950)	+	+	+	+	●	●	●	●	-	●	●	183,75
	i.V.m. P27/P34/P39/P59/P73/950	-	-	-	-	○	○	○	○	-	○	○	0,00
281	AMG Performance steering wheel AMG Performance steering wheel	-	-	-	-	-	-	-	-	+	-	-	441,00
	i.V.m. Code P71	-	-	-	-	-	-	-	-	+	-	-	0,00
286	Luggage net on driver's and front pass. backrest certain countries only not in conjunction with code 555 only in conjunction with code 30P	+	+	+	+	○	○	○	○	+	○	○	0,00
290	Windowbags	S	S	S	S	S	S	S	S	S	S	S	0,00
293	Sidebags in rear	+	+	+	+	●	●	ⓘ	●	+	●	●	393,75

SR 15.04.2018 AJ (800) (Package 1)		GLA											LLP
SR 13.05.2019 AJ (800) (Package 2)		156.908	156.902	156.903	156.905	156.942	156.943	156.944	156.946	156.952	156.945	156.947	
Code	Designation	GLA 200 d Sport Utility Vehicle	GLA 200 d 4MATIC Sport Utility Vehicle	GLA 220 d Sport Utility Vehicle	GLA 220 d 4MATIC Sport Utility Vehicle	GLA 180 Sport Utility Vehicle	GLA 200 Sport Utility Vehicle	GLA 250 Sport Utility Vehicle	GLA 250 4MATIC Sport Utility Vehicle	Mercedes-AMG GLA 45 4MATIC Sport Utility Vehicle	GLA 200 Sport Utility Vehicle RL	GLA 220 4MATIC Sport Utility Vehicle	
	● available at extra charge    ○ available at no extra charge    U annotations existing S standard equipment    - not available - BM 156.945 nur Indien (RL) or Korea (LL)												
	certain countries only	*	*	*	*	○	○	★	○	*	S	○	
294	Kneebag	*	*	*	*	○	○	○	○	*	S	○	
	certain countries only	*	*	*	*	○	○	○	○	*	S	○	
299	PRE-SAFE® system	*	*	*	*	●	●	●	●	*	●	●	
	certain countries only	*	*	*	*	●	●	●	●	*	●	●	
2U0	car2go pre-installation	*	*	*	*	●	●	●	●	*	●	●	
	not in conjunction with code 865	-	-	-	-	-	-	-	-	-	-	-	
301	Front and rear ashtray inserts in the stowage compartments as well as cigarette lighter in the front	*	*	*	*	●	●	●	●	*	●	●	
	certain countries only	*	*	*	*	●	●	●	●	*	●	●	
309	Cup holder	*	*	*	*	○	○	○	○	*	○	○	
	only in conjunction with code 429	-	-	-	-	-	-	●	●	*	●	●	
30B	Owner's Manual and Service Booklet - Slovenian	*	*	*	*	○	○	○	○	*	○	○	
310	Cup holder	*	*	*	*	-	-	●	●	*	●	●	
	certain countries only	-	-	-	-	-	-	●	●	*	●	●	
31B	Owner's Manual and Service Booklet - Hungarian	*	*	*	*	○	○	○	○	*	○	○	
32B	Owner's Manual and Service Booklet - Bulgarian	*	*	*	*	○	○	○	○	*	○	○	
33B	Owner's Manual and Service Booklet - Romanian	*	*	*	*	○	○	○	○	*	○	○	
345	Windscreen wiper with rain sensor	*	*	*	*	○	○	○	○	*	○	○	
	only in conjunction with code U62 and cert. countries only	-	-	-	-	-	-	-	-	-	-	-	
34B	Owner's Manual and Service Booklet - Croatian	*	*	*	*	○	○	○	○	*	○	○	
351	Mercedes-Benz emergency call system	*	*	*	*	○	○	○	○	*	○	○	
	certain countries only	*	*	*	*	○	○	○	○	*	○	○	
	only in conjunction with code 362	-	-	-	-	-	-	-	-	-	-	-	
357	Garmin® MAP PILOT	*	*	*	*	●	●	●	●	*	●	●	
	certain countries only	*	*	*	*	●	●	●	●	*	●	●	
	only in conjunction with code 522	-	-	-	-	-	-	-	-	-	-	-	
35B	Owner's Manual and Service Booklet - Latvian	*	*	*	*	○	○	○	○	*	○	○	
362	Communications module (LTE)	*	*	*	*	○	○	○	○	*	○	○	
	certain countries only	-	-	-	-	-	-	-	-	-	-	-	
367	Preinstallation for Live Traffic Information	*	*	*	*	○	○	○	○	*	○	○	
	certain countries only	*	*	*	*	○	○	○	○	*	○	○	
	in cert. Countries only in conjunction with code 362 and 531	-	-	-	-	-	-	-	-	-	-	-	
	only in conjunction with code 362 (522 oder 531)	-	-	-	-	-	-	-	-	-	-	-	
36B	Owner's Manual and Service Booklet - Lithuanian	*	*	*	*	○	○	○	○	*	○	○	
37B	Owner's Manual and Service Booklet - Slovakian	*	*	*	*	○	○	○	○	*	○	○	
38B	Owner's Manual and Service Booklet - Estonian	*	*	*	*	○	○	○	○	*	○	○	
39B	Owner's Manual and Service Booklet - Serbian	*	*	*	*	○	○	○	○	*	○	○	
3R9	complete winter (M+S) wheel-and-tyre assembly x 4	*	*	*	*	●	●	●	●	*	●	●	
	only Germany	-	-	-	-	-	-	-	-	-	-	-	
	only in conjunction with code R66	-	-	-	-	-	-	-	-	-	-	-	
400	Rear armrest	*	*	*	*	●	●	●	●	*	●	●	
40B	Owner's Manual and Service Booklet - ukrainian	*	*	*	*	○	○	○	○	*	○	○	
413	Panoramic sliding sunroof	*	*	*	*	●	●	●	●	*	●	●	
	not in conjunction with code U40	-	-	-	-	-	-	-	-	-	-	-	
	only in conjunction with code 720 or 725	-	-	-	-	-	-	-	-	-	-	-	

## 19/3/2019 Optional extras for the GLA

SR 15.04.2018 AJ (800) (Package 1)

SR 13.05.2019 AJ (800) (Package 2)

GLA

● available at extra charge    ○ available at no extra charge    ⓘ annotations existing  
S standard equipment    - not available -    BM 156.945 nur Indien (RL) or Korea (LL)

Code	Designation	156.908	156.902	156.903	156.905	156.942	156.943	156.944	156.946	156.952	156.945	156.947	LLP
428	Steering wheel shift paddles only in conjunction with code 429	+	S	S	S	○	S	○	S	-	S	S	0,00
440	Cruise control not in conjunction with code 239	+	S	S	S	○	○	S	S	S	S	S	0,00
442	Multifunction steering wheel	S	S	S	S	S	S	S	S	-	S	S	0,00
459	Suspension with Adaptive Damping system AMG RIDE CONTROL sports suspension certain countries only not in conjunction with code 482, 485, 486, or 550 only in conjunction with code 213 and B59 only in conjunction with code B59; not in conjunction with code 23 or 486  i.V.m. Code 950 i.V.m. Code P71	+	+	+	+	●	●	●	●	+	●	●	1092,00
460	Canada specification	-	-	-	-	-	-	○	○	+	-	-	0,00
461	Instrument cluster with display in miles and English lettering	+	+	+	+	○	○	○	○	+	○	○	0,00
462	Instrument cluster with Asian characters only certain countries	+	+	+	+	○	○	○	○	+	○	○	0,00
471	AMG front axle differential lock certain countries only only in conjunction with code P71 and 475	-	-	-	-	-	-	-	-	+	-	-	0,00
474	Diesel particulate filter certain countries only	S	S	S	S	-	-	-	-	-	-	-	0,00
475	Tyre pressure monitoring system certain countries only Standard Equipment certain countries only i.V.m. S-Code 6P5	+	+	+	+	●	●	●	●	+	●	●	320,25
476	Lane Keeping Assist certain countries only not in conjunction with code 234 only in conjunction with code 280 or 277 in conjunction with Code 22P	+	+	+	+	○	○	○	○	+	○	○	472,50
477	Tyre pressure loss warning system certain countries only	+	+	+	+	○	○	○	○	+	○	○	0,00
482	Off-road comfort suspension not in conjunction with code 486/459 only in conjunction with code 924 or 926	+	+	+	+	●	●	●	●	-	●	●	283,50
485	Comfort suspension certain countries only	S	S	S	S	S	S	S	S	-	S	S	0,00
486	Suspension lowered by 15 mm certain countries only not in conjunction with code 459 only in conjunction with Code 213 and 950	+	+	+	+	○	○	○	○	S	○	○	0,00
48R	48.3 cm (19-inch) 5-spoke light-alloy wheels in conjunction with code 645 not with R66 certain countries only in conjunction with code R01 or R02 only with R66 i.V.m. Code P55 i.V.m. Code P59	+	+	+	+	●	●	●	●	-	●	●	955,50
500	Electrically folding exterior mirrors certain countries only only in conjunction with code P49 (certain countries only)	+	+	+	+	○	○	○	○	+	○	○	0,00

[illegible]

## 19/3/2019 Optional extras for the GLA

SR 15.04.2018 AJ (800) (Package 1)

SR 13.05.2019 AJ (800) (Package 2)

GLA

● available at extra charge    ○ available at no extra charge    ⓘ annotations existing  
S standard equipment    - not available -    BM 156.945 nur Indien (RL) or Korea (LL)

Code	Designation	156.908	156.902	156.903	156.905	156.942	156.943	156.944	156.946	156.952	156.945	156.947	LLP
55U	<b>Roof liner beige fabric</b> not in conjunction with code P73 only in conjunction with code P27 and (105A/625A) or P34 with 855A or P59 with 105A/165A/175A	+	+	+	+	○	○	○	○	-	○	○	0,00
580	<b>Air conditioning system</b> certain countries only	S	S	S	S	S	S	S	S	S	S	S	0,00
581	<b>THERMOTRONIC automatic climate control</b> certain countries only only in conjunction with code P27/P34/P59/P73 or 950	+	+	+	+	●	●	●	●	+	●	●	535,50
58U	<b>Roof liner in crystal grey fabric</b> in conjunction with P34 only in conjunction with code 801A oder P73 not in conjunction with code P27 with code 105A/604A/625A or P59 not with code 105A/165A/175A or 950/P34 or P73	+	+	+	+	○	○	○	○	+	○	○	0,00
598	<b>Petrol particulate filter</b> only in conjunction with code 927	-	-	-	-	○	○	○	○	+	-	○	0,00
608	<b>Adaptive Highbeam Assist</b> only in conjunction with code 631 or 632	+	+	+	+	●	●	●	●	+	●	●	105,00
613	<b>Headlamps for RHD vehicles</b> certain countries only part of standard specification for LHD countries	+	+	+	+	○	○	○	○	+	○	○	0,00
620	<b>Halogen headlamps</b>	+	+	+	+	○	○	○	○	+	○	○	0,00
623	<b>Gulf States specification</b>	-	-	-	-	-	○	-	○	+	-	○	0,00
625	<b>Australia specification</b>	+	+	+	+	○	○	-	○	+	-	○	0,00
631	<b>LED High Performance headlamp (RHD)</b>  only for certain countries Standard (cert. Countries only) i.V.m. Code PEX	+	+	+	+	●	●	●	●	+	●	●	0,00 918,75
632	<b>LED High Performance headlamp</b>  only for certain countries Standard (cert. Countries only) i.V.m. Code PEX	+	+	+	+	●	●	●	●	+	●	●	0,00 918,75
633	<b>45.7 cm (18-inch) AMG 5-spoke light-alloy wheels</b> certain countries only in conjunction with code 645 not in conjunction with R66 not in conjunction with code P55 only in conjunction with Code 950 or PEX	+	+	+	+	○	○	○	○	+	○	○	0,00
634	<b>Omission of first-aid kit</b> certain countries only not in conjunction with code 820	+	+	+	+	○	○	○	○	+	○	○	0,00
635	<b>48.3 cm (19-inch) AMG 5-spoke light-alloy wheels</b> certain countries only in conjunction with code 645 not in conjunction with R66 in conjunction with code R01/R02 only in conjunction with code R66 not in conjunction with code P55 in conjunction with Code 950 in conjunction with Code P59	+	+	+	+	●	●	●	●	+	●	●	1365,00    472,50 892,50
636	<b>Omission of warning triangle</b> not in conjunction with code 820	+	+	+	+	○	○	○	○	+	○	○	0,00
645	<b>M+S winter tyres, set of 4</b> not in conjunction with code 460, 494, 498, 625, or 830	+	+	+	+	●	●	●	●	+	●	●	115,50

## 19/3/2019 Optional extras for the GLA

SR 15.04.2018 ÄJ (800) (Package 1)

SR 13.05.2019 ÄJ (800) (Package 2)

GLA

● available at extra charge ○ available at no extra charge ⓘ annotations existing  
S standard equipment - not available - BM 156.945 nur Indien (RL) or Korea (LL)

Code	Designation	156.908	156.902	156.903	156.905	156.942	156.943	156.944	156.946	156.952	156.945	156.947	LLP
	only in conjunction with code R00/R48/08R/633/R31/01R/82R/48R/65R/77R/635/655/RVI/RVJ/RUG or RUH but not with code R66 or 04R with code R66	-	-	-	-	-	-	-	-	-	-	-	
651	Winter complete wheels fitted only in conjunction with code 1R0/1R7/2R4/3R9/4R6/5R1 er-8R4	-	-	-	-	○	○	○	○	-	○	○	0,00
652	Summer complete tyres fitted only in conjunction with code 1R0/1R7/2R4/3R9/4R6/5R1 er-8R4	-	-	-	-	○	○	○	○	-	○	○	0,00
655	48.3 cm (19-inch) AMG 5-spoke light-alloy wheels certain countries only in conjunction with code R01/R02 only in conjunction with code R66 in conj.with 950 and P55 in conjunction with Code 950 in conjunction with Code P55 in conjunction with Code P59	-	-	-	-	●	●	●	●	-	●	●	1365,00
		-	-	-	-	○	○	○	○	-	○	○	0,00
		-	-	-	-	●	●	●	●	-	●	●	472,50
		-	-	-	-	●	●	●	●	-	●	●	724,50
		-	-	-	-	●	●	●	●	-	●	●	892,50
65R	48.3 cm (19-inch) 5-twin-spoke light-alloy wheels in conjunction with code R01/R02 only in conjunction with code R66 not in conjunction with code 950, 951 in conjunction with Code P55 in conjunction with Code P59	-	-	-	-	●	●	●	●	-	●	●	955,50
		-	-	-	-	●	●	●	●	-	●	●	315,00
		-	-	-	-	●	●	●	●	-	●	●	483,00
666	Freight packaging without tie-down hooks certain countries only not in conjunction with code 820 in conjunction with Code 14P, 15P or 16P	-	-	-	-	●	●	●	●	-	●	●	0,00
		-	-	-	-	○	○	○	○	-	○	○	0,00
668	Prod. prot. f. freight pkgng with tie-down hooks certain countries only not in conjunction with code 820 in conjunction with Code 14P, 15P or 16P	-	-	-	-	●	●	●	●	-	●	●	26,25
		-	-	-	-	○	○	○	○	-	○	○	0,00
669	Collapsible spare wheel certain countries only; Standard certain countries only only in conjunction with code E76 and B12	-	-	-	-	-	-	-	-	-	-	-	0,00
682	Fire extinguisher certain countries only	-	-	-	-	●	●	●	●	-	●	●	0,00
687	Type plate with model year certain countries only Standard certain countries only	-	-	-	-	○	○	○	○	-	○	○	0,00
690	Pre-installation for the spare wheel certain countries only; Standard certain countries only only in conjunction with code E76 and B12	-	-	-	-	○	○	○	○	-	○	○	0,00
700	Produktionsstandort Fahrzeug China only 819L	-	-	-	-	-	○	-	○	-	-	○	0,00
70B	Fluorescent jacket for driver certain countries only not in conjunction with code 71B	-	-	-	-	●	●	●	●	-	●	●	5,25
71B	Fluorescent jackets for driver and passengers not in conjunction with code 70B or 830	-	-	-	-	●	●	●	●	-	●	●	26,25
720	Aluminium roof rails in high-gloss black in conjunction with code 950, P59 only in conjunction with code P55 only in conjunction with code P60	S	S	S	S	S	S	S	S	S	S	S	0,00
725	Aluminium roof rails not in conjunction with code P55 not in conjunction with code P60 only in conjunction with code 950, P59	P	P	P	P	U	U	U	U	S	U	U	0,00
		-	-	-	-	★	★	★	★	-	★	★	
739	aluminium trim with trapeze cut	-	-	-	-	○	○	○	○	-	○	○	0,00

## 19/3/2019 Optional extras for the GLA

SR 15.04.2018 AJ (800) (Package 1)

SR 13.05.2019 AJ (800) (Package 2)

GLA

● available at extra charge    ○ available at no extra charge    U annotations existing  
S standard equipment    - not available -    BM 156.945 nur Indien (RL) or Korea (LL)

Code	Designation	156.908	156.902	156.903	156.905	156.942	156.943	156.944	156.946	156.952	156.945	156.947	LLP
	certain countries only only in conjunction with code P59 oder P73 but not with code U63	-	-	-	-	-	-	-	-	-	-	-	
754	48.3 cm (19-inch) AMG 5-twin-spoke light-alloy wheels not in conjunction with code R66 only in conjunction with code R01	-	-	-	-	-	-	-	-	S	-	-	0,00
758	50.8 cm (20-inch) AMG 10-spoke light-alloy wheels not in conjunction with code R66 only in conjunction with code R01	-	-	-	-	-	-	-	-	!	-	-	630,00
762	Remote control unit	i	i	i	i	o	o	o	o	i	o	o	0,00
763	Key with Radio remote control with panic switch only in conjunction with Code 551 and certain countries only	i	i	i	i	o	o	o	o	i	o	o	0,00
772	AMG bodystyling not in conjunction with code U37 only in conjunction with code PEX/ 950 or 951	p	p	p	p	u	u	u	u	S	u	u	0,00
778	50.8 cm (20-inch) AMG 10-spoke light-alloy wheels not in conjunction with code R66 only in conjunction with code R01	-	-	-	-	-	-	-	-	!	-	-	997,50
77R	48.3 cm (19-inch) 5-twin-spoke light-alloy wheels certain countries only not in conjunction with code 460, 494, P55, 950 only in conjunction with code R01 and R66 in conjunction with Code P59	i	i	i	i	●	●	●	●	-	●	●	787,50
809	Technical modifications	i	i	i	i	o	o	o	o	i	o	o	0,00
810	Harman Kardon® Logic 7® surround sound system not in conjunction with code 520 only in conjunction with code 505/522/531/532	i	i	i	i	●	●	●	●	!	●	●	719,25
815	DVD player only in conjunction with code 531 or 532	i	i	i	i	o	o	o	o	i	o	o	0,00
818	CD player only in conjunction with code 505 or 522	i	i	i	i	o	o	o	o	i	o	o	0,00
820	Tourist vehicle certain countries only not in conjunction with code 634, 636, 666 or 668	i	i	i	i	o	o	o	o	-	o	o	0,00
821	Country code Brazil	-	-	-	-	-	o	o	o	i	-	-	0,00
822	South Africa specification	i	i	i	i	o	o	o	o	i	o	o	0,00
823	Indicator plate fixing Switzerland	i	i	i	i	o	o	o	o	i	o	o	0,00
824	Additional parts for cold countries certain countries only; Standard certain countries only	-	-	-	-	-	-	-	-	-	-	-	0,00
829	Taiwan version	i	i	-	-	o	o	o	-	i	-	-	0,00
82R	45.7 cm (18-inch) 5-spoke light-alloy wheels certain countries only in conjunction with code 645 not with code R66 not in conjunction with code 950/951or P55 i.V.m. Code P59	i	i	i	i	●	●	●	●	-	●	●	472,50
830	China specification	-	-	-	-	-	o	-	o	i	-	o	0,00
831	Indicator plate fixing Italia	i	i	i	i	o	o	o	o	i	o	o	0,00
835	South Korea specification	-	-	-	-	-	-	-	o	i	-	-	0,00
840	Heat-insulating dark-tinted glass certain countries only not in conjunction with code U63 in conjunction with Code P55, P60	i	i	i	i	●	●	●	●	!	●	●	283,50
842	Folding front passenger seat	i	i	i	i	o	o	o	o	-	o	o	0,00

## 19/3/2019 Optional extras for the GLA

SR 15.04.2018 AJ (800) (Package 1)

SR 13.05.2019 AJ (800) (Package 2)

GLA

● available at extra charge    ○ available at no extra charge    U annotations existing  
S standard equipment    - not available -    BM 156.945 nur Indien (RL) or Korea (LL)

Code	Designation	156.908	156.902	156.903	156.905	156.942	156.943	156.944	156.946	156.952	156.945	156.947	LLP
	not in conjunction with code 242 only in conjunction with code U59, 942 and 021A/028A/105A/11A/118A/621A/625A/631A only LHD models	-	-	-	-	-	-	-	-	-	-	-	
857	<b>Media-Display</b> only in conjunction with code 505/520 or 522	+	+	+	+	●	●	●	●	+	●	●	168,00
862	<b>Preinstallation for TV</b> certain countries only only in conjunction with code 531 or 532	+	+	+	+	●	-	-	●	+	-	●	84,00
865	<b>TV receiver</b> certain countries only not in conjunction with code 2U0 only in conjunction with code 532 or 532	+	+	+	+	●	-	-	●	+	●	●	1039,50
871	<b>HANDS-FREE ACCESS</b> only in conjunction with code P17, 889 and 890	+	+	+	+	○	○	○	○	+	○	○	0,00
873	<b>Heated front seats</b> i.V.m. Code P34/P39/P73	+	+	+	+	●	●	●	●	+	●	●	304,50
875	<b>Heated windscreen washer system</b> certain countries only	+	+	+	+	●	●	●	U	+	●	●	120,75
877	<b>Ambient lighting</b> only in conjunction with code U62 and P27/P34/ P39/P59/P73 or 950	+	+	+	+	U	U	U	U	+	U	U	126,00
882	<b>Interior monitoring system</b> certain countries only only in conjunction with code P54	+	+	+	+	○	○	○	○	+	○	○	0,00
885	<b>Increased anti-theft protection</b> only 537L	+	+	+	+	○	○	○	○	+	○	○	0,00
889	<b>KEYLESS-GO</b> certain countries only not in conjunction with code 880 or 893 i.V.m. Code P17	+	+	+	+	●	●	●	●	+	●	●	472,50
890	<b>EASY-PACK tailgate</b> i.V.m. Code P17	+	+	+	+	○	○	○	○	+	○	○	0,00
893	<b>KEYLESS GO starting function</b> certain countries only not in conjunction with code 880 oder 889	+	+	+	+	○	○	○	○	+	○	○	0,00
8R4	<b>Complete winter (M+S) wheel and tyre assembly x 4</b>	-	-	-	-	-	-	-	-	+	-	-	2835,00
913	<b>Air conditioning preinstallation for hot countries</b> certain countries only	+	+	+	+	-	-	-	-	-	-	-	0,00
922	<b>Reduced power version</b> only in conjunction with code 513L only in conjunction with code 524L	-	-	+	+	-	U	-	-	-	-	-	0,00
926	<b>Emission control system with EU4 technology</b> certain countries only	+	-	-	+	○	○	○	○	+	S	○	0,00
927	<b>EU6 emissions standard</b> certain countries only	S	S	S	S	S	S	S	S	S	○	○	0,00
928	<b>EU5 emission standard</b> certain countries only	-	-	-	-	○	○	-	○	+	-	○	0,00
929	<b>Ethanol fuelled engine</b> certain countries only not in conjunction with code 920	-	-	-	-	-	-	-	○	-	-	○	0,00
931	<b>Tandem interior mirror</b> only in conjunction with code U63 (only LHD)	+	+	+	+	○	○	○	○	-	○	○	0,00
932	<b>Storage compartment front seat left</b>	+	+	+	+	○	○	○	○	+	○	○	0,00

## 19/3/2019 Optional extras for the GLA

SR 15.04.2018 AJ (800) (Package 1)

SR 13.05.2019 AJ (800) (Package 2)

GLA

● available at extra charge    ○ available at no extra charge    ⓘ annotations existing  
S standard equipment    - not available -    BM 156.945 nur Indien (RL) or Korea (LL)

Code	Designation	156.908	156.902	156.903	156.905	156.942	156.943	156.944	156.946	156.952	156.945	156.947	LLP
	not in conjunction with code 555 not in conjunction with code 682 (only LHD) only in conjunction with code 30P	-	-	-	-	-	-	-	-	-	-	-	
933	Engine for ethanol fuel E100	-	-	-	-	-	●	-	-	-	-	-	315,00
939	Stowage box under front passenger seat not in conjunction with code 555 not in conjunction with code 682 (only RHD) only in conjunction with code 30P	-	-	-	-	○	○	○	○	-	○	○	0,00
942	Load compartment package in conjunction with code 021A/105A/111A/118A/621A/625A or 631A only with 842 or 242 (RHD not with 842) in conjunction with code 151A/381A/378A/644A/651A/801A/804A/811A/831A/855A, not in conjunction with code 842 only in conjunction with code U35 i.V.m. Code 242/950/P34/P73 i.V.m. P59 ohne 105A/111A/118A	-	-	-	-	-	●	●	●	-	●	●	152,25 210,00
945	Emission control system China certain countries only	-	-	-	-	-	○	-	○	-	-	○	0,00
968	COC document EU6 without registration certificate part II certain countries only	-	-	-	-	○	○	○	○	-	○	○	0,00
969	COC document EU6 with registration certificate part II certain countries only	-	-	-	-	○	○	○	○	-	○	○	0,00
973	Designation as owner-driver rental vehicle	-	-	-	-	○	○	○	○	-	○	○	0,00
981	Omission of vehicle registration document	-	-	-	-	○	○	○	○	-	○	○	0,00
986	Identification no. (US-VIN) certain countries only	-	-	-	-	○	○	○	○	-	○	○	0,00
989	Identification label under windshield certain countries only; Standard certain countries only	-	-	-	-	○	○	○	○	-	○	○	0,00
997	Exhibition vehicle certain countries only	-	-	-	-	○	○	○	○	-	○	○	0,00
B02	Fanfare horn, electronic, for India	-	-	-	-	○	○	○	○	-	S	○	0,00
B03	ECO start/stop function	S	S	S	S	S	S	S	S	S	S	S	0,00
B08	Fanfare horn certain countries only	-	-	-	-	★	★	★	★	-	★	○	0,00
B12	Tyre-change toolkit (certain countries only) only in conjunction with code 690	-	-	-	-	●	●	●	●	-	●	●	31,50
B24	Remote control for auxiliary heater certain countries only only in conjunction with code 228 i.V.m. Code 362	-	-	-	-	○	○	○	○	-	○	○	0,00
B28	AMG carbon-fibre exterior mirrors certain countries only not in conjunction with code 501 oder P47	-	-	-	-	●	○	○	○	-	●	●	210,00 1260,00
B51	TIREFIT with tyre inflation compressor certain countries only in conjunction with code 645 only in conjunction with code 01R/65R/77R/R31/633/635/655 RVI or RVJ (cert. countries only) not in conjunction with code R66 (cert. Countries only) i.V.m. Code 362	-	-	-	-	○	○	○	○	-	○	○	0,00
		-	-	-	-	●	●	●	●	-	●	●	0,00

## 19/3/2019 Optional extras for the GLA

SR 15.04.2018 ÄJ (800) (Package 1)

SR 13.05.2019 ÄJ (800) (Package 2)

GLA

● available at extra charge    ○ available at no extra charge    ⓘ annotations existing  
S standard equipment    - not available -    BM 156.945 nur Indien (RL) or Korea (LL)

Code	Designation	156.908	156.902	156.903	156.905	156.942	156.943	156.944	156.946	156.952	156.945	156.947	LLP
B59	DYNAMIC SELECT	●	●	●	●	●	●	●	●	●	●	●	0,00
	AMG DYNAMIC SELECT	-	-	-	-	-	-	-	-	-	-	-	
E64	ECALL RUSSLAND (GLONASS) certain countries only	-	-	-	-	●	●	●	●	-	●	●	472,50
E74	AMG sports stripes in matt graphite grey (decals) only in conjunction with PEZ	-	-	-	-	-	-	-	-	-	-	-	0,00
E76	Spare wheel certain countries only only in conjunction with code 669 only in conjunction with code 690	ⓘ	ⓘ	ⓘ	ⓘ	ⓘ	ⓘ	ⓘ	ⓘ	ⓘ	ⓘ	ⓘ	262,50
H06	matt black ash wood trim certain countries only not in conjunction with code U63 only in conjunction with code 950/P34/P27 or P73 only LHD i.V.m. Code P34/P73	-	-	-	-	●	●	●	●	-	●	●	273,00
H14	high-gloss brown burr walnut wood trim certain countries only not in conjunction with code U63 Only in conjunction with code P34, P27 or P73 only LHD i.V.m. Code P34/P73	-	-	-	-	●	●	●	●	-	●	●	273,00
H19	Satin-finish light brown poplar wood trim certain countries only not in conjunction with code U63 only in conjunction with code P34, P27 or P73 only LHD i.V.m. Code P34/P73	-	-	-	-	●	●	●	●	-	●	●	273,00
H54	Black matrix-look trim not in conjunction with code U63 only in conjunction with code P27	-	-	-	-	○	○	○	○	-	○	○	0,00
H73	AMG carbon-fibre trim not in conjunction with code U63 only in conjunction with code 950/P27/P34P39/P59    /P73 or PEZ (only AMG-Type) i.V.m. Code PEZ	-	-	-	-	●	●	●	●	-	●	●	945,00
H74	Carbon-fibre structure trim Only in conjunction with Code PEX	-	-	-	-	-	-	-	-	-	-	-	0,00
H79	light aluminium trim with longitudinal grain certain countries only in conjunction with code 950 not in conjunction with code U63  in conjunction with code P34 or P39 not in conjunction with code U63 (RHD) or Mercedes-AMG GLA 45 in conjunction with code P59 not in conjunction with code U63 and cert. Countries only i.V.m. Code P34/P39/P73/950	-	-	-	-	●	●	●	●	-	●	●	0,00 157,50
H81	Sail-pattern trim certain countries only not in conjunction with code U63 only in conjunction with code P59	-	-	-	-	○	○	○	○	-	○	○	0,00

19/3/2019

Optional extras for the GLA

SR 15.04.2018 ÄJ (800) (Package 1)		GLA																					
SR 13.05.2019 ÄJ (800) (Package 2)																							
		156.908	GLA 200 d Sport Utility Vehicle	156.902	GLA 200 d 4MATIC Sport Utility Vehicle	156.903	GLA 220 d Sport Utility Vehicle	156.905	GLA 220 d 4MATIC Sport Utility Vehicle	156.942	GLA 180 Sport Utility Vehicle	156.943	GLA 200 Sport Utility Vehicle	156.944	GLA 250 Sport Utility Vehicle	156.946	GLA 250 4MATIC Sport Utility Vehicle	156.952	Mercedes-AMG GLA 45 4MATIC Sport Utility Vehicle	156.945	GLA 200 Sport Utility Vehicle RL	156.947	GLA 220 4MATIC Sport Utility Vehicle
● available at extra charge    ○ available at no extra charge    ⓘ annotations existing S standard equipment    - not available - BM 156.945 nur Indien (RL) or Korea (LL)																							
Code	Designation																						LLP
H90	AMG Design trim in black / red not in conjunction with code PEZ or P34	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	+	-	-	-	-	0,00
H91	AMG Design trim in black / silver not in conjunction with code PEZ and certain countries only only in conjunction with code P34	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	+	-	-	-	-	0,00
H92	AMG trim element in black DINAMICA microfibre certain countries only not in conjunction with code P34, PEZ only in conjunction with code 651A or 811A only in conjunction with code 950/951 or P39 only with 651A or 811A i.V.m. Code PAH	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	273,00
K08	Radio frequencies for South America certain countries only only in conjunction with code 505/520/522/531	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	0,00
K11	Adaptive brake lights certain countries only	S	S	S	S	S	S	S	S	S	S	S	S	S	S	S	S	S	S	S	S	S	0,00
L66	AMG Performance steering wheel in black DINAMICA microfibre only in conjunction with code 651A or 641A or 811A i.V.m. Code P71 i.V.m. Code PAH/P74 i.V.m. Code PEZ	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	546,00
R00	43.2 cm (17-inch) steel wheels with 10-hole trim certain countries only not in conjunction with code P27, P55, P59, R66, 830, 950,951 only in conjunction with code R01 or 645	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	0,00
R01	Summer tyres in conjunction with code 633/R31/01R or 82R not with R66 (cert. countries only) in conjunction with code 633/R31/01R/82R only with R66 (cert. Countries only) only in conjunction with code (R00/R48/R67/08R/48R/65R/77R/635/655/RVI or RVJ) (cert. countries only) only in conjunction with code 754/758/778/RVU/RVV/RVX/RVH oder RVW	S	S	S	S	S	S	S	S	S	S	S	S	S	S	S	S	S	S	S	S	S	0,00
R02	All season tyres certain countries only only in conjunction with code 48R, 82R, R31, RVI, RVJ, 65R, 635, RUG or RUH	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	115,50
R05	Summer tyres, optimised rolling resistance certain countries only not in conjunction with code R66 only in conjunction with code R31/82R/01R or 633	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	0,00
R31	45.7 cm (18") 5-twin-spoke light-alloy wheels in conjunction with code R01 or 645 not in conjunction with code R66 not in conjunction with code P55,950,951 in conjunction with Code P59	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	609,00
R48	43.2 cm (17-inch) 5-twin-spoke light-alloy wheels certain countries only  in cert. countrie only in conjunction with P59; but not with R66 not in conjunction with code R66, P55, P59 or 950 in conjunction with Code P27	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	136,50
		+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	52,50
		+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	0,00

## 19/3/2019 Optional extras for the GLA

SR 15.04.2018 AJ (800) (Package 1)

SR 13.05.2019 AJ (800) (Package 2)

● available at extra charge    ○ available at no extra charge    ⓘ annotations existing  
S standard equipment    - not available -    BM 156.945 nur Indien (RL) or Korea (LL)

Code	Designation	156.908	156.902	156.903	156.905	156.942	156.943	156.944	156.946	156.952	156.945	156.947	LLP
R66	<b>Run-flat tyres</b> in conjunction with code 04R only in conjunction with code 645 in conjunction with code 633/R31/01R/82R/635/655/48R/65R/77R/RV1 and RVJ only in conjunction with code R01 in conjunction with code R31/01R/82R/635/655/48R/65R/RV1 or RVJ only in conjunction with code R02 not in conjunction with code B51(cert. Countries only)/754/758/778/R00/R05/R48/08R/1R0/1R7/2R4/4R6/5R1/RVU/RVV/RVX- or RVW i.V.m. Code PEX+(RVH/RV/RVJ)	+	+	+	+	○	○	○	○	-	○	○	220,50
R67	<b>45.7 cm (18-inch) 5-spoke light-alloy wheels</b> certain countries only (China)	-	-	-	-	●	●	●	●	-	●	●	640,50
R96	<b>(20-inch) 5-spoke light-alloy wheels</b> certain countries only	-	-	-	-	-	●	-	-	-	-	-	168,00
RVH	<b>48.3 cm (19-inch) AMG multi-spoke light-alloy wheels</b> in conjunction with code 645 not in conjunction with R66 only in conjunction with PEX and P55	+	+	+	+	○	○	○	○	-	○	○	0,00
RVI	<b>48.3 cm (19-inch) AMG multi-spoke light-alloy wheels</b> certain countries only in conjunction with code Code 645 not in conjunction with R66 in conjunction with code Code R01/R02 only in conjunction with R66 i.V.m. Code 950 i.V.m. Code 950+P55 i.V.m. Code P59 i.V.m. Code PEX+P55	+	+	+	+	●	●	●	●	-	●	●	1995,00
		+	+	+	+	●	●	●	●	-	●	●	1050,00
		+	+	+	+	●	●	●	●	-	●	●	682,50
		+	+	+	+	○	○	○	○	-	○	○	1470,00
		+	+	+	+	○	○	○	○	-	○	○	0,00
RVJ	<b>48.3 cm (19-inch) AMG multi-spoke light-alloy wheels</b> certain countries only in conjunction with code Code 645 not in conjunction with R66 in conjunction with code Code R01/R02 only in conjunction with R66 i.V.m. Code 950 i.V.m. Code P59 i.V.m. Code PEX	+	+	+	+	●	●	●	●	-	●	●	1575,00
		+	+	+	+	●	●	●	●	-	●	●	682,50
		+	+	+	+	○	○	○	○	-	○	○	1102,50
		+	+	+	+	○	○	○	○	-	○	○	0,00
RVU	<b>50.8 cm (20-inch) AMG multi-spoke alloy wheels</b> not in conjunction with code R66 only in conjunction with code R01	-	-	-	-	-	-	-	-	+	-	-	840,00
RVV	<b>50.8 cm (20-inch) AMG multi-spoke alloy wheels</b> not in conjunction with code R66 only in conjunction with code R01	-	-	-	-	-	-	-	-	+	-	-	1207,50
RVX	<b>AMG-VIELSPEICHENRAEDER 20" RUNDUM</b> not in conjunction with code R66 only in conjunction with code PEZ and R01	-	-	-	-	-	-	-	-	+	-	-	0,00
U01	<b>Status display for rear seat belts in instrument cluster</b> certain countries only	S	S	S	S	S	S	S	S	S	S	S	0,00
U03	<b>Omission of decals for special models</b> not in conjunction with code E74 not valid only in conjunction with code PEZ	P	P	P	P	P	P	P	P	+	P	P	0,00
U09	<b>Upper section of dashboard in ARTICO man-made leather</b> only in conjunction with code P34, P39/P73 or PEX Standard i.V.m. Code P34/P39/P73 i.V.m. Code PEX	+	+	+	+	●	●	●	●	-	●	●	0,00
		+	+	+	+	○	○	○	○	-	○	○	210,00
		+	+	+	+	○	○	○	○	-	○	○	0,00
		+	+	+	+	○	○	○	○	-	○	○	0,00

## 19/3/2019 Optional extras for the GLA

SR 15.04.2018 AJ (800) (Package 1)

SR 13.05.2019 AJ (800) (Package 2)

GLA

● available at extra charge    ○ available at no extra charge    ⓘ annotations existing  
S standard equipment    - not available -    BM 156.945 nur Indien (RL) or Korea (LL)

Code	Designation	156.908	156.902	156.903	156.905	156.942	156.943	156.944	156.946	156.952	156.945	156.947	LLP
U10	Automatic deactivation of front passenger airbag certain countries only not in conjunction with code 161A/165A/168A in conjunction with Code 108 (only ECE)	-	-	-	-	○	○	○	○	●	○	○	0,00 99,75 0,00
U12	Velour floor mats certain countries only not in conjunction with code 950/P34/P73	-	-	-	-	●	●	●	●	-	●	●	84,00
U13	"EDITION" badge on the wing not in conjunction with code 261 only in conjunction with code PEX	-	-	-	-	○	○	○	○	-	○	○	0,00
U17	Omission of designo seat belts in red only in conjunction with code 651A or 811A	-	-	-	-	-	-	-	-	ⓘ	-	-	0,00
U21	Sports exhaust system	-	-	-	-	-	-	-	-	ⓘ	-	-	682,50
U22	4-way lumbar support not in conjunction with code 555 only in conjunction with code U59 i.V.m. Code P34/P39/P73 i.V.m. Code PEZ	-	-	-	-	○	○	○	○	ⓘ	○	○	0,00 0,00
U25	Door sill panels with "Mercedes-Benz" lettering, illuminated AMG door sill panels with »AMG« lettering, illuminated only in conjunction with code U62	-	-	-	-	●	●	●	●	ⓘ	●	●	157,50
U26	AMG floor mats certain countries only not in conjunction with code P34/P73 only in conjunction with code 950 (Cord floor mats with edging in black and black contrasting topstitching as well as AMG lettering) only in conjunction with code PEZ only in conjunction with code PEZ (AMG floor mats with white "AMG" lettering and piping in white)	ⓘ	ⓘ	ⓘ	ⓘ	ⓘ	ⓘ	ⓘ	ⓘ	ⓘ	○	○	0,00
U35	Socket in load compartment only in conjunction with code 942	-	-	-	-	○	○	○	○	ⓘ	○	○	0,00
U37	Front fog lamps not in conjunction with code 950,951,772	-	-	-	-	●	●	●	●	-	●	●	194,25
U40	Partition net certain countries only not in conjunction with code 413	-	-	-	-	●	●	●	●	ⓘ	●	●	204,75
U43	LNT technology only in conjunction with code 927 and cert. Countries only	-	-	-	-	-	-	-	-	-	-	-	0,00
U47	AMG rear aerofoil certain countries only in conjunction with Code B26	-	-	-	-	-	-	-	-	ⓘ	-	-	787,50 0,00
U60	Active Bonnet certain countries only	●	●	●	●	●	●	●	●	-	●	●	0,00
U64	Full driving school package not in conjunction with code 429 only in conjunction with code U63 only LHD	-	-	-	-	●	●	●	-	-	●	-	1207,50
U65	Additional exterior mirror right and left contains: code U63 only LHD	-	-	-	-	●	●	●	●	-	●	●	126,00
U66	Fußmatten Cord m.Einfassung in Schwarz u.weißer Kontrastziernah sowie EDITION Schriftzug in weiß	-	-	-	-	○	○	○	○	ⓘ	○	○	0,00

## 19/3/2019 Optional extras for the GLA

SR 15.04.2018 ÄJ (800) (Package 1)

**SR 13.05.2019 ÄJ (800) (Package 2)**

GLA

● available at extra charge   ○ available at no extra charge   ◐ annotations existing  
S standard equipment   - not available -   BM 156.945 nur Indien (RL) or Korea (LL)

Code	Designation					1	1	1	1	1	1	LLP
	certain countries only not valid only in conjunction with code PEX									*		
U70	Red-painted brake callipers	-	-	-	-	-	-	-	-	*	-	336,00
Y05	designo seat belts in red	-	-	-	-	●	●	●	●	*	●	0,00
	only in conjunction with code 651A or 811A									*		315,00
Z83	Activation hill-start assist driving school only in conjunction with code U64	*	-	-	-	○	○	○	-	-	○	0,00
Z97	Electronic interface for remote control not in conjunction with code 537 only LHD models and certain countries only	-	*	*	*	●	●	●	●	*	●	399,00
Z98	Paint not feat.on standard sample card not in conjunction with code 830	-	*	*	*	○	○	○	○	-	○	0,00