

(•) Available at extra cost (○) available without additional charge (S) standard equipment (-) not available (L) Left hand drive only (R) Right hand drive only (NS) National Standard "+" AND (code A and B) "/" OR (code A or B) "[]" XOR if necessary at additional charge (exact one of A,B,...) "()" logical grouping
Please note that central restrictions are displayed. Markets may have specific deviation if any. Codes could be valid for certain countries only.

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

			GLB											Local price excl. VAT
Code	equipment	Restrictions	247610 GLB 180 d (L)	247612 GLB 200 d (L)	247613 GLB 200 d 4MATIC (L)	247614 GLB 220 d (L)	247615 GLB 220 d 4MATIC (L)	247684 GLB 180 (L)	247687 GLB 200 (L)	247688 GLB 200 4MATIC (L)	247646 GLB 250 (L)	247647 GLB 250 4MATIC (L)	247651 Mercedes-AMG GLB 35 4MATIC (L)	
		i.V.m. Code PYH	○	○	○	○	○	○	○	○	○	○	■	0,00
P27	Style		●	●	●	●	●	●	●	●	●	●	■	588,00
		Includes codes 310+311A [101A/379A]+725 [B27]+H61+L3E [L3B]+R04 [27R/52R/643/72R/96R/97R/R38/R54	*	*	*	*	*	*	*	*	*	*	*	
		Not in conjunction with 431/463/55U/720/L5C/L5I/P34/P39/P55/PAU/R43/RTF/U28	*	*	*	*	*	*	*	*	*	*	*	
		Only in conjunction with [101A/311A/379A]+428+U12	*	*	*	*	*	*	*	*	*	*	*	
		i.V.m. Code PYD	○	○	○	○	○	○	○	○	○	○	■	0,00
P59	Progressive		●	●	●	●	●	●	●	●	●	●	■	1.401,75
		Includes codes 310+52R [27R/643/72R/96R/97R/R38/R43/R58/RTG/RVV/RVW]+725 [720/B27]+H60 [H15/H	*	*	*	*	*	*	*	*	*	*	*	
		Not in conjunction with 159A/257A/258A/301A/311A/379A/431/651A/H62/L5C/L5I/P39/R04/RTF/U28	*	*	*	*	*	*	*	*	*	*	*	
		Only in conjunction with 428+U12	*	*	*	*	*	*	*	*	*	*	*	
		i.V.m. Code PWS/PWT/PWU/PWV	○	○	○	○	○	○	○	○	○	○	■	0,00
		i.V.m. Code PYF	○	○	○	○	○	○	○	○	○	○	■	0,00
362	Communications module (LTE) for the use of Mercedes		○	○	○	○	○	○	○	○	○	○	○	0,00
20U	Preinstallation for digital key transfer		●	●	●	●	●	●	●	●	●	●	●	52,50
		i.V.m. Code PWS/PWT/PWU/PWV	○	○	○	○	○	○	○	○	○	○	○	0,00
		i.V.m. Code PYA	○	○	○	○	○	○	○	○	○	○	○	0,00
33U	Remote Services Plus		●	●	●	●	●	●	●	●	●	●	●	157,50
		Not in conjunction with 34U	*	*	*	*	*	*	*	*	*	*	*	
34U	Remote Services Premium		●	●	●	●	●	●	●	●	●	●	●	262,50
		Not in conjunction with 33U	*	*	*	*	*	*	*	*	*	*	*	
351	Mercedes-Benz emergency call system		○	○	○	○	○	○	○	○	○	○	○	0,00
00B	Owner's Manual and service information - Danish		○	○	○	○	○	○	○	○	○	○	○	0,00
00U	Remote Services		●	●	●	●	●	●	●	●	●	●	●	105,00
		i.V.m. Code PYA	○	○	○	○	○	○	○	○	○	○	○	0,00
01B	Owner's Manual and service information - Dutch		○	○	○	○	○	○	○	○	○	○	○	0,00
02B	Owner's Manual and service information - German		○	○	○	○	○	○	○	○	○	○	○	0,00
03B	Owner's Manual and service information - Russian		○	○	○	○	○	○	○	○	○	○	○	0,00
04B	Owner's Manual and service information - Finnish		○	○	○	○	○	○	○	○	○	○	○	0,00
05B	Owner's Manual and service information - English		○	○	○	○	○	○	○	○	○	○	○	0,00
06B	Owner's Manual and service information - Italian		○	○	○	○	○	○	○	○	○	○	○	0,00
07B	Owner's Manual and service information - French		○	○	○	○	○	○	○	○	○	○	○	0,00
08B	Owner's Manual and service information - Spanish		○	○	○	○	○	○	○	○	○	○	○	0,00
09B	Owner's Manual and service information - Portuguese		○	○	○	○	○	○	○	○	○	○	○	0,00
104A	ARTICO man-made leather brown		-	-	-	-	-	●	●	●	-	-	-	257,25

[illegible]

[illegible]

[illegible]

			GLB											Local price excl. VAT
Code	equipment	Restrictions	247610 GLB 180 d (L)	247612 GLB 200 d (L)	247613 GLB 200 d 4MATIC (L)	247614 GLB 220 d (L)	247615 GLB 220 d 4MATIC (L)	247684 GLB 180 (L)	247687 GLB 200 (L)	247688 GLB 200 4MATIC (L)	247646 GLB 250 (L)	247647 GLB 250 4MATIC (L)	247651 Mercedes-AMG GLB 35 4MATIC (L)	
546	Active Speed Limit Assist		○	○	○	○	○	○	○	○	○	○	○	0,00
		Not in conjunction with 234/239/243/258/440/504	*	*	*	*	*	*	*	*	*	*	*	
		Only in conjunction with 233+266+365+513	*	*	*	*	*	*	*	*	*	*	*	
548	MBUX multimedia system		○	○	○	○	○	○	○	○	○	○	○	0,00
		Not in conjunction with 256											*	
		Not in conjunction with 549/PBP/PBR/U19	*	*	*	*	*	*	*	*	*	*	*	
549	MBUX multimedia system		○	○	○	○	○	○	○	○	○	○	○	0,00
		Not in conjunction with 548	*	*	*	*	*	*	*	*	*	*	*	
551	Anti-theft alarm system with preinstallation for collision		●	●	●	●	●	●	●	●	●	●	●	262,50
		Not in conjunction with 301A/H59	*	*	*	*	*	*	*	*	*	*	*	
		i.V.m. Code P54	○	○	○	○	○	○	○	○	○	○	○	0,00
		i.V.m. Code P82	○	○	○	○	○	○	○	○	○	○	○	0,00
552	Anti-theft alarm system with preinstallation for collision		○	○	○	○	○	○	○	○	○	○	○	0,00
598	Petrol particulate filter		-	-	-	-	-	○	○	○	○	○	○	0,00
613	Halogen headlamps for left-hand traffic including integral		○	○	○	○	○	○	○	○	○	○	○	0,00
623	Gulf States specification		●	●	●	●	●	●	●	●	●	●	●	157,50
625	Australia specification		○	○	○	○	○	○	○	○	○	○	○	0,00
631	LED High Performance headlamp		●	●	●	●	●	●	●	●	●	●	●	871,50
		i.V.m. Code PWS/PWT/PWU	○	○	○	○	○	○	○	○	○	○	○	0,00
		i.V.m. Code PYA	-	-	-	-	-	-	-	-	-	-	○	0,00
		i.V.m. Code PYD/PYF/PYH	○	○	○	○	○	○	○	○	○	○	-	0,00
634	Omission of first-aid kit		○	○	○	○	○	○	○	○	○	○	○	0,00
636	Omission of hazard warning triangle		○	○	○	○	○	○	○	○	○	○	○	0,00
640	MULTIBEAM LED		●	●	●	●	●	-	-	-	●	●	●	1.312,50
641	MULTIBEAM LED		●	●	●	●	●	●	●	●	●	●	●	1.312,50
		i.V.m. Code PWS/PWT/PWU	●	●	●	●	●	●	●	●	●	●	●	441,00
		i.V.m. Code PYA	-	-	-	-	-	-	-	-	-	-	●	441,00
		i.V.m. Code PYD/PYF/PYH	●	●	●	●	●	●	●	●	●	●	-	441,00
		i.V.m. Code PAD	○	○	○	○	○	○	○	○	○	○	-	0,00
		i.V.m. Code PWV	○	○	○	○	○	○	○	○	○	○	○	0,00
		i.V.m. Code PYO	○	○	○	○	○	○	○	○	○	○	○	0,00
651	Winter complete wheels fitted		○	○	○	○	○	○	○	○	○	○	○	0,00
652	Summer complete tyres fitted		○	○	○	○	○	○	○	○	○	○	○	0,00
662U	MANUFAKTUR mountain grey MAGNO		-	-	-	-	-	●	●	●	-	-	●	1.942,50

			GLB											Local price excl. VAT
Code	equipment	Restrictions	247610 GLB 180 d (L)	247612 GLB 200 d (L)	247613 GLB 200 d 4MATIC (L)	247614 GLB 220 d (L)	247615 GLB 220 d 4MATIC (L)	247684 GLB 180 (L)	247687 GLB 200 (L)	247688 GLB 200 4MATIC (L)	247646 GLB 250 (L)	247647 GLB 250 4MATIC (L)	247651 Mercedes-AMG GLB 35 4MATIC (L)	
666	Freight packaging without tie-down hooks		●	●	●	●	●	●	●	●	●	●	●	26,25
		Not in conjunction with 554/668	*	*	*	*	*	*	*	*	*	*	*	
		Only in conjunction with 550	*	*	*	*	*	*	*	*	*	*	*	
668	Freight packaging with tie-down hooks		●	●	●	●	●	●	●	●	●	●	●	26,25
		Not in conjunction with 550/666	*	*	*	*	*	*	*	*	*	*	*	
679	Product protection-partial protection		○	○	○	-	-	○	○	○	-	○	○	0,00
690	Emergency spare wheel		○	○	○	○	○	○	○	○	○	○	○	0,00
700	Produktionsstandort Fahrzeug China		-	-	-	-	-	○	○	○	-	-	-	0,00
720	Roof rails in black		○	○	○	○	○	○	○	○	○	○	○	0,00
		Available only as part of (P55)	*	*	*	*	*	*	*	*	*	*	*	
		Available only as part of (P60)											*	
		Not in conjunction with 301A/311A/379A/72R/H59/H61/P27/R04/RTF	*	*	*	*	*	*	*	*	*	*	*	
		Only in conjunction with P55	*	*	*	*	*	*	*	*	*	*	*	
		Only in conjunction with P60											*	
762	Radio remote control without panic button		○	○	○	○	○	○	○	○	○	○	○	0,00
763	Radio remote control with panic switch		○	○	○	○	○	○	○	○	○	○	○	0,00
772	AMG bodystyling		○	○	○	○	○	○	○	○	○	○	S	0,00
		Available only as part of (950)	*	*	*	*	*	*	*	*	*	*	*	
		Not in conjunction with 409/428/55U/7U1/7U2/842/B27/H60/U12/U37	*	*	*	*	*	*	*	*	*	*	*	
		Only in conjunction with 950+[27R/R58/RTF/RTG/RVV/RVW]	*	*	*	*	*	*	*	*	*	*	*	
		Only in conjunction with [159A/211A/214A/257A/258A/651A]	*	*	*	*	*	*	*	*	*	*	*	
79B	Preinstallation for digital radio		○	○	○	○	○	○	○	○	○	○	○	0,00
802	Technical modifications		○	○	○	○	○	○	○	○	○	○	○	0,00
820	Tourist vehicle		○	○	○	○	○	○	○	○	○	○	○	0,00
821	Country code Brazil		-	-	-	-	-	○	○	○	○	○	○	0,00
822	South Africa specification		○	○	○	○	○	○	○	○	○	○	○	0,00
823	country code Switzerland		○	○	○	○	○	○	○	○	○	○	○	0,00
824	Additional parts for cold countries (engine air intake sc		○	○	○	○	○	○	○	○	○	○	○	0,00
829	Taiwan version		○	○	○	○	○	○	○	○	○	○	○	0,00
830	China specification		-	-	-	-	-	○	○	○	-	-	○	0,00
831	country code Italia		○	○	○	○	○	○	○	○	○	○	○	0,00
834	New Zealand specification		-	-	○	-	○	○	-	-	-	○	○	0,00
835	South Korea specification		○	○	-	-	-	-	-	-	○	○	○	0,00
852	Sensor system for anti-theft alarm system		-	-	-	-	-	-	-	-	●	●	●	147,00

			GLB											
Code	equipment	Restrictions	247610 GLB 180 d (L)	247612 GLB 200 d (L)	247613 GLB 200 d 4MATIC (L)	247614 GLB 220 d (L)	247615 GLB 220 d 4MATIC (L)	247684 GLB 180 (L)	247687 GLB 200 (L)	247688 GLB 200 4MATIC (L)	247646 GLB 250 (L)	247647 GLB 250 4MATIC (L)	247651 Mercedes-AMG GLB 35 4MATIC (L)	Local price excl. VAT
		i.V.m. Code 362	-	-	-	-	-	-	-	-	●	●	●	178,50
859U	mojave silver metallic		-	-	-	-	-	●	●	●	-	-	-	787,50
		only China						*	*	*				
862	Pre-installation for digital TV Japan		-	●	●	-	-	●	-	-	-	●	●	94,50
865	TV tuner Japan		-	●	●	-	-	●	-	-	-	●	●	945,00
882	Interior monitoring system		○	○	○	○	○	○	○	○	○	○	○	0,00
		Not in conjunction with 301A/H59	*	*	*	*	*	*	*	*	*	*	*	
885	Increased anti-theft protection		○	○	○	○	○	○	○	○	○	○	○	0,00
896U	brillant blue metallic		●	●	●	●	●	●	●	●	●	●	-	787,50
		only China	*	*	*	*	*	*	*	*	*	*	*	
913	Air conditioning preinstallation for hot countries		○	○	○	○	○	-	-	-	-	-	-	0,00
922	Reduced output engines		-	-	-	-	-	○	○	○	-	-	-	0,00
926	Emission control system with EU4 technology		○	○	○	○	○	○	○	○	○	○	○	0,00
927	EU6 emissions standard		○	○	○	○	○	○	○	○	○	○	○	0,00
929	Ethanol fuelled engine		-	-	-	-	-	-	○	-	-	-	-	0,00
936	Cylinder shut-off		-	-	-	-	-	○	○	○	-	-	-	0,00
943	Toll payment system		●	●	●	●	●	●	●	●	●	●	●	210,00
		only China	*	*	*	*	*	*	*	*	*	*	*	
945	Emission control system China		-	-	-	-	-	○	○	○	-	-	○	0,00
959	Emission Control China Stage 7		-	-	-	-	-	○	-	-	-	-	○	0,00
961	Petrol particulate filter		-	-	-	-	-	○	○	○	○	○	○	0,00
968	COC document EU6 without registration certificate part 1		○	○	○	○	○	○	○	○	○	○	○	0,00
969	COC document EU6 with registration certificate part 2		○	○	○	○	○	○	○	○	○	○	○	0,00
971	Diesel particulate filter		S	S	S	S	S	-	-	-	-	-	-	0,00
973	Designation as owner-driver rental vehicle		○	○	○	○	○	○	○	○	○	○	○	0,00
981	Omission of vehicle registration document		○	○	○	○	○	○	○	○	○	○	○	0,00
986	Identification label with VIN number		○	○	○	○	○	○	○	○	○	○	○	0,00
989	Identification label under windshield		○	○	○	○	○	○	○	○	○	○	○	0,00
994	Exhibition vehicle (B-Trade fair)		○	○	○	○	○	○	○	○	○	○	○	0,00
997	Display vehicle for exhibitions (motor show veh.)		○	○	○	○	○	○	○	○	○	○	○	0,00
999	Petrol particulate filter		-	-	-	-	-	○	○	○	○	○	○	0,00
B08	Fanfare horn		○	○	○	○	○	○	○	○	○	○	○	0,00
B12	Tyre-change toolkit		●	●	●	●	●	●	●	●	●	●	●	31,50
		Not in conjunction with 847		*	*		*	*	*	*	*	*	*	

[illegible]

[illegible]

[illegible]

[illegible]

