

[illegible]

			Not in conjunction with 318/628	*	*	*	*	*	*	*	*	*	*	*	*		
			Not in conjunction with P35/PAX	*	*	*	*	*	*	*	*	*	*	*	*		
	P35	DIGITAL LIGHT		●	●	●	●	●	●	●	●	●	●	●	●		1.417,50
			Includes codes 318+628	*	*	*	*	*	*	*	*	*	*	*	*		
			Not in conjunction with 608	*	*	*	*	*	*	*	*	*	*	*	*		
			Not in conjunction with 632/PAX	*	*	*	*	*	*	*	*	*	*	*	*		
			Only in conjunction with 30U+42U+43U									*	*	*			
			Only in conjunction with 628	*	*	*	*	*	*	*	*	*	*	*	*		
			i.V.m. Code PWV	○	○	○	○	○	○	○	○	○	○	○	○		0,00
			i.V.m. Code PYN/PYO/PYQ/PYR	○	○	○	○	○	○	○	○	○	○	○	○		0,00
N/A	PAX	DIGITAL LIGHT		●	●	●	●	●	●	●	●	●	●	●	●		1.863,75
			Includes codes 318+628	*	*	*	*	*	*	*	*	*	*	*	*		
			Not in conjunction with 234/239/258/440/504/E65/E66									*	*	*			
			Not in conjunction with 608	*	*	*	*	*	*	*	*	*	*	*	*		
			Not in conjunction with 632/P35	*	*	*	*	*	*	*	*	*	*	*	*		
			Not in conjunction with L3A									*	*	*			
			Only in conjunction with [233/266/272/546/K32/K33/K34]+30U+42U+43U+628									*	*	*			
			Only in conjunction with [262]									*	*	*			
			i.V.m. Code PWV	●	●	●	●	●	●	●	●	●	●	●	●		446,25
	550	Trailer coupling with ESP[®] trailer stabiliser		●	●	●	●	●	●	●	●	●	●	●	●		882,00
			Not in conjunction with 09R									*	*	*			
			Not in conjunction with 69R									*	*	*			
			Not in conjunction with P76	*	*	*	*	*	*	*	*	*	*	*	*		
	P54	URBAN GUARD vehicle protection		●	●	●	●	●	●	●	●	●	●	●	●		462,00
			Includes codes 551+882	*	*	*	*	*	*	*	*	*	*	*	*		
			Not in conjunction with P82	*	*	*	*	*	*	*	*	*	*	*	*		
	P82	URBAN GUARD vehicle protection Plus		●	●	●	●	●	●	●	●	●	●	●	●		724,50
			Includes codes 551+882	*	*	*	*	*	*	*	*	*	*	*	*		
			Not in conjunction with P54	*	*	*	*	*	*	*	*	*	*	*	*		
	645	M+S winter tyres, set of 4		●	●	●	●	●	●	●	●	●	●	●	●		168,00
			available as of approx. December 2021	*	*	*	*	*	*	*	*	*	*	*	*		
	R01	Summer tyres		○	○	○	○	○	○	○	○	○	○	○	○		0,00
			Not in conjunction with R03	*	*	*	*	*	*	*	*	*	*	*	*		
N/A	R03	Sports tyres		●	●	●	●	●	●	●	●	●	●	●	●		315,00
			Not in conjunction with R01/R66	*	*	*	*	*	*	*	*	*	*	*	*		
			Only in conjunction with [16R]			*											
			Only in conjunction with [R32/R86/R87/RSJ/RSK]	*	*	*	*	*	*	*	*	*	*	*	*		
N/A	R66	run-flat tyres		●	●	●	●	●	●	●	●	●	●	●	●		294,00
			Not in conjunction with 69R	*		*						*	*	*			
			Not in conjunction with B5 1	*	*	*	*	*	*	*	*	*	*	*	*		
			Not in conjunction with R03/R06	*	*	*	*	*	*	*	*	*	*	*	*		
			Not in conjunction with R82/RVA/RVC/RVD	*	*	*	*	*	*	*	*	*	*	*	*		
			i.V.m. Winterkomplettträder 5R6	●	●	●	●	●	●	●	●	●	●	●	●		588,00
	RSJ	45.7 cm (18-inch) AMG 5-spoke light-alloy wheels		●	●	●	●	●	●	●	●	●	●	●	●		1.102,50
			Not in conjunction with P76									*	*	*			
			i.V.m. Code P31	○	○	○	○	○	○	○	○	○	○	○	○		0,00
	RSK	45.7 cm (18-inch) AMG 5-spoke light-alloy wheels		●	●	●	●	●	●	●	●	●	●	●	●		1.312,50
			Not in conjunction with 725/P76									*	*	*			
			Only in conjunction with P55									*	*	*			
			i.V.m. Code P31	○	○	○	○	○	○	○	○	○	○	○	○		0,00
	RVA	48.3 cm (19-inch) AMG multi-spoke light-alloy wheels		●	●	●	●	●	●	●	●	●	●	●	●		1.942,50
			Not in conjunction with P76									*	*	*			
			Not in conjunction with R03/R66	*	*	*	*	*	*	*	*	*	*	*	*		
			Only in conjunction with R01+R06									*	*	*			
			i.V.m. Code P31	●	●	●	●	●	●	●	●	●	●	●	●		787,50
	RVC	48.3 cm (19-inch) AMG multi-spoke light-alloy wheels		●	●	●	●	●	●	●	●	●	●	●	●		2.152,50
			Not in conjunction with P76									*	*	*			
			Not in conjunction with R03/R66	*	*	*	*	*	*	*	*	*	*	*	*		
			Only in conjunction with R01+R06									*	*	*			
			i.V.m. Code P31	●	●	●	●	●	●	●	●	●	●	●	●		997,50
			i.V.m. Code P31+P55	●	●	●	●	●	●	●	●	●	●	●	●		787,50
	RVD	48.3 cm (19-inch) AMG 5-twin-spoke light-alloy wheels		●	●	●	●	●	●	●	●	●	●	●	●		2.362,50
			Not in conjunction with P76									*	*	*			
			Not in conjunction with R03/R66	*	*	*	*	*	*	*	*	*	*	*	*		
			Only in conjunction with R01+R06									*	*	*			
			i.V.m. Code P31	●	●	●	●	●	●	●	●	●	●	●	●		1.207,50
N/A	09R	43.2 cm (17-inch) multi-spoke light-alloy wheels		-	○	-	-	○	○	○	○	-	-	-	-		0,00
			Not in conjunction with 241/242/275/313/399/401/486/51U/550/553/581/725/772/7U3/872/891/E67/E68/E83/E84/H03/H04/H08/H33/H									*					
			Not in conjunction with P14									*					
			Not in conjunction with R03/R06	*	*			*	*	*	*	*					
			Only in conjunction with P75+P76+R01									*					
	16R	43.2 cm (17-inch) multi-spoke light-alloy wheels		-	-	S	-	-	-	-	-	-	-	-	-		0,00
	69R	43.2 cm (17-inch) multi-spoke light-alloy wheels		○	-	-	○	-	-	-	-	-	○	○			0,00
			Not in conjunction with 201/241/242/275/313/399/401/459/486/51U/550/553/581/725/772/7U3/872/891/E67/E68/E83/E84/H03/H04/H08/H3									*	*				
			Not in conjunction with B63									*					
			Not in conjunction with P31									*					
			Not in conjunction with R03/R06/R66	*			*					*	*				
			Only in conjunction with P75+P76+R01									*	*				
N/A	R15	43.2 cm (17-inch) 10-twin-spoke light-alloy wheels		-	-	●	-	-	-	-	-	-	-	-	-		315,00
				●	-	-	●	-	-	-	-	-	●	●			210,00
				-	○	-	-	○	○	○	○	-	-				0,00

			Not in conjunction with 486/772/L5C/P29/P31									*	*	*	
			Not in conjunction with B63											*	
			Not in conjunction with R03/R06	*	*	*	*	*	*	*	*	*	*	*	
			Only in conjunction with R01									*	*	*	
N/A	R24	43.2 cm (17-inch) 5-spoke light-alloy wheels		○	○	○	○	○	○	○	○	○	○	○	0,00
			Not in conjunction with 486/772/L5C/P29									*	*	*	
			Not in conjunction with B63											*	
			Not in conjunction with P31											*	
			Not in conjunction with R03/R06	*	*	*	*	*	*	*	*	*	*	*	
			Only in conjunction with P15+R01									*	*	*	
N/A	R32	45.7 cm (18-inch) 5-spoke light-alloy wheels		●	–	●	●	–	–	–	–	●	●		1.102,50
				–	●	–	–	●	●	●	●	–	–		787,50
			Not in conjunction with 772/L5C/P29/P31									*	*	*	
			Not in conjunction with B63											*	
			i.V.m. Code P15	●	●	●	●	●	●	●	●	●	●	●	577,50
	R69	43.2 cm (17-inch) 5-spoke light-alloy wheels		○	○	○	○	○	○	○	○	○	○	○	0,00
			Not in conjunction with 486/772/L5C/P29									*	*	*	
			Not in conjunction with B63											*	
			Not in conjunction with P31											*	
			Not in conjunction with R03/R06	*	*	*	*	*	*	*	*	*	*	*	
			Only in conjunction with P15+R01									*	*	*	
N/A	R82	48.3 cm (19-inch) 5-spoke light-alloy wheels		●	●	●	●	●	●	●	●	●	●	●	1.417,50
			Not in conjunction with 772/L5C/P29									*	*	*	
			Not in conjunction with B63											*	
			Not in conjunction with P31											*	
			Not in conjunction with R03/R06	*	*	*	*	*	*	*	*	*	*	*	
			Only in conjunction with P15+R01+R06									*	*	*	
	R86	45.7 cm (18-inch) multi-spoke light-alloy wheels		●	–	●	●	–	–	–	–	●	●		1.102,50
				–	●	–	–	●	●	●	●	–	–		787,50
			Not in conjunction with 772/L5C/P29/P31									*	*	*	
			Not in conjunction with B63											*	
			i.V.m. Code P15	●	●	●	●	●	●	●	●	●	●	●	577,50
	R87	45.7 cm (18-inch) 5-twin-spoke light-alloy wheels		●	–	●	●	–	–	–	–	●	●		1.102,50
				–	●	–	–	●	●	●	●	–	–		787,50
			Not in conjunction with 772/L5C/P29/P31									*	*	*	
			Not in conjunction with B63											*	
			i.V.m. Code P15	●	●	●	●	●	●	●	●	●	●	●	577,50
N/A	672	Emergency spare wheel		○	○	○	○	○	○	○	○	○	○	○	0,00
	B51	TIREFIT		○	○	○	○	○	○	○	○	○	○	○	0,00
			Not in conjunction with R66	*	*	*	*	*	*	*	*	*	*	*	
N/A	1R5	Complete set of 4 M+S winter wheels		●	●	●	●	●	●	●	●	●	●	●	1.680,00
			Not in conjunction with 2R9	*		*	*					*	*		
			Not in conjunction with 486/772/P29/P31/U95	*	*	*	*	*	*	*	*	*	*	*	
			Not in conjunction with 5R6	*	*	*	*	*	*	*	*	*	*	*	
			Not in conjunction with B63			*	*	*	*	*	*				
N/A	2R9	Complete set of 4 M+S winter wheels		●	–	●	●	–	–	–	–	●	●		1.680,00
			Not in conjunction with 1R5/5R6	*		*	*					*	*		
			Not in conjunction with 201/459/486/772/L5C/P29/P31									*	*		
			Not in conjunction with B63											*	
N/A	5R6	Complete set of 4 M+S winter wheels		●	●	●	●	●	●	●	●	●	●	●	2.100,00
			Not in conjunction with 1R5	*	*	*	*	*	*	*	*	*	*	*	
			Not in conjunction with 2R9	*		*	*					*	*		
N/A	313	Roller sunblinds in left and right rear doors		●	●	●	●	●	●	●	●	●	●	●	262,50
			Not in conjunction with 09R									*			
			Not in conjunction with 69R									*	*		
			Not in conjunction with H00									*	*	*	
			Not in conjunction with L3A/P75/P76	*	*	*	*	*	*	*	*	*	*	*	
			Only in conjunction with U34	*	*	*	*	*	*	*	*	*	*	*	
			i.V.m. Code P09	○	○	○	○	○	○	○	○	○	○	○	0,00
	345	Windscreen wipers with rain sensor		S	S	S	S	S	S	S	S	S	S	S	0,00
N/A	540	Electric sunblind for rear window		●	●	●	●	●	●	–	–	–			404,25
			Not in conjunction with 840	*	*	*	*	*	*	*	*				
			i.V.m. Code P09	○	○	○	○	○	○	○	–	–	–		0,00
N/A	597	Heated windscreen		●	●	●	●	●	●	●	●	●	●	●	609,00
			Only in conjunction with 94B+B01	*	*	*	*	*	*	*	*				
			Only for left hand drive		*	*	*	*	*	*	*	*	*	*	
	840	Heat-insulating dark-tinted glass		●	●	●	●	●	●	●	●	●	●	●	388,50
			Not in conjunction with 540	*	*	*	*	*	*	*	*				
			Not in conjunction with U50	*	*	*	*	*	*	*	*	*	*	*	
			i.V.m. Code P55	○	○	○	○	○	○	○	○	○	○	○	0,00
			i.V.m. Code PYH	○	○	○	○	○	○	○	○	○	○	○	0,00
	851	Heat and noise-insulating acoustic glass		●	●	●	●	●	●	●	●	●	●	●	126,00
			i.V.m. Code PAE	○	○	○	○	○	○	○	○	○	○	○	0,00
	875	Heated windscreen washer system		●	●	●	●	●	●	●	●	●	●	●	178,50
			Only for left hand drive		*	*	*	*	*	*	*	*	*	*	
	P49	Mirror package		●	●	●	●	●	●	●	●	●	●	●	493,50
			Includes codes 249+500+587	*	*	*	*	*	*	*	*	*	*	*	
			i.V.m. Code PWS/PWT/PWU/PWV	○	○	○	○	○	○	○	○	○	○	○	0,00
			i.V.m. Code PYA	○	○	○	○	○	○	○	○	○	○	○	0,00
	U50	Omission of heat-insulating dark-tinted glass		○	○	○	○	○	○	○	○	○	○	○	0,00
			Not in conjunction with 09R									*			

			Not in conjunction with 69R								*	*	*
			Not in conjunction with 72S								*	*	*
			Not in conjunction with 840	*	*	*	*	*	*	*	*	*	*
			Not in conjunction with P76	*	*	*	*	*	*	*	*	*	*
			Only in conjunction with P55	*	*	*	*	*	*	*	*	*	*
	72B	USB package Plus		●	●	●	●	●	●	●	●	●	●
			Not in conjunction with 75B	*	*	*	*	*	*	*	*	*	*
			i.V.m. Code PYN/PYO/PYQ/PYR	●	●	●	●	●	●	●	●	●	●
			i.V.m. Code PWV	○	○	○	○	○	○	○	○	○	○
	75B	USB package		●	●	●	●	●	●	●	●	●	●
			Not in conjunction with 72B	*	*	*	*	*	*	*	*	*	*
			i.V.m. Code PWS/PWT/PWU	○	○	○	○	○	○	○	○	○	○
			i.V.m. Code PYA	○	○	○	○	○	○	○	○	○	○
	01U	Preinstallation for Navigation Services		○	○	○	○	○	○	○	○	○	○
	355	Extended MBUX functions		S	S	S	S	S	S	S	S	S	S
	365	Hard-disc navigation		○	○	○	○	○	○	○	○	○	○
			only available as a package content of [PBG/PBF]	*	*	*	*	*	*	*	*	*	*
	367	Preinstallation for Live Traffic Information		○	○	○	○	○	○	○	○	○	○
			only available as a package content of [PBG/PBF]	*	*	*	*	*	*	*	*	*	*
N/A	PBF	MBUX Navigation Plus		●	●	●	●	●	●	●	●	●	●
			Includes codes 365+367+383 [384]	*	*	*	*	*	*	*	*	*	*
			Not in conjunction with PBG	*	*	*	*	*	*	*	*	*	*
			Only in conjunction with 01U	*	*	*	*	*	*	*	*	*	*
			i.V.m. Code PWU/PWV	○	○	○	○	○	○	○	○	○	○
	PBG	MBUX Navigation Premium		●	●	●	●	●	●	●	●	●	●
			Includes codes 365+367+383 [384]	*	*	*	*	*	*	*	*	*	*
			Not in conjunction with PBF	*	*	*	*	*	*	*	*	*	*
			Only in conjunction with 01U	*	*	*	*	*	*	*	*	*	*
			i.V.m. Code PWU/PWV	○	○	○	○	○	○	○	○	○	○
			i.V.m. Code PYM/PYN/PYO/PYQ	○	○	○	○	○	○	○	○	○	○
			i.V.m. Code PYR	○	○	○	○	○	○	○	○	○	○
	537	Digital radio		LS	LS	LS	LS	LS	LS	LS	LS	LS	LS
	79B	Preinstallation for digital radio		○	○	○	○	○	○	○	○	○	○
			Only in conjunction with 537	*	*	*	*	*	*	*	*	*	*
	32U	Sound personalisation		○	○	○	○	○	○	○	○	○	○
			Not in conjunction with 853	*	*	*	*	*	*	*	*	*	*
			Only in conjunction with 22U							*	*	*	
			Only in conjunction with 810	*	*	*	*	*	*	*	*	*	*
	810	Burmester® 3D surround sound system		●	●	●	●	●	●	●	●	●	●
			Not in conjunction with 853	*	*	*	*	*	*	*	*	*	*
			Only in conjunction with 22U+32U							*	*	*	
			i.V.m. Code PAE	○	○	○	○	○	○	○	○	○	○
			i.V.m. Code PWV	○	○	○	○	○	○	○	○	○	○
			i.V.m. Code PYO/PYR	○	○	○	○	○	○	○	○	○	○
	853	Advanced Sound System		●	●	●	●	●	●	●	●	●	●
			Not in conjunction with 32U/810/PAE	*	*	*	*	*	*	*	*	*	*
			Only in conjunction with 22U							*	*	*	
N/A	PAE	Sound Comfort package		●	●	●	●	●	●	●	●	●	●
			Includes codes 810+851	*	*	*	*	*	*	*	*	*	*
			Not in conjunction with 853	*	*	*	*	*	*	*	*	*	*
			Only in conjunction with 22U+32U							*	*	*	
	14U	Smartphone integration		●	●	●	●	●					

			Not in conjunction with 228		*	*	*	*	*	*	*	*	*	*	*	*			
			Not in conjunction with 580/581/670		*	*	*	*	*	*	*	*	*	*	*	*			
			Not in conjunction with P21		*	*	*	*	*	*	*	*	*	*	*	*			
			Not in conjunction with PBP											*	*	*			
			Not in conjunction with PBR											*	*	*			
	580	THERMATIC automatic climate control			●	●	●	●	●	●	●	●	●	●	●	●			262,50
			Not in conjunction with 579		*	*	*	*	*	*	*	*	*	*	*	*			
			Not in conjunction with 581/670		*	*	*	*	*	*	*	*	*	*	*	*			
			i.V.m. Code PWS/PWT/PWU		○	○	○	○	○	○	○	○	○	○	○	○			0,00
			i.V.m. Code PYA		○	○	○	○	○	○	○	○	○	○	○	○			0,00
	581	THERMOTRONIC automatic climate control			●	●	●	●	●	●	●	●	●	●	●	●			966,00
			Not in conjunction with 09R											*					
			Not in conjunction with 579		*	*	*	*	*	*	*	*	*	*	*	*			
			Not in conjunction with 580		*	*	*	*	*	*	*	*	*	*	*	*			
			Not in conjunction with 69R											*	*	*			
			Not in conjunction with 859											*	*	*			
			Not in conjunction with H00											*	*				
			Not in conjunction with L3A/P75/P76		*	*	*	*	*	*	*	*	*	*	*	*			
			Only in conjunction with 670+868		*	*	*	*	*	*	*	*	*	*	*	*			
			i.V.m. Code PWV		○	○	○	○	○	○	○	○	○	○	○	○			0,00
			i.V.m. Code PYO/PYR		○	○	○	○	○	○	○	○	○	○	○	○			0,00
	P21	AIR-BALANCE package			●	●	●	●	●	●	●	●	●	●	●	●			351,75
			Not in conjunction with 579		*	*	*	*	*	*	*	*	*	*	*	*			
			i.V.m. Code PBP/PBR		○	○	○	○	○	○	○	○	○	○	○	○			0,00
	890	EASY-PACK tailgate			-	-	-	-	-	-	-	-	S	S	S			0,00	
	942	Boot Comfort package			-	-	-	-	-	-	-	-	●	●	●			315,00	
			Only in conjunction with 542										*	*	*				
	757	Centre console in high-gloss black			S	S	S	S	S	S	S	S	S	S	S	S			0,00
			Not in conjunction with 794/795		*	*	*	*	*	*	*	*	*	*	*	*			
	794	Centre console, criss-cross look, silver grey			●	●	●	●	●	●	●	●	●	●	●	●			157,50
			Not in conjunction with 757/795		*	*	*	*	*	*	*	*	*	*	*	*			
			Not in conjunction with H03/H04/H08/H33/H64											*	*	*			
			only in conjunction with [H00/H50]		*	*	*	*	*	*	*	*	*	*	*	*			
	795	Centre console in a mixed fabric-look finish with metal			●	●	●	●	●	●	●	●	●	●	●	●			157,50
			Not in conjunction with 757/794		*	*	*	*	*	*	*	*	*	*	*	*			
			Not in conjunction with H03/H33/H50		*	*	*	*	*	*	*	*	*	*	*	*			
			only in conjunction with [H00/H04/H08/H64]		*	*	*	*	*	*	*	*	*	*	*	*			
N/A	PBP	ENERGIZING package			●	●	●	●	●	●	●	●	●	●	●	●			1.197,00
			Includes codes 355+464+525+873 [401]+P21		*	*	*	*	*	*	*	*	*	*	*	*			
			Not in conjunction with 09R																

		i.V.m. Code PWT/PWU/PWV	○ ○ ○ ○ ○ ○ ○ ○ ○ ○	0,00
		i.V.m. Code PYM/PYN/PYO/PYQ	○ ○ ○ ○ ○ ○ ○ ○ ○ ○	0,00
		i.V.m. Code PYR	○ ○ ○ ○ ○ ○ ○ ○ ○ ○	0,00
859	Central display		S S S S S S S S S S	0,00
		Not in conjunction with 464/525/581/670/868/PBP/U19	* * *	
		Not in conjunction with PBR	* * *	
		Only in conjunction with 521	* * *	
868	Central display		● ● ● ● ● ● ● ● ● ●	315,00
		Not in conjunction with 859	* * *	
		i.V.m. Code 464	○ ○ ○ ○ ○ ○ ○ ○ ○ ○	0,00
		i.V.m. Code PWS/PWT/PWU/PWV	○ ○ ○ ○ ○ ○ ○ ○ ○ ○	0,00
		i.V.m. Code PYA	○ ○ ○ ○ ○ ○ ○ ○ ○ ○	0,00
U19	MBUX augmented reality for navigation		● ● ● ● ● ● ● ● ● ●	409,50
		Not in conjunction with 521	* * * * *	
		Not in conjunction with 859	* * *	
		Only in conjunction with 235+365+525+868	* * *	
		i.V.m. Code PWU/PWV	○ ○ ○ ○ ○ ○ ○ ○ ○ ○	0,00
		i.V.m. Code PYN/PYO/PYQ/PYR	○ ○ ○ ○ ○ ○ ○ ○ ○ ○	0,00
876	Interior Light package		S S S S S S S S S S	0,00
891	Ambient lighting		○ ○ ○ ○ ○ ○ ○ ○ ○ ○	0,00
		Not in conjunction with 09R	*	
		Not in conjunction with 69R	* *	
		Not in conjunction with H00	* *	
		Not in conjunction with L3A/P75/P76	* * * * *	
894	Ambient lighting		● ● ● ● ● ● ● ● ● ●	294,00
		only in conjunction with 891	* * * * *	
		i.V.m. Code PWT/PWU/PWV	○ ○ ○ ○ ○ ○ ○ ○ ○ ○	0,00
		i.V.m. Code PYN/PYO/PYQ/PYR	○ ○ ○ ○ ○ ○ ○ ○ ○ ○	0,00
51U	Roof liner in black fabric		● ● ● ● ● ● ● ● ● ●	367,50
		Not in conjunction with 09R	*	
		Not in conjunction with 58U/L3A/P75/P76	* * * * *	
		Not in conjunction with 69R	* *	
		Not in conjunction with H00	* *	
		i.V.m. Code P29	○ ○ ○ ○ ○ ○ ○ ○ ○ ○	0,00
58U	Roof liner in crystal grey fabric		○ ○ ○ ○ ○ ○ ○ ○ ○ ○	0,00
		Not in conjunction with 104A/105A/194A/204A/205A/294A/297A/51U/804A	* * * * *	
P65	Seat Comfort package		● ● ● ● ● ● ● ● ● ●	588,00
		Includes codes U22 [399]	* * * * *	
		Not in conjunction with 09R	*	
		Not in conjunction with 241/242/275	* * * * *	
		Not in conjunction with 69R	* *	
		Not in conjunction with E67/E68/E83/E84	* * * * *	
		Not in conjunction with H00	* * *	
		Not in conjunction with L3A/P75/P76	* * * * *	
		i.V.m. Code PWS/PWT	○ ○ ○ ○ ○ ○ ○ ○ ○ ○	0,00
		i.V.m. Code PYE/PYH	○ ○ ○ ○ ○ ○ ○ ○ ○ ○	0,00
275	Memory package		● ● ● ● ● ● ● ● ● ●	1.312,50
		Not in conjunction with 09R	*	
		Not in conjunction with 69R	* *	
		Not in conjunction with H00	* *	
		Not in conjunction with L3A/P75/P76	* * * * *	
		Not in conjunction with P65	* * * * *	
		Only in conjunction with 241+242+P49	* * * * *	
		only in conjunction with [U22/399/409]	* * * * *	
		i.V.m. Code PWS/PWT	● ● ● ● ● ● ● ● ● ●	724,50
		i.V.m. Code PWU/PWV	○ ○ ○ ○ ○ ○ ○ ○ ○ ○	0,00
		i.V.m. Code PYN/PYO/PYQ/PYR	○ ○ ○ ○ ○ ○ ○ ○ ○ ○	0,00
399	multicontour front seats		● ● ● ● ● ● ● ● ● ●	892,50
		Not in conjunction with 09R	*	
		Not in conjunction with 69R	* *	
		Not in conjunction with H00	* *	
		Not in conjunction with L3A/P75/P76/U22	* * * * *	
		only in conjunction with 7U2+[221/222/275/P65]	* * * * *	
		i.V.m. Code PBR	○ ○ ○ ○ ○ ○ ○ ○ ○ ○	0,00
401	Climatised front seats		● ● ● ● ● ● ● ● ● ●	1.134,00
		Not in conjunction with 09R	*	
		Not in conjunction with 69R	* *	
		Not in conjunction with 873	* * * * *	
		Not in conjunction with H00	* *	
		Not in conjunction with L3A/P75/P76	* * * * *	
		not in conjunction with [001A/301A/601A]	* * * * *	
		only in conjunction with [P65/221/222/275]	* * * * *	
		i.V.m. Code PYA	● ● ● ● ● ● ● ● ● ●	792,75
		i.V.m. Code PBR	○ ○ ○ ○ ○ ○ ○ ○ ○ ○	0,00
873	Heated front seats		● ● ● ● ● ● ● ● ● ●	341,25
		Not in conjunction with 401	* * * * *	
		Not in conjunction with PBR	* * * * *	
		i.V.m. Code PBP	○ ○ ○ ○ ○ ○ ○ ○ ○ ○	0,00
		i.V.m. Code PYM/PYN/PYO/PYQ	○ ○ ○ ○ ○ ○ ○ ○ ○ ○	0,00
		i.V.m. Code PYR	○ ○ ○ ○ ○ ○ ○ ○ ○ ○	0,00
U10	Automatic front passenger airbas deactivation		○ ○ ○ ○ ○ ○ ○ ○ ○ ○	0,00

	U22	4-way lumbar support		●●●●●●●●●●●●	210,00
			Not in conjunction with 399	* * * * *	
			Not in conjunction with PBR		
			i.V.m. Code P65	○ ○ ○ ○ ○ ○ ○ ○ ○ ○	0,00
			i.V.m. Code PYA	○ ○ ○ ○ ○ ○ ○ ○ ○ ○	0,00
	287	Folding rear seat backrests		●●●●●●●●●●●●	346,50
			i.V.m. Code PWS/PWT/PWU/PWV	○ ○ ○ ○ ○ ○ ○ ○ ○ ○	0,00
			i.V.m. Code PYA	○ ○ ○ ○ ○ ○ ○ ○ ○ ○	0,00
	287	Folding rear seat backrests		— — — — — — — S S S	0,00
N/A	872	Heated rear seats		●●●●●●●●●●●●	341,25
			Not in conjunction with 09R		
			Not in conjunction with 69R		
			Not in conjunction with H00		
			Not in conjunction with L3A/P75/P76	* * * * *	
			only in conjunction with [873/40 1]	* * * * *	
	321	Fingerprint scanner		●●●●●●●●●●●●	63,00
			only in conjunction with [00U/33U/34U/37U/38U]	* * * * *	
			i.V.m. Code PWS/PWT/PWU/PWV	○ ○ ○ ○ ○ ○ ○ ○ ○ ○	0,00
			i.V.m. Code PYA	○ ○ ○ ○ ○ ○ ○ ○ ○ ○	0,00
	440	Cruise control		S S S S S S S S S S	0,00
			Not in conjunction with 233/239/23P/266/546/K32/K33/K34/P20	* * * * *	
			Not in conjunction with 262		
			Not in conjunction with PAX		
			Only in conjunction with 258		
	L3A	Multifunction sports steering wheel		S S S S S S S S S S	0,00
			Available only as part of (P75)	* * * * *	
			Not in conjunction with 233/241/242/266/275/313/399/401/443/51U/546/553/581/670/7U3/872/891	* * * * *	
			Not in conjunction with 239/23P/U95	* * * * *	
			Not in conjunction with 262/272/H03/H04/H08/H33/H50/H64/L5C/PAX		
			Not in conjunction with 292		
			Not in conjunction with 772	* * * * *	
			Not in conjunction with B63		
			Not in conjunction with E67/E68/E83/E84	* * * * *	
			Not in conjunction with K32	* * * * *	
			Not in conjunction with P 14	* * * * *	
			Only in conjunction with 258+440		
			Only in conjunction with P75	* * * * *	
			Only in conjunction with [00 1A/ 10 1A]	* * * * *	
	L3E	Leather multifunction sports steering wheel		○ ○ ○ ○ ○ ○ ○ ○ ○ ○	0,00
			Not in conjunction with 111A/118A/194A/211A/294A/297A/601A/L3A/P29/U26	* * * * *	
			Not in conjunction with L5C		
	L5C	Multifunction sports steering wheel in nappa leather		○ ○ ○ ○ ○ ○ ○ ○ ○ ○	0,00
			Available only as part of (P29)	* * * * *	
			Not in conjunction with 001A/104A/105A/204A/205A/301A/7U1/L3A/L3E/U12	* * * * *	
			Not in conjunction with 1R5	* * * * *	
			Not in conjunction with 2R9		
			Not in conjunction with P 14/P75	* * * * *	
			Only in conjunction with P29+P31	* * * * *	
N/A	301	Ashtray insert for cup holder		●●●●●●●●●●●●	31,50
			Only in conjunction with 30P	* * * * *	
	30P	Stowage Space package		— — — — — — — S S S	0,00
			Includes codes 310		
	30P	Stowage Space package		S S S S S S S — — —	0,00
			Includes codes 310	* * * * *	
	310	Double cup holder		S S S S S S S S S S	0,00
			Available only as part of (30P)	* * * * *	
			Only in conjunction with 30P	* * * * *	
	H03	brown high-gloss ash wood trim		●●●●●●●●●●●●	357,00
			Not in conjunction with 09R		
			Not in conjunction with 69R		
			Not in conjunction with 795	* * * * *	
			Not in conjunction with H00	* * * * *	
			Not in conjunction with H04/H08/H33/H50/H64	* * * * *	
			Not in conjunction with L3A/P75/P76		
			Only in conjunction with 757		
	H04	Black open-pore aluminium lines wood trim		●●●●●●●●●●●●	409,50
			Not in conjunction with 09R		
			Not in conjunction with 69R		
			Not in conjunction with 794		
			Not in conjunction with H00	* * * * *	
			Not in conjunction with H03/H08/H33/H50/H64	* * * * *	
			Not in conjunction with L3A/P75/P76		
	H08	Anthracite linestructure lime wood trim		●●●●●●●●●●●●	357,00
			Not in conjunction with 09R		
			Not in conjunction with 69R		
			Not in conjunction with 794		
			Not in conjunction with H00	* * * * *	
			Not in conjunction with H03/H04/H33/H50/H64	* * * * *	
			Not in conjunction with L3A/P75/P76		
	H33	Brown open-pore walnut wood trim		●●●●●●●●●●●●	357,00
			Not in conjunction with 09R		

[illegible]

			Not in conjunction with 69R										*	*	
			Not in conjunction with 7U1/L3A/P75/P76/PBR	*	*	*	*	*	*	*	*	*	*	*	*
			Not in conjunction with H00									*	*	*	
			Only in conjunction with 287	*	*	*	*	*	*	*	*	*	*	*	*
			Only in conjunction with U34	*	*	*	*	*	*	*	*	*	*	*	*
			only in conjunction with 7U3+[P14/P29]+[P65/221/222/275]	*	*	*	*	*	*	*	*	*	*	*	*
			i.V.m. Code PYQ/PYR	●	●	●	●	●	●	●	●	●	●	●	1.050,00
	001A	black		○	○	○	○	○	○	○	○	○	○	○	0,00
			Not in conjunction with 292/L5C									*	*	*	
			Not in conjunction with 772	*	*	*	*	*	*	*	*	*	*	*	*
			Not in conjunction with 7U3/P14/P20/P29/P31/PBR	*	*	*	*	*	*	*	*	*	*	*	*
			Not in conjunction with B63	*		*	*	*	*	*	*	*	*	*	*
			Not in conjunction with U95	*	*	*	*	*	*	*	*	*	*	*	*
			Only in conjunction with [H00/P75]									*	*	*	
	201A	black		●	●	●	●	●	●	●	●	●	●	●	1.722,00
			Not in conjunction with 09R									*	*	*	
			Not in conjunction with 69R									*	*	*	
			Not in conjunction with 7U1/L3A/P75/P76	*	*	*	*	*	*	*	*	*	*	*	*
			Not in conjunction with H00									*	*	*	
			in conjunction with P29 only in conjunction with (PBR/399)	*	*	*	*	*	*	*	*	*	*	*	*
			i.V.m. Code PYQ/PYR	○	○	○	○	○	○	○	○	○	○	○	0,00
	204A	sienna brown / black		●	●	●	●	●	●	●	●	●	●	●	1.879,50
			Not in conjunction with 09R									*	*	*	
			Not in conjunction with 58U/7U1/L3A/P29/P75/P76/Y05	*	*	*	*	*	*	*	*	*	*	*	*
			Not in conjunction with 69R									*	*	*	
			Not in conjunction with H00									*	*	*	
			Not in conjunction with L5C									*	*	*	
			Only in conjunction with 51U	*	*	*	*	*	*	*	*	*	*	*	*
			Only in conjunction with P14									*	*	*	
			i.V.m. Code PYQ/PYR	●	●	●	●	●	●	●	●	●	●	●	157,50
	205A	macchiato beige / black		●	●	●	●	●	●	●	●	●	●	●	1.879,50
			Not in conjunction with 09R									*	*	*	
			Not in conjunction with 58U/7U1/L3A/P29/P75/P76/Y05	*	*	*	*	*	*	*	*	*	*	*	*
			Not in conjunction with 69R									*	*	*	
			Not in conjunction with H00									*	*	*	
			Not in conjunction with L5C									*	*	*	
			Only in conjunction with 51U	*	*	*	*	*	*	*	*	*	*	*	*
			Only in conjunction with P14									*	*	*	
			i.V.m. Code PYQ/PYR	●	●	●	●	●	●	●	●	●	●	●	157,50
	211A	black		●	●	●	●	●	●	●	●	●	●	●	1.722,00
			Not in conjunction with 09R									*	*	*	
			Not in conjunction with 69R									*	*	*	
			Not in conjunction with 7U1/L3A/L3E/P75/P76/PBR	*	*	*	*	*	*	*	*	*	*	*	*
			Not in conjunction with H00									*	*	*	
			Not in conjunction with P14	*	*	*	*	*	*	*	*	*	*	*	*
			Only in conjunction with [L5C/P29/U26]									*	*	*	
			i.V.m. Code PYQ/PYR	○	○	○	○	○	○	○	○	○	○	○	0,00
	294A	sienna brown / black		●	●	●	●	●							

			i.V.m. Code PWS/PWT/PWU/PWV		○	○	○	○	○	○	○	○	○	○	○	○	○	0,00
			i.V.m. Code PYE		○	-	○	○	○	-	-	-	○	○				0,00
	P15	AVANTGARDE exterior			●	-	●	●	●	-	-	-	●	●				840,00
					-	●	-	-	-	●	●	●	-	-				262,50
			Includes codes 725 [720]+R69 [R15/R24/R32/R82/R86/R87/RS]/RSK/RVA/RVC/RVD]												*	*	*	
			Includes codes R69 [R15/R24/R32/R82/R86/R87/RS]/RSK/RVA/RVC/RVD]		*	*	*	*	*	*	*	*	*	*				
			Not in conjunction with 09R											*				
			Not in conjunction with 601A/P29		*	*	*	*	*	*	*	*	*	*	*	*	*	
			Not in conjunction with 69R												*	*	*	
			Not in conjunction with 772		*	*	*	*	*	*	*	*	*	*	*	*	*	
			Not in conjunction with B63		*		*	*	*	*	*	*	*	*	*	*	*	
			Not in conjunction with L5C											*	*	*		
			Not in conjunction with U95		*	*	*	*	*	*	*	*	*	*				
			i.V.m. Code PWS/PWT/PWU/PWV		○	○	○	○	○	○	○	○	○	○	○	○	○	0,00
			i.V.m. Code PYE		○	-	○	○	○	-	-	-	○	○				0,00
	P29	AMG Line interior			●	●	●	●	●	●	●	●	●	●	●	●	●	1.459,50
			Includes codes 601A [101A/111A/118A/194A/201A/211A/294A/297A/801A/804A]+891+L5C+RS] [RSK/RVA/RVC/RVD]		*	*	*	*	*	*	*	*	*	*	*	*	*	
			Not in conjunction with 001A/104A/105A/204A/205A/301A/7U1/L3A/L3E/U12		*	*	*	*	*	*	*	*	*	*	*	*	*	
			Not in conjunction with 1R5		*	*	*	*	*	*	*	*	*	*	*	*	*	
			Not in conjunction with 2R9		*	*	*	*	*	*	*	*	*	*	*	*	*	
			Not in conjunction with P14/P75		*	*	*	*	*	*	*	*	*	*	*	*	*	
			Only in conjunction with P31		*	*	*	*	*	*	*	*	*	*	*	*	*	
			i.V.m. Code PWS/PWT/PWU/PWV		●	●	●	●	●	●	●	●	●	●	●	●	●	556,50
			i.V.m. Code PYH		○	○	○	○	○	○	○	○	○	○	○	○	○	0,00
	P31	AMG Line exterior			●	●	●	●	●	●	●	●	●	●	●	●	●	2.467,50
			Includes codes 725 [720]+772+RS] [RSK/RVA/RVC/RVD]											*	*	*		
			Includes codes 772+RS] [RSK/RVA/RVC/RVD]		*	*	*	*	*	*	*	*	*	*	*	*	*	
			Not in conjunction with 001A/L3A/P75		*	*	*	*	*	*	*	*	*	*	*	*	*	
			Not in conjunction with 1R5		*	*	*	*	*	*	*	*	*	*	*	*	*	
			Not in conjunction with 2R9											*	*	*		
			Not in conjunction with 7U1											*	*	*		
			Not in conjunction with H00										*	*	*	*		
			Only in conjunction with [RS]/[RSK]										*	*	*	*		
			Only in conjunction with [RVA/RVC/RVD]										*	*	*	*		
			i.V.m. Code PWS/PWT/PWU/PWV		-	●	-	-	-	●	●	●	-	-				2.205,00
			i.V.m. Code PWS/PWT/PWU/PWV		●	-	●	●	●	-	-	-	●	●				1.627,50
			i.V.m. Code PYH		○	○	○	○	○	○	○	○	○	○	○	○	○	0,00
	P75	Standard interior equipment and appointments			S	S	S	S	S	S	S	S	S	S	S	S	S	0,00
			Includes codes 001A [101A]+58U+7U1 [7U2]+H00+L3A [L3E]+U12		*	*	*	*	*	*	*	*	*	*	*	*	*	
			Not in conjunction with 241/															

	00U	Remote Services		●●●●●●●●●●	105,00
			i.V.m. Code PYA	○○○○○○○○○○	0,00
	01B	Owner's Manual and service information - Dutch		○○○○○○○○○○	0,00
			Not in conjunction with 00B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/12B/13B/14B/15B/16B/17B	* * * * *	
			Not in conjunction with 23B		*
	02B	Owner's Manual and service information - German		○○○○○○○○○○	0,00
			Not in conjunction with 00B/01B/03B/04B/05B/06B/07B/08B/09B/10B/11B/12B/13B/14B/15B/16B/17B	* * * * *	*
			Not in conjunction with 23B		*
	03B	Owner's Manual and service information - Russian		○○○○○○○○○○	0,00
			Not in conjunction with 00B/01B/02B/04B/05B/06B/07B/08B/09B/10B/11B/12B/13B/14B/15B/16B/17B	* * * * *	*
			Not in conjunction with 23B		*
	04B	Owner's Manual and service information - Finnish		○○○○○○○○○○	0,00
			Not in conjunction with 00B/01B/02B/03B/05B/06B/07B/08B/09B/10B/11B/12B/13B/14B/15B/16B/17B	* * * * *	*
			Not in conjunction with 23B		*
	05B	Owner's Manual and service information - English		○○○○○○○○○○	0,00
			Not in conjunction with 00B/01B/02B/03B/04B/06B/07B/08B/09B/10B/11B/12B/13B/14B/15B/16B/17B	* * * * *	*
			Not in conjunction with 23B		*
	05Z	Run-on times MPM 4 hours		○○○○○○○○○○	0,00
			Not in conjunction with 06Z	* * * * *	*
	06B	Owner's Manual and service information - Italian		○○○○○○○○○○	0,00
			Not in conjunction with 00B/01B/02B/03B/04B/05B/07B/08B/09B/10B/11B/12B/13B/14B/15B/16B/17B	* * * * *	*
			Not in conjunction with 23B		*
	06Z	Run-on times MPM w/o time limit		○○○○○○○○○○	0,00
			Not in conjunction with 05Z	* * * * *	*
	07B	Owner's Manual and service information - French		○○○○○○○○○○	0,00
			Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/08B/09B/10B/11B/12B/13B/14B/15B/16B/17B	* * * * *	*
			Not in conjunction with 23B		*
	08B	Owner's Manual and service information - Spanish		○○○○○○○○○○	0,00
			Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/09B/10B/11B/12B/13B/14B/15B/16B/17B	* * * * *	*
			Not in conjunction with 23B		*
	09B	Owner's Manual and service information - Portuguese		○○○○○○○○○○	0,00
			Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/10B/11B/12B/13B/14B/15B/16B/17B	* * * * *	*
			Not in conjunction with 23B		*
	10B	Owner's Manual and service information - Swedish		○○○○○○○○○○	0,00
			Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/11B/12B/13B/14B/15B/16B/17B	* * * * *	*
			Not in conjunction with 23B		*
	11B	Owner's Manual and service information - Arabic		○○○○○○○○○○	0,00
			Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/12B/13B/14B/15B/16B/17B	* * * * *	*
			Not in conjunction with 23B		*
	12B	Owner's Manual and service information - English USA		○○○○○○○○○○	0,00
			Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/13B/14B/15B/16B/17B	* * * * *	*
			Not in conjunction with 23B		*
	13B	Owner's Manual and service information - Norwegian		○○○○○○○○○○	0,00
			Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/12B/14B/15B/16B/17B	* * * * *	*
			Not in conjunction with 23B		*
	14B	Owner's Manual and service information - Greek		○○○○○○○○○○	0,00
			Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/12B/13B/15B/16B/17B	* * * * *	*
			Not in conjunction with 23B		*
	15B	Owner's Manual and service information - Turkish		○○○○○○○○○○	0,00
			Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/12B/13B/14B/16B/17B	* * * * *	*
			Not in conjunction with 23B		*
	16B	Owner's Manual and service information - Polish		○○○○○○○○○○	0,00
			Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/12B/13B/14B/15B/17B	* * * * *	*
			Not in conjunction with 23B		*
	16U	Apple CarPlay		○○○○○○○○○○	0,00
			Only in conjunction with 14U	* * * * *	*
			Only in conjunction with 17U		* * *
	17B	Owner's Manual and service information - Czech		○○○○○○○○○○	0,00
			Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/12B/13B/14B/15B/16B	* * * * *	*
			Not in conjunction with 23B		*
	17U	Android Auto		○○○○○○○○○○	0,00
			Only in conjunction with 14U	* * * * *	*
			Only in conjunction with 16U		* * *
	18B	Owner's Manual and service information - English South Africa		○○○○○○○○○○	0,00
	19B	Owner's Manual and service information - French South Africa		○○○○○○○○○○	0,00
	20B	Owner's Manual and service information - Spanish South America		○○○○○○○○○○	0,00
	21B	Owner's Manual and service information - Portuguese South America		○○○○○○○○○○	0,00
	221	Electrically adjustable front seat, left		●●●●●●●●●●	525,00
			only in conjunction with 222	* * * * *	*
			only in conjunction with P14/P29	* * * * *	*
	222	Electrically adjustable front seat, right		●●●●●●●●●●	525,00
			only in conjunction with 221	* * * * *	*
			only in conjunction with P14/P29	* * * * *	*
	22B	Owner's Manual and service information - Japanese		○○○○○○○○○○	0,00
			Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/12B/13B/14B/15B/16B	* * * * *	*
			Not in conjunction with 23B		*
	22U	MB-CONNECT MBUX Entertainment		○○○○○○○○○○	0,00
			only available as part of [810/853]	* * * * *	*
	232	Garage door opener (frequency range 284-390 MHz)		●●●●●●●●●●	236,25
			only in conjunction with P49	* * * * *	*
	235	Active Parking Assist with PARKTRONIC		○○○○○○○○○○	0,00

	23B	Owner's Manual and service information - simplified Chinese	Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/12B/13B/14B/15B/16B	-	-	-	-	-	-	-	-	-	-	-	-	-	0,00
			Only for left hand drive													*	
	241	Power front left seat with memory function	Not in conjunction with 09R	○	○	○	○	○	○	○	○	○	○	○	○	○	0,00
			Not in conjunction with 69R											*	*	*	
			Not in conjunction with H00										*	*	*	*	
			Not in conjunction with L3A/P75/P76	*	*	*	*	*	*	*	*	*	*	*	*	*	
			Not in conjunction with P65	*	*	*	*	*	*	*	*	*	*	*	*	*	
			Only in conjunction with 242+275+P49	*	*	*	*	*	*	*	*	*	*	*	*	*	
	242	Power front right seat with memory function	Not in conjunction with 09R	○	○	○	○	○	○	○	○	○	○	○	○	○	0,00
			Not in conjunction with 69R											*	*	*	
			Not in conjunction with H00										*	*	*	*	
			Not in conjunction with L3A/P75/P76	*	*	*	*	*	*	*	*	*	*	*	*	*	
			Not in conjunction with P65	*	*	*	*	*	*	*	*	*	*	*	*	*	
			Only in conjunction with 241+275+P49	*	*	*	*	*	*	*	*	*	*	*	*	*	
	249	Interior mirror and driver's exterior mirror automatically dimming	Available only as part of (P49)	○	○	○	○	○	○	○	○	○	○	○	○	○	0,00
			Only in conjunction with P49	*	*	*	*	*	*	*	*	*	*	*	*	*	
	24B	Owner's Manual and service information - traditional Chinese		○	○	○	○	○	○	○	○	○	○	○	○	○	0,00
	25B	Owner's Manual and service information - Korean	Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/12B/13B/14B/15B/16B	○	○	○	○	○	○	○	○	○	○	○	○	○	0,00
			Not in conjunction with 23B	*	*	*	*	*	*	*	*	*	*	*	*	*	
	262	Hintere Sensoren für Spurhalte-Assistent	Not in conjunction with 234/504/E65/E66	○	○	○	○	○	○	○	○	○	○	○	○	○	0,00
			Not in conjunction with 239/258/440										*	*	*		
			Not in conjunction with L3A										*	*	*	*	
			Only in conjunction with [233/266/272/546/K32/K33/K34]										*	*	*	*	
N/A	263	Number plate mounting for Asia / Mexico		○	○	○	○	○	○	○	○	○	○	○	○	○	0,00
N/A	264	Number plate mounting for America		○	○	○	○	○	○	○	○	○	○	○	○	○	0,00
	26B	Owner's Manual and service information - Chinese Taiwan	Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/12B/13B/14B/15B/16B	○	○	○	○	○	○	○	○	○	○	○	○	○	0,00
			Not in conjunction with 23B	*	*	*	*	*	*	*	*	*	*	*	*	*	
	272	Evasive manoeuvre support	Not in conjunction with 234/504/E65/E66	○	○	○	○	○	○	○	○	○	○	○	○	○	0,00
			Not in conjunction with L3A										*	*	*	*	
			Only in conjunction with 233+235+262+266+365+513+546+K32+K33+K34+P49										*	*	*	*	
	27B	Owner's Manual and Service Booklet - Spanish Mexico	Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/12B/13B/14B/15B/16B	○	○	○	○	○	○	○	○	○	○	○	○	○	0,00
			Not in conjunction with 23B	*	*	*	*	*	*	*	*	*	*	*	*	*	
	30B	Owner's Manual and service information - Slovenian	Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/12B/13B/14B/15B/16B	○	○	○	○	○	○	○	○	○	○	○	○	○	0,00
			Not in conjunction with 23B	*	*	*	*	*	*	*	*	*	*	*	*	*	
	30U	Preinstallation for Projection function for lines	Not in conjunction with 608/632	○	○	○	○	○	○	○	○	○	○	○	○	○	0,00
			only available as part of (P35/PAX)	*	*	*	*	*	*	*	*	*	*	*	*	*	
	316	DIGITAL LIGHT SAE RHT	only available as a package content of (P35/PAX)	-	-	-	-	-	○	○	-	-	-	-	-	-	0,00
	317	DIGITAL LIGHT for left hand drive	only available as a package content of (P35/PAX)	○	○	○	○	○	○	○	○	○	○	○	○	○	0,00
	318	DIGITAL LIGHT for right hand traffic	Not in conjunction with 608/632	○	○	○	○	○	○	○	○	○	○	○	○	○	0,00
			only available as a package content of (P35/PAX)	*	*	*	*	*	*	*	*	*	*	*	*	*	
	31B	Owner's Manual and service information - Hungarian	Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/12B/13B/14B/15B/16B	○	○	○	○	○	○	○	○	○	○	○	○	○	0,00
			Not in conjunction with 23B	*	*	*	*	*	*	*	*	*	*	*	*	*	
	325	Centre airbag	Not in conjunction with 23B	○	○	○	○	○	○	○	○	○	○	○	○	○	0,00
	32B	Owner's Manual and service information - Bulgarian	Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/12B/13B/14B/15B/16B	○	○	○	○	○	○	○	○	○	○	○	○	○	0,00
			Not in conjunction with 23B	*	*	*	*	*	*	*	*	*	*	*	*	*	
	33B	Owner's Manual and service information - Romanian	Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/12B/13B/14B/15B/16B	○	○	○	○	○	○	○	○	○	○	○	○	○	0,00
			Not in conjunction with 23B	*	*	*	*	*	*	*	*	*	*	*	*	*	
	34B	Owner's Manual and service information - Croatian	Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/12B/13B/14B/15B/16B	○	○	○	○	○	○	○	○	○	○	○	○	○	0,00
			Not in conjunction with 23B	*	*	*	*	*	*	*	*	*	*	*	*	*	
	35B	Owner's Manual and service information - Latvian	Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/12B/13B/14B/15B/16B	○	○	○	○	○	○	○	○	○	○	○	○	○	0,00
			Not in conjunction with 23B	*	*	*	*	*	*	*	*	*	*	*	*	*	
	36B	Owner's Manual and service information - Lithuanian	Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/12B/13B/14B/15B/16B	○	○	○	○	○	○	○	○	○	○	○	○	○	0,00
			Not in conjunction with 23B	*	*	*	*	*	*	*	*	*	*	*	*	*	
	37B	Owner's Manual and service information - Slovak	Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/12B/13B/14B/15B/16B	○	○	○	○	○	○	○	○	○	○	○	○	○	0,00
			Not in conjunction with 23B	*	*	*	*	*	*	*	*	*	*	*	*	*	
N/A	37U	Advanced connectivity Plus	not in conjunction with 33U	●	●	●	●	●	●	●	●	●	●	●	●	●	262,50
	38B	Owner's Manual and service information - Estonian	Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/12B/13B/14B/15B/16B	○	○	○	○	○	○	○	○	○	○	○	○	○	0,00
			Not in conjunction with 23B	*	*	*	*	*	*	*	*	*	*	*	*	*	

	39B	Owner's Manual and service information - Serbian	Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/12B/13B/14B/15B/16B	*	*	*	*	*	*	*	*	*	*	*	*		0,00
			Not in conjunction with 23B													*	
	40B	Owner's Manual and service information - Ukrainian	Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/12B/13B/14B/15B/16B	*	*	*	*	*	*	*	*	*	*	*	*	*	0,00
			Not in conjunction with 23B													*	
	41B	Owner's Manual and service information - Hebrew	Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/12B/13B/14B/15B/16B	*	*	*	*	*	*	*	*	*	*	*	*	*	0,00
			Not in conjunction with 23B													*	
	42B	Owner's Manual and service information - Indonesian		○	○	○	○	○	○	○	○	○	○	○	○	○	0,00
	42U	Preinstallation for Projection function for symbols		○	○	○	○	○	○	○	○	○	○	○	○	○	0,00
			Not in conjunction with 608/632											*	*	*	
			only available as part of [P35/PAX]	*	*	*	*	*	*	*	*	*	*	*	*	*	
	43B	Owner's Manual and service information - Thai		○	○	○	○	○	○	○	○	○	○	○	○	○	0,00
	43U	Preinstallation for Projection function for animations		○	○	○	○	○	○	○	○	○	○	○	○	○	0,00
			Not in conjunction with 608/632											*	*	*	
			only available as part of [P35/PAX]	*	*	*	*	*	*	*	*	*	*	*	*	*	
	44B	Owner's Manual and service information - Vietnamese		○	○	○	○	○	○	○	○	○	○	○	○	○	0,00
N/A	460	Canada specification		-	-	-	-	-	-	-	-	-	-	-	-	-	0,00
N/A	461	Instrument display in miles with English lettering		○	○	○	○	○	○	○	○	○	○	○	○	○	0,00
	477	Tyre pressure loss warning system		○	○	○	○	○	○	○	○	○	○	○	○	○	0,00
N/A	494	USA specification		-	-	-	-	-	-	○	-	-	-	-	-	-	0,00
N/A	498	Japan specification		-	-	○	○	-	-	-	-	-	-	○	-	-	0,00
	500	Electrically folding exterior mirrors		○	○	○	○	○	○	○	○	○	○	○	○	○	0,00
			Available only as part of (P49)	*	*	*	*	*	*	*	*	*	*	*	*	*	
			Only in conjunction with P49	*	*	*	*	*	*	*	*	*	*	*	*	*	
	501	360° camera		○	○	○	○	○	○	○	○	○	○	○	○	○	0,00
			Available only as part of (P47)										*	*	*		
			Not in conjunction with 09R										*				
			Not in conjunction with 218/P44	*	*	*	*	*	*	*	*	*	*	*	*	*	
			Not in conjunction with 69R										*	*	*		
			Not in conjunction with H00									*	*	*	*		
			Not in conjunction with L3A/P75									*	*	*	*		
			Not in conjunction with P76	*	*	*	*	*	*	*	*	*	*	*	*	*	
			Only in conjunction with P47									*	*	*	*		
			Only in conjunction with P49	*	*	*	*	*	*	*	*	*	*	*	*	*	
	517	HD digital radio standard		○	○	○	○	○	○	○	○	○	○	○	○	○	0,00
	521	MBUX multimedia system		S	S	S	S	S	S	S	S	S	S	S	S	S	0,00
			Not in conjunction with 525/PBP/U19	*	*	*	*	*	*	*	*	*	*	*	*	*	
			Not in conjunction with PBR	*	*	*	*	*	*	*	*	*	*	*	*	*	
	525	MBUX multimedia system		○	○	○	○	○	○	○	○	○	○	○	○	○	0,00
			Not in conjunction with 521	*	*	*	*	*	*	*	*	*	*	*	*	*	
			Not in conjunction with 859										*	*	*		
			only available as part of [865/U19/PBR/PBP]	*	*	*	*	*	*	*	*	*	*	*	*	*	
N/A	536	Sirius satellite radio		-	-	-	-	-	●	●	-	-	-	-	-	-	472,50
	541	Load compartment cover including EASY-PACK safety n		-	-	-	-	-	-	-	S	S	S	S	S	S	0,00
	542	Combined luggage cover/net for luggage comptment.		-	-	-	-	-	-	-	○	○	○	○	○	○	0,00
			Only in conjunction with 942								*	*	*	*	*	*	
	551	Anti-theft alarm system		○	○	○	○	○	○	○	○	○	○	○	○	○	0,00
			Available only as part of (P82)								*	*	*	*	*	*	
			Only in conjunction with P82								*	*	*	*	*	*	
			available only as part of [P54/P82]	*	*	*	*	*	*	*	*	*	*	*	*	*	
	552	Anti-theft alarm system		○	○	○	○	○	○	○	○	○	○	○	○	○	0,00
	554	Pre-installation for trailer coupling		●	●	●	●	●	●	●	●	-	●	-	●	-	168,00
	587	Ambient lighting with projection of brand logo		○	○	○	○	○	○	○	○	○	○	○	○	○	0,00
			Available only as part of (P49)	*	*	*	*	*	*	*	*	*	*	*	*	*	
			Only in conjunction with P49	*	*	*	*	*	*	*	*	*	*	*	*	*	
N/A	623	Gulf States specification		-	-	●	●	-	●	-	-	-	-	-	-	-	157,50
N/A	625	Australia specification		-	-	-	○	-	○	-	-	-	-	-	-	-	0,00
	628	Adaptive Highbeam Assist Plus		○	○	○	○	○	○	○	○	○	○	○	○	○	0,00
			Not in conjunction with 608/632	*	*	*	*	*	*	*	*	*	*	*	*	*	
			only available as part of [P35/PAX]	*	*	*	*	*	*	*	*	*	*	*	*	*	
	631	LED High Performance headlamps for left-hand traffic		○	○	○	○	○	○	○	○	○	○	○	○	○	0,00
	634	Omission of first-aid kit		○	○	○	○	○	○	○	○	○	○	○	○	○	0,00
	636	Omission of warning triangle		○	○	○	○	○	○	○	○	○	○	○	○	○	0,00
	651	Winter complete wheels fitted		○	○	○	○	○	○	○	○	○	○	○	○	○	0,00
			Not in conjunction with 652	*	*	*	*	*	*	*	*	*	*	*	*	*	
	652	Summer complete tyres fitted		○	○	○	○	○	○	○	○	○	○	○	○	○	0,00
			Not in conjunction with 651	*	*	*	*	*	*	*	*	*	*	*	*	*	
	666	Freight packaging without tie-down hooks		●	●	●	●	●	●	●	●	●	●	●	●	●	26,25
			Not in conjunction with 668	*	*	*	*	*	*	*	*	*	*	*	*	*	
			i.V.m. S-Code 14P/15P/16P	○	○	○	○	○	○	○	○	○	○	○	○	○	0,00
	668	Prod. prot. f. freight pkging with tie-down hooks		●	●	●	●	●	●	●	●	●	●	●	●	●	26,25
			Not in conjunction with 666	*	*	*	*	*	*	*	*	*	*	*	*	*	
	670	Residual engine heat utilisation		○	○	○	○	○	○	○	○	○	○	○	○	○	0,00
			Not in conjunction with 579	*	*	*	*	*	*	*	*	*	*	*	*	*	
			Not in conjunction with 580	*	*	*	*	*	*	*	*	*	*	*	*	*	
			Not in conjunction with 859										*	*	*		
			Not in conjunction with H00										*	*	*		
			Not in conjunction with L3A/P75/P76	*	*	*	*	*	*	*	*	*	*	*	*	*	
			Only in conjunction with 581+868	*	*	*	*	*	*	*	*	*	*	*	*	*	

[illegible]

	922	Reduced power version		-	-	○	-	○	-	○	-	-	-	0,00
	925	EU7 emissions standard		○	○	○	○	○	○	○	○	○	○	0,00
	926	Emission control system with EU4 technology		-	-	○	○	○	○	○	-	-	○	0,00
	927	EU6 emissions standard		○	○	○	○	○	○	○	○	○	○	0,00
		Only in conjunction with 6U7+972		*	*									
	943	Toll payment system		●	●	●	●	●	●	●	●	●	●	262,50
N/A	945	Emission control system China		-	-	-	○	-	○	-	-	-	○	0,00
		Only for left hand drive					*	*						
	948	Integrated Starter Generator Generation 2		S	S	S	S	S	S	S	S	S	S	0,00
		Only in conjunction with B01		*	*	*	*	*	*	*				
N/A	959	Emission Control China Stage 7		-	-	-	-	-	-	-	-	-	○	0,00
	964	Abgasanlage COPF mit dritter Lambdasonde		-	-	○	○	○	○	○	-	-	○	0,00
	968	COC document EU6 without registration certificate part I		○	○	○	○	○	○	○	○	○	○	0,00
		Not in conjunction with 687		*	*	*	*	*	*	*				
		Only in conjunction with 6U7+972		*	*									
		Only in conjunction with 927		*	*	*	*	*	*	*				
	969	COC document EU6 with registration certificate part II		○	○	○	○	○	○	○	○	○	○	0,00
	972	Exhaust system with DPF Generation 2.0		○	○	-	-	-	-	○	○	-		0,00
		Only in conjunction with 6U7+927		*	*									
	973	Designation as owner-driver rental vehicle		○	○	○	○	○	○	○	○	○	○	0,00
	981	Omission of vehicle registration document		○	○	○	○	○	○	○	○	○	○	0,00
	983	CoC document EU7 without Reg. Cert. Part II		○	○	○	○	○	○	○	○	○	○	0,00
	985	CoC document EU7 with Reg. Cert. Part II		○	○	○	○	○	○	○	○	○	○	0,00
N/A	986	Identification no. (US-VIN)		○	○	○	○	○	○	○	○	○	○	0,00
	989	Identification label under windshield		○	○	○	○	○	○	○	○	○	○	0,00
N/A	997	Exhibition vehicle		○	○	○	○	○	○	○	○	○	○	0,00
	99P	Versandsteuerung		○	○	○	○	○	○	○	○	○	○	0,00
	B01	EQ Boost starter-alternator		S	S	S	S	S	S	S	S	S	S	0,00
		Only in conjunction with 94B		*	*	*	*	*	*	*				
	B04	EASY-PACK boot box		●	●	●	●	●	●	●	-	-	-	173,25
N/A	B08	Fanfares for Asia		○	○	○	○	○	○	○	○	○	○	0,00
	B63	Sporty engine sound		-	-	○	○	○	○	○	-	-	○	0,00
		Not in conjunction with 001A/L3A/P75				*	*	*	*	*	*		*	
		Not in conjunction with 1R5				*	*	*	*	*				
		Not in conjunction with 2R9											*	
		Not in conjunction with 7U1/H00											*	
		Only in conjunction with P31				*	*	*	*	*	*		*	
	H00	BASIS FOLIATION INSTRUMENT PANEL		S	S	S	S	S	S	S	S	S	S	0,00
		Available only as part of (P75)		*	*	*	*	*	*	*	*	*	*	
		Not in conjunction with 241/242/275/313/399/401/51U/553/581/670/7U3/872/891/H03/H04/H08/H33		*	*	*	*	*	*	*	*	*	*	
		Not in conjunction with 772		*	*	*	*	*	*	*	*	*	*	
		Not in conjunction with B63				*	*	*	*	*	*		*	
		Not in conjunction with E67/E68/E83/E84		*	*	*	*	*	*	*	*	*	*	
		Not in conjunction with L5C										*		
		Not in conjunction with P14/P29/U26		*	*	*	*	*	*	*	*	*		
		Not in conjunction with U95		*	*	*	*	*	*	*	*	*		
		Only in conjunction with P75		*	*	*	*	*	*	*	*	*	*	
		Only in conjunction with [001A/101A]		*	*	*	*	*	*	*	*	*	*	
	K32	Active Lane Change Assist		○	○	○	○	○	○	○	○	○	○	0,00
		Not in conjunction with 234/504		*	*	*	*	*	*	*	*	*	*	
		Not in conjunction with 239/258/440		*	*	*	*	*	*	*	*			
		Not in conjunction with E65/E66		*	*	*	*	*	*	*	*	*	*	
		Not in conjunction with L3A		*	*	*	*	*	*	*	*	*	*	
		Only in conjunction with 233+235+266+272+365+513+546+K33+K34+P49		*	*	*	*	*	*	*	*	*	*	
		Only in conjunction with 262									*	*	*	
		available only as part of 23P/P20		*	*	*	*	*	*	*	*	*	*	
	K33	Extended automatic Re-start in traffic jams		○	○	○	○	○	○	○	○	○	○	0,00
		Not in conjunction with 234/504		*	*	*	*	*	*	*	*	*	*	
		Not in conjunction with 239/258/440		*	*	*	*	*	*	*	*			
		Not in conjunction with E65/E66		*	*	*	*	*	*	*	*	*	*	
		Not in conjunction with L3A		*	*	*	*	*	*	*	*	*	*	
		Only in conjunction with 233+235+266+272+365+513+546+K33+P49		*	*	*	*	*	*	*	*	*	*	
		Only in conjunction with 262+K32									*	*	*	
		available only as part of 23P/P20		*	*	*	*	*	*	*	*	*	*	
	K34	Route-based speed adaptation		○	○	○	○	○	○	○	○	○	○	0,00
		Not in conjunction with 234/504		*	*	*	*	*	*	*	*	*	*	
		Not in conjunction with 239/258/440		*	*	*	*	*	*	*	*			
		Not in conjunction with E65/E66		*	*	*	*	*	*	*	*	*	*	
		Not in conjunction with L3A		*	*	*	*	*	*	*	*	*	*	
		Only in conjunction with 233+235+266+272+365+513+546+K33+P49		*	*	*	*	*	*	*	*	*	*	
		Only in conjunction with 262+K32									*	*	*	
		available only as part of 23P/P20		*	*	*	*	*	*	*	*	*	*	
N/A	K99	Multi-purpose vehicle		-	-	-	-	-	-	-	○	○	○	0,00
L		Left-hand drive		○	○	○	○	○	○	○	○	○	○	0,00
N/A	P09	Sun Protection package		●	●	●	●	●	●	●	-	-	-	651,00
				-	-	-	-	-	-	-	●	●	●	283,50
		Includes codes 313+540+543		*	*	*	*	*	*	*				
		including codes 313+543									*	*	*	
	P53	ENERGIZING AIR CONTROL		●	●	●	●	●	●	●	●	●	●	157,50
		Only for left hand drive		*	*	*	*	*	*	*	*	*	*	
		available as of approx. 3rd quarter 2021		*	*	*	*	*	*	*	*	*	*	

	PAD	Engineering package		● ● ● ● ● ● ● ● ● ●	1.842,75
			Includes codes 201+459	* * * * *	
N/A	PWS	Advanced Package		● - ● ● ● - - - -	4.567,50
				- - - - - - - ● ●	4.305,00
				- ● - - - ● ● - - -	3.990,00
				- - - - - - - ● - -	3.727,50
N/A	PWT	Advanced-Plus Package		● - ● ● ● - - - -	5.575,50
				- - - - - - - ● ●	5.313,00
				- ● - - - ● ● - - -	4.998,00
				- - - - - - - ● - -	4.735,50
N/A	PWU	Premium Package		● - ● ● ● - - - -	7.528,50
				- - - - - - - ● ●	7.287,00
				- ● - - - ● ● - - -	6.951,00
				- - - - - - - ● - -	6.709,50
			i.V.m. Code U19	● - ● ● ● - - - -	7.854,00
			i.V.m. Code U19	- - - - - - - ● ●	7.612,50
			i.V.m. Code U19	- ● - - - ● ● - - -	7.276,50
			i.V.m. Code U19	- - - - - - - ● - -	7.035,00
N/A	PWV	Premium-Plus Package		● - ● ● ● - - - -	11.088,00
				- - - - - - - ● ●	10.846,50
				- ● - - - ● ● - - -	10.510,50
				- - - - - - - ● - -	10.269,00
			i.V.m. Code U19	● - ● ● ● - - - -	11.424,00
			i.V.m. Code U19	- - - - - - - ● ●	11.172,00
			i.V.m. Code U19	- ● - - - ● ● - - -	10.846,50
			i.V.m. Code U19	- - - - - - - ● - -	10.594,50
	PYA	WEU Standard Equipment		LS LS LS LS LS LS LS - - -	0,00
				- - - - - - - LS LS LS	0,00
	PYE	Avantgarde Line		LS - LS LS LS - - - LS LS	0,00
	PYH	AMG Line		● - ● ● ● - - - - ● ●	2.100,00
				- LS - - - LS LS LS - -	0,00
	PYM	Advantage Package		LS LS LS LS LS LS LS LS LS	0,00
	PYN	Premium Package		● ● ● ● ● ● ● ● ● ●	3.152,00
	PYO	Premium Plus package		● ● ● ● ● ● ● - - -	6.285,00
				- - - - - - - ● ● ●	6.023,00
	PYQ	Premium Executive package		● ● ● ● ● ● ● ● ● ●	4.464,00
	PYR	Premium Plus Executive package		● ● ● ● ● ● ● - - -	7.515,00
				- - - - - - - ● ● ●	7.253,00
N/A	R	Right-hand drive		● ● ● ● ● ● ● ● ● ●	1.417,50
N/A	R02	All-season tyres		- - - - - ○ - - -	0,00
	R06	Noise reduced tyre with foam absorber		○ ○ ○ ○ ○ ○ ○ ○ ○ ○	0,00
			Not in conjunction with 09R	* * - - - * * * *	
			Not in conjunction with 69R	* - - - - * - - -	
			Not in conjunction with R15/R24/R69	* * * * * * * * *	
			Not in conjunction with R66	* * * * * * * * *	
			in conjunction with R01 only in conjunction with [R82/RVA/RVC/RVD]	* * * * * * * * *	
			in conjunction with R03 only in conjunction with [22R/R32/R86/R87/RSJ/RSK]	* * * * * * * * *	
	U01	Rear belt status indication in the instrument display		○ ○ ○ ○ ○ ○ ○ ○ ○ ○	0,00
	U16	Exhaust system with acoustic flap		○ ○ ○ ○ ○ ○ ○ ○ ○ ○	0,00
	U41	Fuel/water separator and lubrication package		- ○ - - - - - - -	0,00
			Only for right hand drive	* - - - - - - - -	
	U60	Pedestrian protection		○ ○ ○ ○ ○ ○ ○ ○ ○ ○	0,00
N/A	Z01	Paint not feat.on standard sample card		○ ○ ○ ○ ○ ○ ○ ○ ○ ○	0,00
			Not in conjunction with Z02/Z98	* * * * * * * * *	
			Only in conjunction with 000U	* * * * * * * * *	
N/A	Z02	Paint not feat.on standard sample card		○ ○ ○ ○ ○ ○ ○ ○ ○ ○	0,00
			Not in conjunction with Z01/Z98	* * * * * * * * *	
			Only in conjunction with 000U	* * * * * * * * *	
N/A	Z30	Engine run-on feature		○ ○ ○ ○ ○ ○ ○ ○ ○ ○	0,00
N/A	Z98	Paint not feat.on standard sample card		○ ○ ○ ○ ○ ○ ○ ○ ○ ○	0,00
			Not in conjunction with Z01/Z02	* * * * * * * * *	
			Only in conjunction with 000U	* * * * * * * * *	
N/A	B12	Tyre-change toolkit		○ ○ ○ ○ ○ ○ ○ ○ ○ ○	0,00
	682	Fire extinguisher		LS LS LS LS LS LS LS LS LS	0,00
	70B	Fluorescent jacket for driver		● ● ● ● ● ● ● ● ● ●	5,25
			Not in conjunction with 71B	* * * * * * * * *	
			i.V.m. Code PYA	○ ○ ○ ○ ○ ○ ○ ○ ○ ○	0,00
N/A	71B	Safety vests for driver and passengers		● ● ● ● ● ● ● ● ● ●	26,25
			Not in conjunction with 70B	* * * * * * * * *	
	293	Sidebags in rear		● ● ● ● ● ● ● ● ● ●	393,75
	258	Active Brake Assist		○ ○ ○ ○ ○ ○ ○ ○ ○ ○	0,00
			Not in conjunction with 233/239/23P/266/546/K32/K33/K34/P20	* * * * * * * *	
			Not in conjunction with 262	- - - - - * - - -	
			Not in conjunction with PAX	- - - - - * * * *	
			Only in conjunction with 440	- - - - - * * * *	
	292	PRE-SAFE® impulse side		○ ○ ○ ○ ○ ○ ○ ○ ○ ○	0,00
			Available only as part of (P20)	* * * * * * * * *	
			Not in conjunction with 001A/L3A	* * * * * * * * *	
			Not in conjunction with 234/504	* * * * * * * * *	
			Not in conjunction with 239/23P/258/440	* * * * * * * * *	
			Not in conjunction with E65/E66	* * * * * * * * *	

			Only in conjunction with 235+266+272+365+513+546+K33+K34+P20+P49	*	*	*	*	*	*	*	*	*	*	*		
			Only in conjunction with 262+K32										*	*	*	
299	PRE-SAFE® system			●	●	●	●	●	●	●	●	●	●	●		346,50
			i.V.m. Code P20/23P	○	○	○	○	○	○	○	○	○	○	○		0,00
22P	Lane Tracking package			●	●	●	●	●	●	●	●	●	●	●		819,00
			includes codes 234+243	*	*	*	*	*	*	*	*	*	*	*		
			only in conjunction with P49	*	*	*	*	*	*	*	*	*	*	*		
			i.V.m. Code PYM/PYN/PYO/PYQ	●	●	●	●	●	●	●	●	●	●	●		346,50
			i.V.m. Code PYR	●	●	●	●	●	●	●	●	●	●	●		346,50
233	Active Distance Assist DISTRONIC			○	○	○	○	○	○	○	○	○	○	○		0,00
			Not in conjunction with 234/504	*	*	*	*	*	*	*	*	*	*	*		
			Not in conjunction with 239/258/440	*	*	*	*	*	*	*	*	*	*	*		
			Not in conjunction with E65/E66	*	*	*	*	*	*	*	*	*	*	*		
			Not in conjunction with L3A	*	*	*	*	*	*	*	*	*	*	*		
			Only in conjunction with 235+266+272+365+513+546+K33+K34+P49	*	*	*	*	*	*	*	*	*	*	*		
			Only in conjunction with 262+K32										*	*	*	
234	Active Blind Spot Assist			●	●	●	●	●	●	●	●	●	●	●		472,50
			Not in conjunction with 233/23P/266/546/K32/K33/K34/P20	*	*	*	*	*	*	*	*	*	*	*		
			Not in conjunction with 262/272/292/PAX									*	*	*		
			Only in conjunction with P49	*	*	*	*	*	*	*	*	*	*	*		
			i.V.m. Code 22P	○	○	○	○	○	○	○	○	○	○	○		0,00
			i.V.m. Code PYA	○	○	○	○	○	○	○	○	○	○	○		0,00
239	Active Distance Assist DISTRONIC			●	●	●	●	●	●	●	●	●	●	●		420,00
			Not in conjunction with 233/23P/258/266/440/546/K32/K33/K34/P20	*	*	*	*	*	*	*	*	*	*	*		
			Not in conjunction with 262									*	*	*		
			Not in conjunction with L3A	*	*	*	*	*	*	*	*	*	*	*		
			Not in conjunction with PAX									*	*	*		
			Only in conjunction with 235	*	*	*	*	*	*	*	*	*	*	*		
			available as of approx. June 2021	*	*	*	*	*	*	*	*	*	*	*		
N/A	23P	Driving Assistance package		●	●	●	●	●	●	●	●	●	●	●		2.026,50
			Includes codes 233+299	*	*	*	*	*	*	*	*	*	*	*		
			Not in conjunction with 234/504	*	*	*	*	*	*	*	*	*	*	*		
			Not in conjunction with 239/258/440/P20	*	*	*	*	*	*	*	*	*	*	*		
			Not in conjunction with E65/E66	*	*	*	*	*	*	*	*	*	*	*		
			Not in conjunction with L3A	*	*	*	*	*	*	*	*	*	*	*		
			Only in conjunction with 235+266+272+365+513+546+K33+K34+P49	*	*	*	*	*	*	*	*	*	*	*		
			Only in conjunction with 262+K32									*	*	*		
			i.V.m. Code PYA	●	●	●	●	●	●	●	●	●	●	●		1.554,00
243	Active Lane Keeping Assist			○	○	○	○	○	○	○	○	○	○	○		0,00
266	Active Steering Assist			○	○	○	○	○	○	○	○	○	○	○		0,00
			Not in conjunction with 234/504	*	*	*	*	*	*	*	*	*	*	*		
			Not in conjunction with 239/258/440	*	*	*	*	*	*	*	*	*	*	*		
			Not in conjunction with E65/E66	*	*	*	*	*	*	*	*	*	*	*		
			Not in conjunction with L3A	*	*	*	*	*	*	*	*	*	*	*		
			Only in conjunction with 233+235+272+365+513+546+K33+K34+P49	*	*	*	*	*	*	*	*	*	*	*		
			Only in conjunction with 262+K32									*	*	*		
475	Tyre pressure monitoring system			●	●	●	●	●	●	●	●	●	●	●		320,25
			i.V.m. S-Code 6P5	○	○	○	○	○	○	○	○	○	○	○		0,00
504	Speed Limit Assist			○	○	○	○	○	○	○	○	○	○	○		0,00
			Not in conjunction with 233/23P/266/513/546/K32/K33/K34/P20	*	*	*	*	*	*	*	*	*	*	*		
			Not in conjunction with 262/272/292/PAX									*	*	*		
513	Traffic Sign Assist			●	●	●	●	●	●	●	●	●	●	●		309,75
			Not in conjunction with 504	*	*	*	*	*	*	*	*	*	*	*		
			Only in conjunction with 365	*	*	*	*	*	*	*	*	*	*	*		
			available as of approx. June 2021	*	*	*	*	*	*	*	*	*	*	*		
546	Active Speed Limit Assist			○	○	○	○	○	○	○	○	○	○	○		0,00
			Not in conjunction with 234/504	*	*	*	*	*	*	*	*	*	*	*		
			Not in conjunction with 239/258/440	*	*	*	*	*	*	*	*	*	*	*		
			Not in conjunction with E65/E66	*	*	*	*	*	*	*	*	*	*	*		
			Not in conjunction with L3A	*	*	*	*	*	*	*	*	*	*	*		
			Only in conjunction with 365+513	*	*	*	*	*	*	*	*	*	*	*		
P20	Driving Assistance package Plus			●	●	●	●	●	●	●	●	●	●	●		2.551,50
			Includes codes 233+292+299	*	*	*	*	*	*	*	*	*	*	*		
			Not in conjunction with 001A/L3A	*	*	*	*	*	*	*	*	*	*	*		
			Not in conjunction with 234/504	*	*	*	*	*	*	*	*	*	*	*		
			Not in conjunction with 239/23P/258/440	*	*	*	*	*	*	*	*	*	*	*		
			Not in conjunction with E65/E66	*	*	*	*	*	*	*	*	*	*	*		
			Only in conjunction with 235+266+272+365+513+546+K33+K34+P49	*	*	*	*	*	*	*	*	*	*	*		
			Only in conjunction with 262+K32									*	*	*		
			i.V.m. Code PYA	●	●	●	●	●	●	●	●	●	●	●		2.079,00
218	Reversing camera			●	●	●	●	●	●	●	●	●	●	●		435,75
			Not in conjunction with 501	*	*	*	*	*	*	*	*	*	*	*		
			Not in conjunction with 553/P47									*	*	*		
			i.V.m. Code P44	○	○	○	○	○	○	○	○	○	○	○		0,00
			i.V.m. Code PYA	○	○	○	○	○	○	○	○	○	○	○		0,00
553	Trailer Manoeuvring Assist			—	—	—	—	—	—	—	—	●	●	●		367,50
			Not in conjunction with 09R									*				
			Not in conjunction with 218									*	*	*		
			Not in conjunction with 69R									*	*	*		
			Not in conjunction with H00									*	*	*		
			Not in conjunction with L3A/P75/P76									*	*	*		

[illegible]