

**Standard and special equipment**
**Model year :**

801+051

**Sales Release :**

2020-10-06

**Production Change :**

2021-01-11

Legend

(\*) Available at extra cost (○) available without additional charge (S) standard equipment (-) not available (L) Left hand drive only (R) Right hand drive only (NS) National : Please note that central restrictions are displayed. Markets may have specific deviation if any. Codes could be valid for certain countries only.

			GLS Class						LLP
Code	equipment	Restrictions	167921 GLS 350 d 4MATIC	167923 GLS 400 d 4MATIC	167959 GLS 450 4MATIC	167986 GLS 580 4MATIC	167987 Mercedes-Maybach GLS 600 4MATIC	167989 Mercedes-AMG GLS 63 4MATIC	
B14	AMG carbon-fibre engine cover		-	-	-	-	-	●	787,50
L6G	AMG Performance steering wheel in DINAMICA microfi		-	-	-	-	-	●	514,50
		Not in conjunction with 443						*	
		Only in conjunction with U88						*	
L6H	AMG Performance steering wheel in carbon fibre / DIN		-	-	-	-	-	●	861,00
		Only in conjunction with [H31/H35/H86]						*	
L6J	AMG Performance steering wheel in nappa leather		-	-	-	-	-	S	0,00
L6K	AMG Performance steering wheel in nappa leather / D		-	-	-	-	-	●	441,00
250	AMG Driver's package		-	-	-	-	-	●	1.995,00
421	AMG SPEEDSHIFT TCT 9G		-	-	-	-	-	S	0,00
465	AMG ACTIVE RIDE CONTROL		-	-	-	-	-	S	0,00
467	AMG electronic rear-axle limited-slip differential		-	-	-	-	-	S	0,00
B06	AMG high-performance compound braking system		-	-	-	-	-	S	0,00
B07	AMG high-performance ceramic composite braking sys		-	-	-	-	-	●	4.410,00
		Not in conjunction with 669/B12						*	
U70	AMG high-performance composite braking system		-	-	-	-	-	●	630,00
U78	AMG performance exhaust system, selectable		-	-	-	-	-	●	1.470,00
		i.V.m. Code PYB	-	-	-	-	-	○	0,00
PBE	designo Exclusive Leather package		-	-	-	-	-	●	6.300,00
		Only in conjunction with U61						*	
U61	designo Leather package		-	-	-	-	-	●	13.125,00
901	Interior Chrome package		S	S	S	S	S	S	0,00
P55	Night package		●	●	●	●	-	-	829,50
		Includes codes 840 [U50]+RWH [RPB/RPQ]	*	*	*	*			
		Not in conjunction with R02	*	*					
		Not in conjunction with R66/U12	*	*	*	*			
		Only in conjunction with P31+[RPB/RPQ/RWF/RWH]+U26	*	*	*	*			
		i.V.m. Code PYH	●	●	●	●	-	-	420,00
260	Deletion of model plate on boot lid		○	○	○	○	○	○	0,00
261	Omission of badge		-	-	-	-	○	○	0,00
846	Aluminium-look, illuminated running boards with rubb		●	●	●	●	-	●	656,25
E03	External door handle recesses in high-gloss chrome		●	●	●	●	●	●	110,25
E54	Design side wall trim		●	●	●	●	●	●	462,00
231	Garage door opener		●	●	●	●	●	●	236,25
883	Power closing		●	●	●	●	●	●	577,50
		i.V.m. Code PYB	-	-	-	-	○	-	0,00
		i.V.m. Code PYN/PYO	○	○	○	○	-	○	0,00
B67	Vehicle key in high-gloss black with ornamental surro		●	●	●	●	-	●	0,00
B67	Vehicle key in high-gloss black with ornamental surro		-	-	-	-	S	-	0,00
B67		Not in conjunction with B68	*	*	*	*	*	*	
B68	Vehicle key in high-gloss white with ornamental surro		●	●	●	●	-	●	105,00
			-	-	-	-	○	-	0,00
		Not in conjunction with B67	*	*	*	*	*	*	
P17	KEYLESS-GO Comfort package		●	●	●	-	-	-	0,00
P17	KEYLESS-GO Comfort package		-	-	-	S	S	S	0,00
P17		Includes codes 871+889	*	*	*	*	*	*	
799U	designo diamond white bright		●	●	●	●	●	●	1.743,00
		i.V.m. Code PYB	-	-	-	-	●	-	819,00
		i.V.m. Code C22	-	-	-	-	○	-	0,00
996U	designo hyacinth red metallic		●	●	●	●	●	●	1.302,00
		i.V.m. Code PYB	-	-	-	-	-	-	378,00
C19	cavansite blue / iridium silver		-	-	-	-	●	-	18.375,00

		Not in conjunction with C21/C23/C24/C25/C30					*		
		Only in conjunction with 524+890U					*		
C21	obsidian black / rubellite red		-	-	-	-	●	-	18.375,00
		Not in conjunction with C19/C23/C24/C25/C30					*		
		Only in conjunction with 197U+524					*		
C23	obsidian black / designo kalahari gold metallic		-	-	-	-	●	-	18.375,00
		Not in conjunction with C19/C21/C24/C25/C30					*		
		Only in conjunction with 197U+524					*		
C24	emerald green / mojave silver		-	-	-	-	●	-	18.375,00
		Not in conjunction with C19/C21/C23/C25/C30					*		
		Only in conjunction with 524+989U					*		
C25	iridium silver / designo diamond white bright		-	-	-	-	●	-	18.375,00
		Not in conjunction with C19/C21/C23/C24/C30					*		
		Only in conjunction with 524+775U					*		
C30	iridium silver / selenite grey		-	-	-	-	●	-	18.375,00
		Not in conjunction with 524/C19/C21/C23/C24/C25					*		
		Only in conjunction with 775U					*		
197U	obsidian black		●	●	●	●	●	●	924,00
		i.V.m. Code C21/C23	-	-	-	-	○	-	0,00
		i.V.m. Code PYB	-	-	-	-	○	-	0,00
775U	iridium silver		●	●	●	●	●	●	924,00
		i.V.m. Code C25/C30	-	-	-	-	○	-	0,00
		i.V.m. Code PYB	-	-	-	-	○	-	0,00
859U	Mojave silver		●	●	●	●	●	●	924,00
		i.V.m. Code PYB	-	-	-	-	○	-	0,00
890U	cavansite blue		●	●	●	●	●	●	924,00
		i.V.m. Code C19	-	-	-	-	○	-	0,00
		i.V.m. Code PYB	-	-	-	-	○	-	0,00
896U	brilliant blue		●	●	●	●	●	●	924,00
		i.V.m. Code PYB	-	-	-	-	○	-	0,00
989U	emerald green		●	●	●	●	●	●	924,00
		i.V.m. Code C24	-	-	-	-	○	-	0,00
		i.V.m. Code PYB	-	-	-	-	○	-	0,00
992U	selenite grey		●	●	●	●	●	●	924,00
		i.V.m. Code PYB	-	-	-	-	○	-	0,00
040U	black		○	○	○	○	○	○	0,00
149U	polar white		●	●	●	●	●	●	315,00
		i.V.m. Code PYB	-	-	-	-	○	-	0,00
413	Panoramic sliding sunroof		●	●	●	●	-	●	735,00
			-	-	-	-	S	-	0,00
		Not in conjunction with 414	*	*	*	*	*	*	
		i.V.m. Code PYN/PYO	○	○	○	○	-	○	0,00
414	Sliding sunroof		S	S	S	S	-	S	0,00
		Not in conjunction with 413	*	*	*	*	*	*	
E22	Alustyle Easy-Fix II rail carrier		●	●	●	●	●	●	294,00
628	Adaptive Highbeam Assist Plus		○	○	○	○	○	○	0,00
642	MULTIBEAM LED		●	●	●	-	-	-	0,00
642	MULTIBEAM LED		-	-	-	S	S	S	0,00
642	MULTIBEAM LED	standard equipment in certain countries	*	*	*				
550	Trailer coupling with ESP<sup>®</sup> trailer stabilis		●	●	●	●	●	●	1.008,00
		Only in conjunction with 557	*	*	*	*	*	*	
		for certain countries only	*	*	*	*	*	*	
557	Increased towing capacity		○	○	○	○	○	○	0,00
		Only in conjunction with 550	*	*	*	*	*	*	
551	Anti-theft alarm system with preinstallation for collisic		●	●	●	●	●	●	288,75
		i.V.m. Code P54	○	○	○	○	○	○	0,00
		i.V.m. Code P82	○	○	○	○	○	○	0,00
892	Lockable load compartment floor		●	●	●	●	-	●	73,50
E16	Rim lock set		●	●	●	●	●	●	57,75
P54	URBAN GUARD vehicle protection		●	●	●	●	●	●	493,50
		Includes codes 551+882	*	*	*	*	*	*	
		Not in conjunction with P82	*	*	*	*	*	*	
		i.V.m. Code 362	●	●	●	●	●	●	525,00
		i.V.m. Code PYB	○	○	○	○	○	○	0,00
P82	URBAN GUARD vehicle protection Plus		●	●	●	●	●	●	703,50
		Includes codes 551+882	*	*	*	*	*	*	
		Not in conjunction with P54	*	*	*	*	*	*	
		i.V.m. Code 34U	●	●	●	●	●	●	598,50

		i.V.m. Code PYB	● ● ● ● - ●	105,00
		i.V.m. Code PYB	- - - - ○ -	0,00
R66	run-flat tyres		● ● ● ● - -	367,50
		Not in conjunction with B51/L5C/P31/P55/R06/U26/U50	* * * *	
		Only in conjunction with [94R/R33]	* * * *	
RPA	55.9 cm (22-inch) AMG multi-spoke light-alloy wheels		● ● ● ● - -	1.207,50
		Not in conjunction with 690/P55/R66/U12/U50	* * * *	
		Not in conjunction with R02	* *	
		Only in conjunction with P31+U26	* * * *	
		Only in conjunction with R01	* *	
RPB	55.9 cm (22-inch) AMG multi-spoke light-alloy wheels		● ● ● ● - -	1.522,50
		Not in conjunction with 690/R66/U12	* * * *	
		Not in conjunction with R02	* *	
		Only in conjunction with P31+U26	* * * *	
		Only in conjunction with R01	* *	
		i.V.m. Code P55	● ● ● ● - -	1.207,50
RPC	55.9 cm (22-inch) AMG multi-spoke light-alloy wheels		- - - - - ●	1.890,00
RPQ	58.4 cm (23-inch) AMG 5-twin-spoke light-alloy wheels		● ● ● ● - -	2.625,00
		Not in conjunction with 690/R66/U12	* * * *	
		Not in conjunction with R02	* *	
		Only in conjunction with P31+U26	* * * *	
		Only in conjunction with R01	* *	
		i.V.m. Code P55	● ● ● ● - -	2.310,00
RPR	58.4 cm (23-inch) AMG 5-hole forged wheels		- - - - - ●	3.360,00
RPS	58.4 cm (23-inch) AMG 5-hole forged wheels		- - - - - ●	4.042,50
RWF	53.3 cm (21-inch) AMG 5-twin-spoke light-alloy wheels		○ ○ ○ ○ - -	0,00
		Available only as part of (P31)	* * * *	
		Not in conjunction with R02	* *	
		Not in conjunction with R66/U12	* * * *	
		Only in conjunction with P31+U26	* * * *	
		Only in conjunction with R01	* *	
RWH	53.3 cm (21-inch) AMG 5-twin-spoke light-alloy wheels		● ● ● ● - -	315,00
		Not in conjunction with R02	* *	
		Not in conjunction with R66/U12	* * * *	
		Only in conjunction with P31+U26	* * * *	
		Only in conjunction with R01	* *	
		i.V.m. Code P55	○ ○ ○ ○ - -	0,00
RWI	53.3 cm (21-inch) AMG 10-spoke light-alloy wheels		- - - - - S	0,00
RXW	55.9 cm (22-inch) AMG multi-spoke light-alloy wheels		- - - - - ●	1.207,50
RXX	58.4 cm (23-inch) AMG multi-spoke forged wheels		- - - - - ●	3.150,00
RXY	58.4 cm (23-inch) AMG multi-spoke forged wheels		- - - - - ●	3.832,50
36R	48.3 cm (19-inch) 6-twin-spoke light-alloy wheels		● ● ● - - -	315,00
		Not in conjunction with 669/L5C/P31/P55/R06/R66/U26/U28/U50	* * *	
		i.V.m. Code PYB	○ ○ ○ - - -	0,00
65R	48.3 cm (19-inch) 5-twin-spoke light-alloy wheels		S S S - - -	0,00
		Not in conjunction with 669/L5C/P31/P55/R06/R66/U26/U28/U50	* * *	
94R	50.8 cm (20-inch) 8-spoke light-alloy wheels		● ● ● - - -	945,00
			- - - S - -	0,00
		Not in conjunction with L5C/P31/P55/U26/U50	* * * *	
		Not in conjunction with R02	* *	
		Only in conjunction with R01	* *	
		i.V.m. Code PYB	● ● ● - - -	630,00
95R	53.3 cm (21-inch) 5-triple-spoke light-alloy wheels		● ● ● - - -	1.837,50
			- - - ● - -	892,50
		Not in conjunction with L5C/P31/P55/R66/U26/U50	* * * *	
		Not in conjunction with R02	* *	
		Only in conjunction with R01	* *	
		i.V.m. Code PYB	● ● ● - - -	1.522,50
R33	50.8 cm (20-inch) 5-twin-spoke light-alloy wheels		● ● ● - - -	945,00
			- - - ○ - -	0,00
		Not in conjunction with L5C/P31/P55/U26/U50	* * * *	
		Not in conjunction with R02	* *	
		Only in conjunction with R01	* *	
		i.V.m. Code PYB	● ● ● - - -	630,00
R76	53.3 cm (21-inch) 5-spoke light-alloy wheels		● ● ● - - -	1.837,50
			- - - ● - -	892,50
		Not in conjunction with L5C/P31/P55/R66/U26/U50	* * * *	
		Not in conjunction with R02	* *	

		Only in conjunction with R01	*	*							
		i.V.m. Code PYB	●	●	●	-	-	-			1.522,50
		i.V.m. Code PYB	-	-	-	●	-	-			577,50
R63	55.9 cm (22-inch) Maybach multi-spoke light-alloy wheels		-	-	-	-	S	-			0,00
		Not in conjunction with R65					*				
R65	58.4 cm (23-inch) MAYBACH multi-spoke forged wheels		-	-	-	-	●	-			6.300,00
		Not in conjunction with 645/R63					*				
		Only in conjunction with R01+R06					*				
669	Collapsible spare wheel		●	●	●	●	-	-			367,50
			-	-	-	-	-	●			210,00
			-	-	-	-	○	-			0,00
		Not in conjunction with 36R/65R	*	*	*						
		Not in conjunction with 690/U68	*	*	*	*					
		Not in conjunction with 811/B51	*	*	*	*		*			
		Not in conjunction with B07						*			
		Not in conjunction with B16			*						
		Only in conjunction with 810						*			
		Only in conjunction with B12	*	*	*	*		*			
		i.V.m. Code PYB	●	●	●	●	-	-			315,00
		i.V.m. Code PYB	-	-	-	-	-	●			157,50
690	Emergency spare wheel		●	●	●	●	-	-			136,50
		Not in conjunction with 669/811/B51/RPA/RPB/RPQ/U28/U68	*	*	*	*					
		Not in conjunction with B16			*						
		Only in conjunction with B12	*	*	*	*					
		Included in configuration: code B12	*	*	*	*					
		not in conjunction with P31/U29	*	*	*	*					
		standard equipment in certain countries	*	*	*	*					
		i.V.m. Code PYB	●	●	●	●	-	-			84,00
B51	TIREFIT		●	●	●	●	●	●			52,50
		Not in conjunction with 669/B12	*	*	*	*		*			
		Not in conjunction with 690/R66	*	*	*	*					
		standard equipment in certain countries									
		i.V.m. Code PYB	○	○	○	○	○	○			0,00
297	electric sunblinds in rear doors, left and right		●	●	●	●	-	●			682,50
			-	-	-	-	S	-			0,00
597	Windscreen, heated		-	-	●	●	●	●			609,00
840	Heat-insulating dark-tinted glass		●	●	●	●	-	●			409,50
			-	-	-	-	○	-			0,00
		Not in conjunction with U50	*	*	*	*	*	*			
		standard equipment in certain countries						*			
		i.V.m. Code P55	○	○	○	○	-	-			0,00
		i.V.m. Code P60	-	-	-	-	-	○			0,00
		i.V.m. Code PYB	○	○	○	○	-	○			0,00
874	MAGIC VISION CONTROL		●	●	●	●	●	-			409,50
			-	-	-	-	-	●			231,00
		Not in conjunction with 875	*	*	*	*	*	*			
		i.V.m. Code PYB	○	○	○	○	○	○			0,00
875	Heated windscreen washer system		●	●	●	●	●	-			178,50
			-	-	-	-	-	S			0,00
		Not in conjunction with 874	*	*	*	*	*	*			
P49	Mirror package		S	S	S	S	S	S			0,00
		Includes codes 249+500+587	*	*	*	*	*	*			
		standard equipment in certain countries	*	*	*	*		*			
PAF	Acoustic Comfort package		●	●	●	●	-	●			1.260,00
			-	-	-	-	S	-			0,00
		Includes codes 596	*	*	*	*	*	*			
U50	Omission of heat-insulating dark-tinted glass		○	○	○	○	-	○			0,00
		Not in conjunction with 840	*	*	*	*		*			
		Not in conjunction with R02	*	*							
		Not in conjunction with R66/U12	*	*	*	*					
		Only in conjunction with P31+P55+[RPB/RPQ/RWF/RWH]+U26	*	*	*	*					
		Only in conjunction with P60						*			
518	Media Interface cable kit		●	●	●	●	●	●			52,50
72B	Additional USB ports		S	S	S	S	S	S			0,00
01U	Preinstallation for Navigation Services		●	●	●	●	●	●			105,00
		i.V.m. Code PYB	○	○	○	○	○	○			0,00
355	Extended MBUX functions		S	S	S	S	S	S			0,00
365	Hard-disc navigation		S	S	S	S	S	S			0,00

537	Digital radio		○	○	○	○	○	○	○	0,00
		includes code 79B	*	*	*	*	*	*	*	
		standard equipment in certain countries	*	*	*	*	*	*	*	
PAU	MBUX Innovation package		●	●	●	●	●	●	●	1.375,50
		Includes codes 463+77B	*	*	*	*	*	*	*	
		Not in conjunction with 548	*	*	*	*	*	*	*	
		Not in conjunction with 811	*	*	*	*	*	*	*	
		Only in conjunction with 256							*	
		Only in conjunction with 549+U19	*	*	*	*	*	*	*	
		Only in conjunction with 810						*	*	
		i.V.m. Code U19	●	●	●	●	●	●	●	1.785,00
		i.V.m. Code PYB	-	-	-	-	●	-	-	231,00
447	MBUX rear tablet		○	○	○	○	S	○	○	0,00
		Available only as part of (P11)	*	*	*	*	*	*	*	
		Not in conjunction with 224	*	*	*	*	*	*	*	
		Only in conjunction with P08+P11	*	*	*	*	*	*	*	
864	MBUX Rear Seat Entertainment System		●	●	●	●	●	●	●	2.467,50
		Not in conjunction with 548	*	*	*	*	*	*	*	
		Only in conjunction with 256							*	
		Only in conjunction with 549+866	*	*	*	*	*	*	*	
865	TV receiver		●	●	●	●	●	●	●	1.039,50
		Not in conjunction with 548	*	*	*	*	*	*	*	
		Only in conjunction with 256							*	
		Only in conjunction with 549	*	*	*	*	*	*	*	
		for certain countries only	*	*	*	*	*	*	*	
U31	1 wireless head set		●	●	●	●	●	●	●	210,00
		Not in conjunction with U58	*	*	*	*	*	*	*	
U58	2 wireless head sets		●	●	●	●	●	●	●	420,00
		Not in conjunction with U31	*	*	*	*	*	*	*	
810	Burmester® surround sound system		●	●	●	●	-	-	-	892,50
			-	-	-	-	S	S	S	0,00
		Not in conjunction with 811	*	*	*	*	*	*	*	
		i.V.m. Code PYN/PYO	○	○	○	○	-	-	-	0,00
811	Burmester® high-end 3D surround sound system		●	●	●	●	-	-	-	5.145,00
			-	-	-	-	●	●	●	4.252,50
		Not in conjunction with 669/B12	*	*	*	*	*	*	*	
		Not in conjunction with 690/U68	*	*	*	*	*	*	*	
		Not in conjunction with 77B/810/PAU	*	*	*	*	*	*	*	
		Not in conjunction with B16			*					
		Only in conjunction with 582	*	*	*	*	*	*	*	
		i.V.m. Code PYN/PYO	●	●	●	●	-	-	-	4.252,50
14U	Smartphone integration		●	●	●	●	●	●	●	0,00
14U	Smartphone integration		-	-	-	-	-	-	-	0,00
14U		only in conjunction with 18U	*	*	*	*	*	*	*	
14U		standard equipment in certain countries	*	*	*	*	*	*	*	
380	Car telephony		●	●	●	●	●	●	●	619,50
		Only in conjunction with 274	*	*	*	*	*	*	*	
		Only for left hand drive			*					
856	Business Telephony in the rear		-	-	-	-	●	-	-	997,50
		Not in conjunction with 897					*			
		Only in conjunction with 224+274+380+898+899					*			
897	Wireless charging system for mobile devices in the front		●	●	●	●	-	●	-	210,00
			-	-	-	-	S	-	-	0,00
		Not in conjunction with 856					*			
		Not in conjunction with 899	*	*	*	*	*	*	*	
		for certain countries only	*	*	*	*	*	*	*	
		not in conjunction with 899	*	*	*	*	*	*	*	
		only in conjunction with 72B	*	*	*	*	*	*	*	
		standard equipment in certain countries	*	*	*	*	*	*	*	
		i.V.m. Code PYB	○	○	○	○	-	○	-	0,00
898	Wireless charging system for mobile devices in the rear		-	-	-	-	●	-	-	294,00
			○	○	○	○	-	○	-	0,00
		Available only as part of (P11)	*	*	*	*	*	*	*	
		Not in conjunction with 224	*	*	*	*	*	*	*	
		Only in conjunction with P08+P11	*	*	*	*	*	*	*	
		only in conjunction with P11+447	*	*	*	*	*	*	*	
899	Multifunction telephony		●	●	●	●	-	●	-	514,50
			-	-	-	-	●	-	-	304,50

		Not in conjunction with 897	*	*	*	*	*	*	*		
		Only in conjunction with 274	*	*	*	*	*	*	*		
		Only for left hand drive			*						
		i.V.m. Code PYB	●	●	●	●	-	●			304,50
21U	Dash cam		●	●	●	●	●	●			210,00
			-	-	-	-	-	-			0,00
543	Double sunblind		●	●	●	●	-	●			99,75
			-	-	-	-	-	S	-		0,00
U09	Dashboard and door beltlines in ARTICO man-made lea		●	●	●	●	-	-			472,50
			-	-	-	-	-	S			0,00
		Not in conjunction with U38							*		
		Only in conjunction with [851A/854A]							*		
		i.V.m. Code P22	○	○	○	○	-	-			0,00
U38	Dashboard and door beltlines in nappa leather		●	●	●	●	-	-			1.102,50
			-	-	-	-	S	○			0,00
		Not in conjunction with 55U/58U	*	*	*	*					
		Not in conjunction with 873	*	*	*						
		Not in conjunction with U09							*		
		Only in conjunction with 293+951A	*	*	*	*					
		Only in conjunction with 902	*	*	*						
U67	230 V socket in rear		●	●	●	●	-	●			126,00
U67	230 V socket in rear		-	-	-	-	○	-			0,00
		standard equipment in certain countries						*			
Y05	Red seat belts		-	-	-	-	-	●			315,00
		Not in conjunction with 55U							*		
228	Auxiliary heater		●	●	●	●	●	●			1.281,00
		Only for left hand drive		*	*	*	*	*	*		
443	Steering wheel heating		●	●	●	●	●	●			273,00
		Not in conjunction with L5C	*	*	*	*					
		Not in conjunction with L6G/U88							*		
		only in conjunction with L3D						*			
		i.V.m. Code PYB	-	-	-	-	○	-			0,00
581	THERMOTRONIC automatic climate control		●	●	●	-	-	-			0,00
581	THERMOTRONIC automatic climate control		-	-	-	S	S	S			0,00
581		standard equipment in certain countries	*	*	*						
582	THERMOTRONIC automatic climate control in the rear		●	●	●	●	-	●			724,50
			-	-	-	-	S	-			0,00
		i.V.m. Code PYQ	○	○	○	○	-	○			0,00
B24	Remote control for auxiliary heating		●	●	●	●	●	●			210,00
		Only in conjunction with 228+274	*	*	*	*	*	*	*		
		Only for left hand drive	*	*	*	*	*	*	*		
P21	AIR BALANCE package		●	●	●	●	●	-			351,75
			-	-	-	-	-	○			0,00
		i.V.m. Code PBP/PBR	○	○	○	○	○	-			0,00
		i.V.m. Code PYN/PYO	○	○	○	○	-	-			0,00
P69	Warmth Comfort package		●	●	●	-	-	-			1.522,50
			-	-	-	●	●	●			766,50
		Includes codes 872 [402]+902+906+907	*	*	*	*	*	*			
		Includes codes 902+906+907						*			
		Not in conjunction with 873	*	*	*						
		i.V.m. Code PBR	○	○	○	○	○	○			0,00
		i.V.m. Code PYO	○	○	○	○	-	○			0,00
723	EASY-PACK load compartment cover		S	S	S	S	-	S			0,00
890	EASY-PACK tailgate		S	S	S	S	S	S			0,00
E80	Rear sill protector		●	●	●	●	-	●			162,75
E82	Protection and Care set		●	●	●	●	-	●			120,75
U40	Dividing net for luggage compartment partitioning and		●	●	●	●	-	●			115,50
		Not in conjunction with 224	*	*	*	*	*	*			
		Only in conjunction with 226	*	*	*	*	*	*			
H11	designo high-gloss black flowing lines piano lacquer		-	-	-	-	●	-			603,75
H34	designo high-gloss brown lightlines lime wood		●	●	●	●	-	●			771,75
			-	-	-	-	●	-			603,75
		Not in conjunction with L6H						*			
		i.V.m. Code P22	●	●	●	●	-	-			603,75
H35	designo black flamed open-pore ash wood		●	●	●	●	-	●			462,00
			-	-	-	-	●	-			294,00
		Not in conjunction with L3D	*	*	*	*	*	*			
		Only in conjunction with L3B						*			

		i.V.m. Code P22	● ● ● ● - -	294,00
PBP	ENERGIZING package		● ● ● - - -	729,75
			- - - ● ● -	351,75
			- - - - - ○	0,00
		Includes codes 873 [401/902]+876	* * *	
		Includes codes 876		
		Not in conjunction with 548	* * * * *	
		Not in conjunction with PBR	* * * * *	
		Only in conjunction with 256		*
		Only in conjunction with 549	* * * * *	
		Only in conjunction with P21	* * * *	
		i.V.m. Code PYN	○ ○ ○ ○ - -	0,00
PBR	ENERGIZING package Plus		● ● ● - - -	4.184,25
			- - - ● - -	1.874,25
			- - - - - ●	1.118,25
			- - - - - ●	766,50
		Includes codes 399+876	* * * * *	
		Not in conjunction with 548	* * * * *	
		Not in conjunction with 873/U22	* * *	
		Not in conjunction with PBP	* * * * *	
		Only in conjunction with 256		*
		Only in conjunction with 549+P69	* * * * *	
		Only in conjunction with P21	* * * *	
		i.V.m. Code PYB	- - - - - ○ -	0,00
		i.V.m. Code PYO	○ ○ ○ ○ - ○	0,00
U12	Velour floor mats		● ● ● ● - -	94,50
			- - - - S -	0,00
		Not in conjunction with L5C/P31/P55/U26/U50	* * *	
		Not in conjunction with RPA/RPB/RPQ/RWF/RWH	* * *	
		Not in conjunction with U14		*
		Only in conjunction with [94R/95R/R33/R76]		*
		standard equipment for certain countries	* * * * *	
		i.V.m. Code P22	○ ○ ○ ○ - -	0,00
		i.V.m. Code PYB	○ ○ ○ ○ - -	0,00
U14	High-pile floor mats		- - - - ● -	273,00
		Not in conjunction with U12		*
		i.V.m. Code PYB	- - - - ○ -	0,00
U25	Illuminated AMG door sill panels with »AMG« lettering		- - - - - S	0,00
U26	AMG floor mats		○ ○ ○ ○ - S	0,00
		Not in conjunction with 94R/95R/R33/R76		*
		Not in conjunction with R02	* *	
		Not in conjunction with R66/U12	* * * *	
		Only in conjunction with P31	* * * *	
		Only in conjunction with [RPA/RPB/RPQ/RWF/RWH]	* * *	
256	AMG TRACK PACE		- - - - - ○	0,00
		Only in conjunction with 549		*
463	Head-up Display		● ● ● ● ● ●	1.144,50
		i.V.m. Code PAU	○ ○ ○ ○ ○ ○	0,00
		i.V.m. Code PYB	- - - - ○ -	0,00
		i.V.m. Code PYO	○ ○ ○ ○ - ○	0,00
868	Widescreen cockpit		S S S S S S	0,00
U19	MBUX augmented reality for navigation		● ● ● ● ● ●	409,50
		Not in conjunction with 548	* * * * *	
		Only in conjunction with 256		*
		Only in conjunction with 549	* * * * *	
		i.V.m. Code PAU	○ ○ ○ ○ ○ ○	0,00
		i.V.m. Code PYB	- - - - ○ -	0,00
		i.V.m. Code PYN/PYO	○ ○ ○ ○ - ○	0,00
876	Ambient lighting		S S S S S S	0,00
51U	Roof liner in black fabric		● ● ● ● - -	367,50
			- - - - - S	0,00
		Not in conjunction with 55U/58U/61U	* * * *	*
		Not in conjunction with 565A		*
		i.V.m. Code 284A	○ ○ ○ ○ - -	0,00
55U	Roof liner in macchiato beige fabric		○ ○ ○ ○ - ○	0,00
		Not in conjunction with 51U/58U/61U	* * * *	*
		Not in conjunction with U38	* * *	
		Not in conjunction with Y05		*

		Only in conjunction with 565A						*	
		Only in conjunction with [135A]	*	*	*				
		Only in conjunction with [215A]	*	*	*	*			
58U	Roof liner in crystal grey fabric		○	○	○	○	–	○	0,00
		Not in conjunction with 135A	*	*	*				
		Not in conjunction with 215A/951A/U38	*	*	*	*			
		Not in conjunction with 51U/55U/61U	*	*	*	*		*	
		Not in conjunction with 565A						*	
61U	Roof lining in black DINAMICA microfibre		●	●	●	●	–	●	1.680,00
			–	–	–	–	S	–	0,00
		Not in conjunction with 135A	*	*	*				
		Not in conjunction with 215A	*	*	*	*			
		Not in conjunction with 51U/55U/58U	*	*	*	*		*	
		Not in conjunction with 65U/71U/75U/79U						*	
		Only in conjunction with 543	*	*	*	*	*	*	
		Only in conjunction with 951A						*	
65U	designo roof liner in macchiato beige DINAMICA micro		–	–	–	–	○	–	0,00
		Not in conjunction with 51U/61U/71U/75U/79U							
		Not in conjunction with 61U/71U/75U/79U						*	
		Only in conjunction with 543+954A						*	
71U	designo roof liner in black nappa leather		–	–	–	–	○	–	0,00
		Not in conjunction with 51U/61U/65U/75U/79U							
		Not in conjunction with 61U/65U/75U/79U						*	
		Only in conjunction with 543+951A						*	
75U	designo roof liner in porcelain nappa leather		–	–	–	–	○	–	0,00
		Not in conjunction with 51U/61U/65U/71U/79U							
		Not in conjunction with 61U/65U/71U/79U						*	
		Only in conjunction with 543+954A						*	
79U	designo roof liner in crystal white nappa leather		–	–	–	–	○	–	0,00
		Not in conjunction with 51U/61U/65U/71U/75U							
		Not in conjunction with 61U/65U/71U/75U						*	
		Only in conjunction with 543+959A						*	
399	multicontour front seats		●	●	●	–	–	–	2.310,00
			–	–	–	S	S	S	0,00
		Not in conjunction with 111A/134A/135A/873/U22	*	*	*				
		Only in conjunction with [241/242]+401+436+902	*	*	*				
		included in configuration: code 401 902 436	*	*	*	*			
		only in conjunction with code 201A/204A/205A/284A/958A	*	*	*	*			
		i.V.m. Code PBP	●	●	●	–	–	–	1.932,00
		i.V.m. Code PBR	○	○	○	–	–	–	0,00
		i.V.m. Code PYO	○	○	○	–	–	–	0,00
401	Climatised front seats		●	●	●	–	–	–	1.155,00
			–	–	–	S	S	S	0,00
		Not in conjunction with 873	*	*	*				
		i.V.m. Code P69	●	●	●	–	–	–	777,00
		i.V.m. Code PBP	●	●	●	–	–	–	777,00
		i.V.m. Code 399	○	○	○	–	–	–	0,00
		i.V.m. Code PYO	○	○	○	–	–	–	0,00
452	Seat on front passenger side electrically adjustable fr		●	●	●	●	–	●	210,00
			–	–	–	–	S	–	0,00
		Not in conjunction with 224	*	*	*	*	*	*	
		Only in conjunction with P08+P11	*	*	*	*	*	*	
873	Heated front seats		●	●	●	–	–	–	0,00
873	Heated front seats		–	–	–	–	–	S	0,00
873		Not in conjunction with 399/401/402/406/436/902/951A/P69/PBR/U38	*	*	*				
873		i.V.m. Code PBP	○	○	○	–	–	–	0,00
P64	Memory package		S	S	S	S	S	S	0,00
		Includes codes 242+275	*	*	*	*	*	*	
		includes codes 241/242 + 275	*	*	*	*	*	*	
		only in conjunction with P49	*	*	*	*	*	*	
224	luxury individual seats		–	–	–	–	●	–	3.937,50
			●	●	●	●	–	●	525,00
		Not in conjunction with 226/307/402/406/452/P08/P11/U40	*	*	*	*	*	*	
		Only in conjunction with 872						*	
		Only for left hand drive	*	*	*	*	*	*	
226	5+2-seater		S	S	S	S	–	S	0,00
		Not in conjunction with 224	*	*	*	*	*	*	
308	Refrigerated compartment		–	–	–	–	●	–	1.155,00



402	Climatised rear seats		●	●	●	-	-	-	1.155,00
			-	-	-	●	-	●	777,00
			-	-	-	-	S	-	0,00
		Not in conjunction with 111A/873	*	*	*				
		Not in conjunction with 224/872	*	*	*	*		*	
		Only in conjunction with 401	*	*	*				
		Only in conjunction with 406+P08+P11	*	*	*	*	*	*	
		i.V.m. Code P69	●	●	●	-	-	-	777,00
		i.V.m. Code 406	○	○	○	○	-	○	0,00
		i.V.m. Code PYQ	○	○	○	○	-	○	0,00
406	Multicontour rear seats		●	●	●	●	-	●	2.310,00
			-	-	-	-	S	-	0,00
		Not in conjunction with 111A/873	*	*	*				
		Not in conjunction with 224/872	*	*	*	*		*	
		Only in conjunction with 401	*	*	*				
		Only in conjunction with 402+P08+P11	*	*	*	*	*	*	
		i.V.m. Code PYQ	○	○	○	○	-	○	0,00
437	Luxury rear head restraints		○	○	○	○	S	○	0,00
		Available only as part of (P08)	*	*	*	*	*	*	
		Not in conjunction with 224	*	*	*	*		*	
		Only in conjunction with P08+P11	*	*	*	*	*	*	
449	folding tables in the rear		-	-	-	-	●	-	1.890,00
		Only in conjunction with 224					*		
453	Executive seats		-	-	-	-	S	-	0,00
845	3rd seat row		S	S	S	S	-	S	0,00
872	Heated rear seats		●	●	●	-	-	-	378,00
			-	-	-	○	-	S	0,00
		Not in conjunction with 402/406	*	*	*	*	*	*	
		standard equipment in certain countries						*	
		i.V.m. Code P69	○	○	○	-	-	-	0,00
886	Seat heating for the 3rd seat row		●	●	●	●	-	●	378,00
		Only in conjunction with 582	*	*	*	*	*	*	
903	seat heating Plus for outer rear seats		-	-	-	-	S	-	0,00
P11	Rear Comfort package Plus		●	●	●	●	-	●	1.869,00
			-	-	-	-	-	-	0,00
		Includes codes 447+898	*	*	*	*	*	*	
		Not in conjunction with 224	*	*	*	*	*	*	
		Only in conjunction with P08	*	*	*	*	*	*	
		i.V.m. Code PYQ	○	○	○	○	-	○	0,00
77B	MBUX Interior Assistant		●	●	●	●	●	●	315,00
		Not in conjunction with 811	*	*	*	*	*	*	
		Only in conjunction with 810					*	*	
		i.V.m. Code PAU	○	○	○	○	○	○	0,00
L3B	Multifunction sports steering wheel in nappa leather		S	S	S	○	S	-	0,00
		Not in conjunction with L3D					*		
L3D	Wood/leather multifunction steering wheel		●	●	●	●	●	-	619,50
		Not in conjunction with H31/H35/L3B			*	*	*		
		Only in conjunction with [H22/H31/H34]	*	*	*	*	*	*	
L5C	Multifunction sports steering wheel in nappa leather		○	○	○	○	-	-	0,00
		Available only as part of (P31)	*	*	*	*	*	*	
		Not in conjunction with 443/R66/U12	*	*	*	*	*	*	
		Not in conjunction with 94R/95R/R33/R76				*			
		Not in conjunction with R02	*	*					
		Only in conjunction with P31+U26	*	*	*	*	*	*	
		Only in conjunction with [RPA/RPB/RPQ/RWF/RWH]	*	*	*				
U88	AMG steering wheel buttons		-	-	-	-	-	●	367,50
		Not in conjunction with 443						*	
		i.V.m. Code PYB	-	-	-	-	-	○	0,00
301	Ashtray insert for cup holder		●	●	●	●	●	●	47,25
307	Temperature-controlled cup holder in the rear		●	●	●	●	-	●	220,50
			-	-	-	-	S	-	0,00
		Not in conjunction with 224	*	*	*	*	*	*	
		Only in conjunction with P08+P11	*	*	*	*	*	*	
		standard equipment in certain countries						*	
311	Temperature-controlled cup holder		●	●	●	●	●	●	220,50
			-	-	-	-	-	-	0,00
		standard equipment in certain countries							
		i.V.m. Code PYB	-	-	-	-	○	-	0,00

		i.V.m. Code PYO	○	○	○	○	-	○	0,00
B65	Holder for champagne flutes		-	-	-	-	●	-	840,00
		Only in conjunction with 224+308					*		
735	Exclusive trim package		●	●	●	●	-	●	472,50
			-	-	-	-	S	-	0,00
		Not in conjunction with H46/H64	*	*	*	*		*	
H18	High-gloss anthracite lime wood trim		S	S	S	S	-	S	0,00
		Not in conjunction with L3D	*	*	*	*			
		Not in conjunction with L6H						*	
H22	Brown open-pore walnut wood trim		●	●	●	●	-	●	168,00
			-	-	-	-	○	-	0,00
		Not in conjunction with L6H						*	
		i.V.m. Code P22	○	○	○	○	-	-	0,00
H31	Anthracite open-pore oak wood trim elements		●	●	●	●	-	●	168,00
			-	-	-	-	S	-	0,00
		Not in conjunction with L3D						*	
		Only in conjunction with L38						*	
		i.V.m. Code P22	○	○	○	○	-	-	0,00
H46	Brushed aluminium trim with light longitudinal grain		○	○	○	○	-	○	0,00
		Not in conjunction with 735	*	*	*	*		*	
		Not in conjunction with L3D	*	*	*	*			
		Not in conjunction with L6H						*	
H64	Metal-weave trim		●	●	●	●	-	●	199,50
		Not in conjunction with 735	*	*	*	*		*	
		Not in conjunction with L3D	*	*	*	*			
		Not in conjunction with L6H						*	
		only in conjunction with 876	*	*	*	*			
		i.V.m. Code P22	○	○	○	○	-	-	0,00
H86	AMG carbon-fibre trim		●	●	●	●	-	●	1.837,50
		Not in conjunction with L3D	*	*	*	*			
551A	black		-	-	-	-	-	●	2.100,00
		Not in conjunction with 55U/U09						*	
		Only in conjunction with U38						*	
851A	black		-	-	-	-	-	S	0,00
		Not in conjunction with 55U						*	
854A	truffle brown / black		-	-	-	-	-	●	367,50
		Not in conjunction with 55U						*	
561A	black		-	-	-	-	-	●	2.730,00
		Not in conjunction with 55U/U09						*	
		Only in conjunction with U38						*	
565A	macchiato beige / black		-	-	-	-	-	●	2.730,00
		Not in conjunction with 51U/58U/U09						*	
		Only in conjunction with U38						*	
554A	truffle brown / black		-	-	-	-	-	●	2.467,50
		Not in conjunction with 55U/U09						*	
		Only in conjunction with U38						*	
201A	black		●	●	●	-	-	-	0,00
201A	black		-	-	-	S	-	-	0,00
201A		Not in conjunction with 55U	*	*	*	*			
201A		i.V.m. Code P22	○	○	○	-	-	-	0,00
215A	macchiato beige / black	Delta due to 201A	●	●	●	-	-	-	367,50
215A	macchiato beige / black		-	-	-	●	-	-	367,50
215A		Not in conjunction with 58U/61U	*	*	*	*			
215A		i.V.m. Code P22	●	●	●	-	-	-	367,50
951A	black		●	●	●	-	-	-	3.885,00
			-	-	-	●	-	-	1.837,50
			-	-	-	-	S	-	0,00
		Not in conjunction with 55U/58U/U08	*	*	*	*			
		Not in conjunction with 65U/75U/79U						*	
		Not in conjunction with 873	*	*	*				
		Only in conjunction with 293	*	*	*	*	*		
		Only in conjunction with 902	*	*	*				
		Only in conjunction with U38						*	
		i.V.m. Code P22	●	●	●	-	-	-	1.837,50
954A	mahogany brown / macchiato beige		-	-	-	-	●	-	367,50
		Not in conjunction with 61U/71U/79U						*	
		Only in conjunction with 293+U38						*	
959A	crystal white / silver grey pearl		-	-	-	-	●	-	14.175,00

		Not in conjunction with 61U/65U/71U/75U					*		
		Only in conjunction with 293+543+79U+PBE+U38+U61					*		
214A	espresso brown / black	Delta due to 201A	●	●	●	-	-	-	367,50
214A	espresso brown / black		-	-	-	●	-	-	367,50
214A		Not in conjunction with 55U	*	*	*	*			
214A		i.V.m. Code P22	●	●	●	-	-	-	367,50
284A	truffle brown / black	Delta due to 201A	●	●	●	-	-	-	367,50
284A	truffle brown / black		-	-	-	●	-	-	367,50
284A		Not in conjunction with 55U	*	*	*	*			
284A		i.V.m. Code P22	●	●	●	-	-	-	367,50
P22	EXCLUSIVE interior		●	●	●	-	-	-	2.598,75
			-	-	-	●	-	-	708,75
		Includes codes 201A [214A/215A/284A/951A]+876+901+H22 [H18/H31/H34/H35/H46/H64/H86]+U09+U1	*	*	*	*			
		Not in conjunction with 111A/134A/135A	*	*	*				
		Not in conjunction with U08	*	*	*	*			
		i.V.m. Code PYB	●	●	●	●	-	-	640,50
P31	AMG Line		●	●	●	-	-	-	4.147,50
			-	-	-	●	-	-	3.780,00
		Includes codes 772+L5C [L3B/L3D]+RWF [RPA/RPB/RPO/RWH]	*	*	*	*			
		Not in conjunction with 94R/95R/R33/R76				*			
		Not in conjunction with R02	*	*					
		Not in conjunction with R66/U12	*	*	*	*			
		Only in conjunction with U26	*	*	*	*			
		Only in conjunction with [RPA/RPB/RPO/RWF/RWH]	*	*	*				
		i.V.m. Code PYH	○	○	○	○	-	-	0,00
362	Communications module (LTE) for the use of Mercedes		○	○	○	○	○	○	0,00
20U	Pre-installation for car sharing		●	●	●	●	●	●	52,50
		i.V.m. Code PYB	○	○	○	○	○	○	0,00
33U	Remote Services Plus		●	●	●	●	●	●	157,50
		Not in conjunction with 34U	*	*	*	*	*	*	
34U	Remote Services Premium		●	●	●	●	●	●	262,50
		Not in conjunction with 33U	*	*	*	*	*	*	
		Only for left hand drive				*			
		i.V.m. Code PYB	○	○	○	○	○	○	0,00
351	Mercedes-Benz emergency call system		○	○	○	○	○	○	0,00
00B	Owner's Manual and Service Booklet - Danish		○	○	○	○	○	○	0,00
00U	Remote Services		-	-	-	-	●	-	105,00
01B	Owner's Manual and Service Booklet - Dutch		○	○	○	○	○	○	0,00
02B	Owner's Manual and Service Booklet - German		○	○	○	○	○	○	0,00
03B	Owner's Manual and Service Booklet - Russian		○	○	○	○	○	○	0,00
04B	Owner's Manual and Service Booklet - Finnish		○	○	○	○	○	○	0,00
05B	Owner's Manual and Service Booklet - English		○	○	○	○	○	○	0,00
06B	Owner's Manual and Service Booklet - Italian		○	○	○	○	○	○	0,00
07B	Owner's Manual and Service Booklet - French		○	○	○	○	○	○	0,00
08B	Owner's Manual and Service Booklet - Spanish		○	○	○	○	○	○	0,00
09B	Owner's Manual and Service Booklet - Portuguese		○	○	○	○	○	○	0,00
10B	Owner's Manual and Service Booklet - Swedish		○	○	○	○	○	○	0,00
111A	ARTICO man-made leather black		S	S	S	-	-	-	0,00
		Not in conjunction with 292/399/402/406/436/55U/P22	*	*	*				
11B	Owner's Manual and Service Booklet - Arabic		○	○	○	○	○	○	0,00
12B	Owner's Manual and Service Booklet - Engl. USA/CAN		-	-	○	○	○	○	0,00
12U	Preinstallation for Concierge Service		○	○	○	○	○	○	0,00
		for certain countries only	*	*	*	*	*	*	
		only in conjunction with 362	*	*	*	*	*	*	
		standard equipment in certain countries	*	*	*	*	*	*	
134A	ARTICO man-made leather espresso brown / black		●	●	●	-	-	-	367,50
		Not in conjunction with 292/399/436/55U/P22	*	*	*				
135A	ARTICO man-made leather macchiato beige / black		●	●	●	-	-	-	367,50
		Not in conjunction with 292/399/436/58U/61U/P22	*	*	*				
13B	Owner's Manual and Service Booklet - Norwegian		○	○	○	○	○	○	0,00
14B	Owner's Manual and Service Booklet - Greek		○	○	○	○	○	○	0,00
15B	Owner's Manual and Service Booklet - Turkish		○	○	○	○	○	○	0,00
15U	Pre-installation for Mercedes-Benz Link		○	○	○	○	○	○	0,00
16B	Owner's Manual and Service Booklet - Polish		○	○	○	○	○	○	0,00
16U	Apple CarPlay		○	○	○	○	○	○	0,00
		included in configuration of 14U	*	*	*	*			
17B	Owner's Manual and Service Booklet - Czech		○	○	○	○	○	○	0,00
17U	Android Auto		○	○	○	○	○	○	0,00

		included in configuration of 14U		*	*	*	*	*			
18B	Owner's Manual and Service Booklet - Engl. S. Am.			○	○	○	○	○	○		0,00
18U	Baidu Carlife			-	-	○	○	○	○		0,00
		for certain countries only				*	*	*	*	*	
		only in conjunction with 14U				*	*	*	*	*	
19B	Owner's Manual and Service Booklet - French S. Am.			○	○	○	○	○	○		0,00
20B	Owner's Manual and Service Booklet - Spanish S. Am.			○	○	○	○	○	○		0,00
215	Suspension with adaptive damping system			S	S	S	S	S	S		0,00
		Not in conjunction with 490		*	*	*	*	*	*		
		Not in conjunction with B01		*	*						
		for certain countries only		*	*	*	*	*	*	*	
21B	Owner's Manual and Service Booklet - Portug. S. Am.			○	○	○	○	○	○		0,00
22B	Owner's Manual and Service Booklet - Japanese			○	○	○	○	○	○		0,00
22P	Lane Tracking package			●	●	●	●	-	●		819,00
		for certain countries only		*	*	*	*	*	*		
		includes Codes 234+243		*	*	*	*	*	*	*	
		only in conjunction with P49		*	*	*	*	*	*	*	
232	Garage door opener (frequency range 284-390 MHz)			-	-	●	●	●	●		236,25
		for certain countries only				*	*	*	*	*	
		only in conjunction with P49				*	*	*	*	*	
233	Active Distance Assist DISTRONIC			○	○	○	○	○	○		0,00
		Not in conjunction with 234/243/504		*	*	*	*	*	*	*	
		Only in conjunction with 266+273+513+546+K34		*	*	*	*	*	*	*	
		Only in conjunction with K33					*	*	*	*	
		for certain countries only		*	*	*	*	*	*	*	
		Included in configuration of P20/23P		*	*	*	*	*	*	*	
235	Active Parking Assist with PARKTRONIC			○	○	○	○	S	○		0,00
		Available only as part of (P47)					*	*	*	*	
		included in configuration of P44/P47		*	*	*	*	*	*	*	
23B	Owner's Manual and Service Booklet - simpl. Chinese			-	-	○	○	○	○		0,00
241	Power front left seat with memory function			○	○	○	○	○	○		0,00
		Only for right hand drive		*	*	*	*	*	*	*	
		only available as part of (P64)		*	*	*	*	*	*	*	
242	Power front right seat with memory function			○	○	○	○	S	○		0,00
		Available only as part of (P64)		*	*	*	*	*	*	*	
		Only for left hand drive		*	*	*	*	*	*	*	
249	interior mirror and driver's exterior mirror automatica			○	○	○	○	S	○		0,00
		only available as part of (P49)		*	*	*	*	*	*	*	
24B	Owner's Manual and Service Booklet - trad. Chinese			○	○	○	○	○	○		0,00
25B	Owner's Manual and Service Booklet - Korean			○	○	○	○	○	-		0,00
263	Number plate mounting for Asia / Mexico			○	○	○	○	○	○		0,00
264	Number plate mounting for USA/CAN			-	○	○	○	○	○		0,00
		standard equipment in certain countries			*	*	*	*	*	*	
266	Active Steering Assist			○	○	○	○	○	○		0,00
		Not in conjunction with 234/243/504		*	*	*	*	*	*	*	
		for certain countries only		*	*	*	*	*	*	*	
		included in configuration of P20/23P		*	*	*	*	*	*	*	
26B	Owner's Manual and Service Booklet - Chinese Taiwan			○	○	○	-	○	○		0,00
270	GPS aerial			S	S	S	S	S	S		0,00
273	Exit warning function			○	○	○	○	○	○		0,00
		included in configuration of 233/234		*	*	*	*	*	*	*	
274	Telephone aerial			○	○	○	○	○	○		0,00
		Only for left hand drive				*	*	*	*	*	
		included in configuration of 380/899/B24		*	*	*	*	*	*	*	
275	Driver's seat, electrically adjustable with memory func			●	●	●	-	-	-		845,25
				-	-	-	S	S	S		0,00
		Available only as part of (P64)		*	*	*	*	*	*	*	
		only in conjunction with P49		*	*	*	*	*	*	*	
		i.V.m. Code P64		○	○	○	-	-	-		0,00
27B	Owner's Manual and Service Booklet - Spanish Mexico			-	-	○	○	○	-		0,00
30B	Owner's Manual and Service Booklet - Slovenian			○	○	○	○	○	○		0,00
31B	Owner's Manual and Service Booklet - Hungarian			○	○	○	○	○	○		0,00
32B	Owner's Manual and Service Booklet - Bulgarian			○	○	○	○	○	○		0,00
33B	Owner's Manual and Service Booklet - Romanian			○	○	○	○	○	○		0,00
34B	Owner's Manual and Service Booklet - Croatian			○	○	○	○	○	○		0,00
35B	Owner's Manual and Service Booklet - Latvian			○	○	○	○	○	○		0,00
367	Preinstallation for Live Traffic Information			○	○	○	○	○	○		0,00
		for certain countries only		*	*	*	*	*	*	*	

		only in conjunction with 362	*	*	*	*	*	*				
36B	Owner's Manual and Service Booklet - Lithuanian		○	○	○	○	○	○				0,00
37B	Owner's Manual and Service Booklet - Slovakian		○	○	○	○	○	○				0,00
37U	Advanced connectivity Plus		●	●	●	●	●	●				157,50
38B	Owner's Manual and Service Booklet - Estonian		○	○	○	○	○	○				0,00
		Only for left hand drive				*						
39B	Owner's Manual and Service Booklet - Serbian		○	○	○	○	○	○				0,00
40B	Owner's Manual and Service Booklet - ukrainian		○	○	○	○	○	○				0,00
41B	Owner's Manual and Service Booklet - hebrew		○	○	○	○	○	○				0,00
42B	Owner's Manual and Service Booklet - Indonesian		○	○	○	○	○	○				0,00
436	Comfort front head restraints		○	○	○	○	○	○				0,00
		Not in conjunction with 111A/134A/135A/873/U22	*	*	*							
		Only in conjunction with [241/242]+399+401+902	*	*	*							
		included within: 399	*	*	*	*						
43B	Owner's Manual and Service Booklet - Thai		○	○	○	○	○	○				0,00
44B	Owner's Manual and Service Booklet - Vietnamese		○	○	○	○	○	○				0,00
460	Canada specification		-	-	○	○	○	○				0,00
461	Instrument display in miles with English lettering		○	○	○	○	○	○				0,00
		standard equipment in certain countries	*	*	*	*	*	*	*			
477	Tyre pressure loss warning system		○	○	○	○	○	-				0,00
494	USA specification		-	-	○	○	○	○				0,00
496	Mexico version		-	-	○	○	○	-				0,00
498	Japan specification		○	○	-	○	○	○				0,00
500	Electrically folding exterior mirrors		○	○	○	○	○	○				0,00
		included in configuration of P49	*	*	*	*						
501	360° camera		○	○	○	○	○	S	○			0,00
		Available only as part of (P47)	*	*	*	*	*		*			
		Not in conjunction with 218/P44	*	*	*							
		Only in conjunction with P47	*	*	*							
		included in configuration of P47	*	*	*	*						
		only in conjunction with 249	*	*	*	*						
517	HD digital radio standard		-	-	○	○	○	○				0,00
		standard equipment in certain countries			*	*	*	*	*			
524	Transport protection (full body cover)		●	●	●	●	●	●				168,00
		Not in conjunction with C30						*				
		for certain countries only	*	*	*	*						
		i.V.m. Code C19/C21/C22/C24	-	-	-	-	○	-				0,00
		i.V.m. Code C25/C30	-	-	-	-	○	-				0,00
536	Radio: SIRIUS/SDARS ex factory		-	-	●	●	●	●				462,00
		for certain countries only			*	*	*	*	*			
546	Active Speed Limit Assist		○	○	○	○	○	○				0,00
		Not in conjunction with 234/243/504	*	*	*	*	*		*			
		Only in conjunction with 233+266+273+513+K34	*	*	*	*	*		*			
		Only in conjunction with K33				*		*				
		for certain countries only	*	*	*	*						
		included in configuration of (P20/23P)+513	*	*	*	*						
548	MBUX multimedia system		S	S	S	S	S	S	S			0,00
		Not in conjunction with 549/864/865/866/PAU/PBP/PBR/U19	*	*	*	*	*	*				
		not in conjunction with 21U	*	*	*	*						
549	MBUX multimedia system		○	○	○	○	○	○				0,00
		Not in conjunction with 548	*	*	*	*	*					
		Only in conjunction with 256							*			
		only in conjunction with U19/864/865/21U/PBP/PBR	*	*	*	*						
		standard equipment in certain countries	*	*	*	*						

		i.V.m. Code 640	-	-	○	○	○	○	○	0,00
623	Gulf States specification		-	-	○	○	○	○	○	0,00
625	Australia specification		-	○	○	○	○	○	○	0,00
631	LED High Performance headlamp		○	○	○	-	-	-	-	0,00
632	LED High Performance headlamps		○	○	○	-	-	-	-	0,00
		standard equipment in certain countries	*	*	*					
634	Omission of first-aid kit		○	○	○	○	○	○	○	0,00
		for certain countries only	*	*	*	*	*	*	*	
636	Omission of hazard warning triangle		-	-	○	○	○	○	○	0,00
		for certain countries only			*	*	*	*	*	
640	LED High Performance headlamps with active light fun		-	-	○	S	○	○	○	0,00
		for certain countries only			*	*	*	*	*	
		included in configuration: 608			*	*	*	*	*	
		standard equipment in certain countries			*		*	*	*	
641	MULTIBEAM LED		●	●	●	-	-	-	-	1.365,00
			-	-	-	S	S	○	○	0,00
		for certain countries only	*	*	*	*	*	*	*	
		included in configuration: 628	*	*	*				*	
		standard equipment in certain countries	*	*	*				*	
645	M+S winter tyres, set of 4		-	-	-	-	●	-	-	204,75
		Not in conjunction with R01/R06/R65					*			
		Only in conjunction with R63					*			
666	Freight packaging without tie-down hooks		○	○	○	○	○	○	○	0,00
		for certain countries only	*	*	*	*	*	*	*	
668	Freight packaging with tie-down hooks		●	●	●	●	●	●	●	0,00
668		for certain countries only	*	*	*	*	*	*	*	
668		not in conjunction with 666	*	*	*	*	*	*	*	
687	Model year on model plate		○	○	○	○	○	○	○	0,00
		standard equipment in certain countries	*	*	*	*	*	*	*	
695	Product protection rim		-	-	-	-	○	-	-	0,00
6U8	Location and tracking system		-	●	●	-	-	-	-	336,00
		for certain countries only		*	*					
		only in conjunction with code P54/P82		*	*					
762	Remote control unit		○	○	○	○	○	○	○	0,00
		standard equipment in certain countries	*	*	*	*	*	*	*	
763	Radio remote control with panic switch		○	○	○	○	○	○	○	0,00
		for certain countries only	*	*	*	*	*	*	*	
		only in conjunction with 551	*	*	*	*	*	*	*	
772	AMG bodystyling		○	○	○	○	-	S	S	0,00
		Available only as part of (P31)	*	*	*	*				
		Not in conjunction with 94R/95R/R33/R76				*				
		Not in conjunction with R02	*	*						
		Not in conjunction with R66/U12	*	*	*	*				
		Only in conjunction with P31+U26	*	*	*	*				
		Only in conjunction with [RPA/RPB/RPQ/RWF/RWH]	*	*	*					
79B	Preinstallation for digital radio		○	○	○	○	○	○	○	0,00
		included in configuration of code 537	*	*	*	*	*	*	*	
		standard equipment in certain countries	*	*	*	*	*	*	*	
801	Technical modifications		○	○	○	○	○	○	○	0,00
820	Tourist vehicle		○	○	○	○	○	○	○	0,00
821	Country code Brazil		-	○	○	-	○	○	○	0,00
822	South Africa specification		○	○	○	○	○	○	○	0,00
823	Indicator plate fixing Switzerland		○	○	○	○	○	○	○	0,00
824	Additional parts for cold countries (engine air intake s		○	○	○	-	-	-	-	0,00
		for certain countries only	*	*	*					
829	Taiwan version		○	○	○	-	○	○	○	0,00
830	China specification		-	-	○	○	○	○	○	0,00
831	Italy specification		○	○	○	○	○	○	○	0,00
834	New Zealand specification		-	○	-	○	○	○	○	0,00
835	South Korea specification		○	○	○	○	○	○	-	0,00
852	Sensor system for anti-theft alarm system		-	-	●	●	●	●	●	147,00
		for certain countries only			*	*	*	*	*	
		only in conjunction with code 551			*	*	*	*	*	
855	Telephony in the rear		●	●	●	-	●	●	●	997,50
866	Preinstallation for entertainment and comfort features		●	●	●	●	●	●	●	178,50
		Not in conjunction with 548	*	*	*	*	*	*	*	
		Only in conjunction with 256							*	
		Only in conjunction with 549+864	*	*	*	*	*	*	*	

		i.V.m. Code 864	○	○	○	○	○	○	0,00
871	HANDS-FREE ACCESS		○	○	○	○	○	○	0,00
		included in configuration of P17	*	*	*	*	*	*	
882	Interior monitoring system		○	○	○	○	○	○	0,00
		for certain countries only	*	*	*	*	*	*	
		included in configuration of P54	*	*	*	*	*	*	
885	Increased anti-theft protection		●	●	●	—	●	●	63,00
		for certain countries only	*	*	*	*	*	*	
889	KEYLESS-GO		○	○	○	S	S	S	0,00
		included in configuration of P17	*	*	*	*	*	*	
902	Seat heating Plus for driver and front passenger seats		○	○	○	○	○	○	0,00
		Not in conjunction with 873	*	*	*	*	*	*	
		included in configuration of P69/399	*	*	*	*	*	*	
906	Armrest heating for driver and front passenger		○	○	○	○	○	○	0,00
		Available only as part of (P69)	*	*	*	*	*	*	
		Not in conjunction with 873	*	*	*	*	*	*	
		Only in conjunction with P69	*	*	*	*	*	*	
907	Cushions in rear heated		○	○	○	○	○	○	0,00
		Available only as part of (P69)	*	*	*	*	*	*	
		Not in conjunction with 873	*	*	*	*	*	*	
		Only in conjunction with P69	*	*	*	*	*	*	
913	Air conditioning preinstallation for hot countries		○	○	○	○	○	○	0,00
		standard equipment in certain countries	*	*	*	*	*	*	
926	Emission control system with EU4 technology		—	—	○	○	○	○	0,00
		for certain countries only	*	*	*	*	*	*	
927	EU6 emissions standard		○	○	○	○	○	○	0,00
		for certain countries only	*	*	*	*	*	*	
93B	Integrated Starter Generator Generation 1		—	—	S	S	S	S	0,00
940	ABGASREINIGUNG EURO 7 TECHNIK (ROW-GSP)		—	—	○	—	—	—	0,00
943	Toll payment system		●	●	●	●	●	●	262,50
945	Emission control system China		—	—	○	—	○	—	0,00
94B	Integrated Starter Generator Generation 2		—	—	○	—	—	—	0,00
961	Petrol particulate filter		—	—	○	—	○	○	0,00
		standard equipment in certain countries	*	*	*	*	*	*	
968	COC document EU6 without registration certificate part 1		○	○	○	○	○	○	0,00
		standard equipment in certain countries	*	*	*	*	*	*	
969	COC document EU6 with registration certificate part 2		○	○	○	○	○	○	0,00
		standard equipment in certain countries	*	*	*	*	*	*	
971	Diesel particulate filter		○	○	—	—	—	—	0,00
973	Designation as owner-driver rental vehicle		○	○	○	○	○	○	0,00
981	Omission of vehicle registration document		○	○	○	○	○	○	0,00
986	Identification label with VIN number		○	○	○	○	○	○	0,00
989	Identification label under windshield		○	○	○	○	○	○	0,00
997	Exhibition vehicle		○	○	○	○	○	○	0,00
B01	EQ Boost starter-alternator		○	○	S	S	S	S	0,00
		Not in conjunction with 215	*	*	*	*	*	*	
		Only in conjunction with 481+490	*	*	*	*	*	*	
		48V Technology	*	*	*	*	*	*	
B08	Fanfare horn Asia		○	○	○	○	○	○	0,00
		standard equipment in certain countries	*	*	*	*	*	*	
B16	Two-pipe exhaust system		—	—	○	S	S	S	0,00
		Not in conjunction with 669/690/811/B12	*	*	*	*	*	*	
		Only in conjunction with U68	*	*	*	*	*	*	
		included in configuration of U68	*	*	*	*	*	*	
E07	Positioning and Tracking System		—	●	●	●	●	●	336,00
		for certain countries only	*	*	*	*	*	*	
		only in conjunction with P54/P82	*	*	*	*	*	*	
K32	Active Lane Change Assist		○	○	○	○	○	○	0,00
		for certain countries only	*	*	*	*	*	*	
		included in configuration of P20/23P	*	*	*	*	*	*	
K33	Extended automatic Re-start in traffic jams		○	○	○	○	○	○	0,00
		Not in conjunction with 234/243/504	*	*	*	*	*	*	
		Only in conjunction with 233+266+273+513+546+K34	*	*	*	*	*	*	
		for certain countries only	*	*	*	*	*	*	
		included in configuration of P20/23P	*	*	*	*	*	*	
K34	Route-based speed adaptation		○	○	○	○	○	○	0,00
		Not in conjunction with 234/243/504	*	*	*	*	*	*	
		Only in conjunction with 233+266+273+513+546	*	*	*	*	*	*	

		Only in conjunction with K33				*		*	
		for certain countries only	*	*	*	*	*	*	
		included in configuration of P20/23P	*	*	*	*	*	*	
L	Left-hand drive		○	○	○	○	○	○	0,00
P08	Rear Comfort package		○	○	○	○	–	○	0,00
		Includes codes 201A [111A/284A]+226+293+437+72B	*	*	*				
		Includes codes 201A [284A]+226+293+437+72B				*			
		Includes codes 226+293+437+72B						*	
		Not in conjunction with 224	*	*	*	*		*	
		Only in conjunction with P11	*	*	*	*		*	
P53	Fine particle sensor		–	–	●	●	●	●	157,50
		standard equipment in certain countries			*	*	*	*	
P60	AMG Night package		–	–	–	–	–	●	997,50
		Includes codes 840 [U50]						*	
		i.V.m. Code PYB	–	–	–	–	–	●	588,00
PYB	SE Package		–	–	–	–	●	–	0,00
PYB	SE Package		–	–	–	–	–	●	0,00
PYB	SE Package		–	–	–	●	–	–	0,00
PYB	SE Package		●	●	●	–	–	–	0,00
PYH	AMG Line		●	●	●	–	–	–	4.110,00
			–	–	–	●	–	–	3.760,00
PYN	Premium Package		●	●	●	–	–	–	3.972,00
			–	–	–	●	–	–	3.324,00
			–	–	–	–	–	●	2.644,00
PYO	Premium Plus package		●	●	●	–	–	–	7.811,00
			–	–	–	●	–	–	5.554,00
			–	–	–	–	–	●	4.376,00
PYQ	Executive Rear Package		●	●	●	–	–	–	4.225,00
			–	–	–	●	–	●	3.919,00
R	Right-hand drive		●	●	●	●	●	●	1.811,25
R01	Summer tyres		○	○	○	○	○	○	0,00
		Not in conjunction with 645					*		
		Not in conjunction with R02	*	*					
		for certain countries only	*	*	*	*			
R02	All-season tyres		○	○	○	○	–	–	0,00
		Not in conjunction with L5C/P31/P55/R01/R06/U26/U28/U50	*	*					
		Only in conjunction with [36R/65R]	*	*					
		for certain countries only	*	*	*	*			
R06	Noise reduced tyre with foam absorber		○	○	○	○	S	–	0,00
		Not in conjunction with 36R/65R	*	*	*				
		Not in conjunction with 645					*		
		Not in conjunction with R02	*	*					
		Not in conjunction with R66	*	*	*	*			
		only in conjunction with PAF+R01+(94R/95R/R33/R76/RPA/RPB/RPO/RWF/RWH)	*	*	*	*			
U01	Rear belt status indication in the instrument display		○	○	○	○	○	○	0,00
		for certain countries only	*	*	*	*	*	*	
		standard equipment in certain countries	*	*	*	*	*	*	
U08	Upper part of dashboard in ARTICO man-made leather		S	S	S	S	–	–	0,00
		Not in conjunction with 951A/P22	*	*	*	*			
U10	Automatic front passenger airbag deactivation		S	S	S	S	S	S	0,00
U22	4-way lumbar support		S	S	S	S	S	S	0,00
		Not in conjunction with 399/436/PBR	*	*	*				
		Only in conjunction with [241/242]	*	*	*				
U79	BlueTEC diesel emission control system including AdB		S	S	–	–	–	–	0,00
U80	115 V socket		–	–	●	●	–	●	115,50
			–	–	–	–	○	–	0,00
		for certain countries only			*	*	*	*	
		standard equipment in certain countries			*	*	*	*	
B12	Tyre-change toolkit		○	○	○	○	○	○	0,00
		Not in conjunction with 811/B51	*	*	*	*		*	
		Not in conjunction with B07						*	
		Not in conjunction with B16			*				
		Not in conjunction with U68	*	*	*	*			
		Only in conjunction with 669+810						*	
682	Fire extinguisher		●	●	●	●	●	●	0,00
70B	Fluorescent jacket for driver		●	●	●	●	●	●	5,25
		Not in conjunction with 71B	*	*	*	*	*	*	
		standard equipment in certain countries	*	*	*	*			



71B	Safety vests for driver and passengers		● ● ● ● ● ● ●	36,75
		Not in conjunction with 70B	* * * * *	
293	Sidebags in rear		● ● ● ● - ●	357,00
			- - - - S -	0,00
		standard equipment in certain countries	* * * * *	
		i.V.m. Code PYQ	○ ○ ○ ○ - ○	0,00
294	Kneebag		○ ○ ○ ○ ○ ○ ○	0,00
258	Active Brake Assist		● ● ● ● ● - ●	0,00
258	Active Brake Assist		- - - - - -	0,00
258		Not in conjunction with 292	* * * * *	
258		Only in conjunction with 243	* * * * *	
292	PRE-SAFE® impulse side		○ ○ ○ ○ ○ ○ ○	0,00
		Not in conjunction with 111A/134A/135A/243	* * * * *	
		Not in conjunction with 234/504	* * * * *	
		Not in conjunction with 23P		*
		Only in conjunction with 23U		* * *
		Only in conjunction with 266+273+513+546+K34	* * * * *	
		Only in conjunction with K33		* * *
		Only in conjunction with P20	* * * * *	
23U	Active Stop-and-Go Assist		○ ○ ○ ○ ○ ○ ○	0,00
		Not in conjunction with 234/504	* * * * *	
		Not in conjunction with 23P		*
		Only in conjunction with 266+273+513+546+K33+K34	* * * * *	
		Only in conjunction with 292		* * *
		Only in conjunction with P20	* * * * *	
		for certain countries only	* * * * *	
		included in configuration of P20	* * * * *	
		only in conjunction with 233 292	* * * * *	
234	Blind Spot Assist		● ● ● ● - ●	472,50
			- - - - ○ -	0,00
		Not in conjunction with 233/23P/23U/266/292/546/K33/K34/P20	* * * * *	
		Only in conjunction with 243+273	* * * * *	
		i.V.m. Code 22P	○ ○ ○ ○ - ○	0,00
		i.V.m. Code PYB	- - - ○ - ○	0,00
239	Active Distance Assist DISTRONIC		● ● ● ● - ●	945,00
			- - - - ○ -	0,00
		Not in conjunction with 292	* * *	
		Only in conjunction with 243	* * * * *	
23P	Driving Assistance package		● ● ● ● - ●	2.026,50
			- - - - S -	0,00
		Includes codes 233	* * * * *	
		Not in conjunction with 234/504	* * * * *	
		Not in conjunction with 23U/P20		*
		Not in conjunction with 292	* * *	*
		Only in conjunction with 266+273+513+546+K34	* * * * *	
		Only in conjunction with K33		* * *
		i.V.m. Code PYN	○ ○ ○ ○ - ○	0,00
243	Active Lane Keeping Assist		● ● ● ● ● - ●	0,00
243		Not in conjunction with 233/266/546/K33/K34	* * * * *	
243		Not in conjunction with 292	* * *	
243		i.V.m. Code 22P	○ ○ ○ ○ - ○	0,00
475	Tyre pressure monitoring system		● ● ● ● ● ● ●	320,25
		i.V.m. S-Code 6P5	○ ○ ○ ○ ○ ○ ○	0,00
504	Speed Limit Assist		○ ○ ○ ○ ○ ○ ○	0,00
		Not in conjunction with 233/23P/23U/266/292/513/546/K33/K34/P20	* * * * *	
		Only in conjunction with 243	* * * * *	
513	Traffic Sign Assist		● ● ● ● ● ● ●	309,75
			- - - - - -	0,00
		Not in conjunction with 504	* * * * *	
		for certain countries only	* * * * *	
		standard equipment in certain countries		
		i.V.m. S-Code 51B	● ● ● ● ● ● ●	157,50
		i.V.m. Code 23P	○ ○ ○ ○ ○ ○ ○	0,00
		i.V.m. Code 546	○ ○ ○ ○ ○ ○ ○	0,00
		i.V.m. Code P20	○ ○ ○ ○ ○ ○ ○	0,00
		i.V.m. Code PYB	○ ○ ○ ○ ○ ○ ○	0,00
P20	Driving Assistance package Plus		● ● ● ● - ●	2.551,50
			- - - - - ● -	525,00

		Includes codes 233	*	*	*	*	*	*	*	
		Not in conjunction with 234/504	*	*	*	*	*	*	*	
		Not in conjunction with 23P						*		
		Only in conjunction with 23U+292					*	*	*	
		Only in conjunction with 266+273+513+546+K34	*	*	*	*	*	*	*	
		Only in conjunction with K33				*		*		
		i.V.m. Code PYB	-	-	-	-	○	-		0,00
		i.V.m. Code PYO	○	○	○	○	-	○		0,00
218	Reversing camera		S	S	S	S	-	S		0,00
		Available only as part of (P44)	*	*	*					
		Not in conjunction with 501/553/P47	*	*	*					
		Only in conjunction with P44	*	*	*					
553	Trailer Manoeuvring Assist		●	●	●	●	●	●		367,50
		Not in conjunction with 218/P44	*	*	*					
		Only in conjunction with 550+557	*	*	*	*	*	*		
		Only in conjunction with P47	*	*	*					
		for certain countries only	*	*	*	*				
P44	Parking package with reversing camera		○	○	○	○	-	○		0,00
P44		Includes codes 218+235	*	*	*					
P44		Not in conjunction with 501/553/P47	*	*	*					
P47	Parking Package with 360-degree camera		●	●	●		-	-	●	378,00
			-	-	-	-		●	-	0,00
			-	-	-	-	S	-		0,00
		Includes codes 235+501	*	*	*	*	*	*	*	
		Not in conjunction with 218/P44	*	*	*					
		i.V.m. Code PYB	-	-	-	-	-	○		0,00
		i.V.m. Code PYN/PYO	○	○	○	○	-	-		0,00
915	Fuel tank with a capacity of 90 litres		S	S	S	S	S	S		0,00
U28	Braking system with larger brake disks on the front ax		●	●	●	●	-	-		262,50
		Not in conjunction with 36R/65R	*	*	*					
		Not in conjunction with 690	*	*	*	*				
		Not in conjunction with R02	*	*						
		i.V.m. Code PYH	○	○	○	○	-	-		0,00
U68	Sporty engine sound		●	●	●	●	-	-		367,50
		Not in conjunction with 669/690/811/B12	*	*	*	*				
		Only in conjunction with B16				*				
489	AIRMATIC package		S	S	S	S	S	S	-	0,00
489	AMG RIDE CONTROL+		-	-	-	-	-	S		0,00
490	E-ACTIVE BODY CONTROL		●	●	●	●	●	-		6.825,00
		Not in conjunction with 215	*	*	*	*	*			
		Only in conjunction with 481	*	*	*	*	*			
		Only in conjunction with B01	*	*						
		for certain countries only	*	*	*	*	*			
		includes code 481	*	*	*	*	*			
430	Off-Road Engineering package		●	●	●	●	-	-		1.995,00
		Includes codes 481	*	*	*	*				
481	Underguard		●	●	●	●	●	-		136,50
		i.V.m. Code 430/490	○	○	○	○	○	-		0,00
421	9G-TRONIC		S	S	S	S	S	S	-	0,00