

Model year :	801
Sales Release :	2020-10-20
Production Change :	2020-09-01
Legend	<p>(*) Available at extra cost (○) available without additional charge (S) standard equipment (-) not available (L) Left hand drive only (R) Right hand drive only (NS) National Standard *+ AND (code</p> <p>Please note that central restrictions are displayed. Markets may have specific deviation if any. Codes could be valid for certain countries only.</p>

			S-Class					Long-wheelbase S-Class					
Code	equipment	Restrictions	223030 S 350 d	223031 S 350 d 4MATIC	223033 S 400 d 4MATIC	223061 S 450 4MATIC	223063 S 500 4MATIC	223130 S 350 d	223131 S 350 d 4MATIC	223133 S 400 d 4MATIC	223161 S 450 4MATIC	223163 S 500 4MATIC	LLP
P34	Exclusive package		●	●	●	●	●	●	●	●	●	●	6.037,50
		Includes codes 501A [504A/505A/507A/508A]+735+U25	*	*	*	*	*	*	*	*	*	*	
		Not in conjunction with 51U/55U/58U/B13	*	*	*	*	*	*	*	*	*	*	
		Only in conjunction with [501A/504A/505A/507A/508A]	*	*	*	*	*	*	*	*	*	*	
		includes B05	*	*	*	*	*	*	*	*	*	*	
		only in conjunction with 223+540	*	*	*	*	*	*	*	*	*	*	
		i.V.m. Code PWS	●	●	●	●	●	●	●	●	●	●	5.880,00
		i.V.m. Code PYB	●	●	●	●	●	●	●	●	●	●	5.880,00
		i.V.m. Code 950/951	●	●	●	●	●	●	●	●	●	●	5.670,00
		i.V.m. Code PWS+950	●	●	●	●	●	●	●	●	●	●	5.512,50
		i.V.m. Code PYB+PYH	●	●	●	●	●	●	●	●	●	●	5.512,50
		i.V.m. Code PYO/PYS	●	●	●	●	●	●	●	●	●	●	4.042,50
		i.V.m. Code PYO/PYS+PYH	●	●	●	●	●	●	●	●	●	●	3.675,00
P55	Night package		●	●	●	●	●	●	●	●	●	●	787,50
		Not in conjunction with 550/L2B/U04/U12	*	*	*	*	*	*	*	*	*	*	
		Only in conjunction with 950+[RRG/RVQ/RVR/RVU/RVV/RWK/RWN/RZI]	*	*	*	*	*	*	*	*	*	*	
		i.V.m. Code PYH	●	●	●	●	●	●	●	●	●	●	378,00
260	Omission of model plate on boot lid		○	○	○	○	○	○	○	○	○	○	0,00
231	Garage door opener		●	●	●	●	●	●	●	●	●	●	236,25
		only in conjunction with 249	*	*	*	*	*	*	*	*	*	*	
871	HANDS-FREE ACCESS		○	○	○	○	○	○	○	○	○	○	0,00
		Only in conjunction with 282+7B8+881+942+U35	*	*	*	*	*	*	*	*	*	*	
881	Remote boot lid closing		○	○	○	○	○	○	○	○	○	○	0,00
		Only in conjunction with 282+7B8+871+942+U35	*	*	*	*	*	*	*	*	*	*	
883	Power closing		S	S	S	S	S	S	S	S	S	S	0,00
889	KEYLESS-GO with flush-fitting door handles		●	●	●	●	●	●	●	●	●	●	1.260,00
		Only in conjunction with 7B8	*	*	*	*	*	*	*	*	*	*	
		i.V.m. Code PWS	○	○	○	○	○	○	○	○	○	○	0,00
		i.V.m. Code PYB	○	○	○	○	○	○	○	○	○	○	0,00
B67	Vehicle key in high-gloss black with ornamental surround		●	●	●	●	●	●	●	●	●	●	105,00
		Not in conjunction with B68	*	*	*	*	*	*	*	*	*	*	
		not available in conjunction with 494/460/737L	*	*	*	*	*	*	*	*	*	*	
B68	Vehicle key in high-gloss white with ornamental surround		●	●	●	●	●	●	●	●	●	●	105,00
		Not in conjunction with B67	*	*	*	*	*	*	*	*	*	*	
799U	designo diamond white bright		●	●	●	●	-	●	●	●	●	-	1.816,50
			-	-	-	-	●	-	-	-	-	●	777,00
197U	obsidian black		●	●	●	●	-	●	●	●	●	-	1.039,50
			-	-	-	-	○	-	-	-	-	○	0,00
346U	onyx black		●	●	●	●	-	●	●	●	●	-	1.039,50
			-	-	-	-	○	-	-	-	-	○	0,00
660U	rubellite red		●	●	●	●	-	●	●	●	●	-	1.039,50
			-	-	-	-	○	-	-	-	-	○	0,00
		not in conjunction with upholstery 204A/504A/804A	*	*	*	*	*	*	*	*	*	*	
831U	graphite grey		●	●	●	●	-	●	●	●	●	-	1.039,50
			-	-	-	-	○	-	-	-	-	○	0,00
859U	Mojave silver		●	●	●	●	-	●	●	●	●	-	1.039,50
			-	-	-	-	○	-	-	-	-	○	0,00
922U	high-tech silver		●	●	●	●	-	●	●	●	●	-	1.039,50
			-	-	-	-	○	-	-	-	-	○	0,00
989U	emerald green		●	●	●	●	-	●	●	●	●	-	1.039,50
			-	-	-	-	○	-	-	-	-	○	0,00
		not in conjunction with 507A	*	*	*	*	*	*	*	*	*	*	
992U	selenite grey		●	●	●	●	-	●	●	●	●	-	1.039,50
			-	-	-	-	○	-	-	-	-	○	0,00
998U	anthracite blue		●	●	●	●	-	●	●	●	●	-	1.039,50
			-	-	-	-	○	-	-	-	-	○	0,00
		not in conjunction with 507A	*	*	*	*	*	*	*	*	*	*	

040U	black		○ ○ ○ ● ○ ○ ○ ○ ○ ● ○	0,00
413	Panoramic sliding sunroof		● ● ● ● ● ● ● ● ● ●	1.669,50
		i.V.m. Code PYM/PYN/PYO/PYS	○ ○ ○ ● ○ ○ ○ ○ ○ ○ ○	0,00
318	DIGITAL LIGHT		● ● ● ● ● ● ● ● ● ●	1.984,50
		Not in conjunction with 642	* * * * * * * * * *	
		Only in conjunction with 30U+42U+43U	* * * * * * * * * *	
		i.V.m. Code PYN/PYO/PYS	○ ○ ○ ● ○ ○ ○ ○ ○ ○ ○	0,00
587	Ambient lighting with projection of brand logo		S S S S S S S S S S	0,00
642	MULTIBEAM LED		○ ○ ○ ● ○ ○ ○ ○ ○ ○ ○	0,00
		Not in conjunction with 30U/318/42U/43U	* * * * * * * * * *	
		not in conjunction with 640/641	* * * * * * * * * *	
550	Trailer coupling with ESP[®] trailer stabilis		● ● ● ● ● ● ● ● ● ●	1.197,00
		Not in conjunction with 950/L5C/P55/RRG/RVR/RVV/RWN/RZI/U29	* * * * * * * * * *	
		Not in conjunction with Z87/Z90	* * * * * * * * * *	
		Only in conjunction with 282+7B8+871+881+884+942+U35	* * * * * * * * * *	
596	heat-insulating, noise-insulating and infrared-reflecting		● ● ● ● - ● ● ● ● -	1.207,50
			- - - - S - - - S	0,00
884	Boot lid additional locking device		● ● ● ● ● ● ● ● ● ●	199,50
		Only in conjunction with 282+7B8+871+881+942+U35	* * * * * * * * * *	
885	Increased anti-theft protection		● ● ● ● ● ● ● ● ● ●	94,50
E16	Rim lock set		● ● ● ● ● ● ● ● ● ●	73,50
P54	URBAN GUARD vehicle protection		● ● ● ● ● ● ● ● ● ●	493,50
		Includes codes 551+882	* * * * * * * * * *	
		Not in conjunction with P82	* * * * * * * * * *	
		i.V.m. Code PYB	○ ○ ○ ● ○ ○ ○ ○ ○ ○ ○	0,00
P82	URBAN GUARD vehicle protection Plus		● ● ● ● ● ● ● ● ● ●	756,00
		Includes codes 551+882	* * * * * * * * * *	
		Not in conjunction with P54	* * * * * * * * * *	
		i.V.m. Code PYB	● ● ● ● ● ● ● ● ● ●	262,50
		i.Vm. Code PYM/PYN/PYO/PYS	○ ○ ○ ● ○ ○ ○ ○ ○ ○ ○	0,00
R01	Summer tyres		○ ○ ○ ● ○ ○ ○ ○ ○ ○ ○	0,00
		Not in conjunction with R03	* * * * * * * * * *	
R03	Sports tyres		● ● ● ● ● ● ● ● ● ●	346,50
		Not in conjunction with R01/R66	* * * * * * * * * *	
		Only in conjunction with [10R/15R/77R/R16/R55/R60/R90/RRG/RZI]	* * * * * * * * * *	
		not in conjunction with 498/835	* * * * * * * * * *	
		only in conjunction with R06/R16+R06	* * * * * * * * * *	
R06	Noise reduced tyre with foam absorber		○ ○ ○ ● ○ ○ ○ ○ ○ ○ ○	0,00
		Not in conjunction with 01R/51R	* * * * * * * * * *	
		Not in conjunction with R38	* * * * * * * * * *	
		Not in conjunction with R41	* * * * * * * * * *	
R66	run-flat tyres		● ● ● ● ● ● ● ● ● ●	367,50
		Not in conjunction with 01R/10R/51R/B51/R03/R16/R90/RWK/RWN/RZI	* * * * * * * * * *	
		Not in conjunction with R38	* * * * * * * * * *	
		Not in conjunction with R41	* * * * * * * * * *	
		i.V.m. Code 4R6	● ● ● ● ● ● ● ● ● ●	735,00
RRG	48.3 cm (19-inch) AMG 5-spoke light-alloy wheels		○ ○ ○ ● ○ ○ ○ ○ ○ ○ ○	0,00
		Not in conjunction with 201/218/550/L2B/P44/U04/U12	* * * * * * * * * *	
		Only in conjunction with 216+501+950	* * * * * * * * * *	
		Only for left hand drive	* * * * * * * * * *	
		in conjunction with R03+R06 not with R66	* * * * * * * * * *	
		only in conjunction with R01/R02/R03+R06	* * * * * * * * * *	
RVQ	50.8 cm (20-inch) AMG multi-spoke alloy wheels		● ● - ● - ● ● - ● -	4.357,50
			- - ● - - - - ● - -	3.517,50
			- - - - - - - - - -	2.782,50
			- - - - ● - - - - ●	2.100,00
		Not in conjunction with 216/R03	* * * * * * * * * *	
		Only in conjunction with R01+R06	* * * * * * * * * *	
		i.V.m. Code 950/951	● ● ● ● ● ● ● ● ● ●	1.102,50
RVR	50.8 cm (20-inch) AMG multi-spoke alloy wheels		● ● ● ● ● ● ● ● ● ●	1.417,50
		Not in conjunction with 216/550/8R3/L2B/R03/U04/U12	* * * * * * * * * *	
		Only in conjunction with 950+R01+R06	* * * * * * * * * *	
RVU	50.8 cm (20-inch) AMG multi-spoke alloy wheels		● ● - ● - ● ● - ● -	4.357,50
			- - ● - - - - ● - -	3.517,50
			- - - - - - - - - -	2.782,50
			- - - - ● - - - - ●	2.100,00
		Not in conjunction with 201/218/P44/R03	* * * * * * * * * *	
		Only in conjunction with 216+501+R01+R06	* * * * * * * * * *	
		Only for left hand drive	* * * * * * * * * *	
		i.V.m. Code 950/951	● ● ● ● ● ● ● ● ● ●	1.102,50
RVV	50.8 cm (20-inch) AMG multi-spoke alloy wheels		● ● ● ● ● ● ● ● ● ●	1.417,50
		Not in conjunction with 201/218/550/8R3/L2B/P44/R03/U04/U12	* * * * * * * * * *	
		Only in conjunction with 216+501+950+R01+R06	* * * * * * * * * *	
		Only for left hand drive	* * * * * * * * * *	

RWK	53.3 cm (21-inch) AMG multi-spoke light-alloy wheels		● ● – ● – ● ● – ● –	4.830,00
			– – ● – – – – ● – –	3.990,00
			– – – – – – – – – –	3.255,00
			– – – – ● – – – – ●	2.572,50
		Not in conjunction with 216/R03/R66	* * * * * * * * * *	
		Only in conjunction with R01+R06	* * * * * * * * * *	
		i.V.m. Code 950/951	● ● ● ● ● ● ● ● ● ●	2.205,00
RWN	53.3 cm (21-inch) AMG 5-twin-spoke light-alloy wheels		● ● ● ● ● ● ● ● ● ●	2.520,00
		Not in conjunction with 216/550/L2B/R03/R66/U04/U12	* * * * * * * * * *	
		Only in conjunction with 950+R01+R06	* * * * * * * * * *	
RZI	48.3 cm (19-inch) AMG 5-spoke light-alloy wheels		○ ○ ○ ○ ○ ○ ○ ○ ○ ○	0,00
		Available only as part of (950)	* * * * * * * * * *	
		Not in conjunction with 216/550/L2B/R66/U04/U12	* * * * * * * * * *	
		Only in conjunction with 950	* * * * * * * * * *	
		only in conjunction with R01/R03+R06	* * * * * * * * * *	
01R	45.7 cm (18-inch) 5-twin-spoke light-alloy wheels		● ● – ● – ● ● – ● –	840,00
			– – ○ – ○ – – ○ – ○	0,00
		Not in conjunction with 8R3/950/L5C/P55/R03/R06/R66/U29	* * * * * * * * * *	
		Only in conjunction with R01	* * * * * * * * * *	
		i.V.m. Code PYB	○ ○ – ○ – ○ ○ – ○ –	0,00
10R	48.3 cm (19-inch) multi-twin-spoke light-alloy wheels		● ● – ● – ● ● – ● –	2.415,00
			– – ● – – – – ● – –	1.575,00
			– – – – – – – – – –	840,00
			– – – – ● – – – – ●	157,50
		Not in conjunction with 216/8R3/950/L5C/P55/R66	* * * * * * * * * *	
		only in conjunction with R01/R03+R06	* * * * * * * * * *	
		i.V.m. Code PYB	● ● – ● – ● ● – ● –	1.575,00
		i.V.m. Code PYB	– – – – ○ – – – – ○	0,00
15R	48.3-cm (19-inch) multi-twin-spoke light-alloy wheels		● ● – ● – ● ● – ● –	2.257,50
			– – ● – – – – ● – –	1.417,50
			– – – – – – – – – –	682,50
			– – – – – ○ – – – – ○	0,00
		Not in conjunction with 8R3/950/L5C/P55	* * * * * * * * * *	
		in conjunction with R03+R06 not with R66	* * * * * * * * * *	
		only in conjunction with R01/R02/R03+R06	* * * * * * * * * *	
		i.V.m. Code PYB	● ● – ● – ● ● – ● –	1.417,50
17R	50.8 cm (20-inch) multi-spoke light-alloy wheels		● ● – ● – ● ● – ● –	3.675,00
			– – ● – – – – ● – –	2.835,00
			– – – – – – – – – –	2.100,00
			– – – – ● – – – – ●	1.417,50
		Not in conjunction with 216/8R3/950/L5C/P55/R03	* * * * * * * * * *	
		Only in conjunction with R01+R06	* * * * * * * * * *	
		i.V.m. Code PYB	● ● – ● – ● ● – ● –	2.835,00
		i.V.m. Code PYB	– – – – ● – – – – ●	1.260,00
51R	45.7 cm (18-inch) 10-spoke light-alloy wheels		– – – ● – ○ – ○ ○ ○ – ○	210,00
			○ ○ ○ – ○ ○ ○ ○ – ○	0,00
		Not in conjunction with 8R3/950/L5C/P55/R03/R06/R66/U29	* * * * * * * * * *	
		Only in conjunction with R01	* * * * * * * * * *	
		i.V.m. Code PYB	– – – ○ – – – – ○ –	0,00
60R	50.8 cm (20-inch) multi-spoke light-alloy wheels		● ● – ● – ● ● – ● –	3.517,50
			– – ● – – – – ● – –	2.677,50
			– – – – – – – – – –	1.942,50
			– – – – ● – – – – ●	1.260,00
		Not in conjunction with 8R3/950/L5C/P55/R03	* * * * * * * * * *	
		Only in conjunction with R01+R06	* * * * * * * * * *	
		i.V.m. Code PYB	● ● – ● – ● ● – ● –	2.677,50
77R	48.3 cm (19-inch) 5-twin-spoke light-alloy wheels		● ● – ● – ● ● – ● –	1.575,00
			– – ● – – – – ● – –	735,00
			– – – – ○ – – – – ○	0,00
		Not in conjunction with 8R3/950/L5C/P55	* * * * * * * * * *	
		in conjunction with R03+R06 not with R66	* * * * * * * * * *	
		only in conjunction with R01/R02/R03+R06	* * * * * * * * * *	
		i.V.m. Code PYB	● ● – ● – ● ● – ● –	735,00
R16	48.3-cm (19-inch) multi-twin-spoke light-alloy wheels		● ● – ● – ● ● – ● –	2.415,00
			– – ● – – – – ● – –	1.575,00
			– – – – – – – – – –	840,00
			– – – – ● – – – – ●	157,50
		Not in conjunction with 216/8R3/950/L5C/P55/R66	* * * * * * * * * *	
		only in conjunction with R01/R03+R06	* * * * * * * * * *	
		i.V.m. Code PYB	● ● – ● – ● ● – ● –	1.575,00
		i.V.m. Code PYB	– – – – ○ – – – – ○	0,00
R38	45.7 cm (18-inch) 5-twin-spoke light-alloy wheels		– – – ● – – – – ● –	630,00
			○ ○ – – – ○ ○ ○ – –	0,00
		Not in conjunction with 8R3/950/L5C/P55/R03/R06/R66/U29	* * * * * * * *	

		Only in conjunction with R01	*	*		*		*	*	*	*		
		i.V.m. Code PYB	-	-	-	○	-	-	-	-	○	-	0,00
R41	45.7 cm (18-inch) 10-spoke light-alloy wheels		○	○	-	○	-	○	○	-	○	-	0,00
		Not in conjunction with 8R3/950/L5C/P55/R03/R06/R66/U29				*					*		
		Only in conjunction with R01				*					*		
R42	50.8-cm (20-inch) multi-twin-spoke light-alloy wheels		●	●	-	●	-	●	●	-	●	-	3.202,50
			-	-	●	-	-	-	-	●	-	-	2.362,50
			-	-	-	-	-	-	-	-	-	-	1.627,50
			-	-	-	-	●	-	-	-	-	●	945,00
		Not in conjunction with 8R3/950/L5C/P55/R03	*	*	*	*	*	*	*	*	*	*	
		Only in conjunction with R01+R06	*	*	*	*	*	*	*	*	*	*	
		i.V.m. Code PYB	●	●	-	●	-	●	●	-	●	-	2.362,50
		i.V.m. Code PYB	-	-	-	-	●	-	-	-	-	●	787,50
R51	50.8 cm (20-inch) 10-twin-spoke forged wheels		●	●	-	●	-	●	●	-	●	-	5.460,00
			-	-	●	-	-	-	-	●	-	-	4.620,00
			-	-	-	-	-	-	-	-	-	-	3.885,00
			-	-	-	-	●	-	-	-	-	●	3.202,50
		Not in conjunction with 216/4R5/4R6/8R3/950/L5C/P55/R03	*	*	*	*	*	*	*	*	*	*	
		Only in conjunction with R01+R06	*	*	*	*	*	*	*	*	*	*	
		i.V.m. Code PYB	●	●	-	●	-	●	●	-	●	-	4.620,00
		i.V.m. Code PYB	-	-	-	-	●	-	-	-	-	●	3.045,00
R55	48.3 cm (19-inch) 5-twin-spoke light-alloy wheels		●	●	-	●	-	●	●	-	●	-	2.257,50
			-	-	●	-	-	-	-	●	-	-	1.417,50
			-	-	-	-	-	-	-	-	-	-	682,50
			-	-	-	-	○	-	-	-	-	○	0,00
		Not in conjunction with 8R3/950/L5C/P55	*	*	*	*	*	*	*	*	*	*	
		in conjunction with R03+R06 not with R66	*	*	*	*	*	*	*	*	*	*	
		only in conjunction with R01/R02/R03+R06	*	*	*	*	*	*	*	*	*	*	
		i.V.m. Code PYB	●	●	-	●	-	●	●	-	●	-	1.417,50
R60	48.3-cm (19-inch) multi-twin-spoke light-alloy wheels		●	●	-	●	-	●	●	-	●	-	2.257,50
			-	-	●	-	-	-	-	●	-	-	1.417,50
			-	-	-	-	-	-	-	-	-	-	682,50
			-	-	-	-	○	-	-	-	-	○	0,00
		Not in conjunction with 8R3/950/L5C/P55	*	*	*	*	*	*	*	*	*	*	
		in conjunction with R03+R06 not with R66	*	*	*	*	*	*	*	*	*	*	
		only in conjunction with R01/R02/R03+R06	*	*	*	*	*	*	*	*	*	*	
		i.V.m. Code PYB	●	●	-	●	-	●	●	-	●	-	1.417,50
R73	50.8 cm (20-inch) 10-twin-spoke forged wheels		●	●	-	●	-	●	●	-	●	-	5.302,50
			-	-	●	-	-	-	-	●	-	-	4.462,50
			-	-	-	-	-	-	-	-	-	-	3.727,50
			-	-	-	-	●	-	-	-	-	●	3.045,00
		Not in conjunction with 4R5/4R6/8R3/950/L5C/P55/R03	*	*	*	*	*	*	*	*	*	*	
		Only in conjunction with R01+R06	*	*	*	*	*	*	*	*	*	*	
		i.V.m. Code PYB	●	●	-	●	-	●	●	-	●	-	4.462,50
		i.V.m. Code PYB	-	-	-	-	●	-	-	-	-	●	2.887,50
R90	48.3 cm (19-inch) 5-twin-spoke light-alloy wheels		●	●	-	●	-	●	●	-	●	-	1.785,00
			-	-	●	-	-	-	-	●	-	-	945,00
			-	-	-	-	-	-	-	-	-	-	210,00
			-	-	-	-	○	-	-	-	-	○	0,00
		Not in conjunction with 216/8R3/950/L5C/P55/R66	*	*	*	*	*	*	*	*	*	*	
		only in conjunction with R01/R03+R06	*	*	*	*	*	*	*	*	*	*	
		i.V.m. Code PYB	●	●	-	●	-	●	●	-	●	-	945,00
B51	TIREFIT		●	●	●	●	●	●	●	●	●	●	52,50
		Not in conjunction with R66	*	*	*	*	*	*	*	*	*	*	
		i.V.m. Code PYB	○	○	○	○	○	○	○	○	○	○	0,00
249	interior mirror and driver's exterior mirror automaticall		S	S	S	S	S	S	S	S	S	S	0,00
297	electric sunblinds in rear doors, left and right		●	●	●	●	●	●	●	●	●	●	462,00
		Available only as part of (P09)	*	*	*	*	*	*	*	*	*	*	
		Only in conjunction with P09	*	*	*	*	*	*	*	*	*	*	
		i.V.m. Code P09	○	○	○	○	○	○	○	○	○	○	0,00
540	Electric sunblind for rear window		●	●	●	●	●	●	●	●	●	●	682,50
		Available only as part of (P09)	*	*	*	*	*	*	*	*	*	*	
		Only in conjunction with P09	*	*	*	*	*	*	*	*	*	*	
		i.V.m. Code P09	○	○	○	○	○	○	○	○	○	-	0,00
597	Windscreen, heated		●	●	●	●	●	●	●	●	●	●	609,00
		only in conjunction with 438/445	*	*	*	*	*	*	*	*	*	*	
		i.V.m. Code 596	●	●	●	●	●	●	●	●	●	●	441,00
840	Heat-insulating dark-tinted glass		●	●	●	●	●	●	●	●	●	●	409,50
		for certain countries only	*	*	*	*	*	*	*	*	*	*	
		i.V.m. Code PYH	○	○	○	○	○	○	○	○	○	○	0,00
874	MAGIC VISION CONTROL		●	●	●	●	●	●	●	●	●	●	409,50
		Only in conjunction with 8U0	*	*	*	*	*	*	*	*	*	*	
		i.V.m. Code PYB	○	○	○	○	○	○	○	○	○	○	0,00
8U0	Heated washer fluid reservoir		○	○	○	○	○	○	○	○	○	○	0,00

		Only in conjunction with 874	*	*	*	*	*	*	*	*	*	*	*	*	
P09	Sun Protection package		●	●	●	●	●	●	●	●	●	●	●	●	1.039,50
		Includes codes 297+540	*	*	*	*	*	*	*	*	*	*	*	*	
		i.V.m. Code 413	●	●	●	●	●	●	●	●	●	●	●	●	1.149,75
		i.V.m. Code PYP/PYS	○	○	○	○	○	○	○	○	○	○	○	○	0,00
U50	Omission of heat-insulating dark-tinted glass		○	○	○	○	○	○	○	○	○	○	○	○	0,00
		only in conjunction with 950 and for certain countries	*	*	*	*	*	*	*	*	*	*	*	*	
22U	MBUX Entertainment		○	○	○	○	○	○	○	○	○	○	○	○	0,00
		only in conjunction with 810/811	*	*	*	*	*	*	*	*	*	*	*	*	
72B	USB package Plus		●	●	●	●	●	●	●	●	●	●	●	●	315,00
		i.V.m. Code PYB	○	○	○	○	○	○	○	○	○	○	○	○	0,00
01U	Preinstallation for Navigation Services		○	○	○	○	○	○	○	○	○	○	○	○	0,00
355	Extended MBUX functions		S	S	S	S	S	S	S	S	S	S	S	S	0,00
365	Hard-disc navigation		○	○	○	○	○	○	○	○	○	○	○	○	0,00
PBG	MBUX Navigation Premium		○	○	○	○	○	○	○	○	○	○	○	○	0,00
537	Digital radio		○	○	○	○	○	○	○	○	○	○	○	○	0,00
79B	Preinstallation for digital radio		○	○	○	○	○	○	○	○	○	○	○	○	0,00
447	MBUX rear tablet		●	●	●	●	●	●	●	●	●	●	●	●	525,00
		only in conjunction with 898/72B	*	*	*	*	*	*	*	*	*	*	*	*	
		i.V.m. Code PYP/PYS	○	○	○	○	○	○	○	○	○	○	○	○	0,00
854	MBUX High-End Rear Seat Entertainment System		●	●	●	●	●	●	●	●	●	●	●	●	3.139,50
		Not in conjunction with 521/U67	*	*	*	*	*	*	*	*	*	*	*	*	
		Only in conjunction with 534	*	*	*	*	*	*	*	*	*	*	*	*	
		i.V.m. Code PYS	-	-	-	-	-	○	○	○	○	○	○	○	0,00
865	TV receiver		●	●	●	●	●	●	●	●	●	●	●	●	1.134,00
		Not in conjunction with 521	*	*	*	*	*	*	*	*	*	*	*	*	
		Only in conjunction with 534	*	*	*	*	*	*	*	*	*	*	*	*	
		i.V.m. Code PYS	-	-	-	-	-	○	○	○	○	○	○	○	0,00
U31	1 wireless head set		●	●	●	●	●	●	●	●	●	●	●	●	210,00
		Not in conjunction with U58	*	*	*	*	*	*	*	*	*	*	*	*	
U58	2 wireless head sets		●	●	●	●	●	●	●	●	●	●	●	●	420,00
		Not in conjunction with U31	*	*	*	*	*	*	*	*	*	*	*	*	
		i.V.m. Code PYS	-	-	-	-	-	○	○	○	○	○	○	○	0,00
32U	Sound personalisation		○	○	○	○	○	○	○	○	○	○	○	○	0,00
		only in conjunction with 810/811	*	*	*	*	*	*	*	*	*	*	*	*	
810	Burmester® 3D surround sound system		●	●	●	●	●	●	●	●	●	●	●	●	1.291,50
		Not in conjunction with 811	*	*	*	*	*	*	*	*	*	*	*	*	
		Only in conjunction with 22U+32U	*	*	*	*	*	*	*	*	*	*	*	*	
		i.V.m. Code 22U	●	●	●	●	●	●	●	●	●	●	●	●	1.375,50
		i.V.m. Code PYM/PYN/PYO	○	○	○	○	○	○	○	○	○	○	○	○	0,00
811	Burmester® high-end 4D surround sound system		●	●	●	●	●	●	●	●	●	●	●	●	6.982,50
		Not in conjunction with 810/872	*	*	*	*	*	*	*	*	*	*	*	*	
		Not in conjunction with Z87 /Z90						*	*	*	*	*	*	*	
		Only in conjunction with 223+22U+276+32U+402+413+543+903+P09	*	*	*	*	*	*	*	*	*	*	*	*	
		i.V.m. Code 22U	●	●	●	●	●	●	●	●	●	●	●	●	7.066,50
		i.V.m. Code PYM/PYN/PYO	●	●	●	●	●	●	●	●	●	●	●	●	5.565,00
		i.V.m. Code PYS	-	-	-	-	-	○	○	○	○	○	○	○	0,00
14U	Smartphone integration		S	S	S	S	S	S	S	S	S	S	S	S	0,00
326	Alternative smartphone position in the rear		-	-	-	-	-	●	●	●	●	●	●	●	619,50
		Not in conjunction with 872						*	*	*	*	*	*	*	
		Only in conjunction with 223+224+276+447+582+72B+898						*	*	*	*	*	*	*	
380	Car telephony		●	●	●	●	●	●	●	●	●	●	●	●	892,50
856	Business Telephony in the rear		●	●	●	●	●	●	●	●	●	●	●	●	997,50
		Not in conjunction with 218 /872 /P44	*	*	*	*	*	*	*	*	*	*	*	*	
		Only in conjunction with 223+276+380+447+501+72B+898	*	*	*	*	*	*	*	*	*	*	*	*	
		not in conjunction with 855	*	*	*	*	*	*	*	*	*	*	*	*	
		only in conjunction with 810/811	*	*	*	*	*	*	*	*	*	*	*	*	
897	Wireless charging system for mobile devices in the front		S	S	S	S	S	S	S	S	S	S	S	S	0,00
		Not in conjunction with 899	*	*	*	*	*	*	*	*	*	*	*	*	
898	Wireless charging system for mobile devices in the rear		●	●	●	●	●	●	●	●	●	●	●	●	294,00
		Not in conjunction with 872	*	*	*	*	*	*	*	*	*	*	*	*	
		Only in conjunction with 223+276	*	*	*	*	*	*	*	*	*	*	*	*	
		only in conjunction with 72B/447	*	*	*	*	*	*	*	*	*	*	*	*	
		i.V.m. Code 224	-	-	-	-	-	○	○	○	○	○	○	○	0,00
		i.V.m. Code PYP/PYS	○	○	○	○	○	○	○	○	○	○	○	○	0,00
899	Multifunction telephony		●	●	●	●	●	●	●	●	●	●	●	●	619,50
		Not in conjunction with 897	*	*	*	*	*	*	*	*	*	*	*	*	
543	Double sunblind		○	○	○	○	○	○	○	○	○	○	○	○	0,00
		Only in conjunction with 413+P09	*	*	*	*	*	*	*	*	*	*	*	*	
		i.V.m. Code 460/494	-	-	-	-	●	-	-	-	●	●			110,25
U67	230 V socket in rear		●	●	●	●	●	●	●	●	●	●	●	●	126,00
		Not in conjunction with 854/PBT	*	*	*	*	*	*	*	*	*	*	*	*	
228	Auxiliary heater		●	●	●	●	●	●	●	●	●	●	●	●	1.459,50
		Only for left hand drive	*	*	*	*	*	*	*	*	*	*	*	*	

		i.V.m. Code 00U/33U/34U/37U	●●●●●●●●●●	1.302,00
322	Neck and shoulder heating in the rear		○ ○ ○ ○ ○ ○ ○ ○ ○ ○	0,00
		Available only as part of (P43)	* * * * * * * * * *	
		Not in conjunction with 872	* * * * * * * * * *	
		Only in conjunction with 223+276+402+903+P43	* * * * * * * * * *	
443	Steering wheel heating		●●●●●●●●●●	514,50
		Available only as part of (P69)	* * * * * * * * * *	
		Only in conjunction with P69	* * * * * * * * * *	
		i.V.m. Code P69	○ ○ ○ ○ ○ ○ ○ ○ ○ ○	0,00
581	THERMOTRONIC automatic climate control		S S S S S S S S S S	0,00
582	THERMOTRONIC automatic climate control in the rear		●●●●●●●●●●	1.197,00
		i.V.m. Code PYP/PYS	○ ○ ○ ○ ○ ○ ○ ○ ○ ○	0,00
B24	Remote control for auxiliary heating		○ ○ ○ ○ ○ ○ ○ ○ ○ ○	0,00
		Only in conjunction with 228	* * * * * * * * * *	
		Only for left hand drive	* * * * * * * * * *	
		i.V.m. Code 00U/33U/34U/37U	●●●●●●●●●●	210,00
P21	AIR-BALANCE package		●●●●●●●●●●	388,50
		i.V.m. Code PBS	○ ○ ○ ○ ○ ○ ○ ○ ○ ○	0,00
P69	Warmth Comfort package		●●●●●●●●●●	609,00
		Includes codes 443+906+907	* * * * * * * * * *	
		only in conjunction with 872[402]+873[401]	* * * * * * * * * *	
		i.V.m. Code PBS	○ ○ ○ ○ ○ ○ ○ ○ ○ ○	0,00
282	Through-loading feature		○ ○ ○ ○ ○ ○ ○ ○ ○ ○	0,00
		available only as part of (942)	* * * * * * * * * *	
942	Load Compartment package		●●●●●●●●●●	724,50
		Only in conjunction with 282+7B8+871+881+U35	* * * * * * * * * *	
		only in conjunction with B13/P34	* * * * * * * * * *	
		i.V.m. Code PWS	○ ○ ○ ○ ○ ○ ○ ○ ○ ○	0,00
		i.V.m. Code PYB	○ ○ ○ ○ ○ ○ ○ ○ ○ ○	0,00
E69	EASY-PACK boot box		●●●●●●●●●●	262,50
		Not in conjunction with 308	* * * * * * * * * *	
U35	Socket		○ ○ ○ ○ ○ ○ ○ ○ ○ ○	0,00
		Only in conjunction with 282+7B8+871+881+942	* * * * * * * * * *	
722	Centre console in metallic mixed fabric-look in black silk		●●●●●●●●●●	304,50
		Not in conjunction with 726	* * * * * * * * * *	
		Only in conjunction with H75	* * * * * * * * * *	
		available as of February 2021	* * * * * * * * * *	
726	Centre console in a black crystal-look finish		S S S S S S S S S S	0,00
		Not in conjunction with 722	* * * * * * * * * *	
H17	designo black piano lacquer trim with flowing lines		●●●●●●●●●●	1.365,00
		Not in conjunction with 722	* * * * * * * * * *	
		Only in conjunction with 726	* * * * * * * * * *	
		available as of December 2020	* * * * * * * * * *	
H38	designo brown open-pore walnut wood trim with aluminium		●●●●●●●●●●	3.360,00
		Not in conjunction with 201A/204A/205A/722/L2D	* * * * * * * * * *	
		Only in conjunction with 726	* * * * * * * * * *	
		available as of February 2021	* * * * * * * * * *	
PBS	Front ENERGIZING package		●●●●●●●●●●	4.257,75
		Includes codes 401+432	* * * * * * * * * *	
		Not in conjunction with 521/873/U22	* * * * * * * * * *	
		Only in conjunction with 534+868+902+P21+P69+U19	* * * * * * * * * *	
		includes P21+P69	* * * * * * * * * *	
		i.V.m. Code PYO/PYS	○ ○ ○ ○ ○ ○ ○ ○ ○ ○	0,00
PBT	Rear ENERGIZING package		●●●●●●●●●●	3.113,25
		Includes codes 402	* * * * * * * * * *	
		Not in conjunction with 521/872/873/U22/U67	* * * * * * * * * *	
		Only in conjunction with 223+276+534+854+868+902+903+P21+P43+P69+PBS+U19	* * * * * * * * * *	
		i.V.m. Code PYS	- - - - - ○ ○ ○ ○ ○	0,00
U04	Floor mats with piping in a contrasting colour		○ ○ ○ ○ ○ ○ ○ ○ ○ ○	0,00
		Not in conjunction with 51U/55U/58U/872/950/B13/L5C/P55/RRG/RVR/RVV/RWN/RZ1/U12	* * * * * * * * * *	
		Only in conjunction with [501A/504A/505A/507A/508A]	* * * * * * * * * *	
		not in conjunction with U26/498	* * * * * * * * * *	
U12	Velour floor mats		○ ○ ○ ○ ○ ○ ○ ○ ○ ○	0,00
		Not in conjunction with 501A/504A/505A/507A/508A/61U/65U/68U/950/L5C/P55/RRG/RVR/RVV/RWN/RZ1	* * * * * * * * * *	
		only in conjunction with 201A/204A/205A/801A/804A/805A	* * * * * * * * * *	
U25	Illuminated door sill panels with "Mercedes-Benz" lettering		●●●●●●●●●●	157,50
		i.V.m. Code P34	○ ○ ○ ○ ○ ○ ○ ○ ○ ○	0,00
		i.V.m. Code PWS	○ ○ ○ ○ ○ ○ ○ ○ ○ ○	0,00
		i.V.m. Code PYB	○ ○ ○ ○ ○ ○ ○ ○ ○ ○	0,00
U26	AMG floor mats		○ ○ ○ ○ ○ ○ ○ ○ ○ ○	0,00
		Available only as part of (950)	* * * * * * * * * *	
		Not in conjunction with 550/L2B/U04/U12	* * * * * * * * * *	
		Only in conjunction with 950+([RRG/RVQ/RVR/RVU/RVV/RWK/RWN/RZ1])	* * * * * * * * * *	
438	Head-up Display		●●●●●●●●●●	934,50

		Not in conjunction with 445	*	*	*	*	*	*	*	*	*	*	*	
445	MBUX augmented reality Head-up Display		●	●	●	●	●	●	●	●	●	●	●	3.139,50
		Not in conjunction with 438/521	*	*	*	*	*	*	*	*	*	*	*	
		Only in conjunction with 451+534	*	*	*	*	*	*	*	*	*	*	*	
		i.V.m. Code PYN/PYO/PYS	○	○	○	○	○	○	○	○	○	○	○	0,00
451	3D driver display		●	●	●	●	●	●	●	●	●	●	●	1.039,50
		Not in conjunction with 521	*	*	*	*	*	*	*	*	*	*	*	
		Only in conjunction with 534	*	*	*	*	*	*	*	*	*	*	*	
		i.V.m. Code 445	○	○	○	○	○	○	○	○	○	○	○	0,00
		i.V.m. Code PYM/PYN/PYO/PYS	○	○	○	○	○	○	○	○	○	○	○	0,00
868	OLED central display		●	●	●	●	●	●	●	●	●	●	●	840,00
		Not in conjunction with 521	*	*	*	*	*	*	*	*	*	*	*	
		Only in conjunction with 534+U19	*	*	*	*	*	*	*	*	*	*	*	
		i.V.m. Code PWS	○	○	○	○	○	○	○	○	○	○	○	0,00
		i.V.m. Code PYB	○	○	○	○	○	○	○	○	○	○	○	0,00
U19	MBUX augmented reality for navigation		○	○	○	○	○	○	○	○	○	○	○	0,00
		Not in conjunction with 521	*	*	*	*	*	*	*	*	*	*	*	
		Only in conjunction with 534+868	*	*	*	*	*	*	*	*	*	*	*	
878	Active ambient lighting		●	●	●	●	●	●	●	●	●	●	●	829,50
		i.V.m. Code PYM/PYN/PYO/PYS	○	○	○	○	○	○	○	○	○	○	○	0,00
891	Ambient lighting		S	S	S	S	S	S	S	S	S	S	S	0,00
51U	Roof liner in black fabric		○	○	○	○	○	○	○	○	○	○	○	0,00
		Not in conjunction with 55U/58U/61U/65U/68U/P34/U04	*	*	*	*	*	*	*	*	*	*	*	
		Only in conjunction with [201A/204A/801A/804A]	*	*	*	*	*	*	*	*	*	*	*	
55U	Headlining in beige fabric		○	○	○	○	○	○	○	○	○	○	○	0,00
		Not in conjunction with 51U/58U/61U/65U/68U/77B/P34/U04	*	*	*	*	*	*	*	*	*	*	*	
		Only in conjunction with [205A/805A]	*	*	*	*	*	*	*	*	*	*	*	
58U	Roof liner in neva grey fabric		○	○	○	○	○	○	○	○	○	○	○	0,00
		Not in conjunction with 51U/55U/61U/65U/68U/P34/U04	*	*	*	*	*	*	*	*	*	*	*	
		only in conjunction with 201A/801A	*	*	*	*	*	*	*	*	*	*	*	
61U	Roof lining in black DINAMICA microfibre		○	○	○	○	○	○	○	○	○	○	○	0,00
		Not in conjunction with 51U/55U/58U/65U/68U/872/B13/U12	*	*	*	*	*	*	*	*	*	*	*	
		Only in conjunction with 413+543	*	*	*	*	*	*	*	*	*	*	*	
		Only in conjunction with [501A/504A/507A/508A]+P09	*	*	*	*	*	*	*	*	*	*	*	
		only in conjunction with 223+276+P09+P34	*	*	*	*	*	*	*	*	*	*	*	
		i.V.m. Code 508A	●	●	●	●	●	●	●	●	●	●	●	367,50
65U	Roof lining in beige DINAMICA microfibre		○	○	○	○	○	○	○	○	○	○	○	0,00
		Not in conjunction with 51U/55U/58U/61U/68U/77B/872/B13/U12	*	*	*	*	*	*	*	*	*	*	*	
		Only in conjunction with 223+276+505A+P09+P34	*	*	*	*	*	*	*	*	*	*	*	
		Only in conjunction with 413+543	*	*	*	*	*	*	*	*	*	*	*	
68U	Roof liner in neva grey DINAMICA microfibre		○	○	○	○	○	○	○	○	○	○	○	0,00
		Not in conjunction with 51U/55U/58U/61U/65U/872/B13/U12	*	*	*	*	*	*	*	*	*	*	*	
		Only in conjunction with 413+543	*	*	*	*	*	*	*	*	*	*	*	
		only in conjunction with 223+276+P09+P34	*	*	*	*	*	*	*	*	*	*	*	
		only in conjunction with [501A/508A]+P09	*	*	*	*	*	*	*	*	*	*	*	
		i.V.m. Code 501A	●	●	●	●	●	●	●	●	●	●	●	367,50
439	EASY ADJUST luxury head restraints for driver and front passenger		○	○	○	○	○	○	○	○	○	○	○	0,00
		Available only as part of (P07)	*	*	*	*	*	*	*	*	*	*	*	
		Not in conjunction with 436/872	*	*	*	*	*	*	*	*	*	*	*	
		Only in conjunction with 223+276+561+P07	*	*	*	*	*	*	*	*	*	*	*	
561	Designer belt buckles in front and rear		●	●	●	●	●	●	●	●	●	●	●	315,00
		i.V.m. Code PYP/PYS	○	○	○	○	○	○	○	○	○	○	○	0,00
275	Driver's seat, electrically adjustable with memory function		○	○	○	○	○	○	○	○	○	○	○	0,00
401	Climatised front seats		●	●	●	●	●	●	●	●	●	●	●	897,75
		Not in conjunction with 873	*	*	*	*	*	*	*	*	*	*	*	
		Only in conjunction with 902	*	*	*	*	*	*	*	*	*	*	*	
		i.V.m. Code PBS	○	○	○	○	○	○	○	○	○	○	○	0,00
		i.V.m. Code PYN/PYO/PYS	○	○	○	○	○	○	○	○	○	○	○	0,00
432	Active Multicontour Seat package		●	●	●	●	●	●	●	●	●	●	●	2.100,00
		Not in conjunction with 873/U22	*	*	*	*	*	*	*	*	*	*	*	
		Only in conjunction with 401+902	*	*	*	*	*	*	*	*	*	*	*	
		only in conjunction with 436/439	*	*	*	*	*	*	*	*	*	*	*	
		i.V.m. Code PBS	○	○	○	○	○	○	○	○	○	○	○	0,00
		i.V.m. Code PYN/PYO/PYS	○	○	○	○	○	○	○	○	○	○	○	0,00
436	Comfort front head restraints		○	○	○	○	○	○	○	○	○	○	○	0,00
		Not in conjunction with 453	*	*	*	*	*	*	*	*	*	*	*	
		Not in conjunction with 873/P07/U22	*	*	*	*	*	*	*	*	*	*	*	
		Only in conjunction with 401+432+902	*	*	*	*	*	*	*	*	*	*	*	
452	Seat on front passenger side electrically adjustable from driver's seat		○	○	○	○	○	○	○	○	○	○	○	0,00
		Available only as part of (P07)	*	*	*	*	*	*	*	*	*	*	*	
		Not in conjunction with 436/872	*	*	*	*	*	*	*	*	*	*	*	
		Only in conjunction with 223+276+561+P07	*	*	*	*	*	*	*	*	*	*	*	
873	Heated front seats		S	S	S	S	S	S	S	S	S	S	S	0,00
		Not in conjunction with 401/432/436/902/PBS/PBT	*	*	*	*	*	*	*	*	*	*	*	

		Only in conjunction with U22	*	*	*	*	*	*	*	*	*	*	*	*		
902	Seat heating Plus for driver and front passenger seats		○	○	○	○	○	○	○	○	○	○	○	○		0,00
		Not in conjunction with 873	*	*	*	*	*	*	*	*	*	*	*	*		
		Only in conjunction with 401	*	*	*	*	*	*	*	*	*	*	*	*		
P64	Memory package		S	S	S	S	S	S	S	S	S	S	S	S		0,00
		Includes codes 249+275+321+U22 [432]	*	*	*	*	*	*	*	*	*	*	*	*		
U10	Automatic front passenger airbag deactivation		S	S	S	S	S	S	S	S	S	S	S	S		0,00
U22	4-way lumbar support		○	○	○	○	○	○	○	○	○	○	○	○		0,00
		Not in conjunction with 432/436/PBS/PBT	*	*	*	*	*	*	*	*	*	*	*	*		
223	Electrically-adjustable rear seats including memory function		●	●	●	●	●	●	●	●	●	●	●	●		1.638,00
		Not in conjunction with 872	*	*	*	*	*	*	*	*	*	*	*	*		
		Only in conjunction with 276	*	*	*	*	*	*	*	*	*	*	*	*		
		i.V.m. Code PYP/PYS	○	○	○	○	○	○	○	○	○	○	○	○		0,00
224	First-Class rear compartment		-	-	-	-	-	●	●	●	●	●	●	●		2.940,00
		Not in conjunction with 872						*	*	*	*	*	*	*		
		Only in conjunction with 223+276+447+582+72B+898						*	*	*	*	*	*	*		
276	Rear Seat Memory package		○	○	○	○	○	○	○	○	○	○	○	○		0,00
		Not in conjunction with 872	*	*	*	*	*	*	*	*	*	*	*	*		
		Only in conjunction with 223	*	*	*	*	*	*	*	*	*	*	*	*		
308	Refrigerated compartment		●	●	●	●	●	●	●	●	●	●	●	●		1.207,50
		Not in conjunction with 872/E69	*	*	*	*	*	*	*	*	*	*	*	*		
		Only in conjunction with 223+276	*	*	*	*	*	*	*	*	*	*	*	*		
402	Climatised rear seats		●	●	●	●	●	●	●	●	●	●	●	●		1.328,25
		Not in conjunction with 872	*	*	*	*	*	*	*	*	*	*	*	*		
		Only in conjunction with 223+276+903	*	*	*	*	*	*	*	*	*	*	*	*		
		i.V.m. Code PYO	●	●	●	●	●	●	●	●	●	●	●	●		897,75
		i.V.m. Code PBT	○	○	○	○	○	○	○	○	○	○	○	○		0,00
		i.V.m. Code PYP/PYS	○	○	○	○	○	○	○	○	○	○	○	○		0,00
406	Multicontour rear seats		○	○	○	○	○	○	○	○	○	○	○	○		0,00
		Available only as part of (P43)	*	*	*	*	*	*	*	*	*	*	*	*		
		Not in conjunction with 872	*	*	*	*	*	*	*	*	*	*	*	*		
		Only in conjunction with 223+276+402+903+P43	*	*	*	*	*	*	*	*	*	*	*	*		
449	folding tables in the rear		-	-	-	-	-	●	●	●	●	●	●	●		1.890,00
		Not in conjunction with 872						*	*	*	*	*	*	*		
		Only in conjunction with 223+224+276+447+582+72B+898						*	*	*	*	*	*	*		
453	Executive seat		-	-	-	-	-	●	●	●	●	●	●	●		1.102,50
		Not in conjunction with 436/872/Z99						*	*	*	*	*	*	*		
		Only in conjunction with 223+276+561+582+P07						*	*	*	*	*	*	*		
		i.V.m. Code PYS	-	-	-	-	-	○	○	○	○	○	○	○		0,00
872	Heated rear seats		●	●	●	●	●	●	●	●	●	●	●	●		430,50
		Not in conjunction with 223/276/306/308/402/501A/504A/505A/507A/508A/61U/65U/68U/811/856/898	*	*	*	*	*	*	*	*	*	*	*	*		
		Not in conjunction with 224/326/449/453						*	*	*	*	*	*	*		
		i.V.m. Code PYO	○	○	○	○	○	○	○	○	○	○	○	○		0,00
903	seat heating Plus for outer rear seats		○	○	○	○	○	○	○	○	○	○	○	○		0,00
		Not in conjunction with 872	*	*	*	*	*	*	*	*	*	*	*	*		
		Only in conjunction with 223+276+402	*	*	*	*	*	*	*	*	*	*	*	*		
P07	Chauffeur package		●	●	●	●	●	●	●	●	●	●	●	●		1.018,50
		Includes codes 439+452+562	*	*	*	*	*	*	*	*	*	*	*	*		
		Not in conjunction with 436/872	*	*	*	*	*	*	*	*	*	*	*	*		
		Only in conjunction with 223+276+561	*	*	*	*	*	*	*	*	*	*	*	*		
		i.V.m. Code PYP/PYS	○	○	○	○	○	○	○	○	○	○	○	○		0,00
P43	Rear Seat Comfort package		●	●	●	●	●	●	●	●	●	●	●	●		1.785,00
		Includes codes 322+406	*	*	*	*	*	*	*	*	*	*	*	*		
		Not in conjunction with 872	*	*	*	*	*	*	*	*	*	*	*	*		
		Only in conjunction with 223+276+402+903	*	*	*	*	*	*	*	*	*	*	*	*		
		only in conjunction with 477/854	*	*	*	*	*	*	*	*	*	*	*	*		
		i.V.m. Code PBT	○	○	○	○	○	○	○	○	○	○	○	○		0,00
321	Fingerprint scanner		○	○	○	○	○	○	○	○	○	○	○	○		0,00
77B	MBUX Interior Assistant		●	●	●	●	●	●	●	●	●	●	●	●		567,00
		Not in conjunction with 55U/65U	*	*	*	*	*	*	*	*	*	*	*	*		
		Only in conjunction with [201A/501A/801A]+413	*	*	*	*	*	*	*	*	*	*	*	*		
		available only with black upholstery	*	*	*	*	*	*	*	*	*	*	*	*		
L2B	Multifunction steering wheel in nappa leather		○	○	○	○	○	○	○	○	○	○	○	○		0,00
		Not in conjunction with 950/P55/RRG/RVR/RVV/RWN/RZI	*	*	*	*	*	*	*	*	*	*	*	*		
L2D	Multifunction steering wheel in wood/leather		●	●	●	●	●	●	●	●	●	●	●	●		651,00
		Not in conjunction with H02/H38	*	*	*	*	*	*	*	*	*	*	*	*		
		in conjunction with H17/H29/H37 available as of December 2020	*	*	*	*	*	*	*	*	*	*	*	*		
		in conjunction with H75 available as of February 2021	*	*	*	*	*	*	*	*	*	*	*	*		
		i.V.m. Code 951	-	-	-	○	○	-	-	-	○	○				0,00
L5C	Multifunction sports steering wheel in nappa leather		○	○	○	○	○	○	○	○	○	○	○	○		0,00
		Available only as part of (950)	*	*	*	*	*	*	*	*	*	*	*	*		
		Not in conjunction with 550/U04/U12	*	*	*	*	*	*	*	*	*	*	*	*		
		Only in conjunction with 950+[RRG/RVQ/RVR/RVU/RVV/RWK/RWN/RZI]	*	*	*	*	*	*	*	*	*	*	*	*		
		available as of December 2020	*	*	*	*	*	*	*	*	*	*	*	*		

[illegible]

34U	Remote Services Premium		●●●●●●●●●●	262,50
		Not in conjunction with 33U	* * * * * * * * * *	
		i.V.m. Code 37U	●●●●●●●●●●	105,00
		i.V.m. Code PYB	○ ○ ○ ○ ○ ○ ○ ○ ○ ○	0,00
351	Mercedes-Benz emergency call system		○ ○ ○ ○ ○ ○ ○ ○ ○ ○	0,00
00B	Owner's Manual and Service Booklet - Danish		○ ○ ○ ○ ○ ○ ○ ○ ○ ○	0,00
		Not in conjunction with 01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/13B/14B/15B/16B/17B/30B	* * * * * * * * * *	
00U	Remote Services		- - - - - ●●●●●	105,00
01B	Owner's Manual and Service Booklet - Dutch		○ ○ ○ ○ ○ ○ ○ ○ ○ ○	0,00
		Not in conjunction with 00B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/13B/14B/15B/16B/17B/30B	* * * * * * * * * *	
02B	Owner's Manual and Service Booklet - German		○ ○ ○ ○ ○ ○ ○ ○ ○ ○	0,00
		Not in conjunction with 00B/01B/03B/04B/05B/06B/07B/08B/09B/10B/11B/13B/14B/15B/16B/17B/30B	* * * * * * * * * *	
03B	Owner's Manual and Service Booklet - Russian		○ ○ ○ ○ ○ ○ ○ ○ ○ ○	0,00
		Not in conjunction with 00B/01B/02B/04B/05B/06B/07B/08B/09B/10B/11B/13B/14B/15B/16B/17B/30B	* * * * * * * * * *	
04B	Owner's Manual and Service Booklet - Finnish		○ ○ ○ ○ ○ ○ ○ ○ ○ ○	0,00
		Not in conjunction with 00B/01B/02B/03B/05B/06B/07B/08B/09B/10B/11B/13B/14B/15B/16B/17B/30B	* * * * * * * * * *	
05B	Owner's Manual and Service Booklet - English		○ ○ ○ ○ ○ ○ ○ ○ ○ ○	0,00
		Not in conjunction with 00B/01B/02B/03B/04B/06B/07B/08B/09B/10B/11B/13B/14B/15B/16B/17B/30B	* * * * * * * * * *	
05Z	Run-on times MPM 4 hours		- - - - - ○ ○ ○ ○ ○	0,00
06B	Owner's Manual and Service Booklet - Italian		○ ○ ○ ○ ○ ○ ○ ○ ○ ○	0,00
		Not in conjunction with 00B/01B/02B/03B/04B/05B/07B/08B/09B/10B/11B/13B/14B/15B/16B/17B/30B	* * * * * * * * * *	
06Z	Run-on times MPM w/o time limit		- - - - - ○ ○ ○ ○ ○	0,00
07B	Owner's Manual and Service Booklet - French		○ ○ ○ ○ ○ ○ ○ ○ ○ ○	0,00
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/08B/09B/10B/11B/13B/14B/15B/16B/17B/30B	* * * * * * * * * *	
08B	Owner's Manual and Service Booklet - Spanish		○ ○ ○ ○ ○ ○ ○ ○ ○ ○	0,00
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/09B/10B/11B/13B/14B/15B/16B/17B/30B	* * * * * * * * * *	
09B	Owner's Manual and Service Booklet - Portuguese		○ ○ ○ ○ ○ ○ ○ ○ ○ ○	0,00
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/10B/11B/13B/14B/15B/16B/17B/30B	* * * * * * * * * *	
10B	Owner's Manual and Service Booklet - Swedish		○ ○ ○ ○ ○ ○ ○ ○ ○ ○	0,00
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/11B/13B/14B/15B/16B/17B/30B	* * * * * * * * * *	
10Z	High-beam flashing, daytime, for emerg. vehicle		- - - - - ○ ○ ○ ○ ○	0,00
11B	Owner's Manual and Service Booklet - Arabic		○ ○ ○ ○ ○ ○ ○ ○ ○ ○	0,00
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/13B/14B/15B/16B/17B/30B	* * * * * * * * * *	
11Z	Dayt. run. lamps flashing, daytime, emerg. veh.		- - - - - ○ ○ ○ ○ ○	0,00
12B	Owner's Manual and Service Booklet - Engl. USA/CAN		○ ○ ○ ○ ○ ○ ○ ○ ○ ○	0,00
12U	Preinstallation for Concierge Service		●●●●●●●●●●	105,00
13B	Owner's Manual and Service Booklet - Norwegian		○ ○ ○ ○ ○ ○ ○ ○ ○ ○	0,00
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/14B/15B/16B/17B/30B	* * * * * * * * * *	
14B	Owner's Manual and Service Booklet - Greek		○ ○ ○ ○ ○ ○ ○ ○ ○ ○	0,00
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/13B/15B/16B/17B/30B	* * * * * * * * * *	
15B	Owner's Manual and Service Booklet - Turkish		○ ○ ○ ○ ○ ○ ○ ○ ○ ○	0,00
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/13B/14B/16B/17B/30B	* * * * * * * * * *	
16B	Owner's Manual and Service Booklet - Polish		○ ○ ○ ○ ○ ○ ○ ○ ○ ○	0,00
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/13B/14B/15B/17B/30B	* * * * * * * * * *	
16U	Apple CarPlay		○ ○ ○ ○ ○ ○ ○ ○ ○ ○	0,00
17B	Owner's Manual and Service Booklet - Czech		○ ○ ○ ○ ○ ○ ○ ○ ○ ○	0,00
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/13B/14B/15B/16B/30B	* * * * * * * * * *	
17U	Android Auto		○ ○ ○ ○ ○ ○ ○ ○ ○ ○	0,00
18B	Owner's Manual and Service Booklet - Engl. S. Am.		○ ○ ○ ○ ○ ○ ○ ○ ○ ○	0,00
19B	Owner's Manual and Service Booklet - French S. Am.		○ ○ ○ ○ ○ ○ ○ ○ ○ ○	0,00
20B	Owner's Manual and Service Booklet - Spanish S. Am.		○ ○ ○ ○ ○ ○ ○ ○ ○ ○	0,00
21B	Reversing camera		○ ○ ○ ○ ○ ○ ○ ○ ○ ○	0,00
		Available only as part of (P44)	* * * * * * * * * *	
		Not in conjunction with 216/27U/501/503/856/RRG/RVU/RVV	* * * * * * * * * *	
		Only in conjunction with P44	* * * * * * * * * *	
21B	Owner's Manual and Service Booklet - Portug. S. Am.		○ ○ ○ ○ ○ ○ ○ ○ ○ ○	0,00
21U	Dash cam		○ ○ ○ ○ ○ ○ ○ ○ ○ ○	0,00
		only in conjunction with U19	* * * * * * * * * *	
22B	Owner's Manual and Service Booklet - Japanese		○ ○ ○ ○ ○ ○ ○ ○ ○ ○	0,00
232	Garage door opener (frequency range 284-390 MHz)		●●●●●●●●●●	236,25
		only in conjunction with 249	* * * * * * * * * *	
235	Active Parking Assist with PARKTRONIC		○ ○ ○ ○ ○ ○ ○ ○ ○ ○	0,00
		only in conjunction with P44/P47/PBH	* * * * * * * * * *	
23B	Owner's Manual and Service Booklet - simpl. Chinese		○ ○ ○ ○ ○ ○ ○ ○ ○ ○	0,00
24B	Owner's Manual and Service Booklet - trad. Chinese		○ ○ ○ ○ ○ ○ ○ ○ ○ ○	0,00
25B	Owner's Manual and Service Booklet - Korean		○ ○ ○ ○ ○ ○ ○ ○ ○ ○	0,00
263	Number plate mounting for Asia / Mexico		○ ○ ○ ○ ○ ○ ○ ○ ○ ○	0,00
264	Number plate mounting for USA/CAN		○ ○ ○ ○ ○ ○ ○ ○ ○ ○	0,00
266	Active Steering Assist		○ ○ ○ ○ ○ ○ ○ ○ ○ ○	0,00
26B	Owner's Manual and Service Booklet - Chinese Taiwan		○ ○ ○ ○ ○ ○ ○ ○ ○ ○	0,00
26Z	DVD-Matte vorn beschnitten li. für Einsatzfahrzeuge		○ ○ ○ ○ ○ ○ ○ ○ ○ ○	0,00
27B	Owner's Manual and Service Booklet - Spanish Mexico		○ ○ ○ ○ ○ ○ ○ ○ ○ ○	0,00
27Z	DVD-Matte vorn beschnitten re. für Einsatzfahrzeuge		○ ○ ○ ○ ○ ○ ○ ○ ○ ○	0,00
28Z	DVD-Matte hinten beschnitten für Einsatzfahrzeuge		○ ○ ○ ○ ○ ○ ○ ○ ○ ○	0,00

30B	Owner's Manual and Service Booklet - Slovenian		○	○	○	○	○	○	○	○	○	○	○	○	○	○	0,00
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/13B/14B/15B/16B/17B	*	*	*	*	*	*	*	*	*	*	*	*	*	*	
30U	Projection function for lines		○	○	○	○	○	○	○	○	○	○	○	○	○	○	0,00
		Not in conjunction with 642	*	*	*	*	*	*	*	*	*	*	*	*	*	*	
		Only in conjunction with 318+42U+43U	*	*	*	*	*	*	*	*	*	*	*	*	*	*	
		for certain countries only	*	*	*	*	*	*	*	*	*	*	*	*	*	*	
316	DIGITAL LIGHT		-	-	-	-	-	●	●	●	●	●	●	●	●	●	1.984,50
317	DIGITAL LIGHT		●	●	●	●	●	●	●	●	●	●	●	●	●	●	1.984,50
		i.V.m. Code PYN/PYO/PYS	○	○	○	○	○	○	○	○	○	○	○	○	○	○	0,00
31B	Owner's Manual and Service Booklet - Hungarian		○	○	○	○	○	○	○	○	○	○	○	○	○	○	0,00
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/13B/14B/15B/16B/17B	*	*	*	*	*	*	*	*	*	*	*	*	*	*	
325	Centre airbag		○	○	○	○	○	○	○	○	○	○	○	○	○	○	0,00
32B	Owner's Manual and Service Booklet - Bulgarian		○	○	○	○	○	○	○	○	○	○	○	○	○	○	0,00
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/13B/14B/15B/16B/17B	*	*	*	*	*	*	*	*	*	*	*	*	*	*	
33B	Owner's Manual and Service Booklet - Romanian		○	○	○	○	○	○	○	○	○	○	○	○	○	○	0,00
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/13B/14B/15B/16B/17B	*	*	*	*	*	*	*	*	*	*	*	*	*	*	
34B	Owner's Manual and Service Booklet - Croatian		○	○	○	○	○	○	○	○	○	○	○	○	○	○	0,00
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/13B/14B/15B/16B/17B	*	*	*	*	*	*	*	*	*	*	*	*	*	*	
35B	Owner's Manual and Service Booklet - Latvian		○	○	○	○	○	○	○	○	○	○	○	○	○	○	0,00
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/13B/14B/15B/16B/17B	*	*	*	*	*	*	*	*	*	*	*	*	*	*	
367	Preinstallation for Live Traffic Information		○	○	○	○	○	○	○	○	○	○	○	○	○	○	0,00
36B	Owner's Manual and Service Booklet - Lithuanian		○	○	○	○	○	○	○	○	○	○	○	○	○	○	0,00
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/13B/14B/15B/16B/17B	*	*	*	*	*	*	*	*	*	*	*	*	*	*	
37B	Owner's Manual and Service Booklet - Slovakian		○	○	○	○	○	○	○	○	○	○	○	○	○	○	0,00
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/13B/14B/15B/16B/17B	*	*	*	*	*	*	*	*	*	*	*	*	*	*	
37U	Advanced connectivity Plus		●	●	●	●	●	●	●	●	●	●	●	●	●	●	157,50
38B	Owner's Manual and Service Booklet - Estonian		○	○	○	○	○	○	○	○	○	○	○	○	○	○	0,00
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/13B/14B/15B/16B/17B	*	*	*	*	*	*	*	*	*	*	*	*	*	*	
39B	Owner's Manual and Service Booklet - Serbian		○	○	○	○	○	○	○	○	○	○	○	○	○	○	0,00
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/13B/14B/15B/16B/17B	*	*	*	*	*	*	*	*	*	*	*	*	*	*	
40B	Owner's Manual and Service Booklet - ukrainian		○	○	○	○	○	○	○	○	○	○	○	○	○	○	0,00
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/13B/14B/15B/16B/17B	*	*	*	*	*	*	*	*	*	*	*	*	*	*	
41B	Owner's Manual and Service Booklet - hebrew		○	○	○	○	○	○	○	○	○	○	○	○	○	○	0,00
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/13B/14B/15B/16B/17B	*	*	*	*	*	*	*	*	*	*	*	*	*	*	
421	9G-TRONIC		S	S	S	S	S	S	S	S	S	S	S	S	S	S	0,00
42B	Owner's Manual and Service Booklet - Indonesian		○	○	○	○	○	○	○	○	○	○	○	○	○	○	0,00
42U	Projection function for symbols		○	○	○	○	○	○	○	○	○	○	○	○	○	○	0,00
		Not in conjunction with 642	*	*	*	*	*	*	*	*	*	*	*	*	*	*	
		Only in conjunction with 30U+318+43U	*	*	*	*	*	*	*	*	*	*	*	*	*	*	
		for certain countries only	*	*	*	*	*	*	*	*	*	*	*	*	*	*	
43B	Owner's Manual and Service Booklet - Thai		○	○	○	○	○	○	○	○	○	○	○	○	○	○	0,00
43U	Projection function for animations		○	○	○	○	○	○	○	○	○	○	○	○	○	○	0,00
		Not in conjunction with 642	*	*	*	*	*	*	*	*	*	*	*	*	*	*	
		Only in conjunction with 30U+318+42U	*	*	*	*	*	*	*	*	*	*	*	*	*	*	
44B	Owner's Manual and Service Booklet - Vietnamese		○	○	○	○	○	○	○	○	○	○	○	○	○	○	0,00
460	Canada specification		-	-	-	-	○	-	-	-	-	-	-	-	-	-	0,00
461	Instrument display in miles with English lettering		○	○	○	○	○	○	○	○	○	○	○	○	○	○	0,00
477	Tyre pressure loss warning system		○	○	○	○	○	○	○	○	○	○	○	○	○	○	0,00
494	USA specification		-	-	-	-	-	-	-	-	-	-	○	○	○	○	0,00
498	Japan specification		-	-	○	-	○	-	-	○	-	-	○	-	○	○	0,00
4R5	Complete set of 4 M+S winter wheels		●	●	●	●	●	●	●	●	●	●	●	●	●	●	2.047,50
4R5		Not in conjunction with 4R6/8R3/R51/R73/U29	*	*	*	*	*	*	*	*	*	*	*	*	*	*	
4R5		not in conjunction with U29	*	*	*	*	*	*	*	*	*	*	*	*	*	*	
4R6	complete winter (M+S) wheel-and-tyre assembly x 4		●	●	●	●	●	●	●	●	●	●	●	●	●	●	2.572,50
4R6		Not in conjunction with 4R5/8R3/R51/R73	*	*	*	*	*	*	*	*	*	*	*	*	*	*	
501	360° camera		○	○	○	○	○	○	○	○	○	○	○	○	○	○	0,00
		Not in conjunction with 218/P44	*	*	*	*	*	*	*	*	*	*	*	*	*	*	
		only in conjunction with P47/PBH	*	*	*	*	*	*	*	*	*	*	*	*	*	*	
517	HD digital radio standard		○	○	○	○	○	○	○	○	○	○	○	○	○	○	0,00
521	MBUX multimedia system		S	S	S	S	S	S	S	S	S	S	S	S	S	S	0,00
		Not in conjunction with 445/451/534/854/865/868/PBS/PBT/U19	*	*	*	*	*	*	*	*	*	*	*	*	*	*	
524	Transport protection		●	●	●	●	●	●	●	●	●	●	●	●	●	●	168,00
		available as of December 2020	*	*	*	*	*	*	*	*	*	*	*	*	*	*	
534	MBUX multimedia system		○	○	○	○	○	○	○	○	○	○	○	○	○	○	0,00
		Not in conjunction with 521	*	*	*	*	*	*	*	*	*	*	*	*	*	*	
		only in conjunction with 445/451/534/854/865/868/PBS/PBT/U19	*	*	*	*	*	*	*	*	*	*	*	*	*	*	
536	SIRIUS satellite radio		○	○	○	○	○	○	○	○	○	○	○	○	○	○	0,00
551	Anti-theft alarm system with preinstallation for collisio		●	●	●	●	●	●	●	●	●	●	●	●	●	●	462,00
		i.V.m. Code P54/P82	○	○	○	○	○	○	○	○	○	○	○	○	○	○	0,00
552	Anti-theft alarm system with preinstallation for collisio		○	○	○	○	○	○	○	○	○	○	○	○	○	○	0,00
599	Windscreen with IR-penetrable transm./recep. area		○	○	○	○	○	○	○	○	○	○	○	○	○	○	0,00
608	Adaptive Highbeam Assist		○	○	○	○	○	○	○	○	○	○	○	○	○	○	0,00
623	Gulf States specification		-	-	-	-	-	-	-	-	-	-	●	●	●	●	157,50
625	Australia specification		○	-	-	○	-	-	-	-	-	-	○	-	-	-	0,00

628	Adaptive Highbeam Assist Plus		○	○	○	○	○	○	○	○	○	○	○	0,00
634	Omission of first-aid kit		○	○	○	○	○	○	○	○	○	○	○	0,00
636	Omission of hazard warning triangle		○	○	○	○	○	○	○	○	○	○	○	0,00
640	MULTIBEAM LED		-	-	-	-	-	-	-	-	-	-	-	0,00
640		not in conjunction with 318/641/642/30U/42U/43U						*	*	*	*	*	*	
641	MULTIBEAM LED		○	○	○	○	○	○	○	○	○	○	○	0,00
641		not in conjunction with 318/640/642/30U/42U/43U	*	*	*	*	*	*	*	*	*	*	*	
651	Winter complete wheels fitted		○	○	○	○	○	○	○	○	○	○	○	0,00
652	Summer complete tyres fitted		○	○	○	○	○	○	○	○	○	○	○	0,00
666	Freight packaging without tie-down hooks		○	○	○	○	○	○	○	○	○	○	○	0,00
668	Freight packaging with tie-down hooks		○	○	○	○	○	○	○	○	○	○	○	0,00
679	Product protection-partial protection		○	○	○	○	○	○	○	○	○	○	○	0,00
687	Model year on model plate		○	○	○	○	○	○	○	○	○	○	○	0,00
690	Emergency spare wheel		○	○	○	○	○	○	○	○	○	○	○	0,00
		i.V.m. S-Code 5U0	●	●	●	●	●	●	●	●	●	●	●	525,00
695	Product protection rim		○	○	○	○	○	○	○	○	○	○	○	0,00
762	Remote control unit		○	○	○	○	○	○	○	○	○	○	○	0,00
772	AMG bodystyling		○	○	○	○	○	○	○	○	○	○	○	0,00
		Available only as part of (950)	*	*	*	*	*	*	*	*	*	*	*	
		Not in conjunction with 550/L2B/U04/U12	*	*	*	*	*	*	*	*	*	*	*	
		Only in conjunction with 950+[RRG/RVQ/RVR/RVU/RVV/RWK/RWN/RZI]	*	*	*	*	*	*	*	*	*	*	*	
776	Wider wheel arch for AMG wheels		○	○	○	○	○	○	○	○	○	○	○	0,00
783	Radio remote control with panic switch		○	○	○	○	○	○	○	○	○	○	○	0,00
788	UWB module		○	○	○	○	○	○	○	○	○	○	○	0,00
		only in conjunction with 889/942	*	*	*	*	*	*	*	*	*	*	*	
801	Technical modifications		○	○	○	○	○	○	○	○	○	○	○	0,00
817	Encapsulation for ATA alarm siren		○	○	○	○	○	○	○	○	○	○	○	0,00
820	Tourist vehicle		○	○	○	○	○	○	○	○	○	○	○	0,00
822	South Africa specification		○	○	○	○	○	○	○	○	○	○	○	0,00
823	Switzerland specification		○	○	○	○	○	○	○	○	○	○	○	0,00
824	Additional parts for cold countries (engine air intake sc		-	-	-	○	○	-	-	-	○	○	○	0,00
829	Taiwan version		○	-	-	-	-	○	-	-	○	○	○	0,00
830	China specification		-	-	-	-	-	-	-	-	○	○	○	0,00
831	Italy specification		○	○	○	○	○	○	○	○	○	○	○	0,00
834	New Zealand specification		○	○	○	○	○	○	○	○	○	○	○	0,00
835	South Korea specification		○	-	○	-	-	-	-	-	○	○	○	0,00
836	Singapore specification		○	○	○	○	○	○	○	○	○	○	○	0,00
852	Sensor system for anti-theft alarm system		-	-	-	-	○	-	-	-	○	○	○	0,00
855	Telephony in the rear		●	●	●	●	●	●	●	●	●	●	●	997,50
		not in conjunction with 856	*	*	*	*	*	*	*	*	*	*	*	
882	Interior monitoring system		○	○	○	○	○	○	○	○	○	○	○	0,00
		only in conjunction with P54/P82	*	*	*	*	*	*	*	*	*	*	*	
887	Independent boot locking		●	●	●	●	●	●	●	●	●	●	●	0,00
8R3	Complete set of 4 M+S winter wheels		●	●	●	●	●	●	●	●	●	●	●	3.675,00
8R3		Not in conjunction with 4R5/4R6	*	*	*	*	*	*	*	*	*	*	*	
8R3		Only in conjunction with [RRG/RVQ/RVU/RWK/RWN/RZI]	*	*	*	*	*	*	*	*	*	*	*	
906	Armrest heating for driver and front passenger		○	○	○	○	○	○	○	○	○	○	○	0,00
		Available only as part of (P69)	*	*	*	*	*	*	*	*	*	*	*	
		Only in conjunction with P69	*	*	*	*	*	*	*	*	*	*	*	
907	Heated armrest in rear and in centre console		○	○	○	○	○	○	○	○	○	○	○	0,00
		Available only as part of (P69)	*	*	*	*	*	*	*	*	*	*	*	
		Only in conjunction with P69	*	*	*	*	*	*	*	*	*	*	*	
913	Additional parts hot countries		○	○	○	○	○	○	○	○	○	○	○	0,00
922	Reduced output engines		-	-	-	-	-	-	○	-	-	-	-	0,00
925	EU7 emissions standard		○	○	○	○	○	○	○	○	○	○	○	0,00
926	Emission control system with EU4 technology		-	-	-	○	○	-	-	-	○	○	○	0,00
927	EU6 emissions standard		○	○	○	○	○	○	○	○	○	○	○	0,00
943	Toll payment system		●	●	●	●	●	●	●	●	●	●	●	210,00
		available in conjunction with 830 as of December 2020	*	*	*	*	*	*	*	*	*	*	*	
945	Emission control system China		-	-	-	-	-	-	-	-	○	○	○	0,00
945		Only for left hand drive									*	*	*	
948	Pennant holder and pennant staff right		●	●	●	●	●	●	●	●	●	●	●	1.029,00
951	Sports package USA		-	-	-	●	●	-	-	-	●	●	●	4.483,50
951		includes Codes 772+L2D+RZI+H37+U26				*	*				*	*	*	
968	EU6 COC document without Registration Certificate Part 2		○	○	○	○	○	○	○	○	○	○	○	0,00
969	EU6 COC document with Registration Certificate Part 2		○	○	○	○	○	○	○	○	○	○	○	0,00
971	Diesel particulate filter		S	S	S	-	-	S	S	S	-	-	-	0,00
973	Designation as owner-driver rental vehicle		○	○	○	○	○	○	○	○	○	○	○	0,00
981	Omission of vehicle registration document		○	○	○	○	○	○	○	○	○	○	○	0,00
986	Identification label with VIN number		○	○	○	○	○	○	○	○	○	○	○	0,00
989	Identification label under windshield		○	○	○	○	○	○	○	○	○	○	○	0,00
994	Exhibition vehicle (B-Trade fair)		○	○	○	○	○	○	○	○	○	○	○	0,00
997	Display vehicle for exhibitions (motor show veh.)		○	○	○	○	○	○	○	○	○	○	○	0,00
B01	EQ Boost starter-alternator		-	-	-	○	○	-	-	-	○	○	○	0,00

[illegible]

		Available only as part of (P07)	*	*	*	*	*	*	*	*	*	*	*	*	
		Not in conjunction with 436/872	*	*	*	*	*	*	*	*	*	*	*	*	
		Only in conjunction with 223+276+561+P07	*	*	*	*	*	*	*	*	*	*	*	*	
546	Active Speed Limit Assist	only in conjunction with P20+513	○	○	○	○	○	○	○	○	○	○	○	○	0,00
233	Active Distance Assist DISTRONIC	Available only as part of (P20)	○	○	○	○	○	○	○	○	○	○	○	○	0,00
243	Active Lane Keeping Assist		○	○	○	○	○	○	○	○	○	○	○	○	0,00
475	Tyre pressure monitoring system		●	●	●	●	●	●	●	●	●	●	●	●	336,00
		i.V.m. S-Code 6P5	○	○	○	○	○	○	○	○	○	○	○	○	0,00
513	Traffic Sign Assist		○	○	○	○	○	○	○	○	○	○	○	○	0,00
P20	Driving Assistance package	Includes codes 233	S	S	S	S	S	S	S	S	S	S	S	S	0,00
27U	Preinstallation for INTELLIGENT PARK PILOT	Not in conjunction with 218/383/P44	○	○	○	○	○	○	○	○	○	○	○	○	0,00
		Only in conjunction with 384+7B8+889+PBH	*	*	*	*	*	*	*	*	*	*	*	*	
		use of the function by customers is only possible when national legislation permits operation of Automated Valet Pa	*	*	*	*	*	*	*	*	*	*	*	*	
503	Preinstallation for Remote Parking Assist	Available only as part of (PBH)	○	○	○	○	○	○	○	○	○	○	○	○	0,00
		Not in conjunction with 218/P44	*	*	*	*	*	*	*	*	*	*	*	*	
		Only in conjunction with 501+7B8+889+PBH	*	*	*	*	*	*	*	*	*	*	*	*	
P44	Parking package with reversing camera	Includes codes 218+235	○	○	○	○	○	○	○	○	○	○	○	○	0,00
		Not in conjunction with 216/27U/501/503/856/RRG/RVU/RVV	*	*	*	*	*	*	*	*	*	*	*	*	
		not in conjunction with P47/PBH	*	*	*	*	*	*	*	*	*	*	*	*	
P47	Parking Package with 360-degree camera	Includes codes 235+501	●	●	●	●	●	●	●	●	●	●	●	●	997,50
		Not in conjunction with 27U/503	*	*	*	*	*	*	*	*	*	*	*	*	
		not in conjunction with P44/PBH	*	*	*	*	*	*	*	*	*	*	*	*	
		i.V.m. Code PWS	○	○	○	○	○	○	○	○	○	○	○	○	0,00
PBH	Parking Package with Remote Parking functions	Includes codes 235+501+503	●	●	●	●	●	●	●	●	●	●	●	●	1.627,50
		Only in conjunction with 7B8+889	*	*	*	*	*	*	*	*	*	*	*	*	
		not in conjunction with P44/P47	*	*	*	*	*	*	*	*	*	*	*	*	
		includes 27U for certain countries	*	*	*	*	*	*	*	*	*	*	*	*	
		i.V.m. Code PWS	●	●	●	●	●	●	●	●	●	●	●	●	630,00
		i.V.m. Code PYM/PYN/PYO/PYS	○	○	○	○	○	○	○	○	○	○	○	○	0,00
947	pennant holder and pennant staff		●	●	●	●	●	●	●	●	●	●	●	●	1.029,00
916	Fuel tank with a capacity of 76 litres		●	●	●	●	●	●	●	●	●	●	●	●	105,00
		i.V.m. Code PYB	○	○	○	○	○	○	○	○	○	○	○	○	0,00
U29	Brake system with larger brake discs	Not in conjunction with 01R/4R5/51R/550	●	●	●	●	●	●	●	●	●	●	●	●	262,50
		Not in conjunction with R38	*	*	*	*	*	*	*	*	*	*	*	*	
		Not in conjunction with R41				*							*		
		not in conjunction with 4R5	*	*	*	*	*	*	*	*	*	*	*	*	
		i.V.m. Code PYH	○	○	○	○	○	○	○	○	○	○	○	○	0,00
489	AIRMATIC		S	S	S	S	S	S	S	S	S	S	S	S	0,00
961	Petrol particulate filter		-	-	-	○	-	-	-	-	-	-	○	○	0,00
481	Underguard		●	●	●	●	●	●	●	●	●	●	●	●	136,50
201	Rear-axle steering	Not in conjunction with 216/RRG/RVU/RVV	●	●	●	●	●	●	●	●	●	●	●	●	1.365,00
		Only for left hand drive	*				*								
216	Rear-axle steering	Not in conjunction with 10R/17R/201/218/P44/R16/R51/R90/RVQ/RVR/RWK/RWN/RZI	●	●	●	●	●	●	●	●	●	●	●	●	1.365,00
		Only in conjunction with 501	*	*	*	*	*	*	*	*	*	*	*	*	
		Only for left hand drive	*				*								