

802+052

2021-11-16

2022-01-21

Ap.Пpшт 309

Legend

(\*) Available at extra cost (○) available without additional charge (S) standard equipment (-) not available (L) Left hand drive only (R) Right hand drive only (NS) National Standard  
 \*+ AND (code A and B) \*/ OR (code A or B) [\*] XOR if necessary at additional charge (exact one of A,B,...) [\*] logical grouping

Code	Equipment	Restrictions	EQA		Price Euro excl. VAT	Local price excl. VAT
			243708 ECA 300 4MATIC (L)	243712 ECA 350 4MATIC (L)		
NS						
E08	Approval documentation for driving aids		●	●	120,00	126,00
		Only in conjunction with E5P	*	*		
E09	Entrance guard		●	●	190,00	199,50
		Only in conjunction with E5P	*	*		
E5P	Installation of driving aids		○	○	0,00	0,00
E65	Steering wheel knob, left		●	●	420,00	441,00
		Only in conjunction with E08+E5P	*	*		
E66	Steering wheel knob, right		●	●	420,00	441,00
		Only in conjunction with E08+E5P	*	*		
E67	"Classic" hand control unit		●	●	2.100,00	2.205,00
		Not in conjunction with E68/E83/E84/E89/E92	*	*		
		Only in conjunction with 275+E08+E5P	*	*		
E68	"Classic" leather-covered hand control unit		●	●	2.700,00	2.835,00
		Not in conjunction with E67/E83/E84/E89/E92	*	*		
		Only in conjunction with 275+E08+E5P	*	*		
E83	"Easy speed" leather-covered hand control unit		●	●	2.900,00	3.045,00
		Not in conjunction with E67/E68/E84/E92	*	*		
		Only in conjunction with 275+E08+E5P	*	*		
E84	"Easy speed" hand control unit		●	●	2.300,00	2.415,00
		Not in conjunction with E67/E68/E83/E92	*	*		
		Only in conjunction with 275+E08+E5P	*	*		
E85	Belt buckle opener for the driver		●	●	175,00	183,75
		Only in conjunction with E5P	*	*		
E87	Pedal cover		●	●	500,00	525,00
		Only in conjunction with E08+E5P	*	*		
E88	Combination switch moved to the right		●	●	250,00	262,50
		Only in conjunction with E08+E5P	*	*		
E89	Accelerator pedal moved to the left (electronic)		●	●	1.700,00	1.785,00
		Not in conjunction with E67/E68	*	*		
		Only in conjunction with E08+E5P	*	*		
E92	Pedal extenders (2)		●	●	720,00	756,00
		Not in conjunction with E67/E68/E83/E84	*	*		
		Only in conjunction with E08+E5P	*	*		
904	Supplementary standard equipment		LS	LS	265,00	0,00
		Includes codes 218 [P47]+310+537+608+738+877+890+942+P59 [950/PTD]+U12 [U26/U66]+U22 [409]	*	*		
		Not in conjunction with PBO	*	*		
P55	Night package		●	●	450,00	472,50
		Includes codes 720 [B27]+840+97R [48R/R31/R96/RQO/RTF/RVU]	*	*		
		Not in conjunction with 725/U50	*	*		
		i.V.m. Code PYH	●	●	200,00	210,00
PDA	Advanced package		●	●	2.160,00	2.268,00
		Includes codes 234 [PAY]+458+859+P44 [P47]+P49	*	*		
		Not in conjunction with PBR/PDB/PDC	*	*		
		i.V.m. Code P19	○	○	0,00	0,00
		i.V.m. Code PYM	○	○	0,00	0,00
PDB	Advanced Plus package		●	●	3.090,00	3.244,50
		Includes codes 234 [PAY]+458+581+853+859+897+P17+P44 [P47]+P49	*	*		
		Not in conjunction with PDA/PDC	*	*		
		i.V.m. Code PBO	●	●	2.730,00	2.866,50
		i.V.m. Code P19	●	●	930,00	976,50
		i.V.m. Code PYN/PYQ	○	○	0,00	0,00
PDC	Premium package		●	●	4.670,00	4.903,50
		Includes codes 234 [PAY]+458+581+810+859+897+P17+P47+P49	*	*		

802+052

2021-11-16

2022-01-21

Ap.Пршт 309

Legend

(\*) Available at extra cost (○) available without additional charge (S) standard equipment (-) not available (L) Left hand drive only (R) Right hand drive only (NS) National Standard  
 \*+ AND (code A and B) \*/ OR (code A or B) \*[] XOR if necessary at additional charge (exact one of A,B,...) \*[] logical grouping

Code	Equipment	Restrictions	EQA		Price Euro excl. VAT	Local price excl. VAT
			243708 ECA 300 4MATIC (L)	243712 ECA 350 4MATIC (L)		
		Not in conjunction with 580/B27/P44/PDA/PDB	*	*		
		available approx. as of Production 2nd Quarter 2022	*	*		
		i.V.m. Code P19	●	●	2.510,00	2.635,50
		i.V.m. Code PBO	○	○	0,00	0,00
		i.V.m. Code PYO	○	○	0,00	0,00
871	HANDS-FREE ACCESS		○	○	0,00	0,00
		Available only as part of (P17)	*	*		
		Only in conjunction with P17	*	*		
860	Vehicle key set		○	○	0,00	0,00
		Available only as part of (PTD)	*	*		
		Not in conjunction with 651A/950/P34/RQO	*	*		
		Only in conjunction with PTD	*	*		
P17	KEYLESS-GO Comfort package		●	●	360,00	378,00
		Includes codes 871+889+890	*	*		
		only in conjunction with Code PDB/PDC	*	*		
		i.V.m. Code PDC/PDB	○	○	0,00	0,00
		i.V.m. Code PYN/PYO/PYQ	○	○	0,00	0,00
144U	digital white		●	●	630,00	661,50
191U	cosmos black		●	●	630,00	661,50
667U	denim blue		●	●	630,00	661,50
775U	iridium silver		●	●	630,00	661,50
787U	mountain grey		●	●	630,00	661,50
817U	rosé gold		●	●	630,00	661,50
149U	polar white		●	●	210,00	0,00
696U	night black		LS	LS	0,00	0,00
662U	MANUFAKTUR mountain grey MAGNO		●	●	1.850,00	1.942,50
		Only in conjunction with 524	*	*		
		only in conjunction with 524	*	*		
993U	MANUFAKTUR patagonia red metallic		●	●	950,00	997,50
413	Panoramic sliding sunroof		●	●	1.170,00	1.228,50
		not in conjunction with B27	*	*		
		only in conjunction with Code PDB/PDC	*	*		
		i.V.m. Code PDC	○	○	0,00	0,00
		i.V.m. Code PYO	○	○	0,00	0,00
720	Roof rails in black		○	○	0,00	0,00
		Not in conjunction with 725/B27	*	*		
		only in conjunction with P19/P55	*	*		
725	Polished aluminium roof rails		S	S	0,00	0,00
		Not in conjunction with 720/B27/P55	*	*		
B27	Omission of roof rails		○	○	0,00	0,00
		Not in conjunction with 720/725/PDC	*	*		
		not in conjunction with 413	*	*		
586	Surround lighting with projection of brand logo		●	●	110,00	115,50
		Only in conjunction with U62	*	*		
		i.V.m. Code PYM/PYN/PYO/PYQ	○	○	0,00	0,00
608	Adaptive Highbeam Assist		S	S	0,00	0,00
632	LED High Performance headlamps		S	S	0,00	0,00
550	Trailer coupling with ESP<sup>@</sup> trailer stabilis		●	●	800,00	840,00
P54	URBAN GUARD vehicle protection		●	●	410,00	430,50
		Includes codes 551+882	*	*		
		Not in conjunction with P82	*	*		
		i.V.m. Code 362	●	●	440,00	462,00
P82	URBAN GUARD vehicle protection Plus		●	●	610,00	640,50
		Includes codes 551+882	*	*		
		Not in conjunction with P54	*	*		

802+052

2021-11-16

2022-01-21

Ap.Пpшт 309

Legend

(\*) Available at extra cost (○) available without additional charge (S) standard equipment (-) not available (L) Left hand drive only (R) Right hand drive only (NS) National Standard  
 \*+ AND (code A and B) \*/ OR (code A or B) \*[] XOR if necessary at additional charge (exact one of A,B,...) (\*) logical grouping

Code	Equipment	Restrictions	EQA		Price Euro excl. VAT	Local price excl. VAT
			243708 ECA 300 AMATIC (L)	243712 ECA 350 AMATIC (L)		
		i.V.m. Code 362	●	●	640,00	672,00
		i.V.m. Code 34U+362	●	●	540,00	567,00
R01	Summer tyres		○	○	0,00	0,00
R66	run-flat tyres		●	●	220,00	231,00
RQQ	45.7 cm (18-inch) AMG 5-spoke light-alloy wheels		○	○	0,00	0,00
		Available only as part of (950)	*	*		
		Not in conjunction with 101A/105A/111A/209A/213/321A/325A/391A/428/443/457/48R/55U/618A/698A	*	*		
		Only in conjunction with 950+R01	*	*		
RTF	48.3 cm (19-inch) AMG 5-twin-spoke light-alloy wheels		●	●	1.050,00	1.102,50
		Not in conjunction with 48R/97R/R31/R96/RQQ/RVU/RVV	*	*		
		Only in conjunction with R01	*	*		
		i.V.m. Code PTD	●	●	950,00	997,50
		i.V.m. Code 950	●	●	600,00	630,00
RVU	50.8 cm (20-inch) AMG multi-spoke alloy wheels		●	●	1.650,00	1.732,50
		Not in conjunction with 48R/97R/R31/R96/RQQ/RTF/RVV	*	*		
		Only in conjunction with R01	*	*		
		i.V.m. Code PTD	●	●	1.550,00	1.627,50
		i.V.m. Code 950	●	●	1.200,00	1.260,00
RVV	50.8 cm (20-inch) AMG multi-spoke alloy wheels		○	○	0,00	0,00
		Available only as part of (P19)	*	*		
		Not in conjunction with 48R/97R/R31/R96/RQQ/RTF/RVU	*	*		
		Only in conjunction with P19+R01	*	*		
48R	48.3 cm (19-inch) 5-spoke light-alloy wheels		●	●	550,00	577,50
		Not in conjunction with 651A/950/97R/P34/R31/R96/RQQ/RTF/RVU/RVV	*	*		
		Only in conjunction with R01	*	*		
		i.V.m. Code PTD	●	●	450,00	472,50
97R	45.7 cm (18-inch) 5-twin-spoke light-alloy wheels		●	●	200,00	210,00
		Not in conjunction with 213/457/48R/651A/950/P34/R31/R96/RQQ/RTF/RVU/RVV	*	*		
		Only in conjunction with R01	*	*		
		i.V.m. Code PTD	●	●	100,00	105,00
		i.V.m. Code P55	○	○	0,00	0,00
R31	45.7 cm (18-inch) 5-spoke light-alloy wheels		S	S	0,00	0,00
		Not in conjunction with 213/457/48R/651A/950/97R/P34/R96/RQQ/RTF/RVU/RVV	*	*		
		Only in conjunction with R01	*	*		
R96	45.7 cm (18-inch) 5-spoke light-alloy wheels		●	●	100,00	105,00
		Not in conjunction with 213/457/48R/651A/950/97R/P34/R31/RQQ/RTF/RVU/RVV	*	*		
		Only in conjunction with R01	*	*		
		i.V.m. Code PTD	○	○	0,00	0,00
B51	TIREFIT		LS	LS	50,00	0,00
4R5	Complete set of 4 M+S winter wheels		●	●	1.850,00	1.942,50
840	Heat-insulating dark-tinted glass		●	●	300,00	315,00
		Not in conjunction with U50	*	*		
		i.V.m. Code P19/P55	○	○	0,00	0,00
		i.V.m. Code PYH	○	○	0,00	0,00
875	Heated windscreen washer system		●	●	115,00	120,75
P49	Mirror package		●	●	400,00	420,00
		Includes codes 249+500+U62	*	*		
		only in conjunction with Code PDA/PDB/PDC	*	*		
		i.V.m. Code PDA/PDC/PDB	○	○	0,00	0,00
		i.V.m. Code PYM/PYN/PYO/PYQ	○	○	0,00	0,00
859	Media display		●	●	650,00	682,50
		only in conjunction with Code PDA/PDB/PDC	*	*		
		i.V.m. Code PBR/PDA/PDC/PDB	○	○	0,00	0,00
		i.V.m. Code PYM/PYN/PYO/PYQ	○	○	0,00	0,00
01U	Preinstallation for Navigation Services		○	○	0,00	0,00

802+052

2021-11-16

2022-01-21

Ар.Пршт 309

Legend

(\*) Available at extra cost (○) available without additional charge (S) standard equipment (-) not available (L) Left hand drive only (R) Right hand drive only (NS) National Standard  
 \*+ AND (code A and B) \*/ OR (code A or B) \*[] XOR if necessary at additional charge (exact one of A,B,...) \*() logical grouping

Code	Equipment	Restrictions	EQA		Price Euro excl. VAT	Local price excl. VAT
			243708 ECA 300 4MATIC (L)	243712 ECA 350 4MATIC (L)		
		Available only as part of (PBF)	*	*		
		Only in conjunction with 270+355+PBF	*	*		
355	Extended MBUX functions	Only in conjunction with 270+365	○	○	0,00	0,00
365	Hard-disc navigation	Only in conjunction with 270+355	○	○	0,00	0,00
367	Preinstallation for Live Traffic Information	Only in conjunction with 270+355+365	○	○	0,00	0,00
PBF	Navigation Connectivity package	Includes codes 01U+365	●	●	100,00	105,00
		Only in conjunction with 270+355	*	*		
537	Digital radio	Only in conjunction with 79B	○	○	0,00	0,00
548	MBUX multimedia system	Not in conjunction with 549	○	○	0,00	0,00
PAU	MBUX Innovation package	Includes codes 463+77B	●	●	1.150,00	1.207,50
		Only in conjunction with 859	*	*		
		only in conjunction with PDA/PDB/PDC	*	*		
		i.V.m. Code PYQ/PYQ	○	○	0,00	0,00
810	Burmester® surround sound system	Not in conjunction with 853	●	●	725,00	761,25
		available approx. as of Production 2nd Quarter 2022	*	*		
		only in conjunction with PDC	*	*		
		i.V.m. Code PBR/PDB	●	●	415,00	435,75
		i.V.m. Code PDC	○	○	0,00	0,00
		i.V.m. Code PYQ	○	○	0,00	0,00
853	Advanced Sound System	Available only as part of (PDB)	●	●	310,00	325,50
		Not in conjunction with 810/PDA/PDC	*	*		
		Only in conjunction with PDB	*	*		
		i.V.m. Code PBR/PDB	○	○	0,00	0,00
		i.V.m. Code PYN/PYQ	○	○	0,00	0,00
14U	Smartphone Integration	Only in conjunction with 16U+17U	●	●	300,00	315,00
		i.V.m. Code PBO	○	○	0,00	0,00
897	Wireless charging system for mobile devices in the front	only in conjunction with PDB/PDC	●	●	200,00	210,00
		i.V.m. Code PDC/PDB	○	○	0,00	0,00
		i.V.m. Code PYN/PYQ/PYQ	○	○	0,00	0,00
21U	Dash cam	Only in conjunction with 270+355+365	●	●	200,00	210,00
		available approx. as of Production 2nd Quarter 2022	*	*		
443	Steering wheel heating	Not in conjunction with 431/651A/950/L3E/L5C/L5I/P34/RQQ	●	●	160,00	168,00
		Only in conjunction with 428+L3B	*	*		
580	THERMATIC automatic climate control	Not in conjunction with 581/PBR/PDC	S	S	0,00	0,00
581	THERMOTRONIC automatic climate control	Not in conjunction with 580	LS	LS	510,00	0,00
		only in conjunction with PBN/PDB/PDC	*	*		
		i.V.m. Code PBR/PDC/PDB	○	○	0,00	0,00
		i.V.m. Code PYD/PYH/PYN/PYO	○	○	0,00	0,00
		i.V.m. Code PYQ	○	○	0,00	0,00
890	EASY-PACK tailgate		S	S	0,00	0,00

802+052

2021-11-16

2022-01-21

Ap.Пршт 309

Legend

(\*) Available at extra cost (○) available without additional charge (S) standard equipment (-) not available (L) Left hand drive only (R) Right hand drive only (NS) National Standard  
 \*+ AND (code A and B) \*/ OR (code A or B) \*[] XOR if necessary at additional charge (exact one of A,B,...) \*[] logical grouping

Code	Equipment	Restrictions	EQA		Price Euro excl. VAT	Local price excl. VAT
			243708 ECA 300 4MATIC (L)	243712 ECA 350 4MATIC (L)		
942	Load Compartment package		●	●	150,00	157,50
		Only in conjunction with B13+U35	*	*		
		i.V.m. Code PBO/904	○	○	0,00	0,00
U40	Partition net		●	●	150,00	157,50
PBR	ENERGIZING package Plus		●	●	2.195,00	2.304,75
		Includes codes 409 [950]+581+853 [810]+859+873 [401]+877+P59 [950/PTD]	*	*		
		Not in conjunction with 580/PDA	*	*		
		Only in conjunction with 270+355+365	*	*		
		available approx. as of Production 2nd Quarter 2022	*	*		
		only in conjunction with Code PDB/PDC	*	*		
		i.V.m. Code 7U4	●	●	1.760,00	1.848,00
U12	Velour floor mats		●	●	80,00	84,00
		Not in conjunction with 651A/950/P34/RQQ/U66	*	*		
		i.V.m. Code PBO/904	○	○	0,00	0,00
U26	AMG floor mats		○	○	0,00	0,00
		Available only as part of (950)	*	*		
		Not in conjunction with 101A/105A/111A/209A/321A/325A/391A/428/443/48R/55U/618A/698A/97R/L38	*	*		
		Only in conjunction with 950	*	*		
U45	Door sills with model-series-specific lettering, illuminated		●	●	170,00	178,50
		only in conjunction with PTD/950	*	*		
		i.V.m. Code 950/PTD	○	○	0,00	0,00
		i.V.m. Code PYH/PYD	○	○	0,00	0,00
U66	Floor mats for special model		○	○	0,00	0,00
		Available only as part of (P19)	*	*		
		Not in conjunction with U12/U26	*	*		
		Only in conjunction with P19	*	*		
458	All-digital instrument display		●	●	450,00	472,50
		only in conjunction with Code PDA/PDB/PDC+859	*	*		
		i.V.m. Code PDA/PDC/PDB	○	○	0,00	0,00
		i.V.m. Code PYM/PYN/PYO/PYQ	○	○	0,00	0,00
463	Head-up Display		●	●	990,00	1.039,50
		only in conjunction with PAU	*	*		
		i.V.m. Code PAU	○	○	0,00	0,00
		i.V.m. Code PYQ/PYQ	○	○	0,00	0,00
U19	MBUX augmented reality for navigation		●	●	390,00	409,50
		Only in conjunction with 270+355+365+859	*	*		
		available approx. as of Production 2nd Quarter 2022	*	*		
		i.V.m. Code PYN/PYO/PYQ	○	○	0,00	0,00
877	Ambient lighting		S	S	0,00	0,00
U62	Light and Sight package		S	S	0,00	0,00
51U	Roof liner in black fabric		S	S	0,00	0,00
		Not in conjunction with 55U/58U	*	*		
55U	Roof liner in macchiato beige fabric		○	○	0,00	0,00
		Not in conjunction with 111A/51U/58U/618A/651A/698A/7U4/950/P34/RQQ	*	*		
		only in conjunction with 105A/325A	*	*		
58U	Roof liner in crystal grey fabric		○	○	0,00	0,00
		Not in conjunction with 105A/209A/325A/51U/55U	*	*		
7U2	Comfort Seats		S	S	0,00	0,00
		Not in conjunction with 111A/618A/651A/698A/7U4/P34	*	*		
		Only in conjunction with 286+U59	*	*		
7U4	Sports seats		○	○	0,00	0,00
		Not in conjunction with 101A/105A/209A/321A/325A/391A/409/55U/7U2	*	*		
		Only in conjunction with 286+U59	*	*		
242	Power front right seat with memory function		●	●	285,00	299,25
		Only in conjunction with 275	*	*		

802+052

2021-11-16

2022-01-21

Ap.Пpшт 309

Legend

(\*) Available at extra cost (○) available without additional charge (S) standard equipment (-) not available (L) Left hand drive only (R) Right hand drive only (NS) National Standard  
 \*+ AND (code A and B) \*/ OR (code A or B) \*[] XOR if necessary at additional charge (exact one of A,B,...) \*[] logical grouping

Code	Equipment	Restrictions	EQA		Price Euro excl. VAT	Local price excl. VAT
			243708 EQA 300 4MATIC (L)	243712 EQA 350 4MATIC (L)		
		only in conjunction with 275+U22/409/PBN/PBO	*	*		
		i.V.m. Code PYQ/PYQ	○	○	0,00	0,00
275	Driver's seat, electrically adjustable with memory function		●	●	345,00	362,25
		only in conjunction with U22/409/PBN/PBO	*	*		
		i.V.m. Code PYQ/PYQ	○	○	0,00	0,00
401	Climatised front seats		●	●	890,00	934,50
		Not in conjunction with 873	*	*		
		only in conjunction with 101A/105A/211A	*	*		
		i.V.m. Code PBR/P34	●	●	600,00	630,00
		i.V.m. Code PYN/PYQ/PYQ	●	●	600,00	630,00
409	Multicontour Seat package		●	●	435,00	456,75
		Not in conjunction with 111A/209A/321A/325A/391A/618A/651A/698A/7U4/P34/U22	*	*		
		Only in conjunction with 286+7U2+U59	*	*		
		i.V.m. Code PBR	○	○	0,00	0,00
873	Heated front seats		●	●	290,00	304,50
		Not in conjunction with 401	*	*		
		i.V.m. Code PBR/P19/P34	○	○	0,00	0,00
		i.V.m. Code PYN/PYQ/PYQ	○	○	0,00	0,00
U22	4-way lumbar support		S	S	0,00	0,00
		Not in conjunction with 409	*	*		
		Only in conjunction with U59	*	*		
U59	Seat Comfort package		S	S	0,00	0,00
446	Touchpad without Controller		S	S	0,00	0,00
77B	MBUX Interior Assistant		●	●	300,00	315,00
		Available only as part of (PAU)	*	*		
		Only in conjunction with 859+PAU	*	*		
		i.V.m. Code PAU	○	○	0,00	0,00
		i.V.m. Code PYQ/PYQ	○	○	0,00	0,00
L3B	Multifunction sports steering wheel in nappa leather		○	○	0,00	0,00
		Not in conjunction with 431/651A/950/L3E/L5C/L51/P34/RQQ	*	*		
		Only in conjunction with 428+443	*	*		
L3E	Leather multifunction sports steering wheel		S	S	0,00	0,00
		Not in conjunction with 431/443/651A/950/L3B/L5C/L51/P34/RQQ	*	*		
		Only in conjunction with 428	*	*		
L5C	Multifunction sports steering wheel in nappa leather		○	○	0,00	0,00
		Not in conjunction with 428/443/L3B/L3E/L51	*	*		
		Only in conjunction with 431	*	*		
		only in conjunction with 950/PTD/P19	*	*		
L51	Multifunction sports steering wheel in nappa leather /		●	●	230,00	241,50
		Not in conjunction with 428/443/L3B/L3E/L5C	*	*		
		Only in conjunction with 431	*	*		
		only in conjunction with 950	*	*		
310	Double cup holder		S	S	0,00	0,00
73B	Stowage compartment in centre console with retractable lid		●	●	35,00	36,75
		i.V.m. Code PBO/904	○	○	0,00	0,00
331	Backlit trim		○	○	0,00	0,00
		Not in conjunction with H15/H23/H44	*	*		
		only in conjunction with 54H	*	*		
54H	Spiral-look trim elements, backlit		●	●	150,00	157,50
		Not in conjunction with H15/H23/H44/H60	*	*		
		only in conjunction with 950/PTD	*	*		
		i.V.m. Code PTD/950	○	○	0,00	0,00
		i.V.m. Code PYD/PYH	○	○	0,00	0,00
H15	Black open-pore linden wood trim		●	●	300,00	315,00
		Not in conjunction with 331/54H/H23/H44/H60	*	*		

802+052

2021-11-16

2022-01-21

Ap.Пршт 309

Legend

(\*) Available at extra cost (○) available without additional charge (S) standard equipment (-) not available (L) Left hand drive only (R) Right hand drive only (NS) National Standard  
 \*+ AND (code A and B) \*/ OR (code A or B) \*[] XOR if necessary at additional charge (exact one of A,B,...) \*[] logical grouping

Code	Equipment	Restrictions	EQA		Price Euro excl. VAT	Local price excl. VAT
			243708 EQA 300 4MATIC (L)	243712 EQA 350 4MATIC (L)		
		i.V.m. Code PTD/950	●	●	150,00	157,50
H23	Brown open-pore walnut wood trim		●	●	300,00	315,00
		Not in conjunction with 331/54H/H15/H44/H60	*	*		
		i.V.m. Code 950	●	●	150,00	157,50
H44	Light longitudinal-grain aluminium trim		●	●	200,00	210,00
		Not in conjunction with 331/54H/H15/H23/H60	*	*		
		i.V.m. Code 950	●	●	50,00	52,50
H60	Spiral-look trim elements		S	S	0,00	0,00
		Not in conjunction with 54H/H15/H23/H44	*	*		
101A	black		●	●	145,00	152,25
		Not in conjunction with 111A/618A/651A/698A/7U4/950/P34/RQQ	*	*		
		Only in conjunction with 286+7U2+P59+U59	*	*		
105A	macchiato beige / black		●	●	245,00	257,25
		Not in conjunction with 111A/58U/618A/651A/698A/7U4/950/P34/RQQ	*	*		
		Only in conjunction with 286+7U2+P59+U59	*	*		
391A	rosé gold / titanium grey pearl		○	○	0,00	0,00
		Not in conjunction with 111A/409/618A/651A/698A/7U4/950/P34/RQQ	*	*		
		Only in conjunction with 286+7U2+U59	*	*		
651A	black		○	○	0,00	0,00
		Available only as part of (950)	*	*		
		Not in conjunction with 101A/105A/111A/209A/321A/325A/391A/409/428/443/48R/55U/618A/698A/7U4/950/P34/RQQ	*	*		
		Only in conjunction with 286+7U4+950+U59	*	*		
321A	black		○	○	0,00	0,00
		Not in conjunction with 111A/409/618A/651A/698A/7U4/950/P34/RQQ	*	*		
		Only in conjunction with 286+7U2+U59	*	*		
325A	macchiato beige / black		●	●	100,00	105,00
		Not in conjunction with 111A/409/58U/618A/651A/698A/7U4/950/P34/RQQ	*	*		
		Only in conjunction with 286+7U2+U59	*	*		
209A	neva grey with CYBER CUT blue		○	○	0,00	0,00
		Available only as part of (P19)	*	*		
		Not in conjunction with 111A/409/58U/618A/651A/698A/7U4/950/P34/RQQ	*	*		
		Only in conjunction with 286+7U2+P19+U59	*	*		
211A	black		○	○	0,00	0,00
		Available only as part of (P34)	*	*		
		Not in conjunction with 101A/105A/111A/209A/321A/325A/391A/409/428/443/48R/55U/618A/698A/7U4/950/P34/RQQ	*	*		
		Only in conjunction with 286+7U4+950+P34+U59	*	*		
P34	Leather package		●	●	1.290,00	1.354,50
		Includes codes 211A+873 [401]	*	*		
		Not in conjunction with 101A/105A/111A/209A/321A/325A/391A/409/428/443/48R/55U/618A/698A/7U4/950/P34/RQQ	*	*		
		Only in conjunction with 286+7U4+950+U59	*	*		
		i.V.m. Code PBR	●	●	1.000,00	1.050,00
		i.V.m. Code PYN/PYO/PYQ	●	●	1.000,00	1.050,00
950	AMG Line		●	●	2.990,00	3.139,50
		Includes codes 431+54H [H15/H23/H44]+651A [211A]+725 [720/B27]+772+L5C [L5J]+RQQ [RTF/RVU]+U26+U59	*	*		
		Not in conjunction with 101A/105A/111A/209A/321A/325A/391A/428/443/48R/55U/618A/698A/97R/L38	*	*		
		i.V.m. Code PYH	○	○	0,00	0,00
P59	Progressive		S	S	0,00	0,00
		Includes codes 321A [101A/105A/111A/325A]+725 [720/B27]+H60 [H15/H23/H44]+L3E [L3B]+R31 [48R/97R/L38]	*	*		
		Not in conjunction with 651A/950/P34/RQQ	*	*		
PTD	Electric Art		●	●	790,00	829,50
		Includes codes 391A [209A/618A/698A]+54H [H15/H23]+725 [720/B27]+B60+L5C [L3B]+R96 [48R/97R/RTF/L38]	*	*		
		Not in conjunction with 651A/950/P34/RQQ	*	*		
		i.V.m. Code P19	○	○	0,00	0,00
		i.V.m. Code PYD	○	○	0,00	0,00
362	Communications module (LTE) for the use of Mercedes		○	○	0,00	0,00

802+052

2021-11-16

2022-01-21

Ap.Пршт 309

Legend

(\*) Available at extra cost (○) available without additional charge (S) standard equipment (-) not available (L) Left hand drive only (R) Right hand drive only (NS) National Standard  
 "+ AND (code A and B) "/" OR (code A or B) "[ ]" XOR if necessary at additional charge (exact one of A,B,...) "( )" logical grouping

Code	Equipment	Restrictions	EQA		Price Euro excl. VAT	Local price excl. VAT
			243708 ECA 300 4MATIC (L)	243712 ECA 350 4MATIC (L)		
13U	Preinstallation for Remote and Navigation Services		○	○	0,00	0,00
20U	Preinstallation for digital key transfer		●	●	50,00	52,50
		i.V.m. Code PYA	○	○	0,00	0,00
34U	Remote Services Premium		●	●	250,00	262,50
351	Mercedes-Benz emergency call system		○	○	0,00	0,00
36U	Remote and extended Charging Services Premium		●	●	760,00	798,00
		Not in conjunction with 38U/39U	*	*		
38U	Remote and Charging Services Plus		LS	LS	265,00	0,00
		Not in conjunction with 35U/36U/39U	*	*		
		only in conjunction with 362+13U+365	*	*		
39U	Remote and Charging Services Premium		●	●	525,00	551,25
		Not in conjunction with 35U/36U/38U	*	*		
		only in conjunction with 362+13U+365	*	*		
00B	Owner's Manual and service information - Danish		○	○	0,00	0,00
		Not in conjunction with 01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/12B/13B/14B/15B/16B/17B	*	*		
01B	Owner's Manual and service information - Dutch		○	○	0,00	0,00
		Not in conjunction with 00B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/12B/13B/14B/15B/16B/17B	*	*		
02B	Owner's Manual and service information - German		○	○	0,00	0,00
		Not in conjunction with 00B/01B/03B/04B/05B/06B/07B/08B/09B/10B/11B/12B/13B/14B/15B/16B/17B	*	*		
03B	Owner's Manual and service information - Russian		○	○	0,00	0,00
		Not in conjunction with 00B/01B/02B/04B/05B/06B/07B/08B/09B/10B/11B/12B/13B/14B/15B/16B/17B	*	*		
04B	Owner's Manual and service information - Finnish		○	○	0,00	0,00
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/12B/13B/14B/15B/16B/17B	*	*		
05B	Owner's Manual and service information - English		○	○	0,00	0,00
		Not in conjunction with 00B/01B/02B/03B/04B/06B/07B/08B/09B/10B/11B/12B/13B/14B/15B/16B/17B	*	*		
06B	Owner's Manual and service information - Italian		○	○	0,00	0,00
		Not in conjunction with 00B/01B/02B/03B/04B/05B/07B/08B/09B/10B/11B/12B/13B/14B/15B/16B/17B	*	*		
07B	Owner's Manual and service information - French		○	○	0,00	0,00
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/08B/09B/10B/11B/12B/13B/14B/15B/16B/17B	*	*		
08B	Owner's Manual and service information - Spanish		○	○	0,00	0,00
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/09B/10B/11B/12B/13B/14B/15B/16B/17B	*	*		
09B	Owner's Manual and service information - Portuguese		○	○	0,00	0,00
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/10B/11B/12B/13B/14B/15B/16B/17B	*	*		
10B	Owner's Manual and service information - Swedish		○	○	0,00	0,00
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/11B/12B/13B/14B/15B/16B/17B	*	*		
111A	ARTICO man-made leather black		●	●	145,00	152,25
		Not in conjunction with 101A/105A/209A/321A/325A/391A/409/55U/651A/7U2/950/P34/RQQ	*	*		
		Only in conjunction with 286+7U4+P59+U59	*	*		
115A	ARTICO man-made leather, sport seat beige		●	●	245,00	257,25
		for China only	*	*		
11B	Owner's Manual and service information - Arabic		○	○	0,00	0,00
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/12B/13B/14B/15B/16B/17B	*	*		
12B	Owner's Manual and service information - English USA		○	○	0,00	0,00
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/13B/14B/15B/16B/17B	*	*		
12U	Preinstallation for Concierge Service		○	○	0,00	0,00
13B	Owner's Manual and service information - Norwegian		○	○	0,00	0,00
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/12B/14B/15B/16B/17B	*	*		
14B	Owner's Manual and service information - Greek		○	○	0,00	0,00
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/12B/13B/15B/16B/17B	*	*		
15B	Owner's Manual and service information - Turkish		○	○	0,00	0,00
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/12B/13B/14B/16B/17B	*	*		
15U	Pre-installation for Mercedes-Benz Link		○	○	0,00	0,00
16B	Owner's Manual and service information - Polish		○	○	0,00	0,00
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/12B/13B/14B/15B/17B	*	*		
16U	Apple CarPlay		○	○	0,00	0,00



802+052

2021-11-16

2022-01-21

Ap.Пршт 309

Legend

(\*) Available at extra cost (○) available without additional charge (S) standard equipment (-) not available (L) Left hand drive only (R) Right hand drive only (NS) National Standard  
 "+ AND (code A and B) "/" OR (code A or B) "[ ]" XOR if necessary at additional charge (exact one of A,B,...) "( )" logical grouping

Code	Equipment	Restrictions	EQA		Price Euro excl. VAT	Local price excl. VAT
			243708 ECA 300 4MATIC (L)	243712 ECA 350 4MATIC (L)		
		Only in conjunction with 14U+17U	*	*		
17B	Owner's Manual and service information - Czech		○	○	0,00	0,00
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/12B/13B/14B/15B/16B	*	*		
17U	Android Auto		○	○	0,00	0,00
		Only in conjunction with 14U+16U	*	*		
18B	Owner's Manual and service information - English South		○	○	0,00	0,00
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/12B/13B/14B/15B/16B	*	*		
18U	Baidu Carlife		○	○	0,00	0,00
		for China only	*	*		
19B	Owner's Manual and service information - French South		○	○	0,00	0,00
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/12B/13B/14B/15B/16B	*	*		
1P0	Sonderpreis		○	○	0,00	0,00
20B	Owner's Manual and service information - Spanish South		○	○	0,00	0,00
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/12B/13B/14B/15B/16B	*	*		
213	Direct-Steer system		○	○	0,00	0,00
		Not in conjunction with 485/677/97R/R31/R96/RQ0	*	*		
		Only in conjunction with 457	*	*		
218	Reversing camera		S	S	0,00	0,00
		Not in conjunction with P47	*	*		
21B	Owner's Manual and service information - Portuguese South		○	○	0,00	0,00
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/12B/13B/14B/15B/16B	*	*		
221	Electrically adjustable front seat, left		●	●	225,00	236,25
		for China only	*	*		
222	Electrically adjustable front seat, right		●	●	225,00	236,25
		for China only	*	*		
22B	Owner's Manual and service information - Japanese		○	○	0,00	0,00
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/12B/13B/14B/15B/16B	*	*		
232	Garage door opener (frequency range 284-390 MHz)		●	●	225,00	236,25
23B	Owner's Manual and service information - simplified Chinese		○	○	0,00	0,00
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/12B/13B/14B/15B/16B	*	*		
241	Power front left seat with memory function		●	●	285,00	299,25
		only in conjunction with 275+U22/409	*	*		
		i.V.m. Code PYQ/PYQ	○	○	0,00	0,00
249	Interior mirror and driver's exterior mirror automatically		○	○	0,00	0,00
		Available only as part of (P49)	*	*		
		Only in conjunction with P49	*	*		
24B	Owner's Manual and service information - traditional Chinese		○	○	0,00	0,00
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/12B/13B/14B/15B/16B	*	*		
25B	Owner's Manual and service information - Korean		○	○	0,00	0,00
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/12B/13B/14B/15B/16B	*	*		
263	Number plate mounting for Asia / Mexico		○	○	0,00	0,00
		Not in conjunction with 264/968	*	*		
264	Number plate mounting for America		○	○	0,00	0,00
		Not in conjunction with 263/968	*	*		
266	Active Steering Assist		○	○	0,00	0,00
		Not in conjunction with 234/243/258/440	*	*		
		Only in conjunction with 233	*	*		
26B	Owner's Manual and service information - Chinese Taiwan		○	○	0,00	0,00
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/12B/13B/14B/15B/16B	*	*		
270	Aerial for GPS		○	○	0,00	0,00
27B	Owner's Manual and Service Booklet - Spanish Mexico		○	○	0,00	0,00
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/12B/13B/14B/15B/16B	*	*		
286	Luggage net on driver's and front pass. backrest		S	S	0,00	0,00
287	Folding rear-seat backrests		S	S	0,00	0,00
30B	Owner's Manual and service information - Slovenian		○	○	0,00	0,00

802+052

2021-11-16

2022-01-21

Ap.Пршт 309

Legend

(\*) Available at extra cost (○) available without additional charge (S) standard equipment (-) not available (L) Left hand drive only (R) Right hand drive only (NS) National Standard  
 \*+ AND (code A and B) \*/ OR (code A or B) \*[] XOR if necessary at additional charge (exact one of A,B,...) \*[] logical grouping

Code	Equipment	Restrictions	EQA		Price Euro excl. VAT	Local price excl. VAT
			243708 ECA 300 4MATIC (L)	243712 ECA 350 4MATIC (L)		
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/12B/13B/14B/15B/16B	*	*		
31B	Owner's Manual and service information - Hungarian		○	○	0,00	0,00
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/12B/13B/14B/15B/16B	*	*		
32B	Owner's Manual and service information - Bulgarian		○	○	0,00	0,00
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/12B/13B/14B/15B/16B	*	*		
33B	Owner's Manual and service information - Romanian		○	○	0,00	0,00
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/12B/13B/14B/15B/16B	*	*		
33U	Remote Services Plus		●	●	150,00	157,50
345	Windscreen wipers with rain sensor		S	S	0,00	0,00
34B	Owner's Manual and service information - Croatian		○	○	0,00	0,00
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/12B/13B/14B/15B/16B	*	*		
353U	hydro silver metallic		●	●	630,00	661,50
		for China only	*	*		
35B	Owner's Manual and service information - Latvian		○	○	0,00	0,00
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/12B/13B/14B/15B/16B	*	*		
35U	Remote and extended Charging Services Plus		●	●	500,00	525,00
		Not in conjunction with 38U/39U	*	*		
36B	Owner's Manual and service information - Lithuanian		○	○	0,00	0,00
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/12B/13B/14B/15B/16B	*	*		
37B	Owner's Manual and service information - Slovak		○	○	0,00	0,00
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/12B/13B/14B/15B/16B	*	*		
38B	Owner's Manual and service information - Estonian		○	○	0,00	0,00
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/12B/13B/14B/15B/16B	*	*		
390	Maintenance Service		○	○	0,00	0,00
391	Pick-up and Delivery Service		○	○	0,00	0,00
		Only in conjunction with 390	*	*		
392	Wear Parts package		○	○	0,00	0,00
		Only in conjunction with 390	*	*		
393	Vehicle warranty extension		○	○	0,00	0,00
39B	Owner's Manual and service information - Serbian		○	○	0,00	0,00
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/12B/13B/14B/15B/16B	*	*		
400	Rear armrest		S	S	0,00	0,00
40B	Owner's Manual and service information - Ukrainian		○	○	0,00	0,00
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/12B/13B/14B/15B/16B	*	*		
41B	Owner's Manual and service information - Hebrew		○	○	0,00	0,00
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/12B/13B/14B/15B/16B	*	*		
42B	Steering wheel shift paddles		S	S	0,00	0,00
		Not in conjunction with 431/651A/950/L5C/L5I/P34/RQQ	*	*		
42B	Owner's Manual and service information - Indonesian		○	○	0,00	0,00
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/12B/13B/14B/15B/16B	*	*		
431	Galvanised steering-wheel gearshift paddles		○	○	0,00	0,00
		Not in conjunction with 42B/443/L3B/L3E	*	*		
43B	Owner's Manual and service information - Thai		○	○	0,00	0,00
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/12B/13B/14B/15B/16B	*	*		
440	Cruise control		S	S	0,00	0,00
		Not in conjunction with 233/266/546/K33/K34	*	*		
44B	Owner's Manual and service information - Vietnamese		○	○	0,00	0,00
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/12B/13B/14B/15B/16B	*	*		
461	Instrument display in miles with English lettering		○	○	0,00	0,00
496	Mexico version		○	○	0,00	0,00
498	Japan specification		○	○	0,00	0,00
500	Electrically folding exterior mirrors		○	○	0,00	0,00
		Available only as part of (P49)	*	*		
		Only in conjunction with P49	*	*		
501	360° camera		○	○	0,00	0,00

802+052

2021-11-16

2022-01-21

Ap.Пpшт 309

Legend

(\*) Available at extra cost (○) available without additional charge (S) standard equipment (-) not available (L) Left hand drive only (R) Right hand drive only (NS) National Standard  
 \*+ AND (code A and B) \*/ OR (code A or B) \*[] XOR if necessary at additional charge (exact one of A,B,...) \*[] logical grouping

Code	Equipment	Restrictions	EQA		Price Euro excl. VAT	Local price excl. VAT
			243708 EQA 300 4MATIC (L)	243712 EQA 350 4MATIC (L)		
		Available only as part of (P47)	*	*		
		Not in conjunction with 218/P44	*	*		
		Only in conjunction with P47	*	*		
517	HD digital radio standard		○	○	0,00	0,00
524	Transport protection (full body cover)		○	○	0,00	0,00
543	Sun visor with illuminated vanity mirror		S	S	0,00	0,00
549	MBUX multimedia system		○	○	0,00	0,00
		Not in conjunction with 548	*	*		
551	Anti-theft alarm system		●	●	250,00	262,50
		only in conjunction with P54/P82	*	*		
		i.V.m. Code P54/P82	○	○	0,00	0,00
552	Anti-theft alarm system		●	●	250,00	262,50
		for Belgium only	*	*		
618A	ARTICO man-made leather / Montfoort fabric crystal gr		●	●	100,00	105,00
		Not in conjunction with 101A/105A/209A/321A/325A/391A/409/55U/651A/7U2/950/P34/RQO	*	*		
		Only in conjunction with 286+7U4+U59	*	*		
		for China only	*	*		
623	Gulf States specification		○	○	0,00	0,00
625	Australia specification		-	○	0,00	0,00
631	LED High Performance headlamp		S	S	0,00	0,00
634	Omission of first-aid kit		○	○	0,00	0,00
636	Omission of warning triangle		○	○	0,00	0,00
63B	Charging socket		○	○	0,00	0,00
		Not in conjunction with 64B/65B/66B	*	*		
64B	Vehicle socket		○	○	0,00	0,00
		Not in conjunction with 63B/65B/66B/9B2/9B3/9B6/9B7	*	*		
651	Winter complete wheels fitted		○	○	0,00	0,00
		Not in conjunction with 652	*	*		
		Only in conjunction with 4R5	*	*		
652	Summer complete tyres fitted		○	○	0,00	0,00
		Not in conjunction with 651	*	*		
		Only in conjunction with 4R5	*	*		
65B	Charging socket		○	○	0,00	0,00
		Not in conjunction with 63B/64B/66B/9B2/9B3/9B6/9B7	*	*		
666	Freight packaging without tie-down hooks		●	●	25,00	26,25
		Not in conjunction with 668	*	*		
668	Prod. prot. f. freight pkging with tie-down hooks		●	●	25,00	26,25
		Not in conjunction with 666	*	*		
66B	Charging socket		○	○	0,00	0,00
		Not in conjunction with 63B/64B/65B/9B2/9B3/9B6/9B7	*	*		
687	Type plate with model year		○	○	0,00	0,00
		Not in conjunction with 968	*	*		
698A	FABRIC / LEATHERETTE / MICROFIBER - GREY		●	●	100,00	105,00
		Not in conjunction with 101A/105A/209A/321A/325A/391A/409/55U/651A/7U2/950/P34/RQO	*	*		
		Only in conjunction with 286+7U4+U59	*	*		
700	Produktionsstandort Fahrzeug China		○	○	0,00	0,00
762	Remote control unit		○	○	0,00	0,00
763	Key with Radio remote control with panic switch		○	○	0,00	0,00
		für Mexico only	*	*		
772	AMG bodystyling		○	○	0,00	0,00
		only in conjunction with 950/P19	*	*		
79B	Preinstallation for digital radio		○	○	0,00	0,00
802	Technical modifications		○	○	0,00	0,00
81B	Alternating current charging system (AC charging)		○	○	0,00	0,00
		Not in conjunction with 82B	*	*		

802+052

2021-11-16

2022-01-21

Ap.Пpшт 309

Legend

(\*) Available at extra cost (○) available without additional charge (S) standard equipment (-) not available (L) Left hand drive only (R) Right hand drive only (NS) National Standard  
 "+\* AND (code A and B) \*/" OR (code A or B) "[ ]" XOR if necessary at additional charge (exact one of A,B,...) "( )" logical grouping

Code	Equipment	Restrictions	EQA		Price Euro excl. VAT	Local price excl. VAT
			243708 EQA 300 4MATIC (L)	243712 EQA 350 4MATIC (L)		
820	Tourist vehicle		○	○	0,00	0,00
821	Country code Brazil		○	○	0,00	0,00
822	South Africa specification		○	○	0,00	0,00
823	Indicator plate fixing Switzerland		○	○	0,00	0,00
829	Taiwan version		○	○	0,00	0,00
830	China specification		○	○	0,00	0,00
831	Indicator plate fixing Italia		○	○	0,00	0,00
832	INDIA SPECIFICATION		○	○	0,00	0,00
834	New Zealand specification		-	○	0,00	0,00
859U	mojave silver metallic		●	●	630,00	661,50
		for China only	*	*		
865	TV receiver		●	●	900,00	945,00
		for Japan only	*	*		
882	Interior monitoring system		○	○	0,00	0,00
		only in conjunction with P54/P82	*	*		
885	Increased anti-theft protection		○	○	0,00	0,00
		for 537L only	*	*		
889	KEYLESS-GO		●	●	400,00	420,00
		only in conjunction with PDB/PDC/PBO/PBN	*	*		
		i.V.m. Code P17/PBO	○	○	0,00	0,00
896U	brilliant blue metallic		●	●	630,00	661,50
943	Toll payment system		●	●	200,00	210,00
		for China only	*	*		
968	COC document EU6 without registration certificate part I		○	○	0,00	0,00
		Not in conjunction with 263/264/687	*	*		
969	COC document EU6 with registration certificate part II		○	○	0,00	0,00
973	Designation as owner-driver rental vehicle		○	○	0,00	0,00
981	Omission of vehicle registration document		○	○	0,00	0,00
986	Identification no. (US-VIN)		○	○	0,00	0,00
989	Identification label under windshield		○	○	0,00	0,00
994	Exhibition vehicle (B-Trade fair)		○	○	0,00	0,00
997	Exhibition vehicle		○	○	0,00	0,00
9B7	Charging cable for wallbox and public charging station		●	●	70,00	73,50
		Not in conjunction with 64B/65B/66B/9B2/9B3/9B6	*	*		
		Only in conjunction with 63B	*	*		
B08	Fanfares for Asia		○	○	0,00	0,00
B12	Tyre-change toolkit		●	●	50,00	52,50
B13	Shoulderline trim strip in chrome-look finish		S	S	0,00	0,00
		Only in conjunction with 942+U35	*	*		
B21	Charging cable for domestic socket, 5 m, straight		●	●	240,00	252,00
		Not in conjunction with B31/B35/B36/B39/B40/B41/B80/B81/B84/B85/B86/B88/B89/B93/B94/B96/B98	*	*		
B35	Charging cable for domestic socket, 5 m, straight		●	●	240,00	252,00
		Not in conjunction with B21/B22/B30/B31/B36/B39/B40/B41/B44/B47/B48/B49/B70/B71/B73/B75/B77	*	*		
B36	Charging cable for domestic socket, 5 m, straight		●	●	240,00	252,00
		Not in conjunction with B21/B22/B30/B31/B35/B36/B39/B40/B41/B44/B47/B48/B49/B70/B71/B73/B75/B77	*	*		
B37	Charging cable for domestic socket, 5 m, straight		○	○	0,00	0,00
		Not in conjunction with B84/B95	*	*		
B39	Charging cable for domestic socket, 5 m, straight		●	●	240,00	252,00
		Not in conjunction with B21/B22/B30/B31/B35/B36/B40/B41/B44/B47/B48/B49/B70/B71/B73/B75/B77	*	*		
B40	Charging cable for domestic socket, 4 m, straight		○	○	0,00	0,00
		Not in conjunction with B21/B22/B30/B31/B35/B36/B39/B41/B44/B47/B48/B49/B70/B71/B73/B75/B77	*	*		
B41	Charging cable for domestic socket, 5 m, straight		●	●	240,00	252,00
		Not in conjunction with B21/B22/B30/B31/B35/B36/B39/B40/B44/B47/B48/B49/B70/B71/B73/B75/B77	*	*		
B44	Charging cable for domestic socket, 5 m, straight		●	●	240,00	252,00
		Not in conjunction with B30/B31/B35/B36/B39/B40/B41/B47/B48/B49/B70/B71/B73/B75/B77/B78/B79	*	*		

802+052

2021-11-16

2022-01-21

Ap.Пршт 309

Legend

(\*) Available at extra cost (○) available without additional charge (S) standard equipment (-) not available (L) Left hand drive only (R) Right hand drive only (NS) National Standard  
 "+\* AND (code A and B) \*/" OR (code A or B) "[ ]" XOR if necessary at additional charge (exact one of A,B,...) "( )" logical grouping

Code	Equipment	Restrictions	EQA		Price Euro excl. VAT	Local price excl. VAT
			243708 EQA 300 4MATIC (L)	243712 EQA 350 4MATIC (L)		
B47	Charging cable for domestic socket, 5 m, straight	Not in conjunction with B30/B31/B35/B36/B39/B40/B41/B44/B48/B49/B70/B71/B73/B75/B77/B78/B79	○	○	0,00	0,00
B48	Charging cable for domestic socket, 5 m, straight	Not in conjunction with B30/B31/B35/B36/B39/B40/B41/B44/B47/B49/B70/B71/B73/B75/B77/B78/B79	●	●	240,00	252,00
B49	Charging cable for domestic socket, 5 m, straight	Not in conjunction with B30/B31/B35/B36/B39/B40/B41/B44/B47/B48/B70/B71/B73/B75/B77/B78/B79	●	●	240,00	252,00
B70	Charging cable for domestic socket, 5 m, straight	Not in conjunction with B30/B31/B35/B36/B39/B40/B41/B44/B47/B48/B49/B71/B73/B75/B77/B78/B79	●	●	240,00	252,00
B71	Charging cable for domestic socket, 5 m, straight	Not in conjunction with B30/B31/B35/B36/B39/B40/B41/B44/B47/B48/B49/B70/B73/B75/B77/B78/B79	●	●	240,00	252,00
B73	Charging cable for domestic socket, 5 m, straight	Not in conjunction with B30/B31/B35/B36/B39/B40/B41/B44/B47/B48/B49/B70/B71/B75/B77/B78/B79	●	●	240,00	252,00
B75	Charging cable for domestic socket, 8 m, straight	Not in conjunction with B30/B31/B35/B36/B39/B40/B41/B44/B47/B48/B49/B70/B71/B73/B77/B78/B79	●	●	270,00	283,50
B77	Charging cable for domestic socket, 8 m, straight	Not in conjunction with B30/B31/B35/B36/B39/B40/B41/B44/B47/B48/B49/B70/B71/B73/B75/B78/B79	●	●	270,00	283,50
B78	Charging cable for domestic socket, 8 m, straight	Not in conjunction with B30/B31/B35/B36/B39/B40/B41/B44/B47/B48/B49/B70/B71/B73/B75/B77/B79	●	●	270,00	283,50
B79	Charging cable for domestic socket, 8 m, straight	Not in conjunction with B30/B31/B35/B36/B39/B40/B41/B44/B47/B48/B49/B70/B71/B73/B75/B77/B78	●	●	270,00	283,50
B83	Charging cable for wallbox and public charging stations		●	●	70,00	73,50
B84	Charging cable for domestic socket, 8 m, straight	Not in conjunction with B21/B22/B30/B31/B35/B36/B37/B39/B40/B41/B44/B47/B48/B49/B70/B71/B73	●	●	70,00	73,50
B85	Charging cable for domestic socket, 8 m, straight	Not in conjunction with B21/B22/B30/B31/B35/B36/B39/B40/B41/B44/B47/B48/B49/B70/B71/B73/B75	●	●	70,00	73,50
B86	Charging cable for domestic socket, 8 m, straight	Not in conjunction with B21/B22/B30/B31/B35/B36/B39/B40/B41/B44/B47/B48/B49/B70/B71/B73/B75	●	●	270,00	283,50
B88	Charging cable for domestic socket, 8 m, straight	Not in conjunction with B21/B30/B31/B35/B36/B39/B40/B41/B44/B47/B48/B49/B70/B71/B73/B75/B77	●	●	270,00	283,50
B89	Charging cable for domestic socket, 8 m, straight	Not in conjunction with B21/B30/B31/B35/B36/B39/B40/B41/B44/B47/B48/B49/B70/B71/B73/B75/B77	●	●	270,00	283,50
B93	Charging cable for domestic socket, 8 m, straight	Not in conjunction with B21/B30/B31/B35/B36/B39/B40/B41/B44/B47/B48/B49/B70/B71/B73/B75/B77	●	●	270,00	283,50
B94	Charging cable for domestic socket, 8 m, straight	Not in conjunction with B21/B30/B31/B35/B36/B39/B40/B41/B44/B47/B48/B49/B70/B71/B73/B75/B77	●	●	270,00	283,50
B95	Charging cable for domestic socket, 8 m, straight	Not in conjunction with B22/B30/B31/B35/B36/B37/B39/B40/B41/B44/B47/B48/B49/B70/B71/B73/B75	●	●	70,00	73,50
B96	Charging cable for domestic socket, 8 m, straight	Not in conjunction with B21/B30/B31/B35/B36/B39/B40/B41/B44/B47/B48/B49/B70/B71/B73/B75/B77	●	●	270,00	283,50
B98	Charging cable for domestic socket, 8 m, straight	Not in conjunction with B21/B30/B31/B35/B36/B39/B40/B41/B44/B47/B48/B49/B70/B71/B73/B75/B77	●	●	70,00	73,50
B99	Charging cable for domestic socket, 8 m, straight	Not in conjunction with B30/B31/B35/B36/B39/B40/B41/B44/B47/B48/B49/B70/B71/B73/B75/B77/B78	●	●	270,00	283,50
K32	Active Lane Change Assist		○	○	0,00	0,00
K33	Extended automatic Re-start in traffic jams	Not in conjunction with 234/243/258/440	○	○	0,00	0,00
		Only in conjunction with 233+235	*	*		
K34	Route-based speed adaptation	Not in conjunction with 234/243/258/440	○	○	0,00	0,00
		Only in conjunction with 233	*	*		
L	Left-hand drive		○	○	0,00	0,00
P53	Fine particle sensor	for South Korea and China only	●	●	150,00	157,50
PBO	Supplementary standard equipment	Includes codes 14U+218 [P47]+310+608+70B+73B+877+889+890+942+P59 [950/PTD]+U12 [U26/U66]+U22 [	●	●	970,00	1.018,50

802+052

2021-11-16

2022-01-21

Ap.Пpшт 309

Legend

(\*) Available at extra cost (○) available without additional charge (S) standard equipment (-) not available (L) Left hand drive only (R) Right hand drive only (NS) National Standard  
 "+ AND (code A and B) "/" OR (code A or B) "[ ]" XOR if necessary at additional charge (exact one of A,B,...) "( )" logical grouping

Code	Equipment	Restrictions	EQA		Price Euro excl. VAT	Local price excl. VAT
			243708 ECA 300 4MATIC (L)	243712 ECA 350 4MATIC (L)		
		Not in conjunction with 904	*	*		
PYA	WEU Standard Equipment		LS	LS	295,00	0,00
PYD	Electric Art Interior		●	●	1.300,00	790,00
		i.V.m. Code PYN/PYO/PYQ	●	●	790,00	790,00
PYH	AMG Line		●	-	3.800,00	2.189,00
			-	●	3.800,00	3.290,00
		i.V.m. Code PYN/PYO/PYQ	●	-	3.290,00	2.139,00
		i.V.m. Code PYN/PYO/PYQ	-	●	3.290,00	3.290,00
PYM	Advanced Package		●	-	2.255,00	1.433,00
			-	●	2.255,00	1.875,00
PYN	Premium Package		●	●	3.400,00	2.644,00
		i.V.m. Code U19	●	●	3.725,00	2.956,00
PYO	Premium Plus package		●	●	6.400,00	not available
		available approx. as of Production 2nd Quarter 2022	*	*		
		i.V.m. Code U19	●	●	6.700,00	not available
PYQ	Premium Plus Package II		●	●	5.160,00	not available
		i.V.m. Code U19	●	●	5.460,00	not available
R	Right-hand drive		●	●	1.060,00	1.113,00
U01	Rear belt status indication in the instrument display		○	○	0,00	0,00
U10	Front passenger seat with seat occupancy sensor		●	●	95,00	99,75
U27	Exterior door handles in chrome		●	-	50,00	52,50
U35	12 V socket in load area		S	S	0,00	0,00
U50	Omission of heat-insulating dark-tinted glass		○	○	0,00	0,00
		Not in conjunction with 840/P55	*	*		
U55	Multi-link axle		S	S	0,00	0,00
U60	Pedestrian protection		○	○	0,00	0,00
U80	115 V socket		●	●	115,00	120,75
		only in conjunction with PBN	*	*		
682	Fire extinguisher		LS	LS	110,00	0,00
70B	Fluorescent jacket for driver		●	●	5,00	5,25
		i.V.m. Code PBO	○	○	0,00	0,00
		i.V.m. Code PYA	○	○	0,00	0,00
293	Sidebags in rear		●	●	375,00	393,75
294	Kneebag		○	○	0,00	0,00
258	Active Brake Assist		○	○	0,00	0,00
		Not in conjunction with 233/266/546/K33/K34	*	*		
273	Exit warning function		○	○	0,00	0,00
		only in conjunction with 233/234	*	*		
233	Active Distance Assist DISTRONIC		○	○	0,00	0,00
		Not in conjunction with 234/243/258/440	*	*		
		only in conjunction with 23P/PAY	*	*		
234	Blind Spot Assist		●	●	450,00	450,00
		Not in conjunction with 233/266/546/K33/K34/PAY	*	*		
		Only in conjunction with 243	*	*		
		only in conjunction with PDA/PDB/PDC and P49/275+273	*	*		
		i.V.m. Code P19/PDA/PDC/PDB	●	●	0,00	0,00
		i.V.m. Code PYM/PYN/PYO/PYQ	●	●	0,00	0,00
243	Active Lane Keeping Assist		●	●	450,00	472,50
		Not in conjunction with 233/266/546/K33/K34	*	*		
		i.V.m. S-Code 51B	○	○	0,00	0,00
475	Tyre pressure monitoring system		●	●	305,00	320,25
		i.V.m. S-Code 6P5	○	○	0,00	0,00
504	Speed Limit Assist		○	○	0,00	0,00
		Not in conjunction with 513/546	*	*		
513	Traffic Sign Assist		●	●	295,00	309,75

802+052

2021-11-16

2022-01-21

Ap.Пpшт 309

Legend

(\*) Available at extra cost (○) available without additional charge (S) standard equipment (-) not available (L) Left hand drive only (R) Right hand drive only (NS) National Standard  
 \*+ AND (code A and B) \*/ OR (code A or B) \*[] XOR if necessary at additional charge (exact one of A,B,...) \*() logical grouping

Code	Equipment	Restrictions	EQA		Price Euro excl. VAT	Local price excl. VAT
			243708 EQA 300 4MATIC (L)	243712 EQA 350 4MATIC (L)		
		Not in conjunction with 504	*	*		
		Only in conjunction with 270+355+365	*	*		
546	Active Speed Limit Assist		○	○	0,00	0,00
		Not in conjunction with 234/243/258/440/504	*	*		
		Only in conjunction with 233+270+355+365+513	*	*		
PAY	Driving Assistance Package		●	●	1.600,00	1.680,00
		Includes codes 233+P49 [275]	*	*		
		Not in conjunction with 234	*	*		
		only in conjunction with 275/221/P49	*	*		
		i.V.m. S-Code 51B	●	●	1.210,00	1.270,50
		i.V.m. Code PDA/PDB/PDC	●	●	1.150,00	1.207,50
		i.V.m. Code PYM/PYN/PYO/PYQ	●	●	1.135,00	1.191,75
		i.V.m. S-Code 51B+PDA/PDB/PDC	●	●	760,00	798,00
235	PARKTRONIC Parking Assist		○	○	0,00	0,00
		only in conjunction with P44/P47	*	*		
P44	Parking package with reversing camera		●	●	595,00	624,75
		Includes codes 218+235	*	*		
		Not in conjunction with P47/PDC	*	*		
		only in conjunction with Code PDA/PDB	*	*		
		i.V.m. Code PDA/PDB	○	○	0,00	0,00
		i.V.m. Code PYM/PYN	○	○	0,00	0,00
P47	Parking Package with 360-degree camera		●	●	1.005,00	1.055,25
		Includes codes 235+501	*	*		
		Not in conjunction with 218/P44	*	*		
		only in conjunction with Code PDA/PDB	*	*		
		i.V.m. Code PDA/PDB	●	●	410,00	430,50
		i.V.m. Code PDC	○	○	0,00	0,00
		i.V.m. Code PYQ/PYQ	○	○	0,00	0,00
P19	Edition 1		●	●	7.160,00	7.518,00
		Includes codes 209A+720 [B27]+772+840+873+PDA [PDB/PDC]+PTD+RVV+U66	*	*		
		not in conjunction with Code P55/817U/993U	*	*		
		i.V.m. Code PYM	●	●	5.000,00	5.250,00
		i.V.m. Code PYN/PYO/PYQ	●	●	4.710,00	4.945,50
B59	DYNAMIC SELECT		S	S	0,00	0,00
82B	Alternating current charging system (AC charging)		○	○	0,00	0,00
		Not in conjunction with 81B	*	*		
83B	Direct current charging system (DC charging)		S	S	0,00	0,00
9B2	Charging cable for wallbox and public charging station		○	○	0,00	0,00
		Not in conjunction with 64B/65B/66B/9B3/9B6/9B7	*	*		
		Only in conjunction with 63B	*	*		
9B3	Charging cable for wallbox and public charging station		●	●	70,00	73,50
		Not in conjunction with 64B/65B/66B/9B2/9B6/9B7	*	*		
		Only in conjunction with 63B	*	*		
9B6	Charging cable for wallbox and public charging station		○	○	0,00	0,00
		Not in conjunction with 64B/65B/66B/9B2/9B3/9B7	*	*		
		Only in conjunction with 63B	*	*		
B22	Charging cable for household socket, 5 m, straight		●	●	240,00	252,00
		Not in conjunction with B31/B35/B36/B39/B40/B41/B80/B81/B84/B85/B86/B95	*	*		
B30	Charging cable for domestic socket, 5 m, straight		●	●	240,00	252,00
		Not in conjunction with B31/B35/B36/B39/B40/B41/B44/B47/B48/B49/B70/B71/B73/B75/B77/B78/B79	*	*		
		i.V.m. Code PYA	○	○	0,00	0,00
B31	Charging cable for domestic socket, 5 m, straight		●	●	240,00	252,00
		Not in conjunction with B21/B22/B30/B35/B36/B39/B40/B41/B44/B47/B48/B49/B70/B71/B73/B75/B77	*	*		
		i.V.m. Code PYA	○	○	0,00	0,00
B32	Charging cable for industrial socket, 5 m, straight		●	●	240,00	252,00

802+052

2021-11-16

2022-01-21

Ap.Пpшт 309

Legend

(\*) Available at extra cost (○) available without additional charge (S) standard equipment (-) not available (L) Left hand drive only (R) Right hand drive only (NS) National Standard  
 \*+ AND (code A and B) \*/ OR (code A or B) \*[] XOR if necessary at additional charge (exact one of A,B,...) \*[] logical grouping

Code	Equipment	Restrictions	EQA		Price Euro excl. VAT	Local price excl. VAT
			243708 EQA 300 4MATIC (L)	243712 EQA 350 4MATIC (L)		
		Not in conjunction with B82	*	*		
		i.V.m. Code PYA	○	○	0,00	0,00
B80	Charging cable for domestic socket, 8 m, straight		●	●	270,00	283,50
		Not in conjunction with B21/B22/B30/B31/B35/B36/B39/B40/B41/B44/B47/B48/B49/B70/B71/B73/B75	*	*		
		i.V.m. Code PYA	●	●	30,00	31,50
B81	Charging cable for domestic socket, 8 m, straight		●	●	270,00	283,50
		Not in conjunction with B21/B22/B30/B31/B35/B36/B39/B40/B41/B44/B47/B48/B49/B70/B71/B73/B75	*	*		
		i.V.m. Code PYA	●	●	30,00	31,50
B82	Charging cable for industrial socket, 8 m, straight		●	●	270,00	283,50
		Not in conjunction with B32	*	*		
		i.V.m. Code PYA	●	●	30,00	31,50
B92	Charging cable for household socket, 8 m, straight		●	●	270,00	283,50
457	Adjustable damping		●	●	990,00	1.039,50
		Not in conjunction with 485/677/97R/R31/R96/RQO	*	*		
		Only in conjunction with 213	*	*		
485	Comfort suspension		S	S	0,00	0,00
		Not in conjunction with 213/457/677	*	*		
677	Lowered comfort suspension		○	○	0,00	0,00
		Not in conjunction with 213/457/485	*	*		
B53	Acoustic ambient protection		S	S	0,00	0,00