

(\*) Available at extra cost (○) available without additional charge (S) standard equipment (-) not available (L) Left hand drive only (R) Right hand drive only (NS) National Standard "+" AND (code A and B) "/" OR (code A or B) "I" XOR if necessary at additional charge (exact one of A,B...) "( )" logical grouping

			GLB											
Code	equipment	Restrictions	247610 GLB 180 d (L)	247612 GLB 200 d (L)	247613 GLB 200 d 4MATIC (L)	247614 GLB 220 d (L)	247615 GLB 220 d 4MATIC (L)	247684 GLB 180 (L)	247687 GLB 200 (L)	247688 GLB 200 4MATIC (L)	247646 GLB 250 (L)	247647 GLB 250 4MATIC (L)	247651 Mercedes-AMG GLB 35 (AMG 11)	Local price excl. VAT
NST														
5U6	AMG-specific radiator grille, darkened		-	-	-	-	-	-	-	-	-	-	○	0,00
		Available only as part of (PAZ)											*	
		Not in conjunction with 725											*	
		Only in conjunction with P60+PAZ											*	
7U8	Model badge on boot lid and wings in high-gloss black		-	-	-	-	-	-	-	-	-	-	○	0,00
		Available only as part of (PAZ)											*	
		Not in conjunction with 725											*	
		Only in conjunction with P60+PAZ											*	
P60	AMG Night package		-	-	-	-	-	-	-	-	-	-	●	787,50
		Includes codes 720+840											*	
		Not in conjunction with 725											*	
		i.V.m. Code PYA	-	-	-	-	-	-	-	-	-	-	●	472,50
PAZ	AMG Night Package II		-	-	-	-	-	-	-	-	-	-	●	420,00
		Includes codes 5U6+7U8											*	
		Not in conjunction with 725											*	
		Only in conjunction with P60											*	
U70	red-painted brake callipers		-	-	-	-	-	-	-	-	-	-	●	336,00
L6G	AMG Performance steering wheel in DINAMICA microfibre		-	-	-	-	-	-	-	-	-	-	●	882,00
		Only in conjunction with U88											*	
		i.V.m. Code PWT/PWU/PWV	-	-	-	-	-	-	-	-	-	-	●	105,00
L6j	AMG Performance steering wheel in nappa leather		-	-	-	-	-	-	-	-	-	-	●	441,00
		i.V.m. Code PWT/PWU/PWV	-	-	-	-	-	-	-	-	-	-	○	0,00
		i.V.m. Code PYA	-	-	-	-	-	-	-	-	-	-	○	0,00
L6K	AMG Performance steering wheel in nappa leather / D		-	-	-	-	-	-	-	-	-	-	●	514,50
		i.V.m. Code PWT/PWU/PWV	-	-	-	-	-	-	-	-	-	-	●	105,00
U88	AMG steering wheel buttons		-	-	-	-	-	-	-	-	-	-	●	367,50
		Not in conjunction with 431/L5C											*	
		i.V.m. Code L6G	-	-	-	-	-	-	-	-	-	-	○	0,00
		i.V.m. Code PWT/PWU/PWV	-	-	-	-	-	-	-	-	-	-	○	0,00
426	AMG SPEEDSHIFT DCT 8G		-	-	-	-	-	-	-	-	-	-	\$	0,00
459	AMG RIDE CONTROL suspension		-	-	-	-	-	-	-	-	-	-	\$	0,00
B59	AMG DYNAMIC SELECT		-	-	-	-	-	-	-	-	-	-	\$	0,00
P55	Night package		●	●	●	●	●	●	●	●	●	●	-	472,50
		Includes codes 720+840	*	*	*	*	*	*	*	*	*	*		
		Not in conjunction with 301A/311A/379A/725/72R/H59/H61/P27/R04/RTF	*	*	*	*	*	*	*	*	*	*		
		i.V.m. Code PYH	●	●	●	●	●	●	●	●	●	●	-	131,20
PAD	Engineering package		●	●	●	●	●	●	●	●	●	●	-	3.139,50
		Includes codes 457+642+889+U29	*	*	*	*	*	*	*	*	*	*		
		Not in conjunction with 234/239/243/258/301A/440/485/608/643/72R/H59/R04/R43/U28	*	*	*	*	*	*	*	*	*	*		
		Only in conjunction with 213+233+266+642	*	*	*	*	*	*	*	*	*	*		
		Only in conjunction with 628	*	*	*	*	*	*	*	*	*	*		
		only in conjunction with 23P/PAY	*	*	*	*	*	*	*	*	*	*		
		i.V.m. Code PWS/PWT	●	●	●	●	●	●	●	●	●	●	-	2.404,50
		i.V.m. Code PWU	●	●	●	●	●	●	●	●	●	●	-	2.142,00
		i.V.m. Code PWV	●	●	●	●	●	●	●	●	●	●	-	1.795,50
260	Deletion of model plate on boot lid		○	○	○	○	○	○	○	○	○	○	○	0,00
871	HANDS-FREE ACCESS		○	○	○	○	○	○	○	○	○	○	○	0,00
		Available only as part of (P17)	*	*	*	*	*	*	*	*	*	*	*	
		Not in conjunction with 301A/H59	*	*	*	*	*	*	*	*	*	*	*	
		Only in conjunction with P17	*	*	*	*	*	*	*	*	*	*	*	
889	KEYLESS-GO		●	●	●	●	●	●	●	●	●	●	●	420,00
		Not in conjunction with 301A/H59	*	*	*	*	*	*	*	*	*	*	*	
		i.V.m. Code P17	○	○	○	○	○	○	○	○	○	○	○	0,00
		i.V.m. Code PAD	○	○	○	○	○	○	○	○	○	○	-	0,00
		i.V.m. Code PWU/PWV	○	○	○	○	○	○	○	○	○	○	○	0,00
		i.V.m. Code PYN/PYO	○	○	○	○	○	○	○	○	○	○	○	0,00
P17	KEYLESS-GO Comfort package		●	●	●	●	●	●	●	●	●	●	●	787,50
		Includes codes 871+889+890	*	*	*	*	*	*	*	*	*	*	*	
		Not in conjunction with 301A/H59	*	*	*	*	*	*	*	*	*	*	*	
		i.V.m. Code PAD	●	●	●	●	●	●	●	●	●	●	-	378,00
		i.V.m. Code PWS/PWT	●	●	●	●	●	●	●	●	●	●	●	378,00

(\*) Available at extra cost (○) available without additional charge (S) standard equipment (-) not available (L) Left hand drive only (R) Right hand drive only (NS) National Standard "+" AND (code A and B) "/" OR (code A or B) "I" XOR if necessary at additional charge (exact one of A,B...) "( )" logical grouping

			GLB																							
Code	equipment	Restrictions	247610	GLB 180 d (L)	247612	GLB 200 d (L)	247613	GLB 200 d 4MATIC (L)	247614	GLB 220 d (L)	247615	GLB 220 d 4MATIC (L)	247684	GLB 180 (L)	247687	GLB 200 (L)	247688	GLB 200 4MATIC (L)	247646	GLB 250 (L)	247647	GLB 250 4MATIC (L)	247651	Mercedes-AMG GLB 35 4MATIC (L)	Local price excl. VAT	
		i.V.m. Code PWU/PWV		○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	0,00	
144U	digital white			●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	787,50	
191U	cosmos black			●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	787,50	
667U	denim blue			●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	787,50	
775U	iridium silver			●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	787,50	
787U	mountain grey			●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	787,50	
813U	galaxy blue			●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	787,50	
817U	rosé gold			●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	787,50	
149U	polar white			●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	220,50	
696U	night black			LS	LS	LS	LS	LS	LS	LS	LS	LS	LS	LS	LS	LS	LS	LS	LS	LS	LS	LS	LS	LS	0,00	
993U	MANUFAKTUR patagonia red metallic			●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	997,50	
413	Panoramic sliding sunroof			●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	1.228,50	
		i.V.m. Code PYO		○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	0,00	
725	Polished aluminium roof rails			S	S	S	S	S	S	S	S	S	S	S	S	S	S	S	S	S	S	S	S	S	0,00	
		Not in conjunction with P55		*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	
		Not in conjunction with P60/PAZ																					*			
B27	Omission of roof rails			○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	0,00	
		Not in conjunction with 159A/257A/258A/301A/431/651A/772/950/H59/H62/L5C/L5I/P39/RTF/U26/U28		*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	
		Only in conjunction with 428+U12		*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	
586	Surround lighting with projection of brand logo			●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	115,50
		i.V.m. Code PWV		○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	0,00	
608	Adaptive Highbeam Assist			●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	189,00	
		Not in conjunction with 642		*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	
		Not in conjunction with PAD		*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	
		Only in conjunction with 632		*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	
		i.V.m. Code 640		○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	0,00	
620	Halogen headlamps with integrated LED daytime running lights			○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	0,00	
		Not in conjunction with 608		*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	
		Not in conjunction with PAD		*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	
628	Adaptive Highbeam Assist Plus			○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	0,00	
		Not in conjunction with 608		*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	
		Only in conjunction with 642		*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	
632	LED High Performance headlamps			●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	871,50
		Not in conjunction with PAD		*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	
		i.V.m. Code PWS/PWT/PWU		○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	0,00	
		i.V.m. Code PYA		-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	0,00	
		i.V.m. Code PYD/PYF/PYH		○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	-	-	0,00	
642	MULTIBEAM LED			●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	1.312,50	
		Not in conjunction with 608		*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	
		Only in conjunction with 628		*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	
		i.V.m. Code PWS/PWT/PWU		●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	441,00
		i.V.m. Code PYA		-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	441,00	
		i.V.m. Code PYD/PYF/PYH		●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	441,00
		i.V.m. Code PAD		○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	-	-	0,00	
		i.V.m. Code PWV		○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	0,00	
		i.V.m. Code PYO		○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	0,00	
U37	Front fog lamps			●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	-	-	194,25	
		Not in conjunction with 159A/257A/258A/431/651A/772/950/H62/L5C/L5I/P39/RTF/U26/U28		*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	
		Only in conjunction with 428+U12		*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	
550	Trailer coupling with ESP<sup>®</sup> trailer stabiliser			●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	840,00	
		Not in conjunction with 554/668		*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	
554	Pre-installation for trailer coupling			●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	168,00	
		Not in conjunction with 550/666		*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	
P54	URBAN GUARD vehicle protection			●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	430,50	
		Includes codes 551+882		*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	
		Not in conjunction with 301A/H59		*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	
		Not in conjunction with P82		*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	
		i.V.m. Code 362		●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	462,00	
P82	URBAN GUARD vehicle protection Plus			●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	640,50	
		Includes codes 551+882		*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	
		Not in conjunction with 301A/H59		*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	
		Not in conjunction with P54		*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	
		i.V.m. Code 362		●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	672,00

(\*) Available at extra cost (○) available without additional charge (S) standard equipment (-) not available (L) Left hand drive only (R) Right hand drive only (NS) National Standard "+" AND (code A and B) "/" OR (code A or B) "I" XOR if necessary at additional charge (exact one of A,B...) "( )" logical grouping

[illegible]





(\*) Available at extra cost (○) available without additional charge (S) standard equipment (-) not available (L) Left hand drive only (R) Right hand drive only (NS) National Standard "+" AND (code A and B) "/" OR (code A or B) "I" XOR if necessary at additional charge (exact one of A,B...) "(" logical grouping

			GLB												
			247610 GLB 180 d (L)	247612 GLB 200 d (L)	247613 GLB 200 d 4MATIC (L)	247614 GLB 220 d (L)	247615 GLB 220 d 4MATIC (L)	247684 GLB 180 (L)	247687 GLB 200 (L)	247688 GLB 200 4MATIC (L)	247646 GLB 250 (L)	247647 GLB 250 4MATIC (L)	247651 Mercedes-AMG GLB 35 4MATIC (L)		
Code	equipment	Restrictions												Local price excl. VAT	
U45	Door sills with "Mercedes-Benz" lettering, illuminated		●	●	●	●	●	●	●	●	●	●	-	178,50	
		i.V.m. Code PWU/PWV	○	○	○	○	○	○	○	○	○	○	-	0,00	
		i.V.m. Code PYN/PYO	○	○	○	○	○	○	○	○	○	○	-	0,00	
U45	AMG illuminated door sills with "AMG" lettering and w		-	-	-	-	-	-	-	-	-	-	●	178,50	
		i.V.m. Code PWU/PWV	-	-	-	-	-	-	-	-	-	-	○	0,00	
		i.V.m. Code PYN/PYO	-	-	-	-	-	-	-	-	-	-	○	0,00	
256	AMG TRACK PACE		-	-	-	-	-	-	-	-	-	-	●	262,50	
		Not in conjunction with 548											*		
		Only in conjunction with 365+549											*		
458	All-digital instrument display		●	●	●	●	●	●	●	●	●	●	●	472,50	
		Only in conjunction with 859	*	*	*	*	*	*	*	*	*	*	*		
		i.V.m. Code PWT/PWU/PWV	○	○	○	○	○	○	○	○	○	○	○	0,00	
		i.V.m. Code PYN/PYO	○	○	○	○	○	○	○	○	○	○	○	0,00	
463	Head-up Display		●	●	●	●	●	●	●	●	●	●	●	1.039,50	
		Not in conjunction with 301A/311A/379A/H59/H61/P27/R04	*	*	*	*	*	*	*	*	*	*	*		
		i.V.m. Code PAU	○	○	○	○	○	○	○	○	○	○	○	0,00	
		i.V.m. Code PWV	○	○	○	○	○	○	○	○	○	○	○	0,00	
U19	MBUX augmented reality for navigation		●	●	●	●	●	●	●	●	●	●	●	409,50	
		Not in conjunction with 548	*	*	*	*	*	*	*	*	*	*	*		
		Only in conjunction with 365+549	*	*	*	*	*	*	*	*	*	*	*		
		Only in conjunction with 859	*	*	*	*	*	*	*	*	*	*	*		
		i.V.m. Code PWU/PWV	●	●	●	●	●	●	●	●	●	●	●	325,50	
877	Ambient lighting		●	●	●	●	●	●	●	●	●	●	●	309,75	
		Not in conjunction with 301A/H59	*	*	*	*	*	*	*	*	*	*	*		
		i.V.m. Code PBP/PBR	○	○	○	○	○	○	○	○	○	○	○	0,00	
		i.V.m. Code PWT/PWU/PWV	○	○	○	○	○	○	○	○	○	○	○	0,00	
		i.V.m. Code PYN/PYO	○	○	○	○	○	○	○	○	○	○	○	0,00	
U62	Light and Sight package		○	○	○	○	○	○	○	○	○	○	○	0,00	
51U	Roof liner in black fabric		○	○	○	○	○	○	○	○	○	○	S	0,00	
		Not in conjunction with 58U											*		
55U	Roof liner in macchiato beige fabric		○	○	○	○	○	○	○	○	○	○	○	0,00	
		Not in conjunction with 772/7U1/7U4/950/H59/H61/H62/L5C/L5I/P27/P39/R04/RTF/U26/U28	*	*	*	*	*	*	*	*	*	*	*		
		Only in conjunction with 428+P59	*	*	*	*	*	*	*	*	*	*	*		
		Only in conjunction with [105A/205A/325A]	*	*	*	*	*	*	*	*	*	*	*		
58U	Roof liner in crystal grey fabric		○	○	○	○	○	○	○	○	○	○	○	0,00	
		Not in conjunction with 105A/205A/325A/379A	*	*	*	*	*	*	*	*	*	*	*		
		Not in conjunction with 159A	*	*	*	*	*	*	*	*	*	*	*		
		Not in conjunction with 51U											*		
7U2	Comfort Seats		○	○	○	○	○	○	○	○	○	○	-	0,00	
		Not in conjunction with 159A/211A/214A/257A/258A/301A/431/651A/772/7U1/7U4/950/H62/L5C/L5I/	*	*	*	*	*	*	*	*	*	*	*		
		Only in conjunction with 286+428+U12+U59	*	*	*	*	*	*	*	*	*	*	*		
7U4	Sports seats		●	●	●	●	●	●	●	●	●	●	-	315,00	
			-	-	-	-	-	-	-	-	-	-	S	0,00	
		Not in conjunction with 409/55U/7U1/7U2	*	*	*	*	*	*	*	*	*	*	*		
		Only in conjunction with 286+U59	*	*	*	*	*	*	*	*	*	*	*		
		Only in conjunction with [159A/211A/214A/257A/258A/651A]	*	*	*	*	*	*	*	*	*	*	*		
		i.V.m. Code 950	○	○	○	○	○	○	○	○	○	○	-	0,00	
242	Power front right seat with memory function		●	●	●	●	●	●	●	●	●	●	●	299,25	
		Not in conjunction with 301A/7U1/842	*	*	*	*	*	*	*	*	*	*	*		
		Only in conjunction with 275	*	*	*	*	*	*	*	*	*	*	*		
		Only in conjunction with U22											*		
		i.V.m. Code PWV	○	○	○	○	○	○	○	○	○	○	○	0,00	
		i.V.m. Code PYO	○	○	○	○	○	○	○	○	○	○	○	0,00	
275	Driver's seat, electrically adjustable with memory func		●	●	●	●	●	●	●	●	●	●	●	362,25	
		Not in conjunction with 301A/7U1	*	*	*	*	*	*	*	*	*	*	*		
		Only in conjunction with U22+U59	*	*	*	*	*	*	*	*	*	*	*		
		Only in conjunction with U22											*		
		only in conjunction with (U22/409)+(7U2/7U4)	*	*	*	*	*	*	*	*	*	*	*		
		i.V.m. Code PWV	○	○	○	○	○	○	○	○	○	○	○	0,00	
		i.V.m. Code PYO	○	○	○	○	○	○	○	○	○	○	○	0,00	
401	Climatised front seats		●	●	●	●	●	●	●	●	●	●	●	934,50	
		Not in conjunction with 301A/311A/321A/325A/379A/381A/7U1	*	*	*	*	*	*	*	*	*	*	*		
		Not in conjunction with 651A/873	*	*	*	*	*	*	*	*	*	*	*		

Legend

(\*) Available at extra cost (○) available without additional charge (S) standard equipment (-) not available (L) Left hand drive only (R) Right hand drive only (NS) National Standard \*\* AND (code A and B) "/" OR (code A or B) "[ ]" XOR if necessary at additional charge (exact one of A,B,...) "( )" logical grouping

			GLB											
			247610 GLB 180 d (L)	247612 GLB 200 d (L)	247613 GLB 200 d 4MATIC (L)	247614 GLB 220 d (L)	247615 GLB 220 d 4MATIC (L)	247684 GLB 180 (L)	247687 GLB 200 (L)	247688 GLB 220 d 4MATIC (L)	247646 GLB 250 (L)	247647 GLB 250 4MATIC (L)	247651 Mercedes-AMG GLB 35 4MATIC (L)	
Code	equipment	Restrictions												Local price excl. VAT
		Not in conjunction with Y05											*	
		i.V.m. Code PBP/PBR	●	●	●	●	●	●	●	●	●	●	●	630,00
		i.V.m. Code PYN/PYO	●	●	●	●	●	●	●	●	●	●	●	630,00
409	Multicontour Seat package		●	●	●	●	●	●	●	●	●	●	-	619,50
		Not in conjunction with 431/772/7U1/7U4/842/950/H62/L5C/L5I/P39/RTF/U22/U26/U28	*	*	*	*	*	*	*	*	*	*	*	
		Only in conjunction with [101A/105A/201A/205A]+428+U12	*	*	*	*	*	*	*	*	*	*	*	
		i.V.m. Code PBR	○	○	○	○	○	○	○	○	○	○	-	0,00
7U1	Manually adjustable front seats		○	○	○	○	○	○	○	○	○	○	-	0,00
		Not in conjunction with 242/275/286/293/401/409/431/55U/567/772/7U2/7U4/950/H62/L5C/L5I/P39	*	*	*	*	*	*	*	*	*	*	*	
		Only in conjunction with 301A+428+U12	*	*	*	*	*	*	*	*	*	*	*	
873	Heated front seats		●	●	●	●	●	●	●	●	●	●	●	304,50
		Not in conjunction with 401	*	*	*	*	*	*	*	*	*	*	*	
		i.V.m. Code PBP/PBR	○	○	○	○	○	○	○	○	○	○	○	0,00
		i.V.m. Code PYN/PYO	○	○	○	○	○	○	○	○	○	○	○	0,00
U10	Automatic front passenger airbag deactivation		●	●	●	●	●	●	●	●	●	●	●	99,75
		i.V.m. S-Code 5 1B	○	○	○	○	○	○	○	○	○	○	○	0,00
U22	4-way lumbar support		●	●	●	●	●	●	●	●	●	●	●	220,50
		Not in conjunction with 301A/409	*	*	*	*	*	*	*	*	*	*	*	
		i.V.m. Code PWV	○	○	○	○	○	○	○	○	○	○	○	0,00
		i.V.m. Code PYO	○	○	○	○	○	○	○	○	○	○	○	0,00
U59	Seat Comfort package		○	○	○	○	○	○	○	○	○	○	○	0,00
		Not in conjunction with 301A	*	*	*	*	*	*	*	*	*	*	*	
287	Folding rear seat backrests		S	S	S	S	S	S	S	S	S	S	S	0,00
400	Rear armrest		S	S	S	S	S	S	S	S	S	S	S	0,00
567	Rear seats with fore/aft adjustment		●	●	●	●	●	●	●	●	●	●	●	378,00
		Not in conjunction with 301A/7U1	*	*	*	*	*	*	*	*	*	*	*	
		Not in conjunction with 847	*	*	*	*	*	*	*	*	*	*	*	
		Only in conjunction with 286+7U4+U59	*	*	*	*	*	*	*	*	*	*	*	
		i.V.m. Code PYA	-	-	-	-	-	-	-	-	-	-	○	0,00
		i.V.m. Code PYD/PYF/PYH	○	○	○	○	○	○	○	○	○	○	-	0,00
847	3rd row of seats for 2 people		●	●	●	●	●	●	●	●	●	●	●	1.249,50
		Not in conjunction with 214A/567	*	*	*	*	*	*	*	*	*	*	*	
		Not in conjunction with 301A/379A	*	*	*	*	*	*	*	*	*	*	*	
		Not in conjunction with 643/72R/R04/R43				*	*							
		i.V.m. Code PYA	-	-	-	-	-	-	-	-	-	-	●	787,50
		i.V.m. Code PYD/PYF/PYH	-	-	-	-	-	-	-	-	●	-	-	787,50
		i.V.m. PYF/PYH	●	●	●	●	●	●	●	●	-	●	-	787,50
440	Cruise control		S	S	S	S	S	S	S	S	S	S	S	0,00
		Not in conjunction with 546/K33/K34	*	*	*	*	*	*	*	*	*	*	*	
		Not in conjunction with PAD	*	*	*	*	*	*	*	*	*	*	*	
		Only in conjunction with 243+258	*	*	*	*	*	*	*	*	*	*	*	
446	Touchpad without Controller		S	S	S	S	S	S	S	S	S	S	S	0,00
77B	MBUX Interior Assistant		●	●	●	●	●	●	●	●	●	●	●	315,00
		Only in conjunction with 859	*	*	*	*	*	*	*	*	*	*	*	
		i.V.m. Code PAU	○	○	○	○	○	○	○	○	○	○	○	0,00
		i.V.m. Code PWV	○	○	○	○	○	○	○	○	○	○	○	0,00
L3B	Multifunction sports steering wheel in nappa leather		○	○	○	○	○	○	○	○	○	○	-	0,00
		Not in conjunction with 159A/257A/258A/651A/H62/P39/RTF/U28	*	*	*	*	*	*	*	*	*	*	*	
		Only in conjunction with 428+443+U12	*	*	*	*	*	*	*	*	*	*	*	
L3E	Leather multifunction sports steering wheel		○	○	○	○	○	○	○	○	○	○	-	0,00
		Not in conjunction with 159A/257A/258A/651A/H62/P39/RTF/U28	*	*	*	*	*	*	*	*	*	*	*	
		Only in conjunction with 428+U12	*	*	*	*	*	*	*	*	*	*	*	
L5C	Multifunction sports steering wheel in nappa leather		○	○	○	○	○	○	○	○	○	○	○	0,00
		Available only as part of (950)	*	*	*	*	*	*	*	*	*	*	*	
		Not in conjunction with 409/55U/7U1/7U2/842/B27/H59/H60/H61/P27/U12/U37	*	*	*	*	*	*	*	*	*	*	*	
		Not in conjunction with U88											*	
		Only in conjunction with 431	*	*	*	*	*	*	*	*	*	*	*	
		Only in conjunction with 772+{27R/RTF/RTG/RVV/RVWj}+U26	*	*	*	*	*	*	*	*	*	*	*	
		Only in conjunction with 950	*	*	*	*	*	*	*	*	*	*	*	
		Only in conjunction with [159A/211A/214A/257A/258A/651A]	*	*	*	*	*	*	*	*	*	*	*	
L5I	Multifunction sports steering wheel in nappa leather		●	●	●	●	●	●	●	●	●	●	-	241,50
		Not in conjunction with 409/55U/7U1/7U2/842/B27/H59/H60/H61/P27/U12/U37	*	*	*	*	*	*	*	*	*	*	*	
		Only in conjunction with 431+772+{27R/RTF/RTG/RVV/RVWj}+U26	*	*	*	*	*	*	*	*	*	*	*	

GLB

[illegible]



(\*) Available at extra cost (○) available without additional charge (S) standard equipment (-) not available (L) Left hand drive only (R) Right hand drive only (NS) National Standard "+" AND (code A and B) "/" OR (code A or B) "[ ]" XOR if necessary at additional charge (exact one of A,B,...) "( )" logical grouping

			GLB											
			247610 GLB 180 d (L)	247612 GLB 200 d (L)	247613 GLB 200 d 4MATIC (L)	247614 GLB 220 d (L)	247615 GLB 220 d 4MATIC (L)	247684 GLB 180 (L)	247687 GLB 200 (L)	247688 GLB 200 4MATIC (L)	247646 GLB 250 (L)	247647 GLB 250 4MATIC (L)	247651 Mercedes-AMG GLB 35 4MATIC (L)	
Code	equipment	Restrictions	○	○	○	○	○	○	○	○	○	○	-	Local price excl. VAT
321A	black		*	*	*	*	*	*	*	*	*	*	-	0,00
		Not in conjunction with 401/409/431/55U/772/7U1/7U4/950/H59/H61/H62/L5C/L5I/P27/P34/P39/PBR	*	*	*	*	*	*	*	*	*	*	-	
		Only in conjunction with 286+428+7U2+U12+U59	*	*	*	*	*	*	*	*	*	*	-	
		Only in conjunction with P59	*	*	*	*	*	*	*	*	*	*	-	
325A	macchiato beige / black		●	●	●	●	●	●	●	●	●	●	-	105,00
		Not in conjunction with 401/409/431/58U/772/7U1/7U4/950/H59/H61/H62/L5C/L5I/P27/P34/P39/PBR	*	*	*	*	*	*	*	*	*	*	-	
		Only in conjunction with 286+428+7U2+U12+U59	*	*	*	*	*	*	*	*	*	*	-	
		Only in conjunction with P59	*	*	*	*	*	*	*	*	*	*	-	
381A	black / Bahia brown		●	●	●	●	●	●	●	●	●	●	-	105,00
		Not in conjunction with 401/409/431/55U/772/7U1/7U4/950/H59/H61/H62/L5C/L5I/P27/P34/P39/PBR	*	*	*	*	*	*	*	*	*	*	-	
		Only in conjunction with 286+428+7U2+U12+U59	*	*	*	*	*	*	*	*	*	*	-	
		Only in conjunction with P59	*	*	*	*	*	*	*	*	*	*	-	
301A	black		○	○	○	○	○	○	○	○	○	○	-	0,00
		Not in conjunction with 242/274/275/286/293/401/409/431/463/551/55U/567/772/7U2/7U4/840/842	*	*	*	*	*	*	*	*	*	*	-	
		Only in conjunction with 428+7U1+U12	*	*	*	*	*	*	*	*	*	*	-	
		Only in conjunction with 725+H59	*	*	*	*	*	*	*	*	*	*	-	
159A	neva grey / black		●	●	●	●	●	●	●	●	●	●	-	105,00
		Not in conjunction with 409/428/443/7U1/7U2/842/B27/L3B/L3E/P27/P59/U12/U37	*	*	*	*	*	*	*	*	*	*	-	
		Not in conjunction with 58U/H23	*	*	*	*	*	*	*	*	*	*	*	
		Not in conjunction with P34/P39	*	*	*	*	*	*	*	*	*	*	*	
		Only in conjunction with 286+7U4+U59	*	*	*	*	*	*	*	*	*	*	*	
		Only in conjunction with 431+772+IH15/H62IH27R/RTF/RTG/RVV/RVWU26	*	*	*	*	*	*	*	*	*	*	*	
		Only in conjunction with 51U	*	*	*	*	*	*	*	*	*	*	*	
		Only in conjunction with 950	*	*	*	*	*	*	*	*	*	*	*	
201A	black		○	○	○	○	○	○	○	○	○	○	-	0,00
		Available only as part of (P34)	*	*	*	*	*	*	*	*	*	*	-	
		Not in conjunction with 431/55U/772/7U1/7U4/950/H59/H61/H62/L5C/L5I/P27/P39/R04/RTF/U26/U28	*	*	*	*	*	*	*	*	*	*	-	
		Only in conjunction with 286+428+7U2+P34+U12+U59	*	*	*	*	*	*	*	*	*	*	-	
		Only in conjunction with P59	*	*	*	*	*	*	*	*	*	*	-	
		only in conjunction with 873/401	*	*	*	*	*	*	*	*	*	*	-	
205A	macchiato beige / black		●	●	●	●	●	●	●	●	●	●	-	105,00
		Not in conjunction with 431/58U/772/7U1/7U4/950/H59/H61/H62/L5C/L5I/P27/P39/R04/RTF/U26/U28	*	*	*	*	*	*	*	*	*	*	-	
		Only in conjunction with 286+428+7U2+P34+U12+U59	*	*	*	*	*	*	*	*	*	*	-	
		Only in conjunction with P59	*	*	*	*	*	*	*	*	*	*	-	
		only in conjunction with 873/401	*	*	*	*	*	*	*	*	*	*	-	
211A	black		○	○	○	○	○	○	○	○	○	○	-	0,00
		Not in conjunction with 409/55U/7U1/7U2/842/H59/H61/P27/R04	*	*	*	*	*	*	*	*	*	*	-	
		Not in conjunction with P39	*	*	*	*	*	*	*	*	*	*	-	
		Not in conjunction with Y05	*	*	*	*	*	*	*	*	*	*	*	
		Only in conjunction with 286+7U4+P34+U59	*	*	*	*	*	*	*	*	*	*	*	
		only in conjunction with 873/401	*	*	*	*	*	*	*	*	*	*	*	
P34	Leather package		●	●	●	●	●	●	●	●	●	●	-	1.459,50
			-	-	-	-	-	-	-	-	-	-	●	1.050,00
		Includes codes 201A [205A/211A/214A]	*	*	*	*	*	*	*	*	*	*	*	
		Not in conjunction with H59/H61/P27/R04	*	*	*	*	*	*	*	*	*	*	*	
		Not in conjunction with P39	*	*	*	*	*	*	*	*	*	*	*	
		Not in conjunction with Y05	*	*	*	*	*	*	*	*	*	*	*	
		Only in conjunction with [201A/205A/211A/214A]	*	*	*	*	*	*	*	*	*	*	*	
		Only in conjunction with [211A/214A]	*	*	*	*	*	*	*	*	*	*	*	
		i.V.m. Code 950	●	●	●	●	●	●	●	●	●	●	-	1.050,00
257A	classic red / black		○	○	○	○	○	○	○	○	○	○	-	0,00
		Available only as part of (P39)	*	*	*	*	*	*	*	*	*	*	*	
		Not in conjunction with 409/428/443/55U/7U1/7U2/842/B27/L3B/L3E/P27/P59/U12/U37	*	*	*	*	*	*	*	*	*	*	*	
		Not in conjunction with H23/Y05	*	*	*	*	*	*	*	*	*	*	*	
		Not in conjunction with P34	*	*	*	*	*	*	*	*	*	*	*	
		Only in conjunction with 286+7U4+P39+U59	*	*	*	*	*	*	*	*	*	*	*	
		Only in conjunction with 431+772+IH15/H62IH27R/RTF/RTG/RVV/RVWU26	*	*	*	*	*	*	*	*	*	*	*	
		Only in conjunction with 950	*	*	*	*	*	*	*	*	*	*	*	
		only in conjunction with 873/401	*	*	*	*	*	*	*	*	*	*	*	
258A	titanium grey pearl / black		●	●	●	●	●	●	●	●	●	●	●	105,00
		Not in conjunction with 409/428/443/55U/7U1/7U2/842/B27/L3B/L3E/P27/P59/U12/U37	*	*	*	*	*	*	*	*	*	*	*	
		Not in conjunction with H23/Y05	*	*	*	*	*	*	*	*	*	*	*	
		Not in conjunction with P34	*	*	*	*	*	*	*	*	*	*	*	

(\*) Available at extra cost (○) available without additional charge (S) standard equipment (-) not available (L) Left hand drive only (R) Right hand drive only (NS) National Standard "+" AND (code A and B) "/" OR (code A or B) "I" XOR if necessary at additional charge (exact one of A,B...) "( )" logical grouping

			GLB																						
Code	equipment	Restrictions	247610	GLB 180 d (L)	247612	GLB 200 d (L)	247613	GLB 200 d 4MATIC (L)	247614	GLB 220 d (L)	247615	GLB 220 d 4MATIC (L)	247684	GLB 180 (L)	247687	GLB 200 (L)	247688	GLB 200 4MATIC (L)	247646	GLB 350 (L)	247647	GLB 250 4MATIC (L)	247651	Mercedes-AMG GLB 35 4MATIC (L)	Local price excl. VAT
		Only in conjunction with 286+7U4+P39+U59	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	
		Only in conjunction with 431+772+[H15/H62]+[27R/RTF/RTG/RVV/RVW]+U26	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	
		Only in conjunction with 950	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	
		only in conjunction with 873/401	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	
214A	Bahia brown / black		●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	105,00
		Not in conjunction with 409/55U/7U1/7U2/842/H59/H61/P27/R04	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	
		Not in conjunction with 847/P39	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	
		Not in conjunction with Y05																					*		
		Only in conjunction with 286+7U4+P34+U59	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	
		only in conjunction with 873/401	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	
950	AMG Line		●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	-	3.139,50
			-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	S	0,00	
		Includes codes 310+651A [159A/211A/214A/257A/258A]+725 [720]+772+H62 [H15/H23]+L5C [L5I]+RTF [RTG]	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	
		Includes codes 310+651A [159A/211A/214A/257A/258A]+725 [720]+772+H62 [H15/H23]+L5C [L6I]/L6K]+U26	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	
		Not in conjunction with 409/428/55U/7U1/7U2/842/B27/H60/U12/U37		*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	
		Only in conjunction with [159A/211A/214A/257A/258A/651A]	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	
		Only in conjunction with [27R/RTF/RTG/RVV/RVW]	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	
		i.V.m. Code PWS/PWT/PWU/PWV	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	-	1.737,75
		i.V.m. Code PYH	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	-	0,00
P27	Style		●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	-	588,00
		Includes codes 310+311A [101A/379A]+725 [B27]+H61+L3E [L3B]+R04 [27R/52R/643/72R/97R/R38/R58/R	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	
		Not in conjunction with 431/463/55U/720/L5C/L5I/P34/P39/P55/PAU/R43/RTF/U28	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	
		Only in conjunction with [101A/311A/379A]+428+U12	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	
		i.V.m. Code PYD	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	-	0,00
P59	Progressive		●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	-	1.401,75
		Includes codes 310+52R [27R/643/72R/97R/R38/R43/R58/RTG/RVV/RVW]+725 [720/B27]+H60 [H15/H23	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	
		Not in conjunction with 159A/257A/258A/301A/311A/379A/431/651A/H62/L5C/L5I/P39/R04/RTF/U28	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	
		Only in conjunction with 428+U12	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	
		i.V.m. Code PWS/PWT/PWU/PWV	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	-	0,00
		i.V.m. Code PYF	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	-	0,00
362	Communications module (LTE) for the use of Mercedes		○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	-	0,00
20U	Preinstallation for digital key transfer		●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	-	52,50
		i.V.m. Code PWS/PWT/PWU/PWV	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	-	0,00
		i.V.m. Code PYA	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	-	0,00
33U	Remote Services Plus		●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	-	157,50
		Not in conjunction with 34U	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	
34U	Remote Services Premium		●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	-	262,50
		Not in conjunction with 33U	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	
351	Mercedes-Benz emergency call system		○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	-	0,00
00B	Owner's Manual and service information - Danish		○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	-	0,00
00U	Remote Services		●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	-	105,00
		i.V.m. Code PYA	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	-	0,00
01B	Owner's Manual and service information - Dutch		○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	-	0,00
02B	Owner's Manual and service information - German		○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	-	0,00
03B	Owner's Manual and service information - Russian		○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	-	0,00
04B	Owner's Manual and service information - Finnish		○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	-	0,00
05B	Owner's Manual and service information - English		○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	-	0,00
06B	Owner's Manual and service information - Italian		○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	-	0,00
07B	Owner's Manual and service information - French		○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	-	0,00
08B	Owner's Manual and service information - Spanish		○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	-	0,00
09B	Owner's Manual and service information - Portuguese		○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	-	0,00
104A	ARTICO man-made leather brown		-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	257,25
		China only												*	*	*									
10B	Owner's Manual and service information - Swedish		○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	-	0,00
11B	Owner's Manual and service information - Arabic		○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	-	0,00
12B	Owner's Manual and service information - English USA		○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	-	0,00
12U	Preinstallation for Concierge Service		○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	-	0,00
13B	Owner's Manual and service information - Norwegian		○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	-	0,00
14B	Owner's Manual and service information - Greek		○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	-	0,00
15B	Owner's Manual and service information - Turkish		○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	-	0,00
15U	Pre-installation for Mercedes-Benz Link		○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	-	0,00
16B	Owner's Manual and service information - Polish		○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	-	0,00
16U	Apple CarPlay		○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	-	0,00

(\*) Available at extra cost (○) available without additional charge (S) standard equipment (-) not available (L) Left hand drive only (R) Right hand drive only (NS) National Standard "+" AND (code A and B) "/" OR (code A or B) "[ ]" XOR if necessary at additional charge (exact one of A,B,...) "( )" logical grouping

[illegible]



Legend

(\*) Available at extra cost (○) available without additional charge (S) standard equipment (-) not available (L) Left hand drive only (R) Right hand drive only (NS) National Standard "+" AND (code A and B) "/" OR (code A or B) "I" XOR if necessary at additional charge (exact one of A,B...) "(" logical grouping

			GLB											
			247610 GLB 180 d (L)	247612 GLB 200 d (L)	247613 GLB 200 d 4MATIC (L)	247614 GLB 220 d (L)	247615 GLB 220 d 4MATIC (L)	247684 GLB 180 (L)	247687 GLB 200 (L)	247688 GLB 200 4MATIC (L)	247646 GLB 250 (L)	247647 GLB 250 4MATIC (L)	247651 Mercedes-AMG GLB 35 4MATIC (L)	
Code	equipment	Restrictions												Local price excl. VAT
652	Summer complete tyres fitted		○	○	○	○	○	○	○	○	○	○	○	0,00
662U	MANUFAKTUR mountain grey MAGNO		-	-	-	-	-	-	-	-	-	-	●	1,942,50
666	Freight packaging without tie-down hooks		●	●	●	●	●	●	●	●	●	●	●	26,25
		Not in conjunction with 554/668	*	*	*	*	*	*	*	*	*	*	*	
		Only in conjunction with 550	*	*	*	*	*	*	*	*	*	*	*	
668	Freight packaging with tie-down hooks		LS	LS	LS	LS	LS	LS	LS	LS	LS	LS	LS	26,25
		Not in conjunction with 550/666	*	*	*	*	*	*	*	*	*	*	*	
672	Emergency spare wheel		-	○	○	-	○	○	○	○	○	○	○	0,00
679	Product protection-partial protection		○	○	○	-	○	○	○	○	-	○	○	0,00
687	Model year on model plate		○	○	○	○	○	○	○	○	○	○	○	0,00
700	Produktionsstandort Fahrzeug China		-	-	-	-	○	○	○	○	-	-	-	0,00
720	Roof rails in black		○	○	○	○	○	○	○	○	○	○	○	0,00
		Available only as part of (P55)	*	*	*	*	*	*	*	*	*	*	*	
		Available only as part of (P60)											*	
		Not in conjunction with 301A/311A/379A/72R/H59/H61/P27/R04/RTF	*	*	*	*	*	*	*	*	*	*	*	
		Only in conjunction with P55	*	*	*	*	*	*	*	*	*	*	*	
		Only in conjunction with P60											*	
762	Radio remote control without panic button		○	○	○	○	○	○	○	○	○	○	○	0,00
763	Radio remote control with panic switch		○	○	○	○	○	○	○	○	○	○	○	0,00
772	AMG bodystyling		○	○	○	○	○	○	○	○	○	○	S	0,00
		Available only as part of (950)	*	*	*	*	*	*	*	*	*	*	*	
		Not in conjunction with 409/428/55U/7U1/7U2/842/B27/H60/U12/U37	*	*	*	*	*	*	*	*	*	*	*	
		Only in conjunction with 950+ [27R/RTF/RTG/RVV/RVW]	*	*	*	*	*	*	*	*	*	*	*	
		Only in conjunction with [159A/211A/214A/257A/258A/651A]	*	*	*	*	*	*	*	*	*	*	*	
798	Preinstallation for digital radio		○	○	○	○	○	○	○	○	○	○	○	0,00
802	Technical modifications		○	○	○	○	○	○	○	○	○	○	○	0,00
820	Tourist vehicle		○	○	○	○	○	○	○	○	○	○	○	0,00
821	Country code Brazil		-	-	-	-	○	○	○	○	○	○	○	0,00
822	South Africa specification		○	○	○	○	○	○	○	○	○	○	○	0,00
823	country code Switzerland		○	○	○	○	○	○	○	○	○	○	○	0,00
824	Additional parts for cold countries (engine air intake s		○	○	○	○	○	○	○	○	○	○	○	0,00
829	Taiwan version		○	○	○	○	○	○	○	○	○	○	○	0,00
830	China specification		-	-	-	-	○	○	○	-	-	○	○	0,00
831	country code Italia		○	○	○	○	○	○	○	○	○	○	○	0,00
834	New Zealand specification		-	-	○	-	○	○	-	-	○	-	○	0,00
835	South Korea specification		○	○	-	-	-	-	-	-	○	○	○	0,00
842	Folding front passenger seat		●	●	●	●	●	●	●	●	●	●	-	157,50
		Not in conjunction with 159A/211A/214A/242/257A/258A/301A/409/431/651A/772/950/H62/L5C/L5I/L	*	*	*	*	*	*	*	*	*	*	*	
		Only in conjunction with 428+U12	*	*	*	*	*	*	*	*	*	*	*	
852	Sensor system for anti-theft alarm system		-	-	-	-	-	-	-	●	●	●	●	147,00
		for USA only									*	*	*	
		i.V.m. Code 362	-	-	-	-	-	-	-	●	●	●	●	178,50
859U	mojave silver metallic		-	-	-	-	●	●	●	-	-	-	-	787,50
		only China							*	*	*			
865	TV tuner Japan		-	●	●	-	-	-	-	-	-	●	●	945,00
882	Interior monitoring system		○	○	○	○	○	○	○	○	○	○	○	0,00
		Not in conjunction with 301A/H59	*	*	*	*	*	*	*	*	*	*	*	
885	Increased anti-theft protection		○	○	○	○	○	○	○	○	○	○	○	0,00
		for 537L only	*	*	*	*	*	*	*	*	*	*	*	
896U	brilliant blue metallic		●	●	●	●	●	●	●	●	●	●	-	787,50
		only China	*	*	*	*	*	*	*	*	*	*	*	
913	Air conditioning preinstallation for hot countries		○	○	○	○	-	-	-	-	-	-	-	0,00
922	Reduced output engines		-	-	-	-	○	○	-	-	-	-	-	0,00
926	Emission control system with EU4 technology		○	○	○	○	○	○	○	○	○	○	○	0,00
927	EU6 emissions standard		○	○	○	○	○	○	○	○	○	○	○	0,00
929	Ethanol fuelled engine		-	-	-	-	-	○	-	-	-	-	-	0,00
936	Cylinder shut-off		-	-	-	-	○	○	○	-	-	-	-	0,00
943	Toll payment system		●	●	●	●	●	●	●	●	●	●	●	210,00
		only China	*	*	*	*	*	*	*	*	*	*	*	
945	Emission control system China		-	-	-	-	○	○	○	-	-	-	○	0,00
959	Emission Control China Stage 7		-	-	-	-	○	-	-	-	-	-	○	0,00
961	Petrol particulate filter		-	-	-	-	○	○	○	○	○	○	○	0,00
968	COC document F16 without registration certificate ne		○	○	○	○	○	○	○	○	○	○	○	0,00

(\*) Available at extra cost (○) available without additional charge (S) standard equipment (-) not available (L) Left hand drive only (R) Right hand drive only (NS) National Standard "+" AND (code A and B) "/" OR (code A or B) "I" XOR if necessary at additional charge (exact one of A,B...) "( )" logical grouping

			GLB																							
			247610	GLB 180 d (L)	247612	GLB 200 d (L)	247613	GLB 200 d 4MATIC (L)	247614	GLB 220 d (L)	247615	GLB 220 d 4MATIC (L)	247684	GLB 180 (L)	247687	GLB 200 (L)	247688	GLB 200 4MATIC (L)	247646	GLB 250 (L)	247647	GLB 250 4MATIC (L)	247651	Mercedes-AMG GLB 35 4MATIC (L)		
Code	equipment	Restrictions																							Local price excl. VAT	
969	COC document EU6 with registration certificate part 2		O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O		0,00	
971	Diesel particulate filter		S	S	S	S	S	S	S	S	S	S	S	S	S	S	S	S	S	S	S	S	S		0,00	
973	Designation as owner-driver rental vehicle		O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O		0,00	
981	Omission of vehicle registration document		O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O		0,00	
986	Identification label with VIN number		O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O		0,00	
989	Identification label under windshield		O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O		0,00	
994	Exhibition vehicle (B-Trade fair)		O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O		0,00	
997	Display vehicle for exhibitions (motor show veh.)		O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O		0,00	
999	Petrol particulate filter		-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-		0,00	
B08	Fanfare horn		O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O		0,00	
B12	Tyre-change toolkit		●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●		31,50	
K32	Active Lane Change Assist		O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O		0,00	
K33	Extended automatic Re-start in traffic jams		O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O		0,00	
		Not in conjunction with 234/239/243/258/440/504	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*		
		Only in conjunction with 233+266	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*		
		Only in conjunction with 235+273+365+513+546+K34	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*		
K34	Route-based speed adaptation		O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O		0,00	
		Not in conjunction with 234/239/243/258/440/504	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*		
		Only in conjunction with 233+266	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*		
		Only in conjunction with 273+365+513+546	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*		
L	Left-hand drive		O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O		0,00	
P53	AIR-QUALITY package		●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●		157,50	
		certain countries only	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*		
PAY	Driving Assistance Package		●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●		1.680,00	
		Includes codes 233	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*		
		Not in conjunction with 234	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*		
		Only in conjunction with 266+273	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*		
		only in conjunction with 275/221/P49	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*		
		I.V.m. S-Code 51B	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●		1.270,50	
PWS	Advanced Package		●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	-		3.643,50	
PWT	Advanced-Plus Package		●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	-		4.683,00	
			-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	●		3.843,00		
PWU	Premium Package		●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	-		5.932,50	
			-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	●		5.082,00		
PWV	Premium-Plus Package		●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	-		8.505,00	
			-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	●		7.665,00		
PYA	WEU Standard Equipment		-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	LS		0,00		
			LS	LS	LS	LS	LS	LS	LS	LS	LS	LS	LS	LS	LS	LS	LS	LS	LS	LS	LS	-		0,00		
PYD	Style Line		●	-	-	-	-	-	●	-	-	-	-	-	-	-	-	-	-	-	-	-		1.750,00		
			-	LS	LS	LS	LS	-	LS	LS	LS	LS	LS	LS	LS	LS	LS	LS	LS	LS	LS	-		0,00		
PYF	Progressive Line		●	-	-	-	-	-	●	-	-	-	-	-	-	-	-	-	-	-	-	-		3.035,00		
			-	●	●	●	●	-	●	●	●	●	●	●	●	●	●	●	●	●	●	-		1.285,00		
PYH	AMG Line		●	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-		5.240,00		
			-	●	●	●	●	-	●	●	●	●	●	●	●	●	●	●	●	●	●	-		3.490,00		
PYM	Advantage Package		●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●		1.838,00		
PYN	Premium Package		●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●		3.056,00		
PYO	Premium Plus package		●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●		4.688,00		
R	Right-hand drive		●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●		1.113,00		
R01	Summer tyres		O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O		0,00		
		Not in conjunction with 645/R03	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*			
R02	All-season tyres		-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	●	●		157,50		
		only USA/Canada																			*	*				
U01	Status display for rear seat belts in instrument cluster		O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O		0,00		
U27	Exterior door handles in chrome		-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-		52,50		
		only China																			*	*				
U35	12 V socket in load area		O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O		0,00		
		Only in conjunction with 942	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*			
U41	Water separator and lubrication package		O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O		0,00		
U50	Omission of heat-insulating dark-tinted glass		O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O		0,00		
U55	Multi-link axle		S	S	S	S	S	S	S	S	S	S	S	S	S	S	S	S	S	S	S	S		0,00		
U60	Pedestrian protection		O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O		0,00		
U79	BlueTEC diesel emission control system including AdB		O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O		0,00		
U80	115 V socket		●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●		120,75		



2022-02-01

Δρ. Πρωτ. 309

(\*) Available at extra cost (C) available without additional charge (S) standard equipment (-) not available (L) Left hand drive only (R) Right hand drive only (NS) National Standard "+" AND (code A and B) "/" OR (code A or B) "[]" XOR if necessary at additional charge (exact one of A,B,...) "()" logical grouping

[illegible]