

Legend (*) Available at extra cost (○) available without additional charge (S) standard equipment (-) not available (L) Left hand drive only (R) Right hand drive only (NS) National Standard **+ Please note that central restrictions are displayed. Markets may have specific deviation if any. Codes could be valid for certain countries only.

			CLS Coupé						Local price excl. VAT
Code	Equipment	Restrictions	257314 CLS 220 d	257319 CLS 300 d 4MATIC	257323 CLS 400 d 4MATIC	257350 CLS 350 (L)	257359 CLS 450 4MATIC	257361 Mercedes-AMG CLS 53 4MATIC+	
5U6	AMG-specific radiator grille, darkened		-	-	-	-	-	○	0,00
		Available only as part of (PAZ)						*	
		Only in conjunction with P60+PAZ						*	
772	AMG bodystyling		●	●	●	●	●	●	1.365,00
		Available only as part of (P31)	*	*	*	*	*	*	
		Not in conjunction with 11R/63R/818A/83R/P14/P15	*	*	*	*	*		
		Only in conjunction with P29+P31	*	*	*	*	*		
		i.V.m. Code P31	○	○	○	○	○	○	0,00
B28	AMG Exterior Carbon-Fibre package II		-	-	-	-	-	●	1.837,50
		Not in conjunction with U47						*	
		Only in conjunction with U93						*	
P31	Mercedes-AMG exterior		-	-	-	-	-	S	0,00
		Includes codes 489+772+RRE [RRF/RTY/RTZ/RVM/RVN/RZU]+U47 [U93]						*	
P60	AMG Night package		-	-	-	-	-	●	997,50
		Includes codes 840 [U50]+RRF [RRE/RTY/RTZ/RVM/RVN/RZU]						*	
		i.V.m. Code PYH	-	-	-	-	-	●	787,50
		i.V.m. Code P97	-	-	-	-	-	○	0,00
PAZ	AMG Night Package II		-	-	-	-	-	●	577,50
		Includes codes 5U6+7U8						*	
		Only in conjunction with P60						*	
		i.V.m. Code P97	-	-	-	-	-	○	0,00
U46	Omission of AMG spoiler lip on boot lid		○	○	-	○	○	-	0,00
		Not in conjunction with U95	*			*			
U47	AMG spoiler lip		-	-	-	-	-	S	0,00
		Not in conjunction with B28/U93						*	
U70	red-painted brake callipers		-	-	-	-	-	○	0,00
		Available only as part of (P71)						*	
		Only in conjunction with P71						*	
U93	AMG spoiler lip in carbon fibre on boot lid		-	-	-	-	-	○	0,00
		Not in conjunction with U47						*	
		Only in conjunction with B28						*	
U95	AMG spoiler lip		●	●	●	●	●	-	367,50
		Not in conjunction with U46	*			*			
		i.V.m. Code P31	○	○	○	○	○	-	0,00
		i.V.m. S-Code PVD	-	○	○	-	○	-	0,00
L6J	AMG Performance steering wheel in nappa leather		-	-	-	-	-	S	0,00
		Not in conjunction with L6K						*	
L6K	AMG Performance steering wheel in nappa leather / DI		-	-	-	-	-	●	441,00
		Not in conjunction with 55U/875A/955A/L6J/P87/U12						*	
		Only in conjunction with U26						*	
		i.V.m. Code P71	-	-	-	-	-	○	0,00
P29	Mercedes-AMG interior		-	-	-	-	-	S	0,00
		Includes codes 671A [871A/875A]+873 [401/902]+H41 [736/H01/H16/H32/H64/H73]+L6J [L6K]+U26+U88						*	
U88	AMG steering wheel buttons		-	-	-	-	-	S	0,00
250	AMG Driver's package		-	-	-	-	-	●	1.995,00
		Not in conjunction with R05/R66						*	
421	AMG SPEEDSHIFT TCT 9G		-	-	-	-	-	S	0,00
B59	AMG DYNAMIC SELECT		-	-	-	-	-	S	0,00
P71	AMG DYNAMIC PLUS package		-	-	-	-	-	●	1.575,00
		Includes codes U70						*	
		only in conjunction with L6J/L6K						*	
		i.V.m. Code P97	-	-	-	-	-	○	0,00

802+052
2021-12-14
2022-02-09

Αρ.Πρωτ 309

Legend (*) Available at extra cost (○) available without additional charge (S) standard equipment (-) not available (L) Left hand drive only (R) Right hand drive only (NS) National Standard *+
Please note that central restrictions are displayed. Markets may have specific deviation if any. Codes could be valid for certain countries only.

			CLS Coupé						Local price excl. VAT
Code	Equipment	Restrictions	257314 CLS 220 d	257319 CLS 300 d 4MATIC	257323 CLS 400 d 4MATIC	257350 CLS 350 (L)	257359 CLS 450 4MATIC	257361 Mercedes-AMG CLS 53 4MATIC+	
U78	AMG performance exhaust system, selectable		-	-	-	-	-	●	1.470,00
		i.V.m. Code PYC	-	-	-	-	-	○	0,00
		i.V.m. S-Code 3P8	-	-	-	-	-	○	0,00
E08	Approval documentation for driving aids		●	●	●	●	●	●	126,00
		Only in conjunction with E5P	*	*	*	*	*	*	
		Only for left hand drive	*	*	*		*	*	
E09	Entrance guard		●	●	●	●	●	●	199,50
		Only in conjunction with E5P	*	*	*	*	*	*	
		Only for left hand drive	*	*	*		*	*	
E65	Steering wheel knob, left		●	●	●	●	●	●	441,00
		Only in conjunction with E08+E5P	*	*	*	*	*	*	
		Only for left hand drive	*	*	*		*	*	
E66	Steering wheel knob, right		●	●	●	●	●	●	441,00
		Only in conjunction with E08+E5P	*	*	*	*	*	*	
		Only for left hand drive	*	*	*		*	*	
E67	"Classic" hand control unit		●	●	●	●	●	●	2.205,00
		Not in conjunction with E68/E83/E84/E89/E92/E94	*	*	*	*	*	*	
		Only in conjunction with 275+E08+E5P+P49	*	*	*	*	*	*	
		Only for left hand drive	*	*	*		*	*	
E68	"Classic" leather-covered hand control unit		●	●	●	●	●	●	2.835,00
		Not in conjunction with E67/E83/E84/E89/E92/E94	*	*	*	*	*	*	
		Only in conjunction with 275+E08+E5P+P49	*	*	*	*	*	*	
		Only for left hand drive	*	*	*		*	*	
E83	"Easy speed" leather-covered hand control unit		●	●	●	●	●	●	3.045,00
		Not in conjunction with E67/E68/E84/E92/E94	*	*	*	*	*	*	
		Only in conjunction with 275+E08+E5P+P49	*	*	*	*	*	*	
		Only for left hand drive	*	*	*		*	*	
E84	"Easy speed" hand control unit		●	●	●	●	●	●	2.415,00
		Not in conjunction with E67/E68/E83/E92/E94	*	*	*	*	*	*	
		Only in conjunction with 275+E08+E5P+P49	*	*	*	*	*	*	
		Only for left hand drive	*	*	*		*	*	
E85	Belt buckle opener for the driver		●	●	●	●	●	●	183,75
		Only in conjunction with E5P	*	*	*	*	*	*	
		Only for left hand drive	*	*	*		*	*	
E87	Pedal cover		●	●	●	●	●	●	525,00
		Only in conjunction with E08+E5P	*	*	*	*	*	*	
		Only for left hand drive	*	*	*		*	*	
E88	Combination switch moved to the right		●	●	●	●	●	●	262,50
		Only in conjunction with E08+E5P	*	*	*	*	*	*	
		Only for left hand drive	*	*	*		*	*	
E89	Accelerator pedal moved to the left (electronic)		●	●	●	●	●	●	1.785,00
		Not in conjunction with E67/E68	*	*	*	*	*	*	
		Only in conjunction with E08+E5P	*	*	*	*	*	*	
		Only for left hand drive	*	*	*		*	*	
E92	Pedal extenders (2)		●	●	●	●	●	●	756,00
		Not in conjunction with E67/E68/E83/E84	*	*	*	*	*	*	
		Only in conjunction with E08+E5P	*	*	*	*	*	*	
		Only for left hand drive	*	*	*		*	*	
E94	Left seat repositioning to the rear		●	●	●	●	●	●	787,50
		Not in conjunction with E67/E68/E83/E84	*	*	*	*	*	*	
		Only in conjunction with E08+E5P	*	*	*	*	*	*	
		Only for left hand drive	*	*	*		*	*	
E95	Right seat repositioning to the rear		●	●	●	●	●	●	787,50
		Only in conjunction with E08+E5P	*	*	*	*	*	*	

802+052
2021-12-14
2022-02-09

Αρ.Πρωτ 309

Legend (*) Available at extra cost (○) available without additional charge (S) standard equipment (-) not available (L) Left hand drive only (R) Right hand drive only (NS) National Standard *+
Please note that central restrictions are displayed. Markets may have specific deviation if any. Codes could be valid for certain countries only.

			CLS Coupé						Local price excl. VAT
Code	Equipment	Restrictions	257314 CLS 220 d	257319 CLS 300 d 4MATIC	257323 CLS 400 d 4MATIC	257350 CLS 350 (L)	257359 CLS 450 4MATIC	257361 Mercedes-AMG CLS 53 4MATIC+	
		Only for left hand drive	*	*	*		*	*	
P55	Night package		●	●	●	●	●	-	603,75
		Includes codes 840 [U50]	*	*	*	*	*		
		Only in conjunction with [RRF/RVQ]	*	*	*	*	*		
		i.V.m. Code P31+840	●	●	●	●	●	-	787,50
		i.V.m. Code P31+U50	●	●	●	●	●	-	525,00
		i.V.m. Code PYH	●	●	●	●	●	-	525,00
PAQ	MANUFAKTUR high-pile floor mats and Velour Boot pack		●	●	●	●	●	-	829,50
		Includes codes 304+B62	*	*	*	*	*		
		Not in conjunction with 802A/809A/824A/827A/834A/P89	*	*	*	*	*		
260	Omission of model plate on boot lid		○	○	○	○	○	○	0,00
871	HANDS-FREE ACCESS		○	○	○	○	○	○	0,00
		Available only as part of (P17)	*	*	*	*	*	*	
		Only in conjunction with P17	*	*	*	*	*	*	
881	Boot lid convenience closing feature		●	●	●	●	●	●	551,25
		i.V.m. Code P17	○	○	○	○	○	○	0,00
		i.V.m. Code PYM/PYN/PYO	○	○	○	○	○	○	0,00
883	Power closing		●	●	●	●	●	●	577,50
889	KEYLESS-GO		●	●	●	●	●	●	735,00
		i.V.m. Code P17	○	○	○	○	○	○	0,00
		i.V.m. Code PYM/PYN/PYO	○	○	○	○	○	○	0,00
B67	Vehicle key in high-gloss black with ornamental surround		●	●	●	●	●	●	105,00
P17	KEYLESS-GO Comfort package		●	●	●	●	●	●	1.270,50
		Includes codes 871+881+889	*	*	*	*	*	*	
197U	obsidian black		●	●	●	●	●	●	913,50
		Not in conjunction with P97/U03/U15						*	
831U	graphite grey		●	●	●	●	●	●	913,50
		Not in conjunction with P97/U03/U15						*	
859U	Mojave silver		●	●	●	●	●	●	913,50
		Not in conjunction with P97/U03/U15						*	
922U	high-tech silver		●	●	●	●	●	●	913,50
		Not in conjunction with P97/U03/U15						*	
970U	spectral blue		●	●	●	●	●	●	913,50
		Not in conjunction with P97/U03/U15						*	
989U	emerald green		●	●	●	●	●	●	1.827,00
		Not in conjunction with P97/U03/U15						*	
992U	selenite grey		●	●	●	●	●	●	913,50
		Not in conjunction with P97/U03/U15						*	
040U	black		○	○	○	○	○	○	0,00
		Not in conjunction with P97/U03/U15						*	
149U	polar white		●	●	●	●	●	●	315,00
		Not in conjunction with P97/U03/U15						*	
032U	mystic blue metallic		●	●	●	●	●	●	6.195,00
		Not in conjunction with 11R/63R/818A/83R/P14/P15	*	*	*	*	*		
		Not in conjunction with P97/U03/U15						*	
		Only in conjunction with 235+889	*	*	*	*	*	*	
		Only in conjunction with P29+P31	*	*	*	*	*	*	
041U	graphite metallic		●	●	●	●	●	●	6.195,00
		Not in conjunction with 11R/63R/818A/83R/P14/P15	*	*	*	*	*		
		Not in conjunction with P97/U03/U15						*	
		Only in conjunction with 235+889	*	*	*	*	*	*	
		Only in conjunction with P29+P31	*	*	*	*	*	*	
124U	classic grey non-metallic		●	●	●	●	●	●	6.195,00
		Not in conjunction with 11R/63R/818A/83R/P14/P15	*	*	*	*	*		

802+052
2021-12-14
2022-02-09

Αρ.Πρωτ 309

Legend (*) Available at extra cost (○) available without additional charge (S) standard equipment (-) not available (L) Left hand drive only (R) Right hand drive only (NS) National Standard *+
Please note that central restrictions are displayed. Markets may have specific deviation if any. Codes could be valid for certain countries only.

			CLS Coupé						Local price excl. VAT
Code	Equipment	Restrictions	257314 CLS 220 d	257319 CLS 300 d 4MATIC	257323 CLS 400 d 4MATIC	257350 CLS 350 (L)	257359 CLS 450 4MATIC	257361 Mercedes-AMG CLS 53 4MATIC+	
		Not in conjunction with P97/U03/U15						*	
		Only in conjunction with 235+889	*	*	*	*	*	*	
		Only in conjunction with P29+P31	*	*	*	*	*		
385U	Côte d'Azur light blue metallic		●	●	●	●	●	●	6.195,00
		Not in conjunction with 11R/63R/818A/83R/P14/P15	*	*	*	*	*		
		Not in conjunction with P97/U03/U15						*	
		Only in conjunction with 235+889	*	*	*	*	*	*	
		Only in conjunction with P29+P31	*	*	*	*	*		
773U	Teide light grey metallic		●	●	●	●	●	●	6.195,00
		Not in conjunction with 11R/63R/818A/83R/P14/P15	*	*	*	*	*		
		Not in conjunction with P97/U03/U15						*	
		Only in conjunction with 235+889	*	*	*	*	*	*	
		Only in conjunction with P29+P31	*	*	*	*	*		
297U	MANUFAKTUR selenite grey magno		●	●	●	●	●	●	2.940,00
		Only in conjunction with 524	*	*	*	*	*	*	
		i.V.m. Code P97	-	-	-	-	-	○	0,00
799U	MANUFAKTUR diamond white bright		●	●	●	●	●	●	1.732,50
		Not in conjunction with P97/U03/U15						*	
996U	MANUFAKTUR hyacinth red metallic		●	●	●	●	●	●	1.291,50
		Not in conjunction with P97/U03/U15						*	
049U	MANUFAKTUR cashmere white magno		●	●	●	●	●	●	4.704,00
		Only in conjunction with 524	*	*	*	*	*	*	
		i.V.m. Code P97	-	-	-	-	-	●	1.764,00
414	Sliding sunroof		●	●	●	●	●	●	1.181,25
		i.V.m. Code PYO	○	○	○	○	○	○	0,00
E22	Support for roof attachments		●	●	●	●	●	●	441,00
608	Adaptive Highbeam Assist		●	●	●	●	●	●	189,00
		Not in conjunction with 628/642/P35	*	*	*	*	*	*	
		Only in conjunction with 632	*	*	*	*	*	*	
		i.V.m. Code PYB	○	○	○	○	○	○	0,00
628	Adaptive Highbeam Assist Plus		○	○	○	○	○	○	0,00
		Available only as part of (P35)	*	*	*	*	*	*	
		Not in conjunction with 608/632	*	*	*	*	*	*	
		Only in conjunction with P35	*	*	*	*	*	*	
632	LED High Performance headlamps		○	○	○	○	○	○	0,00
		Not in conjunction with 628/642/P35	*	*	*	*	*	*	
E28	Surround lighting with projection of AMG brand logo		-	-	-	-	-	●	152,25
		i.V.m. Code P97	-	-	-	-	-	○	0,00
E72	Surround lighting with projection of brand logo		●	●	●	●	●	-	131,25
P35	MULTIBEAM LED		●	●	●	●	●	●	1.522,50
		Includes codes 628+642	*	*	*	*	*	*	
		Not in conjunction with 608/632	*	*	*	*	*	*	
550	Trailer coupling with ESP[®] trailer stabilis		●	●	●	●	●	●	1.008,00
887	Independent boot locking		●	●	●	●	●	●	26,25
E16	Rim lock set		●	●	●	●	●	●	52,50
		Only for right hand drive	*	*					
P54	URBAN GUARD vehicle protection		●	●	●	●	●	●	493,50
		Includes codes 551+882	*	*	*	*	*	*	
		Not in conjunction with P82	*	*	*	*	*	*	
P82	URBAN GUARD vehicle protection Plus		●	●	●	●	●	●	703,50
		Includes codes 551+882	*	*	*	*	*	*	
		Not in conjunction with P54	*	*	*	*	*	*	
645	M+S winter tyres, set of 4		●	●	●	●	●	-	204,75
		Not in conjunction with R06/RVQ/RVS	*	*	*	*	*		

802+052
2021-12-14
2022-02-09

Αρ.Πρωτ 309

Legend (*) Available at extra cost (○) available without additional charge (S) standard equipment (-) not available (L) Left hand drive only (R) Right hand drive only (NS) National Standard "+": Please note that central restrictions are displayed. Markets may have specific deviation if any. Codes could be valid for certain countries only.

			CLS Coupé						Local price excl. VAT
Code	Equipment	Restrictions	257314 CLS 220 d	257319 CLS 300 d 4MATIC	257323 CLS 400 d 4MATIC	257350 CLS 350 (L)	257359 CLS 450 4MATIC	257361 Mercedes-AMG CLS 53 4MATIC+	
		only in conjunction with (11R/63R/83R/RRE/RRF)	*	*	*	*	*	-	
R03	Sports tyres		○	○	○	○	○	-	0,00
		Not in conjunction with R66/RVQ/RVS	*	*	*	*	*	-	
R05	Summer tyres		-	-	-	-	-	○	0,00
		Not in conjunction with 250/P97/R01/U03/U15						*	
		Only in conjunction with [RRE/RRF]						*	
R66	run-flat tyres		●	●	●	●	●	●	294,00
		Not in conjunction with 250/P97/U03/U15						*	
		Not in conjunction with B51	*	*	*	*	*	*	
		Not in conjunction with R03	*	*	*	*	*		
		Only in conjunction with [RRE/RRF]						*	
		i.V.m. Code ((RRE/RRF)+R05)	-	-	-	-	-	○	0,00
		i.V.m. div. Rädern (19"/20")	○	○	○	○	○	-	0,00
RRE	48.3 cm (19-inch) AMG 5-twin-spoke light-alloy wheels		-	-	-	-	-	○	0,00
		Not in conjunction with P97/U03/U15						*	
RRE	48.3 cm (19-inch) AMG 5-twin-spoke light-alloy wheels		●	●	●	●	●	-	1.155,00
		Not in conjunction with P55/U50	*	*	*	*	*		
		Only in conjunction with 776	*	*	*	*	*		
		i.V.m. Code P31	○	○	○	○	○	-	0,00
RRF	48.3 cm (19-inch) AMG 5-twin-spoke light-alloy wheels		-	-	-	-	-	S	0,00
		Not in conjunction with P97/U03/U15						*	
RRF	48.3 cm (19-inch) AMG 5-twin-spoke light-alloy wheels		●	●	●	●	●	-	1.470,00
		Only in conjunction with 776	*	*	*	*	*		
		i.V.m. Code P31	●	●	●	●	●	-	315,00
		i.V.m. Code P31+P55	○	○	○	○	○	-	0,00
RTY	50.8 cm (20-inch) AMG 5-twin-spoke light-alloy wheels		-	-	-	-	-	●	1.155,00
		Not in conjunction with P97/R05/R66/U03/U15						*	
		Only in conjunction with R01						*	
RTZ	50.8 cm (20-inch) AMG 5-twin-spoke light-alloy wheels		-	-	-	-	-	●	1.470,00
		Not in conjunction with P97/R05/R66/U03/U15						*	
		Only in conjunction with R01						*	
RVM	50.8 cm (20-inch) AMG multi-spoke light-alloy wheels		-	-	-	-	-	●	945,00
		Not in conjunction with P97/R05/R66/U03/U15						*	
		Only in conjunction with R01						*	
RVN	50.8 cm (20-inch) AMG multi-spoke light-alloy wheels		-	-	-	-	-	●	1.260,00
		Not in conjunction with P97/R05/R66/U03/U15						*	
		Only in conjunction with R01						*	
RVQ	50.8 cm (20-inch) AMG multi-spoke alloy wheels		●	●	●	●	●	-	2.310,00
		Not in conjunction with B51	*	*	*	*	*		
		Only in conjunction with 776+R06+R66	*	*	*	*	*		
		Only in conjunction with R01	*	*	*	*	*		
		only in conjunction with P15/P31	*	*	*	*	*		
		i.V.m. Code P31	●	●	●	●	●	-	1.260,00
		i.V.m. Code P31+P55	●	●	●	●	●	-	945,00
RVS	50.8 cm (20-inch) AMG multi-spoke light-alloy wheels		●	●	●	●	●	-	1.995,00
		Not in conjunction with B51/P55/U50	*	*	*	*	*		
		Only in conjunction with 776+R06+R66	*	*	*	*	*		
		Only in conjunction with R01	*	*	*	*	*		
		only in conjunction with P15/P31	*	*	*	*	*		
		i.V.m. Code P31	●	●	●	●	●	-	945,00
RZU	50.8 cm (20-inch) AMG 5-twin-spoke light-alloy wheels		-	-	-	-	-	●	1.680,00
		Not in conjunction with R05/R66						*	
		Only in conjunction with R01						*	
		i.V.m. Code P97	-	-	-	-	-	○	0,00

802+052
2021-12-14
2022-02-09

Αρ.Πρωτ 309

Legend (*) Available at extra cost (○) available without additional charge (S) standard equipment (-) not available (L) Left hand drive only (R) Right hand drive only (NS) National Standard **+
Please note that central restrictions are displayed. Markets may have specific deviation if any. Codes could be valid for certain countries only.

			CLS Coupé						Local price excl. VAT
Code	Equipment	Restrictions	257314 CLS 220 d	257319 CLS 300 d 4MATIC	257323 CLS 400 d 4MATIC	257350 CLS 350 (L)	257359 CLS 450 4MATIC	257361 Mercedes-AMG CLS 53 4MATIC+	
11R	48.3 cm (19-inch) 5-twin-spoke light-alloy wheels with		●	●	●	●	●	-	630,00
		Not in conjunction with 032U/041U/124U/211A/385U/601A/772/773U/776/802A/807A/809A/824A/827A	*	*	*	*	*		
		Not in conjunction with U29			*		*		
		Only in conjunction with P14+P15	*	*	*	*	*		
63R	48.3 cm (19-inch) multi-spoke light-alloy wheels		●	●	●	●	●	-	367,50
		Not in conjunction with 032U/041U/124U/211A/385U/601A/772/773U/802A/807A/809A/824A/827A/834	*	*	*	*	*		
		Not in conjunction with U29			*		*		
		Only in conjunction with P14+P15	*	*	*	*	*		
83R	45.7 cm (18-inch) 5-twin-spoke light-alloy wheels		○	○	○	○	○	-	0,00
		Available only as part of (P15)	*	*	*	*	*		
		Not in conjunction with 032U/041U/124U/211A/385U/601A/772/773U/776/802A/807A/809A/824A/827A	*	*	*	*	*		
		Not in conjunction with U29			*		*		
		Only in conjunction with P14+P15	*	*	*	*	*		
B51	TIREFIT		●	●	●	●	●	●	52,50
		Not in conjunction with R66	*	*	*	*	*	*	
		Not in conjunction with RVQ/RVS	*	*	*	*	*	*	
		i.V.m. Code PYB	○	○	○	○	○	○	0,00
2R4	Complete set of 4 M+S winter wheels		●	●	●	●	●	-	2.205,00
		only available with MO-tyres	*	*	*	*	*		
4R6	Complete set of 4 M+S winter wheels		●	●	●	●	●	-	2.919,00
		only available with MO-tyres	*	*	*	*	*		
8R4	Complete set of 4 M+S winter wheels		-	-	-	-	-	●	3.465,00
540	Electric sunblind for rear window		●	●	●	●	●	●	404,25
840	Heat-insulating dark-tinted glass		●	●	●	●	●	●	409,50
		Not in conjunction with PAF/U50	*	*	*	*	*	*	
		i.V.m. Code P55	○	○	○	○	○	-	0,00
		i.V.m. Code P60	-	-	-	-	-	○	0,00
		i.V.m. Code PYH	○	○	○	○	○	○	0,00
875	Heated windscreen washer system		●	●	●	●	●	●	178,50
P49	Mirror package		●	●	●	●	●	●	577,50
		Includes codes 249+500	*	*	*	*	*	*	
		i.V.m. Code PWS	○	○	○	○	○	○	0,00
		i.V.m. Code PYB	○	○	○	○	○	○	0,00
		i.V.m. Code PYM/PYN/PYO	○	○	○	○	○	○	0,00
PAF	Acoustic Comfort package		●	●	●	●	●	●	1.155,00
		Includes codes 596	*	*	*	*	*	*	
		Not in conjunction with 840	*	*	*	*	*	*	
U50	Omission of heat-insulating dark-tinted glass		○	○	○	○	○	○	0,00
		Not in conjunction with 840	*	*	*	*	*	*	
		Only in conjunction with P55+[RRF/RVQ]	*	*	*	*	*		
		Only in conjunction with P60					*		
7U8	Typography in high-gloss black		-	-	-	-	-	○	0,00
		Available only as part of (PAZ)						*	
		Only in conjunction with P60+PAZ						*	
355	Extended MBUX functions		S	S	S	S	S	S	0,00
365	Hard-disc navigation		●	●	●	●	●	●	577,50
		i.V.m. Code PBF	○	○	○	○	○	○	0,00
367	Preinstallation for Live Traffic Information		○	○	○	○	○	○	0,00
PBF	Navigation Connectivity package		●	●	●	●	●	●	682,50
		Includes codes 01U+362+365	*	*	*	*	*	*	
		i.V.m. Code PYB	○	○	○	○	○	○	0,00
537	Digital radio		○	○	○	○	○	○	0,00
810	Burmester® surround sound system		●	●	●	●	●	●	971,25
		i.V.m. Code PYN	○	○	○	○	○	○	0,00

802+052
2021-12-14
2022-02-09

Αρ.Πρωτ 309

Legend (*) Available at extra cost (○) available without additional charge (S) standard equipment (-) not available (L) Left hand drive only (R) Right hand drive only (NS) National Standard "+" Please note that central restrictions are displayed. Markets may have specific deviation if any. Codes could be valid for certain countries only.

			CLS Coupé						Local price excl. VAT
Code	Equipment	Restrictions	257314 CLS 220 d	257319 CLS 300 d 4MATIC	257323 CLS 400 d 4MATIC	257350 CLS 350 (L)	257359 CLS 450 4MATIC	257361 Mercedes-AMG CLS 53 4MATIC+	
		i.V.m. Code PYO	○	○	○	○	○	○	0,00
14U	Smartphone integration		●	●	●	●	●	●	420,00
			-	-	-	-	-	-	0,00
		Only in conjunction with 16U+17U	*	*	*	*	*	*	
		i.V.m. Code PWS	○	○	○	○	○	○	0,00
		i.V.m. Code PYB	○	○	○	○	○	○	0,00
897	Wireless charging system for mobile devices in the front		●	●	●	●	●	●	210,00
		Not in conjunction with 274/899	*	*	*	*	*	*	
		i.V.m. Code PYB	○	○	○	○	○	○	0,00
899	Multifunction telephony		●	●	●	●	●	●	514,50
		Not in conjunction with 897	*	*	*	*	*	*	
		Only in conjunction with 274	*	*	*	*	*	*	
21U	Dash cam		●	●	●	●	●	●	210,00
		only in conjunction with U19	*	*	*	*	*	*	
543	Pull-out sun visor		●	●	●	●	●	●	99,75
U17	Omission of coloured seat belts		-	-	-	-	-	○	0,00
		Not in conjunction with 55U/955A/P87/U12/Y05						*	
U38	Dashboard and door beltlines in nappa leather		●	●	●	●	●	●	735,00
		Not in conjunction with 201A/205A/211A/214A/219A/601A	*	*	*	*	*		
		Not in conjunction with 671A						*	
		i.V.m. Code P87	○	○	○	○	○	○	0,00
Y05	Red seat belts		-	-	-	-	-	S	0,00
		Not in conjunction with 55U/955A/P87/U12/U17						*	
228	Auxiliary heater		●	●	●	●	●	●	1.438,50
		Only in conjunction with 916	*	*	*				
		Only for left hand drive	*	*	*		*	*	
		i.V.m. Code 362	●	●	●	●	●	●	1.281,00
443	Steering wheel heating		●	●	●	●	●	●	273,00
		Only in conjunction with 275+P49	*	*	*	*	*	*	
580	THERMATIC automatic climate control		S	S	S	S	S	S	0,00
		Not in conjunction with 581/670	*	*	*	*	*	*	
581	THERMOTRONIC automatic climate control		●	●	●	●	●	●	619,50
		Not in conjunction with 580	*	*	*	*	*	*	
		Only in conjunction with 670	*	*	*	*	*	*	
		i.V.m. Code PYO	○	○	○	○	○	○	0,00
P21	AIR-BALANCE package		●	●	●	●	●	●	351,75
		i.V.m. Code PBP/PBR	○	○	○	○	○	○	0,00
P68	Warmth Comfort package		●	●	●	●	●	-	829,50
			-	-	-	-	-	●	451,50
		Includes codes 902+906	*	*	*	*	*	*	
		Not in conjunction with 873	*	*	*	*	*	*	
		Only in conjunction with 275+P49	*	*	*	*	*	*	
		i.V.m. Code PBP	●	●	●	●	●	-	451,50
		i.V.m. Code PBR	○	○	○	○	○	○	0,00
287	EASY-PACK quickfold		●	●	●	●	●	●	456,75
		i.V.m. Code P97	-	-	-	-	-	○	0,00
		i.V.m. Code PWS	○	○	○	○	○	○	0,00
		i.V.m. Code PYB	○	○	○	○	○	○	0,00
304	MANUFAKTUR velour anti-slip mat with edging in nappa		○	○	○	○	○	○	0,00
660	Centre console in high-gloss grey wood		○	○	○	○	○	○	0,00
		Not in conjunction with 685/728/732/737/764/779	*	*	*	*	*	*	
		Not in conjunction with 736/H01/H16/H32/H36/H41/H64/H73	*	*	*	*	*		
		Not in conjunction with P97/U03/U15						*	
		Only in conjunction with H13						*	

802+052
2021-12-14
2022-02-09

Ap.Πρωτ 309

Legend (*) Available at extra cost (○) available without additional charge (S) standard equipment (-) not available (L) Left hand drive only (R) Right hand drive only (NS) National Standard *+
Please note that central restrictions are displayed. Markets may have specific deviation if any. Codes could be valid for certain countries only.

			CLS Coupé						Local price excl. VAT
Code	Equipment	Restrictions	257314 CLS 220 d	257319 CLS 300 d 4MATIC	257323 CLS 400 d 4MATIC	257350 CLS 350 (L)	257359 CLS 450 4MATIC	257361 Mercedes-AMG CLS 53 4MATIC+	
685	Centre console in brown open-pore walnut wood trim		○	○	○	○	○	○	0,00
		Not in conjunction with 660/736/H01/H16/H32/H41/H64/H73	*	*	*	*	*		
		Not in conjunction with 728/H13	*	*	*	*	*	*	
		Not in conjunction with P97/U03/U15						*	
		Only in conjunction with H36						*	
728	Centre console in black piano-lacquer look		○	○	○	○	○	○	0,00
		Not in conjunction with 660/736/H01/H32/H36/H73	*	*	*	*	*		
		Not in conjunction with 685/732/737/764/779/H13	*	*	*	*	*	*	
		Not in conjunction with P97/U03/U15						*	
		Only in conjunction with [H16/H41/H64]						*	
732	AMG carbon-fibre centre console		●	●	●	●	●	●	997,50
		Not in conjunction with 660/736/H01/H16/H32/H36/H64	*	*	*	*	*		
		Not in conjunction with 728/737/764/779/H13	*	*	*	*	*	*	
		Only in conjunction with [H41/H73]						*	
		i.V.m. Code PYB	●	●	●	●	●	●	840,00
		i.V.m. Code H73	○	○	○	○	○	○	0,00
737	Centre console in black open-pored ash wood		○	○	○	○	○	○	0,00
		Not in conjunction with 660/H01/H16/H32/H36/H64/H73	*	*	*	*	*		
		Not in conjunction with 728/732/764/779/H13	*	*	*	*	*	*	
		Not in conjunction with P97/U03/U15						*	
		Only in conjunction with [736/H41]						*	
764	Centre console in grey open-pore ash wood		○	○	○	○	○	○	0,00
		Not in conjunction with 660/736/H01/H16/H36/H41/H64/H73	*	*	*	*	*		
		Not in conjunction with 728/732/737/779/H13	*	*	*	*	*	*	
		Not in conjunction with P97/U03/U15						*	
		Only in conjunction with H32						*	
779	Centre console in high-gloss light brown sen wood		○	○	○	○	○	○	0,00
		Not in conjunction with 660/736/H16/H32/H36/H41/H64/H73	*	*	*	*	*		
		Not in conjunction with 728/732/737/764/H13	*	*	*	*	*	*	
		Not in conjunction with P97/U03/U15						*	
		Only in conjunction with H01						*	
PBP	ENERGIZING package		●	●	●	●	●	-	939,75
			-	-	-	-	-	●	561,75
		Includes codes 868+873 [401/902]+P21	*	*	*	*	*	*	
		Not in conjunction with 548/PBR	*	*	*	*	*	*	
		Only in conjunction with 549	*	*	*	*	*	*	
PBR	ENERGIZING package Plus		●	●	●	●	●	-	4.593,75
			-	-	-	-	-	●	4.215,75
		Includes codes 401+432+868+P21+P68	*	*	*	*	*	*	
		Not in conjunction with 548/873/PBP	*	*	*	*	*	*	
		Not in conjunction with 601A	*	*	*	*	*		
		Not in conjunction with 671A						*	
		Only in conjunction with 275+549+902+906+P49	*	*	*	*	*	*	
		Only in conjunction with 436	*	*	*	*	*		
B20	MANUFAKTUR velour floor mats with edging in nappa l		○	○	○	○	○	○	0,00
		Not in conjunction with 211A/601A/802A/809A/824A/827A/834A/887A/B23/P89/PAQ	*	*	*	*	*		
B62	MANUFAKTUR high-pile floor mats with edging in napp		●	●	●	●	●	-	546,00
		i.V.m. Code P89/PAQ	○	○	○	○	○	-	0,00
U12	Velour floor mats		S	S	S	S	S	○	0,00
		Not in conjunction with 211A/601A/802A/807A/809A/824A/827A/834A/887A/B23/P89/PAQ	*	*	*	*	*		
		Not in conjunction with 51U/61U/736/H41/L6K/P97/U03/U15/U17/U26/Y05						*	
		Only in conjunction with 275+287+955A+L6J+P49+P87						*	
U26	AMG floor mats		○	○	○	○	○	S	0,00
		Available only as part of (P29)	*	*	*	*	*		

802+052
2021-12-14
2022-02-09

Αρ.Πρωτ 309

Legend (*) Available at extra cost (○) available without additional charge (S) standard equipment (-) not available (L) Left hand drive only (R) Right hand drive only (NS) National Standard *+
Please note that central restrictions are displayed. Markets may have specific deviation if any. Codes could be valid for certain countries only.

			CLS Coupé						Local price excl. VAT
Code	Equipment	Restrictions	257314 CLS 220 d	257319 CLS 300 d 4MATIC	257323 CLS 400 d 4MATIC	257350 CLS 350 (L)	257359 CLS 450 4MATIC	257361 Mercedes-AMG CLS 53 4MATIC+	
		Not in conjunction with 11R/63R/818A/83R/957A/P14/P15/PAQ	*	*	*	*	*		
		Not in conjunction with 955A/P87	*	*	*	*	*	*	
		Not in conjunction with U12						*	
		Only in conjunction with P29+P31	*	*	*	*	*		
U45	AMG illuminated door sills with "AMG" lettering and wi		-	-	-	-	-	●	178,50
		i.V.m. Code P97	-	-	-	-	-	○	0,00
		i.V.m. Code PYB	-	-	-	-	-	○	0,00
U45	Door sills with "Mercedes-Benz" lettering, illuminated		●	●	●	●	●	-	178,50
		i.V.m. Code PYB	○	○	○	○	○	-	0,00
256	AMG Track Pace		-	-	-	-	-	●	262,50
		Not in conjunction with 548						*	
		Only in conjunction with 365+549						*	
463	Head-up Display		●	●	●	●	●	●	1.102,50
		i.V.m. Code PYO	○	○	○	○	○	○	0,00
868	Widescreen cockpit		●	●	●	●	●	●	787,50
		i.V.m. Code PBP/PBR	○	○	○	○	○	○	0,00
		i.V.m. Code PYM/PYN/PYO	○	○	○	○	○	○	0,00
U19	MBUX augmented reality for navigation		●	●	●	●	●	●	409,50
		Not in conjunction with 548	*	*	*	*	*	*	
		Only in conjunction with 365+549+868	*	*	*	*	*	*	
891	Ambient lighting		S	S	S	S	S	S	0,00
H16	MANUFAKTUR piano lacquer, black flowing lines		●	●	●	●	●	●	1.044,75
		Not in conjunction with 660/736/H01/H13/H32/H36/H41/H64/H73	*	*	*	*	*		
		Not in conjunction with 685/732/737/764/779	*	*	*	*	*	*	
		Not in conjunction with P97 /U03/U15						*	
		Only in conjunction with 728	*	*	*	*	*	*	
		i.V.m. Code P87	●	●	●	●	●	●	834,75
		i.V.m. Code PYB	●	●	●	●	●	●	635,25
		i.V.m. Code(PYN/PYO)+P87	●	●	●	●	●	●	425,25
51U	Roof liner in black fabric		●	●	●	●	●	-	367,50
			-	-	-	-	-	○	0,00
		Not in conjunction with 205A/59U/805A/818A/957A	*	*	*	*	*		
		Not in conjunction with 55U/61U/65U/955A/P87	*	*	*	*	*	*	
		Not in conjunction with 875A/U12						*	
		Only in conjunction with U26						*	
		i.V.m. Code P29	○	○	○	○	○	-	0,00
55U	Roof liner in macchiato beige fabric		○	○	○	○	○	○	0,00
		Not in conjunction with 51U/61U/65U	*	*	*	*	*	*	
		Not in conjunction with 59U/B23/P89	*	*	*	*	*		
		Not in conjunction with L6K/P97 /U03/U15/U17/Y05						*	
		Only in conjunction with [201A/205A/214A/801A/805A/818A/844A/955A/957A]	*	*	*	*	*		
		Only in conjunction with [875A/955A]						*	
59U	Roof liner in neva grey fabric		○	○	○	○	○	-	0,00
		Not in conjunction with 205A/51U/55U/61U/65U/802A/805A/809A/818A/824A/827A/834A/955A/957A/P	*	*	*	*	*		
61U	MANUFAKTUR roof liner in black DINAMICA microfibre		●	●	●	●	●	●	1.680,00
		Not in conjunction with 205A/59U/805A/818A/957A	*	*	*	*	*	*	
		Not in conjunction with 51U/55U/65U/955A/P87	*	*	*	*	*	*	
		Not in conjunction with 875A/U12						*	
		Only in conjunction with 414	*	*	*	*	*	*	
		Only in conjunction with U26						*	
65U	MANUFAKTUR roof liner in macchiato beige DINAMICA		●	●	●	●	●	●	1.680,00
		Not in conjunction with 51U/55U/61U	*	*	*	*	*	*	
		Not in conjunction with 59U/B23/P89	*	*	*	*	*		
		Not in conjunction with P97 /U03/U15						*	

802+052
2021-12-14
2022-02-09

Αρ.Πρωτ 309

Legend (*) Available at extra cost (○) available without additional charge (S) standard equipment (-) not available (L) Left hand drive only (R) Right hand drive only (NS) National Standard *+
Please note that central restrictions are displayed. Markets may have specific deviation if any. Codes could be valid for certain countries only.

			CLS Coupé						Local price excl. VAT
Code	Equipment	Restrictions	257314 CLS 220 d	257319 CLS 300 d 4MATIC	257323 CLS 400 d 4MATIC	257350 CLS 350 (L)	257359 CLS 450 4MATIC	257361 Mercedes-AMG CLS 53 4MATIC+	
		Only in conjunction with 414	*	*	*	*	*	*	
		Only in conjunction with [201A/205A/214A/801A/805A/818A/844A/955A/957A]	*	*	*	*	*		
		Only in conjunction with [671A/875A/955A]						*	
955A	macchiato beige / tizian red		○	○	○	○	○	○	0,00
		Available only as part of (P87)						*	
		Not in conjunction with 51U/61U/736/U26	*	*	*	*	*	*	
		Not in conjunction with 59U/B23/P89	*	*	*	*	*		
		Not in conjunction with H41/L6K/P97/U03/U15/U17/Y05						*	
		Only in conjunction with 275+287+L6J+P49+P87+U12						*	
955A	macchiato beige / tizian red		○	○	○	○	○	○	0,00
		Available only as part of (P87)						*	
		Not in conjunction with 51U/61U/736/U26	*	*	*	*	*	*	
		Not in conjunction with 59U/B23/P89	*	*	*	*	*		
		Not in conjunction with H41/L6K/P97/U03/U15/U17/Y05						*	
		Only in conjunction with 275+287+L6J+P49+P87+U12						*	
955A	macchiato beige / tizian red		○	○	○	○	○	○	0,00
		Available only as part of (P87)						*	
		Not in conjunction with 51U/61U/736/U26	*	*	*	*	*	*	
		Not in conjunction with 59U/B23/P89	*	*	*	*	*		
		Not in conjunction with H41/L6K/P97/U03/U15/U17/Y05						*	
		Only in conjunction with 275+287+L6J+P49+P87+U12						*	
955A	macchiato beige / tizian red		○	○	○	○	○	○	0,00
		Available only as part of (P87)						*	
		Not in conjunction with 51U/61U/736/U26	*	*	*	*	*	*	
		Not in conjunction with 59U/B23/P89	*	*	*	*	*		
		Not in conjunction with H41/L6K/P97/U03/U15/U17/Y05						*	
		Only in conjunction with 275+287+L6J+P49+P87+U12						*	
802A	MANUFAKTUR yacht blue / black		○	○	○	○	○	-	0,00
		Available only as part of (P89)	*	*	*	*	*		
		Not in conjunction with 11R/55U/59U/63R/65U/83R/B20/P14/P15/P87/PAQ/U12	*	*	*	*	*		
		Only in conjunction with 275+287+P29+P31+P49+P89	*	*	*	*	*		
809A	MANUFAKTUR deep white / black		○	○	○	○	○	-	0,00
		Not in conjunction with 11R/55U/59U/63R/65U/83R/B20/P14/P15/P87/PAQ/U12	*	*	*	*	*		
		Only in conjunction with 275+287+P29+P31+P49+P89	*	*	*	*	*		
824A	MANUFAKTUR truffle brown / black		○	○	○	○	○	-	0,00
		Not in conjunction with 11R/55U/59U/63R/65U/83R/B20/P14/P15/P87/PAQ/U12	*	*	*	*	*		
		Only in conjunction with 275+287+P29+P31+P49+P89	*	*	*	*	*		
827A	MANUFAKTUR classic red / black		○	○	○	○	○	-	0,00
		Not in conjunction with 11R/55U/59U/63R/65U/83R/B20/P14/P15/P87/PAQ/U12	*	*	*	*	*		
		Only in conjunction with 275+287+P29+P31+P49+P89	*	*	*	*	*		
834A	MANUFAKTUR saddle brown / black		○	○	○	○	○	-	0,00
		Not in conjunction with 11R/55U/59U/63R/65U/83R/B20/P14/P15/P87/PAQ/U12	*	*	*	*	*		
		Only in conjunction with 275+287+P29+P31+P49+P89	*	*	*	*	*		
957A	MANUFAKTUR tizian red / macchiato beige		●	●	●	●	●	-	1.890,00
		Not in conjunction with 51U/59U/61U/736/B23/P89/U26	*	*	*	*	*		
		only in conjunction with 275+287+P87	*	*	*	*	*		
807A	MANUFAKTUR Bengal red / black		●	●	●	●	●	-	4.200,00
		Not in conjunction with 11R/55U/63R/65U/83R/B23/L5C/P14/P15/P87/P89/U12	*	*	*	*	*		
		Only in conjunction with 275+287+431+L2B+P29+P31+P49	*	*	*	*	*		
		i.V.m. Code PYN/PYO	●	●	●	●	●	-	2.572,50
818A	MANUFAKTUR magma grey / macchiato beige		●	●	●	●	●	-	2.457,00
		Not in conjunction with 032U/041U/124U/385U/51U/59U/61U/772/773U/B23/L5C/P29/P31/P87/P89/U12	*	*	*	*	*		
		Not in conjunction with U29			*		*		
		Only in conjunction with 275+287+431+L2B+P14+P15+P49	*	*	*	*	*		

802+052
2021-12-14
2022-02-09

Αρ.Πρωτ 309

Legend (*) Available at extra cost (○) available without additional charge (S) standard equipment (-) not available (L) Left hand drive only (R) Right hand drive only (NS) National Standard *+
Please note that central restrictions are displayed. Markets may have specific deviation if any. Codes could be valid for certain countries only.

			CLS Coupé						Local price excl. VAT
Code	Equipment	Restrictions	257314 CLS 220 d	257319 CLS 300 d 4MATIC	257323 CLS 400 d 4MATIC	257350 CLS 350 (L)	257359 CLS 450 4MATIC	257361 Mercedes-AMG CLS 53 4MATIC+	
275	Memory package		●	●	●	●	●	●	1.071,00
		Only in conjunction with P49	*	*	*	*	*	*	
		i.V.m. Code P97	-	-	-	-	-	○	0,00
		i.V.m. Code PYN	○	○	○	○	○	○	0,00
		i.V.m. Code PYO	○	○	○	○	○	○	0,00
401	Climatised front seats		●	●	●	●	●	-	1.155,00
			-	-	-	-	-	●	777,00
		Not in conjunction with 601A	*	*	*	*	*	*	
		Not in conjunction with 671A						*	
		Not in conjunction with 873	*	*	*	*	*	*	
		Only in conjunction with 275+P49	*	*	*	*	*	*	
		i.V.m. Code P68/432	●	●	●	●	●	-	777,00
		i.V.m. Code PBP	●	●	●	●	●	-	777,00
		i.V.m. Code PYN/PYO	●	●	●	●	●	-	777,00
		i.V.m. Code PBR	○	○	○	○	○	○	0,00
432	Active Multicontour Seat package		●	●	●	●	●	●	2.047,50
		Not in conjunction with 873	*	*	*	*	*	*	
		Only in conjunction with 275+902+P49	*	*	*	*	*	*	
		Only in conjunction with 436	*	*	*	*	*	*	
		i.V.m. Code PBP	●	●	●	●	●	●	1.669,50
		i.V.m. Code PBR	○	○	○	○	○	○	0,00
436	Comfort front head restraints		○	○	○	○	○	-	0,00
		Not in conjunction with 873	*	*	*	*	*	*	
		Only in conjunction with 275+432+902+P49	*	*	*	*	*	*	
873	Heated front seats		●	●	●	●	●	-	378,00
			-	-	-	-	-	S	0,00
		Not in conjunction with 401/432/902/P68/PBR	*	*	*	*	*	*	
		Not in conjunction with 436	*	*	*	*	*	*	
		i.V.m. Code PBP	○	○	○	○	○	-	0,00
		i.V.m. Code PYM/PYN/PYO	○	○	○	○	○	-	0,00
902	Seat heating Plus for driver and front passenger seats		○	○	○	○	○	○	0,00
		Not in conjunction with 873	*	*	*	*	*	*	
872	Heated rear seats		●	●	●	●	●	●	378,00
418	MANUFAKTUR steering wheel in nappa leather, two-ton		●	●	●	●	●	-	1.029,00
		Not in conjunction with 211A/601A/887A/B23/L5C	*	*	*	*	*	*	
		i.V.m. Code P89	○	○	○	○	○	-	0,00
431	Galvanised steering-wheel gearshift paddles		○	○	○	○	○	S	0,00
446	Touchpad without Controller		S	S	S	S	S	S	0,00
77B	MBUX Interior Assistant		●	●	●	●	●	●	315,00
		Only in conjunction with 446	*	*	*	*	*	*	
		i.V.m. Code PYO	○	○	○	○	○	○	0,00
B23	Omission of two-tone steering wheel		○	○	○	○	○	-	0,00
		Not in conjunction with 11R/418/55U/63R/65U/83R/B20/P14/P15/P87/U12	*	*	*	*	*	*	
		Only in conjunction with [802A/809A/824A/827A/834A]	*	*	*	*	*	*	
L2B	Multifunction steering wheel in nappa leather		○	○	○	○	○	-	0,00
		Not in conjunction with 211A/601A/887A/L5C	*	*	*	*	*	*	
		Only in conjunction with 431	*	*	*	*	*	*	
		only in conjunction with P14/P29	*	*	*	*	*	*	
L5C	Multifunction sports steering wheel in nappa leather		○	○	○	○	○	-	0,00
		Not in conjunction with 418/807A/818A/L2B/P14/P87	*	*	*	*	*	*	
		Only in conjunction with 431	*	*	*	*	*	*	
301	Ashtray inserts at front and rear in the stowage compa		●	●	●	●	●	●	47,25
309	Double cup holder		○	○	○	○	○	○	0,00
30P	Stowage Space package		S	S	S	S	S	S	0,00

802+052
2021-12-14
2022-02-09

Ap.Πρωτ 309

Legend

(*) Available at extra cost (○) available without additional charge (S) standard equipment (-) not available (L) Left hand drive only (R) Right hand drive only (NS) National Standard "+"
Please note that central restrictions are displayed. Markets may have specific deviation if any. Codes could be valid for certain countries only.

			CLS Coupé						Local price excl. VAT
Code	Equipment	Restrictions	257314 CLS 220 d	257319 CLS 300 d 4MATIC	257323 CLS 400 d 4MATIC	257350 CLS 350 (L)	257359 CLS 450 4MATIC	257361 Mercedes-AMG CLS 53 4MATIC+	
		Includes codes 309	*	*	*	*	*	*	
736	Open-pore black ash wood trim		●	●	●	●	●	●	409,50
		Not in conjunction with 660/957A/H01/H13/H16/H32/H36/H41/H64/H73	*	*	*	*	*		
		Not in conjunction with 685/728/732/764/779/955A/P87	*	*	*	*	*	*	
		Not in conjunction with P97/U03/U12/U15						*	
		Only in conjunction with 275+737+P49	*	*	*	*	*	*	
		Only in conjunction with U26						*	
		i.V.m. Code PYB	●	●	●	●	●	●	52,50
H01	High-gloss light brown sen wood trim		●	●	●	●	●	●	409,50
		Not in conjunction with 660/736/H13/H16/H32/H36/H41/H64/H73	*	*	*	*	*		
		Not in conjunction with 685/728/732/737/764	*	*	*	*	*	*	
		Not in conjunction with P97/U03/U15						*	
		Only in conjunction with 779	*	*	*	*	*	*	
		i.V.m. Code P87	●	●	●	●	●	●	199,50
		i.V.m. Code PYB	●	●	●	●	●	●	52,50
H13	High-gloss grey wood trim		●	●	●	●	●	●	409,50
		Not in conjunction with 685/728/732/737/764/779	*	*	*	*	*	*	
		Not in conjunction with 736/H01/H16/H32/H36/H41/H64/H73	*	*	*	*	*	*	
		Not in conjunction with P97/U03/U15						*	
		Only in conjunction with 660	*	*	*	*	*	*	
		i.V.m. Code P87	●	●	●	●	●	●	199,50
		i.V.m. Code PYB	●	●	●	●	●	●	52,50
H32	Grey open-pore ash wood trim		●	●	●	●	●	●	409,50
		Not in conjunction with 660/736/H01/H13/H16/H36/H41/H64/H73	*	*	*	*	*		
		Not in conjunction with 685/728/732/737/779	*	*	*	*	*	*	
		Not in conjunction with P97/U03/U15						*	
		Only in conjunction with 764	*	*	*	*	*	*	
		i.V.m. Code P87	●	●	●	●	●	●	199,50
		i.V.m. Code PYB	○	○	○	○	○	○	0,00
H36	Brown open-pore walnut wood trim		●	●	●	●	●	●	409,50
		Not in conjunction with 660/736/H01/H13/H16/H32/H41/H64/H73	*	*	*	*	*		
		Not in conjunction with 728/732/737/764/779	*	*	*	*	*	*	
		Not in conjunction with P97/U03/U15						*	
		Only in conjunction with 685	*	*	*	*	*	*	
		i.V.m. Code PYB	●	●	●	●	●	●	52,50
		i.V.m. Code P87	○	○	○	○	○	○	0,00
H41	Light longitudinal-grain aluminium trim		○	○	○	○	○	○	0,00
		Not in conjunction with 660/736/H01/H13/H16/H32/H36/H64/H73	*	*	*	*	*	*	
		Not in conjunction with 685/764/779/P87	*	*	*	*	*	*	
		Not in conjunction with 955A/P97/U03/U12/U15						*	
		Only in conjunction with U26						*	
H64	Metal-weave trim		●	●	●	●	●	●	472,50
		Not in conjunction with 660/736/H01/H13/H16/H32/H36/H41/H73	*	*	*	*	*		
		Not in conjunction with 685/732/737/764/779	*	*	*	*	*	*	
		Not in conjunction with P97/U03/U15						*	
		Only in conjunction with 728	*	*	*	*	*	*	
		i.V.m. Code P87	●	●	●	●	●	●	262,50
		i.V.m. Code PYB	●	●	●	●	●	●	63,00
H73	AMG carbon-fibre trim		●	●	●	●	●	●	3.097,50
		Not in conjunction with 660/736/H01/H13/H16/H32/H36/H41/H64	*	*	*	*	*		
		Not in conjunction with 685/728/737/764/779	*	*	*	*	*	*	
		Only in conjunction with 732	*	*	*	*	*	*	
		i.V.m. Code PYB	●	●	●	●	●	●	2.688,00
		i.V.m. Code P97	-	-	-	-	-	○	0,00

802+052
2021-12-14
2022-02-09

Αρ.Πρωτ 309

Legend

(*) Available at extra cost (○) available without additional charge (S) standard equipment (-) not available (L) Left hand drive only (R) Right hand drive only (NS) National Standard *+
Please note that central restrictions are displayed. Markets may have specific deviation if any. Codes could be valid for certain countries only.

			CLS Coupé						Local price excl. VAT
Code	Equipment	Restrictions	257314 CLS 220 d	257319 CLS 300 d 4MATIC	257323 CLS 400 d 4MATIC	257350 CLS 350 (L)	257359 CLS 450 4MATIC	257361 Mercedes-AMG CLS 53 4MATIC+	
861A	black		-	-	-	-	-	●	2.383,50
		Not in conjunction with 55U/65U/P87/P97/U03/U12/U15						*	
		Only in conjunction with 275+287+P49+U26						*	
		i.V.m. Code PYH	-	-	-	-	-	○	0,00
871A	black		-	-	-	-	-	●	2.383,50
		Not in conjunction with 55U/65U/P87/P97/U03/U12/U15						*	
		Only in conjunction with 275+287+P49+U26						*	
		i.V.m. Code PYH	-	-	-	-	-	○	0,00
875A	macchiato beige / magma grey		-	-	-	-	-	●	2.593,50
		Not in conjunction with 51U/61U/L6K/P87/P97/U03/U12/U15						*	
		Only in conjunction with 275+287+L6J+P49+U26						*	
		i.V.m. Code PYH	-	-	-	-	-	●	210,00
877A	bengal red / black		-	-	-	-	-	●	2.593,50
		Not in conjunction with 55U/65U/P87/P97/U03/U12/U15						*	
		Only in conjunction with 275+287+P49+U26						*	
		i.V.m. Code PYH	-	-	-	-	-	●	210,00
868A	black / silver grey pearl		-	-	-	-	-	●	2.593,50
		Not in conjunction with 55U/65U/P87/U12						*	
		Only in conjunction with 275+287+P49+U26						*	
		i.V.m. Code PYH	-	-	-	-	-	●	210,00
		i.V.m. Code P97	-	-	-	-	-	○	0,00
601A	black		○	○	○	○	○	-	0,00
		Available only as part of (P29)	*	*	*	*	*		
		Not in conjunction with 11R/401/418/55U/63R/65U/83R/B20/B23/L2B/P14/P15/P87/P89/PBR/U12/U38	*	*	*	*	*		
		Only in conjunction with 431+L5C+P29+P31	*	*	*	*	*		
671A	black		-	-	-	-	-	○	0,00
		Not in conjunction with 401/55U/P87/P97/PBR/U03/U12/U15/U38						*	
		Only in conjunction with U26						*	
201A	black		○	○	○	○	○	-	0,00
		Not in conjunction with B23/P87/P89/U38	*	*	*	*	*		
		i.V.m. Code P31 ohne PYH	●	●	●	●	●	-	1.627,50
205A	macchiato beige / magma grey		●	●	●	●	●	-	210,00
		Not in conjunction with 51U/59U/61U/B23/P87/P89/U38	*	*	*	*	*		
		i.V.m. Code P31 ohne PYH	●	●	●	●	●	-	1.837,50
211A	black		●	●	●	●	●	-	1.627,50
		Not in conjunction with 11R/418/55U/63R/65U/83R/B20/B23/L2B/P14/P15/P87/P89/U12/U38	*	*	*	*	*		
		Only in conjunction with 287+431+L5C+P29+P31	*	*	*	*	*		
		i.V.m. Code PYH	○	○	○	○	○	-	0,00
214A	sienna brown / black		●	●	●	●	●	-	210,00
		Not in conjunction with B23/P87/P89/U38	*	*	*	*	*		
		i.V.m. Code P31 ohne PYH	●	●	●	●	●	-	1.837,50
219A	neva grey / magma grey		●	●	●	●	●	-	210,00
		Not in conjunction with 55U/65U/B23/P87/P89/U38	*	*	*	*	*		
		i.V.m. Code P31 ohne PYH	●	●	●	●	●	-	1.837,50
801A	black		●	●	●	●	●	-	1.270,50
		Not in conjunction with B23/P87/P89	*	*	*	*	*		
		i.V.m. Code P31	●	●	●	●	●	-	2.383,50
		i.V.m. Code PYH	●	●	●	●	●	-	756,00
805A	macchiato beige / magma grey		●	●	●	●	●	-	1.480,50
		Not in conjunction with 51U/59U/61U/B23/P87/P89	*	*	*	*	*		
		i.V.m. Code P31	●	●	●	●	●	-	2.593,50
		i.V.m. Code PYH	●	●	●	●	●	-	756,00
819A	neva grey / magma grey		●	●	●	●	●	-	3.370,50
		Not in conjunction with 55U/65U/B23/P87/P89	*	*	*	*	*		

802+052
2021-12-14
2022-02-09

Αρ.Πρωτ 309

Legend (*) Available at extra cost (○) available without additional charge (S) standard equipment (-) not available (L) Left hand drive only (R) Right hand drive only (NS) National Standard *+
Please note that central restrictions are displayed. Markets may have specific deviation if any. Codes could be valid for certain countries only.

			CLS Coupé						Local price excl. VAT
Code	Equipment	Restrictions	257314 CLS 220 d	257319 CLS 300 d 4MATIC	257323 CLS 400 d 4MATIC	257350 CLS 350 (L)	257359 CLS 450 4MATIC	257361 Mercedes-AMG CLS 53 4MATIC+	
		i.V.m. Code P31	●	●	●	●	●	-	2.593,50
		i.V.m. Code PYH	●	●	●	●	●	-	756,00
844A	sienna brown / black		●	●	●	●	●	-	1.480,50
		Not in conjunction with B23/P87/P89	*	*	*	*	*		
		i.V.m. Code P31	●	●	●	●	●	-	2.593,50
		i.V.m. Code PYH	●	●	●	●	●	-	756,00
887A	black / bengal red		●	●	●	●	●	-	2.593,50
		Not in conjunction with 11R/418/55U/63R/65U/83R/B20/B23/L2B/P14/P15/P87/P89/U12	*	*	*	*	*		
		Only in conjunction with 287+431+L5C+P29+P31	*	*	*	*	*		
		i.V.m. Code PYH	●	●	●	●	●	-	756,00
P14	AVANTGARDE interior		S	S	S	S	S	-	0,00
		Includes codes 59U [51U/55U/61U/65U]+H01 [736/H16/H32/H41/H64/H73]+L2B	*	*	*	*	*		
		Not in conjunction with 032U/041U/124U/211A/385U/601A/772/773U/802A/807A/809A/824A/827A/834	*	*	*	*	*		
		Not in conjunction with U29			*		*		
		Only in conjunction with P15	*	*	*	*	*		
P15	AVANTGARDE exterior		S	S	S	S	S	-	0,00
		Includes codes 83R [11R/RRE/RRF/RVQ/RVS]	*	*	*	*	*		
		Not in conjunction with 032U/041U/124U/211A/385U/601A/772/773U/802A/807A/809A/824A/827A/834	*	*	*	*	*		
		Not in conjunction with U29			*		*		
		Only in conjunction with P14	*	*	*	*	*		
P29	AMG Line interior		○	○	○	○	○	-	0,00
		Includes codes 59U [51U/55U/61U/65U]+601A [201A/205A/211A/801A/805A/887A/955A]+H41 [H16/H32	*	*	*	*	*		
		Not in conjunction with 11R/63R/818A/83R/P14/P15	*	*	*	*	*		
		Only in conjunction with P31	*	*	*	*	*		
P31	AMG Line exterior		●	●	●	●	●	-	1.207,50
		Includes codes 772+RRE [RRF/RVQ/RVS]+U95 [U46]	*			*			
		Includes codes 772+RRE [RRF/RVQ/RVS]+U95		*	*	*	*		
		Not in conjunction with 11R/63R/818A/83R/P14/P15	*	*	*	*	*		
		Only in conjunction with P29	*	*	*	*	*		
		i.V.m. Code U46	●	●	-	●	●	-	997,50
		i.V.m. Code PYH	○	○	○	○	○	-	0,00
P87	MANUFAKTUR interior in macchiato beige / titian red		-	-	-	-	-	●	4.882,50
			●	●	●	●	●	-	3.255,00
		Includes codes 55U [65U]+955A [957A]+H36 [H01/H13/H16/H32/H64/H73]+L2B+U38	*	*	*	*	*		
		Includes codes 55U [65U]+955A+H36 [H01/H13/H16/H32/H64/H73]+U38						*	
		Not in conjunction with 51U/61U/736/H41/U26	*	*	*	*	*	*	
		Not in conjunction with 59U/B23/L5C/P89	*	*	*	*	*		
		Not in conjunction with L6K/P97/U03/U15/U17/Y05						*	
		Only in conjunction with 275+287+P49	*	*	*	*	*	*	
		Only in conjunction with 431+[955A/957A]	*	*	*	*	*		
		Only in conjunction with L6J+U12						*	
		i.V.m. Code P31	●	●	●	●	●	-	4.882,50
		i.V.m. Code PYN/PYO	●	●	●	●	●	-	2.362,50
		i.V.m. Code PYN/PYO	-	-	-	-	-	●	1.706,25
P89	MANUFAKTUR interior in a two-tone finish		●	●	●	●	●	-	5.145,00
		Includes codes 418 [B23]+802A [809A/824A/827A/834A]+B62 [U26]	*	*	*	*	*		
		Not in conjunction with 11R/55U/59U/63R/65U/83R/B20/P14/P15/P87/PAQ/U12	*	*	*	*	*		
		Only in conjunction with 275+287+P29+P31+P49	*	*	*	*	*		
		Only in conjunction with [802A/809A/824A/827A/834A]	*	*	*	*	*		
		i.V.m. Code PYN/PYO	●	●	●	●	●	-	1.963,50
362	Communications module (LTE) for the use of Mercedes		○	○	○	○	○	○	0,00
20U	Pre-installation for car sharing		●	●	●	●	●	●	52,50
		i.V.m. Code PYB	○	○	○	○	○	○	0,00
33U	Remote Services Plus		●	●	●	●	●	●	157,50

802+052
2021-12-14
2022-02-09

Ap.Πρωτ 309

Legend (*) Available at extra cost (○) available without additional charge (S) standard equipment (-) not available (L) Left hand drive only (R) Right hand drive only (NS) National Standard *+
Please note that central restrictions are displayed. Markets may have specific deviation if any. Codes could be valid for certain countries only.

			CLS Coupé						Local price excl. VAT
Code	Equipment	Restrictions	257314 CLS 220 d	257319 CLS 300 d 4MATIC	257323 CLS 400 d 4MATIC	257350 CLS 350 (L)	257359 CLS 450 4MATIC	257361 Mercedes-AMG CLS 53 4MATIC+	
		Not in conjunction with 34U	*	*	*	*	*	*	
		i.V.m. Code PYB	○	○	○	○	○	○	0,00
34U	Remote Services Premium		●	●	●	●	●	●	262,50
		Not in conjunction with 33U	*	*	*	*	*	*	
351	Mercedes-Benz emergency call system		○	○	○	○	○	○	0,00
00B	Owner's Manual and service information - Danish		○	○	○	○	○	○	0,00
01B	Owner's Manual and service information - Dutch		○	○	○	○	○	○	0,00
01U	Preinstallation for Navigation Services		○	○	○	○	○	○	0,00
		Available only as part of (PBF)	*	*	*	*	*	*	
		Only in conjunction with PBF	*	*	*	*	*	*	
02B	Owner's Manual and service information - German		○	○	○	○	○	○	0,00
03B	Owner's Manual and service information - Russian		○	○	○	○	○	○	0,00
04B	Owner's Manual and service information - Finnish		○	○	○	○	○	○	0,00
05B	Owner's Manual and service information - English		○	○	○	○	○	○	0,00
06B	Owner's Manual and service information - Italian		○	○	○	○	○	○	0,00
07B	Owner's Manual and service information - French		○	○	○	○	○	○	0,00
08B	Owner's Manual and service information - Spanish		○	○	○	○	○	○	0,00
09B	Owner's Manual and service information - Portuguese		○	○	○	○	○	○	0,00
10B	Owner's Manual and service information - Swedish		○	○	○	○	○	○	0,00
11B	Owner's Manual and service information - Arabic		○	○	○	○	○	○	0,00
12B	Owner's Manual and service information - English USA		-	-	-	-	○	○	0,00
12U	Preinstallation for Concierge Service		○	○	○	○	○	○	0,00
13B	Owner's Manual and service information - Norwegian		○	○	○	○	○	○	0,00
14B	Owner's Manual and service information - Greek		○	○	○	○	○	○	0,00
15B	Owner's Manual and service information - Turkish		○	○	○	○	○	○	0,00
15U	Pre-installation for Mercedes-Benz Link		○	○	○	○	○	○	0,00
16B	Owner's Manual and service information - Polish		○	○	○	○	○	○	0,00
16U	Apple CarPlay		○	○	○	○	○	○	0,00
		Only in conjunction with 14U+17U	*	*	*	*	*	*	
17B	Owner's Manual and service information - Czech		○	○	○	○	○	○	0,00
17U	Android Auto		○	○	○	○	○	○	0,00
		Only in conjunction with 14U+16U	*	*	*	*	*	*	
18B	Owner's Manual and service information - English South Africa		○	○	○	○	○	○	0,00
18U	Baidu Carlife		-	-	-	-	-	-	0,00
19B	Owner's Manual and service information - French South Africa		○	○	○	○	○	○	0,00
20B	Owner's Manual and service information - Spanish South Africa		○	○	○	○	○	○	0,00
21B	Owner's Manual and service information - Portuguese South Africa		○	○	○	○	○	○	0,00
221	Electrically adjustable front seat, left		●	-	-	-	-	-	446,25
			-	-	-	-	○	○	0,00
222	Electrically adjustable front seat, right		●	-	-	-	-	-	446,25
			-	-	-	-	○	○	0,00
22B	Owner's Manual and service information - Japanese		○	-	-	-	○	○	0,00
232	Garage door opener (frequency range 284-390 MHz)		-	-	-	●	●	●	236,25
23B	Owner's Manual and service information - simplified Chinese		-	-	-	○	-	-	0,00
23U	Active traffic-assist		○	○	○	○	○	○	0,00
		Not in conjunction with 234/243/258/504	*	*	*	*	*	*	
		Only in conjunction with 235+292+365+513+546+K33+K34+P49	*	*	*	*	*	*	
		Only in conjunction with P20	*	*	*	*	*	*	
249	interior mirror and driver's exterior mirror automatical		○	○	○	○	○	○	0,00
		Available only as part of (P49)	*	*	*	*	*	*	
		Only in conjunction with P49	*	*	*	*	*	*	
24B	Owner's Manual and service information - traditional Chinese		○	○	○	○	○	○	0,00
251	Increase in top speed, USA		-	-	-	-	-	●	2.310,00
25B	Owner's Manual and service information - Korean		-	○	○	-	○	○	0,00

802+052
2021-12-14
2022-02-09

Αρ.Πρωτ 309

Legend (*) Available at extra cost (○) available without additional charge (S) standard equipment (-) not available (L) Left hand drive only (R) Right hand drive only (NS) National Standard *+
Please note that central restrictions are displayed. Markets may have specific deviation if any. Codes could be valid for certain countries only.

			CLS Coupé						Local price excl. VAT
Code	Equipment	Restrictions	257314 CLS 220 d	257319 CLS 300 d 4MATIC	257323 CLS 400 d 4MATIC	257350 CLS 350 (L)	257359 CLS 450 4MATIC	257361 Mercedes-AMG CLS 53 4MATIC+	
261	Omission of badge		-	-	-	-	-	○	0,00
263	Number plate mounting for Asia / Mexico		○	○	○	○	○	○	0,00
264	Number plate mounting for America		-	-	-	-	○	○	0,00
		Only for left hand drive						*	
26B	Owner's Manual and service information - Chinese Taiwan		-	-	-	○	-	○	0,00
270	Aerial for GPS		S	S	S	S	S	S	0,00
274	Telephone aerial		○	○	○	○	○	○	0,00
		Not in conjunction with 897	*	*	*	*	*	*	
		Only in conjunction with 899	*	*	*	*	*	*	
27B	Fully electric front seats		-	-	-	-	●	●	892,50
			○	-	-	-	-	-	0,00
27B	Owner's Manual and Service Booklet - Spanish Mexico		○	○	○	○	○	○	0,00
30B	Owner's Manual and service information - Slovenian		○	○	○	○	○	○	0,00
31B	Owner's Manual and service information - Hungarian		○	○	○	○	○	○	0,00
32B	Owner's Manual and service information - Bulgarian		○	○	○	○	○	○	0,00
33B	Owner's Manual and service information - Romanian		○	○	○	○	○	○	0,00
34B	Owner's Manual and service information - Croatian		○	○	○	○	○	○	0,00
35B	Owner's Manual and service information - Latvian		○	○	○	○	○	○	0,00
36B	Owner's Manual and service information - Lithuanian		○	○	○	○	○	○	0,00
37B	Owner's Manual and service information - Slovak		○	○	○	○	○	○	0,00
37U	Advanced connectivity Plus		●	●	●	●	●	●	262,50
38B	Owner's Manual and service information - Estonian		○	○	○	○	○	○	0,00
39B	Owner's Manual and service information - Serbian		○	○	○	○	○	○	0,00
40B	Owner's Manual and service information - Ukrainian		○	○	○	○	○	○	0,00
41B	Owner's Manual and service information - Hebrew		○	○	○	○	○	○	0,00
42B	Owner's Manual and service information - Indonesian		○	○	○	○	○	○	0,00
43B	Owner's Manual and service information - Thai		○	○	○	○	○	○	0,00
44B	Owner's Manual and service information - Vietnamese		○	○	○	○	○	○	0,00
460	Canada specification		-	-	-	-	○	○	0,00
461	Instrument display in miles with English lettering		○	○	○	○	○	○	0,00
469	Increased tyre pressure		○	○	○	○	○	-	0,00
477	Tyre pressure loss warning system		○	○	○	○	○	○	0,00
481	Underguard		●	●	●	●	●	-	115,50
494	USA specification		-	-	-	-	○	○	0,00
498	Japan specification		○	-	-	-	○	○	0,00
500	Electrically folding exterior mirrors		○	○	○	○	○	○	0,00
		Available only as part of (P49)	*	*	*	*	*	*	
		Only in conjunction with P49	*	*	*	*	*	*	
501	360° camera		○	○	○	○	○	○	0,00
		Available only as part of (P47)	*	*	*	*	*	*	
		Not in conjunction with 218/P44	*	*	*	*	*	*	
		Only in conjunction with P47+P49	*	*	*	*	*	*	
513	Traffic Sign Assist		●	●	●	●	●	●	309,75
		Not in conjunction with 504	*	*	*	*	*	*	
		Only in conjunction with 365	*	*	*	*	*	*	
		i.V.m. Code PYB	○	○	○	○	○	○	0,00
517	HD digital radio standard		○	○	○	○	○	○	0,00
524	Transport protection (full body cover)		●	●	●	●	●	●	168,00
536	Sirius satellite radio		-	-	-	-	●	●	708,75
548	MBUX multimedia system		○	○	○	○	○	○	0,00
		Not in conjunction with 256						*	
		Not in conjunction with 549/PBP/PBR/U19	*	*	*	*	*	*	
549	MBUX multimedia system		○	○	○	○	○	○	0,00
		Not in conjunction with 548	*	*	*	*	*	*	

Legend (*) Available at extra cost (○) available without additional charge (S) standard equipment (-) not available (L) Left hand drive only (R) Right hand drive only (NS) National Standard "+": Please note that central restrictions are displayed. Markets may have specific deviation if any. Codes could be valid for certain countries only.

			CLS Coupé						Local price excl. VAT
Code	Equipment	Restrictions	257314 CLS 220 d	257319 CLS 300 d 4MATIC	257323 CLS 400 d 4MATIC	257350 CLS 350 (L)	257359 CLS 450 4MATIC	257361 Mercedes-AMG CLS 53 4MATIC+	
551	Anti-theft alarm system (ATA) with tow-away protection		○	○	○	○	○	○	0,00
552	Anti-theft alarm system with preinstallation for collision		○	○	○	○	○	○	0,00
596	heat-insulating, noise-insulating and infrared-reflecting		○	○	○	○	○	○	0,00
		Available only as part of (PAF)	*	*	*	*	*	*	
		Not in conjunction with 840	*	*	*	*	*	*	
		Only in conjunction with PAF	*	*	*	*	*	*	
623	Gulf States specification		-	-	-	○	○	○	0,00
625	Australia specification		○	-	-	○	○	○	0,00
631	LED High Performance headlamps		○	○	○	○	○	○	0,00
634	Omission of first-aid kit		○	○	○	○	○	○	0,00
636	Omission of warning triangle		○	○	○	○	○	○	0,00
640	LED Intelligent Light System (LHD)		-	-	-	-	○	○	0,00
641	MULTIBEAM LED		○	○	○	○	○	○	0,00
642	MULTIBEAM LED		○	○	○	○	○	○	0,00
		Available only as part of (P35)	*	*	*	*	*	*	
		Not in conjunction with 608/632	*	*	*	*	*	*	
		Only in conjunction with P35	*	*	*	*	*	*	
651	Winter complete wheels fitted		○	○	○	○	○	○	0,00
652	Summer complete tyres fitted		○	○	○	○	○	○	0,00
666	Freight packaging without tie-down hooks		LS	LS	LS	LS	LS	LS	0,00
668	Prod. prot. f. freight pkging with tie-down hooks		●	●	●	●	●	●	26,25
670	Residual engine heat utilisation		○	○	○	○	○	○	0,00
		Not in conjunction with 580	*	*	*	*	*	*	
		Only in conjunction with 581	*	*	*	*	*	*	
687	Type plate with model year		○	○	○	○	○	○	0,00
		Not in conjunction with 966/967	*	*	*	*	*	*	
690	Pre-installation for the spare wheel		○	○	○	○	○	○	0,00
6U7	BlueTEC diesel emission control system including generator		○	○	-	-	-	-	0,00
		Not in conjunction with 927/971	*						
		Not in conjunction with U79	*	*					
		Only in conjunction with B01	*						
		Only in conjunction with U85	*	*					
762	Remote control unit		○	○	○	○	○	○	0,00
763	Key with Radio remote control with panic switch		-	-	-	○	○	○	0,00
776	Wider wheel arch for AMG wheels		○	○	○	○	○	S	0,00
		Not in conjunction with 11R/83R	*	*	*	*	*		
		only in conjunction with P31	*	*	*	*	*		
79B	Preinstallation for digital radio		○	○	○	○	○	○	0,00
802	Technical modifications		○	○	○	○	○	○	0,00
817	Encapsulation for ATA alarm siren		○	○	○	○	○	○	0,00
820	Tourist vehicle		○	○	○	○	○	○	0,00
821	Country code Brazil		-	-	-	○	-	○	0,00
822	South Africa specification		○	○	○	○	○	○	0,00
823	Indicator plate fixing Switzerland		○	○	○	○	○	○	0,00
824	Additional parts for cold countries		○	○	○	○	○	○	0,00
827	Number plate mounting China		○	○	○	○	○	○	0,00
829	Taiwan version		○	○	○	○	○	○	0,00
830	China specification		-	-	-	-	-	-	0,00
831	Indicator plate fixing Italy		○	○	○	○	○	○	0,00
834	New Zealand specification		○	-	-	○	○	○	0,00
835	South Korea specification		-	○	○	-	○	○	0,00
852	Sensor system for anti-theft alarm system		-	-	-	-	○	○	0,00
865	TV receiver		●	●	●	●	●	●	1.039,50
876	Interior Light package		S	S	S	S	S	S	0,00

802+052
2021-12-14
2022-02-09

Αρ.Πρωτ 309

Legend (*) Available at extra cost (○) available without additional charge (S) standard equipment (-) not available (L) Left hand drive only (R) Right hand drive only (NS) National Standard "+
Please note that central restrictions are displayed. Markets may have specific deviation if any. Codes could be valid for certain countries only.

			CLS Coupé						Local price excl. VAT
Code	Equipment	Restrictions	257314 CLS 220 d	257319 CLS 300 d 4MATIC	257323 CLS 400 d 4MATIC	257350 CLS 350 (L)	257359 CLS 450 4MATIC	257361 Mercedes-AMG CLS 53 4MATIC+	
882	Interior monitoring system		○	○	○	○	○	○	0,00
885	Increased anti-theft protection		●	●	●	●	●	●	63,00
906	Armrest heating for driver and front passenger		○	○	○	○	○	○	0,00
		Available only as part of (P68)	*	*	*	*	*	*	
		Not in conjunction with 873	*	*	*	*	*	*	
		Only in conjunction with 275+P49+P68	*	*	*	*	*	*	
910	Alternator, with higher capacity		○	○	○	○	○	○	0,00
913	Air conditioning preinstallation for hot countries		○	○	○	○	○	○	0,00
919	Air Conditioning Enhancement package/improved cool		○	○	○	○	○	○	0,00
922	Reduced power version		-	-	-	-	-	-	0,00
926	Emission control system with EU4 technology		-	-	-	○	○	○	0,00
927	EU6 emissions standard		○	○	○	○	○	○	0,00
		Not in conjunction with 6U7/972/B01/B63	*						
		Not in conjunction with U79		*					
		Only in conjunction with 6U7+972		*					
		Only in conjunction with 971	*		*				
		Only in conjunction with U79	*						
		Only in conjunction with U85	*	*					
943	Toll payment system		●	●	●	●	●	●	210,00
945	Emission control system China		-	-	-	-	-	-	0,00
961	Petrol particulate filter		-	-	-	○	○	○	0,00
966	COC document EU5 without registration certificate par		○	○	○	○	○	○	0,00
		Not in conjunction with 687/967	*	*	*	*	*	*	
967	COC document EU5 with registration certificate part II		○	○	○	○	○	○	0,00
		Not in conjunction with 687/966	*	*	*	*	*	*	
968	COC document EU6 without registration certificate par		○	○	○	○	○	○	0,00
969	COC document EU6 with registration certificate part II		○	○	○	○	○	○	0,00
971	Diesel particulate filter		○	-	○	-	-	-	0,00
		Not in conjunction with 6U7/972/B01/B63	*						
		Only in conjunction with U79+U85	*						
972	Exhaust system with DPF Generation 2.0		○	○	-	-	-	-	0,00
		Not in conjunction with 927/971	*						
		Only in conjunction with B01	*						
973	Designation as owner-driver rental vehicle		○	○	○	○	○	○	0,00
978	Vehicle for bodybuilder		○	○	○	○	○	-	0,00
981	Omission of vehicle registration document		○	○	○	○	○	○	0,00
986	Identification no. (US-VIN)		○	○	○	○	○	○	0,00
989	Identification label under windshield		○	○	○	○	○	○	0,00
997	Exhibition vehicle		○	○	○	○	○	○	0,00
999	Petrol particulate filter		-	-	-	○	-	-	0,00
B01	EQ Boost starter-alternator		○	○	-	S	S	S	0,00
		Not in conjunction with 927/971	*						
		invalid	*						
B08	Fanfares for Asia		○	○	○	○	○	○	0,00
B12	Tyre-change toolkit		○	○	○	○	○	○	0,00
B18	Spectacles compartment for driver		○	○	○	○	○	○	0,00
B63	Sporty engine sound		○	○	S	S	S	-	0,00
		Not in conjunction with 927/971	*						
		Only in conjunction with B01	*						
C52	AMG Indoor car cover		-	-	-	-	-	○	0,00
		Available only as part of (P97)						*	
		Not in conjunction with 55U/65U/685/728/737/764/779/H13/P87/R05/R66/U12/Z01/Z02/Z98						*	
		Only in conjunction with 868A						*	
		Only in conjunction with [049U/297U]+H73+RZU+5U6+732+7U8+P49+P60+P97+R01+U26						*	

802+052
2021-12-14
2022-02-09

Αρ.Πρωτ 309

Legend (*) Available at extra cost (○) available without additional charge (S) standard equipment (-) not available (L) Left hand drive only (R) Right hand drive only (NS) National Standard **+
Please note that central restrictions are displayed. Markets may have specific deviation if any. Codes could be valid for certain countries only.

			CLS Coupé						Local price excl. VAT
Code	Equipment	Restrictions	257314 CLS 220 d	257319 CLS 300 d 4MATIC	257323 CLS 400 d 4MATIC	257350 CLS 350 (L)	257359 CLS 450 4MATIC	257361 Mercedes-AMG CLS 53 4MATIC+	
E07	Location and tracking system		-	-	●	●	●	●	336,00
E5P	Installation of driving aids		○	○	○	○	○	○	0,00
		Only for left hand drive	*	*	*		*	*	
		only in conjunction with E08/E09/E85	*	*	*	*	*	*	
K32	Active Lane Change Assist		○	○	○	○	○	○	0,00
K33	Extended automatic Re-start in traffic jams		○	○	○	○	○	○	0,00
		Not in conjunction with 234/243/258/504	*	*	*	*	*	*	
		Only in conjunction with 233+235+365+513+546+K34+P49	*	*	*	*	*	*	
K34	Route-based speed adaptation		○	○	○	○	○	○	0,00
		Not in conjunction with 234/243/258/504	*	*	*	*	*	*	
		Only in conjunction with 233+365+513+546+P49	*	*	*	*	*	*	
L	Left-hand drive		○	○	○	○	○	○	0,00
P53	Fine particle sensor		-	○	-	-	○	○	0,00
P97	Limited Edition		-	-	-	-	-	●	14.595,00
		Includes codes 275+287+C52+E28+H73+L6J [L6K]+P71+PAZ+RZU+U15 [U03]+U33+U45						*	
		Not in conjunction with 55U/65U/685/728/737/764/779/H13/P87/R05/R66/U12/Z01/Z02/Z98						*	
		Only in conjunction with 868A						*	
		Only in conjunction with [049U/297U]+H73+RZU+5U6+732+7U8+P49+P60+R01+U26+U70						*	
		i.V.m. Code PYN/PYO	-	-	-	-	-	●	10.095,75
PWS	Standard equipment package		●	●	●	-	-	-	2.604,00
			-	-	-	●	●	●	2.551,50
PYB	SE Package		-	-	-	-	LS	LS	0,00
			LS	LS	LS	-	-	-	0,00
			-	-	-	LS	-	-	0,00
PYC	SE Plus Package		-	-	-	-	-	LS	0,00
PYH	AMG Line		LS	LS	-	LS	-	-	0,00
			-	-	LS	-	LS	-	0,00
			-	-	-	-	-	LS	0,00
PYM	Advantage Package		-	-	-	-	-	●	4824,75
			●	●	-	●	-	-	2.746,00
			-	-	LS	-	LS	-	0,00
		invalid						*	
PYN	Premium Package		●	●	-	●	-	-	4.152,00
			-	-	●	-	●	-	1.556,00
			-	-	-	-	-	LS	5.071,50
PYO	Premium Plus package		●	●	-	●	-	-	6.191,00
			-	-	●	-	●	-	3.758,00
			-	-	-	-	-	●	2.299,00
R	Right-hand drive		●	●	●	●	●	●	1.905,75
R01	Summer tyres		○	○	○	○	○	○	0,00
		Not in conjunction with R05						*	
R02	All-season tyres		-	-	-	-	○	○	0,00
R06	Noise reduced tyre with foam absorber		○	○	○	○	○	○	0,00
		Not in conjunction with 645	*	*	*	*	*		
		in conjunction with 460/494 only with R01+R66+RVO/RVP/RTY/RTZ/RZU						*	
		in conjunction with R01+R66 only with 11R/49R/R82/R98/RRE/RRF/RVO/RVP/RVR	*		*	*	*	*	
		in conjunction with R03 not with R66	*		*	*	*	*	
		in conjunction with R03 only with 11R/49R/R82/RRE/RRF	*	*	*	*	*	*	
U01	Status display for rear seat belts in instrument cluster		○	○	○	○	○	○	0,00
U03	Omission of decals for special models		-	-	-	-	-	○	0,00
		Not in conjunction with 55U/65U/685/728/737/764/779/H13/P87/R05/R66/U12/U15/Z01/Z02/Z98						*	
		Only in conjunction with 868A						*	
		Only in conjunction with [049U/297U]+H73+RZU+5U6+732+7U8+P49+P60+P97+R01+U26						*	
U10	Automatic front passenger airbag deactivation		○	○	○	○	○	○	0,00

802+052
2021-12-14
2022-02-09

Αρ.Πρωτ 309

Legend (*) Available at extra cost (○) available without additional charge (S) standard equipment (-) not available (L) Left hand drive only (R) Right hand drive only (NS) National Standard *+
Please note that central restrictions are displayed. Markets may have specific deviation if any. Codes could be valid for certain countries only.

			CLS Coupé						Local price excl. VAT
Code	Equipment	Restrictions	257314 CLS 220 d	257319 CLS 300 d 4MATIC	257323 CLS 400 d 4MATIC	257350 CLS 350 (L)	257359 CLS 450 4MATIC	257361 Mercedes-AMG CLS 53 4MATIC+	
U15	Edition decals		-	-	-	-	-	○	0,00
		Available only as part of (P97)						*	
		Not in conjunction with 55U/65U/685/728/737/764/779/H13/P87/R05/R66/U03/U12/Z01/Z02/Z98						*	
		Only in conjunction with 868A						*	
		Only in conjunction with [049U/297U]+H73+RZU+5U6+732+7U8+P49+P60+P97+R01+U26						*	
U16	Sports exhaust system		-	-	-	○	○	-	0,00
U33	Special model badge, interior		-	-	-	-	-	○	0,00
		Available only as part of (P97)						*	
		Not in conjunction with 55U/65U/685/728/737/764/779/H13/P87/R05/R66/U12/Z01/Z02/Z98						*	
		Only in conjunction with 868A						*	
		Only in conjunction with [049U/297U]+H73+RZU+5U6+732+7U8+P49+P60+P97+R01+U26						*	
U79	BlueTEC diesel emission control system including AdBl		S	○	S	-	-	-	0,00
		Not in conjunction with 6U7	*	*					
		Not in conjunction with 927		*					
		Only in conjunction with U85	*	*					
U80	115 V socket		-	-	-	-	●	●	126,00
U90	Low-Line package China		-	-	-	-	-	-	0,00
U92	High-Line package China		-	-	-	-	-	-	0,00
Z01	Paint not feat.on standard sample card		○	○	○	○	○	○	0,00
		Not in conjunction with P97/U03/U15						*	
		Not in conjunction with Z02/Z98	*	*	*	*	*	*	
		Only in conjunction with 524	*	*	*	*	*	*	
Z02	Paint not feat.on standard sample card		○	○	○	○	○	○	0,00
		Not in conjunction with P97/U03/U15						*	
		Not in conjunction with Z01/Z98	*	*	*	*	*	*	
		Only in conjunction with 524	*	*	*	*	*	*	
Z98	Paint not feat.on standard sample card		○	○	○	○	○	○	0,00
		Not in conjunction with P97/U03/U15						*	
		Not in conjunction with Z01/Z02	*	*	*	*	*	*	
		Only in conjunction with 524	*	*	*	*	*	*	
682	Fire extinguisher		LS	LS	LS	LS	LS	LS	0,00
70B	Fluorescent jacket for driver		●	●	●	●	●	●	5,25
293	Sidebags in rear		●	●	●	●	●	●	399,00
294	Kneebag		S	S	S	S	S	S	0,00
U60	Pedestrian protection		○	○	○	○	○	○	0,00
258	Active Brake Assist		LS	LS	LS	LS	LS	LS	0,00
		Not in conjunction with 233/23U/266/546/K33/K34	*	*	*	*	*	*	
		Only in conjunction with 243	*	*	*	*	*	*	
292	PRE-SAFE® impulse side		○	○	○	○	○	○	0,00
		Available only as part of (P20)	*	*	*	*	*	*	
		Not in conjunction with 234/504	*	*	*	*	*	*	
		Only in conjunction with 365+513+546+K34+P20+P49	*	*	*	*	*	*	
22P	Lane Tracking package		●	●	●	●	●	●	819,00
233	Active Distance Assist DISTRONIC		○	○	○	○	○	○	0,00
		Not in conjunction with 234/243/258/504	*	*	*	*	*	*	
		Only in conjunction with 365+513+546+K34+P49	*	*	*	*	*	*	
		only in conjunction with 23P/P20	*	*	*	*	*	*	
234	Blind Spot Assist		●	●	●	●	●	●	472,50
		Not in conjunction with 233/23U/266/546/K33/K34/P20	*	*	*	*	*	*	
		Only in conjunction with 243+258	*	*	*	*	*	*	
		Only in conjunction with P49	*	*	*	*	*	*	
		i.V.m. Code 22P	○	○	○	○	○	○	0,00
		i.V.m. Code PYM/PYN/PYO	○	○	○	○	○	○	0,00
23P	Driving Assistance package		●	●	●	●	●	●	2.026,50

802+052
2021-12-14
2022-02-09

Αρ.Πρωτ 309

Legend (*) Available at extra cost (○) available without additional charge (S) standard equipment (-) not available (L) Left hand drive only (R) Right hand drive only (NS) National Standard *+
Please note that central restrictions are displayed. Markets may have specific deviation if any. Codes could be valid for certain countries only.

			CLS Coupé						Local price excl. VAT
Code	Equipment	Restrictions	257314 CLS 220 d	257319 CLS 300 d 4MATIC	257323 CLS 400 d 4MATIC	257350 CLS 350 (L)	257359 CLS 450 4MATIC	257361 Mercedes-AMG CLS 53 4MATIC+	
		Includes codes 233+266	*	*	*	*	*	*	
		Not in conjunction with 234/23U/504	*	*	*	*	*	*	
		Only in conjunction with 365+513+546+K34+P49	*	*	*	*	*	*	
243	Active Lane Keeping Assist		○	○	○	○	○	○	0,00
		Not in conjunction with 233/23U/266/546/K33/K34	*	*	*	*	*	*	
		Only in conjunction with 258	*	*	*	*	*	*	
266	Active Steering Assist		○	○	○	○	○	○	0,00
		Not in conjunction with 234/243/258	*	*	*	*	*	*	
		only in conjunction with 23P/P20	*	*	*	*	*	*	
475	Tyre pressure monitoring system		●	●	●	●	●	-	320,25
			-	-	-	-	-	○	0,00
		i.V.m. S-Code 6P5	○	○	○	○	○	-	0,00
504	Speed Limit Assist		○	○	○	○	○	○	0,00
		Not in conjunction with 233/23U/513/546/K33/K34/P20	*	*	*	*	*	*	
		Only in conjunction with 243+258	*	*	*	*	*	*	
546	Active Speed Limit Assist		○	○	○	○	○	○	0,00
		Not in conjunction with 234/243/258/504	*	*	*	*	*	*	
		Only in conjunction with 233+365+513+K34+P49	*	*	*	*	*	*	
P20	Driving Assistance package Plus		●	●	●	●	●	●	2.551,50
		Includes codes 233+266+292	*	*	*	*	*	*	
		Not in conjunction with 234/504	*	*	*	*	*	*	
		Only in conjunction with 365+513+546+K34+P49	*	*	*	*	*	*	
		i.V.m. Code PYB	●	●	●	●	●	●	2.079,00
218	Reversing camera		●	●	●	●	●	●	420,00
		Not in conjunction with 553/P47	*	*	*	*	*	*	
		i.V.m. Code P44	○	○	○	○	○	○	0,00
235	Active Parking Assist with PARKTRONIC		●	●	●	●	●	●	782,25
		in conjunction with 218 only with P44	*	*	*	*	*	*	
		in conjunction with P44/P47/830 automatically added	*	*	*	*	*	*	
		i.V.m. Code P44/P47	○	○	○	○	○	○	0,00
553	Trailer Manoeuvring Assist		●	●	●	●	●	●	367,50
		Not in conjunction with 218/P44	*	*	*	*	*	*	
		Only in conjunction with 550+P47+P49	*	*	*	*	*	*	
P44	Parking package with reversing camera		●	●	●	●	●	●	1.097,25
		Includes codes 218+235	*	*	*	*	*	*	
		Not in conjunction with 553/P47	*	*	*	*	*	*	
		i.V.m. Code PWS	○	○	○	○	○	○	0,00
		i.V.m. Code PYB	○	○	○	○	○	○	0,00
P47	Parking Package with 360-degree camera		●	●	●	●	●	●	1.580,25
		Includes codes 235+501	*	*	*	*	*	*	
		Not in conjunction with 218/P44	*	*	*	*	*	*	
		Only in conjunction with P49	*	*	*	*	*	*	
		i.V.m. Code PWS	●	●	●	●	●	●	483,00
		i.V.m. Code PYM	○	○	○	○	○	○	0,00
		i.V.m. Code PYN	○	○	○	○	○	○	0,00
		i.V.m. Code PYO	○	○	○	○	○	○	0,00
915	Fuel tank with a capacity of 80 litres		-	-	-	-	●	●	105,00
		Not in conjunction with 916					*	*	
		i.V.m. Code PYB	-	-	-	-	○	○	0,00
916	Fuel tank with a capacity of 66 litres		●	●	●	-	-	-	52,50
			-	-	-	○	S	S	0,00
		Not in conjunction with 915					*	*	
		i.V.m. Code PWS	○	○	○	-	-	-	0,00
		i.V.m. Code PYB	○	○	○	-	-	-	0,00

802+052
2021-12-14
2022-02-09

Αρ.Πρωτ 309

Legend
(*) Available at extra cost (○) available without additional charge (S) standard equipment (-) not available (L) Left hand drive only (R) Right hand drive only (NS) National Standard *+
Please note that central restrictions are displayed. Markets may have specific deviation if any. Codes could be valid for certain countries only.

			CLS Coupé						Local price excl. VAT
Code	Equipment	Restrictions	257314 CLS 220 d	257319 CLS 300 d 4MATIC	257323 CLS 400 d 4MATIC	257350 CLS 350 (L)	257359 CLS 450 4MATIC	257361 Mercedes-AMG CLS 53 4MATIC+	
B59	DYNAMIC SELECT		S	S	S	S	S	-	0,00
U29	Braking system with larger brake discs on the front axl		●	●	-	●	-	-	262,50
			-	-	○	-	○	-	0,00
		Not in conjunction with 11R/63R/818A/83R/P14/P15			*		*		
		Only in conjunction with P29+P31			*		*		
		i.V.m. Code PYH	○	○	-	○	-	-	0,00
U85	AdBlue® tank with 23.5-litre capacity		S	○	S	-	-	-	0,00
489	AIR BODY CONTROL		●	●	●	●	●	-	1.995,00
		Not in conjunction with 677	*	*	*	*	*		
489	AMG RIDE CONTROL+		-	-	-	-	-	S	0,00
677	Lowered comfort suspension		S	S	S	S	S	-	0,00
		Not in conjunction with 489	*	*	*	*	*		
421	9G-TRONIC		S	S	S	S	S	-	0,00