

Standard and special equipment

Model year : 804
 Sales Release : 2023-09-05
 Production Change : 2023-06-30
 Pricing Date : 2023-09-05

Legend

(*) Applicable (*) Available at extra cost (○) available without additional charge (S) standard equipment (I) Applicable from PPM (-) not available (L) Left hand drive
 Please note that central restrictions are displayed. Markets may have specific deviation if any. Codes could be valid for certain countries only.

			CLE-Klasse Coupe			
Code	Equipment	Restrictions	236304 CLE 220 d Coupé	236350 CLE 200 Coupé	236347 CLE 300 4MATIC Coupé	LLP
000U	special paintwork		○	○	○	0,00
		Only in conjunction with Z01/Z98	*	*	*	0
00B	Owner's Manual and service information - Danish		○	○	○	0,00
00U	Remote Services		●	●	●	105,00
		Not in conjunction with 33U/34U	*			0
		Not in conjunction with 33U/34U/37U		*	*	0
		Only in conjunction with 382/383	*			0
		I.V.m. Code PSE/PSF/PSI/PSJ	○	○	○	0,00
		I.V.m. Code PSN/PSQ	○	○	○	0,00
01B	Owner's Manual and service information - Dutch		○	○	○	0,00
01R	45.7 cm (18-inch) 5-twin-spoke light-alloy wheels		○	○	○	0,00
		Only in conjunction with P15	*	*	*	0
01U	Preinstallation for Navigation Services		○	○	○	0,00
		Only in conjunction with 382/383	*			0
		Only in conjunction with PBG/PBG		*	*	0
		Only in conjunction with PBG+(382/383)	*			0
01W	Mercedes-Benz Connect Package, 1 year		●	●	●	126,00
		Not in conjunction with 02W/03W	*	*	*	0
02B	Owner's Manual and service information - German		○	○	○	0,00
02W	Mercedes-Benz Connect Package, 2 years		●	●	●	252,00
		Not in conjunction with 01W/03W	*	*	*	0
03B	Owner's Manual and service information - Russian		○	○	○	0,00
03W	Mercedes-Benz Connect Package, 3 years		●	●	●	378,00
		Not in conjunction with 01W/02W	*	*	*	0
040U	black		○	○	○	0,00
04B	Owner's Manual and service information - Finnish		○	○	○	0,00
05B	Owner's Manual and service information - English		○	○	○	0,00
06B	Owner's Manual and service information - Italian		○	○	○	0,00
07B	Owner's Manual and service information - French		○	○	○	0,00
08B	Owner's Manual and service information - Spanish		○	○	○	0,00
09B	Owner's Manual and service information - Portuguese		○	○	○	0,00
101A	ARTICO man-made leather black		○	○	○	0,00
		Only in conjunction with P14/P29	*	*	*	0
104A	ARTICO man-made leather tonka brown / black		●	●	●	157,50
		Not in conjunction with 970U	*	*	*	0
		Only in conjunction with P14/P29	*	*	*	0
105A	ARTICO man-made leather macchiato beige / black		●	●	●	157,50
		Only in conjunction with P14/P29	*	*	*	0
10B	Owner's Manual and service information - Swedish		○	○	○	0,00
11B	Owner's Manual and service information - Arabic		○	○	○	0,00
12B	Owner's Manual and service information - English USA/C		-	-	○	0,00
13B	Owner's Manual and service information - Norwegian		○	○	○	0,00
149U	polar white		●	●	●	288,75
14B	Owner's Manual and service information - Greek		○	○	○	0,00
14U	Smartphone Integration		●	●	●	315,00
		I.V.m. Code PDA/PDB/PDC/PDD	○	○	○	0,00
15B	Owner's Manual and service information - Turkish		○	○	○	0,00
16B	Owner's Manual and service information - Polish		○	○	○	0,00

Standard and special equipment

Model year :

804

Sales Release :

2023-09-05

Production Change :

2023-06-30

Pricing Date :

2023-09-05

Legend

(*) Applicable (*) Available at extra cost (○) available without additional charge (S) standard equipment (I) Applicable from PPM (-) not available (L) Left hand drive
Please note that central restrictions are displayed. Markets may have specific deviation if any. Codes could be valid for certain countries only.

Code	Equipment	Restrictions	CLE-Klasse Coupe			LLP
			236304 CLE 220 d Coupé	236350 CLE 200 Coupé	236347 CLE 300 4MATIC Coupé	
16U	Apple CarPlay		○	○	○	0,00
17B	Owner's Manual and service information - Czech		○	○	○	0,00
17U	Android Auto		○	○	○	0,00
18B	Owner's Manual and service information - English South		-	○	○	0,00
197U	obsidian black		●	●	●	850,50
19B	Owner's Manual and service information - French South		-	○	○	0,00
201	Rear-axle steering		●	●	●	1.102,50
		Only in conjunction with PAD	*	*	*	0
		i.V.m. Code PAD	○	○	○	0,00
201A	Leather black		●	●	●	1.564,50
		Only in conjunction with P14/P29	*	*	*	0
204A	Leather tonka brown / black		●	●	●	1.722,00
		Not in conjunction with 970U	*	*	*	0
		Only in conjunction with P14/P29	*	*	*	0
205A	Leather macchiato beige / black		●	●	●	1.722,00
		Only in conjunction with P14/P29	*	*	*	0
207	Active Distance Assist DISTRONIC		●	●	●	420,00
		Not in conjunction with 239		*	*	0
		Only in conjunction with 258+5B0	*	*	*	0
207A	Leather power red / black		●	●	●	1.722,00
		Not in conjunction with H33/970U	*	*	*	0
		Only in conjunction with P14/P29	*	*	*	0
20B	Owner's Manual and service information - Spanish South		-	○	○	0,00
20U	Preinstallation for digital key transfer		●	●	●	52,50
		Only in conjunction with 382/383	*			0
		Only in conjunction with PDA/PDB/PDC/PDD	*	*	*	0
		i.V.m. Code PDA/PDB/PDC/PDD	○	○	○	0,00
218	Reversing camera		S	S	S	0,00
		Not in conjunction with 501	*	*	*	0
21B	Owner's Manual and service information - Portuguese South		-	○	○	0,00
21U	Dash cam		●	●	●	210,00
228	Auxiliary heater		●	●	●	1.281,00
		Only in conjunction with L	*	*	*	0
22B	Owner's Manual and service information - Japanese		-	○	-	0,00
232	Garage door opener (frequency range 284-390 MHz)		-	●	●	236,25
		Not in conjunction with 968/969		*	*	0
233	Active Distance Assist DISTRONIC		○	○	○	0,00
		Not in conjunction with 234/239/258		*	*	0
		Not in conjunction with 234/258	*			0
		Only in conjunction with 243+262+266+272+513+K33+K34+P20	*	*	*	0
234	Blind Spot Assist		●	●	●	472,50
		Not in conjunction with 233	*	*	*	0
		i.V.m. Code PDB/PDC/PDD	○	○	○	0,00
235	Active Parking Assist with PARKTRONIC		○	○	○	0,00
239	DISTRONIC PLUS		-	○	○	0,00
		Not in conjunction with 207/233/258		*	*	0
		Not in conjunction with 440			*	0
23B	Owner's Manual and service information - simplified Chinese		-	○	-	0,00

Standard and special equipment

Model year : 804
 Sales Release : 2023-09-05
 Production Change : 2023-06-30
 Pricing Date : 2023-09-05

Legend

(*) Applicable (*) Available at extra cost (○) available without additional charge (S) standard equipment (I) Applicable from PPM (-) not available (L) Left hand drive
 Please note that central restrictions are displayed. Markets may have specific deviation if any. Codes could be valid for certain countries only.

			CLE-Klasse Coupe			
Code	Equipment	Restrictions	236304 CLE 220 d Coupé	236350 CLE 200 Coupé	236347 CLE 300 4MATIC Coupé	LLP
241	Power front left seat with memory function		○	○	○	0,00
242	Power front right seat with memory function		○	○	○	0,00
243	Active Lane Keeping Assist		○	○	○	0,00
		Only in conjunction with 233	*	*	*	0
249	Interior mirror and driver's exterior mirror automatically		○	○	○	0,00
248	Owner's Manual and service information - traditional Chinese		○	○	○	0,00
258	Active Brake Assist		○	○	○	0,00
		Not in conjunction with 233	*			0
		Not in conjunction with 233/239		*	*	0
		Only in conjunction with 5B0	*	*	*	0
25B	Owner's Manual and service information - Korean		-	○	-	0,00
260	Omission of model plate on boot lid		○	○	○	0,00
262	Rear sensors for the lane departure assistant		○	○	○	0,00
		Only in conjunction with 233/507	*	*	*	0
263	Number plate mounting		-	○	-	0,00
		Not in conjunction with 264/823/826/827		*		0
264	Number plate mounting		-	○	○	0,00
		Not in conjunction with 263/823/826/827		*		0
		Not in conjunction with 823/826			*	0
266	Active Steering Assist		○	○	○	0,00
		Only in conjunction with 233	*	*	*	0
26B	Owner's Manual and service information - Chinese Taiwan		-	○	○	0,00
272	Evasive manoeuvre support		○	○	○	0,00
		Only in conjunction with 233/507	*	*	*	0
275	Memory Package		S	S	S	0,00
27B	Owner's Manual and service information - Spanish Mexico		-	-	○	0,00
287	Folding rear seat backrests		S	S	S	0,00
292	PRE-SAFE® Impulse Side		○	○	○	0,00
		Only in conjunction with 233+P20	*	*	*	0
293	Sidebags in rear		●	●	●	393,75
299	PRE-SAFE® system		S	S	S	0,00
2R4	Complete set of 4 M+S winter wheels		●	●	●	2.100,00
		Not in conjunction with 4R2	*	*	*	0
		Not in conjunction with 645	*	*	*	0
		Only in conjunction with 651/652	*	*	*	0
301	Ashtray insert for cup holder		●	●	●	31,50
30B	Owner's Manual and service information - Slovenian		○	○	○	0,00
30P	Stowage Space Package		S	S	S	0,00
		Includes codes 310	*	*	*	0
30U	Preinstallation for projection function for lines		○	○	○	0,00
		Only in conjunction with P35/PAX	*	*	*	0
310	Double cup holder		○	○	○	0,00
316	DIGITAL LIGHT		-	-	○	0,00
		Only in conjunction with P35/PAX			*	0
317	DIGITAL LIGHT		○	○	○	0,00
		Only in conjunction with P35/PAX	*	*	*	0
318	DIGITAL LIGHT		○	○	○	0,00
		Only in conjunction with P35/PAX	*	*	*	0

Standard and special equipment

Model year : 804
 Sales Release : 2023-09-05
 Production Change : 2023-06-30
 Pricing Date : 2023-09-05

Legend

(*) Applicable (*) Available at extra cost (○) available without additional charge (S) standard equipment (I) Applicable from PPM (-) not available (L) Left hand drive
 Please note that central restrictions are displayed. Markets may have specific deviation if any. Codes could be valid for certain countries only.

			CLE-Klasse Coupe		
Code	Equipment	Restrictions	236304 CLE 220 d Coupé	236350 CLE 200 Coupé	236347 CLE 300 4MATIC Coupé
					LLP
31B	Owner's Manual and service information - Hungarian		○	○	○
321	Fingerprint scanner		●	●	●
		Only in conjunction with (PDA/PDB/PDC/PDD)+(00U/33U/34U)	*		
		Only in conjunction with (PDA/PDB/PDC/PDD)+(00U/33U/34U/37U)		*	*
		I.V.m. Code PDA/PDB/PDC/PDD	○	○	○
325	Centre airbag		S	S	S
32B	Owner's Manual and service information - Bulgarian		○	○	○
32U	Sound personalisation		○	○	○
		Only in conjunction with 810	*	*	*
33B	Owner's Manual and service information - Romanian		○	○	○
33U	Remote Services Plus		●	●	●
		Not in conjunction with 00U/34U	*		
		Not in conjunction with 00U/34U/37U		*	*
		Only in conjunction with 382/383	*		
345	Windscreen wipers with rain sensor		S	S	S
34B	Owner's Manual and service information - Croatian		○	○	○
34U	Remote Services Premium		●	●	●
		Not in conjunction with 00U/33U	*	*	*
		Only in conjunction with 382/383	*		
		I.V.m. Code PSE/PSF/PSI/PSJ	●	●	●
		I.V.m. Code PSN/PSQ	●	●	●
351	Mercedes-Benz emergency call system		○	○	○
355	Extended MBUX functions		S	S	S
35B	Owner's Manual and service information - Latvian		○	○	○
365	Hard-disc navigation		○	○	○
		Only in conjunction with PBF/PBG		*	*
		Only in conjunction with PBG	*		
367	Preinstallation for Live Traffic Information		○	○	○
		Only in conjunction with PBF/PBG		*	*
		Only in conjunction with PBG+(382/383)	*		
36B	Owner's Manual and service information - Lithuanian		○	○	○
37B	Owner's Manual and service information - Slovak		○	○	○
37U	Remote Services Advanced		-	●	●
		Not in conjunction with 00U/33U		*	*
382	Communications module (5G) for the use of Mercedes m		●	●	●
		I.V.m Code PSE/PSF/PSI	○	○	○
		I.V.m. Code PSJ/PSN/PSQ	○	○	○
383	Communications module (LTE) for the use of Mercedes n		○	○	○
38B	Owner's Manual and service information - Estonian		○	○	○
399	multicontour front seats		●	●	●
		Not in conjunction with U22	*	*	*
		Only in conjunction with PBR	*	*	*
		I.V.m. Code PBR	○	○	○
39B	Owner's Manual and service information - Serbian		○	○	○
401	Climatised front seats		●	●	●
		Not in conjunction with 601A	*	*	*
		Not in conjunction with 873	*	*	*
		I.V.m. Code PBR	○	○	○

Standard and special equipment

Model year : 804
 Sales Release : 2023-09-05
 Production Change : 2023-06-30
 Pricing Date : 2023-09-05

Legend

(*) Applicable (*) Available at extra cost (○) available without additional charge (S) standard equipment (I) Applicable from PPM (-) not available (L) Left hand drive
 Please note that central restrictions are displayed. Markets may have specific deviation if any. Codes could be valid for certain countries only.

Code	Equipment	Restrictions	CLE-Klasse Coupe			LLP
			236304 CLE 220 d Coupé	236350 CLE 200 Coupé	236347 CLE 300 4MATIC Coupé	
40B	Owner's Manual and service information - Ukrainian		○	○	○	0,00
413	Panoramic sliding sunroof		●	●	●	1.491,00
		I.V.m. Code PDD	○	○	○	0,00
41B	Owner's Manual and service information - Hebrew		○	○	○	0,00
421	9G-TRONIC		§	§	§	0,00
42B	Owner's Manual and service information - Indonesian		○	○	○	0,00
42U	Preinstallation for projection function for symbols		○	○	○	0,00
		Only in conjunction with P35/PAX	*	*	*	0
43B	Owner's Manual and service information - Thai		○	○	○	0,00
43U	Preinstallation for projection function for animations		○	○	○	0,00
		Only in conjunction with P35/PAX	*	*	*	0
440	CRUISE CONTROL		-	-	○	0,00
		Not in conjunction with 233/239/5B0			*	0
443	Steering wheel heating		○	○	○	0,00
		Only in conjunction with PAV+(L3E/L5C)+(401/873)	*	*	*	0
444	Head-up display		●	●	●	1.039,50
		I.V.m. Code PDD	○	○	○	0,00
44B	Owner's Manual and service information - Vietnamese		○	○	○	0,00
459	DYNAMIC BODY CONTROL suspension with adjustable damping		●	●	●	945,00
		Only in conjunction with PAD	*	*	*	0
		I.V.m. Code PAD	○	○	○	0,00
460	Canada specification		-	-	○	0,00
		Only in conjunction with 264+413+513+517+536+543+551+634+636+783+852+887+986+989+PAV+P17			*	0
461	Instrument display in miles with English lettering		○	○	○	0,00
464	Driver display		●	●	●	525,00
		I.V.m. Code PDA/PDB/PDC/PDD	○	○	○	0,00
475	Tyre pressure monitor		●	●	●	320,25
		I.V.m. S-Code 6P5	○	○	○	0,00
477	Tyre pressure loss warning		-	○	○	0,00
481	Underguard		●	●	●	115,50
486	Sports suspension		●	●	●	357,00
		Only in conjunction with P31	*	*	*	0
		I.V.m. Code P31	○	○	○	0,00
494	USA specification		-	-	○	0,00
		Only in conjunction with 232+264+293+413+461+517+536+543+551+634+636+783+810+852+875+887+986+989+P17			*	0
496	Mexico version		-	-	○	0,00
497	Indonesia specification		-	○	○	0,00
		Only in conjunction with 682+B08		*	*	0
498	Japan specification		-	○	-	0,00
		Only in conjunction with (P15/P31)+(P14/P29)+(P35/PAX/631)+(853/810)		*		0
49U	Pre-installation for MBUX Entertainment Plus		●	●	●	126,00
		Only in conjunction with 382/383	*			0
		Only in conjunction with PDD		*	*	0
		Only in conjunction with PDD+(382/383)	*			0
		I.V.m Code PSQ	○	○	○	0,00
4R2	Complete set of 4 M+S winter wheels		●	●	●	2.835,00
		Not in conjunction with 2R4	*	*	*	0

Standard and special equipment
Model year :

804

Sales Release :

2023-09-05

Production Change :

2023-06-30

Pricing Date :

2023-09-05

Legend

(*) Applicable (*) Available at extra cost (○) available without additional charge (S) standard equipment (I) Applicable from PPM (-) not available (L) Left hand drive
Please note that central restrictions are displayed. Markets may have specific deviation if any. Codes could be valid for certain countries only.

Code	Equipment	Restrictions	CLE-Klasse Coupe			LLP
			236304 CLE 220 d Coupé	236350 CLE 200 Coupé	236347 CLE 300 4MATIC Coupé	
		Not in conjunction with 645	*	*	*	0
		Only in conjunction with 651/652	*	*	*	0
500	Electrically folding exterior mirrors		○	○	○	0,00
501	360° camera		○	○	○	0,00
		Not in conjunction with 218	*	*	*	0
		Only in conjunction with P47/PBH	*	*	*	0
504	Speed Limit Assist		○	○	○	0,00
		Not in conjunction with 233	*	*	*	0
		Not in conjunction with 513	*	*	*	0
507	Memory Parking Assist		○	○	○	0,00
		Only in conjunction with PBH+233+262+272	*	*	*	0
513	Traffic Sign Assist		●	●	●	309,75
		Not in conjunction with 504	*	*	*	0
		Only in conjunction with 365	*	*	*	0
		I.V.m. Code PSI/PSJ/PSN/PSQ	○	○	○	0,00
517	HD digital radio standard		-	○	○	0,00
51U	Roof liner in black fabric		○	○	○	0,00
		I.V.m. Code 101A/201A/801A	●	●	●	367,50
		I.V.m. Code 104A/105A/204A	○	○	○	0,00
		I.V.m. Code 205A/804A	○	○	○	0,00
		I.V.m. Code P29	○	○	○	0,00
524	Transport protection (full body cover)		●	●	●	168,00
		Only in conjunction with 000U/818U/Z01/Z98	*	*	*	0
		I.V.m. Code 818U	○	○	○	0,00
528	MBUX multimedia system		S	S	S	0,00
		I.V.m. Code PDA/PDB/PDC/PDD	S	S	S	0,00
536	Sirius satellite radio		-	-	●	472,50
		Not in conjunction with 968/969			*	0
537	Digital radio		○	○	○	0,00
		Only in conjunction with 798	*	*	*	0
543	Pull-out sun visor		●	●	●	52,50
546	Active Speed Limit Assist		○	○	○	0,00
		Only in conjunction with 513+P20	*	*	*	0
550	Trailer coupling with ESP® trailer stabilisation		●	●	●	1.023,75
551	Anti-theft alarm system		○	○	○	0,00
		Only in conjunction with P54/P82	*	*	*	0
552	Anti-theft alarm system with preinstallation for collision		○	○	○	0,00
		Only in conjunction with P54/P82	*	*	*	0
580	THERMATIC automatic climate control		●	●	●	262,50
		I.V.m. Code PDA/PDB/PDC/PDD	○	○	○	0,00
587	Ambient lighting with projection of brand logo		○	○	○	0,00
58U	Roof liner in neva grey fabric		○	○	○	0,00
		Only in conjunction with P14+{101A/201A/801A}/P29+{101A/201A/601A/801A}	*	*	*	0
580	Pre-installation for DISTRONIC		○	○	○	0,00
		Not in conjunction with 440			*	0
		Only in conjunction with 258	*	*	*	0
601A	ARTICO man-made leather / MICROCUT microfibre black		○	○	○	0,00
		Only in conjunction with P29	*	*	*	0

Standard and special equipment
Model year :

804

Sales Release :

2023-09-05

Production Change :

2023-06-30

Pricing Date :

2023-09-05

Legend

(*) Applicable (*) Available at extra cost (○) available without additional charge (S) standard equipment (I) Applicable from PPM (-) not available (L) Left hand drive
Please note that central restrictions are displayed. Markets may have specific deviation if any. Codes could be valid for certain countries only.

Code	Equipment	Restrictions	CLE-Klasse Coupe			LLP
			236304 CLE 220 d Coupé	236350 CLE 200 Coupé	236347 CLE 300 4MATIC Coupé	
608	Adaptive Highbeam Assist		●	●	●	189,00
		Not in conjunction with 317/318			*	0
		Not in conjunction with 628	*	*	*	0
		Only in conjunction with (PDA/PDB/PDC/PDD)+(631/632)	*	*		0
		Only in conjunction with PDA/PDB/PDC/PDD			*	0
		I.V.m. Code PDA/PDB/PDC/PDD	○	○	○	0,00
623	Gulf States specification		—	○	○	0,00
		Only in conjunction with 682+687+986+989+(672+R66/R66)+B12		*	*	0
625	Australia specification		—	○	○	0,00
		Only in conjunction with 537		*	*	0
628	Adaptive Highbeam Assist Plus		○	○	○	0,00
		Not in conjunction with 608	*	*	*	0
		Only in conjunction with (P35/PAX)+(317/318)	*	*	*	0
631	Headlamps, LED, static, left-side traffic		○	○	○	0,00
632	LED High Performance headlamps		○	○	○	0,00
634	Omission of first-aid kit		○	○	○	0,00
636	Omission of warning triangle		○	○	○	0,00
645	M+S winter tyres, set of 4		●	●	●	168,00
		Not in conjunction with 651/652	*	*	*	0
		Only in conjunction with RVA/RVB	*	*	*	0
651	Winter complete wheels fitted		○	○	○	0,00
		Not in conjunction with 645/652	*	*	*	0
		Only in conjunction with 2R4/4R2	*	*	*	0
652	Summer complete tyres fitted		○	○	○	0,00
		Not in conjunction with 645/651	*	*	*	0
		Only in conjunction with 2R4/4R2	*	*	*	0
666	Freight packaging without tie-down hooks		●	●	●	26,25
		Not in conjunction with 668	*	*	*	0
		Only in conjunction with 550	*	*	*	0
		I.V.m. S-Code 14P/15P/16P	○	○	○	0,00
668	Freight packaging with tie-down hooks		●	●	●	26,25
		Not in conjunction with 550	*	*	*	0
		Not in conjunction with 666	*	*	*	0
670	Residual engine heat utilisation		○	○	○	0,00
672	Emergency spare wheel		—	○	○	0,00
		Only in conjunction with B12		*	*	0
677	Comfort suspension with ride-height lowering		○	○	○	0,00
		Only in conjunction with P15	*	*	*	0
682	Fire extinguisher		●	●	●	115,50
687	Type plate with model year		○	○	○	0,00
		Not in conjunction with 968/969	*	*	*	0
6U7	BlueTEC diesel emission control system including genera		○	—	—	0,00
708	Fluorescent jacket for driver		●	●	●	5,25
		Not in conjunction with 71B	*	*	*	0
		I.V.m. Code PSE/PSF/PSI	○	○	○	0,00
		I.V.m. Code PSJ/PSN/PSQ	○	○	○	0,00
712	CKD delivery scope India		—	—	○	0,00
71B	Safety vests for driver and passengers		●	●	●	26,25

Standard and special equipment

Model year :

804

Sales Release :

2023-09-05

Production Change :

2023-06-30

Pricing Date :

2023-09-05

Legend

(*) Applicable (*) Available at extra cost (○) available without additional charge (S) standard equipment (I) Applicable from PPM (-) not available (L) Left hand drive
Please note that central restrictions are displayed. Markets may have specific deviation if any. Codes could be valid for certain countries only.

Code	Equipment	Restrictions	CLE-Klasse Coupe			LLP
			236304 CLE 220 d Coupé	236350 CLE 200 Coupé	236347 CLE 300 4MATIC Coupé	
		Not in conjunction with 70B	*	*	*	0
71H	Light silver metallic mixed fabric trim element		●	●	●	409,50
		Only in conjunction with 757	*	*	*	0
72B	USB Package Plus		●	●	●	315,00
		Not in conjunction with 75B	*	*	*	0
757	Centre console in high-gloss black		S	S	S	0,00
75B	USB Package		●	●	●	84,00
		Not in conjunction with 72B	*	*	*	0
		Only in conjunction with PDA/PDB/PDC/PDD	*	*	*	0
		I.V.m. Code PDA/PDB/PDC/PDD	○	○	○	0,00
762	Radio remote control		-	○	-	0,00
		Not in conjunction with 968/969		*		0
772	AMG bodystyling		○	○	○	0,00
		Only in conjunction with P31	*	*	*	0
77B	MBUX Interior Assistant		●	●	●	409,50
		Only in conjunction with PDD	*	*	*	0
		I.V.m Code PSQ	○	○	○	0,00
783	Radio remote control with panic switch		-	-	○	0,00
		Not in conjunction with 968/969			*	0
		Only in conjunction with 551			*	0
794	Centre console, criss-cross look, silver grey		●	●	●	157,50
		Only in conjunction with H50	*	*	*	0
795	Centre console in a mixed fabric-look finish with metal e		●	●	●	157,50
		Only in conjunction with H04/H08/H64	*	*	*	0
79B	Preinstallation for digital radio		○	○	○	0,00
		Only in conjunction with 382/383/537	*			0
		Only in conjunction with 537		*	*	0
801A	Nappa leather black		●	●	●	2.614,50
		Only in conjunction with (P14/P29)+(U22/399)+U34	*	*	*	0
804	Technical modifications		○	○	○	0,00
804A	Nappa leather tonka brown / black		●	●	●	2.772,00
		Not in conjunction with 970U	*	*	*	0
		Only in conjunction with (P14/P29)+(U22/399)+U34	*	*	*	0
809A	Nappa leather white / black		●	●	●	2.772,00
		Only in conjunction with (P14/P29)+(U22/399)+U34	*	*	*	0
810	Burmester® 3D surround sound system		●	●	●	1.165,50
		Not in conjunction with 853	*	*	*	0
		Only in conjunction with 32U	*	*	*	0
		I.V.m. Code PDD	○	○	○	0,00
818U	MANUFAKTUR graphite grey magno		●	●	●	4.515,00
820	Tourist vehicle		○	○	○	0,00
822	South Africa specification		-	○	○	0,00
823	Indicator plate fixing Switzerland		○	○	○	0,00
		Not in conjunction with 263/264/826/827		*		0
		Not in conjunction with 264/826			*	0
824	Additional parts for cold countries (engine air intake scre		○	○	○	0,00
826	Number plate mounting		-	○	○	0,00
		Not in conjunction with 263/264/823/827		*		0

Standard and special equipment

Model year :

804

Sales Release :

2023-09-05

Production Change :

2023-06-30

Pricing Date :

2023-09-05

Legend

(*) Applicable (*) Available at extra cost (○) available without additional charge (S) standard equipment (I) Applicable from PPM (-) not available (L) Left hand drive
Please note that central restrictions are displayed. Markets may have specific deviation if any. Codes could be valid for certain countries only.

Code	Equipment	Restrictions	CLE-Klasse Coupe			LLP
			236304 CLE 220 d Coupé	236350 CLE 200 Coupé	236347 CLE 300 4MATIC Coupé	
		Not in conjunction with 264/823			*	0
827	Number plate mounting		-	○	-	0,00
		Not in conjunction with 263/264/823/826		*		0
829	Taiwan version		-	○	○	0,00
		Only in conjunction with B08+826		*	*	0
82R	45.7 cm (18-inch) 5-spoke light-alloy wheels		●	●	●	210,00
		Only in conjunction with P15	*	*	*	0
830	China specification		-	○	-	0,00
		Only in conjunction with P29+P31+413+634+827+986+989+70B+B08+P53+R01+U10		*		0
831U	graphite grey		●	●	●	850,50
834	New Zealand specification		-	○	○	0,00
		Only in conjunction with 537		*	*	0
835	South Korea specification		-	○	-	0,00
		Only in conjunction with 513+79B+943+986+B08+P20+P35+P53+PAV+U10+(P15/P31)+(P14/P29)+634		*		0
840	Heat-insulating dark-tinted glass		●	●	●	388,50
		Not in conjunction with U50	*	*	*	0
		I.V.m. PSF/PSJ/PSN/PSQ	○	○	○	0,00
		I.V.m. Code P55	○	○	○	0,00
852	Sensor system for anti-theft alarm system		-	-	○	0,00
		Not in conjunction with 882			*	0
		Only in conjunction with 551			*	0
853	Advanced Sound System		●	●	●	483,00
		Not in conjunction with 810	*	*	*	0
865	TV receiver		-	●	-	1.039,50
868	Central display		●	●	●	315,00
		I.V.m. Code PDA/PDB/PDC/PDD	○	○	○	0,00
871	HANDS-FREE ACCESS		○	○	○	0,00
		Only in conjunction with P17	*	*	*	0
873	Heated front seats		●	●	●	367,50
		Not in conjunction with 401	*	*	*	0
		Only in conjunction with PDA/PDB/PDC/PDD	*	*	*	0
		I.V.m. Code PDA/PDB/PDC/PDD	○	○	○	0,00
875	Heated windscreen washer system		●	●	●	178,50
		Only in conjunction with L	*	*	*	0
		Only in conjunction with PAV	*	*	*	0
		I.V.m. Code PAV	○	○	○	0,00
876	Interior Light Package		S	S	S	0,00
881	Boot lid convenience closing feature		●	●	●	262,50
		Only in conjunction with P17	*	*	*	0
		I.V.m. Code P17	○	○	○	0,00
882	Interior monitoring system		○	○	○	0,00
		Not in conjunction with 852			*	0
		Only in conjunction with P54/P82	*	*	*	0
885	Increased anti-theft protection		○	○	○	0,00
		Only in conjunction with R	*	*	*	0
885U	MANUFAKTUR opalite white bright		●	●	●	1.564,50
887	Independent boot locking		●	●	●	26,25
889	KEYLESS-GO		S	S	S	0,00

Standard and special equipment

Model year : 804
 Sales Release : 2023-09-05
 Production Change : 2023-06-30
 Pricing Date : 2023-09-05

Legend

(*) Applicable (*) Available at extra cost (○) available without additional charge (S) standard equipment (I) Applicable from PPM (-) not available (L) Left hand drive
 Please note that central restrictions are displayed. Markets may have specific deviation if any. Codes could be valid for certain countries only.

			CLE-Klasse Coupe		
			236304 CLE 220 d Coupé	236350 CLE 200 Coupé	236347 CLE 300 4MATIC Coupé
Code	Equipment	Restrictions	LLP		
88B	Passive person presence reminder		S	S	S
891	Ambient lighting		●	●	●
		I.V.m. Code PDA/PDB/PDC/PDD	○	○	○
893	KEYLESS GO starting function		S	S	S
894	Ambient lighting Plus		●	●	●
		Only in conjunction with -PDA/PBR	*	*	*
		I.V.m. Code PDB/PDC/PDD	○	○	○
		I.V.m. Code PBR	○	○	○
897	Wireless charging system for mobile devices in the front		●	●	●
		I.V.m. Code PDA/PDB/PDC/PDD	○	○	○
913	Air conditioning preinstallation for hot countries		○	○	○
916	Fuel tank with a capacity of 66 litres		S	S	S
91P	Employee discount model		○	○	○
922U	high-tech silver		●	●	●
926	Emission control system with EU4 technology		—	○	○
927	EU6 emissions standard		○	○	○
943	Toll payment system		—	●	●
945	Emission control system China		—	○	—
94B	Integrated Starter Generator Generation 2		S	S	S
956U	MANUFAKTUR alpine grey solid		●	●	●
968	COC document EU6 without registration certificate part I		○	○	○
		Not in conjunction with 232		*	*
		Not in conjunction with 263/264		*	
		Not in conjunction with 264			*
		Not in conjunction with 687	*	*	*
		Not in conjunction with 762		*	
		Not in conjunction with 969/981	*	*	*
		Only in conjunction with 927+351+986		*	*
		Only in conjunction with 986	*		
969	COC document EU6 with registration certificate part II		○	○	○
		Not in conjunction with 232		*	*
		Not in conjunction with 687	*	*	*
		Not in conjunction with 762		*	
		Not in conjunction with 968/981	*	*	*
		Only in conjunction with 927+351+986		*	*
		Only in conjunction with 986	*		
970U	spectral blue		●	●	●
		Not in conjunction with 104A/204A/207A/804A	*	*	*
972	Exhaust system with DPF Generation 2.0		○	—	—
973	Designation as owner-driver rental vehicle		○	○	○
981	Omission of vehicle registration document		○	○	○
		Not in conjunction with 968/969	*	*	*
		Only in conjunction with 986	*	*	*
986	Identification no. (US-VIN)		○	○	○
		Only in conjunction with 981/968/969	*	*	*
989	Identification label under windshield		○	○	○
993U	MANUFAKTUR patagonia red metallic		●	●	●
997	Display vehicle for exhibitions (motor show veh.)		○	○	○

Standard and special equipment
Model year :

804

Sales Release :

2023-09-05

Production Change :

2023-06-30

Pricing Date :

2023-09-05

Legend

(*) Applicable (*) Available at extra cost (○) available without additional charge (S) standard equipment (I) Applicable from PPM (-) not available (L) Left hand drive
Please note that central restrictions are displayed. Markets may have specific deviation if any. Codes could be valid for certain countries only.

			CLE-Klasse Coupe		
			236304 CLE 220 d Coupé	236350 CLE 200 Coupé	236347 CLE 300 4MATIC Coupé
Code	Equipment	Restrictions			LLP
B01	Mild Hybrid Antrieb		○	○	○
B08	Fanfares for Asia		○	○	○
B12	Tyre-change toolkit		○	○	○
B51	TIREFIT		●	●	●
		Not in conjunction with R66		*	*
		Only in conjunction with PDA/PDB/PDC/PDD		*	*
		I.V.m. Code PDA/PDB/PDC/PDD	○	○	○
B59	DYNAMIC SELECT		S	S	S
B63	Sporty engine sound		○	○	○
		Only in conjunction with P31	*	*	*
H04	Black open-pore aluminium lines wood trim		●	●	●
		Not in conjunction with 794	*	*	*
H08	Anthracite llinestructure lime wood trim		●	●	●
		Not in conjunction with 794	*	*	*
H33	Brown open-pore walnut wood trim		●	●	●
		Not in conjunction with 207A	*	*	*
		Only in conjunction with 757	*	*	*
H50	Silver grey diamond-pattern trim		S	S	S
		Not in conjunction with 795/P29	*	*	*
H64	Metal structure trim element		●	●	●
		Not in conjunction with 794	*	*	*
		I.V.m. Code P29	○	○	○
H73	AMG carbon-fibre trim		●	●	●
		Only in conjunction with 757	*	*	*
K32	Active Lane Change Assist		○	○	○
		Only in conjunction with 233+266+365	*	*	*
K33	Extended automatic Re-start in traffic jams		○	○	○
		Only in conjunction with 365+233	*	*	*
K34	Route-based speed adaptation		○	○	○
		Only in conjunction with 365+233	*	*	*
L	Left-hand drive		○	○	○
		Only in conjunction with -(401/873/913)/(401/873)+-(233/443/810/913/72B)/(401/873)+(233/443/810/72B)+-913/913)+(927/945)		*	
		Only in conjunction with -(401/873/913)/(401/873)+-(233/443/810/913/72B)/(401/873)+(233/443/810/72B)+-913/913)+927			*
L3E	Leather multifunction sports steering wheel		S	S	S
		Only in conjunction with P14	*	*	*
L5C	Multifunction sports steering wheel in nappa leather		○	○	○
		Only in conjunction with P29	*	*	*
P14	AVANTGARDE interior		○	○	○
		Includes codes (101A/104A/105A/201A/204A/205A/207A/801A/804A/809A)+58U+(H50/71H/H04/H08/H33/H64/H73)+L3 F+U12	*	*	*
		Not in conjunction with 601A	*	*	*
		Only in conjunction with (218/501)+P15+U12	*	*	*
P15	AVANTGARDE exterior		○	○	○
		Includes codes (01R/82R/R17/R55)+(677/459)	*	*	*
		Only in conjunction with P14	*	*	*
P17	KEYLESS-GO Comfort Package		●	●	●
		Includes codes 871+881	*	*	*
		Only in conjunction with 871+881	*	*	*

Standard and special equipment
Model year :

804

Sales Release :

2023-09-05

Production Change :

2023-06-30

Pricing Date :

2023-09-05

Legend

(*) Applicable (*) Available at extra cost (○) available without additional charge (S) standard equipment (I) Applicable from PPM (-) not available (L) Left hand drive

Please note that central restrictions are displayed. Markets may have specific deviation if any. Codes could be valid for certain countries only.

			CLE-Klasse Coupe		
Code	Equipment	Restrictions	236304 CLE 220 d Coupé	236350 CLE 200 Coupé	236347 CLE 300 4MATIC Coupé
		I.V.m. Code PDC/PDD	○	○	○
P20	Driving Assistance Package Plus		●	●	●
		Includes codes 233+292+U10	*	*	*
		Only in conjunction with 233+292	*		
		Only in conjunction with 233+292+U10		*	*
		I.V.m. Code PDB/PDC/PDD	●	●	●
P21	AIR BALANCE package		●	●	●
		Only in conjunction with PBR	*		*
		Only in conjunction with PBR/PBU		*	
		I.V.m. Code PBR/PBU	○	○	○
P29	AMG Line interior		○	○	○
		Includes codes (51U/58U)+(601A/101A/104A/105A/201A/204A/205A/207A/801A/804A/809A)+(H64/71H/H04/H08/H33/H50/H73)+L5C+U26+U34	*	*	*
		Only in conjunction with (218/501)+P31+(101A/104A/105A/201A/204A/205A/207A/601A/801A/804A/809A)+U26+U34	*	*	*
P31	AMG Line exterior		●	●	●
		Includes codes (486/459)+772+B63+(RVA/RSJ)/RSK/RVB/RVM/RVN)+U29	*	*	*
		Only in conjunction with B63+P29+U29+772	*	*	*
		I.V.m. Code PSF/PSJ/PSN/PSQ	—	○	○
		I.V.m. Code PSF/PSJ/PSN/PSQ	○	—	—
P35	DIGITAL LIGHT		●	●	●
		Includes codes (318/316/317)+(628/608)			*
		Includes codes (318/317)+(628/608)	*	*	*
		Not in conjunction with PAX	*	*	*
		Only in conjunction with 42U+43U+(316+608/(317/318)+628)+30U			*
		Only in conjunction with 42U+43U+(317/318)+628+30U	*	*	
		I.V.m. Code PDC/PDD	○	○	○
P44	Parking Package with reversing camera		●	●	●
		Includes codes 218+235	*	*	*
		Not in conjunction with P47/PBH	*	*	*
		Only in conjunction with (PDA/PDB)+218	*	*	*
		I.V.m. Code PDA/PDB/PDC/PDD	○	○	○
P47	Parking Package with 360-degree camera		●	●	●
		Includes codes 235+501	*	*	*
		Not in conjunction with P44/PBH	*	*	*
		Only in conjunction with 501	*	*	*
		I.V.m. Code PDC/PDD	○	○	○
P49	Mirror Package		●	●	●
		Includes codes 249+500+587	*	*	*
		I.V.m. Code PDA/PDB/PDC/PDD	○	○	○
P53	ENERGIZING AIR CONTROL		●	●	●
P54	GUARD 360° Vehicle protection		●	●	●
		Includes codes 551+882	*	*	*
		Not in conjunction with P82	*	*	*
		Only in conjunction with 551+882	*	*	*
P55	Night Package		●	●	●
		Includes codes (840/U50)+(RVB/RSJ)/RSK/RVA/RVM/RVN)	*	*	*
		Only in conjunction with P31+(840/U50)	*	*	*
		I.V.m. Code PSF/PSN/PSQ	●	●	●

LLP

0,00

2.394,00

0

0

0

2.084,25

351,75

0

0

0,00

0,00

0

0

4.189,50

0

0

0,00

0,00

1.417,50

0

0

0

0

0

0,00

661,50

0

0

0

0,00

483,00

0

0

0

0,00

493,50

0

0,00

157,50

462,00

0

0

0

787,50

0

0

399,00

Standard and special equipment

Model year : 804
 Sales Release : 2023-09-05
 Production Change : 2023-06-30
 Pricing Date : 2023-09-05

Legend

(*) Applicable (*) Available at extra cost (○) available without additional charge (S) standard equipment (I) Applicable from PPM (-) not available (L) Left hand drive
 Please note that central restrictions are displayed. Markets may have specific deviation if any. Codes could be valid for certain countries only.

			CLE-Klasse Coupe		
Code	Equipment	Restrictions	236304 CLE 220 d Coupé	236350 CLE 200 Coupé	236347 CLE 300 4MATIC Coupé
					LLP
P82	GUARD 360 ° Vehicle protection Plus		●	●	●
		Includes codes 31U+551+882	*	*	*
		Not in conjunction with P54	*	*	*
		Only in conjunction with 551+{(882/552+882/852)}			*
		Only in conjunction with 551+882	*	*	
		I.V.m. Code 34U	●	●	●
PAD	Engineering Package		●	●	●
		Includes codes 201+459	*	*	*
		Not in conjunction with R01	*	*	*
		Only in conjunction with 201+459	*	*	*
PAV	Winter Package		●	●	●
		Includes codes 443	*	*	*
		Includes codes 443+875	*	*	*
		Only in conjunction with 443	*	*	*
		Only in conjunction with 443+875	*	*	*
PAX	DIGITAL LIGHT with projection function		●	●	●
		Includes codes (30U/42U/43U)+(318/316/317)+(628/608)			*
		Includes codes (30U/42U/43U)+(318/317)+(628/608)	*	*	*
		Not in conjunction with P35	*	*	*
		Only in conjunction with 42U+30U+43U+PDD+(PBF/PBG)+(316+608/(317/318)+628)			*
		Only in conjunction with 42U+30U+43U+PDD+(PBF/PBG)+(317/318)+628		*	
		Only in conjunction with 42U+30U+43U+PDD+PBG+(317/318)+628	*		
		I.V.m. Code PDD	○	○	○
PBF	MBUX Navigation Plus		-	●	●
		Includes codes 01U+365+367+502		*	*
		Not in conjunction with PBG		*	*
		Only in conjunction with 01U+365+367		*	*
		I.V.m. Code PDB/PDC/PDD	-	○	○
PBG	MBUX Navigation Premium		●	●	●
		Includes codes 01U+365+367+502	*	*	*
		Not in conjunction with PBF		*	*
		Only in conjunction with {(382/383)+01U/382/383}+{(382/383)+367/382/383}+(382/383)+365	*		
		Only in conjunction with 01U+365+367		*	*
		I.V.m. S-Code 8P3	●	●	●
		I.V.m. PDB/PDC/PDD+S-Code 8P3	●	●	●
		I.V.m. PSE/PSF/PSI/PSJ/PSN/PSQ	○	○	○
		I.V.m. PDB/PDC/PDD	○	○	○
PBH	Parking package with Memory Parking Assist		●	●	●
		Includes codes 235+501+507	*	*	*
		Not in conjunction with P44/P47	*	*	*
		Only in conjunction with P20+501+507	*	*	*
		I.V.m. Code PDC/PDD	●	●	●
PBR	ENERGIZING Package Plus		●	●	●
		Includes codes 399+401+894+P21	*	*	*
		Not in conjunction with PBU		*	
		Not in conjunction with PDA	*	*	*
		Only in conjunction with (201A/204A/205A/207A/801A/804A/809A)+399+401+894+P21	*	*	*
		I.V.m. Code PDB/PDC/PDD	●	●	●

1.890,00

Standard and special equipment
Model year :

804

Sales Release :

2023-09-05

Production Change :

2023-06-30

Pricing Date :

2023-09-05

Legend

(*) Applicable (*) Available at extra cost (○) available without additional charge (S) standard equipment (I) Applicable from PPM (-) not available (L) Left hand drive
Please note that central restrictions are displayed. Markets may have specific deviation if any. Codes could be valid for certain countries only.

			CLE-Klasse Coupe			LLP
Code	Equipment	Restrictions	236304 CLE 220 d Coupé	236350 CLE 200 Coupé	236347 CLE 300 4MATIC Coupé	
PBU	ENERGIZING package China		—	●	—	567,00
		Includes codes P21		*		0
		Not in conjunction with PBR		*		0
		Only in conjunction with P21		*		0
PDA	Advanced Package		○	○	○	0,00
		Includes codes 14U+20U+321+464+580+608+(75B/72B)+868+(873/401)+891+897+B51+(P44/P47/PBH)+P49	*	*	*	0
		Only in conjunction with (-00U/33U/34U/37U)/321+(608/628)+(72B/75B)+(401/873)+(PBH/P44/P47)+(B51/R66/672)+20U		*	*	0
		Only in conjunction with (321/-00U/33U/34U)+(608/628)+(72B/75B)+(401/873)+(PBH/P44/P47)+20U	*			0
PDB	Advanced Plus Package		●	●	●	1.464,75
		Includes codes 14U+20U+(234/P20)+321+464+580+608+(75B/72B)+868+(873/401)+891+894+897+B51+(P44/P47/PBH)+P49+(PBG/PBF)+U25		*	*	0
		Includes codes 14U+20U+(234/P20)+321+464+580+608+(75B/72B)+868+(873/401)+891+894+897+B51+(P44/P47/PBH)+P49+PBG+U25	*			0
		Only in conjunction with (233/234)+894+U25+(PBF/PBG)+(-00U/33U/34U/37U)/321+513+(608/628)+(72B/75B)+(401/873)+(PBH/P44/P47)+(B51/R66/672)+20U		*	*	0
		Only in conjunction with (233/234)+894+U25+PBG+(321/-00U/33U/34U)+513+(608/628)+(72B/75B)+(401/873)+(PBH/P44/P47)+20U	*			0
		I.V.m. Code PBF	●	●	●	1.375,50
		I.V.m. PSI/PSJ	○	○	○	0,00
PDC	Premium Package		●	●	●	3.276,00
		Includes codes 14U+20U+(234/P20)+321+464+580+608+(75B/72B)+868+(873/401)+891+894+897+B51+P17+P35+(P47/PBH)+P49+(PBG/PBF)+U25		*	*	0
		Includes codes 14U+20U+(234/P20)+321+464+580+608+(75B/72B)+868+(873/401)+891+894+897+B51+P17+P35+(P47/PBH)+P49+PBG+U25	*			0
		Only in conjunction with (233/234)+894+U25+(PBF/PBG)+(-00U/33U/34U/37U)/321+513+(608/628)+(72B/75B)+(401/873)+(B51/R66/672)+P17+P35+(P47/PBH)+U19+20U		*	*	0
		Only in conjunction with (233/234)+894+U25+PBG+(321/-00U/33U/34U)+513+(608/628)+(72B/75B)+(401/873)+P17+P35+(P47/PBH)+U19+20U	*			0
		I.V.m. Code PBF	●	●	●	3.186,75
		I.V.m. Code PSN	○	○	○	0,00
PDD	Premium Plus Package		●	●	●	6.531,00
		Includes codes 14U+20U+(234/P20)+321+413+444+464+580+608+(75B/72B)+810+868+(873/401)+891+894+897+B51+P17+(P47/PBH)+P49+(PAX/P35)+(PBG/PBF)+U25		*	*	0
		Includes codes 14U+20U+(234/P20)+321+413+444+464+580+608+(75B/72B)+810+868+(873/401)+891+894+897+B51+P17+(P47/PBH)+P49+(PAX/P35)+PBG+U25	*			0
		Only in conjunction with 20U+413+444+49U+513+77B+810+894+P17+PAX+PBG+U19+U25+(233/234)+(321/-00U/33U/34U)+608/628)+(72B/75B)+(401/873)+(P47/PBH)	*			0
		Only in conjunction with 20U+413+444+49U+513+77B+810+894+P17+PAX+U19+U25+(233/234)+(PBF/PBG)+(-00U/33U/34U/37U)/321+(608/628)+(72B/75B)+(401/873)+(B51/R66/672)+(P47/PBH)		*	*	0
		I.V.m. Code PAX	●	●	●	6.888,00
		I.V.m. Code PBF+PAX	●	●	●	6.798,75
		I.V.m. Code PBF	●	●	●	6.441,75
		I.V.m. Code PSQ	○	○	○	0,00
PSE	AVANTGARDE Advanced		●	●	—	1.113,00
		Includes codes (00U/34U)+382+70B+PBG+PDA	*	*		0
		Only in conjunction with PDA+(00U/34U)+70B+PBG+382	*	*		0
PSF	AMG Line Advanced		●	●	●	5.633,25
		Includes codes (00U/34U)+382+70B+840+P29+P31+PBG+PDA	*	*	*	0
		Only in conjunction with PDA+(00U/34U)+70B+PBG+382+P31+P29+(840/U50)	*	*	*	0

Standard and special equipment

Model year :

804

Sales Release :

2023-09-05

Production Change :

2023-06-30

Pricing Date :

2023-09-05

Legend

(*) Applicable (*) Available at extra cost (○) available without additional charge (S) standard equipment (I) Applicable from PPM (-) not available (L) Left hand drive
Please note that central restrictions are displayed. Markets may have specific deviation if any. Codes could be valid for certain countries only.

			CLE-Klasse Coupe			
			236304 CLE 220 d Coupé	236350 CLE 200 Coupé	236347 CLE 300 4MATIC Coupé	
Code	Equipment	Restrictions				LLP
PSI	AVANTGARDE Advanced Plus		●	●	I	2.215,50
		Includes codes (00U/34U)+382+513+70B+PDB	*	*		0
		Only in conjunction with PDB+(00U/34U)+70B+382+513	*	*		0
PSJ	AMG Line Advanced Plus		●	●	●	6.735,75
		Includes codes (00U/34U)+382+513+70B+840+P29+P31+PDB	*	*	*	0
		Only in conjunction with PDB+(00U/34U)+70B+382+513+P31+P29+(840/U50)	*	*	*	0
PSN	AMG Line Premium		●	●	●	8.872,50
		Includes codes (00U/34U)+382+513+70B+840+P29+P31+PDC+U19	*	*	*	0
		Only in conjunction with PDC+(00U/34U)+70B+382+513+P31+P29+(840/U50)+U19	*	*	*	0
PSQ	AMG Line Premium Plus		●	●	●	12.915,00
		Includes codes (00U/34U)+382+49U+513+70B+77B+840+P29+P31+PDD+U19	*	*	*	0
		Only in conjunction with PDD+(00U/34U)+70B+382+513+P31+P29+(840/U50)+U19+49U+77B	*	*	*	0
R	Right-hand drive		●	●	●	1.417,50
R01	Summer tyres		○	○	○	0,00
R02	All-season tyres		—	—	○	0,00
		Not in conjunction with 651/652			*	0
		Only in conjunction with R66			*	0
R03	Sports tyres		●	●	●	315,00
		Only in conjunction with R06+RVA	*	*	*	0
R06	Noise reduced tyre with foam absorber		○	○	○	0,00
		Only in conjunction with R03	*	*	*	0
R17	48.3 cm (19-inch) 5-twin-spoke light-alloy wheels		●	●	●	892,50
		Only in conjunction with P15	*	*	*	0
R55	48.3 cm (19-inch) 5-twin-spoke light-alloy wheels		●	●	●	735,00
		Only in conjunction with P15	*	*	*	0
R66	run-flat tyres		—	●	●	294,00
		Not in conjunction with B51		*	*	0
		Only in conjunction with (475/477)+R01		*		0
		Only in conjunction with (R02/R01)+(475/477)			*	0
RSJ	45.7 cm (18-inch) AMG 5-twin-spoke light-alloy wheels		○	○	○	0,00
		Only in conjunction with P31	*	*	*	0
RSK	45.7 cm (18-inch) AMG 5-twin-spoke light-alloy wheels		○	○	○	0,00
		Only in conjunction with P31	*	*	*	0
RVA	48.3 cm (19-inch) AMG multi-spoke light-alloy wheels		○	○	○	0,00
		Only in conjunction with P31	*	*	*	0
RVB	48.3 cm (19-inch) AMG multi-spoke light-alloy wheels		●	●	●	315,00
		Only in conjunction with P31	*	*	*	0
		I.V.m. Code P55	○	○	○	0,00
RVM	50.8 cm (20-inch) AMG multi-spoke light-alloy wheels		●	●	●	787,50
		Only in conjunction with P31	*	*	*	0
RVN	50.8 cm (20-inch) AMG multi-spoke light-alloy wheels		●	●	●	1.102,50
		Only in conjunction with P31	*	*	*	0
		I.V.m. Code P55	●	●	●	787,50
U01	Rear belt status indication in the instrument display		○	○	○	0,00
		Not in conjunction with U23	*	*	*	0
U02	Belt feeder		S	S	S	0,00
U10	Automatic front passenger airbag deactivation		○	○	○	0,00
U12	Velour floor mats		S	S	S	0,00

Standard and special equipment

Model year : 804
 Sales Release : 2023-09-05
 Production Change : 2023-06-30
 Pricing Date : 2023-09-05

Legend

(*) Applicable (*) Available at extra cost (○) available without additional charge (S) standard equipment (I) Applicable from PPM (-) not available (L) Left hand drive
 Please note that central restrictions are displayed. Markets may have specific deviation if any. Codes could be valid for certain countries only.

			CLE-Klasse Coupe		
			236304 CLE 220 d Coupé	236350 CLE 200 Coupé	236347 CLE 300 4MATIC Coupé
Code	Equipment	Restrictions			LLP
		Not in conjunction with U26	*	*	0
		Only in conjunction with P14	*	*	0
U19	MBUX augmented reality for navigation		●	●	409,50
		Only in conjunction with (PDC/PDD)+365	*	*	0
		I.V.m. Code PSN/PSQ	○	○	0,00
U22	4-way lumbar support		○	○	0,00
		Not in conjunction with 399	*	*	0
U23	Seat occupancy sensor for rear seats		○	○	0,00
		Not in conjunction with U01	*	*	0
U25	Illuminated door sill panels with "Mercedes-Benz" lettering		●	●	157,50
		Not in conjunction with PDA	*	*	0
		Only in conjunction with P14/P29	*	*	0
		I.V.m. Code PDB/PDC/PDD	○	○	0,00
U26	AMG floor mats		○	○	0,00
		Not in conjunction with U12	*	*	0
		Only in conjunction with P29	*	*	0
U29	Braking system with larger brake discs on the front axle		●	●	262,50
		Only in conjunction with P15/P31	*	*	0
		I.V.m. Code P31	○	○	0,00
U30	Diesel-Abgasreinigung mit SDPF		S	-	0,00
U34	Instrument panel and beltlines in ARTICO man-made leather		●	●	493,50
		Only in conjunction with P14+(801A/804A/809A)/P29	*	*	0
		Only in conjunction with P14/P29	*	*	0
		I.V.m. Code P29	○	○	0,00
U50	Omission of heat-insulating dark-tinted glass		○	○	0,00
		Not in conjunction with 840	*	*	0
		Only in conjunction with P55/P31+-P55	*	*	0
U60	Pedestrian protection		○	○	0,00
U95	AMG spoiler lip		●	●	367,50
		Only in conjunction with P31	*	*	0
Y05	Red seat belts		●	●	315,00
		Only in conjunction with 101A/201A/601A/801A	*	*	0
Z01	Paint not feat.on standard sample card		○	○	0,00
		Not in conjunction with Z98	*	*	0
		Only in conjunction with 000U/077U	*	*	0
Z98	Paint not feat.on standard sample card		○	○	0,00
		Not in conjunction with Z01	*	*	0
		Only in conjunction with 000U/077U	*	*	0

