

Pricing Date :

(*) Applicable (•) Available at extra cost (○) available without additional charge (S) standard equipment (!) Applicable from PPM (-) not available (L) Left hand drive only (R) Right hand drive only (NS) National Standard "+* AND (code A and B)"/" OR (code A or B) "[1] XOR if necessary at additional charge (exact one of A.B...) "(1" In logical grouping
Please note that central restrictions are displayed. Markets may have specific deviation if any.

VAT

Legend

				GL B							
				247612 GLB 200 d	247613 GLB 200 d 4MATIC	247615 GLB 220 d 4MATIC	247687 GLB 200	247645 GLB 220 4MATIC	247647 GLB 250 4MATIC	247651 Mercedes-AMG GLB 35 4MATIC	
N/A	Code	Equipment	Restrictions								Local Price excl.VAT
	00B	Owner's Manual and service information - Danish		○	○	○	○	○	○	○	0,00
	00U	Remote Services		LS	LS	LS	LS	LS	LS	LS	0,00
			Not in conjunction with 33U				*				0,00
			Not in conjunction with 33U/34U				*				0,00
			Not in conjunction with 33U/34U/37U	*	*	*		*	*	*	0,00
			Not in conjunction with 33U/37U	*	*	*		*	*	*	0,00
			Not in conjunction with 37U								0,00
			Only in conjunction with 362			*	*	*	*	*	0,00
			i.V.m. Code PSA/PSD/PSE/PSI	-	-	-	-	○	-	-	0,00
			i.V.m. Code PSA/PSD/PSE/PSI	○	○	○	○	-	○	-	0,00
			i.V.m. Code PSJ/PSN/PSQ	-	-	-	-	○	-	○	0,00
			i.V.m. Code PSJ/PSN/PSQ	○	○	○	○	-	○	-	0,00
	01B	Owner's Manual and service information - Dutch		○	○	○	○	○	○	○	0,00
	01R	45.7 cm (18-inch) 5-twin-spoke light-alloy wheels		●	●	●	●	●	●	-	630,00
			Not in conjunction with 950	*	*	*	*	*	*	*	0,00
			i.V.m. Code P59	○	○	○	○	○	○	-	0,00
	01U	Preinstallation for Navigation Services		○	○	○	○	○	○	○	0,00
			Only in conjunction with 362			*	*	*	*	*	0,00
			Only in conjunction with PBF/PBG	*	*	*	*	*	*	*	0,00
			Only in conjunction with PBG								0,00
	02B	Owner's Manual and service information - German		○	○	○	○	○	○	○	0,00
	03B	Owner's Manual and service information - Russian		○	○	○	○	○	○	○	0,00
	03H	Brown open-pore lime wood trim		●	●	●	●	●	●	●	273,00
			Only in conjunction with P59/950	*	*	*	*	*	*	*	0,00
	04B	Owner's Manual and service information - Finnish		○	○	○	○	○	○	○	0,00
	05B	Owner's Manual and service information - English		○	○	○	○	○	○	○	0,00
	06B	Owner's Manual and service information - Italian		○	○	○	○	○	○	○	0,00
	07B	Owner's Manual and service information - French		○	○	○	○	○	○	○	0,00
	08B	Owner's Manual and service information - Spanish		○	○	○	○	○	○	○	0,00
	09B	Owner's Manual and service information - Portuguese		○	○	○	○	○	○	○	0,00
	0K1	OFFROAD TRACK		-	●	●	-	●	●	●	263,00
			Only in conjunction with 365		*	*		*	*	*	0,00
	101A	ARTICO man-made leather black		●	●	●	●	●	●	-	153,00
			Only in conjunction with P59	*	*	*	*	*	*	*	0,00
	104A	ARTICO man-made leather brown		-	-	-	●	●	-	-	258,00
			Only in conjunction with L				*	*			0,00
			Only in conjunction with P59				*	*			0,00
	105A	ARTICO man-made leather macchiato beige / black		●	●	●	●	●	●	-	258,00
			Only in conjunction with P59	*	*	*	*	*	*	*	0,00
	10B	Owner's Manual and service information - Swedish		○	○	○	○	○	○	○	0,00
	11B	Owner's Manual and service information - Arabic		○	○	○	○	○	○	○	0,00
	12B	Owner's Manual and service information - English UK		-	-	-	-	-	○	○	0,00
	13B	Owner's Manual and service information - Norwegian		○	○	○	○	○	○	○	0,00
	149U	polar white		●	●	●	●	●	●	-	289,00
	149U			-	-	-	-	-	-	○	0,00
	14B	Owner's Manual and service information - Greek		○	○	○	○	○	○	○	0,00
	14U	Smartphone integration		●	●	●	●	●	●	●	315,00
			Only in conjunction with 16U+17U	*	*	*	*	*	*	*	

N/A	Code	Equipment	Restrictions	247612 GLB 200 d	247613 GLB 200 d 4MATIC	247615 GLB 220 d 4MATIC	247687 GLB 200	247645 GLB 220 4MATIC	247647 GLB 250 4MATIC	247651 Mercedes-AMG GLB 35 4MATIC	Local Price excl.VAT
	158A	ARTICO man-made leather sage grey / black		●	●	●	●	●	●	●	153,00
			Only in conjunction with P59/950	*	*	*	*	*	*	*	0,00
			i.V.m. Code 950	○	○	○	○	○	○	○	0,00
	15B	Owner's Manual and service information - Turkish		○	○	○	○	○	○	○	0,00
	16B	Owner's Manual and service information - Polish		○	○	○	○	○	○	○	0,00
	16U	Apple CarPlay		○	○	○	○	○	○	○	0,00
			Only in conjunction with 14U	*	*	*	*	*	*	*	0,00
	17B	Owner's Manual and service information - Czech		○	○	○	○	○	○	○	0,00
	17U	Android Auto		○	○	○	○	○	○	○	0,00
			Only in conjunction with 14U	*	*	*	*	*	*	*	0,00
	18B	Owner's Manual and service information - English Sc		-	-	○	○	○	○	○	0,00
	191U	Metallic paint cosmos black		●	●	●	●	●	●	-	788,00
	191U			-	-	-	-	-	-	○	0,00
	197U	Metallic paint obsidian black		-	-	-	●	●	-	-	788,00
			Only in conjunction with L				*	*			0,00
	19B	Owner's Manual and service information - French So		-	-	○	○	○	○	○	0,00
	1P0	Sonderpreis		○	○	○	○	○	○	○	0,00
	207	Active Distance Assist DISTRONIC Plus		●	●	●	●	●	●	●	420,00
			Not in conjunction with 239	*	*	*	*	*	*	*	0,00
			Only in conjunction with 5B0	*	*	*	*	*	*	*	0,00
	20B	Owner's Manual and service information - Spanish S		-	-	○	○	-	○	○	0,00
	20U	Preinstallation for digital key transfer		LS	LS	LS	LS	LS	LS	LS	0,00
			Only in conjunction with 362			*	*	*	*	*	0,00
			i.V.m. Code PSA/PSD/PSE	-	-	-	-	○	-	-	0,00
			i.V.m. Code PSI/PSJ/PSN/PSQ	-	-	-	-	○	-	-	0,00
			i.V.m. Code PSA/PSD/PSE	-	○	-	○	-	-	○	0,00
			i.V.m. Code PSI/PSJ/PSN/PSQ	○	-	○	-	-	○	-	0,00
			i.V.m. Code PSI/PSJ/PSN/PSQ	-	○	-	○	-	-	○	0,00
			i.V.m. Code PSA/PSD/PSE	○	-	○	-	-	○	-	0,00
	211A	Leather black		○	○	○	○	○	○	○	0,00
			Only in conjunction with 873+(P34/P39)	*	*	*	*	*	*	*	0,00
			Only in conjunction with 873+P39							*	0,00
	213	Direct-Steer system		○	○	○	○	○	○	S	0,00
			Only in conjunction with 457	*	*	*	*	*	*	*	0,00
	214A	Rough leather / leather Bahia brown / black		●	●	●	●	●	●	-	105,00
			Not in conjunction with 847	*	*	*	*	*	*	*	0,00
			Only in conjunction with 873+P34	*	*	*	*	*	*	*	0,00
	218	Reversing camera		○	○	○	○	○	○	○	0,00
			Not in conjunction with P47	*	*	*	*	*	*	*	0,00
			i.V.m. Code P44	-	-	-	-	-	-	-	0,00
	21B	Owner's Manual and service information - Portugues		-	-	○	○	○	○	○	0,00
	21U	Dash cam		●	●	●	●	●	●	●	210,00
			Only in conjunction with (PBF/PBG)+(PDB/PDC/PDD)							*	0,00
			Only in conjunction with PBF/PBG	*	*	*	*	*	*	*	0,00
			Only in conjunction with PBG								0,00
			Only in conjunction with PBG+(PDA/PDB/PDC/PDD)								0,00
	221	Electrically adjustable front seat, left		-	-	-	○	○	-	-	0,00
			Not in conjunction with 241				*	*			0,00
			Only in conjunction with L				*	*			0,00
	222	Electrically adjustable front seat, right		-	-	-	-	●	-	-	237,00
			Not in conjunction with 242				*	*			0,00
			Only in conjunction with 221				*	*			0,00
			Only in conjunction with L				*	*			0,00
	228	Auxiliary heater		●	●	●	●	●	●	●	1.155,00
			Only in conjunction with L	*	*	*	*	*	*	*	0,00
	22B	Owner's Manual and service information - Japanese		○	○	-	-	-	-	○	0,00
	22U	Pre-installation for MBUX Entertainment		○	○	○	○	○	○	○	0,00

N/A	Code	Equipment	Restrictions	247612 GLB 200 d	247613 GLB 200 d 4MATIC	247615 GLB 220 d 4MATIC	247687 GLB 200	247645 GLB 220 4MATIC	247647 GLB 250 4MATIC	247651 Mercedes-AMG GLB 35 4MATIC	Local Price excl.VAT
			Only in conjunction with 362			*	*	*	*	*	0,00
			Only in conjunction with 853/810	*	*	*	*	*	*	*	0,00
	232	Garage door opener (frequency range 284-390 MHz)		-	-	•	•	•	•	•	237,00
			Not in conjunction with 968/969			*	*	*	*	*	0,00
			Only in conjunction with P49			*	*	*	*	*	0,00
	234	Blind Spot Assist		•	•	•	•	•	•	•	473,00
			Only in conjunction with (500/275)+273	*	*	*	*	*	*	*	0,00
			Only in conjunction with 273							*	0,00
			i.V.m. Code PDC/PDD	-	-	-	-	-	-	-	0,00
			i.V.m. Code PDC/PDD	○	○	○	○	○	○	○	0,00
			i.V.m. Code P79	-	-	-	-	-	-	-	0,00
			i.V.m. Code P79	○	○	○	○	○	○	○	0,00
	235	Active Parking Assist with PARKTRONIC		•	•	•	•	•	•	•	709,00
			Only in conjunction with P44/P47	*	*	*	*	*	*	*	0,00
			i.V.m. Code P44/P47	○	○	○	○	○	○	○	0,00
	239	Active Distance Assist DISTRONIC		•	•	•	•	•	•	•	420,00
			Not in conjunction with 207/258	*	*	*	*	*	*	*	0,00
			Not in conjunction with 258								0,00
			Only in conjunction with P79	*	*	*	*	*	*	*	0,00
			i.V.m. Code P79	-	-	-	-	-	-	-	0,00
			i.V.m. Code P79	○	○	○	○	○	○	○	0,00
	238	Owner's Manual and service information - simplified		-	-	-	○	○	-	○	0,00
	241	Power front left seat with memory function		•	•	•	•	•	•	•	300,00
			Not in conjunction with 221				*	*			0,00
			Only in conjunction with 275	*	*	*	*	*	*	*	0,00
			Only in conjunction with R	*	*	*	*	*	*	*	0,00
			i.V.m. Code PDD	-	-	-	-	○	-	-	0,00
			i.V.m. Code PDD	-	-	-	-	-	-	○	0,00
			i.V.m. Code PDD	○	○	○	○	-	○	-	0,00
	242	Power front right seat with memory function		•	•	•	•	•	•	•	300,00
			Not in conjunction with 222					*			0,00
			Only in conjunction with 275	*	*	*	*	*	*	*	0,00
			Only in conjunction with L	*	*	*	*	*	*	*	0,00
			i.V.m. Code PDD	-	-	-	-	○	-	-	0,00
			i.V.m. Code PDD	-	-	-	-	-	-	○	0,00
			i.V.m. Code PDD	○	○	○	○	-	○	-	0,00
	243	Active Lane Keeping Assist		•	•	•	•	•	•	•	473,00
			i.V.m. S-Code 51B	○	○	○	○	○	○	○	0,00
			i.V.m. Code P79	-	-	-	-	-	-	-	0,00
			i.V.m. Code P79	○	○	○	○	○	○	○	0,00
	249	Automatically dimming driver's side door mirror		-	-	-	-	○	○		0,00
			Not in conjunction with 252					*	*		0,00
			Only in conjunction with L					*	*		0,00
			Only in conjunction with P49					*			0,00
	24B	Owner's Manual and service information - traditional		○	○	○	○	○	○	○	0,00
	252	Automatically dimming rear-view mirror		○	○	○	○	○	○	○	0,00
			Not in conjunction with 249					*	*		0,00
			Only in conjunction with P49	*	*	*	*	*	*	*	0,00
	256	AMG TRACK PACE		-	-	-	-	-	-	•	263,00
			Only in conjunction with 365					*			0,00
	258	Active Brake Assist		○	○	○	○	○	○	○	0,00
			Not in conjunction with 239	*	*	*	*	*	*	*	0,00
			Only in conjunction with -B01/5B0				*		*		0,00
			Only in conjunction with 5B0				*	*			0,00
	25B	Owner's Manual and service information - Korean		○	-	-	-	-	○	○	0,00
	25R	43.2 cm (17-inch) 5-twin-spoke light-alloy wheels		○	○	○	○	○	○	-	0,00
			Not in conjunction with 950/PAD	*			*	*			0,00

N/A	Code	Equipment	Restrictions	247612	GLB 200 d	247613	GLB 200 d 4MATIC	247615	GLB 220 d 4MATIC	247687	GLB 200	247645	GLB 220 4MATIC	247647	GLB 250 4MATIC	247651	Mercedes-AMG GLB 35 4MATIC	Local Price excl.VAT
			Not in conjunction with 950/PAD/847		*	*							*				0,00	
	260	Deletion of model plate on boot lid		○	○	○	○	○	○	○	○	○	○	○	○		0,00	
	261	Omission of badge on the wings		-	-	-	-	-	-	-	-	-	-	-	○		0,00	
	263	Number plate mounting for Asia / Mexico		○	○	-	-	-	-	-	-	-	-	-	○		0,00	
			Not in conjunction with 264/823/827/831												*		0,00	
			Not in conjunction with 823/831	*	*												0,00	
	264	Number plate mounting for USA/CAN		-	-	○	○	○	○	○	○	○	○	○	○		0,00	
			Not in conjunction with 263/823/827/831												*		0,00	
			Not in conjunction with 823/827/831			*	*	*	*	*	*	*	*	*	*		0,00	
	266	Active Steering Assist		○	○	○	○	○	○	○	○	○	○	○	○		0,00	
			Only in conjunction with P79	*	*	*	*	*	*	*	*	*	*	*	*		0,00	
	26B	Owner's Manual and service information - Chinese T		-	-	-	○	-	-	-	○						0,00	
	270	GPS aerial		\$	\$	\$	\$	\$	\$	\$	\$	\$	\$	\$	\$		0,00	
	273	Exit warning function		○	○	○	○	○	○	○	○	○	○	○	○		0,00	
			Only in conjunction with 234	*	*	*	*	*	*	*	*	*	*	*	*		0,00	
	275	Driver's seat, electrically adjustable with memory fu		●	●	●	●	●	●	●	●	●	●	●	●		363,00	
			i.V.m. Code PDD	-	-	-	-	○	-	-							0,00	
			i.V.m. Code PDD	-	-	-	-	-	-	-	○						0,00	
			i.V.m. Code PDD	○	○	○	○	○	-	○	-						0,00	
	277A	Leather, two-tone red pepper / black		●	●	●	●	●	●	●	●	●	●	●	●		105,00	
			Only in conjunction with 873+P39	*	*	*	*	*	*	*	*	*	*	*	*		0,00	
	27B	Owner's Manual and service information - Spanish M		-	-	-	-	-	○	-	-	○					0,00	
	27R	48.3 cm (19-inch) 5-twin-spoke light-alloy wheels		●	●	●	●	●	●	●	●	●	●	●	-		1.103,00	
			Not in conjunction with 950	*	*	*	*	*	*	*	*	*	*	*	*		0,00	
			i.V.m. Code P55/P59	●	●	●	●	●	●	●	●	●	●	-			473,00	
	286	Luggage net on driver`s and front pass. backrest		○	○	○	○	○	○	○	○	○	○	○	○		0,00	
	287	Folding rear seat backrests		\$	\$	\$	\$	\$	\$	\$	\$	\$	\$	\$	\$		0,00	
	293	Sidebags in rear		●	●	●	●	●	●	●	●	●	●	●	●		394,00	
			Not in conjunction with 413+550+847+(853/810)+890+U40		*	*											0,00	
	294	Knee airbag		○	○	○	○	○	○	○	○	○	○	○	○		0,00	
	299	PRE-SAFE® system		●	●	●	●	●	●	●	●	●	●	●	●		347,00	
			i.V.m. Code P79	○	○	○	○	○	○	○	○	○	○	○	○		0,00	
	30B	Owner's Manual and service information - Slovenian		○	○	○	○	○	○	○	○	○	○	○	○		0,00	
	310	Double cup holder		\$	\$	\$	\$	\$	\$	\$	\$	\$	\$	\$	\$		0,00	
	311A	ARTICO man-made leather / Bertrix fabric black		○	○	○	○	○	○	○	○	○	○	-			0,00	
			Not in conjunction with 950	*	*	*	*	*	*	*	*	*	*	*	*		0,00	
	318A	ARTICO man-made leather / Bertrix fabric sage grey		●	●	●	●	●	●	●	●	●	●	-			105,00	
			Only in conjunction with 7U2+P59	*	*	*	*	*	*	*	*	*	*	*	*		0,00	
	31B	Owner's Manual and service information - Hungarian		○	○	○	○	○	○	○	○	○	○	○	○		0,00	
	321	Fingerprint scanner		○	○	○	○	○	○	○	○	○	○	○	○		0,00	
			Not in conjunction with PDA	*	*	*	*	*	*	*	*	*	*	*	*		0,00	
			i.V.m. Code PDB/PDC/PDD	○	○	○	○	○	○	○	○	○	○	○	○		0,00	
	32B	Owner's Manual and service information - Bulgarian		○	○	○	○	○	○	○	○	○	○	○	○		0,00	
	32U	Sound personalisation		○	○	○	○	○	○	○	○	○	○	○	○		0,00	
			Only in conjunction with 810	*	*	*	*	*	*	*	*	*	*	*	*		0,00	
	331	Backlit trim		○	○	○	○	○	○	○	○	○	○	○	○		0,00	
			Only in conjunction with 56H	*	*	*	*	*	*	*	*	*	*	*	*		0,00	
	33B	Owner's Manual and service information - Romanian		○	○	○	○	○	○	○	○	○	○	○	○		0,00	
	33U	Remote Services Plus		●	●	●	●	●	●	●	●	●	●	●	●		158,00	
			Not in conjunction with 00U					*									0,00	
			Not in conjunction with 00U/34U					*									0,00	
			Not in conjunction with 00U/34U/37U	*	*	*	*	*	*	*	*	*	*	*	*		0,00	
			Not in conjunction with 00U/37U	*	*	*	*	*	*	*	*	*	*	*	*		0,00	
			Only in conjunction with 362			*	*	*	*	*	*	*	*	*	*		0,00	
			i.V.m. Code PSA/PSD/PSE/PSI	●	●	●	●	●	●	●	●	●	●	●	-		53,00	
			i.V.m. Code PSJ/PSN/PSQ	-	-	-	-	-	-	-	-	-	-	-	●		53,00	
			i.V.m. Code PSI/PSN/PSQ	●	●	●	●	●	●	●	●	●	●	●	-		53,00	

N/A	Code	Equipment	Restrictions	247612 GLB 200 d	247613 GLB 200 d 4MATIC	247615 GLB 220 d 4MATIC	247687 GLB 200	247645 GLB 220 4MATIC	247647 GLB 250 4MATIC	247651 Mercedes-AMG GLB 35 4MATIC	Local Price excl.VAT
	345	Windscreen wipers with rain sensor		\$	\$	\$	\$	\$	\$	\$	0,00
	34B	Owner's Manual and service information - Croatian		○	○	○	○	○	○	○	0,00
	34U	Remote Services Premium		●	●	●	●	●	●	●	263,00
			Not in conjunction with 00U/33U	*	*	*	*	*	*	*	0,00
			Only in conjunction with 362			*	*	*	*	*	0,00
			i.V.m. Code PSA/PSD/PSE/PSI	●	●	●	●	●	●	●	158,00
			i.V.m. Code PSJ/PSN/PSQ	-	-	-	-	-	-	●	158,00
			i.V.m. Code PSJ/PSN/PSQ	●	●	●	●	●	●	-	158,00
	351	Mercedes-Benz emergency call system		○	○	○	○	○	○	○	0,00
			Only in conjunction with 362			*	*	*	*	*	0,00
	355	Extended MBUX functions		○	○	○	○	○	○	○	0,00
	35B	Owner's Manual and service information - Latvian		○	○	○	○	○	○	○	0,00
	362	Communication module (LTE) for the use of Digital E		○	○	○	○	○	○	○	0,00
			Only in conjunction with 20U+(33U/34U)+351+(00U/37U)+79B+(00U/33U/34U)			*	*				0,00
			Only in conjunction with 20U+(33U/34U)+351+79B+(00U/33U/34U)				*				0,00
			Only in conjunction with 20U+34U+351+79B+(00U/37U)						*		0,00
			Only in conjunction with 20U+34U+351+79B+(00U/37U)+(33U/37U)							*	0,00
	365	Hard-disc navigation		●	●	●	●	●	●	●	578,00
			Only in conjunction with PBF/PBG	*	*	*	*	*	*	*	0,00
			Only in conjunction with PBG								0,00
			i.V.m. Code PBF	-	-	-	-	-	-	-	0,00
			i.V.m. Code PBF/PBG	-	-	-	-	○	-	-	0,00
			i.V.m. Code PBF/PBG	○	○	○	○	-	○	○	0,00
	367	Preinstallation for Live Traffic Information		○	○	○	○	○	○	○	0,00
			Only in conjunction with 362			*	*	*	*	*	0,00
	36B	Owner's Manual and service information - Lithuania		○	○	○	○	○	○	○	0,00
	37B	Owner's Manual and service information - Slovak		○	○	○	○	○	○	○	0,00
	37U	Remote Services Advanced		●	●	●	-	●	●	●	158,00
			Not in conjunction with 00U	*	*	*		*	*	*	0,00
			Not in conjunction with 00U/33U	*	*	*		*	*	*	0,00
			Only in conjunction with 362			*		*	*	*	0,00
	38B	Owner's Manual and service information - Estonian		○	○	○	○	○	○	○	0,00
	39B	Owner's Manual and service information - Serbian		○	○	○	○	○	○	○	0,00
	400	Rear armrest		\$	\$	\$	\$	\$	\$	\$	0,00
	40B	Owner's Manual and service information - Ukrainian		○	○	○	○	○	○	○	0,00
	413	Panoramic sliding sunroof		●	●	●	●	●	●	●	1.260,00
			Not in conjunction with B27	*	*	*	*	*	*	*	0,00
			Only in conjunction with 720/725	*	*	*	*	*	*	*	0,00
			i.V.m. Code PDD	-	-	-	-	○	-	-	0,00
			i.V.m. Code PDD	○	○	○	○	-	○	○	0,00
	41B	Owner's Manual and service information - Hebrew		○	○	○	○	○	○	○	0,00
	426	8G-DCT		\$	\$	\$	-	○	\$	-	0,00
	426	AMG SPEEDSHIFT DCT 8G		-	-	-	-	-	-	\$	0,00
	428	Steering wheel shift paddles		○	○	○	○	○	○	-	0,00
			Not in conjunction with 431	*	*	*	*	*	*	*	0,00
			Not in conjunction with L5C	*	*	*	*	*	*	*	0,00
			Only in conjunction with L3E								0,00
	429	7G-DCT		-	-	-	\$	-	-	-	0,00
	42B	Owner's Manual and service information - Indonesia		-	-	○	○	○	○	○	0,00
	430	Off-Road Engineering Package		-	○	○	-	○	○	-	0,00
			Includes codes 355/859		*	*		*	*		0,00
	431	Galvanised steering-wheel gearshift paddles		○	○	○	○	○	○	-	0,00
			Not in conjunction with 428	*	*	*	*	*	*	*	0,00
			Only in conjunction with L5C	*	*	*	*	*	*	*	0,00
	43B	Owner's Manual and service information - Thai		-	-	○	○	○	○	○	0,00
	440	CRUISE CONTROL		\$	\$	\$	\$	-	\$	\$	0,00
			Not in conjunction with 239								0,00

N/A	Code	Equipment	Restrictions	247612	GLB 200 d	247613	GLB 200 d 4MATIC	247615	GLB 220 d 4MATIC	247687	GLB 200	247645	GLB 220 4MATIC	247647	GLB 250 4MATIC	247651	Mercedes-AMG GLB 35 4MATIC	Local Price excl.VAT
			Not in conjunction with 239/580	*	*	*	*	*	*	*	*	*	*	*	*	*		0,00
	443	Steering wheel heating		○	○	○	○	○	○	○	○	○	○	○	○	○		0,00
			Only in conjunction with PAV	*	*	*	*	*	*	*	*	*	*	*	*	*		0,00
	448	Owner's Manual and service information - Vietnamese		-	-	-	-	-	-	-	-	-	-	-	-	-		0,00
	457	Adjustable damping		●	●	●	●	●	●	●	●	●	●	●	●	●		1.040,00
			Only in conjunction with 213	*	*	*	*	*	*	*	*	*	*	*	*	*		0,00
			i.V.m. Code PAD/P19	○	○	○	○	○	○	○	○	○	○	○	○	-		0,00
	458	All-digital instrument display		LS	LS	LS	LS	LS	LS	LS	LS	LS	LS	LS	LS	LS		0,00
			i.V.m. Code PDB/PDC/PDD	○	○	○	○	○	○	○	○	○	○	○	○	○		0,00
	459	AMG RIDE CONTROL suspension		-	-	-	-	-	-	-	-	-	-	-	-	○		0,00
	460	Canada specification		-	-	-	-	-	-	-	-	○	○	○	○	○		0,00
			Only in conjunction with (218/P47)+264+275+294+551+634+636+763+840+873+PAV+U10+(U12/U26)+(P59/950) +258/239)+242+413+517+875+942+986+989+141)+(U37/950)												*			0,00
			Only in conjunction with (218/P47)+264+275+294+551+634+636+763+873+PAV+U10+(258/239)+242+413+517+ 875+942+986+989+141U	○	○	○	○	○	○	○	○	○	○	○	○	○		0,00
	461	Instrument display in miles with English lettering		○	○	○	○	○	○	○	○	○	○	○	○	○		0,00
	463	Head-up Display		●	●	●	●	●	●	●	●	●	●	●	●	●		1.040,00
			Only in conjunction with 950	*	*	*	*	*	*	*	*	*	*	*	*	*		0,00
			i.V.m. Code PDD	-	-	-	-	-	-	-	-	-	-	-	-	-		0,00
			i.V.m. Code PDD	○	○	○	○	○	○	-	○	○	○	○	○	○		0,00
	475	Tyre pressure monitoring system		●	●	●	●	●	●	●	●	●	●	●	●	●		321,00
			i.V.m. S-Code 6P5	○	○	○	○	○	○	○	○	○	○	○	○	○		0,00
	477	Tyre pressure loss warning system		○	○	○	○	○	○	○	○	○	○	○	-	○		0,00
	485	Comfort suspension		○	○	○	○	○	○	○	○	○	○	○	-	○		0,00
			Not in conjunction with 213	*	*	*	*	*	*	*	*	*	*	*	*	*		0,00
	494	USA specification		-	-	-	-	-	-	-	○	○	○	○	○	○		0,00
			Only in conjunction with 232+413+(853/810)+14U+(218/P47)+(258/239)+264+294+461+517+536+(567/847)+63 4+636+763+942+986+989+U10												*			0,00
			Only in conjunction with 242+840+14U+(218/P47)+(258/239)+264+294+458+461+517+536+(567/847)+634+636 +763+942+986+989+(P59+U37/950)+U10	-	-	-	-	-	○	○	-	○	○	○	○	○		0,00
	496	Mexico version		-	-	-	-	-	○	○	-	○	○	○	○	○		0,00
			Only in conjunction with 264+517+687+986+989								*				*			0,00
			Only in conjunction with 672+264+517+687+986+989												*			0,00
	497	Indonesia specification		-	-	-	-	○	-	○	○	○	○	○	○	○		0,00
			Only in conjunction with 294+682+B08					*	*	*	*	*	*	*	*	*		0,00
	498	Japan specification		○	○	-												

N/A	Code	Equipment	Restrictions	247612	GLB 200 d	247613	GLB 200 d 4MATIC	247615	GLB 220 d 4MATIC	247687	GLB 200	247645	GLB 220 4MATIC	247647	GLB 250 4MATIC	247651	Mercedes-AMG GLB 35 4MATIC	Local Price excl.VAT
	580	THERMATIC automatic climate control		○	○	○		○	○	○	○	○	○	○			0,00	
			Not in conjunction with P53												*		0,00	
			Not in conjunction with PDC/PDD			*	*										0,00	
			Not in conjunction with PDC/PDD/P53	*				*	*	*							0,00	
			Only in conjunction with PDB												*		0,00	
	581	THERMOTRONIC automatic climate control		●	●	●	●	●	●	●	●	●	●	●			536,00	
			i.V.m. Code PDC/PDD	-	-	-	-	-	○	-	-	-	-	-	-		0,00	
			i.V.m. Code PDC/PDD	○	○	○	○	○	-	○	○						0,00	
	586	Surround lighting with projection of brand logo		●	●	●	●	●	●	●	●	●	●	●			116,00	
			i.V.m. Code PDD	-	-	-	-	○	-	-	-	-	-	-	-		0,00	
			i.V.m. Code PDD	○	○	○	○	-	○	○							0,00	
	58U	Roof liner in crystal grey fabric		○	○	○	○	○	○	○	○	○	○	○			0,00	
			Not in conjunction with 105A	*	*	*	*	*	*	*							0,00	
	5B0	Pre-installation for DISTRONIC		○	○	○	○	○	○	○	○	○	○	○			0,00	
			Only in conjunction with 258							*	*						0,00	
			Only in conjunction with 258+(B01/207)					*									0,00	
			Only in conjunction with 258+207	*	*	*								*			0,00	
	5R2	Complete set of 4 M+S winter wheels		○	○	○	○	○	○	○	-						0,00	
			Not in conjunction with 4R9	*	*	*	*	*	*	*							0,00	
			Not in conjunction with 645	*	*	*	*	*	*	*							0,00	
			Only in conjunction with 652+PGL	*	*	*	*	*	*	*							0,00	
			Only in conjunction with L	*	*	*	*	*	*	*							0,00	
			i.V.m. S-Code 7S7	●	●	●	●	●	●	●	-						2.205,00	
	5U6	AMG-specific radiator grille, darkened		-	-	-	-	-	-	-	○						0,00	
			Only in conjunction with PAZ								*						0,00	
	608	Adaptive Highbeam Assist		○	○	○	○	○	○	○	○	○	○	○			0,00	
			Not in conjunction with 628	*	*	*	*	*	*	*	*						0,00	
			Only in conjunction with 631/-642	*	*	*	*	*	*	*	*			*	*		0,00	
			Only in conjunction with 631/632	*	*	*	*	*	*								0,00	
			Only in conjunction with 632														0,00	
			i.V.m. Code 640	-	-	-	-	-	-	-	-						0,00	
	623	Gulf States specification		-	-	-	●	●	●	●	●						158,00	
			Only in conjunction with B12+(672+-R66/R66)+682+687+986+989+U60					*	*	*	*						0,00	
	625	Australia specification		-	-	-	○	-	○	○							0,00	
			Only in conjunction with U60+(258/239)+537				*		*	*							0,00	
	628	Adaptive Highbeam Assist Plus		○	○	○	○	○	○	○	○	○	○	○			0,00	
			Not in conjunction with 608	*	*	*	*	*	*	*	*			*			0,00	
			Only in conjunction with 641/642	*	*	*	*	*	*	*	*			*			0,00	
			Only in conjunction with 642														0,00	
	631	LED High Performance headlamp		○	○	○	○	○	○	○	○	○	○	○			0,00	
			Not in conjunction with 632/640/641/642								*	*					0,00	
			Not in conjunction with 632/641/642	*	*	*	*	*	*								0,00	
			Not in conjunction with PAD/PDD	*	*	*	*	*	*	*							0,00	
			Not in conjunction with PDD											*			0,00	
			Only in conjunction with 608	*	*	*	*	*	*	*	*	*	*	*			0,00	
			Only in conjunction with R	*	*	*	*	*	*	*	*	*	*	*	*		0,00	
	632	LED High Performance headlamps		○	○	○	○	○	○	○	○	○	○	○			0,00	
			Not in conjunction with 631/641								*	*					0,00	
			Not in conjunction with 631/641/642	*	*	*	*	*	*								0,00	
			Not in conjunction with PAD/PDD	*	*	*	*	*	*	*							0,00	
			Not in conjunction with PDD												*		0,00	
			Only in conjunction with 608	*	*	*	*	*	*	*	*	*	*	*	*		0,00	
			Only in conjunction with L	*	*	*	*	*	*	*	*	*	*	*	*		0,00	
	634	Omission of first-aid kit		○	○	○	○	○	○	○	○	○	○	○			0,00	
	636	Omission of hazard warning triangle		○	○	○	○	○	○	○	○	○	○	○			0,00	
	640	MULTIBEAM LED		-	-	-	-	-	-	-	●	●					305,00	
			Not in conjunction with 631/641								*	*						

N/A	Code	Equipment	Restrictions	247612 GLB 200 d	247613 GLB 200 d 4MATIC	247615 GLB 220 d 4MATIC	247687 GLB 200	247645 GLB 220 4MATIC	247647 GLB 250 4MATIC	247651 Mercedes-AMG GLB 35 4MATIC	Local Price excl.VAT
			Only in conjunction with 608						*	*	0,00
			Only in conjunction with L						*	*	0,00
	641	MULTIBEAM LED		●	●	●	●	●	●	●	305,00
			Not in conjunction with 631/632/640/642						*	*	0,00
			Not in conjunction with 631/632/642	*	*	*	*	*	*	*	0,00
			Only in conjunction with 628	*	*	*	*	*	*	*	0,00
			Only in conjunction with R	*	*	*	*	*	*	*	0,00
			i.V.m. Code PAD	-	-	-	-	○	-	-	0,00
			i.V.m. Code PDD	-	-	-	-	○	-	-	0,00
			i.V.m. Code PDD	-	-	-	-	-	○	-	0,00
			i.V.m. Code PAD	○	○	○	○	-	○	-	0,00
			i.V.m. Code PDD	○	○	○	○	-	○	-	0,00
	642	MULTIBEAM LED		●	●	●	●	●	●	-	305,00
	642			-	-	-	-	-	-	LS	0,00
			Not in conjunction with 631/641						*	*	0,00
			Only in conjunction with 628	*	*	*	*	*	*	*	0,00
			Only in conjunction with L	*	*	*	*	*	*	*	0,00
			i.V.m. Code PAD	-	-	-	-	○	-	-	0,00
			i.V.m. Code PDD	-	-	-	-	○	-	-	0,00
			i.V.m. Code PAD	○	○	○	○	-	○	-	0,00
			i.V.m. Code PDD	-	-	-	-	-	-	○	0,00
			i.V.m. Code PDD	○	○	○	○	-	○	-	0,00
	645	M+S winter tyres, set of 4		●	●	●	●	●	●	-	158,00
			Not in conjunction with 652	*	*	*	*	*	*	*	0,00
			Only in conjunction with R58/R62/RTF				*	*			0,00
			Only in conjunction with R62/RTF	*	*	*			*		0,00
	651A	ARTICO man-made leather upholstery / MICROCUT n		○	○	○	○	○	○	S	0,00
			Only in conjunction with 950	*	*	*	*	*	*	*	0,00
	652	Summer complete tyres fitted		○	○	○	○	○	○	○	0,00
			Not in conjunction with 645	*	*	*	*	*	*	*	0,00
			Not in conjunction with R66							*	0,00
			Only in conjunction with 4R9/5R2	*	*	*	*	*	*	*	0,00
			Only in conjunction with 8R4							*	0,00
			Only in conjunction with L	*	*	*	*	*	*	*	0,00
	654A	ARTICO man-made leather upholstery / MICROCUT n		●	●	●	●	●	●	●	105,00
			Only in conjunction with 950	*	*	*	*	*	*	*	0,00
	662U	MANUFAKTUR mountain grey MAGNO		-	-	-	●	●	-	-	2.310,00
	666	Freight packaging without tie-down hooks		●	●	●	●	●	●	●	27,00
			Not in conjunction with 668	*	*	*	*	*	*	*	0,00
			Only in conjunction with 550	*	*	*	*	*	*	*	0,00
	668	Freight packaging with tie-down hooks		LS	LS	LS	LS	LS	LS	LS	0,00
			Not in conjunction with 550	*	*	*	*	*	*	*	0,00
			Not in conjunction with 666	*	*	*	*	*	*	*	0,00
	672	Emergency spare wheel		-	-	○	○	-	○	○	0,00
			Not in conjunction with R66				*	*	*	*	0,00
			Only in conjunction with B12			*	*	*	*	*	0,00
	679	Product protection-partial protection		○	○	○	○	○	○	○	0,00
			Not in conjunction with 524	*	*	*	*	*	*	*	0,00
			Not in conjunction with 662U				*	*			0,00
	682	Fire extinguisher		LS	LS	LS	LS	LS	LS	LS	0,00
	687	Model year on model plate		○	○	○	○	○	○	○	0,00
			Not in conjunction with 968/969	*	*	*	*	*	*	*	0,00
	696U	Solid paint night black		○	○	○	○	○	○	○	0,00
	6U6	AMG fuel cap		-	-	-	-	-	-	●	103,00
	700	CBU vehicle China		-	-	-	○	○	-	-	0,00
	70B	Fluorescent jacket for driver		●	●	●	●	●	●	●	6,00
			i.V.m. Code PSA/PSD/PSE/PSI	○	○	○	○	○	○	○	0,00

N/A	Code	Equipment	Restrictions	247612 GLB 200 d	247613 GLB 200 d 4MATIC	247615 GLB 220 d 4MATIC	247687 GLB 200	247645 GLB 220 4MATIC	247647 GLB 250 4MATIC	247651 Mercedes-AMG GLB 35 4MATIC	Local Price excl.VAT
			i.V.m. Code PSJ/PSN/PSQ	○	○	○	○	○	○	○	0,00
	720	Roof rails in black		○	○	○	○	○	○	○	0,00
			Not in conjunction with 725/B27	*	*	*	*	*	*	*	0,00
			Only in conjunction with P55	*	*	*	*	*	*	*	0,00
			Only in conjunction with P60							*	0,00
	725	Polished aluminium roof rails		○	○	○	○	○	○	\$	0,00
			Not in conjunction with 720/B27	*	*	*	*	*	*	*	0,00
			Not in conjunction with P55	*	*	*	*	*	*	*	0,00
			Not in conjunction with P60							*	0,00
	72B	USB Package Plus		○	○	○	○	○	○	○	0,00
	73B	Stowage compartment in centre console with retractable lid		○	○	○	○	○	○	○	0,00
	762	Radio remote control without panic button		○	○	○	○	○	○	○	0,00
			Not in conjunction with 763					*	*	*	0,00
			Not in conjunction with 968/969	*	*	*	*	*	*	*	0,00
	763	Radio remote control with panic switch		-	-	-	-	○	○	○	0,00
			Not in conjunction with 762					*	*	*	0,00
			Not in conjunction with 968/969					*	*	*	0,00
			Only in conjunction with 551					*	*	*	0,00
	772	AMG bodystyling		○	○	○	○	○	○	\$	0,00
			Only in conjunction with 950	*	*	*	*	*	*	*	0,00
	77B	MBUX Interior Assistant		○	○	○	○	○	○	○	0,00
			Only in conjunction with PDD	*	*	*	*	*	*	*	0,00
	787U	Metallic paint mountain grey		●	●	●	●	●	●	-	788,00
	787U			-	-	-	-	-	-	○	0,00
	79B	Preinstallation for digital radio		○	○	○	○	○	○	○	0,00
			Only in conjunction with 362/537+362			*	*	*	*	*	0,00
	7U2	Comfort Seats		○	○	○	○	○	○	-	0,00
			Only in conjunction with 101A/104A/105A/311A/318A			*	*				0,00
			Only in conjunction with 101A/105A/311A/318A	*	*	*		*			0,00
	7U4	Sports seats		●	●	●	●	●	●	-	315,00
				-	-	-	-	-	-	\$	0,00
			Only in conjunction with 158A/211A/214A/277A/651A/654A	*	*	*	*	*	*	*	0,00
			i.V.m. Code 950	○	○	○	○	○	○	-	0,00
			i.V.m. Code P34	-	-	-	-	-	-	\$	0,00
			i.V.m. Code P34	○	○	○	○	○	○	-	0,00
	7U8	Model badge on boot lid and wings in high-gloss black		-	-	-	-	-	-	○	0,00
			Only in conjunction with PAZ							*	0,00
	805	Technical modifications		○	○	○	○	○	○	○	0,00
	810	Burmester® surround sound system		●	●	●	●	●	●	●	951,00
			Not in conjunction with 853	*	*	*	*	*	*	*	0,00
			Only in conjunction with 22U+32U	*	*	*	*	*	*	*	0,00
			Only in conjunction with 32U								0,00
			i.V.m. Code PDC/PDD	●	●	●	●	●	●	●	625,00
	820	Tourist vehicle		○	○	○	○	○	○	○	0,00
	821	Country code Brazil		-	-	-	-	○	-	○	0,00
			Only in conjunction with (258/239)+294+827+986+B51					*	*	*	0,00
	822	South Africa specification		-	-	○	○	-	○	○	0,00
			Only in conjunction with (258/239)+989			*	*	*	*	*	0,00
	823	country code Switzerland		○	○	○	○	○	○	○	0,00
			Not in conjunction with 263/264/827/831							*	0,00
			Not in conjunction with 263/831	*	*						0,00
			Not in conjunction with 264/827/831			*	*	*	*	*	0,00
			Not in conjunction with 831								0,00
	824	Additional parts for cold countries (engine air intake)		○	○	○	○	○	○	○	0,00
	827	Number plate mounting		-	-	○	○	○	○	○	0,00
			Not in conjunction with 263/264/823/831							*	0,00
			Not in conjunction with 264/823/831			*	*	*	*	*	0,00

N/A	Code	Equipment	Restrictions	247612 GLB 200 d	247613 GLB 200 d 4MATIC	247615 GLB 220 d 4MATIC	247687 GLB 200	247645 GLB 220 4MATIC	247647 GLB 250 4MATIC	247651 Mercedes-AMG GLB 35 4MATIC	Local Price excl.VAT
			Only in conjunction with L			*	*	*	*	*	0,00
	829	Taiwan version		-	-	-	○	-	-	○	0,00
			Only in conjunction with (258/239)+B08+827				*			*	0,00
	830	China specification		-	-	-	○	○	-	○	0,00
			Only in conjunction with (P44/P47)+234+242+873+413+14U+P60+PBF+70B+239+634+827+986+989+B08+U26							*	0,00
			Only in conjunction with 14U+21U+222+413+458+500+70B+847+877+889+P17+P55+P59+U37+239+634+827+986+989+B08+PBF+(U12/U26)					*			0,00
			Only in conjunction with 14U+21U+222+413+458+500+70B+847+877+889+P17+P55+P59+U37+239+634+827+986+989+B08+PBF+(U12/U26)				*				0,00
	831	country code Italia		○	○	○	○	○	○	○	0,00
			Not in conjunction with 263/264/823/827							*	0,00
			Not in conjunction with 263/823	*	*						0,00
			Not in conjunction with 264/823/827			*	*	*	*		0,00
			Not in conjunction with 823								0,00
	834	New Zealand specification		-	-	-	○	-	○	○	0,00
			Only in conjunction with U60				*		*	*	0,00
	835	South Korea specification		○	-	-	-	-	○	○	0,00
			Only in conjunction with 14U+21U+222+413+458+500+70B+847+877+889+P17+P55+P59+U37+239+634+827+986+989+B08+PBF+(U12/U26)						*		0,00
			Only in conjunction with 14U+21U+222+413+458+500+70B+847+877+889+P17+P55+P59+U37+239+634+827+986+989+B08+PBF+(U12/U26)							*	0,00
			Only in conjunction with 14U+21U+222+413+458+500+70B+847+877+889+P17+P55+P59+U37+239+634+827+986+989+B08+PBF+(U12/U26)	*							0,00
	836	Additional parts for Singapore		-	-	-	○	-	-	○	0,00
			Only in conjunction with 294+B08				*			*	0,00
			Only in conjunction with 922+294+B08								0,00
	840	Heat-insulating dark-tinted glass		●	●	●	●	●	●	●	315,00
			Not in conjunction with U50	*	*	*	*	*	*	*	0,00
			Only in conjunction with P59/950	*	*	*	*	*	*	*	0,00
			i.V.m. Code P55	○	○	○	○	○	○	-	0,00
			i.V.m. Code P60	-	-	-	-	-	-	○	0,00
			i.V.m. Code PSJ/PSN/PSQ	-	-	-	-	○	-	-	0,00
			i.V.m. Code PSJ/PSN/PSQ	-	-	-	-	-	-	○	0,00
			i.V.m. Code PSJ/PSN/PSQ	○	○	○	○	-	○	-	0,00
	847	3rd row of seats for 2 people		●	●	●	●	●	●	●	1.250,00
			Not in conjunction with 214A/567	*	*						0,00
			Not in conjunction with 214A/567/672			*	*	*	*		0,00
			Not in conjunction with 567/672							*	0,00
	852	Sensor system for anti-theft alarm system		-	-	-	-	-	●	●	147,00
			Not in conjunction with 882						*	*	0,00
			Only in conjunction with L						*	*	0,00
			Only in conjunction with P82						*	*	0,00
			i.V.m. Code 362	-	-	-	-	-	●	●	179,00
			i.V.m. Code P54/P82	-	-	-	-	-	○	○	0,00
	853	Advanced Sound System		●	●	●	●	●	●	●	326,00
			Not in conjunction with 810	*	*	*	*	*	*	*	0,00
			Only in conjunction with 22U	*	*	*	*	*	*	*	0,00
			i.V.m. Code PDC/PDD	-	-	-	-	-	-	-	0,00
			i.V.m. Code PDC/PDD	-	-	-	-	○	-	-	0,00
			i.V.m. Code PDC/PDD	○	○	○	○	-	○	○	0,00
	859	CENTRAL MEDIA DISPLAY		○	○	○	○	○	○	○	0,00
				-	-	-	-	-	-	-	683,00
	865	TV tuner Japan		●	●	-	-	-	-	●	945,00
			Only in conjunction with R	*	*					*	0,00
	871	HANDS-FREE ACCESS		○	○	○	○	○	○	○	0,00
			Only in conjunction with P17	*	*	*	*	*	*	*	0,00
	873	Heated front seats		●	●	●	●	●	●	●	336,00
			i.V.m. Code PAV	-	-	-	-	○	-	○	0,00
			i.V.m. Code PAV	○	○	○	○	-	○	-	0,00
			i.V.m. Code PSA/PSD/PSE/PSI	-	-	-	-	○	-	-	0,00
			i.V.m. Code PSJ/PSN/PSQ	-	-	-	-	-	-	○	0,00

N/A	Code	Equipment	Restrictions	247612 GLB 200 d	247613 GLB 200 d 4MATIC	247615 GLB 220 d 4MATIC	247687 GLB 200	247645 GLB 220 4MATIC	247647 GLB 250 4MATIC	247651 Mercedes-AMG GLB 35 4MATIC	Local Price excl.VAT
			i.V.m. Code PSA/PSD/PSE/PSI	○	○	○	○	-	○	-	0,00
			i.V.m. Code PSJ/PSN/PSQ	-	-	-	-	○	-	-	0,00
			i.V.m. Code PSJ/PSN/PSQ	○	○	○	○	-	○	-	0,00
	875	Heated windscreen washer system		○	○	○	○	○	○	○	0,00
			Only in conjunction with PAV	*	*	*	*	*	*	*	0,00
	877	Ambient lighting		○	○	○	○	○	○	○	0,00
			Not in conjunction with PDA	*	*	*	*	*	*	*	0,00
	882	Interior monitoring system		○	○	○	○	○	○	○	0,00
			Not in conjunction with 852						*	*	0,00
			Only in conjunction with P54/P82	*	*	*	*	*	*	*	0,00
	885	Increased anti-theft protection		○	○	○	○	○	○	○	0,00
	889	KEYLESS-GO		○	○	○	○	○	○	○	0,00
			Only in conjunction with P17	*	*	*	*	*	*	*	0,00
			i.V.m. Code P17	○	○	○	○	○	○	○	0,00
			i.V.m. Code P17	-	-	-	-	-	-	-	0,00
			i.V.m. Code PAD	○	○	○	○	○	○	-	0,00
			i.V.m. Code PAD	-	-	-	-	-	-	-	0,00
	888	Passive person presence reminder		○	○	○	○	○	○	○	0,00
	890	EASY-PACK tailgate		○	○	○	○	○	○	○	0,00
			Only in conjunction with PDA/PDB/P17	*	*	*	*	*	*	*	0,00
			i.V.m. Code P17	-	-	-	-	○	-	-	0,00
			i.V.m. Code P17	○	○	○	○	-	○	○	0,00
			i.V.m. Code P17	-	-	-	-	-	-	-	0,00
	897	Wireless charging system for mobile devices in the f		●	●	●	●	●	●	●	210,00
			i.V.m. Code PDB/PDC/PDD	-	-	-	-	-	-	-	0,00
			i.V.m. Code PDB/PDC/PDD	-	-	-	-	○	-	-	0,00
			i.V.m. Code PDB/PDC/PDD	○	○	○	○	-	○	○	0,00
	8R4	Complete set of 4 M+S winter wheels		-	-	-	-	-	-	○	0,00
			Only in conjunction with 652+PGP							*	0,00
			Only in conjunction with L							*	0,00
			i.V.m. S-Code 7S7	-	-	-	-	-	-	●	3.360,00
	913	Air conditioning preinstallation for hot countries		○	○	○	-	-	-	-	0,00
	916	Fuel tank with a capacity of 60 litres		-	\$	\$	-	○	\$	\$	0,00
	922	Reduced output engines		-	-	-	-	-	-	-	0,00
			Only in conjunction with R								0,00
	922U	Metallic paint high-tech silver		●	●	●	●	●	●	-	788,00
	922U			-	-	-	-	-	-	○	0,00
	926	Emission control system with EU4 technology		-	-	-	○	-	○	○	0,00
			Not in conjunction with 927						*		0,00
			Not in conjunction with 927/945				*		*		0,00
	927	EU6 emissions standard		○	○	○	○	○	○	○	0,00
			Not in conjunction with 926						*		0,00
			Not in conjunction with 926/945				*		*		0,00
			Not in conjunction with 945					*			0,00
	942	Load Compartment Package		●	●	●	●	●	●	●	158,00
			Only in conjunction with U35	*	*	*	*	*	*	*	0,00
			i.V.m. Code PSA/PSD/PSE/PSI	-	-	-	-	○	-	-	0,00
			i.V.m. Code PSJ/PSN/PSQ	-	-	-	-	-	-	○	0,00
			i.V.m. Code PSA/PSD/PSE/PSI	○	○	○	○	-	○	-	0,00
			i.V.m. Code PSJ/PSN/PSQ	-	-	-	-	○	-	-	0,00
			i.V.m. Code PSJ/PSN/PSQ	○	○	○	○	-	○	-	0,00
	943	Toll payment system		●	●	-	●	●	●	●	210,00
	945	Emission control system China		-	-	-	○	○	-	○	0,00
			Not in conjunction with 926/927				*		*		0,00
			Not in conjunction with 927					*			0,00
	950	AMG Line		●	●	●	●	●	●	-	1.785,00
				-	-	-	-	-	-	\$	0,00

N/A	Code	Equipment	Restrictions	247612 GLB 200 d	247613 GLB 200 d 4MATIC	247615 GLB 220 d 4MATIC	247687 GLB 200	247645 GLB 220 4MATIC	247647 GLB 250 4MATIC	247651 Mercedes-AMG GLB 35 4MATIC	Local Price excl.VAT
			Includes codes 310+651A+725+772+(H62/03H/56H/H15)+(L6J/L6K)+U26							*	0,00
			Includes codes 310+651A+725+772+(H62/03H/56H/H15)+L5C+(RTF/RTG)+U26	*	*	*	*	*	*		0,00
			Only in conjunction with 772+(U28/PAD)								0,00
			Only in conjunction with 772+B63+(U28/PAD)	*	*	*	*	*	*		0,00
			Only in conjunction with 772+B63+U28								0,00
			i.V.m. Code PSJ/PSN/PSQ	-	-	-	-	○	-	-	0,00
			i.V.m. Code PSJ/PSN/PSQ	○	○	○	○	-	○	-	0,00
	960	Government version		-	-	●	-	-	-	-	63,00
			Only in conjunction with L			*					0,00
	968	COC document EU6 without registration certificate		○	○	○	○	○	○	○	0,00
			Not in conjunction with 232			*	*	*	*	*	0,00
			Not in conjunction with 263	*	*						0,00
			Not in conjunction with 263/264							*	0,00
			Not in conjunction with 264			*	*	*	*		0,00
			Not in conjunction with 687	*	*	*	*	*	*	*	0,00
			Not in conjunction with 762	*	*	*	*				0,00
			Not in conjunction with 762/763					*	*	*	0,00
			Not in conjunction with 969/981	*	*	*	*	*	*	*	0,00
			Only in conjunction with 351+986			*					0,00
			Only in conjunction with 927+351+986				*	*	*	*	0,00
			Only in conjunction with 927+986	*	*						0,00
	969	COC document EU6 with registration certificate part		○	○	○	○	○	○	○	0,00
			Not in conjunction with 232			*	*	*	*	*	0,00
			Not in conjunction with 687	*	*	*	*	*	*	*	0,00
			Not in conjunction with 762	*	*	*	*				0,00
			Not in conjunction with 762/763					*	*	*	0,00
			Not in conjunction with 968/981	*	*	*	*	*	*	*	0,00
			Only in conjunction with 351+986			*					0,00
			Only in conjunction with 927+351+986				*	*	*	*	0,00
			Only in conjunction with 927+986	*	*						0,00
	970U	Metallic paint spectral blue		●	●	●	●	●	●	-	788,00
	970U			-	-	-	-	-	-	○	0,00
	971	Diesel particulate filter		S	S	S	-	-	-	-	0,00
	973	Designation as owner-driver rental vehicle		○	○	○	○	○	○	○	0,00
	981	TÜV German Technical Inspection Authority - individ		○	○	○	○	○	○	○	0,00
			Not in conjunction with 968/969	*	*	*	*	*	*	*	0,00
	986	Identification label with VIN number		○	○	○	○	○	○	○	0,00
			Only in conjunction with 968/969/981	*	*	*	*	*	*	*	0,00
	989	Identification label under windshield		○	○	○	○	○	○	○	0,00
	993U	MANUFAKTUR paint MANUFAKTUR patagonia red m		●	●	●	●	●	●	-	1.050,00
	993U			-	-	-	-	-	-	○	262,50
	994	Exhibition vehicle (B-Trade fair)		○	○	○	○	○	○	○	0,00
			Not in conjunction with 997	*	*	*	*	*	*	*	0,00
	997	Display vehicle for exhibitions (motor show veh.)		○	○	○	○	○	○	○	0,00
			Not in conjunction with 994	*	*	*	*	*	*	*	0,00
	B01	Mild Hybrid Antrieb		-	-	-	○	○	○	○	0,00
	B08	Fanfare horn		○	○	○	○	○	○	○	0,00
			Not in conjunction with P59/950			*	*	*	*		0,00
	B12	Tyre-change toolkit		●	●	●	●	●	●	●	32,00
			Only in conjunction with 672			*	*	*	*	*	0,00
	B27	Omission of roof rails		○	○	○	○	-	○	○	0,00
			Not in conjunction with 413	*	*	*	*		*	*	0,00
			Not in conjunction with 720/725	*	*	*	*		*	*	0,00
			Only in conjunction with P55/P59	*	*	*	*		*	*	0,00
	B51	TIREFIT		LS	LS	LS	LS	LS	LS	LS	0,00
			Not in conjunction with R66	*	*	*	*	*	*	*	0,00
			i.V.m. Code PSA/PSD/PSE/PSI	-	-	-	-	○	-	-	0,00

N/A	Code	Equipment	Restrictions	247612 GLB 200 d	247613 GLB 200 d 4MATIC	247615 GLB 220 d 4MATIC	247687 GLB 200	247645 GLB 220 4MATIC	247647 GLB 250 4MATIC	247651 Mercedes-AMG GLB 35 4MATIC	Local Price excl.VAT
			i.V.m. Code PSA/PSD/PSE/PSI	○	○	○	○	-	○	-	0,00
			i.V.m. Code PSJ/PSN/PSQ	-	-	-	-	○	-	○	0,00
			i.V.m. Code PSJ/PSN/PSQ	○	○	○	○	-	○	-	0,00
	B59	AMG DYNAMIC SELECT		-	-	-	-	-	-	\$	0,00
	B59	DYNAMIC SELECT		\$	\$	\$	\$	\$	\$	-	0,00
	B63	Sporty engine sound		○	○	○	○	○	-		0,00
			Only in conjunction with 950	*	*	*	*	*	*	*	0,00
	E56	WINTER WHEELS FITTED BY THE SERVICE PROVIDER		○	○	○	○	○	○	○	0,00
			Only in conjunction with 652	*	*	*	*	*	*	*	0,00
			Only in conjunction with L	*	*	*	*	*	*	*	0,00
	H15	Black open-pore linden wood trim		●	●	●	●	●	●	●	273,00
			Only in conjunction with P59/950	*	*	*	*	*	*	*	0,00
	H59	Carbon-fibre-look trim		-	-	-	\$	-	-	-	0,00
			Not in conjunction with 877				*				0,00
			Only in conjunction with L				*				0,00
	H62	Carbon-structure trim		○	○	○	○	○	○	\$	0,00
			Only in conjunction with 950	*	*	*	*	*	*	*	0,00
	K33	Extended automatic Re-start in traffic jams		○	○	○	○	○	○	○	0,00
			Only in conjunction with 365+P79							*	0,00
			Only in conjunction with P79								0,00
			Only in conjunction with P79+235+365	*	*	*	*	*	*	*	0,00
	K34	Route-based speed adaptation		○	○	○	○	○	○	○	0,00
			Only in conjunction with 365+P79	*	*	*	*	*	*	*	0,00
			Only in conjunction with P79								0,00
	L	Left-hand drive		○	○	○	○	○	○	○	0,00
			Only in conjunction with 945				*				0,00
	L3E	Leather multifunction sports steering wheel		○	○	○	○	○	○	-	0,00
			Not in conjunction with 950								0,00
			Not in conjunction with 950/P00	*	*	*	*	*	*	*	0,00
			Only in conjunction with 428	*	*	*	*	*	*	*	0,00
	L3M	Multifunction sports steering wheel in ARTICO man-		○	○	○	○	○	○	-	0,00
			Only in conjunction with P00+428	*	*	*	*	*	*	*	0,00
	L5C	Multifunction sports steering wheel in nappa leather		○	○	○	○	○	○	-	0,00
			Only in conjunction with 950+431	*	*	*	*	*	*	*	0,00
	L6J	AMG Performance steering wheel in nappa leather		-	-	-	-	-	-	○	0,00
	L6K	AMG Performance steering wheel in nappa leather /		-	-	-	-	-	-	●	515,00
	P00	Leather-free Package		○	○	○	○	○	○	-	0,00
			Includes codes L3M	*	*	*	*	*	*	*	0,00
			Not in conjunction with 950/P34/P79/PAV	*	*	*	*	*	*	*	0,00
	P17	KEYLESS-GO Comfort Package		○	○	○	○	○	○	○	0,00
			Includes codes 871+889+890	*	*	*	*	*	*	*	0,00
			Not in conjunction with PDA	*	*	*	*	*	*	*	0,00
			Only in conjunction with 871+889	*	*	*	*	*	*	*	0,00
			Only in conjunction with 871+889+890	*	*	*	*	*	*	*	0,00
			i.V.m. Code PAD	-	-	-	-	-	-	-	0,00
	P34	Leather Package		●	●	●	●	●	●	-	1.775,00
			Only in conjunction with 873+(211A/214A)+P59	*	*	*	*	*	*	*	0,00
	P39	AMG Leather Package		●	●	●	●	●	●	●	1.050,00
			Only in conjunction with 873+(211A/277A)							*	0,00
			Only in conjunction with 873+(211A/277A)+950	*	*	*	*	*	*	*	0,00
	P44	Parking package with reversing camera		●	●	●	●	●	●	●	641,00
			Includes codes 218+235	*	*	*	*	*	*	*	0,00
			Not in conjunction with P47	*	*	*	*	*	*	*	0,00
			Not in conjunction with PDA/PDD						*		0,00
			Not in conjunction with PDD	*	*	*	*	*	*	*	0,00
			Only in conjunction with 218							*	0,00
			Only in conjunction with 218+235	*	*	*	*	*	*	*	0,00

N/A	Code	Equipment	Restrictions	247612	GLB 200 d	247613	GLB 200 d 4MATIC	247615	GLB 220 d 4MATIC	247687	GLB 200	247645	GLB 220 4MATIC	247647	GLB 250 4MATIC	247651	Mercedes-AMG GLB 35 4MATIC	Local Price excl.VAT
			i.V.m. Code PDA/PDB/PDC/PDD	-	-	-	-	-	-	-	-	-	-	-	-	-	0,00	
			i.V.m. Code PDA/PDB/PDC/PDD	○	○	○	○	○	○	○	○	○	○	○	○	○	0,00	
	P47	Parking Package with 360-degree camera		●	●	●	●	●	●	●	●	●	●	●	●	●	1.423,00	
			Includes codes 235+501	*	*	*	*	*	*	*	*	*	*	*	*	*	0,00	
			Not in conjunction with P44	*	*	*	*	*	*	*	*	*	*	*	*	*	0,00	
			Only in conjunction with (P59/950)+234+235+501	*	*	*	*	*	*	*	*	*	*	*	*	*	0,00	
			Only in conjunction with 234+501												*	0,00		
			Only in conjunction with 501												*	0,00		
			i.V.m. Code PDA/PDB/PDC	●	●	●	●	●	●	●	●	●	●	●	●	●	431,00	
			i.V.m. Code PDD	-	-	-	-	-	-	-	-	-	-	-	-	-	0,00	
			i.V.m. Code PDD	○	○	○	○	○	○	○	○	○	○	○	○	○	0,00	
	P49	Mirror Package		●	●	●	●	●	●	●	●	●	●	●	●	●	441,00	
			Includes codes 249+500											*	*	0,00		
			Includes codes 500	*	*	*	*	*	*	*	*	*	*	*	*	*	0,00	
			Only in conjunction with (249/252)+500											*	*	0,00		
			Only in conjunction with 252+500	*	*	*	*	*	*	*	*	*	*	*	*	*	0,00	
			i.V.m. Code PDA/PDB/PDC/PDD	-	-	-	-	-	-	-	-	-	-	-	-	-	0,00	
			i.V.m. Code PDA/PDB/PDC/PDD	○	○	○	○	○	○	○	○	○	○	○	○	○	0,00	
	P53	AIR-QUALITY package		●	-	-	-	●	●	●	●	●	●	●	●	●	158,00	
			Includes codes 426+581+859	*						*	*	*	*	*	*	*	0,00	
			Includes codes 581+859						*	*	*	*	*	*	*	*	0,00	
			Only in conjunction with 580/581					*	*	*	*	*	*	*	*	*	0,00	
			Only in conjunction with 581	*								*	*	*	*	*	0,00	
	P54	GUARD 360° Vehicle protection		*	*	*	*	*	*	*	*	*	*	*	*	*	0,00	
				●	●	●	●	●	●	●	●	●	●	●	●	●	431,00	
			Includes codes 551+882	*	*	*	*	*	*	*	*	*	*	*	*	*	0,00	
			Not in conjunction with P82	*	*	*	*	*	*	*	*	*	*	*	*	*	0,00	
			Only in conjunction with 551+882	*	*	*	*	*	*	*	*	*	*	*	*	*	0,00	
			i.V.m. Code 362	●	●	●	●	●	●	●	●	●	●	●	●	●	462,00	
	P55	Night Package		●	●	●	●	●	●	●	●	●	●	●	●	-	473,00	
			Includes codes 720+840	*	*	*	*	*	*	*	*	*	*	*	*	*	0,00	
			Only in conjunction with (P59/950)+840	*	*	*	*	*	*	*	*	*	*	*	*	*	0,00	
			Only in conjunction with P59/950													*	0,00	
			i.V.m Code PSJ/PSN/PSQ	-	-	-	-	-	-	-	-	-	-	-	-	-	158,00	
			i.V.m Code PSJ/PSN/PSQ	●	●	●	●	●	●	●	●	●	●	●	●	●	158,00	
	P59	PROGRESSIVE		LS	LS	LS	LS	LS	LS	LS	LS	LS	LS	LS	LS	-	0,00	
			Includes codes (01R/25R/27R/52R/R38/R62/R74/RTG/RVT/RVU)+287+310+(51U/58U)+(55H/03H/56H)	*	*	*	*	*	*	*	*	*	*	*	*	*	0,00	
			Includes codes (01R/25R/27R/52R/R38/R62/R74/RTG/RVT/RVU)+															

[illegible]

N/A	Code	Equipment	Restrictions	247612 GLB 200 d	247613 GLB 200 d 4MATIC	247615 GLB 220 d 4MATIC	247687 GLB 200	247645 GLB 220 4MATIC	247647 GLB 250 4MATIC	247651 Mercedes-AMG GLB 35 4MATIC	Local Price excl.VAT
			i.V.m. Code PSD/PSE	○	○	○	○	○	○	-	0,00
	PDB	Advanced Plus Package		●	●	●	●	●	●	-	745,50
				-	-	-	-	-	-	○	0,00
			Includes codes 321+458+859+877+(P44/P47)+P49							*	0,00
			Includes codes 321+458+859+877+(P44/P47)+P49+P59	*	*	*	*	*	*		0,00
			Includes codes 458+859+877+(P44/P47)+P59								0,00
			Only in conjunction with				*				0,00
			Only in conjunction with (00U/33U/34U/37U)+(P44/P47)+73B+897							*	0,00
			Only in conjunction with (00U/33U/34U/37U)+(P59/950)+321+458+877+P17+(P44/P47)+P49+U22+73B+897	*					*		0,00
			Only in conjunction with (00U/33U/34U/37U)+(P59/950)+321+458+877+P17+(P44/P47)+P49+U22+897		*	*		*			0,00
			Only in conjunction with (P44/P47)+897+(00U/37U)								0,00
			Only in conjunction with (P59/950)+321+877+P17+(P44/P47)+897								0,00
			i.V.m. Code PSI/PSJ	○	○	○	○	○	○	○	0,00
	PDC	Premium Package		●	●	●	●	●	●	●	4.584,00
				■	■	■	■	■	■	■	1.911,00
			Includes codes 321+400+458+581+73B+859+877+897+P17+(P44/P47)+P49+(U45/PBF)							*	0,00
			Includes codes 321+400+458+581+73B+859+877+897+P17+(P44/P47)+P49+P59					*			0,00
			Includes codes	*	*	*	*	*	*		0,00
			Includes codes 321+400+458+581+73B+859+877+897+P17+(P44/P47)+P49+P59+U45								0,00
			Includes codes 321+400+458+581+859+877+897+P17+(P44/P47)+P49+P59+U45								0,00
			Only in conjunction with (00U/33U/34U)+(P59/950)+321+458+581+(853/810)+877+P17+(P44/P47)+P49+(PBF/PBG)+U22+U45+897+234				*				0,00
			Only in conjunction with (00U/33U/34U/37U)+(P59/950)+321+458+581+(853/810)+877+P17+(P44/P47)+P49+(PBF/PBG)+U22+U45+897+234		*	*		*			0,00
			Only in conjunction with (00U/33U/34U/37U)+(P59/950)+321+458+581+(853/810)+877+P17+(P44/P47)+P49+(PBF/PBG)+U22+U45+897+234								0,00
			Only in conjunction with 73B+(00U/33U/34U/37U)+(P59/950)+321+458+581+(853/810)+877+P17+(P44/P47)+P49+(PBF/PBG)+U22+U45+897+234	*					*		0,00
			Only in conjunction with 73B+(00U/33U/34U/37U)+(P59/950)+321+458+581+(853/810)+877+P17+(P44/P47)+P49+PBG+U22+U45+897+234								0,00
			Only in conjunction with 73B+U19+(00U/33U/34U/37U)+581+(853/810)+(P44/P47)+(PBF/PBG)+U45+897+234							*	0,00
			i.V.m. Code U19	●	●	●	●	●	●	-	4.930,00
	PDC		i.V.m. Code U19	-	-	-	-	-	-	LS	0,00
			i.V.m. Code PBF+U19	●	●	●	●	●	●	■	4.841,00
			i.V.m. Code PBF+U19	■	■	■	■	■	■	■	2.169,00
			i.V.m. Code PBF	●	●	●	●	●	●	■	4.494,00
			i.V.m. Code PBF	■	■	■	■	■	■	■	1.822,00
	PDC		i.V.m. S-Code 8P3+PBG	●	●	●	●	●	●	-	1.485,75
			i.V.m. S-Code 8P3+PBG	-	-	-	-	-	-	●	1.633,00
			i.V.m. Code PSN	●	●	●	●	●	●	●	0,00
	PDD	Premium Plus Package		●	●	●	●	●	●	■	8.091,00
				■	■	■	■	■	■	■	5.418,00
			Includes codes 242+321+400+458+581+642+73B+77B+(853/810)+859+877+897+P17+P47+P49+(PBG/P							*	0,00
			Includes codes 242+321+400+458+581+642+73B+77B+(853/810)+859+877+897+P17+P47+P49+P59+(PBG/PBF)+U22+U45	*	*	*	*	*	*		0,00
			Includes codes 242+321+400+458+581+642+73B+77B+(853/810)+859+877+897+P17+P47+P49+P59+PBG								0,00
			Includes codes 242+321+400+458+581+77B+(853/810)+859+877+897+P17+P47+P49+P59+PBG+U22+U								0,00
			Includes codes 321+400+458+581+73B+77B+(853/810)+859+877+897+P17+P47+P49+(PBG/PBF)+U22+							*	0,00
			Includes codes 321+400+458+581+73B+77B+(853/810)+859+877+897+P17+P47+P49+P59+(PBG/PBF)+					*			0,00
			Includes codes 321+400+458+581+73B+77B+(853/810)+859+877+897+P17+P47+P49+P59+(PBG/PBF)+	*	*	*	*		*		0,00
			Only in conjunction with (241/242)+321+458+463+73B+77B+(853/810)+877+950+P17+P49+(PBF/PBG)+U22+U45+581+586+(641/642)+897+P47+(00U/33U/34U/37U)	*							0,00
			Only in conjunction with (241/242)+321+458+463+73B+77B+(853/810)+877+950+P17+P49+(PBF/PBG)+U22+U45+586+581+(-632/641)+897+P47+(00U/33U/34U/37U)						*		0,00
			Only in conjunction with (241/242)+321+458+463+77B+(853/810)+877+950+P17+P49+(PBF/PBG)+U22+U45+581+586+(641/642)+897+P47+(00U/33U/34U)				*				0,00

N/A	Code	Equipment	Restrictions	247612 GLB 200 d	247613 GLB 200 d 4MATIC	247615 GLB 220 d 4MATIC	247687 GLB 200	247645 GLB 220 4MATIC	247647 GLB 250 4MATIC	247651 Mercedes-AMG GLB 35 4MATIC	Local Price excl.VAT
			Includes codes {00U/33U/34U}+70B+{840/U50}+873+942+{B51/R66}+PBG+PDC							*	0,00
			Only in conjunction with PDC+873+{B51/R66}+{00U/33U/34U}+PBG+942+70B+{840/U50}							*	0,00
N/A	PSQ	AMG Line Premium Plus		●	●	●	●	●	●	-	12.464,00
			Includes codes {00U/33U/34U}+70B+{840/U50}+873+942+950+{B51/R66}+PBG+PDD	*	*	*	*	*	*		0,00
			Only in conjunction with	*	*	*	*	*	*		0,00
			i.v.m Code U19	●	●	●	●	●	●	-	12.810,00
N/A	PSQ	Premium Plus		-	-	-	-	-	-	●	6.999,00
			Includes codes {00U/33U/34U}+70B+{840/U50}+873+942+{B51/R66}+PBG+PDD							*	0,00
			Only in conjunction with PDD+873+{B51/R66}+{00U/33U/34U}+PBG+942+70B+{840/U50}							*	0,00
N/A	R	Right-hand drive		●	●	●	●	●	●	●	1.113,00
	R01	Summer tyres		○	○	○	○	○	○	○	0,00
			Only in conjunction with 25R/(01R/52R/R38/R74)+-R66/(01R/52R/R38/R74)+R66/(R58/27R)+-					*			0,00
			Only in conjunction with 25R/(01R/52R/R38/R74)+-R66/(01R/52R/R38/R74)+R66/(R58/27R)+-				*				0,00
			Only in conjunction with 25R/(01R/52R/R38/R74)+-R66/(01R/52R/R38/R74)+R66/(R58/27R)+-	*	*	*			*		0,00
			Only in conjunction with 27R+-R66/RVT/RVU/RTF/RTG								0,00
			Only in conjunction with RVL+-R66/RTH/RVZ/-RTH/RVL/RVZ)							*	0,00
	R02	All-season tyres		-	-	-	-	-	●	●	158,00
			Not in conjunction with 652						*	*	0,00
			Only in conjunction with R66+{27R/01R/52R/R38/R74/RTF/RTG}						*		0,00
			Only in conjunction with R66+{RTH/RVL/RVZ}						*		0,00
	R03	Sports tyres		●	●	●	●	●	●	-	315,00
			Only in conjunction with RTF	*	*	*	*	*	*		0,00
	R38	45.7 cm (18-inch) 5-twin-spoke light-alloy wheels		●	●	●	●	●	●	-	630,00
			Not in conjunction with 950	*	*	*	*	*	*		0,00
			Only in conjunction with R01	*	*	*	*	*	*		0,00
			Only in conjunction with R01/R02+R66						*		0,00
			Only in conjunction with R02+R66								0,00
			i.V.m. Code (P55+P59)/P59	○	○	○	○	○	○	-	0,00
	R58	48.3 cm (19") 10-spoke light-alloy wheels		-	-	-	●	●	-	-	1.103,00
			Only in conjunction with L				*	*			0,00
			Only in conjunction with P59				*	*			0,00
			i.V.m. Code P55/P59	-	-	-	●	●	-	-	473,00
	R62	43.2 cm (17-inch) 5-twin-spoke light-alloy wheels		○	○	○	○	○	○	-	0,00
			Not in conjunction with 950/P55/PAD	*			*	*			0,00
			Not in conjunction with 950/P55/PAD/847		*	*			*		0,00
	R66	Run-flat tyres		●	●	●	●	●	●	●	231,00
			Not in conjunction with 25R/R03/645+{R58/RTF}				*	*			0,00
			Not in conjunction with 25R/R03/645+RTF	*	*	*					0,00
			Not in conjunction with 25R/R03/645+RTF/R01						*		0,00
			Not in conjunction with B51	*	*	*	*	*	*	*	0,00
			Not in conjunction with R01/RWX/RWY							*	0,00
			Only in conjunction with R01+{27R/01R/52R/R38/R74/RTF/RTG}	*	*	*					0,00
			Only in conjunction with R01+{R58/27R/01R/52R/R38/R74/RTF/RTG}				*	*			0,00
			Only in conjunction with R02+{27R/01R/52R/R38/R74/RTF/RTG}						*		0,00
			Only in conjunction with								0,00
			Only in conjunction with R02+{RTH/RVL/RVZ}							*	0,00
			i.V.m. Code PSA/PSD/PSE/PSI	●	●	●	●	●	●	●	179,00
			i.V.m. Code PSJ/PSN/PSQ	●	●	●	●	●	●	●	179,00
	R74	45.7 cm (18-inch) 5-twin-spoke light-alloy wheels		●	●	●	●	●	●	-	630,00
			Not in conjunction with P55/950	*	*	*	*	*	*		0,00
			i.V.m. Code P59	○	○	○	○	○	○	-	0,00
	R88	6-double-spoke light-alloy wheel 43,2 cm (17")		-	-	-	-	●	-	-	1.103,00
			Not in conjunction with 950/R66					*			0,00
			Only in conjunction with R01					*			0,00
			i.V.m. Code P59/P55	-	-	-	-	●	-	-	473,00
	RTF	48.3 cm (19-inch) AMG 5-twin-spoke light-alloy wheel		○	○	○	○	○	○	-	0,00

N/A	Code	Equipment	Restrictions	247612 GLB 200 d	247613 GLB 200 d 4MATIC	247615 GLB 220 d 4MATIC	247687 GLB 200	247646 GLB 220 4MATIC	247647 GLB 250 4MATIC	247651 Mercedes-AMG GLB 35 4MATIC	Local Price excl.VAT
			Not in conjunction with P55	*	*	*	*	*	*		0,00
			Only in conjunction with 950	*	*	*	*	*	*		0,00
	RTG	48.3 cm (19-inch) AMG 5-twin-spoke light-alloy wheels		●	●	●	●	●	●	-	1.523,00
			i.V.m. Code (P55+P59)/P59/P55	●	●	●	●	●	●	-	893,00
			i.V.m. Code 950	●	●	●	●	●	●	-	473,00
			i.V.m. Code P55+950	○	○	○	○	○	○	-	0,00
	RTH	48.3 cm (19-inch) AMG 5-twin-spoke light-alloy wheels		-	-	-	-	-	-	●	0,00
			Only in conjunction with R01+-R66/R02+R66							*	0,00
	RTW	50.8 cm (20-inch) AMG 5-twin-spoke light-alloy wheels		-	-	-	-	-	-	●	1.050,00
			Only in conjunction with R01							*	0,00
	RTX	50.8 cm (20-inch) AMG 5-twin-spoke light-alloy wheels		-	-	-	-	-	-	●	1.050,00
	RVL	48.3 cm (19-inch) AMG 10-spoke light-alloy wheels		-	-	-	-	-	-	●	578,00
	RVT	50.8 cm (20-inch) AMG multi-spoke alloy wheels		●	●	●	●	●	●	-	2.048,00
			Not in conjunction with U28			*					0,00
			i.V.m. Code (P55+P59)/P55/P59	●	●	●	●	●	●	-	1.628,00
			i.V.m. Code 950/ (950+P55)	●	●	●	●	●	●	-	1.365,00
	RVU	50.8 cm (20-inch) AMG multi-spoke alloy wheels		●	●	●	●	●	●	-	2.048,00
			Not in conjunction with P55+P59	*	*		*	*	*		0,00
			Not in conjunction with P55+P59/U28			*					0,00
			i.V.m. Code (P55+P59)/P55/P59	●	●	●	●	●	●	-	1.628,00
			i.V.m. Code 950/ (950+P55)	●	●	●	●	●	●	-	1.365,00
	RVZ	48.3 cm (19-inch) AMG 10-spoke light-alloy wheels		-	-	-	-	-	-	●	578,00
			Only in conjunction with R01+-R66/R02+R66							*	0,00
	RWX	53.3 cm (21-inch) AMG multi-spoke light-alloy wheels		-	-	-	-	-	-	●	1.260,00
	RWY	53.3 cm (21-inch) AMG multi-spoke light-alloy wheels		-	-	-	-	-	-	●	1.628,00
	U01	Status display for rear seat belts in instrument cluster		○	○	○	○	○	○	○	0,00
	U10	Automatic front passenger airbag deactivation		●	●	●	●	●	●	●	100,00
			Only in conjunction with 222					*			0,00
			i.V.m. S-Code 51B	○	○	○	○	○	○	○	0,00
	U12	Velour floor mats		○	○	○	○	○	○	-	0,00
			Not in conjunction with 950	*	*	*	*	*	*		0,00
			Not in conjunction with U26	*	*	*	*	*	*		0,00
	U17	Omission of MANUFAKTUR seat belts in red		-	-	-	-	-	-	○	0,00
			Not in conjunction with Y05							*	0,00
			Only in conjunction with 651A							*	0,00
	U19	MBUX augmented reality for navigation		●	●	●	●	●	●	●	410,00

N/A	Code	Equipment	Restrictions	247612 GLB 200 d	247613 GLB 200 d 4MATIC	247615 GLB 220 d 4MATIC	247687 GLB 200	247645 GLB 220 4MATIC	247647 GLB 250 4MATIC	247651 Mercedes-AMG GLB 35 4MATIC	Local Price excl.VAT
			Only in conjunction with PDC/PDD+P47	*	*	*	*	*	*	*	0,00
			i. V. m. PDC/PDD	○	○	○	○	○	○	○	0,00
	U22	4-way lumbar support		○	○	○	○	○	○	○	0,00
			Only in conjunction with 221				*	*			0,00
	U26	AMG floor mats		○	○	○	○	○	○	\$	0,00
			Not in conjunction with U12	*	*	*	*	*	*		0,00
			Only in conjunction with 950	*	*	*	*	*	*	*	0,00
	U27	Exterior door handles in chrome		-	-	-	-	-	-	-	53,00
			Not in conjunction with 889								0,00
	U28	Sports brake system		○	○	○	○	○	○	-	0,00
			Not in conjunction with U29	*	*	*	*	*	*	*	0,00
			Only in conjunction with 950	*	*	*	*	*	*	*	0,00
	U29	Braking system with larger brake discs on the front		○	○	○	○	○	○	-	0,00
			Not in conjunction with U28	*	*	*	*	*	*	*	0,00
			Only in conjunction with PAD	*	*	*	*	*	*	*	0,00
	U35	12 V socket		○	○	○	○	○	○	○	0,00
			Only in conjunction with 942	*	*	*	*	*	*	*	0,00
	U37	Front fog lamps		●	●	●	●	●	●	-	195,00
			Not in conjunction with 772/950	*	*	*	*	*	*	*	0,00
	U40	Partition net		●	●	●	●	●	●	●	158,00
	U41	Water separator and lubrication package		-	-	○	-	-	-	-	0,00
			Only in conjunction with R			*					0,00
	U45	AMG illuminated door sills with "AMG" lettering and		-	-	-	-	-	-	○	0,00
			Not in conjunction with PDB						*		0,00
	U45	Door sills with "Mercedes-Benz" lettering, illuminated		○	○	○	○	○	○	-	0,00
			Only in conjunction with PDC/PDD	*	*	*	*	*	*	*	0,00
	U50	Omission of heat-insulating dark-tinted glass		○	○	○	○	○	○	○	0,00
			Not in conjunction with 840	*	*	*	*	*	*	*	0,00
			Not in conjunction with P55	*	*	*	*	*	*	*	0,00
			Not in conjunction with P60							*	0,00
			Only in conjunction with P59/950	*	*	*	*	*	*	*	0,00
	U55	Multi-link axle		\$	\$	\$	\$	\$	\$	\$	0,00
	U59	Seat Comfort Package		○	○	○	○	○	○	○	0,00
	U60	Pedestrian protection		○	○	○	○	○	○	○	0,00
	U62	Light and Sight Package		○	○	○	○	○	○	○	0,00
			Includes codes 77B	*	*	*	*	*	*	*	0,00
	U70	red-painted brake callipers		-	-	-	-	-	-	●	336,00
	U79	BlueTEC diesel emission control system including Ad		○	○	○	-	-	-	-	0,00
	U80	115 V socket		-	-	-	-	-	●	●	121,00
	U88	AMG steering wheel buttons		-	-	-	-	-	-	○	0,00
	Y05	MANUFAKTUR seat belts in red		-	-	-	-	-	-	○	0,00
			Not in conjunction with U17							*	0,00
			Only in conjunction with 651A							*	0,00