

| | | | | GLB Offroader | | | | | | | Local Price excl.VAT |
|-----|------|--|--------------------------------------|------------------|-------------------------|-------------------------|----------------|-----------------------|-----------------------|-----------------------------------|----------------------|
| N/A | Code | Equipment | Restrictions | 247612 GLB 200 d | 247613 GLB 200 d 4MATIC | 247615 GLB 220 d 4MATIC | 247687 GLB 200 | 247645 GLB 220 4MATIC | 247647 GLB 250 4MATIC | 247651 Mercedes-AMG GLB 35 4MATIC | |
| | 00B | Owner's Manual and service information - Danish | | ○ | ○ | ○ | ○ | ○ | ○ | ○ | 0,00 |
| | 00U | Remote Services | | LS | LS | LS | LS | LS | LS | LS | |
| | | | Not in conjunction with 33U/34U | | | | * | | | | 0,00 |
| | | | Not in conjunction with 33U/34U/37U | * | * | * | | * | * | * | 0,00 |
| | | | Not in conjunction with 37U | | | | | | | | 0,00 |
| | | | Only in conjunction with 362 | | | * | * | * | * | * | 0,00 |
| | | | i.V.m. Code PSA/PSD/PSE/PSI | - | - | - | - | ○ | - | - | 0,00 |
| | | | i.V.m. Code PSA/PSD/PSE/PSI | ○ | ○ | ○ | ○ | - | ○ | - | 0,00 |
| | | | i.V.m. Code PSJ/PSN/PSQ | - | - | - | - | ○ | - | ○ | 0,00 |
| | | | i.V.m. Code PSJ/PSN/PSQ | ○ | ○ | ○ | ○ | - | ○ | - | 0,00 |
| | 01B | Owner's Manual and service information - Dutch | | ○ | ○ | ○ | ○ | ○ | ○ | ○ | 0,00 |
| | 01R | 45.7 cm (18-inch) 5-twin-spoke light-alloy wheels | | ● | ● | ● | ● | ● | ● | - | 630,00 |
| | | | Not in conjunction with 950 | * | * | * | * | * | * | * | 0,00 |
| | | | Only in conjunction with R01 | * | * | * | * | * | * | * | 0,00 |
| | | | Only in conjunction with R01/R02 | | | | | | * | | 0,00 |
| | | | Only in conjunction with R02 | | | | | | | | 0,00 |
| | | | i.V.m. Code P59 | ○ | ○ | ○ | ○ | ○ | ○ | - | 0,00 |
| | 01U | Preinstallation for Navigation Services | | ○ | ○ | ○ | ○ | ○ | ○ | ○ | 0,00 |
| | | | Only in conjunction with 362 | | | * | * | * | * | * | 0,00 |
| | | | Only in conjunction with PBF/PBG | * | * | * | * | * | * | * | 0,00 |
| | | | Only in conjunction with PBG | | | | | | | | 0,00 |
| | 01W | Mercedes-Benz Connect Package, 1 year | | ● | ● | ● | ● | ● | ● | ● | 126,00 |
| | | | Not in conjunction with 02W/03W | * | * | * | * | * | * | * | 0,00 |
| | | | Only in conjunction with L | * | * | * | * | * | * | * | 0,00 |
| | 02B | Owner's Manual and service information - German | | ○ | ○ | ○ | ○ | ○ | ○ | ○ | 0,00 |
| | 02W | Mercedes-Benz Connect Package, 2 years | | ● | ● | ● | ● | ● | ● | ● | 252,00 |
| | | | Not in conjunction with 01W/03W | * | * | * | * | * | * | * | 0,00 |
| | | | Only in conjunction with L | * | * | * | * | * | * | * | 0,00 |
| | 03B | Owner's Manual and service information - Russian | | ○ | ○ | ○ | ○ | ○ | ○ | ○ | 0,00 |
| | 03H | Brown open-pore lime wood trim | | ● | ● | ● | ● | ● | ● | ● | 273,00 |
| | | | Only in conjunction with 950/P34/P59 | * | * | * | * | * | * | * | 0,00 |
| | 03W | Mercedes-Benz Connect Package, 3 years | | ● | ● | ● | ● | ● | ● | ● | 378,00 |
| | | | Not in conjunction with 01W/02W | * | * | * | * | * | * | * | 0,00 |
| | | | Only in conjunction with L | * | * | * | * | * | * | * | 0,00 |
| | 04B | Owner's Manual and service information - Finnish | | ○ | ○ | ○ | ○ | ○ | ○ | ○ | 0,00 |
| | 05B | Owner's Manual and service information - English | | ○ | ○ | ○ | ○ | ○ | ○ | ○ | 0,00 |
| | 06B | Owner's Manual and service information - Italian | | ○ | ○ | ○ | ○ | ○ | ○ | ○ | 0,00 |
| | 07B | Owner's Manual and service information - French | | ○ | ○ | ○ | ○ | ○ | ○ | ○ | 0,00 |
| | 08B | Owner's Manual and service information - Spanish | | ○ | ○ | ○ | ○ | ○ | ○ | ○ | 0,00 |
| | 09B | Owner's Manual and service information - Portuguese | | ○ | ○ | ○ | ○ | ○ | ○ | ○ | 0,00 |
| | 101A | ARTICO man-made leather black | | ● | ● | ● | ● | ● | ● | - | 153,00 |
| | | | Only in conjunction with 7U2+P59 | * | * | * | * | * | * | * | 0,00 |
| | 104A | ARTICO man-made leather brown | | - | - | - | ● | ● | - | - | 258,00 |
| | | | Only in conjunction with 7U2+P59 | | | | * | * | | | 0,00 |
| | 105A | ARTICO man-made leather macchiato beige / black | | ● | ● | ● | ● | ● | ● | - | 258,00 |
| | | | Only in conjunction with 7U2+P59 | * | * | * | * | * | * | * | 0,00 |
| | 10B | Owner's Manual and service information - Swedish | | ○ | ○ | ○ | ○ | ○ | ○ | ○ | 0,00 |
| | 11B | Owner's Manual and service information - Arabic | | ○ | ○ | ○ | ○ | ○ | ○ | ○ | 0,00 |
| | 12B | Owner's Manual and service information - English USA/CAN | | - | - | - | - | - | ○ | ○ | 0,00 |
| | 13B | Owner's Manual and service information - Norwegian | | ○ | ○ | ○ | ○ | ○ | ○ | ○ | 0,00 |
| | 149U | polar white | | ● | ● | ● | ● | ● | ● | - | 289,00 |
| | 149U | | | - | - | - | - | - | - | ○ | 0,00 |

| | | | | | | | | | | | |
|--|------|---|--|----|----|----|----|----|----|----|----------|
| | 14B | Owner's Manual and service information - Greek | | ○ | ○ | ○ | ○ | ○ | ○ | ○ | 0,00 |
| | 14U | Smartphone integration | | ● | ● | ● | ● | ● | ● | ● | 315,00 |
| | | | Only in conjunction with 16U+17U | * | * | * | * | * | * | * | 0,00 |
| | 158A | ARTICO man-made leather sage grey / black | | ● | ● | ● | ● | ● | ● | ● | 153,00 |
| | | | Only in conjunction with 7U4+(P59/950) | * | * | * | * | * | * | * | 0,00 |
| | | | i.V.m. Code 950 | ○ | ○ | ○ | ○ | ○ | ○ | ○ | 0,00 |
| | 15B | Owner's Manual and service information - Turkish | | ○ | ○ | ○ | ○ | ○ | ○ | ○ | 0,00 |
| | 16B | Owner's Manual and service information - Polish | | ○ | ○ | ○ | ○ | ○ | ○ | ○ | 0,00 |
| | 16U | Apple CarPlay | | ○ | ○ | ○ | ○ | ○ | ○ | ○ | 0,00 |
| | | | Only in conjunction with 14U | * | * | * | * | * | * | * | 0,00 |
| | 17B | Owner's Manual and service information - Czech | | ○ | ○ | ○ | ○ | ○ | ○ | ○ | 0,00 |
| | 17U | Android Auto | | ○ | ○ | ○ | ○ | ○ | ○ | ○ | 0,00 |
| | | | Only in conjunction with 14U | * | * | * | * | * | * | * | 0,00 |
| | 18B | Owner's Manual and service information - English South America | | - | - | ○ | ○ | ○ | ○ | ○ | 0,00 |
| | 191U | cosmos black metallic | | ● | ● | ● | ● | ● | ● | ● | 788,00 |
| | 191U | | | - | - | - | - | - | - | ○ | 0,00 |
| | 197U | obsidian black | | - | - | - | ● | ● | - | - | 788,00 |
| | 19B | Owner's Manual and service information - French South America | | - | - | ○ | ○ | ○ | ○ | ○ | 0,00 |
| | 1P0 | Sonderpreis | | ○ | ○ | ○ | ○ | ○ | ○ | ○ | 0,00 |
| | 207 | Active Distance Assist DISTRONIC | | ● | ● | ● | ● | ● | ● | ● | 420,00 |
| | | | Not in conjunction with 239 | * | * | * | * | * | * | * | 0,00 |
| | | | Only in conjunction with 5B0 | * | * | * | * | * | * | * | 0,00 |
| | 20B | Owner's Manual and service information - Spanish South America | | - | - | ○ | ○ | - | ○ | ○ | 0,00 |
| | 20U | Preinstallation for digital key transfer | | LS | LS | LS | LS | LS | LS | LS | 0,00 |
| | | | Only in conjunction with 362 | - | - | * | * | * | * | * | 0,00 |
| | | | i.V.m. Code PSA/PSD/PSE | - | - | - | - | ○ | - | - | 0,00 |
| | | | i.V.m. Code PSI/PSJ/PSN/PSQ | - | - | - | - | ○ | - | - | 0,00 |
| | | | i.V.m. Code PSA/PSD/PSE | - | ○ | - | ○ | - | - | ○ | 0,00 |
| | | | i.V.m. Code PSI/PSJ/PSN/PSQ | ○ | - | ○ | - | - | ○ | - | 0,00 |
| | | | i.V.m. Code PSI/PSJ/PSN/PSQ | - | ○ | - | ○ | - | - | ○ | 0,00 |
| | | | i.V.m. Code PSA/PSD/PSE | ○ | - | ○ | - | - | ○ | - | 0,00 |
| | 211A | Leather black | | ○ | ○ | ○ | ○ | ○ | ○ | ○ | 0,00 |
| | | | Only in conjunction with 873+(P34/P39)+7U4 | * | * | * | * | * | * | * | 0,00 |
| | | | Only in conjunction with 873+P39 | | | | | | | * | 0,00 |
| | 213 | Direct-Steer system | | ○ | ○ | ○ | ○ | ○ | ○ | S | 0,00 |
| | | | Only in conjunction with 457 | * | * | * | * | * | * | * | 0,00 |
| | 214A | Rough leather / leather Bahia brown / black | | ● | ● | ● | ● | ● | ● | - | 105,00 |
| | | | Not in conjunction with 847 | * | * | * | * | * | * | * | 0,00 |
| | | | Only in conjunction with 873+P34+P59+7U4 | * | * | * | * | * | * | * | 0,00 |
| | 218 | Reversing camera | | ○ | ○ | ○ | ○ | ○ | ○ | ○ | 0,00 |
| | | | Not in conjunction with 501 | | | | | | | | 0,00 |
| | | | Not in conjunction with 501/235+P44 | * | * | * | * | * | * | * | 0,00 |
| | | | Only in conjunction with P44 | | | | | | | | 0,00 |
| | | | i.V.m. Code P44 | - | - | - | - | - | - | - | 0,00 |
| | 21B | Owner's Manual and service information - Portuguese South America | | - | - | ○ | ○ | ○ | ○ | ○ | 0,00 |
| | 21U | Dash cam | | ● | ● | ● | ● | ● | ● | ● | 210,00 |
| | | | Only in conjunction with (PBF/PBG)+(PDB/PDC/PDD)/365+(P44/P47) | | | | | | | * | 0,00 |
| | | | Only in conjunction with PBF/PBG/365+(P44/P47) | * | * | * | * | * | * | * | 0,00 |
| | | | Only in conjunction with PBG+(PDB/PDC/PDD) | | | | | | | | 0,00 |
| | | | Only in conjunction with PBG/365+(P44/P47) | | | | | | | | 0,00 |
| | 221 | Electrically adjustable front seat, left | | - | - | - | ○ | ○ | - | - | 0,00 |
| | | | Not in conjunction with 241 | | | | * | * | | | 0,00 |
| | | | Not in conjunction with 275 | | | | * | * | | | 0,00 |
| | | | Only in conjunction with L | | | | * | * | | | 0,00 |
| | | | Only in conjunction with U22 | | | | * | * | | | 0,00 |
| | 222 | Electrically adjustable front seat, right | | - | - | - | - | ● | - | - | 237,00 |
| | | | Not in conjunction with 242 | | | | | * | | | 0,00 |
| | | | Only in conjunction with 221 | | | | | * | | | 0,00 |
| | | | Only in conjunction with L | | | | | * | | | 0,00 |
| | 228 | Auxiliary heater | | ● | ● | ● | ● | ● | ● | ● | 1.155,00 |
| | | | Only in conjunction with L | * | * | * | * | * | * | * | 0,00 |
| | 22B | Owner's Manual and service information - Japanese | | ○ | ○ | - | - | - | - | ○ | 0,00 |
| | 22U | Pre-installation for MBUX Entertainment | | ○ | ○ | ○ | ○ | ○ | ○ | ○ | 0,00 |
| | | | Only in conjunction with 362 | | | * | * | * | * | * | 0,00 |
| | | | Only in conjunction with 810/853 | * | * | * | * | * | * | * | 0,00 |
| | 232 | Garage door opener (frequency range 284-390 MHz) | | - | - | ● | ● | ● | ● | ● | 237,00 |
| | | | Not in conjunction with 968/969 | | | | * | * | * | * | 0,00 |
| | | | Only in conjunction with P49 | | | | * | * | * | * | 0,00 |
| | 234 | Blind Spot Assist | | ● | ● | ● | ● | ● | ● | ● | 473,00 |
| | | | Only in conjunction with (P49/275)+273 | * | * | * | | | * | | 0,00 |
| | | | Only in conjunction with (P49/275/500)+273 | | | | * | * | | | 0,00 |
| | | | Only in conjunction with 273 | | | | | | * | | 0,00 |

| | | | | | | | | | | |
|-----|--|---|---|---|---|---|---|---|---|--------|
| | | i.V.m. Code PDC/PDD | - | - | - | - | - | - | - | 0,00 |
| | | i.V.m. Code PDC/PDD | ○ | ○ | ○ | ○ | ○ | ○ | ○ | 0,00 |
| | | i.V.m. Code P79 | - | - | - | - | - | - | - | 0,00 |
| | | i.V.m. Code P79 | ○ | ○ | ○ | ○ | ○ | ○ | ○ | 0,00 |
| 235 | Active Parking Assist with PARKTRONIC | | ● | ● | ● | ● | ● | ● | ● | 709,00 |
| | | Only in conjunction with P44/P47 | * | * | * | * | * | * | * | 0,00 |
| | | i.V.m. Code P44/P47 | ○ | ○ | ○ | ○ | ○ | ○ | ○ | 0,00 |
| 239 | Active Distance Assist DISTRONIC | | ● | ● | ● | ● | ● | ● | ● | 420,00 |
| | | Not in conjunction with 207/258 | * | * | * | * | * | * | * | 0,00 |
| | | Not in conjunction with 258 | | | | | | | | 0,00 |
| | | Not in conjunction with 440 | * | * | * | * | * | * | * | 0,00 |
| | | Only in conjunction with P79 | * | * | * | * | * | * | * | 0,00 |
| | | i.V.m. Code P79 | - | - | - | - | - | - | - | 0,00 |
| | | i.V.m. Code P79 | ○ | ○ | ○ | ○ | ○ | ○ | ○ | 0,00 |
| 238 | Owner's Manual and service information - simplified Chinese | | - | - | - | ○ | ○ | - | ○ | 0,00 |
| 241 | Power front left seat with memory function | | ● | ● | ● | ● | ● | ● | ● | 300,00 |
| | | Not in conjunction with 221 | | | | * | * | | | 0,00 |
| | | Only in conjunction with 275 | | | | | | | * | 0,00 |
| | | Only in conjunction with 275+U22 | * | * | * | * | * | * | * | 0,00 |
| | | Only in conjunction with R | * | * | * | * | * | * | * | 0,00 |
| | | i.V.m. Code PDD | - | - | - | - | ○ | - | - | 0,00 |
| | | i.V.m. Code PDD | - | - | - | - | - | - | ○ | 0,00 |
| | | i.V.m. Code PDD | ○ | ○ | ○ | ○ | - | ○ | - | 0,00 |
| 242 | Power front right seat with memory function | | ● | ● | ● | ● | ● | ● | ● | 300,00 |
| | | Not in conjunction with 222 | | | | | * | | | 0,00 |
| | | Only in conjunction with 275 | | | | | | | * | 0,00 |
| | | Only in conjunction with 275+U22 | * | * | * | * | * | * | * | 0,00 |
| | | Only in conjunction with L | * | * | * | * | * | * | * | 0,00 |
| | | i.V.m. Code PDD | - | - | - | - | ○ | - | - | 0,00 |
| | | i.V.m. Code PDD | - | - | - | - | - | - | ○ | 0,00 |
| | | i.V.m. Code PDD | ○ | ○ | ○ | ○ | - | ○ | - | 0,00 |
| 243 | Active Lane Keeping Assist | | ● | ● | ● | ● | ● | ● | ● | 473,00 |
| | | i.V.m. S-Code 51B | ○ | ○ | ○ | ○ | ○ | ○ | ○ | 0,00 |
| | | i.V.m. Code P79 | - | - | - | - | - | - | - | 0,00 |
| | | i.V.m. Code P79 | ○ | ○ | ○ | ○ | ○ | ○ | ○ | 0,00 |
| 249 | Automatically dimming driver's side door mirror | | - | - | - | - | - | ○ | ○ | 0,00 |
| | | Not in conjunction with 252 | | | | | | * | * | 0,00 |
| | | Only in conjunction with L | | | | | | * | * | 0,00 |
| | | Only in conjunction with P49 | | | | | | * | | 0,00 |
| 248 | Owner's Manual and service information - traditional Chinese | | ○ | ○ | ○ | ○ | ○ | ○ | ○ | 0,00 |
| 252 | Automatically dimming rear-view mirror | | ○ | ○ | ○ | ○ | ○ | ○ | ○ | 0,00 |
| | | Not in conjunction with 249 | | | | | | * | * | 0,00 |
| | | Only in conjunction with P49 | * | * | * | * | * | * | * | 0,00 |
| 256 | AMG Track Pace | | - | - | - | - | - | - | ● | 263,00 |
| | | Only in conjunction with 365 | | | | | | | * | 0,00 |
| 258 | Active Brake Assist | | ○ | ○ | ○ | ○ | ○ | ○ | ○ | 0,00 |
| | | Not in conjunction with 239 | * | * | * | * | * | * | * | 0,00 |
| | | Only in conjunction with -B01/5B0 | | | | * | | | | 0,00 |
| | | Only in conjunction with 5B0 | | | | | * | * | | 0,00 |
| 25B | Owner's Manual and service information - Korean | | ○ | - | - | - | - | ○ | ○ | 0,00 |
| 25R | 43.2 cm (17-inch) 5-twin-spoke light-alloy wheels | | ○ | ○ | ○ | ○ | ○ | ○ | - | 0,00 |
| | | Not in conjunction with R66/U28/U29/950 | * | | | * | * | | | 0,00 |
| | | Not in conjunction with R66/U28/U29/950/847 | | * | * | * | * | * | | 0,00 |
| | | Only in conjunction with R01 | * | * | * | * | * | * | * | 0,00 |
| 260 | Deletion of model plate on boot lid | | ○ | ○ | ○ | ○ | ○ | ○ | ○ | 0,00 |
| 261 | Omission of badge on the wings | | - | - | - | - | - | - | ○ | 0,00 |
| 263 | Number plate mounting for Asia / Mexico | | ○ | ○ | - | - | - | - | ○ | 0,00 |
| | | Not in conjunction with 264/823/827/831 | | | | | | | * | 0,00 |
| | | Not in conjunction with 823/831 | * | * | | | | | | 0,00 |
| 264 | Number plate mounting for USA/CAN | | - | - | ○ | ○ | ○ | ○ | ○ | 0,00 |
| | | Not in conjunction with 263/823/827/831 | | | | | | | * | 0,00 |
| | | Not in conjunction with 823/827/831 | | | * | * | * | * | * | 0,00 |
| 266 | Active Steering Assist | | ○ | ○ | ○ | ○ | ○ | ○ | ○ | 0,00 |
| | | Only in conjunction with P79 | * | * | * | * | * | * | * | 0,00 |
| 268 | Owner's Manual and service information - Chinese Taiwan | | - | - | - | ○ | - | - | ○ | 0,00 |
| 270 | GPS aerial | | S | S | S | S | S | S | S | 0,00 |
| 273 | Exit warning function | | ○ | ○ | ○ | ○ | ○ | ○ | ○ | 0,00 |
| | | Only in conjunction with 234 | * | * | * | * | * | * | * | 0,00 |
| 275 | Driver's seat, electrically adjustable with memory function | | ● | ● | ● | ● | ● | ● | ● | 363,00 |
| | | Only in conjunction with (7U2/7U4)+U22 | * | * | * | * | * | * | * | 0,00 |
| | | i.V.m. Code PDD | - | - | - | - | ○ | - | - | 0,00 |

| | | | | | | | | | | | |
|------|---|--|-----------------|---|---|---|---|---|---|---|----------|
| | | | i.V.m. Code PDD | - | - | - | - | - | - | 0 | 0,00 |
| | | | i.V.m. Code PDD | 0 | 0 | 0 | 0 | - | 0 | - | 0,00 |
| 277A | Leather, two-tone red pepper / black | | | • | • | • | • | • | • | • | 105,00 |
| | | Only in conjunction with 873+P39 | | | | | | | | * | 0,00 |
| | | Only in conjunction with 873+P39+950+7U4 | | * | * | * | * | * | * | * | 0,00 |
| 27B | Owner's Manual and service information - Spanish Mexico | | | - | - | - | - | 0 | - | 0 | 0,00 |
| 27R | 48.3 cm (19-inch) 5-twin-spoke light-alloy wheels | | | • | • | • | • | • | • | - | 1.103,00 |
| | | Not in conjunction with 950 | | * | * | * | * | * | * | * | 0,00 |
| | | i.V.m. Code P55/P59 | | • | • | • | • | • | • | - | 473,00 |
| 286 | Luggage net on driver's and front pass. backrest | | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0,00 |
| 287 | Folding rear seat backrests | | | S | S | S | S | S | S | S | 0,00 |
| 293 | Sidebags in rear | | | • | • | • | • | • | • | • | 394,00 |
| | | Not in conjunction with 413+550+847+(810/853)+890+U40 | | | * | * | | | | | 0,00 |
| 294 | Knee airbag | | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0,00 |
| | | Only in conjunction with 497 | | | | | * | * | * | * | 0,00 |
| 299 | PRE-SAFE® system | | | • | • | • | • | • | • | • | 347,00 |
| | | i.V.m. Code P79 | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0,00 |
| 30B | Owner's Manual and service information - Slovenian | | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0,00 |
| 310 | Double cup holder | | | S | S | S | S | S | S | S | 0,00 |
| 311A | ARTICO man-made leather / Bertrix fabric black | | | 0 | 0 | 0 | 0 | 0 | 0 | - | 0,00 |
| | | Not in conjunction with 950 | | * | * | * | * | * | * | * | 0,00 |
| 318A | ARTICO man-made leather / Bertrix fabric sage grey / black | | | • | • | • | • | • | • | - | 105,00 |
| | | Only in conjunction with 7U2+P59 | | * | * | * | * | * | * | * | 0,00 |
| 31B | Owner's Manual and service information - Hungarian | | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0,00 |
| 32B | Owner's Manual and service information - Bulgarian | | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0,00 |
| 32U | Sound personalisation | | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0,00 |
| | | Only in conjunction with 810 | | * | * | * | * | * | * | * | 0,00 |
| 331 | Back-illuminated trim-part | | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0,00 |
| | | Only in conjunction with 56H | | * | * | * | * | * | * | * | 0,00 |
| 33B | Owner's Manual and service information - Romanian | | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0,00 |
| 33U | Remote Services Plus | | | • | • | • | • | • | • | • | 158,00 |
| | | Not in conjunction with 00U/34U | | | | | * | | | | 0,00 |
| | | Not in conjunction with 00U/34U/37U | | * | * | * | * | * | * | * | 0,00 |
| | | Only in conjunction with 362 | | | | * | * | * | * | * | 0,00 |
| | | i.V.m. Code PSA/PSD/PSE/PSI | | • | • | • | • | • | • | - | 53,00 |
| | | i.V.m. Code PSJ/PSN/PSQ | | - | - | - | - | - | - | • | 53,00 |
| | | i.V.m. Code PSJ/PSN/PSQ | | • | • | • | • | • | • | - | 53,00 |
| 345 | Windscreen wipers with rain sensor | | | S | S | S | S | S | S | S | 0,00 |
| 34B | Owner's Manual and service information - Croatian | | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0,00 |
| 34U | Remote Services Premium | | | • | • | • | • | • | • | • | 263,00 |
| | | Not in conjunction with 00U/33U | | * | * | * | * | * | * | * | 0,00 |
| | | Only in conjunction with 362 | | | | * | * | * | * | * | 0,00 |
| | | i.V.m. Code PSA/PSD/PSE/PSI | | • | • | • | • | • | • | - | 158,00 |
| | | i.V.m. Code PSJ/PSN/PSQ | | - | - | - | - | - | - | • | 158,00 |
| | | i.V.m. Code PSJ/PSN/PSQ | | • | • | • | • | • | • | - | 158,00 |
| 351 | Mercedes-Benz emergency call system | | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0,00 |
| | | Only in conjunction with 362 | | | | * | * | * | * | * | 0,00 |
| 355 | Extended MBUX functions | | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0,00 |
| 35B | Owner's Manual and service information - Latvian | | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0,00 |
| 362 | Communication module (LTE) for the use of Mercedes me connect | | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0,00 |
| | | Only in conjunction with 34U+351+79B+(00U/37U) | | | | | | | * | | 0,00 |
| | | Only in conjunction with 34U+351+79B+(00U/37U)+(33U/37U) | | | | | | | | * | 0,00 |
| | | Only in conjunction with 351+(33U/34U)+(00U/33U/34U)+79B | | | | | * | | | | 0,00 |
| | | Only in conjunction with 351+(33U/34U)+(00U/37U)+(00U/33U/34U)+79B | | | | * | * | * | * | * | 0,00 |
| 365 | Hard-disc navigation | | | • | • | • | • | • | • | • | 578,00 |
| | | Only in conjunction with PBF/PBG | | * | * | * | * | * | * | * | 0,00 |
| | | Only in conjunction with PBG | | | | | | | | | 0,00 |
| | | i.V.m. Code PBF | | - | - | - | - | - | - | - | 0,00 |
| | | i.V.m. Code PBF/PBG | | - | - | - | - | 0 | - | - | 0,00 |
| | | i.V.m. Code PBF/PBG | | 0 | 0 | 0 | 0 | - | 0 | 0 | 0,00 |
| 367 | Preinstallation for Live Traffic Information | | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0,00 |
| | | Only in conjunction with 362 | | | | * | * | * | * | * | 0,00 |
| 36B | Owner's Manual and service information - Lithuanian | | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0,00 |
| 37B | Owner's Manual and service information - Slovak | | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0,00 |
| 37U | Remote Services Advanced | | | • | • | • | - | • | • | • | 158,00 |
| | | Not in conjunction with 00U | | | | | | | | | 0,00 |
| | | Not in conjunction with 00U/33U | | * | * | * | * | * | * | * | 0,00 |
| | | Only in conjunction with 362 | | | | * | * | * | * | * | 0,00 |
| 38B | Owner's Manual and service information - Estonian | | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0,00 |
| 39B | Owner's Manual and service information - Serbian | | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0,00 |
| 400 | Rear armrest | | | S | S | S | S | S | S | S | 0,00 |

[illegible]

| | | | | | | | | | | | |
|-----|--|---|----|----|----|----|----|----|----|---|----------|
| | | Not in conjunction with 679 | * | * | * | * | * | * | * | | 0,00 |
| | | Only in conjunction with 662U | | | | | | | | | 0,00 |
| | | Only in conjunction with 720/725 | * | * | * | | | * | * | | 0,00 |
| | | Only in conjunction with 720/725/(720/725)+662U | | | | * | * | | | | 0,00 |
| 525 | MBUX multimedia system | | ○ | ○ | ○ | ○ | ○ | ○ | ○ | | 0,00 |
| | | Not in conjunction with 810 | | | * | | | | | | 0,00 |
| | | Not in conjunction with U19+810 | * | * | | * | * | * | * | | 0,00 |
| | | Only in conjunction with 256/U19/943 | | | | | | | | * | 0,00 |
| | | Only in conjunction with 943 | | | | | | | | | 0,00 |
| | | Only in conjunction with U19 | | | * | | | | | | 0,00 |
| | | Only in conjunction with U19/943 | * | * | | * | * | * | * | | 0,00 |
| 52R | 45.7 cm (18-inch) 5-spoke light-alloy wheels | | ● | ● | ● | ● | ● | ● | ● | - | 630,00 |
| | | | - | - | - | - | - | - | - | - | 840,00 |
| | | Not in conjunction with 950 | * | * | * | * | * | * | * | | 0,00 |
| 52R | i.V.m. Code P59 | | LS | LS | LS | LS | LS | LS | LS | - | 0,00 |
| | i.V.m. Code P55 | | - | - | - | - | ○ | - | - | - | 0,00 |
| | i.V.m. Code P55 | | ○ | ○ | ○ | ○ | - | ○ | - | - | 0,00 |
| | i.V.m. Code (P55+P59)/P59 | | - | - | - | - | ○ | - | - | - | 0,00 |
| | i.V.m. Code (P55+P59)/P59 | | ○ | ○ | ○ | ○ | - | ○ | - | - | 0,00 |
| 534 | MBUX multimedia system | | ○ | ○ | ○ | ○ | ○ | ○ | ○ | ○ | 0,00 |
| | | Only in conjunction with U19+810 | * | * | * | * | * | * | * | * | 0,00 |
| 536 | Radio: SIRIUS/SDARS ex factory | | - | - | - | - | - | ● | ● | | 368,00 |
| | | Not in conjunction with 968/969 | | | | | | * | * | | 0,00 |
| 537 | Digital radio | | ○ | ○ | ○ | ○ | ○ | ○ | ○ | | 0,00 |
| | | Only in conjunction with 79B | * | * | * | * | * | * | * | * | 0,00 |
| 543 | Pull-out sun visor | | S | S | S | S | S | S | S | S | 0,00 |
| 546 | Active Speed Limit Assist | | ○ | ○ | ○ | ○ | ○ | ○ | ○ | ○ | 0,00 |
| | | Only in conjunction with P79+513 | * | * | * | * | * | * | * | * | 0,00 |
| 550 | Trailer coupling with ESP® trailer stabilisation | | ● | ● | ● | ● | ● | ● | ● | | 840,00 |
| 551 | Anti-theft alarm system with preinstallation for collision detection | | ● | ● | ● | ● | ● | ● | ● | | 263,00 |
| | | Only in conjunction with P54/P82 | * | * | * | * | * | * | * | * | 0,00 |
| | i.V.m. Code P54 | | ○ | ○ | ○ | ○ | ○ | ○ | ○ | ○ | 0,00 |
| | i.V.m. Code P82 | | ○ | ○ | ○ | ○ | ○ | ○ | ○ | ○ | 0,00 |
| 552 | Anti-theft alarm system with preinstallation for collision detection | | ○ | ○ | ○ | ○ | ○ | ○ | ○ | ○ | 0,00 |
| | | Only in conjunction with P54/P82 | * | * | * | * | * | * | * | * | 0,00 |
| 55H | Star Pattern trim elements | | ○ | ○ | ○ | ○ | ○ | ○ | ○ | - | 0,00 |
| 55U | Roof liner in macchiato beige fabric | | ○ | ○ | ○ | ○ | ○ | ○ | ○ | - | 0,00 |
| | | Only in conjunction with 105A | * | * | * | * | * | * | * | | 0,00 |
| 567 | Rear seats with fore/aft adjustment | | ● | ● | ● | ● | ● | ● | ● | | 378,00 |
| | | Not in conjunction with 847 | * | * | * | * | * | * | * | * | 0,00 |
| | | Only in conjunction with 7U2/7U4 | * | * | * | * | * | * | * | | 0,00 |
| 56H | Star Pattern trim | | ● | ● | ● | ● | ● | ● | ● | | 105,00 |
| | | Only in conjunction with (P59/950)+331 | | | | | | | | | 0,00 |
| | | Only in conjunction with 331 | | | | | | | | * | 0,00 |
| | | Only in conjunction with 877+(P59/950)+331 | * | * | * | * | * | * | * | | 0,00 |
| 580 | THERMATIC automatic climate control | | ○ | ○ | ○ | ○ | ○ | ○ | ○ | ○ | 0,00 |
| | | Not in conjunction with P53 | | | | | | | | * | 0,00 |
| | | Not in conjunction with PDC/PDD | | * | * | | | | | | 0,00 |
| | | Not in conjunction with PDC/PDD/P53 | * | | | * | * | * | | | 0,00 |
| | | Only in conjunction with PDB | | | | | | | | * | 0,00 |
| 581 | THERMOTRONIC automatic climate control | | ● | ● | ● | ● | ● | ● | ● | | 536,00 |
| | i.V.m. Code PDC/PDD | | - | - | - | - | ○ | - | - | - | 0,00 |
| | i.V.m. Code PDC/PDD | | ○ | ○ | ○ | ○ | - | ○ | ○ | ○ | 0,00 |
| 586 | Surround lighting with projection of brand logo | | ○ | ○ | ○ | ○ | ○ | ○ | ○ | ○ | 0,00 |
| | | Only in conjunction with PDD | * | * | * | * | * | * | * | * | 0,00 |
| 58U | Roof liner in crystal grey fabric | | ○ | ○ | ○ | ○ | ○ | ○ | ○ | ○ | 0,00 |
| | | Not in conjunction with 105A | * | * | * | * | * | * | * | | 0,00 |
| 5B0 | Pre-installation for DISTRONIC | | ○ | ○ | ○ | ○ | ○ | ○ | ○ | ○ | 0,00 |
| | | Only in conjunction with 258 | | | | | * | * | | | 0,00 |
| | | Only in conjunction with 258+(B01/207) | | | | * | | | | | 0,00 |
| | | Only in conjunction with 258+207 | * | * | * | | | | * | | 0,00 |
| 5R2 | Complete set of 4 M+S winter wheels | | ○ | ○ | ○ | ○ | ○ | ○ | ○ | - | 0,00 |
| | | Not in conjunction with 4R9 | * | * | * | * | * | * | * | | 0,00 |
| | | Not in conjunction with 645 | * | * | * | * | * | * | * | | 0,00 |
| | | Only in conjunction with 652+PGL | * | * | * | * | * | * | * | | 0,00 |
| | | Only in conjunction with L | * | * | * | * | * | * | * | | 0,00 |
| | i.V.m. S-Code 7S7 | | ● | ● | ● | ● | ● | ● | ● | - | 2.205,00 |
| 5U6 | AMG-specific radiator grille, darkened | | - | - | - | - | - | - | - | ○ | 0,00 |
| | | Only in conjunction with PAZ | | | | | | | * | | 0,00 |
| 608 | Adaptive Highbeam Assist | | ○ | ○ | ○ | ○ | ○ | ○ | ○ | ○ | 0,00 |
| | | Not in conjunction with 628 | * | * | * | * | * | * | * | * | 0,00 |
| | | Only in conjunction with 631/-/642 | | | | | | * | * | | 0,00 |

| | | | | | | | | | | | |
|------|--|---|----|----|----|----|----|----|----|--|----------|
| | | Only in conjunction with 631/632 | * | * | * | * | * | | | | 0,00 |
| | | Only in conjunction with 632 | | | | | | | | | 0,00 |
| | | i.V.m. Code 640 | - | - | - | - | - | - | | | 0,00 |
| 623 | Gulf States specification | | - | - | - | ● | - | ● | ● | | 158,00 |
| | | Only in conjunction with U60+B12+682+687+(672+-R66/R66)+986+989 | | | | * | | * | * | | 0,00 |
| 625 | Australia specification | | - | - | - | ○ | - | ○ | ○ | | 0,00 |
| | | Only in conjunction with U60+(258/239)+537 | | | | * | | * | * | | 0,00 |
| 628 | Adaptive Highbeam Assist Plus | | ○ | ○ | ○ | ○ | ○ | ○ | ○ | | 0,00 |
| | | Not in conjunction with 608 | * | * | * | * | * | * | * | | 0,00 |
| | | Only in conjunction with 641/642 | * | * | * | * | * | * | * | | 0,00 |
| | | Only in conjunction with 642 | | | | | | | | | 0,00 |
| 631 | LED High Performance headlamp | | ○ | ○ | ○ | ○ | ○ | ○ | ○ | | 0,00 |
| | | Not in conjunction with 632/640/641/642 | | | | | | * | * | | 0,00 |
| | | Not in conjunction with 632/641/642 | * | * | * | * | * | | | | 0,00 |
| | | Not in conjunction with PAD/PDD | * | * | * | * | * | * | | | 0,00 |
| | | Not in conjunction with PDD | | | | | | | * | | 0,00 |
| | | Only in conjunction with 608 | * | * | * | * | * | * | * | | 0,00 |
| | | Only in conjunction with R | * | * | * | * | * | * | * | | 0,00 |
| 632 | LED High Performance headlights | | ○ | ○ | ○ | ○ | ○ | ○ | ○ | | 0,00 |
| | | Not in conjunction with 631/641 | | | | | | * | * | | 0,00 |
| | | Not in conjunction with 631/641/642 | * | * | * | * | * | | | | 0,00 |
| | | Not in conjunction with PAD/PDD | * | * | * | * | * | * | | | 0,00 |
| | | Not in conjunction with PDD | | | | | | | * | | 0,00 |
| | | Only in conjunction with 608 | * | * | * | * | * | * | * | | 0,00 |
| | | Only in conjunction with L | * | * | * | * | * | * | * | | 0,00 |
| 634 | Omission of first-aid kit | | ○ | ○ | ○ | ○ | ○ | ○ | ○ | | 0,00 |
| 636 | Omission of hazard warning triangle | | ○ | ○ | ○ | ○ | ○ | ○ | ○ | | 0,00 |
| 640 | MULTIBEAM LED | | - | - | - | - | - | ● | ● | | 305,00 |
| | | Not in conjunction with 631/641 | | | | | | * | * | | 0,00 |
| | | Only in conjunction with 608 | | | | | | * | * | | 0,00 |
| | | Only in conjunction with L | | | | | | * | * | | 0,00 |
| 641 | MULTIBEAM LED | | ● | ● | ● | ● | ● | ● | ● | | 305,00 |
| | | Not in conjunction with 631/632/640/642 | | | | | | * | * | | 0,00 |
| | | Not in conjunction with 631/632/642 | * | * | * | * | * | | | | 0,00 |
| | | Only in conjunction with 628 | * | * | * | * | * | * | * | | 0,00 |
| | | Only in conjunction with R | * | * | * | * | * | * | * | | 0,00 |
| | | i.V.m. Code PAD | - | - | - | - | ○ | - | - | | 0,00 |
| | | i.V.m. Code PDD | - | - | - | - | ○ | - | - | | 0,00 |
| | | i.V.m. Code PDD | - | - | - | - | - | ○ | | | 0,00 |
| | | i.V.m. Code PAD | ○ | ○ | ○ | ○ | - | ○ | - | | 0,00 |
| | | i.V.m. Code PDD | ○ | ○ | ○ | ○ | - | ○ | - | | 0,00 |
| 642 | MULTIBEAM LED | | ● | ● | ● | ● | ● | ● | - | | 305,00 |
| 642 | | | - | - | - | - | - | - | LS | | 0,00 |
| | | Not in conjunction with 631/632/641 | * | * | * | * | * | | | | 0,00 |
| | | Not in conjunction with 631/641 | | | | | | * | * | | 0,00 |
| | | Only in conjunction with 628 | * | * | * | * | * | * | * | | 0,00 |
| | | Only in conjunction with L | * | * | * | * | * | * | * | | 0,00 |
| | | i.V.m. Code PAD | - | - | - | - | ○ | | - | | 0,00 |
| | | i.V.m. Code PDD | - | - | - | - | ○ | - | - | | 0,00 |
| | | i.V.m. Code PAD | ○ | ○ | ○ | ○ | - | ○ | - | | 0,00 |
| | | i.V.m. Code PDD | - | - | - | - | - | ○ | | | 0,00 |
| | | i.V.m. Code PDD | ○ | ○ | ○ | ○ | - | ○ | - | | 0,00 |
| 645 | M+S winter tyres, set of 4 | | ● | ● | ● | ● | ● | ● | - | | 158,00 |
| | | Not in conjunction with 652 | * | * | * | * | * | * | | | 0,00 |
| | | Only in conjunction with R58/R62/RTF | | | | | * | * | | | 0,00 |
| | | Only in conjunction with R62/RTF | * | * | * | | | * | | | 0,00 |
| 651A | ARTICO man-made leather / DINAMICA microfibre black | | ○ | ○ | ○ | ○ | ○ | ○ | S | | 0,00 |
| | | Only in conjunction with 7U4+950 | * | * | * | * | * | * | * | | 0,00 |
| 652 | Summer complete tyres fitted | | ○ | ○ | ○ | ○ | ○ | ○ | ○ | | 0,00 |
| | | Not in conjunction with 645 | * | * | * | * | * | * | | | 0,00 |
| | | Not in conjunction with R66 | | | | | | | * | | 0,00 |
| | | Only in conjunction with 4R9/5R2 | * | * | * | * | * | * | | | 0,00 |
| | | Only in conjunction with 8R4 | | | | | | | * | | 0,00 |
| | | Only in conjunction with L | * | * | * | * | * | * | * | | 0,00 |
| 654A | ARTICO man-made leather upholstery / MICROCUT microfibre Bahia | | ● | ● | ● | ● | ● | ● | ● | | 105,00 |
| | | Only in conjunction with 7U4+950 | * | * | * | * | * | * | | | 0,00 |
| 662U | MANUFAKTUR mountain grey MAGNO | | - | - | - | ● | ● | - | - | | 2.310,00 |
| 666 | Freight packaging without tie-down hooks | | ● | ● | ● | ● | ● | ● | ● | | 27,00 |
| | | Not in conjunction with 668 | * | * | * | * | * | * | * | | 0,00 |
| | | Only in conjunction with 550 | * | * | * | * | * | * | * | | 0,00 |
| 668 | Freight packaging with tie-down hooks | | LS | LS | LS | LS | LS | LS | LS | | 0,00 |
| | | Not in conjunction with 550 | * | * | * | * | * | * | * | | 0,00 |

| | | | | | | | | | | | | |
|--|------|--|---|----|----|----|----|----|----|----|---|--------|
| | | | Not in conjunction with 666 | * | * | * | * | * | * | * | * | 0,00 |
| | 672 | Emergency spare wheel | | - | - | ○ | ○ | - | ○ | ○ | | 0,00 |
| | | | Not in conjunction with 847 | | | * | | | | | | 0,00 |
| | | | Not in conjunction with R66 | | | | | | * | * | | 0,00 |
| | | | Not in conjunction with R66+847 | | | | * | | | | | 0,00 |
| | | | Only in conjunction with B12 | | | * | * | | * | * | | 0,00 |
| | 679 | Product protection-partial protection | | ○ | ○ | ○ | ○ | ○ | ○ | ○ | | 0,00 |
| | | | Not in conjunction with 524 | * | * | * | * | * | * | * | | 0,00 |
| | | | Only in conjunction with 720/725 | * | * | * | * | * | * | * | | 0,00 |
| | 682 | Fire extinguisher | | LS | LS | LS | LS | LS | LS | LS | | 0,00 |
| | 687 | Model year on model plate | | ○ | ○ | ○ | ○ | ○ | ○ | ○ | | 0,00 |
| | | | Not in conjunction with 968/969 | * | * | * | * | * | * | * | | 0,00 |
| | 696U | night black | | ○ | ○ | ○ | ○ | ○ | ○ | ○ | | 0,00 |
| | 6U6 | AMG fuel cap | | - | - | - | - | - | - | ● | | 103,00 |
| | 700 | CBU vehicle China | | - | - | - | ○ | ○ | - | - | | 0,00 |
| | 70B | Fluorescent jacket for driver | | ● | ● | ● | ● | ● | ● | ● | | 6,00 |
| | | | i.V.m. Code PSA/PSD/PSE/PSI | ○ | ○ | ○ | ○ | ○ | ○ | ○ | | 0,00 |
| | | | i.V.m. Code PSJ/PSN/PSQ | ○ | ○ | ○ | ○ | ○ | ○ | ○ | | 0,00 |
| | 720 | Roof rails in black | | ○ | ○ | ○ | ○ | ○ | ○ | ○ | | 0,00 |
| | | | Not in conjunction with 725/B27 | * | * | * | * | * | * | * | | 0,00 |
| | | | Only in conjunction with P55 | * | * | * | * | * | * | * | | 0,00 |
| | | | Only in conjunction with P60 | | | | | | | * | | 0,00 |
| | 725 | Polished aluminium roof rails | | ○ | ○ | ○ | ○ | ○ | ○ | S | | 0,00 |
| | | | Not in conjunction with 720/B27 | * | * | * | * | * | * | * | | 0,00 |
| | | | Not in conjunction with P55 | * | * | * | * | * | * | * | | 0,00 |
| | | | Not in conjunction with P60 | | | | | | | * | | 0,00 |
| | 72B | USB Package Plus | | ○ | ○ | ○ | ○ | ○ | ○ | ○ | | 0,00 |
| | 73B | Stowage compartment in centre console with retractable cover | | ○ | ○ | ○ | ○ | ○ | ○ | ○ | | 0,00 |
| | 762 | Radio remote control without panic button | | ○ | ○ | ○ | ○ | ○ | ○ | ○ | | 0,00 |
| | | | Not in conjunction with 763 | | | | | * | * | * | | 0,00 |
| | | | Not in conjunction with 968/969 | * | * | * | * | * | * | * | | 0,00 |
| | 763 | Radio remote control with panic switch | | - | - | - | - | ○ | ○ | ○ | | 0,00 |
| | | | Not in conjunction with 762 | | | | | * | * | * | | 0,00 |
| | | | Not in conjunction with 968/969 | | | | | * | * | * | | 0,00 |
| | | | Only in conjunction with 551 | | | | | * | * | * | | 0,00 |
| | 772 | AMG bodystyling | | ○ | ○ | ○ | ○ | ○ | ○ | S | | 0,00 |
| | | | Only in conjunction with 950 | * | * | * | * | * | * | * | | 0,00 |
| | 77B | MBUX Interior Assistant | | ○ | ○ | ○ | ○ | ○ | ○ | ○ | | 0,00 |
| | | | Only in conjunction with PDD | * | * | * | * | * | * | * | | 0,00 |
| | 787U | mountain grey metallic | | ● | ● | ● | ● | ● | ● | - | | 788,00 |
| | 787U | | | - | - | - | - | - | - | ○ | | 0,00 |
| | 79B | Preinstallation for digital radio | | ○ | ○ | ○ | ○ | ○ | ○ | ○ | | 0,00 |
| | | | Only in conjunction with 362/537+-362 | | | * | * | * | * | * | | 0,00 |
| | 7U2 | Comfort Seats | | ○ | ○ | ○ | ○ | ○ | ○ | - | | 0,00 |
| | | | Only in conjunction with 101A/104A/105A/311A/318A | | | * | * | | | | | 0,00 |
| | | | Only in conjunction with 101A/105A/311A/318A | * | * | * | | * | | | | 0,00 |
| | 7U4 | Sports seats | | ● | ● | ● | ● | ● | ● | - | | 315,00 |
| | | | | - | - | - | - | - | - | S | | 0,00 |
| | | | Not in conjunction with 101A/104A/105A/311A/318A | | | * | * | | | | | 0,00 |
| | | | Not in conjunction with 101A/105A/311A/318A | * | * | * | | * | | | | 0,00 |
| | | | i.V.m. Code 950 | ○ | ○ | ○ | ○ | ○ | ○ | - | | 0,00 |
| | | | i.V.m. Code P34 | - | - | - | - | - | - | S | | 0,00 |
| | | | i.V.m. Code P34 | ○ | ○ | ○ | ○ | ○ | ○ | - | | 0,00 |
| | 7U8 | Model badge on boot lid and wings in high-gloss black | | - | - | - | - | - | - | ○ | | 0,00 |
| | | | Only in conjunction with PAZ | | | | | | | * | | 0,00 |
| | 805 | Technical modifications | | ○ | ○ | ○ | ○ | ○ | ○ | ○ | | 0,00 |
| | 810 | Burmester® surround sound system | | ● | ● | ● | ● | ● | ● | ● | | 951,00 |
| | | | Not in conjunction with 853 | * | * | * | * | * | * | * | | 0,00 |
| | | | Only in conjunction with 22U+32U | * | * | * | * | * | * | * | | 0,00 |
| | | | Only in conjunction with 32U | | | | | | | | | 0,00 |
| | | | i.V.m. Code PDC/PDD | ● | ● | ● | ● | ● | ● | ● | | 625,00 |
| | 820 | Tourist vehicle | | ○ | ○ | ○ | ○ | ○ | ○ | ○ | | 0,00 |
| | 824 | Additional parts for cold countries (engine air intake screen) | | ○ | ○ | ○ | ○ | ○ | ○ | ○ | | 0,00 |
| | 827 | Number plate mounting | | - | - | ○ | ○ | ○ | ○ | ○ | | 0,00 |
| | | | Not in conjunction with 263/264/823/831 | | | | | | | * | | 0,00 |
| | | | Not in conjunction with 264/823/831 | | | * | * | * | * | * | | 0,00 |
| | | | Only in conjunction with L | | | * | * | * | * | * | | 0,00 |
| | 840 | Heat-insulating dark-tinted glass | | ● | ● | ● | ● | ● | ● | ● | | 315,00 |
| | | | Not in conjunction with U50 | * | * | * | * | * | * | * | | 0,00 |
| | | | Only in conjunction with P59/950 | * | * | * | * | * | * | * | | 0,00 |
| | | | i.V.m. Code P55 | ○ | ○ | ○ | ○ | ○ | ○ | - | | 0,00 |
| | | | i.V.m. Code P60 | - | - | - | - | - | - | ○ | | 0,00 |

| | | | | | | | | | | |
|------|--|--|---|---|---|---|---|---|---|----------|
| | | i.V.m. Code PSJ/PSN/PSQ | - | - | - | - | 0 | - | - | 0,00 |
| | | i.V.m. Code PSJ/PSN/PSQ | - | - | - | - | - | 0 | | 0,00 |
| | | i.V.m. Code PSJ/PSN/PSQ | 0 | 0 | 0 | 0 | - | 0 | - | 0,00 |
| 847 | 3rd row of seats for 2 people | | • | • | • | • | • | • | • | 1.250,00 |
| | | Not in conjunction with 567/214A | * | * | | | | | | 0,00 |
| | | Not in conjunction with 567/672 | | | | | | | * | 0,00 |
| | | Not in conjunction with 567/672/214A | | | * | * | * | * | | 0,00 |
| | | Only in conjunction with B51+R66 | | | * | * | | | | 0,00 |
| 852 | Sensor system for anti-theft alarm system | | - | - | - | - | - | • | • | 147,00 |
| | | Not in conjunction with 882 | | | | | | * | * | 0,00 |
| | | Only in conjunction with L | | | | | | * | * | 0,00 |
| | | Only in conjunction with P82 | | | | | | * | * | 0,00 |
| | | i.V.m. Code 362 | - | - | - | - | - | • | • | 179,00 |
| | | i.V.m. Code P54/P82 | - | - | - | - | - | 0 | 0 | 0,00 |
| 853 | Advanced Sound System | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0,00 |
| | | Not in conjunction with 810 | * | * | * | * | * | * | * | 0,00 |
| | | Not in conjunction with PDB | | | | | | | * | 0,00 |
| | | Only in conjunction with (PDC/PDD)+22U | * | * | * | * | * | * | * | 0,00 |
| | | Only in conjunction with 22U | | | | | | | * | 0,00 |
| 859 | Media display | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0,00 |
| | | | - | - | - | - | - | - | - | 683,00 |
| 865 | TV tuner Japan | | • | • | - | - | - | - | • | 945,00 |
| | | Only in conjunction with R | * | * | | | | | * | 0,00 |
| 871 | HANDS-FREE ACCESS | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0,00 |
| | | Only in conjunction with P17 | * | * | * | * | * | * | * | 0,00 |
| 873 | Heated front seats | | • | • | • | • | • | • | • | 336,00 |
| | | i.V.m. Code PAV | - | - | - | - | 0 | - | 0 | 0,00 |
| | | i.V.m. Code PAV | 0 | 0 | 0 | 0 | - | 0 | - | 0,00 |
| | | i.V.m. Code PSA/PSD/PSE/PSI | - | - | - | - | 0 | - | - | 0,00 |
| | | i.V.m. Code PSJ/PSN/PSQ | - | - | - | - | - | - | 0 | 0,00 |
| | | i.V.m. Code PSA/PSD/PSE/PSI | 0 | 0 | 0 | 0 | - | 0 | - | 0,00 |
| | | i.V.m. Code PSJ/PSN/PSQ | - | - | - | - | 0 | - | - | 0,00 |
| | | i.V.m. Code PSJ/PSN/PSQ | 0 | 0 | 0 | 0 | - | 0 | - | 0,00 |
| 875 | Heated windscreen washer system | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0,00 |
| | | Only in conjunction with PAV | * | * | * | * | * | * | * | 0,00 |
| 877 | Ambient lighting | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0,00 |
| | | Not in conjunction with PDA | * | * | * | * | * | * | * | 0,00 |
| 882 | Interior monitoring system | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0,00 |
| | | Not in conjunction with 852 | | | | | | * | * | 0,00 |
| | | Only in conjunction with P54/P82 | * | * | * | * | * | * | * | 0,00 |
| 885 | Increased anti-theft protection | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0,00 |
| 885U | MANUFAKTUR opalite white bright | | - | - | - | • | • | - | - | 788,00 |
| 889 | KEYLESS-GO | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0,00 |
| | | Only in conjunction with P17 | * | * | * | * | * | * | * | 0,00 |
| | | i.V.m. Code P17 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0,00 |
| | | i.V.m. Code P17 | - | - | - | - | - | - | - | 0,00 |
| | | i.V.m. Code PAD | 0 | 0 | 0 | 0 | 0 | 0 | - | 0,00 |
| | | i.V.m. Code PAD | - | - | - | - | - | - | - | 0,00 |
| 888 | Passive person presence reminder | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0,00 |
| 890 | EASY-PACK tailgate | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0,00 |
| | | i.V.m. Code P17 | - | - | - | - | 0 | - | - | 0,00 |
| | | i.V.m. Code P17 | 0 | 0 | 0 | 0 | - | 0 | 0 | 0,00 |
| | | i.V.m. Code P17 | - | - | - | - | - | - | - | 0,00 |
| 897 | Wireless charging system for mobile devices in the front | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0,00 |
| | | Not in conjunction with PDA | * | * | * | * | * | * | * | 0,00 |
| | | Only in conjunction with P59/950 | * | * | * | * | * | * | * | 0,00 |
| | | Only in conjunction with PDB | | | | | | | * | 0,00 |
| | | Only in conjunction with PDB/PDC/PDD | | | | | | | * | 0,00 |
| 8R4 | Complete set of 4 M+S winter wheels | | - | - | - | - | - | - | 0 | 0,00 |
| | | Only in conjunction with 652+PGP | | | | | | | * | 0,00 |
| | | Only in conjunction with L | | | | | | | * | 0,00 |
| | | i.V.m. S-Code 7S7 | - | - | - | - | - | - | • | 3.360,00 |
| 913 | Air conditioning preinstallation for hot countries | | 0 | 0 | 0 | - | - | - | - | 0,00 |
| 916 | Fuel tank with a capacity of 60 litres | | - | S | S | - | 0 | S | S | 0,00 |
| 922 | Reduced output engines | | - | - | - | - | - | - | - | 0,00 |
| | | Only in conjunction with R | | | | | | | | 0,00 |
| 922U | high-tech silver | | • | • | • | • | • | • | - | 788,00 |
| 922U | | | - | - | - | - | - | 0 | - | 0,00 |
| 926 | Emission control system with EU4 technology | | - | - | - | 0 | - | 0 | 0 | 0,00 |
| | | Not in conjunction with 927 | | | | | | * | * | 0,00 |
| | | Not in conjunction with 927/945 | | | * | | | * | * | 0,00 |

| | | | | |
|------|--|--|-----------------|----------|
| 927 | EU6 emissions standard | | ○ ○ ○ ○ ○ ○ ○ ○ | 0,00 |
| | | Not in conjunction with 926 | ○ ○ ○ ○ ○ ○ ○ * | 0,00 |
| | | Not in conjunction with 926/945 | ○ ○ ○ ○ ○ ○ * | 0,00 |
| | | Not in conjunction with 945 | ○ ○ ○ ○ ○ ○ * | 0,00 |
| 942 | Load Compartment Package | | ● ● ● ● ● ● ● ● | 158,00 |
| | | Only in conjunction with U35 | * * * * * * * * | 0,00 |
| | | i.V.m. Code PSA/PSD/PSE/PSI | - - - - - ○ - - | 0,00 |
| | | i.V.m. Code PSJ/PSN/PSQ | - - - - - - - ○ | 0,00 |
| | | i.V.m. Code PSA/PSD/PSE/PSI | ○ ○ ○ ○ ○ - ○ - | 0,00 |
| | | i.V.m. Code PSJ/PSN/PSQ | - - - - - ○ - - | 0,00 |
| | | i.V.m. Code PSJ/PSN/PSQ | ○ ○ ○ ○ ○ - ○ - | 0,00 |
| 943 | Toll payment system | | ● ● ● ● ● ● ● ● | 210,00 |
| 945 | Emission control system China | | - - - ○ ○ ○ - ○ | 0,00 |
| | | Not in conjunction with 926/927 | ○ ○ ○ ○ ○ * | 0,00 |
| | | Not in conjunction with 927 | ○ ○ ○ ○ ○ * | 0,00 |
| 950 | AMG Line | | ● ● ● ● ● ● ● - | 1.785,00 |
| | | | - - - - - - S | 0,00 |
| | | Includes codes 310+651A+725+772+(H62/03H/56H/H15)+(L6K/L6J)+U26 | ○ ○ ○ ○ ○ ○ * | 0,00 |
| | | Includes codes 310+651A+725+772+(H62/03H/56H/H15)+L5C+(RTF/RTG)+U26 | * * * * * * | 0,00 |
| | | Not in conjunction with 101A/104A/105A/311A/318A/P59/55H | ○ ○ ○ ○ ○ * | 0,00 |
| | | Not in conjunction with 101A/104A/105A/311A/318A/P59/55H/H59 | ○ ○ ○ ○ ○ * | 0,00 |
| | | Not in conjunction with 101A/105A/311A/318A/P59/55H | * * * * * | 0,00 |
| | | Only in conjunction with (457/485)+(720/725)+(RTF/RTG/RVT/RVU)+(U28/U29)+772+U26+L5C | ○ ○ ○ ○ ○ ○ ○ ○ | 0,00 |
| | | Only in conjunction with (457/485)+(720/725)+(RTF/RTG/RVT/RVU)+772+B63+U26+U28+L5C | ○ ○ ○ ○ ○ ○ ○ ○ | 0,00 |
| | | Only in conjunction with (457/485)+(720/725)+(RTF/RTG/RVT/RVU)+U26+(U28/U29)+772+B63+L5C | * * * * * * | 0,00 |
| | | i.V.m. Code PSJ/PSN/PSQ | - - - - - ○ - - | 0,00 |
| | | i.V.m. Code PSJ/PSN/PSQ | ○ ○ ○ ○ ○ - ○ - | 0,00 |
| 960 | Government version | | - - ● - - - - - | 63,00 |
| | | Only in conjunction with L | ○ ○ ○ ○ ○ ○ ○ ○ | 0,00 |
| 968 | COC document EU6 without registration certificate part 2 | | ○ ○ ○ ○ ○ ○ ○ ○ | 0,00 |
| | | Not in conjunction with 232 | ○ ○ ○ ○ ○ ○ ○ * | 0,00 |
| | | Not in conjunction with 263 | * * * * * | 0,00 |
| | | Not in conjunction with 263/264 | ○ ○ ○ ○ ○ ○ * | 0,00 |
| | | Not in conjunction with 264 | ○ ○ ○ ○ ○ ○ * | 0,00 |
| | | Not in conjunction with 687 | * * * * * * | 0,00 |
| | | Not in conjunction with 762 | * * * * * | 0,00 |
| | | Not in conjunction with 762/763 | ○ ○ ○ ○ ○ ○ * | 0,00 |
| | | Not in conjunction with 836 | ○ ○ ○ ○ ○ ○ * | 0,00 |
| | | Not in conjunction with 969/981 | * * * * * * | 0,00 |
| | | Only in conjunction with 351+986 | ○ ○ ○ ○ ○ ○ * | 0,00 |
| | | Only in conjunction with 927+351+986 | * * * * * * | 0,00 |
| | | Only in conjunction with 927+986 | * * * * * * | 0,00 |
| 969 | COC document EU6 with registration certificate part 2 | | ○ ○ ○ ○ ○ ○ ○ ○ | 0,00 |
| | | Not in conjunction with 232 | ○ ○ ○ ○ ○ ○ * | 0,00 |
| | | Not in conjunction with 687 | * * * * * * | 0,00 |
| | | Not in conjunction with 762 | * * * * * | 0,00 |
| | | Not in conjunction with 762/763 | ○ ○ ○ ○ ○ ○ * | 0,00 |
| | | Not in conjunction with 836 | ○ ○ ○ ○ ○ ○ * | 0,00 |
| | | Not in conjunction with 968/981 | * * * * * * | 0,00 |
| | | Only in conjunction with 351+986 | ○ ○ ○ ○ ○ ○ * | 0,00 |
| | | Only in conjunction with 927+351+986 | ○ ○ ○ ○ ○ ○ * | 0,00 |
| | | Only in conjunction with 927+986 | * * * * * * | 0,00 |
| 970U | spectral blue | | ● ● ● ● ● ● ● - | 788,00 |
| 970U | | | - - - - - - ○ | 0,00 |
| 971 | Diesel particulate filter | | S S S - - - - | 0,00 |
| 973 | Designation as owner-driver rental vehicle | | ○ ○ ○ ○ ○ ○ ○ ○ | 0,00 |
| 981 | TÜV German Technical Inspection Authority - individual approval, G | | ○ ○ ○ ○ ○ ○ ○ ○ | 0,00 |
| | | Not in conjunction with 968/969 | * * * * * * | 0,00 |
| 986 | Identification label with VIN number | | ○ ○ ○ ○ ○ ○ ○ ○ | 0,00 |
| | | Only in conjunction with 968/969/981 | * * * * * * | 0,00 |
| 989 | Identification label under windshield | | ○ ○ ○ ○ ○ ○ ○ ○ | 0,00 |
| 993U | MANUFAKTUR patagonia red metallic | | ● ● ● ● ● ● ● - | 998,00 |
| 993U | | | - - - - - - ○ | 0,00 |
| 994 | Exhibition vehicle (B-Trade fair) | | ○ ○ ○ ○ ○ ○ ○ ○ | 0,00 |
| | | Not in conjunction with 997 | * * * * * * | 0,00 |
| 997 | Display vehicle for exhibitions (motor show veh.) | | ○ ○ ○ ○ ○ ○ ○ ○ | 0,00 |
| | | Not in conjunction with 994 | * * * * * * | 0,00 |
| 801 | Mild Hybrid Antrieb | | - - - ○ ○ ○ ○ ○ | 0,00 |
| 808 | Fanfare horn | | ○ ○ ○ ○ ○ ○ ○ ○ | 0,00 |
| | | Not in conjunction with P59/772 | ○ ○ ○ ○ ○ * | 0,00 |
| | | Only in conjunction with 497 | ○ ○ ○ ○ ○ * | 0,00 |
| | | Only in conjunction with 497 /-(P59/772) | ○ ○ ○ ○ ○ * | 0,00 |

| | | | | |
|-----|--|--|----------------------|----------|
| B12 | Tyre-change toolkit | | ● ● ● ● ● ● ● | 32,00 |
| | | Only in conjunction with 672 | ○ ○ * * * * * | 0,00 |
| B27 | Omission of roof rails | | ○ ○ ○ ○ - ○ ○ | 0,00 |
| | | Not in conjunction with 413 | * * * * * * * | 0,00 |
| | | Not in conjunction with 720/725 | * * * * * * * | 0,00 |
| | | Only in conjunction with P55/P59 | * * * * * * * | 0,00 |
| B51 | TIREFIT | | LS LS LS LS LS LS LS | 0,00 |
| | | Not in conjunction with R66 | * * * * * * * | 0,00 |
| | | Only in conjunction with -R66/847 | - - * * | 0,00 |
| | | i.V.m. Code PSA/PSD/PSE/PSI | - - - - ○ - - | 0,00 |
| | | i.V.m. Code PSA/PSD/PSE/PSI | ○ ○ ○ ○ - ○ - | 0,00 |
| | | i.V.m. Code PSJ/PSN/PSQ | - - - - ○ - ○ | 0,00 |
| | | i.V.m. Code PSJ/PSN/PSQ | ○ ○ ○ ○ - ○ - | 0,00 |
| B59 | AMG DYNAMIC SELECT | | - - - - - S | 0,00 |
| B59 | DYNAMIC SELECT | | S S S S S - | 0,00 |
| B63 | Sporty engine sound | | ○ ○ ○ ○ ○ ○ - | 0,00 |
| | | Only in conjunction with 950 | * * * * * * | 0,00 |
| H15 | Black open-pore linden wood trim | | ● ● ● ● ● ● ● | 273,00 |
| | | Only in conjunction with P59/950 | * * * * * * | 0,00 |
| H59 | Carbon-fibre-look trim | | - - - S - - - | 0,00 |
| | | Not in conjunction with 950/877 | - - - * | 0,00 |
| H62 | Carbon-structure trim | | ○ ○ ○ ○ ○ ○ S | 0,00 |
| | | Only in conjunction with 950 | * * * * * * | 0,00 |
| K33 | Extended automatic Re-start in traffic jams | | ○ ○ ○ ○ ○ ○ ○ | 0,00 |
| | | Only in conjunction with 365+P79 | | 0,00 |
| | | Only in conjunction with P79 | | 0,00 |
| | | Only in conjunction with P79+235+365 | * * * * * * | 0,00 |
| K34 | Route-based speed adaptation | | ○ ○ ○ ○ ○ ○ ○ | 0,00 |
| | | Only in conjunction with 365+P79 | * * * * * * | 0,00 |
| | | Only in conjunction with P79 | | 0,00 |
| L | Left-hand drive | | ○ ○ ○ ○ ○ ○ ○ | 0,00 |
| | | Only in conjunction with 945 | | 0,00 |
| L3E | Leather multifunction sports steering wheel | | ○ ○ ○ ○ ○ ○ - | 0,00 |
| | | Not in conjunction with 950 | * * * * * * | 0,00 |
| | | Only in conjunction with 428 | * * * * * * | 0,00 |
| L3M | Multifunction sports steering wheel in ARTICO man-made leather | | ○ ○ ○ ○ ○ ○ - | 0,00 |
| | | Not in conjunction with 950/P34/P79 | * * * * * * | 0,00 |
| | | Only in conjunction with 428 | * * * * * * | 0,00 |
| L5C | Multifunction sports steering wheel in nappa leather | | ○ ○ ○ ○ ○ ○ - | 0,00 |
| | | Only in conjunction with 950+431 | * * * * * * | 0,00 |
| L6J | AMG Performance steering wheel in nappa leather | | - - - - - ○ | 0,00 |
| L6K | AMG Performance steering wheel in nappa leather / MICROCUT mic | | - - - - - ● | 515,00 |
| P17 | KEYLESS-GO Comfort Package | | ○ ○ ○ ○ ○ ○ ○ | 0,00 |
| | | Includes codes 871+889+890 | * * * * * * | 0,00 |
| | | Not in conjunction with PDA | * * * * * * | 0,00 |
| | | Only in conjunction with 871+889+890 | * * * * * * | 0,00 |
| | | i.V.m. Code PAD | - - - - - - | 0,00 |
| P34 | Leather package | | ● ● ● ● ● ● - | 1.775,00 |
| | | Only in conjunction with 873+(211A/214A)+P59 | * * * * * * | 0,00 |
| P39 | AMG Leather Package | | ● ● ● ● ● ● ● | 1.050,00 |
| | | Only in conjunction with (211A/277A)+873+950 | * * * * * * | 0,00 |
| | | Only in conjunction with 873+(211A/277A) | | 0,00 |
| P44 | Parking package with reversing camera | | ○ ○ ○ ○ ○ ○ ○ | 0,00 |
| | | Includes codes 218+235 | * * * * * * | 0,00 |
| | | Not in conjunction with P47 | * * * * * * | 0,00 |
| | | Not in conjunction with PDD | * * * * * * | 0,00 |
| | | Only in conjunction with (PDA/PDB)+218 | | 0,00 |
| | | Only in conjunction with 218 | | 0,00 |
| | | Only in conjunction with 218+235 | * * * * * * | 0,00 |
| P47 | Parking Package with 360-degree camera | | ● ● ● ● ● ● ● | 1.423,00 |
| | | Includes codes 235+501 | * * * * * * | 0,00 |
| | | Not in conjunction with P44 | * * * * * * | 0,00 |
| | | Only in conjunction with (P59/950)+234+235+501 | * * * * * * | 0,00 |
| | | Only in conjunction with (P59/950)+234+501 | | 0,00 |
| | | Only in conjunction with 234+235+501 | | 0,00 |
| | | Only in conjunction with 501 | | 0,00 |
| | | i.V.m. Code PDA/PDB/PDC | ● ● ● ● ● ● ● | 431,00 |
| | | i.V m. Code PDD | - - - - ○ - - | 0,00 |
| | | i.V m. Code PDD | ○ ○ ○ ○ - ○ ○ | 0,00 |
| P49 | Mirror Package | | ○ ○ ○ ○ ○ ○ ○ | 0,00 |
| | | Includes codes 249+500 | | 0,00 |
| | | Includes codes 500 | * * * * * | 0,00 |

| | | | | | | | | | | | | | | |
|--|-----|-------------------------------------|---|----|----|----|----|----|----|----|---|--|--|----------|
| | | | Only in conjunction with (249/252)+500 | | | | | | * | | | | | 0,00 |
| | | | Only in conjunction with 252+500 | * | * | * | * | * | * | | | | | 0,00 |
| | P53 | AIR-QUALITY package | | ● | - | - | ● | ● | ● | ● | | | | 158,00 |
| | | | Includes codes 426+581+859 | * | | | | * | * | * | | | | 0,00 |
| | | | Includes codes 581+859 | | | | * | | | | | | | 0,00 |
| | | | Only in conjunction with 580/581 | | | | * | * | | | * | | | 0,00 |
| | | | Only in conjunction with 581 | * | | | | | | * | | | | 0,00 |
| | | | Only in conjunction with L | * | | | | * | * | * | * | | | 0,00 |
| | P54 | URBAN GUARD vehicle protection | | ● | ● | ● | ● | ● | ● | ● | ● | | | 431,00 |
| | | | Includes codes 551+882 | * | * | * | * | * | * | * | * | | | 0,00 |
| | | | Not in conjunction with P82 | * | * | * | * | * | * | * | * | | | 0,00 |
| | | | Only in conjunction with 551+882 | * | * | * | * | * | * | * | * | | | 0,00 |
| | | | i.V.m. Code 362 | ● | ● | ● | ● | ● | ● | ● | ● | | | 462,00 |
| | P55 | Night Package | | ● | ● | ● | ● | ● | ● | ● | - | | | 473,00 |
| | | | Includes codes 720+840 | * | * | * | * | * | * | * | | | | 0,00 |
| | | | Only in conjunction with (P59/950)+(-R74/RTF/RVU)/RVU+950) | | | | | | | | | | | 0,00 |
| | | | Only in conjunction with (P59/950)+840+(-R62/R74/RTF/RVU)/RVU+950) | * | * | * | * | * | * | * | | | | 0,00 |
| | | | i.V.m Code PSJ/PSN/PSQ | - | - | - | - | ● | - | - | | | | 158,00 |
| | | | i.V.m Code PSJ/PSN/PSQ | ● | ● | ● | ● | - | ● | - | | | | 158,00 |
| | P59 | PROGRESSIVE | | LS | LS | LS | LS | LS | LS | LS | - | | | 0,00 |
| | | | Includes codes (01R/25R/27R/52R/R38/R62/R74/RTG/RVT/RVU)+287+310+(51U/58U)+(55H/03H/56H/H15) Includes codes (01R/27R/52R/R38/R74/RTG/RVT/RVU)+287+310+(51U/58U)+(55H/03H/56H/H15) | * | * | * | * | * | * | * | | | | 0,00 |
| | | | Includes codes 01R+287+310+(51U/58U)+(55H/56H) | | | | | | | | | | | 0,00 |
| | | | Not in conjunction with 950 | * | * | * | * | * | * | * | | | | 0,00 |
| | | | i.V.m. Code PSE/PSI | - | - | - | - | ○ | - | - | | | | 0,00 |
| | | | i.V.m. Code PSE/PSI | ○ | ○ | ○ | ○ | - | ○ | - | | | | 0,00 |
| | P60 | AMG Night Package | | - | - | - | - | - | - | ● | | | | 788,00 |
| | | | Includes codes 720+840 | | | | | | | | * | | | 0,00 |
| | | | Only in conjunction with (720/B27)+840/720/B27 | | | | | | | | * | | | 0,00 |
| | | | i.V.m. Code PSJ/PSN/PSQ | - | - | - | - | - | - | ● | | | | 473,00 |
| | P79 | Driving Assistance Package | | ● | ● | ● | ● | ● | ● | ● | | | | 2.027,00 |
| | | | Includes codes 234+239+243+266+299 | | | | | | | | | | | 0,00 |
| | | | Includes codes 234+239+243+266+299+(P49/275) | * | * | * | * | * | * | * | * | | | 0,00 |
| | | | Only in conjunction with (K34/-365)+(275/221/P49)+234+239+243+266+299+(K33/-235/-365) | | | | | * | | | | | | 0,00 |
| | | | Only in conjunction with (K34/-365)+(P49/275)+234+239+243+266+299+(K33/-235/-365) | * | * | * | * | | * | | | | | 0,00 |
| | | | Only in conjunction with (K34/-365)+234+239+243+266+299+(K33/-235/-365) | | | | | | | * | | | | 0,00 |
| | | | Only in conjunction with (K34/-365)+234+239+243+266+299+(K33/-365) | | | | | | | | | | | 0,00 |
| | | | Only in conjunction with K34+234+243+266+299+K33 | | | | | | | | | | | 0,00 |
| | | | i.V.m. S-Code 51B | ● | ● | ● | ● | ● | ● | ● | | | | 1.617,00 |
| | | | i.V.m. Code PDC/PDD | ● | ● | ● | - | ● | ● | ● | | | | 1.617,00 |
| | | | i.V.m. S-Code 51B+PDC/PDD | ● | ● | ● | ● | ● | ● | ● | | | | 1.208,00 |
| | | | i.V.m. Code PAD | ○ | ○ | ○ | ○ | ○ | ○ | ○ | | | | 0,00 |
| | P82 | URBAN GUARD vehicle protection Plus | | ● | ● | ● | ● | ● | ● | ● | | | | 641,00 |
| | | | Includes codes 31U+551 | | | | | | | | | | | 0,00 |
| | | | Includes codes 31U+551+882 | * | * | * | * | * | * | * | * | | | 0,00 |
| | | | Not in conjunction with P54 | * | * | * | * | * | * | * | * | | | 0,00 |
| | | | Only in conjunction with 551+552+882 | * | * | * | * | * | * | * | | | | 0,00 |
| | | | Only in conjunction with 552+551+(882/852) | | | | | | * | * | | | | 0,00 |
| | | | Only in conjunction with 852 | | | | | | | | | | | 0,00 |
| | | | i.V.m. Code 362 | ● | ● | ● | ● | ● | ● | ● | | | | 672,00 |
| | | | i.V.m. Code 34U+362 | ● | ● | ● | ● | ● | ● | ● | | | | 567,00 |
| | PAD | Engineering Package | | ● | ● | ● | ● | ● | ● | - | | | | 4.106,00 |
| | | | Includes codes 457+642+889+U29 | * | * | * | * | * | * | * | | | | 0,00 |
| | | | Includes codes 457+889+U29 | * | * | * | * | * | * | * | | | | 0,00 |
| | | | Only in conjunction with P79+457+(641/642)+889+U29 | * | * | * | * | * | * | * | | | | 0,00 |
| | | | Only in conjunction with P79+457+642+889+U29 | | | | | | | | | | | 0,00 |
| | | | i.V.m. Code PDB | ● | ● | ● | ● | ● | ● | - | | | | 3.686,00 |
| | | | i.V.m. Code PDC | ● | ● | ● | ● | ● | ● | - | | | | 3.287,00 |
| | | | i.V.m. Code PDD | - | - | - | - | - | - | - | | | | 3.024,00 |
| | | | i.V.m. Code PSJ/PSJ | ● | ● | ● | ● | ● | ● | - | | | | 3.276,00 |
| | | | i.V.m. Code PSI/PSJ | - | - | - | - | - | - | - | | | | 3.276,00 |
| | | | i.V.m. Code PDD | ● | ● | ● | ● | ● | ● | - | | | | 3.024,00 |
| | | | i.V.m. Code PSN | ● | ● | ● | ● | ● | ● | - | | | | 2.877,00 |
| | | | i.V.m. Code PSQ | ● | ● | ● | ● | ● | ● | - | | | | 2.615,00 |
| | PAV | Winter Package | | ● | ● | ● | ● | ● | ● | ● | | | | 525,00 |
| | | | Includes codes 443+873+875 | * | * | * | * | * | * | * | * | | | 0,00 |
| | | | Only in conjunction with 443+873+875 | * | * | * | * | * | * | * | * | | | 0,00 |
| | | | i.V.m.Code PSA/PSD/PSE/PSI+873 | ● | ● | ● | ● | ● | ● | - | | | | 247,00 |
| | | | i.V.m. Code PGC/PGL/PGP | - | - | - | - | - | - | - | | | | 0,00 |
| | | | i.V.m. Code PSJ/PSN/PSQ + 873 | - | - | - | - | - | - | ● | | | | 247,00 |
| | | | i.V.m. Code PSJ/PSN/PSQ + 873 | ● | ● | ● | ● | ● | ● | - | | | | 247,00 |

| | | | | | | | | | | | |
|-----|---|--|---|----|----|----|----|----|----|----|----------|
| | | | i.V.m. Code PGC/PGL/PGP | - | - | - | - | - | - | 0 | 0,00 |
| | | | i.V.m. Code PGC/PGL/PGP | 0 | 0 | 0 | 0 | 0 | 0 | - | 0,00 |
| PAZ | AMG Night Package II | | | - | - | - | - | - | - | • | 420,00 |
| | | | Includes codes 5U6+7U8 | | | | | | | * | 0,00 |
| | | | Only in conjunction with P60+5U6+7U8 | | | | | | | * | 0,00 |
| PBF | MBUX Navigation Plus | | | • | • | • | • | • | • | • | 630,00 |
| | | | Includes codes 01U+365 | * | * | * | * | * | * | * | 0,00 |
| | | | Not in conjunction with PBG | * | * | * | * | * | * | * | 0,00 |
| | | | Only in conjunction with 01U+367+365 | * | * | * | * | * | * | * | 0,00 |
| | | | i.V.m. Code PDC/PDD | - | - | - | - | 0 | - | - | 0,00 |
| | | | i.V.m. Code PDC/PDD | 0 | 0 | 0 | 0 | - | 0 | 0 | 0,00 |
| PBG | Preinstallation for Navigation and Comfort Connectivity package | | | • | • | • | • | • | • | • | 735,00 |
| | | | Includes codes 01U+365 | * | * | * | * | * | * | * | 0,00 |
| | | | Not in conjunction with PBF | * | * | * | * | * | * | * | 0,00 |
| | | | Only in conjunction with 01U+365 | | | | | | | | 0,00 |
| | | | Only in conjunction with 01U+367+365 | * | * | * | * | * | * | * | 0,00 |
| PBG | | | i.V.m. S-Code 8P3 | LS | LS | LS | LS | LS | LS | LS | 0,00 |
| | | | i.V.m. Code PDC/PDD | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0,00 |
| | | | i.V.m. Code PSA/PSD/PSE/PSI | 0 | 0 | 0 | 0 | 0 | 0 | - | 0,00 |
| | | | i.V.m. Code PSJ/PSN/PSQ | - | - | - | - | - | - | 0 | 0,00 |
| | | | i.V.m. Code PSI/PSN/PSQ | 0 | 0 | 0 | 0 | 0 | 0 | - | 0,00 |
| PDA | Advanced Package | | | LS | LS | LS | LS | LS | LS | - | 0,00 |
| | | | Includes codes 218+73B+859 | * | * | * | * | * | * | | 0,00 |
| | | | Only in conjunction with 73B+890+(P44/P47)+P49+U22+20U+(00U/33U/34U/37U) | * | | | | | * | | 0,00 |
| | | | Only in conjunction with 890+(P44/P47)+(00U/37U) | | | | | | | | 0,00 |
| | | | Only in conjunction with 890+(P44/P47)+P49+U22+20U+(00U/33U/34U) | | | | * | | | | 0,00 |
| | | | Only in conjunction with 890+(P44/P47)+P49+U22+20U+(00U/33U/34U/37U) | | * | * | | * | | | 0,00 |
| | | | i.V.m. Code PSD/PSE | 0 | 0 | 0 | 0 | 0 | 0 | - | 0,00 |
| PDB | Advanced Plus Package | | | • | • | • | • | • | • | - | 703,50 |
| | | | | - | - | - | - | - | - | 0 | 0,00 |
| | | | Includes codes 458+859+877+(P44/P47)+P49 | | | | | | | * | 0,00 |
| | | | Includes codes 458+859+877+(P44/P47)+P49+P59 | * | * | * | * | * | * | | 0,00 |
| | | | Only in conjunction with (00U/33U/34U)+(P59/950)+458+877+P17+(P44/P47)+P49+U22+20U+897 | | | | * | | | | 0,00 |
| | | | Only in conjunction with (00U/33U/34U/37U)+(P44/P47)+20U+73B+897 | | | | | | | * | 0,00 |
| | | | Only in conjunction with (00U/33U/34U/37U)+(P59/950)+458+877+P17+(P44/P47)+P49+U22+20U+73B+897 | * | | | | | * | | 0,00 |
| | | | Only in conjunction with (00U/33U/34U/37U)+(P59/950)+458+877+P17+(P44/P47)+P49+U22+20U+897 | | * | * | | * | | | 0,00 |
| | | | i.V.m. Code PSI/PSJ | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0,00 |
| PDC | Premium Package | | | LS | LS | LS | LS | LS | LS | LS | 4.542,00 |
| | | | | LS | LS | LS | LS | LS | LS | LS | 1.911,00 |
| | | | Includes codes 400+458+581+73B+859+877+897+P17+(P44/P47)+P49+(U45/PBF) | | | | | | | * | 0,00 |
| | | | Includes codes 400+458+581+73B+859+877+897+P17+(P44/P47)+P49+P59 | | | | | * | | | 0,00 |
| | | | Includes codes 400+458+581+73B+859+877+897+P17+(P44/P47)+P49+P59+(U45/PBF) | * | * | * | * | * | * | * | 0,00 |
| | | | Only in conjunction with 73B+U19+(00U/33U/34U/37U)+(P59/950)+458+581+(810/853)+877+P17+(P44/P47)+P49+(PBF/PBG)+U22+U45+20U+897+234 | * | | | | | * | | 0,00 |
| | | | Only in conjunction with 73B+U19+(00U/33U/34U/37U)+581+(810/853)+(P44/P47)+(PBF/PBG)+U45+20U+897+234 | | | | | | | * | 0,00 |
| | | | Only in conjunction with U19+(00U/33U/34U)+(P59/950)+458+581+(810/853)+877+P17+(P44/P47)+P49+(PBF/PBG)+U22+U45+20U+897+234 | | | | * | | | | 0,00 |
| | | | Only in conjunction with U19+(00U/33U/34U/37U)+(P59/950)+458+581+(810/853)+877+P17+(P44/P47)+P49+(PBF/PBG)+U22+U45+20U+897+234 | | * | * | | * | | | 0,00 |
| PDC | | | i.V.m. Code U19 | • | • | • | • | • | • | - | 2.068,50 |
| PDC | | | i.V.m. Code U19 | - | - | - | - | - | - | LS | 0,00 |
| | | | i.V.m. Code PBF+U19 | LS | LS | LS | LS | LS | LS | LS | 4.799,00 |
| | | | i.V.m. Code PBF+U19 | LS | LS | LS | LS | LS | LS | LS | 2.169,00 |
| | | | i.V.m. Code PBF | LS | LS | LS | LS | LS | LS | LS | 4.452,00 |
| | | | i.V.m. Code PBF | LS | LS | LS | LS | LS | LS | LS | 1.822,00 |
| PDC | | | i.V.m. S-Code 8P3+PBG | • | • | • | • | • | • | - | 1.443,75 |
| | | | i.V.m. S-Code 8P3+PBG | LS | LS | LS | LS | LS | LS | LS | 1.632,00 |
| | | | i.V.m. Code PSN | LS | LS | LS | LS | LS | LS | LS | 0,00 |
| PDD | Premium Plus Package | | | LS | LS | LS | LS | LS | LS | LS | 8.049,00 |
| | | | | LS | LS | LS | LS | LS | LS | LS | 5.418,00 |
| | | | Includes codes 242+400+458+581+642+73B+77B+(853/810)+859+877+897+P17+P47+P49+(PBG/PBF)+U22+U45 | | | | | | | * | 0,00 |
| | | | Includes codes 242+400+458+581+642+73B+77B+(853/810)+859+877+897+P17+P47+P49+P59+(PBG/PBF)+U22+U45 | * | * | * | * | * | * | | 0,00 |
| | | | Includes codes 400+458+581+73B+77B+(853/810)+859+877+897+P17+P47+P49+(PBG/PBF)+U22+U45 | | | | | | | * | 0,00 |
| | | | Includes codes 400+458+581+73B+77B+(853/810)+859+877+897+P17+P47+P49+P59+(PBG/PBF)+U22 | | | | | * | | | 0,00 |
| | | | Includes codes 400+458+581+73B+77B+(853/810)+859+877+897+P17+P47+P49+P59+(PBG/PBF)+U22+U45 | * | * | * | * | * | * | | 0,00 |
| | | | Only in conjunction with (241/242)+458+463+73B+77B+(810/853)+877+950+P17+P49+(PBF/PBG)+U22+U45+581+586+(641/642)+20U+U19+897+P47+(00U/33U/34U/37U) | * | | | | | | | 0,00 |
| | | | Only in conjunction with (241/242)+458+463+73B+77B+(810/853)+877+950+P17+P49+(PBF/PBG)+U22+U45+586+581+(-632/641)+20U+U19+897+P47+(00U/33U/34U/37U) | | | | | | * | | 0,00 |

| | | | | | | | | | | | | | | | |
|-----|--|--|---|--|---|---|---|---|---|---|---|---|--|--|-----------|
| | | | Only in conjunction with (241/242)+458+463+77B+(810/853)+877+950+P17+P49+(PBF/PBG)+U22+U45+581+586+(641/642)+20U +U19+897+P47+(00U/33U/34U) | | | | * | | | | | | | | 0,00 |
| | | | Only in conjunction with (241/242)+458+463+77B+(810/853)+877+950+P17+P49+(PBF/PBG)+U22+U45+581+586+(641/642)+20U +U19+897+P47+(00U/33U/34U/37U) | | * | * | | * | | | | | | | 0,00 |
| | | | Only in conjunction with (241/242)+463+73B+77B+(810/853)+(PBF/PBG)+U45+581+586+(- 632/641)+20U+U19+897+P47+(00U/33U/34U/37U) | | | | | | | | | * | | | 0,00 |
| | | | Only in conjunction with 463+77B+(810/853)+950+PBG+U45+586+640+U19+P47 | | | | | | | | | | | | 0,00 |
| | | | i.V.m. Code U19 | | ● | ● | ● | ● | ● | ● | ● | - | | | 5.575,50 |
| | | | i.V.m. Code U19 | | - | - | - | - | - | - | - | ● | | | 3.202,50 |
| | | | i.V.m. Code PBF+U19 | | ● | ● | ● | ● | ● | ● | ● | - | | | 8.306,00 |
| | | | i.V.m. Code PBF+U19 | | - | - | - | - | - | - | - | ● | | | 5.676,00 |
| | | | i.V.m. Code PBF | | ● | ● | ● | ● | ● | ● | ● | - | | | 7.959,00 |
| | | | i.V.m. Code PBF | | - | - | - | - | - | - | - | ● | | | 5.329,00 |
| | | | i.V.m. S-Code 8P3 + PBG | | ● | ● | ● | ● | ● | ● | ● | - | | | 4.950,75 |
| | | | i.V.m. S-Code 8P3 + PBG | | - | - | - | - | - | - | - | ● | | | 3.202,50 |
| | | | i.V.m. Code PSQ | | ● | ● | ● | ● | ● | ● | ● | - | | | 0,00 |
| PGC | | Winter Package Plus with 43.2 cm (17-inch) winter wheel and tyre | | | ● | ● | ● | ● | ● | ● | ● | - | | | 1.943,00 |
| | | | Includes codes 4R9+PAV | | * | * | * | * | * | * | * | - | | | 0,00 |
| | | | Not in conjunction with PGL | | * | * | * | * | * | * | * | - | | | 0,00 |
| | | | Only in conjunction with L | | * | * | * | * | * | * | * | - | | | 0,00 |
| | | | Only in conjunction with PAV+4R9 | | * | * | * | * | * | * | * | - | | | 0,00 |
| | | | i.V.m. Code PSA/PSD/PSE/PSI | | ● | ● | ● | ● | ● | ● | ● | - | | | 1.665,00 |
| | | | i.V.m. Code PSJ/PSN/PSQ | | ● | ● | ● | ● | ● | ● | ● | - | | | 1.665,00 |
| PGL | | Winter Package Plus with 48.3 cm (19-inch) winter wheel and tyre | | | ● | ● | ● | ● | ● | ● | ● | - | | | 2.730,00 |
| | | | Includes codes 5R2+PAV | | * | * | * | * | * | * | * | - | | | 0,00 |
| | | | Not in conjunction with PGC | | * | * | * | * | * | * | * | - | | | 0,00 |
| | | | Only in conjunction with L | | * | * | * | * | * | * | * | - | | | 0,00 |
| | | | Only in conjunction with PAV+5R2 | | * | * | * | * | * | * | * | - | | | 0,00 |
| | | | i.V.m. Code PSA/PSD/PSE/PSI | | ● | ● | ● | ● | ● | ● | ● | - | | | 2.452,00 |
| | | | i.V.m. Code PSJ/PSN/PSQ | | ● | ● | ● | ● | ● | ● | ● | - | | | 2.452,00 |
| PGP | | Winter Package Plus with 48.3 cm (19-inch) winter wheel and tyre | | | - | - | - | - | - | - | - | ● | | | 3.885,00 |
| | | | Includes codes 8R4+PAV | | | | | | | | | * | | | 0,00 |
| | | | Only in conjunction with L | | | | | | | | | * | | | 0,00 |
| | | | Only in conjunction with PAV+8R4 | | | | | | | | | * | | | 0,00 |
| | | | i.V.m. Code PSJ/PSN/PSQ | | - | - | - | - | - | - | - | ● | | | 3.607,00 |
| PSA | | Entry | | | ● | ● | ● | ● | ● | ● | ● | - | | | 1.544,00 |
| | | | Includes codes (00U/33U/34U)+70B+873+942+(B51/R66)+PBG | | * | * | * | * | * | * | * | - | | | 0,00 |
| | | | Includes codes (00U/34U)+70B+873+942+(B51/R66)+PBG | | | | | | | * | * | - | | | 0,00 |
| | | | Only in conjunction with 873+(B51/R66)+942+PBG+(00U/33U/34U)+70B | | * | * | * | * | * | * | * | - | | | 0,00 |
| PSD | | Entry Advanced | | | ● | ● | ● | ● | ● | ● | ● | - | | | 2.998,00 |
| | | | Includes codes (00U/33U/34U)+70B+873+942+(B51/R66)+PBG+PDA | | * | * | * | * | * | * | * | - | | | 0,00 |
| | | | Includes codes (00U/34U)+70B+873+942+(B51/R66)+PBG+PDA | | | | | | | * | * | - | | | 0,00 |
| | | | Only in conjunction with PDA+873+(B51/R66)+942+PBG+(00U/33U/34U)+70B | | * | * | * | * | * | * | * | - | | | 0,00 |
| PSE | | Progressive Line Advanced | | | ● | ● | ● | ● | ● | ● | ● | - | | | 4.353,00 |
| | | | Includes codes (00U/33U/34U)+70B+873+942+(B51/R66)+P59+PBG+PDA | | * | * | * | * | * | * | * | - | | | 0,00 |
| | | | Includes codes (00U/34U)+70B+873+942+(B51/R66)+P59+PBG+PDA | | | | | | | * | * | - | | | 0,00 |
| | | | Only in conjunction with PDA+873+(B51/R66)+942+PBG+(00U/33U/34U)+70B+P59 | | * | * | * | * | * | * | * | - | | | 0,00 |
| PSI | | Progressive Line Advanced Plus | | | ● | ● | ● | ● | ● | ● | ● | - | | | 5.529,00 |
| | | | Includes codes (00U/33U/34U)+70B+873+942+(B51/R66)+P59+PBG+PDB | | * | * | * | * | * | * | * | - | | | 0,00 |
| | | | Includes codes (00U/34U)+70B+873+942+(B51/R66)+P59+PBG+PDB | | | | | | | * | * | - | | | 0,00 |
| | | | Only in conjunction with PDB+873+(B51/R66)+942+PBG+(00U/33U/34U)+70B+P59 | | * | * | * | * | * | * | * | - | | | 0,00 |
| PSJ | | AMG Line Advanced Plus | | | ● | ● | ● | ● | ● | ● | ● | - | | | 7.629,00 |
| | | | Includes codes (00U/33U/34U)+70B+(840/U50)+873+942+950+(B51/R66)+PBG+PDB | | * | * | * | * | * | * | * | - | | | 0,00 |
| | | | Includes codes (00U/34U)+70B+(840/U50)+873+942+950+(B51/R66)+PBG+PDB | | | | | | | * | * | - | | | 0,00 |
| | | | Only in conjunction with PDB+873+(B51/R66)+942+PBG+(00U/33U/34U)+70B+950+(840/U50) | | * | * | * | * | * | * | * | - | | | 0,00 |
| PSJ | | Advanced Plus | | | - | - | - | - | - | - | - | ● | | | 1.859,00 |
| | | | Includes codes (00U/33U/34U)+70B+(840/U50)+873+942+(B51/R66)+PBG+PDB | | | | | | | | | * | | | 0,00 |
| | | | Only in conjunction with PDB+873+(B51/R66)+(00U/33U/34U)+PBG+942+70B+(840/U50) | | | | | | | | | * | | | 0,00 |
| PSN | | AMG Line Premium | | | ● | ● | ● | ● | ● | ● | ● | - | | | 9.261,00 |
| | | | Includes codes (00U/33U/34U)+70B+(840/U50)+873+942+950+(B51/R66)+PBG+PDC | | * | * | * | * | * | * | * | - | | | 0,00 |
| | | | Includes codes (00U/34U)+70B+(840/U50)+873+942+950+(B51/R66)+PBG+PDC | | | | | | | * | * | - | | | 0,00 |
| | | | Only in conjunction with PDC+873+(B51/R66)+942+PBG+(00U/33U/34U)+70B+950+(840/U50) | | * | * | * | * | * | * | * | - | | | 0,00 |
| PSN | | Premium | | | - | - | - | - | - | - | - | ● | | | 3.492,00 |
| | | | Includes codes (00U/33U/34U)+70B+(840/U50)+873+942+(B51/R66)+PBG+PDC | | | | | | | | | * | | | 0,00 |
| | | | Only in conjunction with PDC+873+(B51/R66)+(00U/33U/34U)+PBG+942+70B+(840/U50) | | | | | | | | | * | | | 0,00 |
| PSQ | | AMG Line Premium Plus | | | ● | ● | ● | ● | ● | ● | ● | - | | | 12.768,00 |
| | | | Includes codes (00U/33U/34U)+70B+(840/U50)+873+942+950+(B51/R66)+PBG+PDD | | * | * | * | * | * | * | * | - | | | 0,00 |
| | | | Includes codes (00U/34U)+70B+(840/U50)+873+942+950+(B51/R66)+PBG+PDD | | | | | | | * | * | - | | | 0,00 |
| | | | Only in conjunction with PDD+873+(B51/R66)+942+PBG+(00U/33U/34U)+70B+950+(840/U50) | | * | * | * | * | * | * | * | - | | | 0,00 |
| PSQ | | Premium Plus | | | - | - | - | - | - | - | - | ● | | | 6.999,00 |
| | | | Includes codes (00U/33U/34U)+70B+(840/U50)+873+942+(B51/R66)+PBG+PDD | | | | | | | | | * | | | 0,00 |
| | | | Only in conjunction with PDD+873+(B51/R66)+(00U/33U/34U)+PBG+942+70B+(840/U50) | | | | | | | | | * | | | 0,00 |
| R | | Right-hand drive | | | ● | ● | ● | ● | ● | ● | ● | - | | | 1.113,00 |

| | | | | | | | | | | | | | | |
|--|-----|---|--|---|---|---|---|---|---|---|---|--|--|----------|
| | R01 | Summer tyres | | | | | | | | | | | | 0,00 |
| | | | Only in conjunction with 25R/(01R/52R/R38/R74)+-R66/(01R/52R/R38/R74)+R66/(R58/27R)+-R66/(R58/27R)+R66/R62/R88/RVT/RVU/RTF/RTG | | | | | * | | | | | | 0,00 |
| | | | Only in conjunction with 25R/(01R/52R/R38/R74)+-R66/(01R/52R/R38/R74)+R66/(R58/27R)+-R66/(R58/27R)+R66/R62/R62/RVT/RVU/RTF/RTG | | | | | * | | | | | | 0,00 |
| | | | Only in conjunction with 25R/(01R/52R/R38/R74)+-R66/(01R/52R/R38/R74)+R66/27R+-R66/27R+R66/R62/RVT/RVU/RTF/RTG | * | * | * | | | * | | | | | 0,00 |
| | | | Only in conjunction with 27R+R66/RVT/RVU/RTF/RTG | | | | | | | | | | | 0,00 |
| | | | Only in conjunction with RVL+-R66/RTH/RVZ/--(RTH/RVL/RVZ) | | | | | | | | * | | | 0,00 |
| | R02 | All-season tyres | | - | - | - | - | - | • | • | | | | 158,00 |
| | | | Not in conjunction with 652 | | | | | | * | * | | | | 0,00 |
| | | | Only in conjunction with R66+(27R/01R/52R/R38/R74/RTF/RTG) | | | | | | * | | | | | 0,00 |
| | | | Only in conjunction with R66+(RTH/RVL/RVZ) | | | | | | | | * | | | 0,00 |
| | R03 | Sports tyres | | • | • | • | • | • | • | • | - | | | 315,00 |
| | | | Only in conjunction with RTF | * | * | * | * | * | * | * | | | | 0,00 |
| | R38 | 45.7 cm (18-inch) 5-twin-spoke light-alloy wheels | | • | • | • | • | • | • | • | - | | | 630,00 |
| | | | Not in conjunction with 950 | * | * | * | * | * | * | * | | | | 0,00 |
| | | | Only in conjunction with R01 | * | * | * | * | * | * | | | | | 0,00 |
| | | | Only in conjunction with R02+R66 | | | | | | | | | | | 0,00 |
| | | | Only in conjunction with R02+R66/R01 | | | | | | | * | | | | 0,00 |
| | | | i.V.m. Code (P55+P59)/P59 | ○ | ○ | ○ | ○ | ○ | ○ | ○ | - | | | 0,00 |
| | R58 | 48.3 cm (19") 10-spoke light-alloy wheels | | - | - | - | • | • | - | - | | | | 1.103,00 |
| | | | Not in conjunction with 950/R66 | | | | * | * | | | | | | 0,00 |
| | | | Only in conjunction with R01 | | | | * | * | | | | | | 0,00 |
| | | | i.V.m. Code P55/P59 | - | - | - | • | • | - | - | | | | 473,00 |
| | R62 | 43.2 cm (17-inch) 5-twin-spoke light-alloy wheels | | ○ | ○ | ○ | ○ | ○ | ○ | ○ | - | | | 0,00 |
| | | | Not in conjunction with 950/PAD | * | | | * | * | | | | | | 0,00 |
| | | | Not in conjunction with 950/PAD/847 | | * | * | | | * | | | | | 0,00 |
| | R66 | run-flat tyres | | • | • | • | • | • | • | • | • | | | 231,00 |
| | | | Not in conjunction with 25R/R03/645+(R58/RTF) | | | | * | * | | | | | | 0,00 |
| | | | Not in conjunction with 25R/R03/645+RTF | * | * | * | | | | | | | | 0,00 |
| | | | Not in conjunction with 25R/R03/645+RTF/R01 | | | | | | * | | | | | 0,00 |
| | | | Not in conjunction with B51 | * | * | * | * | * | * | * | * | | | 0,00 |
| | | | Not in conjunction with R01/RWX/RWY | | | | | | | * | | | | 0,00 |
| | | | Only in conjunction with R01+(27R/01R/52R/R38/R74/RTF/RTG) | * | * | * | | | | | | | | 0,00 |
| | | | Only in conjunction with R01+(R58/27R/01R/52R/R38/R74/RTF/RTG) | | | | * | * | | | | | | 0,00 |
| | | | Only in conjunction with R02+(27R/01R/52R/R38/R74/RTF/RTG) | | | | | | * | | | | | 0,00 |
| | | | Only in conjunction with R02+(R01+(RTF/RTG)/RTF/RTG/R01+27R/52R/R38/01R/R74/27R) | | | | | | | | | | | 0,00 |
| | | | Only in conjunction with R02+(RTH/RVL/RVZ) | | | | | | | * | | | | 0,00 |
| | | | i.V.m. Code PSA/PSD/PSE/PSI | • | • | • | • | • | • | • | • | | | 179,00 |
| | | | i.V.m. Code PSJ/PSN/PSQ | • | • | • | • | • | • | • | • | | | 179,00 |
| | R74 | 45.7 cm (18-inch) 5-twin-spoke light-alloy wheels | | • | • | • | • | • | • | • | - | | | 630,00 |
| | | | Not in conjunction with 950 | * | * | * | * | * | * | * | | | | 0,00 |
| | | | Only in conjunction with R01 | * | * | * | * | * | * | | | | | 0,00 |
| | | | Only in conjunction with R02+R66 | | | | | | | | | | | 0,00 |
| | | | Only in conjunction with R02+R66/R01 | | | | | | * | | | | | 0,00 |
| | | | i.V.m. Code P59 | ○ | ○ | ○ | ○ | ○ | ○ | ○ | - | | | 0,00 |
| | R88 | 6-double-spoke light-alloy wheel 43,2 cm (17") | | - | - | - | - | • | - | - | | | | 1.103,00 |
| | | | Not in conjunction with 950/R66 | | | | | * | | | | | | 0,00 |
| | | | Only in conjunction with R01 | | | | | * | | | | | | 0,00 |
| | | | i.V.m. Code P59/P55 | - | - | - | - | • | - | - | | | | 473,00 |
| | RTF | 48.3 cm (19-inch) AMG 5-twin-spoke light-alloy wheels | | ○ | ○ | ○ | ○ | ○ | ○ | ○ | - | | | 0,00 |
| | | | Only in conjunction with 950+(R01/645+-R66/R02+R66/R03+-R66) | | | | | | * | | | | | 0,00 |
| | | | Only in conjunction with 950+(R01/645+-R66/R03+-R66) | * | * | * | * | * | | | | | | 0,00 |
| | | | Only in conjunction with 950+(R01/R02+R66/R03+-R66) | | | | | | | | | | | 0,00 |
| | RTG | 48.3 cm (19-inch) AMG 5-twin-spoke light-alloy wheels | | • | • | • | • | • | • | • | - | | | 1.523,00 |
| | | | i.V.m. Code (P55+P59)/P59/P55 | • | • | • | • | • | • | • | - | | | 893,00 |
| | | | i.V.m. Code 950 | • | • | • | • | • | • | • | - | | | 473,00 |
| | | | i.V.m. Code P55+950 | ○ | ○ | ○ | ○ | ○ | ○ | ○ | - | | | 0,00 |
| | RTH | 48.3 cm (19-inch) AMG 5-twin-spoke light-alloy wheels | | - | - | - | - | - | - | S | | | | 0,00 |
| | | | Only in conjunction with R02+R66/R01+-R66 | | | | | | | * | | | | 0,00 |
| | RTW | 50.8 cm (20-inch) AMG 5-twin-spoke light-alloy wheels | | - | - | - | - | - | - | • | | | | 1.050,00 |
| | | | Only in conjunction with R01 | | | | | | | * | | | | 0,00 |
| | RTX | 50.8 cm (20-inch) AMG 5-twin-spoke light-alloy wheels | | - | - | - | - | - | - | • | | | | 1.050,00 |
| | | | Only in conjunction with R01 | | | | | | | * | | | | 0,00 |
| | RVL | 48.3 cm (19-inch) AMG 10-spoke light-alloy wheels | | - | - | - | - | - | - | • | | | | 578,00 |
| | | | Only in conjunction with R02+R66/R01+-R66 | | | | | | | * | | | | 0,00 |
| | RVT | 50.8 cm (20-inch) AMG multi-spoke alloy wheels | | • | • | • | • | • | • | • | - | | | 2.048,00 |
| | | | Not in conjunction with R66 | * | * | | * | * | * | | | | | 0,00 |
| | | | Not in conjunction with U28/R66 | | | * | | | | | | | | 0,00 |
| | | | Only in conjunction with R01 | * | * | * | * | * | * | | | | | 0,00 |
| | | | i.V.m. Code (P55+P59)/P55/P59 | • | • | • | • | • | • | • | - | | | 1.628,00 |
| | | | i.V.m. Code 950/ (950+P55) | • | • | • | • | • | • | • | - | | | 1.365,00 |
| | RVU | 50.8 cm (20-inch) AMG multi-spoke alloy wheels | | • | • | • | • | • | • | • | - | | | 2.048,00 |

| | | | | | | | | | | | | |
|--|-----|---|--|---|---|---|---|---|---|---|---|----------|
| | | | Not in conjunction with R66 | * | * | | * | * | * | | | 0,00 |
| | | | Not in conjunction with U28/R66 | | | * | | | | | | 0,00 |
| | | | Only in conjunction with R01 | * | * | * | * | * | * | | | 0,00 |
| | | | i.V.m. Code (P55+P59)/P55/P59 | ● | ● | ● | ● | ● | ● | - | | 1.628,00 |
| | | | i.V.m. Code 950/ (950+P55) | ● | ● | ● | ● | ● | ● | - | | 1.365,00 |
| | RVZ | 48.3 cm (19-inch) AMG 10-spoke light-alloy wheels | | - | - | - | - | - | - | ● | | 578,00 |
| | | | Only in conjunction with R02+R66/R01+R66 | | | | | | | * | | 0,00 |
| | RWX | 53.3 cm (21-inch) AMG multi-spoke light-alloy wheels | | - | - | - | - | - | - | ● | | 1.260,00 |
| | RWY | 53.3 cm (21-inch) AMG multi-spoke light-alloy wheels | | - | - | - | - | - | - | ● | | 1.628,00 |
| | U01 | Status display for rear seat belts in instrument cluster | | ○ | ○ | ○ | ○ | ○ | ○ | ○ | | 0,00 |
| | U10 | Automatic front passenger airbag deactivation | | ● | ● | ● | ● | ● | ● | ● | | 100,00 |
| | | | Only in conjunction with 222 | | | | | * | | | | 0,00 |
| | | | i.V.m. S-Code 51B | ○ | ○ | ○ | ○ | ○ | ○ | ○ | | 0,00 |
| | U12 | Velour floor mats | | ○ | ○ | ○ | ○ | ○ | ○ | - | | 0,00 |
| | | | Not in conjunction with 950 | * | * | * | * | * | * | * | | 0,00 |
| | | | Not in conjunction with U26 | * | * | * | * | * | * | * | | 0,00 |
| | U17 | Omission of MANUFAKTUR seat belts in red | | - | - | - | - | - | - | ○ | | 0,00 |
| | | | Not in conjunction with Y05 | | | | | | | * | | 0,00 |
| | | | Only in conjunction with 651A | | | | | | | * | | 0,00 |
| | U19 | MBUX augmented reality for navigation | | ○ | ○ | ○ | ○ | ○ | ○ | ○ | | 0,00 |
| | | | Not in conjunction with PDB | * | * | * | * | * | * | * | | 0,00 |
| | | | Only in conjunction with (PDC/PDD)+365+(P44/P47) | * | * | * | * | * | * | * | | 0,00 |
| | | | Only in conjunction with 365+(P44/P47) | | | | | | | * | | 0,00 |
| | U22 | 4-way lumbar support | | ○ | ○ | ○ | ○ | ○ | ○ | ○ | | 0,00 |
| | | | Only in conjunction with 221 | | | | * | * | | | | 0,00 |
| | U26 | AMG floor mats | | ○ | ○ | ○ | ○ | ○ | ○ | ○ | S | 0,00 |
| | | | Not in conjunction with U12 | * | * | * | * | * | * | * | | 0,00 |
| | | | Only in conjunction with 950 | * | * | * | * | * | * | * | | 0,00 |
| | U27 | Exterior door handles in chrome | | - | - | - | - | - | - | - | | 53,00 |
| | | | Not in conjunction with 889 | | | | | | | | | 0,00 |
| | U28 | Sports brake system | | ○ | ○ | ○ | ○ | ○ | ○ | ○ | - | 0,00 |
| | | | Not in conjunction with 4R9/U29 | * | * | * | * | * | * | * | | 0,00 |
| | | | Not in conjunction with U29 | * | * | * | * | * | * | * | | 0,00 |
| | | | Only in conjunction with 950 | * | * | * | * | * | * | * | | 0,00 |
| | U29 | Braking system with larger brake discs on the front axle | | ○ | ○ | ○ | ○ | ○ | ○ | ○ | - | 0,00 |
| | | | Not in conjunction with U28 | * | * | * | * | * | * | * | | 0,00 |
| | | | Only in conjunction with PAD | * | * | * | * | * | * | * | | 0,00 |
| | U35 | 12 V socket | | ○ | ○ | ○ | ○ | ○ | ○ | ○ | ○ | 0,00 |
| | | | Only in conjunction with 942 | * | * | * | * | * | * | * | * | 0,00 |
| | U37 | Front fog lamps | | ● | ● | ● | ● | ● | ● | ● | - | 195,00 |
| | | | Not in conjunction with 772/950 | * | * | * | * | * | * | * | | 0,00 |
| | U40 | Partition net | | ● | ● | ● | ● | ● | ● | ● | ● | 158,00 |
| | U41 | Water separator and lubrication package | | - | - | ○ | - | - | - | - | | 0,00 |
| | | | Only in conjunction with R | | | * | | | | | | 0,00 |
| | U45 | AMG illuminated door sills with "AMG" lettering and with exchange | | - | - | - | - | - | - | - | ○ | 0,00 |
| | | | Not in conjunction with PDB | | | | | | | * | | 0,00 |
| | U45 | Door sills with "Mercedes-Benz" lettering, illuminated and with exc | | ○ | ○ | ○ | ○ | ○ | ○ | ○ | - | 0,00 |
| | | | Not in conjunction with PDB | | | | | | | | | 0,00 |
| | | | Only in conjunction with PDC/PDD | * | * | * | * | * | * | * | | 0,00 |
| | U50 | Omission of heat-insulating dark-tinted glass | | ○ | ○ | ○ | ○ | ○ | ○ | ○ | | 0,00 |
| | | | Not in conjunction with 840 | * | * | * | * | * | * | * | * | 0,00 |
| | | | Not in conjunction with P55 | * | * | * | * | * | * | * | * | 0,00 |
| | | | Not in conjunction with P60 | | | | | | | * | | 0,00 |
| | | | Only in conjunction with P59/950 | * | * | * | * | * | * | * | * | 0,00 |
| | U55 | Multi-link axle | | S | S | S | S | S | S | S | S | 0,00 |
| | U59 | Seat Comfort Package | | ○ | ○ | ○ | ○ | ○ | ○ | ○ | ○ | 0,00 |
| | U60 | Pedestrian protection | | ○ | ○ | ○ | ○ | ○ | ○ | ○ | ○ | 0,00 |
| | U62 | Light and Sight Package | | ○ | ○ | ○ | ○ | ○ | ○ | ○ | ○ | 0,00 |
| | | | Includes codes 77B | * | * | * | * | * | * | * | * | 0,00 |
| | U70 | red-painted brake callipers | | - | - | - | - | - | - | ● | | 336,00 |
| | U79 | BlueTEC diesel emission control system including AdBlue® reservo | | ○ | ○ | ○ | ○ | - | - | - | | 0,00 |
| | U80 | 115 V socket | | - | - | - | - | - | ● | ● | | 121,00 |
| | U88 | AMG steering wheel buttons | | - | - | - | - | - | - | ○ | | 0,00 |
| | Y05 | MANUFAKTUR seat belts in red | | - | - | - | - | - | - | ○ | | 0,00 |
| | | | Not in conjunction with U17 | | | | | | | * | | 0,00 |
| | | | Only in conjunction with 651A | | | | | | | * | | 0,00 |