

## Optional extras for the B-Class

Valid from 15.09.2011

		B Sportstourer				LLP (EUR)
Code	Designation	B 180 CDI BlueEFFICIENCY 246.200	B 200 CDI BlueEFFICIENCY 246.201	B 180 BlueEFFICIENCY 246.242	B 200 BlueEFFICIENCY 246.243	
L	Left-hand drive	○	○	○	○	0,00
191U	Cosmos black metallic	●	●	●	●	490,00
240U	Lotus blue metallic	●	●	●	●	490,00
589U	Jupiter red	○	○	○	○	0,00
650U	Cirrus white	○	○	○	○	0,00
696U	Night black	○	○	○	○	0,00
761U	Polar silver metallic	●	●	●	●	490,00
787U	Mountain grey metallic	●	●	●	●	490,00
893U	monolithgrau	●	●	●	●	490,00
894U	universumblau	●	●	●	●	490,00
895U	canyonbeige	●	●	●	●	490,00
001A	Fabric Venlo black Not in conjunction with Code 248, 400, 460, 952, P34, U57 or U59	○	○	○	○	0,00
011A	Fabric Domburg black Not in conjunction with Code 248, 952 or P34 Only in conjunction with Code U59	○	○	○	○	0,00
018A	Fabric Domburg grey Not in conjunction with Code 248, 952 or P34 Only in conjunction with Code U59	○	○	○	○	0,00
101A	Black ARTICO man-made leather Not in conjunction with Code P34 Only in conjunction with Code U59 in conjunction with Code 952	●	●	●	●	240,00
		●	●	●	●	120,00
105A	Fabric/leather saharabeige Not in conjunction with Code P34 Only in conjunction with Code U59 in conjunction with Code 952	●	●	●	●	240,00
		●	●	●	●	120,00
108A	Alpaca grey ARTICO man-made leather Not in conjunction with Code P34 Only in conjunction with Code U59 in conjunction with Code 952	●	●	●	●	240,00
		●	●	●	●	120,00
201A	Leather black Not in conjunction with Code 248 Only in conjunction with Code P34 and U59	○	○	○	○	0,00
204A	Leather Not in conjunction with Code 248 Only in conjunction with Code P34 and U59	○	○	○	○	0,00
208A	Leather grey Not in conjunction with Code 248 Only in conjunction with Code P34 and U59	○	○	○	○	0,00
411	6-speed manual transmission Not in conjunction with Code 239	S	S	S	S	0,00
429	7G-DCT expected delivery first quarter 2012 Only in conjunction with Code 428 Only in conjunction with Code 440 or 239 Only in conjunction with Code U64	●	●	●	●	1.820,00
601A	Fabric black/multicolor Not in conjunction with Code 248 or P34 Only in conjunction with Code 952 and U59	○	○	○	○	0,00
608A	Fabric/leather slate grey Not in conjunction with Code 248 or P34 Only in conjunction with Code 952 and U59	○	○	○	○	0,00
22P	Lane tracking package	●	●	●	●	750,00

## Optional extras for the B-Class

Valid from 15.09.2011

		B Sportstourer				LLP (EUR)
Code	Designation	B 180 CDI BlueEFFICIENCY 246.200	B 200 CDI BlueEFFICIENCY 246.201	B 180 BlueEFFICIENCY 246.242	B 200 BlueEFFICIENCY 246.243	
	Certain countries only only in conjunction with Code 234, 476					
30P	<b>Stowage Space package</b> only in conjunction with Code 286, 939 and (932 or 682)	•	•	•	•	190,00
900	<b>Chrome package</b> Not in conjunction with Code 952 or P55 only in conjunction with Code 001A or 011A, 018A, 101A, 105A, 108A, 201A, 204A or 208A, Code 543, 736 or H03, or H88	•	•	•	•	295,00
952	<b>Sports package</b>  Not in conjunction with Code 900 Only in conjunction with Code 101A, 105A, 108A/201A, 204A, 208A/601A, 608A; 280, 543 & 485/486; 51U/58U, H89/H03/736; R24/R43, 01R, 25R, 26R	- •	• -	- •	• -	1.320,00 1.495,00
P34	<b>Exclusive Package</b> in conjunction with Code 450 Not in conjunction with Code U12 Only in conjunction with Code 837 Not in conjunction with Code 248 Only in conjunction with Code 280, 736 oder H03; 880, 873, U12, U22, 200A  Only in conjunction with Code 900 or 952 <b>in conjunction with Code 952</b>	•     •	•     •	•     •	•     •	1.615,00     1.275,00
P49	<b>Mirror package</b> only in conjunction with Code 249, 500	•	•	•	•	295,00
P54	<b>Anti-Theft Protection package</b> Certain countries only Consisting of: Code 551, 882	•	•	•	•	400,00
P55	<b>Night package</b> Not in conjunction with Code 965 Only in conjunction with Code 614 or 618 oder 621 or 622; 840, 01R, 952	•	•	•	•	750,00
U59	<b>Seat comfort package</b> Not in conjunction with upholstery 001A <b>in conjunction with Code 952 or Code P34</b>	• ○	• ○	• ○	• ○	135,00 0,00
U62	<b>light and sight package</b> only in conjunction with Code 345, 543	•	•	•	•	290,00
U63	<b>Basic driving school package</b> expected delivery first quarter 2012 including code U59, U62, 931 Not in conjunction with Code 310 Only in conjunction with Code U59, U62, 931 <b>in conjunction with U64</b>	•     ○	•     ○	•     ○	•     ○	495,00     0,00
498	<b>Japanese version</b>	-	-	•	•	450,00
01R	<b>45.7 cm (18-inch) 5-twin-spoke light-alloy wheels</b>  Not in conjunction with Code 965, 645 Only in conjunction with Code R66, R01 <b>in conjunction with Code 952</b> <b>in conjunction with Code P55</b>	- •  • ○	• -  • ○	- •  • ○	• -  • ○	1.190,00 1.440,00  500,00 0,00
202	<b>Literature in German</b>	○	○	○	○	0,00
205	<b>Literature in English</b>	○	○	○	○	0,00
206	<b>Literature in Italian</b>	○	○	○	○	0,00
207	<b>Literature in French</b>	○	○	○	○	0,00
208	<b>Literature in Spanish</b>	○	○	○	○	0,00
209	<b>Literature in Portuguese</b>	○	○	○	○	0,00

## Optional extras for the B-Class

Valid from 15.09.2011

		B Sportstourer				LLP (EUR)
Code	Designation	B 180 CDI BlueEFFICIENCY 246.200	B 200 CDI BlueEFFICIENCY 246.201	B 180 BlueEFFICIENCY 246.242	B 200 BlueEFFICIENCY 246.243	
210	Swedish literature	○	○	○	○	0,00
213	Direct-steer system Only in conjunction with Code 486	○	○	○	○	0,00
218	Reversing camera	●	●	●	●	290,00
220	PARKTRONIC system (PTS) Only Japan	-	-	●	●	570,00
234	Blind Spot Assist Certain countries only Certain countries only in conj. with Code 509 or 512 or 527 Only in conj. with Code 22P	○	○	○	○	0,00
235	Active parking assist Not Japan	●	●	●	●	675,00
239	DISTRONIC PLUS Certain countries only expected delivery first quarter 2012 Not in conjunction with Code 252 or 440 Only in conjunction with Code 429	●	●	●	●	860,00
23Z	Vorrüstung Tetra Funk Motorola expected delivery first quarter 2012 Only in conjunction with Code 970, 974 or 975	●	●	●	●	140,00
240	LED-daytime running lights Not in conjunction with Code U37 Only in conj. with Code 614, 618, 621 or 622	○	○	○	○	0,00
241	Front seat left, elect.adjust.w.mem. switch Only in conjunction with Code 001A Only in conjunction with Code 275 Right-hand-drive vehicles only	●	●	●	●	280,00
242	Front pass. seat, electrically adj. with memory function LHD version Not in conjunction with Code 001A or U57 Only in conjunction with Code 275	●	●	●	●	280,00
248	Rear seats with integrated child seats expected delivery first quarter 2012 Not in conjunction with Code U57 or P34 Only in conjunction with Code 101A, 105A, 108A in conjunction with 965 in conjunction with 450	● ○	● ○	● ○	● ○	330,00 110,00 0,00
249	Automatically dimming int.and ext.mirrors Only in conjunction with Code P49	○	○	○	○	0,00
24Z	Vorrüstung Tetra Funk Sepura expected delivery first quarter 2012 Only in conjunction with Code 970, 974 or 975	●	●	●	●	140,00
252	COLLISION PREVENTION ASSIST Certain countries only Not in conjunction with Code 239	S	S	S	S	0,00
257	round LED daytime running lights Not in conjunction with Code 614, 615, 618, 621 or 622 Only cert. countries	S	S	S	S	0,00
25R	10-spoke 43.2 cm (17") light-alloy wheel Only in conjunction with Code 645 in conjunction with Code 952	- ● ○	● - ○	- ● ○	● - ○	660,00 910,00 0,00
25Z	Vorrüstung Analog Funk TDX9 expected delivery first quarter 2012	●	●	●	●	140,00

**Optional extras for the B-Class**  
Valid from 15.09.2011

		B Sportstourer				LLP (EUR)
Code	Designation	B 180 CDI BlueEFFICIENCY 246.200	B 200 CDI BlueEFFICIENCY 246.201	B 180 BlueEFFICIENCY 246.242	B 200 BlueEFFICIENCY 246.243	
	Only in conjunction with Code 970, 974 or 975					
260	Omission of model plate on boot lid	○	○	○	○	0,00
263	Number plate mounting for Asia/Mexico	○	○	○	○	0,00
26R	43.2 cm (17-inch) 7-twin-spoke light-alloy wheels	●	●	●	●	1.240,00
	Not in conjunction with Code 645	-	-	-	-	990,00
	in conjunction with Code 952	●	●	●	●	130,00
275	Memory package	●	●	●	●	335,00
	Not in conjunction with Code 001A					
	Only in conjunction with Code U22, U59					
280	Leather steering wheel	●	●	●	●	175,00
	i.V.m. 952 oder P34	○	○	○	○	0,00
286	Luggage net on driver's and front pass. backrest	○	○	○	○	0,00
	Only in conjunction with Code 30P					
290	windowbags	S	S	S	S	0,00
293	Sidebags in rear	●	●	●	●	375,00
294	Kneebag	S	S	S	S	0,00
299	PRE-SAFE® system	●	●	●	●	330,00
	Not in conjunction with Code 460					
301	Smoker package	●	●	●	●	45,00
310	Cup holder	●	●	●	●	25,00
	Only in conjunction with Code U63 or 938					
333	Special instrument panel	●	●	●	●	80,00
	expected delivery first quarter 2012					
	Only in conjunction with Code 965					
334	Two-way radio retainer in glove compartment	●	●	●	●	60,00
	expected delivery first quarter 2012					
	Only in conjunction with Code 965					
	in conjunction with 450	○	○	○	○	0,00
335	Two-way radio mount in boot	●	●	●	●	60,00
	expected delivery first quarter 2012					
	Only in conjunction with Code 965					
336	Preinstallation for taximeter	●	●	●	●	55,00
	expected delivery first quarter 2012					
	Only in conjunction with Code 965					
337	Taximeter integr.in the rear-view mirror	●	●	●	●	830,00
	expected delivery first quarter 2012					
	Only in conjunction with Code 965					
341	Taxi roof sign	●	●	●	●	245,00
	expected delivery first quarter 2012					
	not in conjunction with code 342					
	Only in conjunction with Code 965					
342	Connection, taxi roof sign	●	●	●	●	70,00
	expected delivery first quarter 2012					
	Not in conjunction with Code 413, 341, 970, 974, 975					
	Only in conjunction with Code 965					
345	Windscreen wiper with rain sensor	○	○	○	○	0,00
	Only in conjunction with Code U62					
356	Roof aerial for taxi two-way radio	●	●	●	●	195,00
	expected delivery first quarter 2012					
	not in conjunction with code 537					
	Only in conjunction with Code 965 or code 970, 974, 975					
	i.V.m. 386, 508, 509, 512, 527	●	●	●	●	115,00
386	Convenience telephony	●	●	●	●	350,00

## Optional extras for the B-Class

Valid from 15.09.2011

		B Sportstourer				LLP (EUR)
Code	Designation	B 180 CDI BlueEFFICIENCY 246.200	B 200 CDI BlueEFFICIENCY 246.201	B 180 BlueEFFICIENCY 246.242	B 200 BlueEFFICIENCY 246.243	
	Only in conjunction with Code 510, 512, 523 or 527					
400	<b>Rear armrest</b> Not in conjunction with Code 001A <b>in conjunction with Code U57</b>	● ○	● ○	● ○	● ○	165,00 0,00
413	<b>Panoramic sliding sunroof</b> Not in conjunction with Code 342, 970, 974, 975 Only in conjunction with Code 543, 51U	●	●	●	●	1.145,00
428	<b>Steering wheel shift buttons</b> Only in conjunction with Code 429	○	○	○	○	0,00
440	<b>Cruise control</b> Not in conjunction with Code 239 <b>in conjunction with Code 429</b>	● ○	● ○	● ○	● ○	250,00 0,00
442	<b>Luxury multifunction steering wheel</b>	S	S	S	S	0,00
450	<b>Taxi version, international</b> expected delivery first quarter 2012 Only in conj. w. Code 100A or 200A; 965, 334, 837	●	●	●	●	830,00
461	<b>Instrument with mileage reading</b> expected delivery first quarter 2012	○	○	○	○	0,00
462	<b>Instrument cluster with Asian characters</b> Cert. countries only	○	○	○	○	0,00
474	<b>Diesel particulate filter</b> Part of standard specification in Germany and WEU countries	●	●	-	-	475,00
476	<b>Lane keeping assist</b> Only in conjunction with Code 22P and Code 280	○	○	○	○	0,00
477	<b>Tyre pressure loss warning system</b>	S	S	S	S	0,00
485	<b>Comfort suspension</b>	S	S	S	S	0,00
486	<b>Sports suspension</b> Not in conjunction with Code 965, 970, 974, 975 Only in conjunction with Code 213 and 952	○	○	○	○	0,00
500	<b>Electrically folding exterior mirrors</b> Only in conjunction with Code P49	○	○	○	○	0,00
508	<b>Pre-installation for Becker® MAP PILOT</b> (C. coun. on.); on. in conj. w. Code 510/523	●	●	●	●	220,00
509	<b>Becker® MAP PILOT</b> (Certain countries only); only in conjunction with Code 510 or 523 required with code 22P for certain countries (additional price)	●	●	●	●	720,00
510	<b>Audio 20 CD</b>	●	●	●	●	150,00
512	<b>COMAND Online</b> (& in c. c. on. icw Code 513)	●	●	●	●	2.920,00
513	<b>Speed Limit Assist</b> (Certain c. only); only in conj. w. Code 512 /527	○	○	○	○	0,00
518	<b>Media Interface</b> Not in conjunction with Code 523	●	●	●	●	220,00
51U	<b>Roof liner fabric black</b> Only in conjunction with Code 413 or 952 or 204A	○	○	○	○	0,00
523	<b>Audio 20 CD</b> Not in conjunction with Code 498, 513, 518, 537, 810, 830	S	S	S	S	0,00
526	<b>Comand DVD (without navigation)</b> Only in conjunction with Code 498	-	-	●	●	1.100,00
527	<b>COMAND Online</b> (cert. c. o. in con. w. Code 513) Certain countries only	●	●	●	●	2.620,00
537	<b>Digital radio (DAB)</b> (C. c. on.) & not in conj. w. Code 356 or Z97	●	●	●	●	410,00

## Optional extras for the B-Class

Valid from 15.09.2011

		B Sportstourer				LLP (EUR)
Code	Designation	B 180 CDI BlueEFFICIENCY 246.200	B 200 CDI BlueEFFICIENCY 246.201	B 180 BlueEFFICIENCY 246.242	B 200 BlueEFFICIENCY 246.243	
	Only in conjunction with Code 510, 512 or 527					
538	<b>Attention Assist</b>	S	S	S	S	0,00
543	<b>Sun visors with illuminated vanity mirrors</b> Only in conj. with Code 413, U62, 900 or 952	O	O	O	O	0,00
550	<b>Trailer coupling</b> Not in conjunction with Code 460	•	•	•	•	790,00
551	<b>Anti-theft warning system</b> included in code P54 for certain countries Only in conjunction with Code 460 <b>in conjunction with Code P54</b>	•	•	•	•	250,00
		O	O	O	O	0,00
55R	<b>40.6 cm (16-inch) 10-spoke light-alloy wheels</b> Not in conjunction with Code 952, P55	- •	• -	- •	• -	250,00 400,00
567	<b>Vario-Rücksitzbank</b> Only in conjunction with Code U57	O	O	O	O	0,00
580	<b>Air conditioning system</b>	S	S	S	S	0,00
581	<b>THERMOTRONIC automatic climate control</b> Only in conjunction with Code 900 or 952	•	•	•	•	510,00
58U	<b>Roof liner fabric grey</b> Not in conjunction with Code 413, 204A or (105A in conjunction with Code 952)	S	S	S	S	0,00
600	<b>Headlamp cleaning system</b> Only in conj. w. Code 614 or 618, 621 or 622	O	O	O	O	0,00
608	<b>Adaptive Main Beam Assist</b> Only in conjunction with Code 621 or 622	O	O	O	O	0,00
613	<b>Headlamps for RHD vehicles</b> Only in conjunction with Code P55 Part of standard specification for LHD countries	O	O	O	O	0,00
614	<b>Bi-xenon headlamps</b> Not in conjunction with Code U37 On. icw Code 600 & 240	•	•	•	•	845,00
618	<b>Bi-xenon headlamps for RHD vehicles</b> Not in conjunction with Code U37 Only icw Code 600 & 240	•	•	•	•	845,00
621	<b>Intelligent Light System</b> Not in conjunction with Code U37 Only in conjunction with Code 240 and 600	•	•	•	•	1.400,00
622	<b>Intelligent Light System</b> Not in conjunction with Code U37 Only in conjunction with Code 240 and 600	•	•	•	•	1.400,00
623	<b>Gulf States version</b>	-	-	O	O	0,00
625	<b>Australia specification</b>	•	•	•	•	125,00
634	<b>Omission of first-aid kit</b> Not in conjunction with Code 820	O	O	O	O	0,00
636	<b>Omission of warning triangle</b> Not in conjunction with Code 820	O	O	O	O	0,00
643	<b>40.6-cm (16") steel wheel with 10-hole trim</b>	- •	S -	- •	S -	0,00 250,00
645	<b>Set of 4 M+S winter tyres</b> Only in conjunction with Code R00, 643, 55R or 25R	•	•	•	•	110,00
666	<b>Prod. prot. f. freight pkging w/o tie-down hooks</b>	•	•	•	•	25,00
668	<b>Prod. prot. f. freight pkging with tie-down hooks</b>	•	•	•	•	25,00
682	<b>Fire extinguisher</b> Not in conjunction with Code 932 or 939	•	•	•	•	110,00

## Optional extras for the B-Class

Valid from 15.09.2011

Code	Designation	B Sportstourer				LLP (EUR)
		B 180 CDI BlueEFFICIENCY 246.200	B 200 CDI BlueEFFICIENCY 246.201	B 180 BlueEFFICIENCY 246.242	B 200 BlueEFFICIENCY 246.243	
687	Type plate with model year	○	○	○	○	0,00
723	EASY-PACK load compartment cover	●	●	●	●	0,00
736	Black ash wood trim, high-gloss in conjunction with P34	○	○	○	○	260,00
762	Remote control unit Only in conjunction with Code 460	○	○	○	○	0,00
763	Radio remote control with panic switch Only in conjunction with Code 551 and Certain countries only	○	○	○	○	0,00
802	Technical modifications	○	○	○	○	0,00
810	Harman Kardon® Logic 7® surround sound system not in conjunction with code 970, 974, 975 Only in conj. with Code 510, 512, 526 or 527	●	●	●	●	660,00
817	Alarm for anti-theft warning system Only in conjunction with Code 551 and Certain countries only	○	○	○	○	0,00
820	Tourist vehicles	○	○	○	○	0,00
822	Addit. parts for South African vehicles	○	○	○	○	0,00
823	Add.parts for Swiss vehicles	○	○	○	○	0,00
824	Add.parts for countries w.low temperatures	○	○	-	-	0,00
829	Taiwan vehicles, additional parts	○	○	○	○	0,00
830	Vehicles for China, additional parts	-	-	○	○	0,00
831	Italy vehicles, additional parts	○	○	○	○	0,00
837	Floor mats, rubber Only in conjunction with Code 965 in conjunction with P55	●	●	●	●	180,00
840	heat-insulating dark-tinted glass Certain countries only Only in conjunction with Code 900 or 952 in conjunction with P55	○	○	○	○	0,00
842	Tischklappfunktion Beifahrersitz Only in conjunction with Code U57 Only LHD models	○	○	○	○	0,00
862	Preinstallation for TV Right-hand-drive vehicles only	-	-	●	●	80,00
873	Heated front seats in conjunction with P34	○	○	○	○	290,00
875	Heated windscreen washer system	●	●	●	●	115,00
880	Centr. interlock system w/infrared remote control Only in conjunction with Code P34	○	○	○	○	0,00
882	Interior motion sensor Only in conjunction with Code P54	○	○	○	○	0,00
885	Enhanced anti-theft protection only 537L	○	○	○	○	0,00
911	Information for special units	○	○	○	○	0,00
912	Special unit for noise and vibration mitigation	○	○	○	○	0,00
913	Engine fittings for air conditioner	○	○	-	-	0,00
918	Catalytic converter for leaded fuel expected delivery 2. quarter 2012	-	-	○	○	0,00
926	Emission control EU4 technology	-	-	○	○	0,00
927	Emission control system with EURO 6 technology Certain countries only	●	●	●	●	500,00
928	Emission control system with EU5 technology Certain countries only	●	●	○	○	0,00
931	Tandem interior mirror	○	○	○	○	0,00

## Optional extras for the B-Class

Valid from 15.09.2011

		B Sportstourer				LLP (EUR)
Code	Designation	B 180 CDI BlueEFFICIENCY 246.200	B 200 CDI BlueEFFICIENCY 246.201	B 180 BlueEFFICIENCY 246.242	B 200 BlueEFFICIENCY 246.243	
	Only in conjunction with Code U63 or 970,974 or 975					
932	<b>Storage compartment front seat left</b> Not in conjunction with Code 682 (only LHD) Only in conjunction with Code 30P	○	○	○	○	0,00
934	<b>Emergency alarm for taxi/rental vehicle</b> only in conjunction with code 965	●	●	●	●	245,00
938	<b>Preinst. for 2-way radio hands-free system</b> not in conjunction with code 310 only in conjunction with code 965	●	●	●	●	130,00
939	<b>Storage compartment under right driver's seat</b> Not in conjunction with Code 682 (only RHD) Only in conjunction with Code 30P	○	○	○	○	0,00
941	<b>Preinstallation for CB radio</b> Only in conjunction with Code 965	●	●	●	●	65,00
942	<b>Load compartment package</b> Only in conjunction with Code U35 <b>in conjunction with Code U57</b> <b>in conjunction with U57</b>	● - ○	● ○ -	● ○ -	● ○ -	65,00 0,00 0,00
962	<b>Preparation for signal unit (light bar)</b> only in conjunction with code 970, 974, 975	●	●	●	●	160,00
965	<b>Preinstallation for hire car</b> expected delivery first quarter 2012 not in conjunction with code 970, 974, 975, 486, 01R, P55, U63, R66 <b>in conjunction with 450</b>	● ○	● ○	● ○	● ○	495,00 0,00
966	<b>CoC document EU5 without Reg. Cert. Part II</b>	○	○	○	○	0,00
967	<b>COC document EU5 with Reg. Cert. Part II</b>	○	○	○	○	0,00
968	<b>CoC document EU6 without Reg. Cert. Part II</b>	○	○	-	-	0,00
969	<b>COC document EU6 with Reg. Cert. Part II</b>	○	○	○	○	0,00
970	<b>Preparation for police vehicle</b> expected delivery 2. quarter 2012 not in conjunction with code 413, 486, U63, 974, 975, 810, 952, 965, P10, 450 only in conjunction with code 260, Z90	●	●	●	●	990,00
974	<b>Preparation for fire service command vehicle</b> expected delivery 2. quarter 2012 not in conjunction with code 413, 486, U63, 970, 975, 810, 952, 965, P10, 450 only in conjunction with code 260, Z90	●	●	●	●	990,00
975	<b>Preparation for emergency doctor vehicle</b> expected delivery 2. quarter 2012 not in conjunction with code 413, 486, U63, 970, 974, 810, 952, 965, P10, 450 only in conjunction with code 260, Z90	●	●	●	●	990,00
981	<b>Omission of German log book and w/o GOP No.</b>	○	○	○	○	0,00
986	<b>ID no. (VIN no.)</b>	○	○	○	○	0,00
989	<b>Identification label under windshield</b>	○	○	○	○	0,00
B03	<b>ECO start/stop function</b>	S	S	S	S	0,00
B08	<b>Fanfares for Asia</b> Certain countries only	○	○	○	○	0,00
B12	<b>Tyre-change tool kit</b> (Certain countries only) not Germany only in conjunction with code E76/460/623	●	●	●	●	30,00
B51	<b>Tirefit</b> (Certain countries only)	○	○	○	○	0,00



**Optional extras for the B-Class**  
Valid from 15.09.2011

		B Sportstourer				LLP (EUR)
Code	Designation	B 180 CDI BlueEFFICIENCY 246.200	B 200 CDI BlueEFFICIENCY 246.201	B 180 BlueEFFICIENCY 246.242	B 200 BlueEFFICIENCY 246.243	
	not in conjunction with code R66					
E76	<b>Spare wheel</b> Certain countries only Only in conjunction with Code B12	●	●	●	●	220,00
H03	<b>Brown burr walnut wood trim, matt satin finish</b> <b>in conjunction with Code P34</b>	● ○	● ○	● ○	● ○	260,00 0,00
H88	<b>Trim elements in matrix look</b> Not in conjunction with Code 952 or P34	S	S	S	S	0,00
H89	<b>honeycomb-look trim</b> Not in conjunction with Code 900 or P34 Only in conjunction with Code 952	○	○	○	○	0,00
K07	<b>Entfall Navigationsdaten</b>	○	○	○	○	0,00
K08	<b>Radio frequencies for South America</b>	○	○	○	○	0,00
K11	<b>Adaptive brake lights</b> Certain countries only	S	S	S	S	0,00
R00	<b>Steel wheel</b>	S	-	S	-	0,00
R01	<b>Summer tyres</b>	S	S	S	S	0,00
R24	<b>43.2 cm (17-inch) 5-spoke light-alloy wheels</b> Not in conjunction with Code 645 Only in conjunction with Code 952	○	○	○	○	0,00
R43	<b>43.2 cm (17-inch) 10-spoke light-alloy wheels</b>  Not in conjunction with Code 645 <b>in conjunction with Code 952</b>	● - ○	- ● ○	● - ○	- ● ○	1.110,00 860,00 0,00
R66	<b>Tyres with run-flat capability</b> Not in conjunction with Code R00 <b>in conjunction with Code 01R</b>	● ○	● ○	● ○	● ○	130,00 0,00
U01	<b>Belt buckle with switch</b> Certain countries only	S	S	S	S	0,00
U12	<b>Velour floor mats</b> Not in conjunction with Code 450 <b>in conjunction with Code P34</b>	● ○	● ○	● ○	● ○	80,00 0,00
U18	<b>Automatic child seat recognition</b>	●	●	●	●	50,00
U22	<b>4-way lumbar support</b> Only in conjunction with Code U59 <b>in conjunction with Code P34</b>	● ○	● ○	● ○	● ○	155,00 0,00
U35	<b>Steckdose im Laderaum</b> Only in conjunction with Code 942	○	○	○	○	0,00
U37	<b>Front fog lamps</b> Not in conjunction with Code 240, 614, 615, 618, 621 or 622	●	●	●	●	185,00
U40	<b>Partition net</b> expected delivery first quarter 2012	●	●	●	●	185,00
U57	<b>EASY-VARIO-PLUS-System</b> Not in conjunction with Code 242, 248, 001A Only in conjunction with Code 400, 567, 842, 942, U59	●	●	●	●	565,00
U64	<b>Full driving school package</b> expected delivery first quarter 2012 including Code U63 Not in conjunction with Code 429 or U12	●	●	●	●	1.095,00
U65	<b>Additional exterior mirror</b> Contains: Code U63	●	●	●	●	50,00
Z90	<b>Multi-function control unit f.spec.funct.</b> Only in conjunction with Code 970, 974 oder 975	○	○	○	○	0,00
Z97	<b>Elektronische Kundenwunsch Schnittstelle</b>	●	●	●	●	380,00

## Optional extras for the B-Class

Valid from 15.09.2011

Code	Designation	B Sportstourer				LLP (EUR)
		B 180 CDI BlueEFFICIENCY 246.200	B 200 CDI BlueEFFICIENCY 246.201	B 180 BlueEFFICIENCY 246.242	B 200 BlueEFFICIENCY 246.243	
	not in conjunction with code 537, 965 Only LHD models and Certain countries only					
<b>Z98</b>	<b>Paint not feat.on standard sample card</b>	○	○	○	○	<b>0,00</b>