

Optional extras for the B-Class

Valid from 11.05.2012

● available at extra charge ○ available at no extra charge ○ annotations existing
S standard equipment - not available

		B Sportstourer					P	EUR
Code	Designation	246.200 B 180 CDI Blue	246.201 CDI Blue	246.242 B 180 Blue	246.243 B 200 Blue	246.244 B 250 Blue		
L	Left-hand drive	○	○	○	○	○	○	0,00
R	Right-hand drive	●	●	●	●	●	●	1113,00
191U	cosmos black metallic	●	●	●	●	●	●	514,50
240U	lotus blue metallic	●	●	●	●	●	●	514,50
589U	jupiter red	○	○	○	○	○	○	0,00
623U	light ivory	○	○	○	○	○	○	0,00
650U	cirrus white	○	○	○	○	○	○	0,00
696U	night black	○	○	○	○	○	○	0,00
761U	polar silver metallic	●	●	●	●	●	●	514,50
787U	mountain grey metallic	●	●	●	●	●	●	514,50
893U	monolith grey metallic	●	●	●	●	●	●	514,50
894U	universe blue	●	●	●	●	●	●	514,50
895U	canyon beige metallic	●	●	●	●	●	●	514,50
001A	fabric Venlo black Not in conjunction with Code 248, 400, 460, 952, P34, U57 or U59	○	○	○	○	○	○	0,00
011A	fabric Domburg black Not in conjunction with Code 248, 952 or P34 Only in conjunction with Code U59	○	○	○	○	○	○	0,00
018A	fabric Domburg grey Not in conjunction with Code 248, 952 or P34 Only in conjunction with Code U59	○	○	○	○	○	○	0,00
101A	black ARTICO man-made leather Not in conjunction with Code P34 Only in conjunction with Code U59 in conjunction with Code 952	●	●	●	●	●	●	252,00
105A	sahara beige ARTICO man-made leather Not in conjunction with Code P34 Only in conjunction with Code U59 in conjunction with Code 952	●	●	●	●	●	●	126,00
108A	alpaca grey ARTICO man-made leather Not in conjunction with Code P34 Only in conjunction with Code U59 in conjunction with Code 952	●	●	●	●	●	●	252,00
201A	leather black Not in conjunction with Code 248 Only in conjunction with Code P34 and U59	○	○	○	○	○	○	0,00
204A	leather Not in conjunction with Code 248 Only in conjunction with Code P34 and U59	○	○	○	○	○	○	0,00
208A	leather grey Not in conjunction with Code 248 Only in conjunction with Code P34 and U59	○	○	○	○	○	○	0,00
411	6-speed manual transmission Not in conjunction with Code 239	S	S	S	S	-	-	0,00
429	7G-DCT Only in conjunction with Code 428 Only in conjunction with Code 440 or 239 Only in conjunction with Code U64	-	-	-	-	S	-	0,00
601A	fabric black/multicolor Not in conjunction with Code 248 or P34 Only in conjunction with Code 952 and U59	○	○	○	○	○	○	0,00
608A	fabric/leather slate grey	○	○	○	○	○	○	0,00

Optional extras for the B-Class

Valid from 11.05.2012

● available at extra charge ○ available at no extra charge ○ annotations existing
S standard equipment - not available

		B Sportstourer					C P	EUR
Code	Designation	246.200	246.201	246.242	246.243	246.244		
		B 180 CDI BlueEFFICIENCY Sports Tourer	B 200 CDI BlueEFFICIENCY Sports Tourer	B 180 BlueEFFICIENCY Sports Tourer	B 200 BlueEFFICIENCY Sports Tourer	B 250 BlueEFFICIENCY Sports Tourer		
	Not in conjunction with Code 248 or P34 Only in conjunction with Code 952 and U59							
22P	Lane tracking package Certain countries only only in conjunction with Code 234, 476	●	●	●	●	●		787,50
30P	Stowage Space package only in conjunction with Code 286, 939 and (932 or 682)	●	●	●	●	●		199,50
900	Chrome package Not in conjunction with Code 952 or P55 only in conjunction with Code 001A or 011A, 018A, 101A, 105A, 108A, 201A, 204A or 208A, Code 543, 736 or H03, or H88	●	●	●	●	●		288,75
952	Sports package Not in conjunction with Code 900 Only in conjunction with Code 101A, 105A, 108A/201A, 204A, 208A/601A, 608A; 280, 543 & 486/677; 51U/58U, H89/H03/736; R24/R43, 01R, 25R, 26R; 643 or 55R only in conj. with code 645, only for Netherlands, 553L	- ● -	● - -	- ● -	● - -	- - ●		1470,00 1653,75 1023,75
	in conjunction with Code 55R or 643	●	●	●	●	●		924,00
P34	Exclusive Package in conjunction with Code 450 Not in conjunction with Code U12 Only in conjunction with Code 837 Not in conjunction with Code 248 Only in conjunction with Code 900 or 952, 280, 736 oder H03; 880, 873, U12, U22, U64, 200A	●	●	●	●	●		1695,75
	in conjunction with Code 952	●	-	-	-	-		1050,00
	in conjunction with code 952	●	●	●	●	●		1338,75
P49	Mirror package only in conjunction with Code 249, 500	●	●	●	●	●		309,75
P54	Anti-Theft Protection package Certain countries only Consisting of: Code 551, 882	●	●	●	●	●		420,00
P55	Night package Not in conjunction with Code 965 Only in conjunction with Code 614/615 or 618 oder 621 or 622; 840, 01R, 952	●	●	●	●	●		787,50
U59	Seat Comfort package Not in conjunction with upholstery 001A i.V.m. 952/P34/U63 in Verbindung mit 952/U63/P34	● ○ -	● - ○	● - ○	● - ○	● - ○		141,75 0,00 0,00
U62	Light and Sight package only in conjunction with Code 345, 543 in conjunction with code U63 in conjunction with code U63	● ○ -	● - ○	● - ○	● - ○	● - ○		341,25 0,00 0,00
U63	Basic driving school package including code U59, U62, 931 Not in conjunction with Code 310 Only in conjunction with Code U59, U62, 931 in conjunction with code U64 in conjunction with code U64	● - ○	● ○ -	● ○ -	● ○ -	● ○ -		519,75 0,00 0,00
498	Japanese version	-	-	●	●	●		472,50
01R	45.7 cm (18-inch) 5-twin-spoke light-alloy wheels	-	●	-	●	-		1249,50

Valid from 11.05.2012

Code	Designation
------	-------------

		●	-	●	-	-	1512,00
		-	-	-	-	●	525,00
	Not in conjunction with Code 965, 645 Only in conjunction with Code R66, R01 in conjunction with Code 952 in conjunction with Code P55	●	●	●	●	●	525,00
		○	○	○	○	○	0,00
03U	travel guide certain countries only in conjunction with code 512 or 527	●	●	●	●	●	157,50
202	Literature in German	○	○	○	○	○	0,00
205	Literature in English	○	○	○	○	○	0,00
206	Literature in Italian	○	○	○	○	○	0,00
207	Literature in French	○	○	○	○	○	0,00
208	Literature in Spanish	○	○	○	○	○	0,00
209	Literature in Portuguese	○	○	○	○	○	0,00
210	Swedish literature	○	○	○	○	○	0,00
213	Direct-steer system Only in conjunction with Code 486	○	○	○	○	○	0,00
218	Reversing camera	●	●	●	●	●	304,50
220	PARKTRONIC system (PTS) Only Japan	-	-	●	●	●	598,50
228	Auxiliary heater Certain countries only Only in conjunction with Code B24	●	●	●	●	●	1312,50
232	Garage door opener Only in conjunction with Code 245, P49, 460 or 494	-	-	-	-	●	236,25
234	Blind Spot Assist Certain countries only Only in conj. with Code 22P	○	○	○	○	○	0,00
235	Active Parking Assist Not Japan	●	●	●	●	●	708,75
239	DISTRONIC PLUS Certain countries only Not in conjunction with Code 252 or 440 Only in conjunction with Code 429	●	●	●	●	●	903,00
240	LED-daytime running lights Not in conjunction with Code U37 Only in conj. with Code 614, 618, 621 or 622	○	○	○	○	○	0,00
241	Front seat left, elect.adjust.w.mem. switch Only in conjunction with Code 000A Only in conjunction with Code 275 Right-hand-drive vehicles only	●	●	●	●	●	294,00
242	Front pass. seat, electrically adj. with memory function LHD version Not in conjunction with Code 000A or U57 Only in conjunction with Code 275	●	●	●	●	●	294,00
245	Compass Only in conj. with Code 232, P49 and 460 or 494	-	-	-	-	●	110,25
248	Rear seats with integrated child seats Not in conjunction with Code U57 or P34 Only in conjunction with Code 101A, 105A, 108A in conjunction with code 965	●	●	●	●	●	346,50
		●	●	●	●	●	115,50

Optional extras for the B-Class

Valid from 11.05.2012

● available at extra charge ○ available at no extra charge ○ annotations existing
S standard equipment - not available

		B Sportstourer					P	EUR
Code	Designation	B 180 CDI BlueEFFICIENCY Sports Tourer	B 200 CDI BlueEFFICIENCY Sports Tourer	B 180 BlueEFFICIENCY Sports Tourer	B 200 BlueEFFICIENCY Sports Tourer	B 250 BlueEFFICIENCY Sports Tourer		
	in conjunction with code 450	○	○	○	○	○	○	0,00
249	Automatically dimming int.and ext.mirrors Only in conjunction with Code P49	○	○	○	○	○	○	0,00
252	COLLISION PREVENTION ASSIST Certain countries only Not in conjunction with Code 239	S	S	S	S	S	S	0,00
257	round LED daytime running lamps Not in conjunction with Code 614, 615, 618, 621or 622 Only cert. countries	S	S	S	S	S	S	0,00
25R	43.2 cm (17-inch) 10-spoke light-alloy wheels Only in conjunction with Code 645 Only in conjunction with code P55 in conjunction with Code 952	- - ● ○	- - ● ○	- - ● ○	- - ● ○	- - ● ○	○	0,00 693,00 955,50 0,00
25Z	Vorrüstung Analog Funk TDX9	●	●	●	●	●	●	147,00
260	Omission of model plate on boot lid	○	○	○	○	○	○	0,00
263	Number plate mounting for Asia/Mexico	○	○	○	○	○	○	0,00
264	Number plate mounting for America	○	○	○	○	○	○	0,00
26R	43.2 cm (17-inch) 7-twin-spoke light-alloy wheels Not in conjunction with Code 645 in conjunction with Code 952	● - - ●	- - ● ●	● - ● ●	- - ● ●	- ● - ●	●	1302,00 136,50 1039,50 136,50
275	Memory package Not in conjunction with Code 000A Only in conjunction with Code U22, U59	●	●	●	●	●	●	351,75
280	Leather steering wheel in conjunction with code 952 or P34 in conjunction with code 952/P34	● - ○	● ○ ○	● ○ ○	● ○ ○	● ○ ○	●	183,75 0,00 0,00
286	Luggage net on driver's and front pass. backrest Only in conjunction with Code 30P	○	○	○	○	○	○	0,00
290	windowbags	S	S	S	S	S	S	0,00
293	Sidebags in rear	●	●	●	●	●	●	393,75
294	Kneebag	S	S	S	S	S	S	0,00
299	PRE-SAFE® system Not in conjunction with Code 460	●	●	●	●	●	●	346,50
301	Smoker package	●	●	●	●	●	●	47,25
310	Cup holder not in conjunction with Code U63 or 938	●	●	●	●	●	●	26,25
333	Special instrument panel Only in conjunction with Code 965	●	●	●	●	●	●	84,00
334	Two-way radio retainer in glove compartment Only in conjunction with Code 965 in conjunction with Code 450	● ○	● ○	● ○	● ○	● ○	●	63,00 0,00
335	Two-way radio mount in boot Only in conjunction with Code 965	●	●	●	●	●	●	63,00
336	Preinstallation for taximeter Only in conjunction with Code 965	●	●	●	●	●	●	57,75
337	Taximeter integr.in the rear-view mirror Only in conjunction with Code 965	●	●	●	●	●	●	871,50
341	Taxi roof sign not in conjunction with code 342	●	●	●	●	●	●	257,25

Valid from 11.05.2012

● available at extra charge ○ available at no extra charge ◐ annotations existing
S standard equipment - not available

Optional extras for the B Class		B Sportstourer					CLP EUR
Code	Designation	246.200	246.201	246.242	246.243	246.244	
	Valid from 11.05.2012	B 180 CDI Blue	CDI Blue	CDI Blue	CDI Blue	CDI Blue	
	● available at extra charge ○ available at no extra charge ○ annotations existing S standard equipment - not available						
	Only in conjunction with Code 965						
342	Connection, taxi roof sign Not in conjunction with Code 413, 341 Only in conjunction with Code 965	●	●	●	●	●	73,50
345	Windscreen wiper with rain sensor Only in conjunction with Code U62	○	○	○	○	○	0,00
347	Ecall emergency call system, Europe Certain countries only Only in conjunction with Code 512 or 527	○	○	○	○	○	0,00
348	mbrace Only in conjunction with Code 460	-	-	-	-	●	630,00
356	Roof aerial for taxi two-way radio Only in conjunction with Code 965 in conjunction with Codes 386, 508, 509, 512, 527	●	●	●	●	●	204,75
379	Telephone module with Bluetooth SAP Certain countries only Only in conjunction with Code 386	●	●	●	●	●	462,00
386	Convenience telephony Not in conjunction with Code 830 Only in conjunction with Code 510, 512, 514, 523 or 527	●	●	●	●	●	367,50
400	Rear armrest Not in conjunction with Code 001A in conjunction with Code U57	○	○	○	○	○	0,00
413	Panoramic sliding sunroof Not in conjunction with Code 342 Only in conjunction with Code 543, 51U	●	●	●	●	●	1202,25
428	Steering wheel shift buttons Only in conjunction with Code 429	○	○	○	○	○	0,00
440	Cruise control Not in conjunction with Code 239 in conjunction with codes 429 in conjunction with code 429	- ● ○ -	- ● - ○	- ● ○ -	- ● ○ -	S - - ○	0,00 262,50 0,00 0,00
442	Luxury multifunction steering wheel	S	S	S	S	S	0,00
450	Taxi version, international Only in conj. w. Code 100A or 200A; 965, 334 or 335, 837	●	●	●	●	●	871,50
460	Canada version/additional parts	-	-	-	-	●	404,25
461	Instrument with mileage reading	○	○	○	○	○	0,00
462	Instrument cluster with Asian characters Cert. countries only	○	○	○	○	○	0,00
474	Diesel particulate filter Not in conjunction with code 926 Part of standard specification in Germany and WEU countries	●	●	-	-	-	498,75
476	Lane keeping assist Only in conjunction with Code 22P and Code 280	○	○	○	○	○	0,00
477	Tyre pressure loss warning system	S	S	S	S	S	0,00
485	Comfort suspension Not in conjunction with Code 952 or 498	S	S	S	S	S	0,00
500	Electrically folding exterior mirrors Only in conjunction with Code P49	○	○	○	○	○	0,00
502	3 years of free map updates Certain countries only Only in conjunction with Code 512 or 527	○	○	○	○	○	0,00

Optional extras for the B-Class

Valid from 11.05.2012

● available at extra charge ○ available at no extra charge U annotations existing
S standard equipment - not available

Code	Designation	B Sportstourer					P	EUR
		246.200	246.201	246.242	246.243	246.244		
		B 180 CDI BlueEFFICIENCY Sports Tourer	B 200 CDI BlueEFFICIENCY Sports Tourer	B 180 BlueEFFICIENCY Sports Tourer	B 200 BlueEFFICIENCY Sports Tourer	B 250 BlueEFFICIENCY Sports Tourer		
508	Pre-installation for Becker® MAP PILOT (C. coun. on.); on. in conj. w. Code 510/523	●	●	●	●	●		231,00
509	Becker® MAP PILOT (Certain countries only); only in conjunction with Code 510 or 523 required with code 22P for certain countries (additional price)	●	●	●	●	●		756,00
510	Audio 20 CD with 6-disc CD changer Not in conjunction with Code 460 or 498	●	●	●	●	●		157,50
512	COMAND Online with 6-disc DVD changer (& in c. c. on. icw Code 513)	●	●	●	●	●		3097,50
513	Speed Limit Assist (Certain c. only); only in conj. w. Code 512 /527	○	○	○	○	○		0,00
514	COMAND APS China Certain countries only	●	●	●	●	●		2782,50
518	Media Interface Only in conjunction with Code 510 or 512/514/526/527	●	●	●	●	●		231,00
51U	Black fabric roof liner Only in conjunction with Code 413 or 952 or 204A	○	○	○	○	○		0,00
523	Audio 20 CD Not in conjunction with Code 498 or 513/518/537/810/830/862	S	S	S	S	S		0,00
526	Comand DVD (without navigation) Only in conjunction with Code 498	-	-	●	●	●		1155,00
527	COMAND Online (Certain countries only in conjunction with code 513) Certain countries only	●	●	●	●	●		2782,50
536	Sirius satellite radio Only in conjunction with Code 460 or 494	-	-	-	-	●		367,50
537	Digital radio (DAB) (Certain countries only) & not in conjunction with code Z97 Only in conjunction with Code 510, 512 or 527	●	●	●	●	●		430,50
538	ATTENTION ASSIST	S	S	S	S	S		0,00
543	Sun visors with illuminated vanity mirrors Only in conjunction with Code 413, U62, 900 or 952	○	○	○	○	○		0,00
550	Trailer coupling Not in conjunction with Code 460	●	●	●	●	●		829,50
551	Anti-theft warning system Only in conjunction with Code 460 in conjunction with Code P54 For certain count. scope of delivery of Code P54	●	●	●	●	●		262,50
		○	○	○	○	○		0,00
55R	40.6 cm (16-inch) 10-spoke light-alloy wheels in conjunction with Code 952 only in in conjunction with Code 645 Not in conjunction with Code P55	-	●	-	●	-		262,50
		●	-	●	-	-		420,00
567	VARIO REAR SEAT Only in conjunction with Code U57	○	○	○	○	○		0,00
580	Air conditioning system	S	S	S	S	S		0,00
581	THERMOTRONIC automatic climate control Only in conjunction with Code 900 or 952	●	●	●	●	●		535,50
58U	Grey fabric roof liner Not in conjunction with Code 413, 204A or (105A in conjunction with Code 952)	S	S	S	S	S		0,00
600	Headlamp cleaning system Only in conj. w. Code 614 or 615, 618, 621 or 622	○	○	○	○	○		0,00

Optional extras for the B-Class

Valid from 11.05.2012

● available at extra charge ○ available at no extra charge ○ annotations existing
S standard equipment - not available

		B Sportstourer					C P	EUR
Code	Designation	246.200	246.201	246.242	246.243	246.244		
		B 180 CDI BlueEFFICIENCY Sports Tourer	B 200 CDI BlueEFFICIENCY Sports Tourer	B 180 BlueEFFICIENCY Sports Tourer	B 200 BlueEFFICIENCY Sports Tourer	B 250 BlueEFFICIENCY Sports Tourer		
608	Adaptive Main Beam Assist Only in conjunction with Code 615 or 621/622	○	○	○	○	○		0,00
613	Headlamps for RHD vehicles Only in conjunction with Code P55 Part of standard specification for LHD countries	○	○	○	○	○		0,00
614	Bi-xenon headlamps Not in conjunction with Code U37 On. icw Code 600 & 240	●	●	●	●	●		887,25
615	Bi-xenon headl. (LHD veh.) w. corn. function Not in conjunction with Code U37 Only in conj. with Code 460, 240 and 600 Scope of delivery of Code P55	-	-	-	-	●		1312,50
618	Bi-xenon headlamps for RHD vehicles Not in conjunction with Code U37 Only icw Code 600 & 240	●	●	●	●	●		887,25
621	Intelligent Light System Not in conjunction with Code U37 Only in conjunction with Code 240 and 600	●	●	●	●	●		1470,00
622	Intelligent Light System Not in conjunction with Code U37 Only in conjunction with Code 240 and 600	●	●	●	●	●		1470,00
625	Australia specification	●	●	●	●	●		131,25
634	Omission of first-aid kit Not in conjunction with Code 820	○	○	○	○	○		0,00
636	Omission of warning triangle Not in conjunction with Code 820	○	○	○	○	○		0,00
643	40.6-cm (16") steel wheel with 10-hole trim in conjunction with Code 952 only in in conjunction with Code 645	- ●	S -	- ●	S -	- -		0,00 262,50
645	winter (M+S) wheel and tyre assembly x 4 Only in conjunction with Code R00, 643, 55R or 25R	●	●	●	●	●		115,50
666	Prod. prot. f. freight pkging w/o tie-down hooks Certain countries only Not in conjunction with Code 820 in conjunction with Code 14P, 15P and 16P	○	○	○	○	○		0,00
668	Prod. prot. f. freight pkging with tie-down hooks Certain countries only Not in conjunction with Code 820	●	●	●	●	●		26,25
677	AVANTGARDE suspension Only in conjunction with Code 213, 952	○	○	○	○	○		0,00
682	Fire extinguisher Not in conjunction with Code 932 or 939	●	●	●	●	●		115,50
687	Type plate with model year	○	○	○	○	○		0,00
690	Pre-installation for the spare wheel Certain countries only Only in conjunction with Code E76, B12	○	○	○	○	○		0,00
723	Retractable load compartment cover	S	S	S	S	S		0,00
736	black high-gloss ash wood trim in conjunction with Code 952 in conjunction with Code 952	● - ○	● ○ -	● ○ -	● ○ -	● ○ -		273,00 0,00 0,00
762	Remote control unit Only in conjunction with Code 460	○	○	○	○	○		0,00
763	Radio remote control with panic switch	○	○	○	○	○		0,00

Optional extras for the B-Class

Valid from 11.05.2012

● available at extra charge ○ available at no extra charge U annotations existing
S standard equipment - not available

		B Sportstourer						P	EUR
Code	Designation	246.200	B 180 CDI BlueEFFICIENCY Sports Tourer	246.201	B 200 CDI BlueEFFICIENCY Sports Tourer	246.242	B 180 BlueEFFICIENCY Sports Tourer	246.243	B 200 BlueEFFICIENCY Sports Tourer
	Only in conjunction with Code 551 and Certain countries only								
802	Technical modifications	○	○	○	○	○	○	○	0,00
810	Harman Kardon® Logic 7® surround sound system Only in conj. with Code 510, 512, 514, 526 or 527	●	●	●	●	●	●	●	693,00
817	Alarm for anti-theft warning system Only in conjunction with Code 551 and Certain countries only	○	○	○	○	○	○	○	0,00
820	Tourist vehicles Not in conjunction with Code 634 or 636/666/668	○	○	○	○	○	○	○	0,00
822	Addit. parts for South African vehicles	○	○	○	○	○	○	○	0,00
823	Add.parts for Swiss vehicles	○	○	○	○	○	○	○	0,00
824	Add.parts for countries w.low temperatures	○	○	-	-	-	-	-	0,00
829	Taiwan vehicles, additional parts	○	○	○	○	○	-	-	0,00
830	Vehicles for China, additional parts	-	-	○	○	○	○	○	0,00
831	Italy vehicles, additional parts	○	○	○	○	○	○	○	0,00
835	Vehicles for South Korea, additional parts	-	○	-	-	-	-	○	0,00
837	Floor mats, rubber Only in conjunction with Code 965 Sc. of del. of Code 450	●	●	●	●	●	●	●	189,00
	in conjunction with Code 450	-	○	○	○	○	○	○	0,00
	in conjunction with Code 450	○	-	-	-	-	-	-	0,00
840	heat-insulating dark-tinted glass Certain countries only Only in conjunction with Code 900 or 952	●	●	●	●	●	●	●	231,00
	in conjunction with Code P55	○	○	○	○	○	○	○	0,00
842	Tischklappfunktion Beifahrersitz Only in conjunction with Code U57 Only LHD models	○	○	○	○	○	○	○	0,00
862	Preinstallation for TV Only in conjunction with Code 498 and Code 526 Right-hand-drive vehicles only	-	-	●	●	●	●	●	84,00
873	Heated front seats in conjunction with Code P34 in conjunction with Code P34	●	●	●	●	●	●	●	304,50
		-	○	○	○	○	○	○	0,00
		○	-	-	-	-	-	-	0,00
875	Heated windscreen washer system	●	●	●	●	●	●	●	120,75
880	Centr. interlock system w/infrared remote control Only in conjunction with Code P34	○	○	○	○	○	○	○	0,00
882	Interior motion sensor Only in conjunction with Code P54	○	○	○	○	○	○	○	0,00
885	Enhanced anti-theft protection only 537L	○	○	○	○	○	○	○	0,00
912	Special unit for noise and vibration mitigation	○	○	○	○	○	○	○	0,00
913	Engine fittings for air conditioner	○	○	-	-	-	-	-	0,00
918	Catalytic converter for leaded fuel expected delivery 3. quarter 2012	-	-	○	○	-	-	-	0,00
920	Direct petrol injection with stratified charging Certain countries only	-	-	-	-	-	-	○	0,00
926	Emission control EU4 technology	-	-	○	○	○	○	○	0,00
927	Emission control system with EURO 6 technology Certain countries only	-	-	S	S	S	S	S	0,00
928	Emission control system with EU5 technology Certain countries only	S	S	○	○	○	○	○	0,00
931	Tandem interior mirror Only in conjunction with Code U63	○	○	○	○	○	○	○	0,00

Optional extras for the B-Class

Valid from 11.05.2012

● available at extra charge ○ available at no extra charge U annotations existing
S standard equipment - not available

Code	Designation	B Sportstourer					CLP	EUR
		246.200 B 180 CDI BlueEFFICIENCY Sports Tourer	246.201 B 200 CDI BlueEFFICIENCY Sports Tourer	246.242 B 180 BlueEFFICIENCY Sports Tourer	246.243 B 200 BlueEFFICIENCY Sports Tourer	246.244 B 250 BlueEFFICIENCY Sports Tourer		
932	Storage compartment front seat left Not in conjunction with Code 682 (only LHD) Only in conjunction with Code 30P	○	○	○	○	○		0,00
934	Emergency alarm for taxi/rental vehicle only in conjunction with code 965	●	●	●	●	●		257,25
938	Preinst. for 2-way radio hands-free system not in conjunction with code 310 only in conjunction with code 965	●	●	●	●	●		136,50
939	Storage compartment under right driver's seat Not in conjunction with Code 682 (only RHD) Only in conjunction with Code 30P	○	○	○	○	○		0,00
941	Preinstallation for CB radio Only in conjunction with Code 965	●	●	●	●	●		68,25
942	Load compartment package Only in conjunction with Code U35 in conjunction with Code U57 in conjunction with Code U57	● - ○	● ○ -	● ○ -	● ○ -	● ○ -		68,25 0,00 0,00
962	Preparation for signal unit (light bar)	●	●	●	●	●		168,00
965	Preinstallation for hire car not in conjunction with code 460, 498, 486, 01R, P55, U63, R66 in conjunction with Code 450	● ○	● ○	● ○	● ○	● ○		519,75 0,00
966	CoC document EU5 without Reg. Cert. Part II	○	○	○	○	○		0,00
967	CoC document EU5 with Reg. Cert. Part II	○	○	○	○	○		0,00
968	CoC document EU6 without Reg. Cert. Part II	-	-	○	○	○		0,00
969	CoC document EU6 with Reg. Cert. Part II	-	-	○	○	○		0,00
981	Omission of German log book and w/o GOP No.	○	○	○	○	○		0,00
986	ID no. (US-VIN)	○	○	○	○	○		0,00
989	Identification label under windshield	○	○	○	○	○		0,00
B03	ECO start/stop function	S	S	S	S	S		0,00
B08	Fanfares for Asia Certain countries only	○	○	○	○	○		0,00
B12	Tyre-change tool kit (Certain countries only) not Germany only in conjunction with code 690/623	●	●	●	●	●		31,50
B24	remote control for auxiliary heater Certain countries only Only in conjunction with Code 228	○	○	○	○	○		0,00
B51	TIREFIT (Certain countries only) not in conjunction with code R66	S	S	S	S	S		0,00
E76	Spare wheel Certain countries only Only in conjunction with Code 690, B12	●	●	●	●	●		240,45
H03	Brown burr walnut wood trim, matt satin finish in conjunction with Code P34 in conjunction with Code P34	● - ○	● ○ -	● ○ -	● ○ -	● ○ -		273,00 0,00 0,00
H88	Trim elements in matrix look Not in conjunction with Code 900, 952 or P34	S	S	S	S	S		0,00
H89	honeycomb-look trim Not in conjunction with Code 900 or P34 Only in conjunction with Code 952	○	○	○	○	○		0,00
K08	Radio frequencies for South America	○	○	○	○	○		0,00
K11	Adaptive brake lights	S	S	S	S	S		0,00

Optional extras for the B-Class

Valid from 11.05.2012

● available at extra charge ○ available at no extra charge ○ annotations existing
S standard equipment - not available

		B Sportstourer					P	EUR
Code	Designation	246.200	246.201	246.242	246.243	246.244		
		B 180 CDI BlueEFFICIENCY Sports Tourer	B 200 CDI BlueEFFICIENCY Sports Tourer	B 180 BlueEFFICIENCY Sports Tourer	B 200 BlueEFFICIENCY Sports Tourer	B 250 BlueEFFICIENCY Sports Tourer		
	Certain countries only							
K99	Multi-purpose vehicle	○	○	○	○	○		0,00
R00	38.1 cm (15-inch) steel wheels with 10-hole	S	-	S	-	-		0,00
R01	Summer tyres	S	S	S	S	S		0,00
R02	All season tyres	-	-	-	-	●		115,50
	Only in conjunction with code 460							
R24	43.2 cm (17-inch) 5-spoke light-alloy wheels Not in conjunction with Code 645, P55 Only in conjunction with Code 952	○	○	○	○	○		0,00
R43	43.2 cm (17-inch) 10-spoke light-alloy wheels Not in conjunction with Code 645, P55 in conjunction with Code 952	- ● -	- ● -	- ● -	- ● -	S - -		0,00 1165,50 903,00
R66	Tyres with run-flat capability Not in conjunction with Code R00 in conjunction with Code 01R	● ○	● ○	● ○	● ○	● ○		136,50 0,00
U01	Belt buckle with switch Certain countries only	S	S	S	S	S		0,00
U12	Velour floor mats Not in conjunction with Code U64 or Code 450 in conjunction with Code P34	● ○	● ○	● ○	● ○	● ○		84,00 0,00
U18	Automatic child seat recognition	●	●	●	●	●		52,50
U22	4-way lumbar support Only in conjunction with Code U59 in conjunction with Code P34 in conjunction with Code P34	● - ○	● ○ -	● ○ -	● ○ -	● ○ -		162,75 0,00 0,00
U25	Door sill panels with "Mercedes-Benz" lettering, illuminated Only in conjunction with Code U62	●	●	●	●	●		157,50
U35	12 V socket in load area Only in conjunction with Code 942	○	○	○	○	○		0,00
U37	Front fog lamps Not in conjunction with Code 240, 614, 615, 618, 621 or 622	●	●	●	●	●		194,25
U40	Partition net	●	●	●	●	●		194,25
U57	EASY-VARIO-PLUS-system Not in conjunction with Code 242, 248, 001A or 460 Only in conjunction with Code 400,567,842,942,U59	●	●	●	●	●		593,25
U64	Full driving school package expected delivery first quarter 2012 including Code U63 Not in conjunction with Code 429 or U12	●	●	●	●	●		1149,75
U65	Additional exterior mirror Contains: Code U63	●	●	●	●	●		52,50
Z90	Multi-function control unit f.spec.funct.	○	○	○	○	○		0,00
Z97	Electronic customer's request interface not in conjunction with code 537, 965 Only LHD models and Certain countries only	●	●	●	●	●		399,00
Z98	Paint not feat.on standard sample card	○	○	○	○	○		0,00