

## 24/11/2016 Optional extras for the GLA

Valid from 09.01.2017 FL (808)

National Package

National Standard

Delta to NST

Not for Greece

● available at extra charge    ○ available at no extra charge    U annotations existing  
S standard equipment    - not available -    BM 156.945 nur Indien (RL) or Korea (LL)

Code	Designation	156.912	GLA 180 d Sport Utility Vehicle	156.908	GLA 200 d Sport Utility Vehicle	156.902	GLA 200 d 4MATIC Sport Utility Vehicle	156.903	GLA 220 d Sport Utility Vehicle	156.905	GLA 220 d 4MATIC Sport Utility Vehicle	156.942	GLA 180 Sport Utility Vehicle	156.943	GLA 200 Sport Utility Vehicle	156.944	GLA 250 Sport Utility Vehicle	156.946	GLA 250 4MATIC Sport Utility Vehicle	156.952	Vehicle	156.945	GLA 200 Sport Utility Vehicle RHD	156.947	GLA 220 4MATIC Sport Utility Vehicle	LLP
DB1	<b>Progressive Plus Auto package</b> National Package Included: 429-P49-P59-218-14U-175U/191U/589U/650U/696U/761U/787U/890U/895U/990U	●											●												1888,00	
DB2	<b>Progressive Plus package</b> National Package Included: P49-P59-218-14U-175U/191U/589U/650U/696U/761U/787U/890U/895U/990U	●												●											1149,00	
DB3	<b>Offroad Auto package</b> National Package Included: 429-P27-P49-218-30P-14U-400-482-175U/191U/589U/650U/696U/761U/787U/890U/895U/990U	●												●											1882,00	
DB4	<b>Offroad package</b> National Package Included: P27-P49-218-30P-14U-400-482-175U/191U/589U/650U/696U/761U/787U/890U/895U/990U	●												●											1142,00	
DB5	<b>Sport package</b> National Package Included: 950-218-14U-P49-857	●												●											2760,00	
DB6	<b>White Art Plus</b> National Package Included: PEK-950-P49-P55-218-429-632	●												●											6144,00	
L	Left-hand drive	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	0,00	
R	Right-hand drive	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	1113,00	
000U	paintwork not yet finalised	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	0,00	
149U	polar white certain countries only	-	-	-	-	-	-	-	-	-	-	○	○	○	○	○	○	○	○	-	○	○	○	○	0,00	
175U	elbaite green metallic	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	619,50	
191U	cosmos black metallic	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	619,50	
589U	jupiter red	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	0,00	
650U	cirrus white	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	0,00	
662U	desiqno mountain grey magno	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	1837,50	
696U	night black	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	0,00	
761U	polar silver metallic	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	619,50	
787U	mountain grey metallic	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	619,50	
890U	cavansite blue metallic	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	619,50	
895U	canyon beige metallic	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	619,50	
895U	brilliant blue metallic certain countries only	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	619,50	
990U	orient brown metallic	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	619,50	
992U	selenite grey metallic certain countries only	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	-	●	●	●	●	619,50	
996U	desiqno hyacinth red metallic certain countries only	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	-	●	●	●	●	1837,50	
021A	Coari fabric black certain countries only not in conjunction with code 950, P27, P34, P59	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	-	○	○	○	○	○	0,00	
028A	Coari fabric crystal grey certain countries only not in conjunction with code 950, P27, P34, P59	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	-	○	○	○	○	○	0,00	
105A	ARTICO man-made leather sahara beige not in conjunction with code P34 or 950 only in conjunction with code P27 or P59 only in conjunction with code U59 in conjunction with Code P27 oder P59	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	-	●	●	●	●	●	273,00	
111A	ARTICO man-made leather black not in conjunction with code P34 or 950 only in conjunction with code U59 in conj. W. Code P27 oder P59	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	-	●	●	●	●	●	136,50	
118A	ARTICO man-made leather crystal grey not in conjunction with code P34 or 950 only in conjunction with code U59 in conj. W. Code P27 oder P59	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	-	●	●	●	●	●	136,50	
161A	black ARTICO man-made leather certain countries only only in conjunction with code P59; not in conjunction with U10	-	-	-	-	-	-	-	-	-	-	-	●	●	●	●	●	●	-	●	●	●	●	●	136,50	
165A	almond beige / black ARTICO man-made leather certain countries only only in conjunction with code P59; not in conjunction with U10	-	-	-	-	-	-	-	-	-	-	-	●	●	●	●	●	●	-	●	●	●	●	●	136,50	
168A	ARTICO man-made leather crystal grey certain countries only only in conjunction with code P59; not in conjunction with U10	-	-	-	-	-	-	-	-	-	-	-	●	●	●	●	●	●	-	●	●	●	●	●	136,50	
175A	Kunstleder - beige / schwarz certain countries only not in conjunction with code U10 only in conjunction with code P59	-	-	-	-	-	-	-	-	-	-	-	●	●	●	●	●	●	-	●	●	●	●	●	136,50	
378A	ARTICO man-made leather / Maringá fabric crystal grey with white seams certain countries only not in conjunction with code P34 only in conjunction with code P59, U59	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	-	○	○	○	○	○	0,00	
381A	ARTICO man-made leather / Maringá fabric black with white seams certain countries only not in conjunction with code P34 only in conjunction with code P59, U59	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	-	○	○	○	○	○	0,00	
411	6-speed manual transmission not in conjunction with code 239	S	S	-	-	-	-	S	S	-	-	S	S	-	-	S	S	-	-	-	-	-	-	-	0,00	
429	7G-DCT - dual clutch automatic transmission AMG SPEEDSHIFT DCT 7-speed sports transmission not in conjunction with code U64 Standard Certain countries only	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	●	-	●	●	●	●	●	1848,00	
621A	Ledernachbildung ARTICO / Stoff Macapá certain countries only only in conjunction with code P27, U59	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	-	○	○	○	○	○	0,00	

**Valid from 09.01.2017 FL (808)**

Not for Greece

● available at extra charge   Oavailable at no extra charge   U annotations existing  
S standard equipment   - not available - **BM 156.945 nur Indien (RL) or Korea (LL)**

[illegible]

Not for Greece

● available at extra charge   ○ available at no extra charge   U annotations existing  
S standard equipment   - not available -   **BM 156.945 nur Indien (RL) or Korea (LL)**

[illegible]

**Valid from 09.01.2017 FL (808)**

Not for Greece

● available at extra charge   ○ available at no extra charge   U annotations existing  
S standard equipment   - not available -   **BM 156.945 nur Indien (RL) or Korea (LL)**

[illegible]

Valid from 09.01.2017 FL (808)

Not for Greece

[illegible]

Valid from 09.01.2017 FL (808)

Not for Greece

● available at extra charge   ○ available at no extra charge   U annotations existing  
S standard equipment   - not available -   **BM 156.945 nur Indien (RL) or Korea (LL)**

[illegible]

Valid from 09.01.2017 FL (808)

Not for Greece

● available at extra charge   ○ available at no extra charge   U annotations existing  
S standard equipment   - not available -   **BM 156.945 nur Indien (RL) or Korea (LL)**

[illegible]

**Valid from 09.01.2017 FL (808)**

Not for Greece

[illegible]



24/11/2016 Optional extras for the GLA

Valid from 09.01.2017 FL (808)

National Package
National Standard
Delta to NST
Not for Greece

● available at extra charge    ○ available at no extra charge    U annotations existing  
S standard equipment    - not available - BM 156.945 nur Indien (RL) or Korea (LL)

Code	Designation	156.912	156.908	156.902	156.903	156.905	156.942	156.943	156.944	156.946	156.952	LLP
	only in conjunction with code 505/520 or 522											
862	Preinstallation for TV certain countries only only in conjunction with code 531 or 532	●	●	●	-	-	●	-	-	●	●	84.00
865	TV receiver certain countries only not in conjunction with code 2U0 only in conjunction with code 532 or 532	●	●	●	-	-	●	-	-	●	●	1039.50
871	HANDS-FREE ACCESS only in conjunction with code P17, 889 and 890	○	○	○	○	○	○	○	○	○	○	0.00
873	Heated front seats I.V.m. Code P34/P39/P73	●	●	●	●	●	●	●	●	●	●	304.50
875	Heated windscreen washer system certain countries only	U	●	U	●	U	●	●	●	U	●	120.75
877	Ambient lighting only in conjunction with code U62 and P27/P34/ P39/P59/P73 or 950 I.V.m. Code P74	U	U	U	U	U	U	U	U	U	U	126.00
880	Enhanced central locking system not in conjunction with code 889 or 893 only in conjunction with code P34/P39 or P73	○	○	○	○	○	○	○	○	○	○	0.00
882	Interior monitoring system certain countries only only in conjunction with code P54	○	○	○	○	○	○	○	○	○	○	0.00
885	Increased anti-theft protection only 537L	○	○	○	○	○	○	○	○	○	○	0.00
889	KEYLESS-GO certain countries only not in conjunction with code 880 or 893 I.V.m. Code P17	●	●	●	●	●	●	●	●	●	●	472.50
890	EASY-PACK tailgate I.V.m. Code P17	●	●	●	●	●	●	●	●	●	●	409.50
893	KEYLESS GO starting function certain countries only not in conjunction with code 880 oder 889	S	S	S	S	S	S	S	S	S	S	0.00
894	Complete winter (M+S) wheel-and-tyre assembly x 4	-	-	-	-	-	-	-	-	●	-	2835.00
913	Air conditioning preinstallation for hot countries certain countries only	○	○	○	○	-	-	-	-	-	-	0.00
922	Reduced power version only in conjunction with code 513L only in conjunction with code 524L	-	-	-	U	U	U	U	-	-	-	0.00
926	Emission control system with EU4 technology certain countries only	○	○	-	-	○	○	○	○	○	S	0.00
927	EU6 emissions standard certain countries only	S	S	S	S	S	S	S	S	S	○	0.00
928	EU5 emission standard certain countries only	-	-	-	-	○	○	○	○	○	S	0.00
929	Ethanol fuelled engine certain countries only not in conjunction with code 920	-	-	-	-	-	-	-	-	○	○	0.00
931	Tandem interior mirror only in conjunction with code U63 (only LHD)	○	○	○	○	○	○	○	○	○	○	0.00
932	Storage compartment front seat left not in conjunction with code 555 not in conjunction with code 682 (only LHD) only in conjunction with code 30P	○	○	○	○	○	○	○	○	U	○	0.00
933	Engine for ethanol fuel E100	-	-	-	-	-	●	-	-	-	-	315.00
939	Storage box under front passenger seat not in conjunction with code 555 not in conjunction with code 682 (only RHD) only in conjunction with code 30P	○	○	○	○	○	○	○	○	U	○	0.00
942	Load compartment package in conjunction with code 021A/028A/105A/111A/118A/621A/625A or 631A only with 842 or 242 (RHD not with 842) in conjunction with code 381A/378A/651A/801A/804A/811A/831A/855A, not in conjunction with code 842 only in conjunction with code U35 in conjunction with Code 242, 950, P34, P73 or (P59 AND NOT 111A/105A/118A)	●	●	●	●	●	●	●	●	●	●	152.25
968	COC document EU6 without registration certificate part II certain countries only	○	○	○	○	○	○	○	○	○	○	0.00
969	COC document EU6 with registration certificate part II certain countries only	○	○	○	○	○	○	○	○	○	○	0.00
973	Designation as owner-driver rental vehicle	○	○	○	○	○	○	○	○	○	○	0.00
981	Omission of vehicle registration document	○	○	○	○	○	○	○	○	○	○	0.00
986	Identification no. (US-VIN) certain countries only	○	○	○	○	○	○	○	○	○	○	0.00
989	Identification label under windshield certain countries only; Standard certain countries only	○	○	○	○	○	○	○	○	○	○	0.00
997	Exhibition vehicle certain countries only	○	○	○	○	○	○	○	○	○	○	0.00
B02	Fanfare horn, electronic, for India	-	○	○	○	○	○	○	○	○	S	0.00
B03	ECO start/stop function	S	S	S	S	S	S	S	S	S	S	0.00
B08	Fanfare horn certain countries only	U	U	U	U	U	U	U	U	U	S	0.00
B12	Tyre-change toolkit (certain countries only) only in conjunction with code 690	●	●	●	●	●	●	●	●	●	●	31.50
B24	remote control for auxiliary heater certain countries only only in conjunction with code 228 I.V.m. Code 360/362	-	○	○	○	○	○	○	○	-	○	0.00
B28	AMG carbon-fibre exterior mirrors certain countries only not in conjunction with code 501 oder P44	U	●	●	●	●	●	●	●	U	●	210.00
		★	●	●	●	●	●	★	★	●	●	1260.00

Valid from 09.01.2017 FL (808)

Not for Greece

● available at extra charge   ○ available at no extra charge   U annotations existing  
S standard equipment   - not available -   **BM 156.945 nur Indien (RL) or Korea (LL)**

[illegible]

**Valid from 09.01.2017 FL (808)**

## Not for Greece

Code	Designation	LLP
	<b>In conjunction with Code P59</b>	<b>136,50</b>
R48	<b>43.2 cm (17-inch) 5-twin-spoke light-alloy wheels</b> certain countries only in cert. countries only in conjunction with P59; but not with R66 not in conjunction with code R66, P55, P59 or 950 <b>in conjunction with Code P27</b>	<b>52,50</b>
R66	<b>Run-flat tyres</b> in conjunction with code 04R only in conjunction with code 645 in conjunction with code 633/R31/01R/82R/635/655/48R/65R/77R/RUG/RUH/RV1 and RVJ only in conjunction with code R01 in conjunction with code R31/01R/82R635/655/48R/65R/RUG/RUH/RV1 or RVJ only in conjunction with code R02 not in conjunction with code B51(certain countries only) /754/758/778/R00/R05/R48/08R/1R0/1R7/2R4/4R6/5R1/RVU/RVV or RVW	<b>220,50</b>
RUG	<b>48.3 cm (19-inch) AMG multi-spoke light-alloy wheels )</b> in conjunction with code 645 not with code R66 in conjunction with code R01/R02 only in conjunction with code R66 only in conjunction with PEK	<b>0,00</b>
RUH	<b>48.3 cm (19-inch) AMG multi-spoke light-alloy wheels</b> in conjunction with code 645 not with code R66 in conjunction with code R01/R02 only in conjunction with code R66 only in conjunction with PEK	<b>0,00</b>
RV1	<b>48.3 cm (19-inch) AMG multi-spoke light-alloy wheels</b> certain countries only in conjunction with code Code 645 not in conjunction with R66 in conjunction with code Code R01/R02 only in conjunction with R66 <b>i.V.m. Code 950</b> <b>i.V.m. Code 950+P55</b> <b>i.V.m. Code P59</b>	<b>1995,00</b>
RVJ	<b>48.3 cm (19-inch) AMG multi-spoke light-alloy wheels</b> certain countries only in conjunction with code Code 645 not in conjunction with R66 in conjunction with code Code R01/R02 only in conjunction with R66 <b>i.V.m. Code 950</b> <b>i.V.m. Code P59</b>	<b>1575,00</b>
RVU	<b>50.8 cm (20-inch) AMG multi-spoke alloy wheels</b> not in conjunction with code R66 only in conjunction with code R01	<b>840,00</b>
RVV	<b>50.8 cm (20-inch) AMG multi-spoke alloy wheels</b> not in conjunction with code R66 only in conjunction with code R01	<b>1207,50</b>
RVW	<b>50.8 cm (20-inch) AMG 10-spoke light-alloy wheels</b> certain countries only not in conjunction with code R66 only in conjunction with code P74 and R01	<b>0,00</b>
U01	<b>Status display for rear seat belts in instrument cluster</b> certain countries only	<b>0,00</b>
U03	<b>Omission of decals for special models</b> not in conjunction with code U15 only in conjunction with code PEK	<b>0,00</b>
U09	<b>Upper section of dashboard in ARTICO man-made leather</b> only in conjunction with code P34, P39/P73 Standard <b>i.V.m. Code P34/P39/P73</b>	<b>210,00</b>
U10	<b>Automatic deactivation of front passenger airbag</b> certain countries only not in conjunction with code 161A/165A/168A <b>in conjunction with Code 108 (only ECE)</b>	<b>99,75</b>
U12	<b>Velour floor mats</b> certain countries only not in conjunction with code 950/P34/P73	<b>84,00</b>
U13	<b>"EDITION" badge on the wing</b> not in conjunction with code 261 only in conjunction with code PEK	<b>0,00</b>
U15	<b>Decals in matt black</b> not in conjunction with Code U03 only in conjunction with Code PEK and 650U	<b>0,00</b>
U17	<b>Omission of designo seat belts in red</b> only in conjunction with code 651A or 811A	<b>0,00</b>
U21	<b>Sports exhaust system</b>	<b>682,50</b>
U22	<b>4-way lumbar support</b> not in conjunction with code 555 only in conjunction with code U59 <b>i.V.m. Code P34/P39/P73</b>	<b>162,75</b>
U25	<b>Door sill panels with "Mercedes-Benz" lettering, illuminated</b> AMG door sill panels with »AMG« lettering, illuminated only in conjunction with code U62	<b>0,00</b>
U26	<b>AMG floor mats</b> certain countries only Cord floor mats with edging in black and black contrasting topstitching as well as AMG lettering (i.c.w. PEK) not in conjunction with code P34/P73 not in conjunction with code P74 only in conjunction with code 950 (Cord floor mats with edging in black and black contrasting topstitching as well as AMG lettering)	<b>0,00</b>
U35	<b>Socket in load compartment</b> only in conjunction with code 942	<b>0,00</b>
U37	<b>Front fog lamps</b> not in conjunction with code 950,951,772	<b>194,25</b>
U40	<b>Partition net</b> certain countries only not in conjunction with code 413	<b>204,75</b>
U47	<b>AMG rear aerofoil</b> certain countries only <b>in conjunction with Code B26</b>	<b>787,50</b>

**24/11/2016** **Optional extras for the GLA**

Valid from 09.01.2017 FL (808)

Valid from 09.01.2017 FL (808)

National Package

National Standard

Delta to NST

Not for Greece

● available at extra charge   O available at no extra charge   U annotations existing  
S standard equipment   - not available -   BM 156.945 nur Indien (RL) or Korea (LL)

Code	Description	S	T	F	C	P	V	E	L	A	B	N	M	O	I	D	R	LLP
U60	<b>Active Bonnet</b> certain countries only	S	S	S	S	S	S	S	S	-	S	S						0.00
U64	<b>Full driving school package</b> not in conjunction with code 429 only in conjunction with code U63 only LHD	●	●	-	-	-	●	●	●	-	-	●	-	■	■	■		1207.50
U65	<b>Additional exterior mirror right and left</b> contains: code U63 only LHD	●	●	●	●	●	●	●	●	-	●	●		■	■	■		126.00
U70	<b>Red-painted brake callipers</b>	-	-	-	-	-	-	-	-	●	-	-		-	-	-		336.00
Y05	<b>designo seat belts in red</b>  only in conjunction with code 651A or 811A	-	●	-	-	-	●	-	●	-	●	-	○	-	■	■		0.00 315.00
Z83	<b>Activation hill-start assist driving school</b> only in conjunction with code U64	○	○	-	-	-	○	○	○	-	*	○	-	○	-	-		0.00
Z97	<b>Electronic interface</b> not in conjunction with code 537 only LHD models and certain countries only	●	●	●	●	●	●	●	●	●	●	●	■	■	■	■		399.00