

27/2/2018 Optional extras for the A-Class

Valid from 05.03.2018 (808+058)

1) A 250 available in 2. quarter of 2018

 ● available at extra charge ◯ available at no extra charge ◯ annotations existing
 S standard equipment - not available

A			
Limousine			
	A 180 d	A 200	A 250 ¹⁾
	177.003	177.087	177.046

		LLP		
L	Left-hand drive	○	○	○
R	Right-hand drive	●	●	●
144U	digital white metallic available expected 2. Quarter 2018	○	○	○
149U	polar white	●	●	●
	only in conjunction with Code PYF	●	●	●
191U	cosmos black metallic	●	●	●
589U	jupiter red	○	○	○
662U	designo mountain grey magno	●	●	●
696U	night black available expected 2. Quarter 2018	○	○	○
775U	iridium silver metallic	●	●	●
787U	mountain grey metallic	●	●	●
001A	Tandel fabric black Not in conjunction with Code P27/P59 or 950 only in conjunction with code 7U1	○	○	○
101A	Black ARTICO man-made leather only in conjunction with Code 7U2 and P27/P59	●	●	●
105A	ARTICO man-made leather macchiato beige / black Only in conjunction with Code P59 and 7U2	●	●	●
109A	ARTICO man-made leather neva grey / black Only in conjunction with Code P27 and 7U2	●	●	●
111A	ARTICO man-made leather black certain countries only only in conjunction with Code 7U3 and (P27/P59)	●	●	●
	only in conjunction with Code PYF	●	●	●
115A	ARTICO man-made leather, sports seat macchiato beige / black certain countries only only in conjunction with code 7U3 and P59	●	●	●
	only in conjunction with Code PYF	●	●	●
119A	ARTICO man-made leather, sports seat neva grey / black only in conjunction with code 7U3 and P27	●	●	●
159A	Two-tone ARTICO man-made leather neva grey / black only in conjunction with code 7U3 and 950	○	○	○
201A	Leather black only in conjunction with Code P34 and P59 and 7U2	○	○	○
204A	Leather bahia brown / black only in conjunction with Code P34 and 7U3	○	○	○
205A	Leather macchiato beige / black Only in conjunction with Code P34 and P59 and 7U2	○	○	○
211A	Leather black only in conjunction with code P34 and 7U3	○	○	○
257A	Two-tone leather classic red / black only in conjunction with code 7U3 and P39	○	○	○
258A	Two-tone leather titanium grey pearl / black only in conjunction with code 7U3 and P39	○	○	○
311A	ARTICO man-made leather / Bertrix fabric black only in conjunction with code P27 and 7U2	○	○	○
321A	ARTICO man-made leather / Fléron fabric black only in conjunction with code P59 and 7U2	○	○	○
371A	ARTICO man-made leather/ Bertrix fabric, two-tone black / neva grey only in conjunction with Code P27 and 7U2	○	○	○
372A	ARTICO man-made leather/ Bertrix fabric, two-tone black indigo blue / black only in conjunction with Code P27 and 7U2	○	○	○
381A	ARTICO man-made leather/ Fléron fabric, two-tone black / Bahia brown only in conjunction with code P59 and 7U2	○	○	○
411	6-speed manual transmission available expected 2. Quarter 2018 certain countries only invalid	S	S	-
429	7G-DCT	S	-	S
611A	ARTICO man-made leather / DINAMICA microfibre black only in conjunction with code P19 and 7U3	○	○	○
651A	ARTICO man-made leather/DINAMICA microfibre upholstery black Only in conjunction with Code 950 and 7U3	○	○	○
22P	Lane Tracking package certain countries only not in conjunction with code 23P or 51B only in conjunction with Code 234 and 243	●	●	●
23P	Driving Assistance package available expected 4. Quarter 2018 in conjunction with Code 365 only in conjunction with Code 513 not in conjunction with Code 22P	●	●	●

27/2/2018 Optional extras for the A-Class
Valid from 05.03.2018 (808+058)
1) A 250 available in 2. quarter of 2018

● available at extra charge ◐ available at no extra charge ◑ annotations existing
S standard equipment - not available

		A Limousine			
		177.003 A 180 d	177.087 A 200	177.046 A 250 ¹⁾	
					LLP
L	Left-hand drive only in conjunction with code 233, 299 and (275/P49) i.V.m. Code 51B	●	●	●	0,00 1585,50
431	Galvanised steering-wheel gearshift paddles not in conjunction with code 428 only in conjunction with code (426/429) and L5C/L5I	○	○	○	0,00
950	AMG Line not in conjunction with code P27 or P59 only in conjunction with code (159A/651A/204A/211A/257A/258A/611A) only in conjunction with code Code 310 and (651A/H44/H15/H23/H45) and (677/485/459) and 772 and (RQS/RQT/RVG/RVK)+(U26/U00) and U62 i.V.m. Code P19 i.V.m. Code PYH, only available via PYH	◑	◑	◑	3097,50 0,00 0,00
P19	Edition 1 available expected 2. Quarter 2018 only in conjunction with code (144U/149U/191U/662U/696U/787U) and 611A and (631/632/640/641/642) and 877, 950, P55, RVI and U66 i.V.m. Code PYH	◑	◑	◑	6195,00 2226,00
P27	Style certain countries only Not in conjunction with Code P59 or 950 Only in conjunction with Code 2U5, 310 and (101A/109A/111A/119A/311A/371A/372A) and U62 and R78/76R/643/R00/R11/R30/R31/R55/01R or T2R i.V.m. Code PYB/PYD, only available via PYB or PYD	◑	◑	◑	0,00 0,00
P34	Leather package Not in conjunction with Code P39 Only in conjunction with Code (401/873), (201A/204A/205A/211A), 950 or P59 i.V.m. Code 950	●	●	●	1459,50 1207,50
P39	AMG Leather package Not in conjunction with Code P34 only in conjunction with code 950, (257A/258A) and (401/873), only available on AMG Line (PYH)	●	●	●	1207,50
P44	Parking Package not in conjunction with P47 only in conjunction with code 235 and 218 i.V.m. Code PYA i.V.m. Code PYM/PYN/PYO	●	●	●	976,50 624,75 0,00
P47	Parking Package with 360° camera not in conjunction with code P44 or 218 only in conjunction with code (P27/P59/950) and (233/234) and 235, 501, 270 and 274 only i.V.m. Code PYM/PYN/PYO	◑	◑	◑	1407,00 430,50
P49	Mirror package Consisting of: Code 249, 500 and U62 i.V.m. Code PYM/PYN/PYO	●	●	●	383,25 0,00
P54	Anti-Theft Protection package certain countries only only in conjunction with code 551, 882 and U62	●	●	●	430,50
P55	Night package only in conjunction with code P59, and 01R/643/R00/R11/R30/R31/R55/R78/72R/76R/RQT/RVG/RVK or 950 and (RVG/RVK/RVI or RQT but not with 645) i.V.m. Code 950 i.V.m. Code P19	◑	◑	◑	840,00 409,50 0,00
P59	Progressive not in conjunction with code P27/950 only in conjunction with code 310 and 2U5 and (101A/105A/111A/115A/201A/205A/211A/321A/381A) and (101A/105A/201A/204A) and 72R/643/R00/R11/R30/R31/R55/R78/01R/76R and (H15/H23/H44/H45/H55/H59) and U62 i.V.m. Code PYF, only available via PYF	- ◑	- ◑	◑ -	1412,25 1648,50 0,00
PAC	Vorteils-Paket	S	S	S	0,00
PAD	Engineering package only in conjunction with code U29, 459, (641/642) and 889	●	●	●	3108,00
PBF	Connectivity paket certain countries only not in conjunction with code PBG only in conjunction with code 365 and 01U	●	●	●	682,50
PBG	Comfort Connectivity package certain countries only not in conjunction with code PBF only in conjunction with code 365, 01U, 02U and 12U	●	●	●	808,50

27/2/2018 Optional extras for the A-Class

Valid from 05.03.2018 (808+058)

1) A 250 available in 2. quarter of 2018

 ● available at extra charge ○ available at no extra charge U annotations existing
 S standard equipment - not available

A Limousine			
177.003	A 180 d		
177.087	A 200		
177.046	A 250 ¹⁾		

		LLP		
L	Left-hand drive	○	○	○
	only in conjunction with code 859			0,00
PBI	Konnektivitäts-Paket Smartphone	●	●	●
	certain countries only			420,00
	only in conjunction with code 08U, 09U and 14U			
PYA	WEU Standard Equipment	●	●	●
	certain countries only			0,00
PYB	SE Package	●	●	-
	certain countries only			0,00
PYD	Style Line	-	-	S
	Delta due to PYB	●	●	-
	certain countries only			887,00
PYF	Progressive Line	-	-	●
	Delta due to PYB	●	●	-
	certain countries only			2819,25
	Delta due to PYB	●	●	-
	certain countries only			1411,00
PYH	AMG Line	-	-	●
	Delta due to PYB & U12	●	●	-
	certain countries only			1989,75
	Delta due to PYB & U12	●	●	-
	certain countries only			2777,25
PYM	Advantage Package	●	●	●
	certain countries only			1720,00
	only in conjunction with Code PYF	●		
				1335,00
PYN	Premium Package	●	●	●
	certain countries only			3304,00
PYO	Premium Plus Package	●	●	●
	certain countries only			4699,00
U59	Seat comfort package	○	○	○
	not in conjunction with code 7U1			0,00
U62	Light and sight package	○	○	○
	only in conjunction with Code 543, B18 und (P27/P59 or 950)			0,00
U63	Basic driving school package	●	●	●
	available expected 2. Quarter 2018			572,25
	code U12 or U26 available			
	not in conjunction with code 426/429/840/877/896/897 or 899			
	only in conjunction with code P27/P59 or 950 and U00, U65 and 931			
	only LHD (certain countries only)			
00B	Owner's Manual and Service Booklet - Danish	○	○	○
01B	Owner's Manual and Service Booklet - Dutch	○	○	○
01R	45.7 cm (18-inch) 5-twin-spoke light-alloy wheels	-	-	●
	not in conjunction with code 950	●	●	-
	i.V.m. Code P27	●	●	-
	i.V.m. Code P55	-	-	●
	i.V.m. Code P59	○	○	○
	only available i.V.m. Code PYF	●	●	●
		●	●	●
				1312,50
				1627,50
				1155,00
				840,00
				0,00
				840,00
				840,00
01U	Navigation services	○	○	○
	certain countries only			0,00
	only in conjunction with code 362			
	only in conjunction with code PBG or PBF			
02B	Owner's Manual and Service Booklet - German	○	○	○
02U	Office function in the vehicle	○	○	○
	certain countries only			0,00
	only in conjunction with code PBG and 859			
03B	Owner's Manual and Service Booklet - Russian	○	○	○
04B	Owner's Manual and Service Booklet - Finnish	○	○	○
05B	Owner's Manual and Service Booklet - English	○	○	○
06B	Owner's Manual and Service Booklet - Italian	○	○	○
07B	Owner's Manual and Service Booklet - French	○	○	○
08B	Owner's Manual and Service Booklet - Spanish	○	○	○
08U	Vehicle Setup	○	○	○
	certain countries only			0,00
	only in conjunction with 09U, 362 and (PBI in certain countries only)			
09B	Owner's Manual and Service Booklet - Portuguese	○	○	○
				0,00

27/2/2018 Optional extras for the A-Class

Valid from 05.03.2018 (808+058)

1) A 250 available in 2. quarter of 2018

 ● available at extra charge ◯ available at no extra charge U annotations existing
 S standard equipment - not available

A			
Limousine			
	A 180 d	A 200	A 250 ¹⁾
	177,003	177,087	177,046

LLP

L	Left-hand drive	○	○	○	0,00
09U	Vehicle Monitoring certain countries only only in conjunction with 08U, 362 and (PBI in certain countries only)	○	○	○	0,00
10B	Owner's Manual and Service Booklet - Swedish	○	○	○	0,00
11B	Owner's Manual and Service Booklet - Arabic	○	○	○	0,00
12B	Owner's Manual and Service Booklet - Engl. USA/CAN	○	○	○	0,00
12U	Preinstallation for Concierge Service certain countries only only in conjunction with 362 and PBG	○	○	○	0,00
13B	Owner's Manual and Service Booklet - Norwegian	○	○	○	0,00
14B	Owner's Manual and Service Booklet - Greek	○	○	○	0,00
14U	Smartphone integration certain countries only only in conj. With Code 16U and 17U i.V.m. Code PBI	●	●	●	262,50
15B	Owner's Manual and Service Booklet - Turkish	○	○	○	0,00
16B	Owner's Manual and Service Booklet - Polish	○	○	○	0,00
16U	Apple CarPlay only in conj. With Code 14U	○	○	○	0,00
17B	Owner's Manual and Service Booklet - Czech	○	○	○	0,00
17U	Android Auto only in conj.with Code 14U	○	○	○	0,00
18B	Owner's Manual and Service Booklet - Engl. S. Am.	○	○	○	0,00
19B	Owner's Manual and Service Booklet - French S. Am.	○	○	○	0,00
20B	Owner's Manual and Service Booklet - Spanish S. Am.	○	○	○	0,00
213	Direct-Steer system only in conjunction with code (459/677) or (486 only AMG)	○	○	○	0,00
218	Reversing camera not in conjunction with code 501 i.V.m. Code P44 i.V.m. Code PYA	●	●	●	0,00
21B	Owner's Manual and Service Booklet - Portug. S. Am.	○	○	○	0,00
228	Auxiliary heater available expected 2. Quarter 2018 certain countries only in conjunction with code B24 only LHD	●	●	●	1155,00
22B	Owner's Manual and Service Booklet - Japanese	○	○	○	0,00
232	Garage door opener (frequency range 284-390 MHz) Certain countries only (460/494/777L) Only in conjunction with Code U62 or P49	●	●	●	236,25
233	Active Distance Assist DISTRONIC available expected 4. Quarter 2018 certain countries only not in conjunction with Code L3A, 234, 258 or 440 only in conjunction with Code 23P, 266, 270, 273, (426/429)	○	○	○	0,00
234	Blind Spot Assist Certain countries only not in conjunction with code 233 only in conjunction with code 270, 273 and(275 or P49) i.V.m. Code 22P	●	●	●	472,50
235	Active Parking Assist with PARKTRONIC only available i.V.m. Code P44/P47	○	○	○	0,00
239	Active Distance Assist DISTRONIC Not in conjunction with Code L3A/ 233/258 or 440 Only in conjunction with Code 426 or 429	●	●	●	630,00
23B	Owner's Manual and Service Booklet - simpl. Chinese	○	○	○	0,00
241	Front seat left, electrically adjustable memory switch Only in conjunction with Code 275 Right-hand-drive vehicles only i.V.m. Code PYO	●	●	●	299,25
242	Front pass. seat, electrically adj. with memory function LHD version Only in conjunction with Code 275 i.V.m. Code PYO	○	○	○	0,00
243	Active Lane Keeping Assist not in conjunction with code 233 i.V.m. Code 22P/51B	●	●	●	0,00
249	Interior mirror and driver's exterior mirror automatically dimming Only in conjunction with Code P49	○	○	○	0,00
24B	Owner's Manual and Service Booklet - trad. Chinese	○	○	○	0,00
258	Active Brake Assist Certain countries only not in conjunction with code 233 or 239	○	○	○	0,00

27/2/2018 Optional extras for the A-Class
Valid from 05.03.2018 (808+058)
1) A 250 available in 2. quarter of 2018

● available at extra charge ◌ available at no extra charge U annotations existing
S standard equipment - not available

A			
Limousine			
	A 180 d	A 200	A 250 ¹⁾
	177,003	177,087	177,046

					LLP
L	Left-hand drive	◌	◌	◌	0,00
25B	Owner's Manual and Service Booklet - Korean	◌	◌	◌	0,00
260	Omission of model plate on boot lid	◌	◌	◌	0,00
263	Number plate mounting for Asia / Mexico certain countries only and not in conj. With code 968	◌	◌	◌	0,00
264	Number plate mounting for America not in conjunction with Code 968	◌	◌	◌	0,00
266	DISTRONIC PLUS with Cross-Traffic Assist (DTR+Q) certain countries only only in conjunction with code 233	◌	◌	◌	0,00
26B	Owner's Manual and Service Booklet - Chinese Taiwan	◌	◌	◌	0,00
270	Aerial for GPS only in conjunction with Code 501/899/B24/233/234/355/362	◌	◌	◌	0,00
273	Exit Warning Assistant only in conjunction with Code 233 or 234	◌	◌	◌	0,00
274	Aerial for telephone only in conjunction with code 501/899 or B24	◌	◌	◌	0,00
275	Driver's seat, electrically adjustable with memory function only in conjunction with code (U22/409) i.V.m. Code PYO	●	●	●	362,25
286	Luggage net on driver's and front pass. backrest only in conjunction with code 7U2/7U3	U	U	U	0,00
287	Folding rear-seat backrests only in conjunction with code 7U2/7U3	U	U	U	0,00
293	Sidebags in rear certain countries only only in conjunction with code 7U2/7U3	U	U	U	393,75
294	Kneebag Certain countries only	U	U	U	0,00
299	PRE-SAFE® system i.V.m. Code 23P	●	●	●	346,50
2R9	Winter (M+S) wheel and tyre assembly x 4 certain countries only and only in conj. With code 651 or 652	●	●	●	1417,50
2U0	Car2Go wiring harness and coding certain countries only only in conjunction with code (355/859)	●	●	●	178,50
2U5	Painted side skirts only in conjunction with P27/P59	◌	◌	◌	0,00
301	Ashtray insert for cup holder with cigarette lighter certain countries only	●	●	●	47,25
30B	Owner's Manual and Service Booklet - Slovenian	◌	◌	◌	0,00
310	Twin cup holder i.V.m. Code P27/P59/950 i.V.m. Code PYA	●	●	●	0,00
31B	Owner's Manual and Service Booklet - Hungarian	◌	◌	◌	0,00
32B	Owner's Manual and Service Booklet - Bulgarian	◌	◌	◌	0,00
33B	Owner's Manual and Service Booklet - Romanian	◌	◌	◌	0,00
345	Windscreen wiper with rain sensor	S	S	S	0,00
34B	Owner's Manual and Service Booklet - Croatian	◌	◌	◌	0,00
351	Mercedes-Benz emergency call system only in conj. With Code 362	◌	◌	◌	0,00
355	Extended MBUX functions certain countries only only in conjunction with Code (548/549) and 270 and 446 i.V.m. Code PYA	●	●	●	0,00
35B	Owner's Manual and Service Booklet - Latvian	◌	◌	◌	0,00
362	Communications module (LTE) for the use of Mercedes me connect services cert. Countries only only in conjunction with code 270 and 351 Standard in certain countries only	◌	◌	◌	0,00
365	Hard-disc navigation only in conjunction with code 355 i.V.m. Code PYM/PYN/PYO	●	●	●	577,50
367	Preinstallation for Live Traffic Information only in conj. with Code 355 and 362 and certain countries only i.V.m. Code PYA	◌	◌	◌	0,00
36B	Owner's Manual and Service Booklet - Lithuanian	◌	◌	◌	0,00
37B	Owner's Manual and Service Booklet - Slovakian	◌	◌	◌	0,00
38B	Owner's Manual and Service Booklet - Estonian	◌	◌	◌	0,00
39B	Owner's Manual and Service Booklet - Serbian	◌	◌	◌	0,00
3R1	winter (M+S) wheel and tyre assembly x 4 certain countries only and only in conj. With code 651 or 652 not in conjunction with Code U29	●	●	-	1102,50

27/2/2018 Optional extras for the A-Class
Valid from 05.03.2018 (808+058)
1) A 250 available in 2. quarter of 2018

● available at extra charge ◌ available at no extra charge ◌ annotations existing
S standard equipment - not available

A Limousine			
177.003	A 180 d	177.087	A 200
		177.046	A 250 ¹⁾

		LLP			
L	Left-hand drive	◌	◌	◌	0,00
400	Rear armrest only in conjunction with Code 287 only available i.V.m. Code PYN/PYO	●	●	●	173,25
		◌	◌	◌	0,00
401	Climatised front seats certain countries only in conjunction with Sportseat code 7U3 available expected 2. Quarter 2018 not in conjunction with code 873 only in conjunction with Code 101A/105A/109A/111A/115A/119A/159A/201A/204A/205A/211A/257A/258A or 259A only available i.V.m. Code PYN/PYO	●	●	●	934,50
		●	●	●	630,00
409	Multicontour seat package available expected 2. Quarter 2018 certain countries only only in conjunction with code 7U2 but not with code U22	◌	◌	◌	619,50
		★	★	★	
40B	Owner's Manual and Service Booklet - ukrainian	◌	◌	◌	0,00
413	Panoramic sliding sunroof only in conjunction with Code U62 and 51U i.V.m. Code PYO	◌	◌	◌	976,50
		★	★	★	
		◌	◌	◌	0,00
41B	Owner's Manual and Service Booklet - hebrew	◌	◌	◌	0,00
428	Steering wheel shift paddles Only in conjunction with Code 426 or 429 and (L3A/L3B or L3E)	S	◌	S	0,00
42B	Owner's Manual and Service Booklet - Indonesian	◌	◌	◌	0,00
43B	Owner's Manual and Service Booklet - Thai	◌	◌	◌	0,00
440	Cruise control Not in conjunction with Code 233 or 239	S	S	S	0,00
443	Heated multifunction steering wheel not in conjunction with code 950 (except with code 460) only in conjunction with code (426/429) and L3B i.V.m. Code P59/950	●	●	●	351,75
		●	●	●	168,00
446	Touchpad i.V.m. Code PYA	●	●	●	0,00
		◌	◌	◌	0,00
44B	Owner's Manual and Service Booklet - Vietnamese	◌	◌	◌	0,00
458	All-digital instrument display As single option only available i.V.m Code PYM only in conjunction with code 859 und 365 i.V.m. Code PYN/PYO	●	●	●	472,50
		◌	◌	◌	0,00
459	Suspension with Adaptive Damping system certain countries only only in conjunction with code 213 i.V.m. Code 950 (ohne PYH) i.V.m. Code PAD	●	●	●	1039,50
		●	●	●	735,00
		◌	◌	◌	0,00
460	Canada specification	-	-	◌	0,00
463	Head-up Display only in conjunction with code 355/859 and P59 or 950, only i.V.m Code PYM/PYN/PYO	●	●	●	1039,50
474	Diesel particulate filter	◌	-	-	0,00
475	Tyre pressure monitoring system Certain countries only i.V.m. S-Code 6P5	●	●	●	320,25
		◌	◌	◌	0,00
477	Tyre pressure loss warning system Certain countries only	◌	◌	◌	0,00
482	Suspension with higher ground clearance Certain countries only	●	●	●	105,00
485	Comfort suspension Not in conjunction with Code 950	S	S	S	0,00
500	Electrically folding exterior mirrors Only in conjunction with Code P49	◌	◌	◌	0,00
501	360° camera not in conjunction with code 218 only in conjunction with code 270 and 274 and (233/234) and P47	◌	◌	◌	0,00
		★	★	★	
504	Speed Limit Assist not in conjunction with Code 513, 365 and 233 only in conjunction with Code 51B	◌	◌	◌	0,00
513	Traffic Sign Assist not in conjunction with Code 504 only in conjunction with Code 23P and 365 and certain countries only	●	●	●	309,75
517	HD digital radio standard certain countries only	◌	◌	◌	0,00
51B	Rating Laenderset EURO-NCAP certain countries only only in conjunction with code (258 or 239) and (243 or 233) and (504 or 513)	◌	◌	◌	0,00
51U	Roof liner in black fabric not available as single option, standard with SE (PYB), Style (PYD), Progressive (PYF) and AMG Line (PYH)	◌	◌	◌	0,00

27/2/2018 Optional extras for the A-Class
Valid from 05.03.2018 (808+058)
1) A 250 available in 2. quarter of 2018

● available at extra charge ○ available at no extra charge U annotations existing
S standard equipment - not available

A Limousine			
	A 180 d	A 200	A 250 ¹⁾
	177.003	177.087	177.046

		LLP		
L	Left-hand drive	○	○	○
524	Transport protection certain countries only and only in conj. With code 662U not in conjunction with code 820	●	●	●
536	Sirius satellite radio certain countries only only in conjunction with code 355/859	-	-	●
537	Digital radio certain countries only not in conjunction with code 79B	●	●	●
539	Digital radio standard DRM (Digital Radio Mondial) certain countries only	●	●	●
543	Sun visor with illuminated vanity mirror Only in conj. with Code U62	○	○	○
545	MBUX multimedia system certain countries only not in conjunction with code 355/859/PBF or PBG	S	S	S
546	Automatic speed control certain countries only only in conjunction with code 233 and 513	○	○	○
548	MBUX multimedia system certain countries only not in conjunction with code 256 not in conjunction with code 859 only in conjunction with code 355	U ★	U ★	U ★
549	MBUX multimedia system only in conjunction with code 859 and 355	○	○	○
550	Trailer coupling with ESP® trailer stabilisation certain countries only	●	●	●
551	Anti-theft alarm system Only in conjunction with Code P54 or certain countries only i.V.m. Code P54	●	●	●
552	Anti-theft alarm system Only in conjunction with Code P54 and 513L	○	○	○
580	Air conditioning system certain countries only	○	○	○
581	THERMOTRONIC automatic climate control only available i.V.m. Code PYF/PYH	●	●	●
58U	Roof liner in crystal grey fabric not in conjunction with code 105A/109A/115A/119A/159A/205A or 371A Not in conjunction with Code 413	U ★	U ★	U ★
598	Petrol particulate filter certain countries only only in conjunction with code 927	-	○	○
608	Adaptive Highbeam Assist certain countries only Only in conjunction with Code 631/632 or 640 i.V.m. Code 640	●	●	●
613	Headlamps for RHD vehicles not in conjunction with code PAD Part of standard specification for LHD countries	○	○	○
620	Halogen headlamps with integrated LED daytime running lamps certain countries only not in conjunction with code PAD standard RHD	○	○	○
623	Gulf States specification	-	●	●
625	Australia specification	○	○	○
628	Adaptive Highbeam Assist Plus not in conjunction with code 608 only in conjunction with Code 641/642	○	○	○
631	LED High Performance headlamp (RHD) Certain countries only not in conjunction with Code PAD i.V.m. Code P19 i.V.m. Code PYD/PYF/PYH	U ★	U ★	U ★
632	LED High Performance headlamp for right-hand traffic Certain countries only not in conjunction with code PAD i.V.m. Code P19 i.V.m. Code PYD/PYF/PYH	U ★	U ★	U ★
634	Omission of first-aid kit certain countries only	○	○	○
636	Omission of warning triangle certain countries only	○	○	○

27/2/2018 Optional extras for the A-Class
Valid from 05.03.2018 (808+058)
1) A 250 available in 2. quarter of 2018

● available at extra charge ○ available at no extra charge U annotations existing
S standard equipment - not available

A Limousine			
177.003	A 180 d		
177.087	A 200		
177.046	A 250 ¹⁾		

					LLP
L	Left-hand drive not in conjunction with code 820	○	○	○	0,00
640	Headlamps, LED, dynamic, SAE, right-side traffic certain countries only only in conjunction with code 608 i.V.m. Code P19	-	-	●	1312,50
641	MULTIBEAM LED LV/RL available expected 2. Quarter 2018 certain countries only only in conjunction with code 628 i.V.m. Code P19 i.V.m. Code PAD i.V.m. Code PYD/PYF/PYH i.V.m. Code PYO	●	●	●	1312,50
		●	●	●	441,00
		○	○	○	0,00
		●	●	●	441,00
		○	○	○	0,00
642	MULTIBEAM LED available expected 2. Quarter 2018 certain countries only only in conjunction with code 628 i.V.m. Code P19 i.V.m. Code PAD i.V.m. Code PYD/PYF/PYH i.V.m. Code PYO	●	●	●	1312,50
		●	●	●	441,00
		○	○	○	0,00
		●	●	●	441,00
		○	○	○	0,00
643	43.2 cm (17-inch) steel wheels with wheel trims certain countries only not in conjunction with code 950 i.V.m. Code P59	-	-	S	0,00
		●	●	-	315,00
		○	○	○	0,00
645	M+S winter tyres, set of 4 Only in conjunction with code R78/T2R/RQT/RVG	U	U	U	115,50
		★	★	★	
651	Winter complete wheels fitted only in conjunction with code 3R1/2R9/8R5/8R2	○	○	○	0,00
652	Summer complete tyres fitted only in conjunction with code 3R1/2R9/8R5/8R2	○	○	○	0,00
666	Freight packaging without tie-down hooks Certain countries only Not in conjunction with Code 820	●	●	●	0,00
668	Prod. prot. f. freight pkging with tie-down hooks Certain countries only Not in conjunction with Code 820	●	●	●	26,25
677	Lowered comfort suspension not in conjunction with code 486 Only in conjunction with Code 213 i.V.m. Code 950 i.V.m. Code PYA	●	●	●	0,00
		○	○	○	0,00
		○	○	○	0,00
682	Fire extinguisher certain countries only	●	●	●	0,00
687	Type plate with model year certain countries only	○	○	○	0,00
690	Collapsible spare wheel Certain countries only and only in conjunction with Code E76 and B12	-	○	○	0,00
70B	Fluorescent jacket for driver not in conj. With 71B	●	●	●	5,25
71B	Fluorescent jackets for driver and passengers certain countries only not in conj. With 70B	●	●	●	26,25
72R	43.2 cm (17-inch) 10-spoke light-alloy wheels not in conjunction with code 950 i.V.m. Code P27 i.V.m. Code P59 only available i.V.m. Code PYF, not with code P55	-	-	●	472,50
		●	●	-	787,50
		-	-	○	0,00
		●	●	-	315,00
		○	○	○	0,00
		○	○	○	0,00
73B	Stowage compartment in centre console, with retractable cover certain countries only only in conjunction with code 426/429	●	●	●	0,00
		●	●	●	36,75
762	Remote control unit certain countries only not in conjunction with code 968/969	○	○	○	0,00
763	Key with Radio remote control with panic switch not in conjunction with code 762/968/969 Only in conjunction with Code 551 and Certain countries only	○	○	○	0,00
76R	43.2 cm (17-inch) 5-twin-spoke light-alloy wheels	-	-	●	472,50

27/2/2018 Optional extras for the A-Class

Valid from 05.03.2018 (808+058)

1) A 250 available in 2. quarter of 2018

● available at extra charge ○ available at no extra charge U annotations existing
S standard equipment - not available

A Limousine			
	A 180 d	A 200	A 250 ¹⁾
	177.003	177.087	177.046

					LLP
L	Left-hand drive	○	○	○	0,00
	not in conjunction with code 950	●	●	-	787,50
	i.V.m. Code P27	-	-	○	0,00
	i.V.m. Code P59	●	●	-	315,00
	only available i.V.m. Code PYD	○	○	○	0,00
772	AMG bodystyling	○	○	○	0,00
	Only in conjunction with Code 950				
79B	Preinstallation for digital radio	○	○	○	0,00
	certain countries only				
	not in conjunction with code 537				
	only in conjunction with code (355/859) and 362				
7U1	Manually adjustable front seats	○	○	○	0,00
	not in conjunction with code 555				
	only in conjunction with code 001A				
7U2	Luxury front seats	○	○	○	0,00
	only in conjunction with code 101A/105A/109A/201A/205A/311A/321A/371A/372A/381A and U59, 286 und 287				
7U3	Sports front seats	●	●	●	246,75
	only in conjunction with code 111A/115A/119A/159A/204A/211A/257A/258A/259A/611A/651A/671A and U59, 286 and 287				
	i.V.m. Code 950	○	○	○	0,00
	only in conjunction with Code PYF	●	-	-	145,00
808	Technical modifications	○	○	○	0,00
810	Burmester® surround sound system	U	U	U	698,25
	not in conjunction with code 853				
	not in conjunction with code Z97	★	★	★	
	only in conjunction with code 355/859				
	only available i.V.m. Code PYN/PYO	●	●	●	435,75
820	Tourist vehicles	○	○	○	0,00
	not in conjunction with code 634/636/969				
821	Country code Brazil	-	○	○	0,00
822	South Africa specification	○	○	○	0,00
823	Indicator plate fixing Switzerland	○	○	○	0,00
824	Additional parts for cold countries	○	○	○	0,00
829	Taiwan version	○	○	○	0,00
830	China specification	-	○	-	0,00
831	Indicator plate fixing Italia	○	○	○	0,00
835	South Korea specification	-	-	○	0,00
840	Heat-insulating dark-tinted glass	U	U	U	315,00
	Certain countries only				
	not in conjunction with code U63	★	★	★	
	only in conjunction with code P27/P59/950				
	i.V.m. Code P55	○	○	○	0,00
853	Soundsystem	●	●	●	262,50
	certain countries only				
	not in conjunction with code 810				
	i.V.m. Code PYN/PYO	○	○	○	0,00
859	Media-Display	●	●	●	682,50
	in certain countries not with code 362				
	only in conjunction with code 549 and 446				
	only available i.V.m. Code PYN/PYN/PYO	○	○	○	0,00
873	Heated front seats	●	●	●	304,50
	not in conjunction with code 401				
	i.V.m. Code PYN/PYO	○	○	○	0,00
875	Heated windscreen washer system	●	●	●	120,75
	certain countries only				
877	Ambient lighting	●	●	●	278,25
	only in conj. With Code P27/P59 or 950				
	i.V.m. Code P19	○	○	○	0,00
	i.V.m. Code PYN/PYO, not available as single option	○	○	○	0,00
882	Interior monitoring system	○	○	○	0,00
	certain countries only				
	Only in conjunction with Code P54 and U62				
885	Increased anti-theft protection	○	○	○	0,00
	only 537L				
889	KEYLESS-GO	●	●	●	420,00
	only in conj. With Code P27/P59 or 950				
	i.V.m. Code PAD	○	○	○	0,00
	i.V.m. Code PYN/PYO, not available as single option	○	○	○	0,00

27/2/2018 Optional extras for the A-Class
Valid from 05.03.2018 (808+058)
1) A 250 available in 2. quarter of 2018

● available at extra charge ◯ available at no extra charge U annotations existing
S standard equipment - not available

A Limousine			
	A 180 d	A 200	A 250 ¹⁾
	177.003	177.087	177.046

LLP

L	Left-hand drive	●	◯	U	0,00
896	Preinstallation for Digital vehicle key for smartphone certain countries only only in conjunction with code (897/899) and 362	●	●	●	105,00
897	Wireless charging and connection via Bluetooth certain countries only not in conjunction with code 899 only in conjunction with code P27/P59 or 950	●	●	●	210,00
899	Multifunction telephony certain countries only not in conjunction with code 897 only in conjunction with code (P27/P59 or 950) and 270, 274	●	●	●	514,50
8R2	Complete winter (M+S) wheel-and-tyre assembly x 4, 19-inch, light-alloy certain countries only and only in conj. With code 651 or 652	●	●	●	2467,50
8R5	Complete winter wheel - AMG spoked design, 18" certain countries only and only in conj. With code 651 or 652	●	●	●	2205,00
913	Air conditioning preinstallation for hot countries Certain countries only	◯	-	-	0,00
922	Reduced power version certain countries only (524L/528L/810L)	-	◯	-	0,00
926	Emission control system with EU4 technology Certain countries only	◯	◯	◯	0,00
927	EU6 emissions standard Certain countries only	◯	◯	◯	0,00
928	EU5 emission standard Certain countries only	-	◯	◯	0,00
931	Tandem interior mirror available expected 2. Quarter 2018 Only in conjunction with Code U63 (only LHD)	◯	◯	◯	0,00
933	Add.parts f.telematic alarm identific. available expected 2. Quarter 2018 certain countries only	-	●	-	315,00
936	Zylinderabschaltung only in conjunction with Code 429 (in cert. Countries) certain countries only	-	◯	-	0,00
942	Load compartment package available expected 2. Quarter 2018 certain countries only Only in conjunction with Code U35 and Code U40	U ★	U ★	U ★	157,50
945	Emission control system China only in conjunction with code 830	-	◯	◯	0,00
968	COC document EU6 without registration certificate part II Certain countries only	◯	◯	◯	0,00
969	COC document EU6 with registration certificate part II Certain countries only	◯	◯	◯	0,00
981	Omission of vehicle registration document certain countries only	◯	◯	◯	0,00
986	Identification no. (US-VIN) Certain countries only	◯	◯	◯	0,00
989	Identification label under windshield certain countries only	◯	◯	◯	0,00
B08	Fanfares for Asia	◯	◯	◯	0,00
B12	Tyre-change toolkit Certain countries only i.c. w. Code 690 or 669	●	●	●	31,50
B18	Spectacles compartment for driver only in conjunction with code U62	◯	◯	◯	0,00
B24	remote control for auxiliary heater available expected 2. Quarter 2018 Certain countries only Only in conjunction with Code 228, 270 and 274 and in cert. countries with 362	●	●	●	210,00
B51	TIREFIT Certain countries only Not in conjunction with Code R66 i.V.m. Code PYA	●	●	●	0,00
B59	DYNAMIC SELECT	S	S	S	0,00
B63	Sporty engine sound available expected 2. Quarter 2018 not valid only in conjunction with code (548/549) and 950	-	U ★	U ★	0,00
H15	wood linden black open-pored trim only in conjunction with code P59 or (950 but not with P19) i.V.m. Code P39	●	●	●	273,00
H23	Trim in brown open-pore walnut wood only in conjunction with code P59/P34	●	●	●	273,00

27/2/2018 Optional extras for the A-Class

Valid from 05.03.2018 (808+058)

1) A 250 available in 2. quarter of 2018

 ● available at extra charge ◌ available at no extra charge ◌ annotations existing
 S standard equipment - not available

A			
Limousine			
	A 180 d	A 200	A 250 1)
	177,003	177,087	177,046
			A 250 1)

		LLP		
L	Left-hand drive	◌	◌	◌
H44	Light longitudinal-grain aluminium trim only in conjunction with code 950/P59 i.V.m. Code P19 i.V.m. Code P39 oder 159A	●	●	●
		◌	◌	◌
		◌	◌	◌
H45	Light linear-grain aluminium trim only in conjunction with code P59 or (950 but not with P19) i.V.m. Code P39 oder 159A	●	●	●
		◌	◌	◌
H55	Trim in dark carbon-fibre look only in conjunction with code P59	◌	◌	◌
H59	Carbon-fibre-look trim only in conjunction with code P59	◌	◌	◌
K32	Active Lane Change Assist certain countries only and only in conjunction with code 266 and 365	◌	◌	◌
K33	Extended automatic Re-start in traffic jams certain countries only and only in conjunction with code 233, 235 and 365	◌	◌	◌
K34	Route-based speed adaptation certain countries only and only in conjunction with code 233 and 365	◌	◌	◌
L3A	Multifunction sports steering wheel not in conjunction with code (P59/950) and 233/239 and 443	S	S	S
L3B	Multifunction sports steering wheel in nappa leather not in conjunction with code 950 (except with code 460) only in conjunction with code 428 and 443	◌	◌	◌
		★	★	★
L3E	Leather multifunction sports steering wheel not in conjunction with Code 443 or 950 i.V.m. Code P59 i.V.m. Code PYB/PYD	●	●	●
		◌	◌	◌
		◌	◌	◌
L5C	Multifunction sports steering wheel in nappa leather not in conjunction with code 443 only in conjunction with code 950	◌	◌	◌
L5I	Multifunction sports steering wheel in nappa leather / DINAMICA microfibre available expected 2. Quarter 2018 not in conjunction with code 443 only in conjunction with code 950 and (426/429)	●	●	●
R00	40.6 cm (16-inch) steel wheels with 10-hole trim in certain countries only in conjunction with code R01 or R05 Not in conjunction with Code 950 or U29	S	S	-
R01	Summer tyres only in conjunction with code 01R/643/R00/R11/R30/R31/R55/R78/643/72R/76R/RQS/RQT/RVG/RVK	◌	◌	◌
R03	Sports tyres only in conjunction with Code 01R/R31 only in conjunction with Code RQS/RQT	◌	◌	◌
R05	Tyres with optimised rolling resistance Certain countries only and only in conj. With code (R00/R30/R78)	◌	◌	◌
R11	43.2 cm (17-inch) 5-twin-spoke light-alloy wheels Not in conjunction with Code 950 i.V.m. Code P27 i.V.m. Code P55 i.V.m. Code P59 i.V.m. Code PYB i.V.m. Code PYD/PYF	-	-	●
		●	●	-
		-	-	●
		●	●	-
		◌	◌	◌
		●	●	●
		●	●	-
		●	●	●
R30	40.6 cm (16") multi-spoke light-alloy wheels not in conjunction with code 950 i.V.m. Code P27 i.V.m. Code P59 i.V.m. Code PYB	●	●	-
		●	●	-
		◌	◌	-
		●	●	-
R31	45.7 cm (18-inch) 5-spoke light-alloy wheels not in conjunction with code 950 i.V.m. Code P27 i.V.m. Code P55 i.V.m. Code P59 i.V.m. Code PYF	-	-	●
		●	●	-
		-	-	●
		◌	◌	◌
		●	●	●
		●	●	●
R55	48.3 cm (19-inch) 5-twin-spoke light-alloy wheels not in conjunction with code 950 i.V.m. Code P27 i.V.m. Code P55 i.V.m. Code P59	-	-	●
		●	●	-
		-	-	●
		●	●	-
		●	●	●
		●	●	●

27/2/2018 **Optional extras for the A-Class**

Valid from 05.03.2018 (808+058)

Valid from 05.03.2018 (808+058)

1) A 250 available in 2. quarter of 2018

● available at extra charge ○ available at no extra charge U annotations existing
S standard equipment - not available

[illegible]

27/2/2018 Optional extras for the A-Class
Valid from 05.03.2018 (808+058)
1) A 250 available in 2. quarter of 2018

● available at extra charge ○ available at no extra charge U annotations existing
S standard equipment - not available

A Limousine			
177.003	A 180 d	177.087	A 200
		177.046	A 250 ¹⁾

					LLP
L	Left-hand drive only in conjunction with code PAD	○	○	○	0,00
U35	12 V socket in load area Only in conjunction with Code 942	○	○	○	0,00
U40	Partition net only i.V.m Code 942 and certain countries only	●	●	●	157,50
U54	TORSION BEAM AXLE certain countries only and only in conjunction with Code (R00/R30/R78/643/72R/76R/R11/01R/R31/RQS or RQT) not in conjunction with code 459	S	○	-	0,00
U55	MULTI-LINK-AXLE certain countries only and only in conjunction with Code (01R/R31/R55/RQS/RQT/RVG or RVK)	○	○	S	0,00
U60	Pedestrian protection Certain countries only	○	○	○	0,00
U64	Full driving school package available expected 2. Quarter 2018 only in conjunction with Code U63 only LHD	●	●	●	1260,00
U65	Additional exterior mirror right and left available expected 2. Quarter 2018 only in conjunction with code U63 only LHD	●	●	●	126,00
U66	Floormats special model certain countries only not in conjunction with Code U12 or U26 only in conjunction with Code P19	○	○	○	0,00
U67	230 V socket in the rear certain countries only not in conjunction with code U80	●	●	●	84,00
U79	BlueTEC diesel emission control system including AdBlue® reservoir certain countries only	○	-	-	0,00
U80	115 V socket certain countries only	●	●	●	84,00
Z83	Activation hill-start assist driving school available expected 2. Quarter 2018 Only in conjunction with Code U64	○	○	○	0,00
Z97	Electronic interface for remote control certain countries only not in conjunction with code 810 or (550/554)	●	●	●	399,00