

27/8/2018 **Optional extras for the A-Class**
Valid from 03.09.2018 (809)

Valid from 03.09.2018 (809)

1) 177.144 only USA/CANADA

● available at extra charge ○ available at no extra charge U annotations existing
S standard equipment - not available

Valid from 03.09.2018 (809)		Sedan										
		177.103	A 180 d	177.187	A 200	177.145	A 220 4MATIC	177.146	A 250	177.147	A 250 4MATIC	
1) 177.144 only USA/CANADA												
● available at extra charge C available at no extra charge U annotations existing S standard equipment - not available												
LLP												
L	Left-hand drive	○	○	○	○	○	○	○	○	○	0,00	
R	Right-hand drive	●	●	●	●	●	●	●	●	●	1113,00	
144U	digital white metallic available 1. Quarter 2019	U	U	U	U	U	U	U	U	U	619,50	
149U	polar white	●	●	●	●	●	●	●	●	●	0,00	
191U	cosmos black metallic	●	●	●	●	●	●	●	●	●	619,50	
589U	jupiter red	○	○	○	○	○	○	○	○	○	0,00	
662U	designo mountain grey magno invalid	U	U	U	U	U	U	U	U	U	1942,50	
667U	denim blue metallic not yet valid (available from the End of 1. Quarter 2019) i.V.m. Code P33	U	U	U	U	U	U	U	U	U	619,50	
696U	night black	○	○	○	○	○	○	○	○	○	0,00	
775U	iridium silver metallic	●	●	●	●	●	●	●	●	●	619,50	
787U	mountain grey metallic	●	●	●	●	●	●	●	●	●	619,50	
859U	mojave silver metallic	●	●	●	●	●	●	●	●	●	619,50	
914U	sun yellow	-	-	-	-	-	-	-	-	-	0,00	
001A	Tandel fabric black Not in conjunction with Code P27/P59 or 950 only in conjunction with code 7U1	○	○	○	○	○	○	○	○	○	0,00	
101A	Black ARTICO man-made leather only in conjunction with Code 7U2 and P27/P59	●	●	●	●	●	●	●	●	●	152,25	
105A	ARTICO man-made leather macchiato beige / black Only in conjunction with Code P59 and 7U2	●	●	●	●	●	●	●	●	●	152,25	
109A	ARTICO man-made leather neva grey / black Only in conjunction with Code P27 and 7U2	●	●	●	●	●	●	●	●	●	152,25	
111A	ARTICO man-made leather black certain countries only only in conjunction with Code 7U3 and (P27/P59)	-	-	-	-	-	-	-	-	-	152,25	
115A	ARTICO man-made leather, sports seat macchiato beige / black certain countries only only in conjunction with code 7U3 and P59	-	-	-	-	-	-	-	-	-	152,25	
119A	ARTICO man-made leather, sports seat neva grey / black only in conjunction with code 7U3 and P27	-	-	-	-	-	-	-	-	-	152,25	
159A	Two-tone ARTICO man-made leather neva grey / black only in conjunction with code 7U3/555 and 950 only in conjunction with code 7U4 and 950	U	U	U	U	U	U	U	U	U	0,00	
201A	Leather black only in conjunction with Code P34 and P59 and 7U2	○	○	○	○	○	○	○	○	○	0,00	
204A	Leather bahia brown / black only in conjunction with Code P34 and 7U3/555 only in conjunction with Code P34 and 7U4	U	U	U	U	U	U	U	U	U	0,00	
205A	Leather macchiato beige / black Only in conjunction with Code P34 and P59 and 7U2	○	○	○	○	○	○	○	○	○	0,00	
211A	Leather black only in conjunction with code P34 and 7U3/555 only in conjunction with code P34 and 7U4	U	U	U	U	U	U	U	U	U	0,00	
257A	Two-tone leather classic red / black only in conjunction with code 7U3/555 and P39 only in conjunction with code 7U4 and P39	U	U	U	U	U	U	U	U	U	0,00	
258A	Two-tone leather titanium grey pearl / black only in conjunction with code 7U3/555 and P39 only in conjunction with code 7U4 and P39	U	U	U	U	U	U	U	U	U	0,00	
311A	ARTICO man-made leather / Bertrix fabric black certain countries only only in conjunction with code P27 and 7U2	U	U	U	U	U	U	U	U	U	0,00	
321A	ARTICO man-made leather / Fléron fabric black certain countries only only in conjunction with code P59 and 7U2	○	○	○	○	○	○	○	○	○	0,00	
371A	ARTICO man-made leather/ Bertrix fabric, two-tone black / neva grey certain countries only only in conjunction with Code P27 and 7U2	○	○	○	○	○	○	○	○	○	0,00	
372A	ARTICO man-made leather/ Bertrix fabric, two-tone black indigo blue / black certain countries only only in conjunction with Code P27 and 7U2	○	○	○	○	○	○	○	○	○	0,00	
381A	ARTICO man-made leather/ Fléron fabric, two-tone black / Bahia brown certain countries only only in conjunction with code P59 and 7U2	○	○	○	○	○	○	○	○	○	0,00	
411	6-speed manual transmission certain countries only invalid	S	S	-	-	-	-	-	-	-	0,00	
426	8G-DCT not in conjunction with code U63 invalid	-	-	-	U	U	U	U	U	U	0,00 1953,00	
429	7G-DCT AMG SPEEDSHIFT DCT 7G	S	-	S	S	S	S	S	S	S	0,00 1848,00	
611A	ARTICO man-made leather / DINAMICA microfibre black only in conjunction with code P19 and 7U3	-	-	-	-	-	-	-	-	-	0,00	
621A	Fabric/synth.leather/microfibre - blk/anthracite only in conjunction with code P19 and 7U4	○	○	○	○	○	○	○	○	○	0,00	
651A	ARTICO man-made leather/DINAMICA microfibre upholstery black	U	U	U	U	U	U	U	U	U	0,00	

27/8/2018 **Optional extras for the A-Class**
Valid from 03.09.2018 (809)

Valid from 03.09.2018 (809)

1) 177.144 only USA/CANADA

● available at extra charge ○ available at no extra charge U annotations existing
S standard equipment - not available

[illegible]

27/8/2018 Optional extras for the A-Class

Valid from 03.09.2018 (809)

1) 177.144 only USA/CANADA

● available at extra charge ◌ available at no extra charge ◌ annotations existing
S standard equipment - not available

		Sedan				
		177.103 A 180 d	177.187 A 200	177.145 A 220 4MATIC	177.146 A 250	177.147 A 250 4MATIC
		LLP				
L	Left-hand drive only in conjunction with code P59, and 01R/643/R00/R11/R30/R31/R55/R78/72R/76R/RQT/RVG/RVK or 950 and (RVG/RVK/RV1 or (RQT but not with 645) i.V.m. Code 950 i.V.m. Code P19	◌	◌	◌	◌	◌
		●	●	●	●	●
		-	-	-	-	-
		409,50				
		0,00				
P59	Progressive not in conjunction with code P27/950 only in conjunction with code 310 and 2U5 and (101A/105A/111A/115A/201A/205A/211A/321A/381A) and (101A/105A/201A/204A) and 72R/643/R00/R11/R30/R31/R55/R78/01R/76R/RQT/RVG/RVK and (H15/H23/H44/H45/H55/H59) and U62 only in conjunction with code 310 and 2U5 and (101A/105A/201A/204A/205A/211A/321A/381A) and 72R/643/R00/R11/R30/R31/R55/R78/01R/RQT/RVG/RVK or 76R and (H15/H23/H44/H45/H55/H59) and U62 i.V.m. Code PYF	◌	◌	◌	◌	◌
		●	●	●	●	●
		-	-	-	-	-
		1412,25				
		1648,50				
P60	AMG Night package only in conjunction with code 840; certain countries also without Code 840 i.V.m. Code P33	-	-	-	-	-
		-	-	-	-	-
		787,50				
		0,00				
PAC	Vorteils-Paket	S	S	S	S	S
PAD	Engineering package certain countries only only in conjunction with code 23P, U29, 459, (641/642) and 889	●	●	●	●	●
PBF	Preinstallation for Connectivity package certain countries only not in conjunction with code PBG only in conjunction with code 365 and 01U	●	●	●	●	●
PBG	Preinstallation for Comfort Connectivity package certain countries only not in conjunction with code PBF only in conjunction with code 365, 01U, 02U and 12U only in conjunction with code 859	●	●	●	●	●
PBI	Preinstallation for Smartphone Connectivity package only in conjunction with code Code 08U, 09U and 14U and only certain countries	●	●	●	●	●
PBP	ENERGIZING package not in conjunction with code PBR not yet valid only in conjunction with code (P27/P59/950) and 355 and (853/810) and 859 and (873/401) and 877	◌	◌	◌	◌	◌
		●	●	●	●	●
		-	-	-	-	-
		1470,00				
PBR	ENERGIZING package Plus not in conjunction with PBP not yet valid only in conjunction with code (P27/P59) und 355, 409, 581 and (853/810) and 859 and (873/401) and 877 or 950, 355, 581 and (853/810) and 859 and (873/401) and 877 i.V.m. Code 7U3/7U4	◌	◌	◌	◌	◌
		●	●	●	●	●
		-	-	-	-	-
		2625,00				
PYA	WEU Standard Equipment certain countries only	●	●	●	●	●
PYB	SE Package certain countries only	●	●	-	-	-
PYD	Style Line	-	-	●	-	●
		●	●	●	●	●
		-	-	-	-	-
		0,00				
		0,00				
		881,00				
	certain countries only					
PYF	Progressive Line certain countries only	-	-	●	●	●
		●	●	-	-	-
		543,00				
		1407,00				
PYH	AMG Line certain countries only	-	-	●	●	●
		●	●	-	-	-
		1981,00				
		2479,00				
PYM	Advantage Package certain countries only	●	●	●	●	●
PYN	Premium Package certain countries only	●	●	●	●	●
		-	-	-	-	-
		3344,00				
PYO	Premium Plus Package certain countries only	●	●	●	●	●
		-	-	-	-	-
		4736,00				
U59	Seat comfort package not in conjunction with code 7U1 Standard	◌	◌	◌	◌	◌
U62	Light and sight package only in conjunction with Code 543, B18 und (P27/P59 or 950)	◌	◌	◌	◌	◌
U63	Basic driving school package code U12 or U26 available not in conjunction with code 242/429/840/877/897 or 899 only in conjunction with code P27/P59 or 950 and U00 and 931 only LHD (certain countries only) i.V.m. Code U64	-	-	-	-	-
		-	-	-	-	-
		0,00				
494	USA specification	-	-	◌	-	-
		-	-	-	-	-
		0,00				

27/8/2018 Optional extras for the A-Class

Valid from 03.09.2018 (809)

1) 177.144 only USA/CANADA

● available at extra charge ○ available at no extra charge U annotations existing
S standard equipment - not available

		Sedan				
		177.103 A 180 d	177.187 A 200	177.145 A 220 4MATIC	177.146 A 250	177.147 A 250 4MATIC
		LLP				
L	Left-hand drive	○	○	○	○	○
498	Japan specification invalid	-	-	○	-	○
00B	Owner's Manual and Service Booklet - Danish	○	○	○	○	○
01B	Owner's Manual and Service Booklet - Dutch	○	○	○	○	○
01R	45.7 cm (18-inch) 5-twin-spoke light-alloy wheels	●	●	●	●	●
	not in conjunction with code 950					
	i.V.m. Code P27	●	●	-	-	-
	i.V.m. Code P55	○	○	○	○	○
	i.V.m. Code P59	●	●	●	●	●
	i.V.m. Code PYF	●	●	●	●	●
01U	Preinstallation for Navigation Services	○	○	○	○	○
	certain countries only					
	only in conjunction with code 362					
	only in conjunction with code PBG or PBF					
02B	Owner's Manual and Service Booklet - German	○	○	○	○	○
02U	Preinstallation for Office in the car	○	○	○	○	○
	certain countries only					
	only in conjunction with code PBG and 859					
03B	Owner's Manual and Service Booklet - Russian	○	○	○	○	○
04B	Owner's Manual and Service Booklet - Finnish	○	○	○	○	○
05B	Owner's Manual and Service Booklet - English	○	○	○	○	○
06B	Owner's Manual and Service Booklet - Italian	○	○	○	○	○
07B	Owner's Manual and Service Booklet - French	○	○	○	○	○
08B	Owner's Manual and Service Booklet - Spanish	○	○	○	○	○
08U	Preinstallation for Vehicle Setup	●	●	●	●	●
	only in conjunction with 09U und 362					
	only in conjunction with PBI or certain in countries					
	i.V.m. Code PBI	○	○	○	○	○
09B	Owner's Manual and Service Booklet - Portuguese	○	○	○	○	○
09U	Preinstallation for Vehicle Monitoring	●	●	●	●	●
	only in conjunction with 08U and 362					
	only in conjunction with PBI or certain in countries					
	i.V.m. Code PBI	○	○	○	○	○
10B	Owner's Manual and Service Booklet - Swedish	○	○	○	○	○
11B	Owner's Manual and Service Booklet - Arabic	○	○	○	○	○
12B	Owner's Manual and Service Booklet - Engl. USA/CAN	○	○	○	○	○
12U	Preinstallation for Concierge Service	○	○	○	○	○
	certain countries only					
	only in conjunction with 362 and PBG					
13B	Owner's Manual and Service Booklet - Norwegian	○	○	○	○	○
14B	Owner's Manual and Service Booklet - Greek	○	○	○	○	○
14U	Smartphone integration	●	●	●	●	●
	certain countries only					
	only in conj. With Code 16U and 17U					
	only in conj. With Code 16U, 17U and (18U c.c.o)					
	i.V.m. Code PBI	○	○	○	○	○
15B	Owner's Manual and Service Booklet - Turkish	○	○	○	○	○
15U	Pre-installation for Mercedes-Benz Link	S	S	S	S	S
16B	Owner's Manual and Service Booklet - Polish	○	○	○	○	○
16U	Apple CarPlay	○	○	○	○	○
	only in conj. With Code 14U					
17B	Owner's Manual and Service Booklet - Czech	○	○	○	○	○
17U	Android Auto	○	○	○	○	○
	only in conj. with Code 14U					
18B	Owner's Manual and Service Booklet - Engl. S. Am.	○	○	○	○	○
18U	Baidu CarLife	-	-	-	-	-
	certain countries only (China)					
	only in conjunction with code 14U and (355 or 859)					
19B	Owner's Manual and Service Booklet - French S. Am.	○	○	○	○	○
20B	Owner's Manual and Service Booklet - Spanish S. Am.	○	○	○	○	○
20U	Pre-installation for car sharing	●	●	●	●	●
	certain countries only					
	only in conjunction with code 362					
213	Direct-Steer system	○	○	○	○	○
	only in conjunction with code (459/677) or (486 only AMG)					
218	Reversing camera	●	●	●	●	●
	not in conjunction with code 501					
	i.V.m. Code P44	○	○	○	○	○
	i.V.m. Code PYA	○	○	○	○	○
21B	Owner's Manual and Service Booklet - Portug. S. Am.	○	○	○	○	○
21U	Dashcam	U	U	U	U	U
	certain countries only					
	not yet valid	*	*	*	*	*
	only in conjunction with code 859 und 365					
228	Auxiliary heater	U	U	U	U	U
	available 2. Quarter 2019	*	*	*	*	*
	certain countries only in conjunction with code B24					
	only LHD					
22B	Owner's Manual and Service Booklet - Japanese	○	○	○	○	○
231	Garage door opener	U	U	U	U	U
	certain countries only					
	not yet valid	*	*	*	*	*

27/8/2018 Optional extras for the A-Class

Valid from 03.09.2018 (809)

1) 177.144 only USA/CANADA

● available at extra charge C available at no extra charge U annotations existing
S standard equipment - not available

		Sedan					LLP
		177.103 A 180 d	177.187 A 200	177.145 A 220 4MATIC	177.146 A 250	177.147 A 250 4MATIC	
L	Left-hand drive	○	○	○	○	○	0,00
	only in conjunction with code P49						
232	Garage door opener (frequency range 284-390 MHz) Certain countries only (460/494/777L) Only in conjunction with Code U62 or P49	●	●	●	●	●	236,25
233	Active Distance Assist DISTRONIC certain countries only not in conjunction with Code L3A, 234, 258 or 440 only in conjunction with Code 23P, 266, 270, 273, 426/429	○	○	○	○	○	0,00
234	Blind Spot Assist Certain countries only not in conjunction with code 233 only in conjunction with code 270, 273 and(275 or P49) i.V.m. Code 22P	●	●	●	●	●	472,50
		○	○	○	○	○	0,00
235	Active Parking Assist with PARKTRONIC i.V.m. Code P44/P47	●	●	●	●	●	708,75
		○	○	○	○	○	0,00
239	Active Distance Assist DISTRONIC certain countries only Not in conjunction with CodeL3A/ 233/258 or 440 Only in conjunction with Code 426/429	●	●	●	●	●	630,00
23B	Owner's Manual and Service Booklet - simpl. Chinese	○	○	○	○	○	0,00
241	Electrically adjustable front passenger seat with memory for left-hand traffic Only in conjunction with Code 275 Right-hand-drive vehicles only i.V.m. Code PYO	●	●	●	●	●	299,25
		○	○	○	○	○	0,00
242	Front pass. seat, electrically adj. with memory function LHD version Only in conjunction with Code 275 i.V.m. Code PYO	●	●	●	●	●	299,25
		○	○	○	○	○	0,00
243	Active Lane Keeping Assist not in conjunction with code 233 i.V.m. Code 22P/51B	●	●	●	●	●	472,50
		○	○	○	○	○	0,00
249	Interior mirror and driver's exterior mirror automatically dimming Only in conjunction with Code P49	○	○	○	○	○	0,00
24B	Owner's Manual and Service Booklet - trad. Chinese	○	○	○	○	○	0,00
256	AMG Track Pace only in conjunction with code 345 and 549	-	-	-	-	-	262,50
258	Active Brake Assist Certain countries only not in conjunction with code 233 or 239	○	○	○	○	○	0,00
25B	Owner's Manual and Service Booklet - Korean	○	○	○	○	○	0,00
260	Omission of model plate on boot lid	○	○	○	○	○	0,00
261	Omission of emblem on front wing	-	-	-	-	-	0,00
263	Number plate mounting for Asia / Mexico certain countries only and not in conj. With code 968	○	○	○	○	○	0,00
264	Number plate mounting for America not in conjunction with Code 968	○	○	○	○	○	0,00
266	DISTRONIC PLUS with Cross-Traffic Assist (DTR+Q) certain countries only only in conjunction with code 233	○	○	○	○	○	0,00
26B	Owner's Manual and Service Booklet - Chinese Taiwan	○	○	○	○	○	0,00
26U	Preinstallation for engine remote start certain countries only	-	-	●	●	●	105,00
270	Aerial for GPS only in conjunction with Code 501/899/B24/233/234/355/362	○	○	○	○	○	0,00
273	Exit Warning Assistant only in conjunction with Code 233 or 234	○	○	○	○	○	0,00
274	Aerial for telephone only in conjunction with code 501/899 or B24	○	○	○	○	○	0,00
275	Driver's seat, electrically adjustable with memory function in conjunction with code 555 only with (241/242) and 409 only in conjunction with code (U22/409) i.V.m. Code PYO	●	●	●	●	●	362,25
		○	○	○	○	○	0,00
286	Luggage net on driver's and front pass. backrest only in conjunction with code 7U2/7U3 only in conjunction with code 7U2/7U4	U	U	U	U	U	0,00
		*	*	*	*	*	
287	Folding rear-seat backrests only in conjunction with code 7U2/7U3 or 555 only in conjunction with code 7U2/7U4 or 555	U	U	U	U	U	0,00
		*	*	*	*	*	
293	Sidebags in rear certain countries only only in conjunction with code 7U2/7U3/555 only in conjunction with code 7U2/7U4/555	U	U	U	U	U	393,75
		*	*	*	*	*	
294	Kneebag Certain countries only	○	○	○	○	○	0,00
299	PRE-SAFE® system i.V.m. Code 23P	●	●	●	●	●	346,50
		○	○	○	○	○	0,00
2R9	Winter (M+S) wheel and tyre assembly x 4 certain countries only and only in conj. With code 651 or 652	-	-	-	-	-	1417,50
2U0	car2go pre-installation certain countries only only in conjunction with code (355/859)	●	●	●	●	●	178,50
2U5	Painted side skirts only in conjunction with P27/P59	○	○	○	○	○	0,00

27/8/2018 **Optional extras for the A-Class**
Valid from 03.09.2018 (809)

Valid from 03.09.2018 (809)

1) 177.144 only USA/CANADA

● available at extra charge ○ available at no extra charge U annotations existing
S standard equipment - not available

Optional Extras for the V-Class		Sedan										
		177-103	A 180 d	177-187	A 200	177-145	A 220 4MATIC	177-146	A 250	177-147	A 250 4MATIC	
1) 177.144 only USA/CANADA												
● available at extra charge ○ available at no extra charge U annotations existing S standard equipment - not available												
L	Left-hand drive	○	○	○	○	○	○	○	○	○	○	LLP
301	Ashtray insert for cup holder with cigarette lighter certain countries only	●	●	●	●	●	●	●	●	●	●	47,25
30B	Owner's Manual and Service Booklet - Slovenian	○	○	○	○	○	○	○	○	○	○	0,00
310	Twin cup holder i.V.m. Code P27/P59/950 i.V.m. Code PYA	-	-	-	-	-	-	-	-	-	-	0,00 26,25 0,00 0,00
31B	Owner's Manual and Service Booklet - Hungarian	○	○	○	○	○	○	○	○	○	○	0,00
32B	Owner's Manual and Service Booklet - Bulgarian	○	○	○	○	○	○	○	○	○	○	0,00
33B	Owner's Manual and Service Booklet - Romanian	○	○	○	○	○	○	○	○	○	○	0,00
34S	Windscreen wiper with rain sensor	S	S	S	S	S	S	S	S	S	S	0,00
34B	Owner's Manual and Service Booklet - Croatian	○	○	○	○	○	○	○	○	○	○	0,00
351	Mercedes-Benz emergency call system only in conj. With Code 362	○	○	○	○	○	○	○	○	○	○	0,00
355	Extended MBUX functions certain countries only only in conjunction with Code (548/549) and 270 and 446 i.V.m. Code PYA	-	-	-	-	-	-	-	-	-	-	0,00 472,50
35B	Owner's Manual and Service Booklet - Latvian	○	○	○	○	○	○	○	○	○	○	0,00
362	Communications module (LTE) for the use of Mercedes me connect services cert. Countries only only in conjunction with code 270 and 351 Standard in certain countries only	○	○	○	○	○	○	○	○	○	○	0,00
365	Hard-disc navigation only in conjunction with code 355 i.V.m. Code PBF/PBG i.V.m. Code PYM/PYN/PYO	●	●	●	●	●	●	●	●	●	●	577,50 0,00 0,00 0,00
367	Preinstallation for Live Traffic Information only in conj. with Code 355 and 362 and certain countries only i.V.m. Code PYA	○	○	○	○	○	○	○	○	○	○	0,00
36B	Owner's Manual and Service Booklet - Lithuanian	○	○	○	○	○	○	○	○	○	○	0,00
37B	Owner's Manual and Service Booklet - Slovakian	○	○	○	○	○	○	○	○	○	○	0,00
38B	Owner's Manual and Service Booklet - Estonian	○	○	○	○	○	○	○	○	○	○	0,00
39B	Owner's Manual and Service Booklet - Serbian	○	○	○	○	○	○	○	○	○	○	0,00
3R1	winter (M+S) wheel and tyre assembly x 4 certain countries only and only in conj. With code 651 or 652 not in conjunction with Code U29	-	-	-	-	-	-	-	-	-	-	1102,50
400	Rear armrest only in conjunction with Code 287 i.V.m. Code PYN/PYO	●	●	●	●	●	●	●	●	●	●	173,25 0,00
401	Climatised front seats certain countries only in conjunction with code 555 only i.c.w. 159A/204A/211A/257A/258A/651A/658A not in conjunction with code 873 only in conjunction with (101A/105A/109A/111A/115A/119A/159A/201A/204A/205A/211A/257A/258A/259A) only in conjunction with (101A/105A/109A/159A/201A/204A/205A/211A/257A/258A) i.V.m. Code PYN/PYO	U	U	U	U	U	U	U	U	U	U	934,50 630,00
409	Multicontour seat package not in conjunction with code U22/311A/321A/371A/372A/381A not in conjunction with code U22/842/830/311A/321A/371A/372A/381A only in conjunction with code 555 and 275 only in conjunction with code 7U2 i.V.m. Code PBR	-	-	-	-	-	-	-	-	-	-	420,00 619,50 0,00
40B	Owner's Manual and Service Booklet - ukrainian	○	○	○	○	○	○	○	○	○	○	0,00
413	Panoramic sliding sunroof only in conjunction with Code U62 only in conjunction with Code U62 and 51U i.V.m. Code PYO	U	U	U	U	U	U	U	U	U	U	976,50 0,00
41B	Owner's Manual and Service Booklet - hebrew	○	○	○	○	○	○	○	○	○	○	0,00
428	Steering wheel shift paddles Only in conjunction with Code 426/429 and (L3A/L3B or L3E)	S	○	S	S	S	S	S	S	S	S	0,00
42B	Owner's Manual and Service Booklet - Indonesian	○	○	○	○	○	○	○	○	○	○	0,00
43B	Owner's Manual and Service Booklet - Thai	○	○	○	○	○	○	○	○	○	○	0,00
440	Cruise control Not in conjunction with Code 233 or 239	S	S	S	S	S	S	S	S	S	S	0,00
443	Heated multifunction steering wheel not in conjunction with code 950 (except with code 460/494) only in conjunction with code 426/429 and L3B i.V.m. Code P59/950 i.V.m. Code PYB/PYD/PYF	●	●	●	●	●	●	●	●	●	●	351,75 168,00 168,00
446	Touchpad Standard i.V.m. Code PYA	-	-	-	-	-	-	-	-	-	-	0,00 147,00
44B	Owner's Manual and Service Booklet - Vietnamese	○	○	○	○	○	○	○	○	○	○	0,00
45B	All-digital instrument display	-	-	-	-	-	-	-	-	-	-	0,00

27/8/2018 Optional extras for the A-Class

Valid from 03.09.2018 (809)

1) 177.144 only USA/CANADA

● available at extra charge ◌ available at no extra charge ◌ annotations existing
S standard equipment - not available

		Sedan					LLP
		177.103 A 180 d	177.187 A 200	177.145 A 220 4MATIC	177.146 A 250	177.147 A 250 4MATIC	
L	Left-hand drive	◌	◌	◌	◌	◌	0,00
	only in conjunction with code 859 und 365	●	●	●	●	●	472,50
	i.V.m. Code PYN/PYO	◌	◌	◌	◌	◌	0,00
459	Suspension with Adaptive Damping system	●	●	●	●	●	1039,50
	AMG RIDE CONTROL suspension						
	certain countries only						
	only in conjunction with code 213						
	i.V.m. Code 950 (ohne PYH)	●	●	●	●	●	735,00
	i.V.m. Code PAD	◌	◌	◌	◌	◌	0,00
460	Canada specification	-	-	-	-	-	0,00
461	Instrument cluster with display in miles and English lettering	◌	◌	◌	◌	◌	0,00
463	Head-up Display	●	●	●	●	●	1039,50
	only in conjunction with code 355/859 and P59 or 950						
474	Diesel particulate filter	◌	-	-	-	-	0,00
475	Tyre pressure monitoring system	●	●	●	●	●	320,25
	Certain countries only						
	i.V.m. S-Code 6P5	◌	◌	◌	◌	◌	0,00
477	Tyre pressure loss warning system	◌	◌	◌	◌	◌	0,00
	Certain countries only						
482	Suspension with higher ground clearance	●	●	●	●	●	105,00
	Certain countries only						
485	Comfort suspension	S	S	S	S	S	0,00
	Not in conjunction with Code 950						
486	AMG suspension	-	-	-	-	-	0,00
	only in conj. With Code 213						
4P8		◌	◌	◌	◌	◌	0,00
500	Electrically folding exterior mirrors	◌	◌	◌	◌	◌	0,00
	Only in conjunction with Code P49						
501	360° camera	◌	◌	◌	◌	◌	0,00
	not in conjunction with code 218						
	only in conjunction with code 270 and 274 and P47						
504	Speed Limit Assist	◌	◌	◌	◌	◌	0,00
	not in conjunction with Code 513, 365 and 233						
	only in conjunction with Code 51B						
513	Traffic Sign Assist	●	●	●	●	●	309,75
	not in conjunction with Code 504						
	only in conjunction with Code 365 and certain countries only						
517	HD digital radio standard	◌	◌	◌	◌	◌	0,00
	certain countries only						
518	Media Interface including consumer cable set	●	●	●	●	●	52,50
	certain countries only						
51B	Rating Countries EURO-NCAP	◌	◌	◌	◌	◌	0,00
	certain countries only						
	only in conjunction with code (258 or 239) and (243 or 233) and (504 or 513)						
51U	Roof liner in black fabric	◌	◌	◌	◌	◌	0,00
	Standard						
524	Transport protection	●	●	●	●	●	168,00
	certain countries only and only in conj. With code 662U						
	not in conjunction with code 820						
536	Sirius satellite radio	-	-	◌	-	-	367,50
	certain countries only						
	only in conjunction with code 355/859			*			
	only in conjunction with code 413						
537	Digital radio	●	●	●	●	●	210,00
	certain countries only						
	not in conjunction with code 79B						
539	Digital radio standard	●	●	●	●	●	210,00
	certain countries only						
543	Sun visor with illuminated vanity mirror	◌	◌	◌	◌	◌	0,00
	Only in conj. with Code U62						
545	MBUX multimedia system	S	S	S	S	S	0,00
	certain countries only						
	not in conjunction with code 256/355/365/458/513/859/21U/PBP/PBR/PBF or PBG						
546	Automatic speed control	◌	◌	◌	◌	◌	0,00
	certain countries only						
	only in conjunction with code 233 and 513						
547	MBUX multimedia system	◌	◌	◌	◌	◌	0,00
	certain countries only	*	*	*	*	*	
	not in conjunction with code 355						
	not yet valid (available 2. Quarter 2019)						
	only in conjunction with code 859						
548	MBUX multimedia system	◌	◌	◌	◌	◌	0,00
	certain countries only	*	*	*	*	*	
	not in conjunction with code 256						
	not in conjunction with code 859						
	only in conjunction with code 355						
549	MBUX multimedia system	◌	◌	◌	◌	◌	0,00
	only in conjunction with code 859 and 355						
550	Trailer coupling with ESP® trailer stabilisation	●	●	●	●	●	840,00
	certain countries only						
551	Anti-theft alarm system	●	●	●	●	●	262,50
	Only in conjunction with Code P54 or certain countries only						

27/8/2018 Optional extras for the A-Class

Valid from 03.09.2018 (809)

1) 177.144 only USA/CANADA

● available at extra charge ○ available at no extra charge U annotations existing
S standard equipment - not available

		Sedan					LLP
		177.103 A 180 d	177.187 A 200	177.145 A 220 4MATIC	177.146 A 250	177.147 A 250 4MATIC	
L	Left-hand drive	○	○	○	○	○	0,00
	i.V.m. Code P54	○	○	○	○	○	0,00
552	Anti-theft alarm system	○	○	○	○	○	0,00
	Only in conjunction with Code P54 and 513L						
555	AMG Performance seats	-	-	-	-	-	2047,50
	not in conjunction with code U22						
	only in conjunction with code U59, U10, 287, (159A/204A/211A/257A/258A/651A/658A)						
	i.V.m. Code P33	-	-	-	-	-	0,00
580	THERMATIC automatic climate control	○	○	○	○	○	0,00
	certain countries only						
581	THERMOTRONIC automatic climate control	●	●	●	●	●	535,50
	i.V.m. Code PBR/PYF/PYH	○	○	○	○	○	0,00
	i.V.m. Code PYA	-	-	-	-	-	0,00
58U	Roof liner in crystal grey fabric	U	U	U	U	U	0,00
	not in conjunction with code 105A/109A/115A/119A/159A/205A/371A or 611A						
	not in conjunction with code 105A/109A/159A/205A/371A or 621A	*	*	*	*	*	
	Not in conjunction with Code 413						
598	Petrol particulate filter	-	○	○	○	○	0,00
	certain countries only						
	only in conjunction with code 927						
5U3	AIRPANEL	●	●	●	●	●	84,00
	certain countries only						
608	Adaptive Highbeam Assist	●	●	●	●	●	189,00
	certain countries only						
	Only in conjunction with Code 631/632 or 640	-	-	○	○	○	0,00
	i.V.m. Code 640						
613	Headlamps for RHD vehicles	○	○	○	○	○	0,00
	not in conjunction with code PAD						
	Part of standard specification for LHD countries						
620	Halogen headlamps with integrated LED daytime running lamps	○	○	○	○	○	0,00
	certain countries only						
	not in conjunction with code PAD						
	standard RHD						
623	Gulf States specification	-	U	U	U	U	157,50
	not yet valid		*	*	*	*	
625	Australia specification	U	U	-	U	U	0,00
	not yet valid	*	*		*	*	
628	Adaptive Highbeam Assist Plus	○	○	○	○	○	0,00
	not in conjunction with code 608						
	only in conjunction with Code 641/642						
631	LED High Performance headlamp	●	●	●	●	●	871,50
	Certain countries only						
	not in conjunction with Code PAD						
	i.V.m. Code P19	○	○	○	○	○	0,00
	i.V.m. Code PYA	○	-	-	-	-	0,00
	i.V.m. Code PYD/PYF/PYH	○	○	○	○	○	0,00
632	LED High Performance headlamp	●	●	●	●	●	871,50
	Certain countries only						
	not in conjunction with code PAD	○	○	○	○	○	0,00
	i.V.m. Code P19	-	-	-	-	-	0,00
	i.V.m. Code PYA	○	○	○	○	○	0,00
	i.V.m. Code PYD/PYF/PYH	○	○	○	○	○	0,00
634	Omission of first-aid kit	○	○	○	○	○	0,00
	certain countries only						
	not in conjunction with code 820						
636	Omission of warning triangle	○	○	○	○	○	0,00
	certain countries only						
	not in conjunction with code 820						
640	MULTIBEAM LED	-	-	●	●	●	1312,50
	certain countries only						
	only in conjunction with code 608						
	i.V.m. Code P19	-	-	●	●	●	441,00
641	MULTIBEAM LED LV/RL	●	●	●	●	●	1312,50
	certain countries only						
	only in conjunction with code 628						
	i.V.m. Code P19	●	●	●	●	●	441,00
	i.V.m. Code PAD	○	○	○	○	○	0,00
	i.V.m. Code PYA	○	-	-	-	-	441,00
	i.V.m. Code PYD/PYF/PYH	●	●	●	●	●	441,00
	i.V.m. Code PYO	○	○	○	○	○	0,00
642	MULTIBEAM LED	●	●	●	●	●	1312,50
	certain countries only						
	only in conjunction with code 628						
	i.V.m. Code P19	●	●	●	○	●	441,00
	i.V.m. Code PAD	○	○	○	○	○	0,00
	i.V.m. Code PYA	-	-	-	-	-	441,00
	i.V.m. Code PYD/PYF/PYH	●	●	●	●	●	441,00
	i.V.m. Code PYO	○	○	○	○	○	0,00
643	43.2 cm (17-inch) steel wheels with wheel trims	-	-	S	S	S	0,00
	certain countries only	●	●	-	-	-	315,00
	not in conjunction with code 950						
	i.V.m. Code P59	○	○	-	-	-	0,00

27/8/2018 Optional extras for the A-Class

Valid from 03.09.2018 (809)

1) 177.144 only USA/CANADA

● available at extra charge ◌ available at no extra charge ◌ annotations existing
S standard equipment - not available

		Sedan					LLP
		177.103 A 180 d	177.187 A 200	177.145 A 220 4MATIC	177.146 A 250	177.147 A 250 4MATIC	
L	Left-hand drive	◌	◌	◌	◌	◌	0,00
645	M+S winter tyres, set of 4 Only in conjunction with code R78/72R/RVG/RV/RVJ	●	●	●	●	●	115,50
651	Winter complete wheels fitted not in conjunction with code R66 only in conjunction with code 3R1/2R9/8R5/8R2/8R1	-	-	-	-	-	0,00
652	Summer complete tyres fitted not in conjunction with code R66 only in conjunction with code 3R1/2R9/8R5/8R2/8R1	-	-	-	-	-	0,00
666	Freight packaging without tie-down hooks Certain countries only Not in conjunction with Code 820	●	●	●	●	●	0,00
	i.V.m. Code 14P/15P/16P	-	◌	-	◌	-	0,00
668	Prod. prot. f. freight pkging with tie-down hooks Certain countries only Not in conjunction with Code 820	●	●	●	●	●	26,25
669	Collapsible spare wheel certain countries only and only with B12	-	-	-	-	-	0,00
677	Lowered comfort suspension not in conjunction with code 486 Only in conjunction with Code 213 i.V.m. Code 950	●	●	●	●	●	304,50
	i.V.m. Code PYA	◌	◌	◌	◌	◌	0,00
682	Fire extinguisher certain countries only	●	●	●	●	●	0,00
687	Type plate with model year certain countries only	◌	◌	◌	◌	◌	0,00
690	Collapsible spare wheel Certain countries only and only in conjunction with Code E76 and B12	-	◌	◌	◌	◌	0,00
70B	Fluorescent jacket for driver certain countries only not in conj. With 71B	◌ ★	◌ ★	◌ ★	◌ ★	◌ ★	5,25
71B	Fluorescent jackets for driver and passengers certain countries only not in conj. With 70B	●	●	●	●	●	26,25
72R	43.2 cm (17-inch) 10-spoke light-alloy wheels not in conjunction with code 950 i.V.m. Code P27	- ●	- ●	● -	● -	● -	472,50 787,50
	i.V.m. Code P59	●	-	◌	◌	◌	0,00
	i.V.m. Code PYF	◌	◌	◌	◌	◌	0,00
73B	Stowage compartment in centre console, with retractable cover certain countries only only in conjunction with code 426/429	●	●	●	●	●	36,75
	i.V.m. Code PYA	-	-	-	-	-	0,00
762	Remote control unit certain countries only not in conjunction with code 968/969	◌	◌	◌	◌	◌	0,00
763	Key with Radio remote control with panic switch not in conjunction with code 762/968/969 Only in conjunction with Code 551 and Certain countries only	◌	◌	◌	◌	◌	0,00
76R	43.2 cm (17-inch) 5-twin-spoke light-alloy wheels not in conjunction with code 950 i.V.m. Code P27	- ●	- ●	● -	● -	● -	472,50 787,50
	i.V.m. Code P59	●	-	◌	◌	◌	0,00
	i.V.m. Code PYD	◌	◌	◌	◌	◌	0,00
772	AMG bodystyling Only in conjunction with Code 950	◌	◌	◌	◌	◌	0,00
776	Wider wheel arch for AMG wheels only in conjunction with code RQT/RVH/RV/LRT/RTK	◌	◌	◌	◌	◌	0,00
79B	Preinstallation for digital radio certain countries only not in conjunction with code 537 only in conjunction with code (355/859) and 362	◌	◌	◌	◌	◌	0,00
7U1	Manually adjustable front seats not in conjunction with code 555 only in conjunction with code 001A	◌	◌	◌	◌	◌	0,00
7U2	Luxury seats only in conjunction with code 101A/105A/109A/201A/205A/311A/321A/371A/372A/381A and U59, 286 und 287	◌	◌	◌	◌	◌	0,00
7U3	Sports seats not in conjunction with code 555 only in conjunction with code 111A/115A/119A/159A/204A/211A/257A/258A/259A/611A/651A/671A and U59, 286 und 287 i.V.m. Code 950	- -	- -	- -	- -	- -	0,00 246,75
7U4	Sports seats only in conjunction with code 159A/204A/211A/257A/258A/621A/651A and U59, 286 und 287 i.V.m. Code 950	●	●	●	●	●	246,75
		◌	◌	◌	◌	◌	0,00

27/8/2018	Optional extras for the A-Class
	Valid from 03.09.2018 (809)

Valid from 03.09.2018 (809)

1) 177.144 only USA/CANADA

● available at extra charge ○ available at no extra charge U annotations existing
S standard equipment - not available

Sedan						
L	Left-hand drive	O	O	O	O	LLP
809	Technical modifications	O	O	O	O	0,00
810	Burmester® surround sound system not in conjunction with code 853 not in conjunction with code Z97 only in conjunction with code 355/859 i.V.m. Code PYN i.V.m. Code PYN/PYO i.V.m. Code PYO	●	●	●	●	698,25
820	Tourist vehicles not in conjunction with code 634/636/969	-	*	*	*	435,75
821	Country code Brazil not yet valid	-	U	U	U	435,75
822	South Africa specification	O	O	O	O	0,00
823	Indicator plate fixing Switzerland	O	O	O	O	0,00
824	Additional parts for cold countries	O	O	O	O	0,00
829	Taiwan version	O	O	-	O	0,00
830	China specification	-	-	-	-	0,00
831	Indicator plate fixing Italia	O	O	O	O	0,00
835	South Korea specification not yet valid	-	-	U	U	0,00
840	Heat-insulating dark-tinted glass Certain countries only not in conjunction with code U63 only in conjunction with code P27/P59/950 i.V.m. Code P55 i.V.m. Code P55/P60	●	●	●	●	315,00
842	Folding front passenger seat not in conjunction with code 241/242/409 Only in conjunction with Code 7U2 Only LHD models	-	-	-	-	157,50
853	Advanced Sound System certain countries only not in conjunction with code 810 i.V.m. Code PBP/PBR/PYN/PYO	●	●	●	●	262,50
859	Media-Display not in conjunction with code 362 (c.c.o.) 835, 355 only in conjunction with code 547/549 and 446 i.V.m. PBP/PBR/PYM/PYN/PYO	O	O	O	O	0,00
862	Preinstallation for TV not in conj. With Code 865 only in conjunction with Code 355, 859 and 498	-	-	-	●	94,50
865	TV receiver certain countries only not in conj. With code 862 only in conj. With Code 355, 859 and 498	-	-	-	●	945,00
871	HANDS-FREE ACCESS certain countries only only in conjunction with code P17	O	O	O	O	0,00
873	Heated front seats not in conjunction with code 401 i.V.m. Code P33 i.V.m. Code PBP/PBR/PYN/PYO	●	●	●	●	304,50
875	Heated windscreen washer system certain countries only	●	●	●	●	120,75
877	Ambient lighting only in conj. With Code P27/P59 or 950 i.V.m. Code P19 i.V.m. Code P33 i.V.m. Code PBP/PBR/PYN/PYO	●	●	●	●	278,25
882	Interior monitoring system certain countries only Only in conjunction with Code P54 and U62	O	O	O	O	0,00
885	Increased anti-theft protection only 537L	O	O	O	O	0,00
889	KEYLESS-GO only in conj. With Code P27/P59 or 950 i.V.m. Code PAD i.V.m. Code PYN/PYO	●	●	●	●	420,00
896	Preinstallation for Digital vehicle key for smartphone certain countries only only in conjunction with code (897/899) and 362	●	●	●	●	105,00
897	Wireless charging and connection via Bluetooth certain countries only not in conjunction with code 899 only in conjunction with code P27/P59 or 950	●	●	●	●	210,00
899	Multifunction telephony certain countries only not in conjunction with code 897 only in conjunction with code (P27/P59 or 950) and 270, 274	●	●	●	●	514,50
8R1	Complete winter wheel - AMG twin-spoke design, 18" certain countries only and only in conj. With code 651 or 652	-	-	-	-	2205,00
8R2	Complete winter (M+S) wheel-and-tvre assembly x 4	-	-	-	-	2467,50

27/8/2018 Optional extras for the A-Class

Valid from 03.09.2018 (809)

1) 177.144 only USA/CANADA

● available at extra charge ○ available at no extra charge U annotations existing
S standard equipment - not available

		Sedan					LLP
		177.103 A 180 d	177.187 A 200	177.145 A 220 4MATIC	177.146 A 250	177.147 A 250 4MATIC	
L	Left-hand drive certain countries only and only in conj. With code 651 or 652	○	○	○	○	○	0,00
8R5	Complete winter wheel - AMG spoked design, 18" certain countries only and only in conj. With code 651 or 652	-	-	-	-	-	2205,00
913	Air conditioning preinstallation for hot countries Certain countries only	○	-	-	-	-	0,00
916	Fuel tank with increased capacity	-	-	S	-	S	0,00 0,00
922	Reduced power version certain countries only (524L/528L/810L)	-	○	-	-	-	0,00
926	Emission control system with EU4 technology Certain countries only	○	○	○	○	○	0,00
927	EU6 emissions standard Certain countries only	○	○	○	○	○	0,00
928	EU5 emission standard Certain countries only	-	-	-	-	-	0,00
931	Tandem interior mirror Only in conjunction with Code U63 (only LHD)	-	-	-	-	-	0,00
933	Engine for ethanol fuel E100 certain countries only	-	●	-	-	-	315,00
936	Cylinder cut-off certain countries only only in conjunction with Code 426/429 (cert. Countries only)	-	○	-	-	-	0,00
942	Load compartment package certain countries only Only in conjunction with Code P27/P59 or 950 and U35	-	●	●	●	●	157,50 99,75
945	Emission control system China only in conjunction with code 830	-	-	-	-	-	0,00
968	COC document EU6 without registration certificate part II Certain countries only	○	○	○	○	○	0,00
969	COC document EU6 with registration certificate part II Certain countries only	○	○	○	○	○	0,00
971	Exhaust system with DPF Generation 1.5	-	-	-	-	-	0,00
981	Omission of vehicle registration document certain countries only	○	○	○	○	○	0,00
986	Identification no. (US-VIN) Certain countries only	○	○	○	○	○	0,00
989	Identification label under windshield certain countries only	○	○	○	○	○	0,00
B08	Fanfares for Asia	○	○	○	○	○	0,00
B12	Tyre-change toolkit Certain countries only i.e. w. Code 690 or 669	●	●	●	●	●	31,50
B18	Spectacles compartment for driver only in conjunction with code U62	○	○	○	○	○	0,00
B24	Remote control for auxiliary heater Certain countries only Only in conjunction with Code 228, 270 and 274 and in cert. countries with 362	●	●	●	●	●	210,00
B51	TIREFIT Certain countries only Not in conjunction with Code R66 i.V.m. Code PYA	●	●	●	●	●	52,50 0,00
B59	DYNAMIC SELECT	S	S	S	S	S	0,00
B63	Sporty engine sound only in conjunction with code 950 and (355 or 859)	-	○	○	○	○	0,00
E74	Adhesive film not in conjunction with code U03 only in conjunction with Code P33	-	-	-	-	-	0,00
H15	wood linden black open-pored trim only in conjunction with code P59 or (950 but not with P19) i.V.m. Code P39	●	●	●	●	●	273,00 115,50
H23	Brown open-pore walnut wood trim only in conjunction with code P59/P34	●	●	●	●	●	273,00
H44	Light longitudinal-grain aluminium trim only in conjunction with code 950/P59 i.V.m. Code P19 i.V.m. Code P34+950 i.V.m. Code P39 oder 159A i.V.m. Code PYA	●	●	●	●	●	157,50 0,00 0,00 0,00 0,00
H45	Light linear-grain aluminium trim only in conjunction with code P59 or (950 but not with P19) i.V.m. Code P39 oder 159A	●	●	●	●	●	157,50 0,00
H55	Trim in dark carbon-fibre look certain countries only only in conjunction with code P59	○	U	○	U	○	0,00 0,00
H59	Carbon-fibre-look trim only in conjunction with code P59	○	○	○	○	○	0,00
H95	Trim Aluminium AMG Design silver/black only in conjunction with code P33	-	-	-	-	-	0,00
K32	Active Lane Change Assist certain countries only and only in conjunction with code 266 and 365	○	○	○	○	○	0,00
K33	Extended automatic Re-start in traffic jams certain countries only and only in conjunction with code 233, 235 and 365	○	○	○	○	○	0,00

27/8/2018 Optional extras for the A-Class

Valid from 03.09.2018 (809)

1) 177.144 only USA/CANADA

● available at extra charge ◌ available at no extra charge ◌ annotations existing
S standard equipment - not available

		Sedan					LLP
		177.103 A 180 d	177.187 A 200	177.145 A 220 4MATIC	177.146 A 250	177.147 A 250 4MATIC	
L	Left-hand drive	◌	◌	◌	◌	◌	0,00
K34	Route-based speed adaptation certain countries only and only in conjunction with code 233 and 365	◌	◌	◌	◌	◌	0,00
L3A	Multifunction sports steering wheel not in conjunction with code (P59/950) and 233/239 and 443	S	S	S	S	S	0,00
L3B	Multifunction sports steering wheel in nappa leather only in conjunction with code 428 and 443	◌	◌	◌	◌	◌	0,00
L3E	Leather multifunction sports steering wheel not in conjunction with Code 443 or 950 i.V.m. Code P59 i.V.m. Code PYB/PYD	●	●	●	●	●	183,75
		◌	◌	◌	◌	◌	0,00
		◌	◌	◌	◌	◌	0,00
L5C	Multifunction sports steering wheel in nappa leather not in conjunction with code 443 only in conjunction with code 950 Standard	◌	◌	◌	◌	◌	0,00
L5I	Multifunction sports steering wheel in nappa leather / DINAMICA microfibre not in conjunction with code 443 only in conjunction with code 950 and 426/429	●	●	●	●	●	241,50
L6G	AMG Performance steering wheel only in conjunction with Code U88	-	-	-	-	-	882,00
L6J	AMG Performance steering wheel in nappa leather i.V.m. Code P33 i.V.m. Code PYA	-	-	-	-	-	441,00
		-	-	-	-	-	0,00
		-	-	-	-	-	0,00
L6K	AMG Performance steering wheel in nappa leather / DINAMICA microfibre	-	-	-	-	-	514,50
R00	40.6 cm (16-inch) steel wheels with 10-hole trim in certain countries only in conjunction with code R01 or R05 Not in conjunction with Code 950 or U29	S	S	-	-	-	0,00
R01	Summer tyres only in conjunction with code 01R/643/R00/R11/R30/R31/R55/R78/643/72R/76R/RQS/RQT/RVG/RVK	◌	◌	◌	◌	◌	0,00
R02	All season tyres certain countries only and only in conjunction with Code (01R/R31/643/72R/76R/R11/RQT/RQS) certain countries only and only in conjunction with Code (01R/R31/72R/76R/R11/RQT/RQS) only in conjunction with code RQT and R66 and only USA/CANADA	-	-	◌	◌	◌	115,50
				★	★	★	
R03	Sports tyres only in conjunction with Code 01R/R31 only in conjunction with Code RQS/RQT	◌	◌	◌	◌	◌	0,00
R05	Tyres with optimised rolling resistance Certain countries only and only in conjunction with code (R00/R30/R78)	◌	◌	-	-	-	0,00
R11	43.2 cm (17-inch) 5-twin-spoke light-alloy wheels Not in conjunction with Code 950 i.V.m. Code P27 i.V.m. Code P55 i.V.m. Code P59 i.V.m. Code PYB i.V.m. Code PYD/PYF	●	●	●	●	●	682,50
		●	●	-	-	-	997,50
		●	●	●	●	●	210,00
		●	●	-	-	-	525,00
		◌	◌	◌	◌	◌	0,00
		●	●	●	●	●	210,00
		●	●	-	-	-	525,00
		●	●	●	●	●	210,00
R1A	Sports tyres only in conjunction with code R31/01R/RQS/RQT	◌	◌	◌	◌	◌	0,00
R30	40.6 cm (16") multi-spoke light-alloy wheels not in conjunction with code 950 i.V.m. Code P27 i.V.m. Code P59 i.V.m. Code PYB	●	●	-	-	-	682,50
		●	●	-	-	-	210,00
		◌	◌	-	-	-	0,00
		●	●	-	-	-	210,00
R31	45.7 cm (18") 5-twin-spoke light-alloy wheels not in conjunction with code 950 i.V.m. Code P27 i.V.m. Code P55 i.V.m. Code P59 i.V.m. Code PYF	●	●	●	●	●	1312,50
		●	●	-	-	-	1627,50
		●	●	-	-	-	1155,00
		-	-	●	●	●	840,00
		◌	◌	◌	◌	◌	0,00
		●	●	●	●	●	840,00
		●	●	●	●	●	840,00
R55	48.3 cm (19-inch) 5-twin-spoke light-alloy wheels not in conjunction with code 950 i.V.m. Code P27 i.V.m. Code P55 i.V.m. Code P59 i.V.m. Code PYF	-	-	●	●	●	1785,00
		●	●	-	-	-	2100,00
		-	-	●	●	●	1312,50
		●	●	-	-	-	1627,50
		●	●	●	●	●	472,50
		●	●	●	●	●	1312,50
		●	●	●	●	●	1312,50
R66	Run-flat tyres Not in conjunction with Code R05, B51, 645 only in conjunction with code RQT and R02 and only in conjunction with USA/CAN only in conjunction with code with 01R/R31/RQS or RQT	-	-	●	●	●	0,00
		●	●	●	●	●	231,00
R78	40.6 cm (16-inch) 5-twin-spoke light-alloy wheels Not in conjunction with Code 950 i.V.m. Code P27/P59 i.V.m. Code PYB	●	●	-	-	-	472,50
		◌	◌	-	-	-	0,00
		◌	◌	-	-	-	0,00

Valid from 03.09.2018 (809)

● available at extra charge ○ available at no extra charge U annotations existing
S standard equipment - not available

Special models for the V-Class		Sedan										
Valid from 03.09.2018 (809)		177-103	A 180 d	177-187	A 200	177-145	A 220 4MATIC	177-146	A 250	177-147	A 250 4MATIC	
1) 177.144 only USA/CANADA												
● available at extra charge C available at no extra charge U annotations existing S standard equipment - not available												
LLP												
L	Left-hand drive	○	○	○	○	○	○	○	○	○	0,00	
RQS	45.7 cm (18-inch) AMG 5-twin-spoke light-alloy wheels not in conjunction with code P55 only in conjunction with code 950	○	○	○	○	○	○	○	○	○	0,00	
RQT	45.7 cm (18-inch) AMG 5-twin-spoke light-alloy wheels not in conjunction with code 645 i.V.m. Code 950 i.V.m. Code P27 i.V.m. Code P55 i.V.m. Code P55+950 i.V.m. Code P59 i.V.m. Code PYH+P55	-	-	-	-	-	-	-	-	-	0,00 1785,00 2100,00 210,00 1312,50 1627,50 472,50 0,00 1312,50 0,00	
RTI	48.3 cm (19-inch) AMG 5-twin-spoke light-alloy wheels only in conjunction with 950 and R01 and 776 or 460/494	-	-	-	-	-	-	-	-	-	840,00	
RTK	48.3 (19-inch) AMG multi-spoke light-alloy wheels only in conjunction with code P33, R01 and (776/460 or 494)	-	-	-	-	-	-	-	-	-	0,00	
RVG	48.3 cm (19-inch) AMG multi-spoke light-alloy wheels not in conjunction with code R66 i.V.m. Code 950 i.V.m. Code P27 i.V.m. Code P55+P59 i.V.m. Code P59	-	-	-	-	●	●	●	●	●	2047,50 2362,50 630,00 1575,00 1890,00 735,00 1575,00	
RVH	48.3 cm (19-inch) AMG multi-spoke light-alloy wheels only in conjunction with 950 and R01 and 776 or 460/494	-	-	-	-	-	-	-	-	-	630,00	
RVI	48.3 cm (19-inch) AMG multi-spoke light-alloy wheels only in conjunction with code P19 and R01	-	-	-	-	-	-	-	-	-	0,00	
RVJ	48.3 cm (19-inch) AMG multi-spoke light-alloy wheels only in conjunction with code P19 and R01	○	○	○	○	○	○	○	○	○	0,00	
RVK	48.3 cm (19-inch) AMG multi-spoke light-alloy wheels not in conjunction with code R66 i.V.m. Code 950 i.V.m. Code P27 i.V.m. Code P55+P59 i.V.m. Code P59 i.V.m. Code PYH+P55	-	-	●	●	●	●	●	●	●	2415,00 2730,00 997,50 1942,50 2257,50 1102,50 1942,50 997,50	
RVL	48.3 cm (19") AMG Leichtmetallräder im Vielspeichen-Design only in conjunction with 950 and R01 and 776 or 460/494	-	-	-	-	-	-	-	-	-	997,50	
U00	Velour floor mats for driving instruction vehicles only in conjunction with code U63 only LHD	-	-	-	-	-	-	-	-	-	0,00	
U01	Rear belt status indication in the instrument display Certain countries only	○	○	○	○	○	○	○	○	○	0,00	
U03	Omission of decals for special models not in conjunction with Code E74 only in conjunction with code P33	-	-	-	-	-	-	-	-	-	0,00	
U10	Automatic deactivation of front passenger airbag certain countries only i.V.m. Code 51B	●	●	●	●	●	●	●	●	●	99,75	
U12	Velour floor mats certain countries only Not in conjunction with Code 950 or U26 i.V.m. Code PYA	○	○	○	○	○	○	○	○	○	0,00	
U17	Omission of red seat belt	-	-	-	-	-	-	-	-	-	0,00	
U19	MBUX augmented reality for navigation certain countries only only in conjunction with code 365, 859	●	●	●	●	●	●	●	●	●	262,50	
U22	4-way lumbar support not in conjunction with code 409 only in conjunction with Code U59 i.V.m. Code PYO	●	●	●	●	●	●	●	●	●	162,75	
U25	Illuminated door sill panels with "Mercedes-Benz" lettering AMG door sill panels with »AMG« lettering, illuminated Only in conjunction with Code U62 i.V.m. Code PYN/PYO	●	●	●	●	●	●	●	●	●	157,50	
U26	AMG floor mats certain countries only not in conjunction with Code U12 or P19 Only in conjunction with Code 950	○	○	○	○	○	○	○	○	○	0,00	
U29	Braking system with larger brake discs on the front axle only in conjunction with code PAD	○	○	○	○	○	○	○	○	○	0,00	
U35	12 V socket in load area Only in conjunction with Code 942	○	○	○	○	○	○	○	○	○	0,00	
U40	Partition net certain countries only	-	-	-	-	-	-	-	-	-	157,50	
U41	Fuel/water separator and lubrication package	-	-	-	-	-	-	-	-	-	0,00	
U54	TORSION BEAM AXLE certain countries only and only in conjunction with Code (R00/R30/R78/643/728/R68/R11/01R/R31/RQS or RQT)	S	○	-	-	-	-	-	-	-	0,00	

27/8/2018 Optional extras for the A-Class

Valid from 03.09.2018 (809)

1) 177.144 only USA/CANADA

● available at extra charge Cavailable at no extra charge U annotations existing
S standard equipment - not available

		Sedan					LLP
		177.103 A 180 d	177.187 A 200	177.145 A 220 4MATIC	177.146 A 250	177.147 A 250 4MATIC	
L	Left-hand drive not in conjunction with code 459	○	○	○	○	○	0,00
U55	MULTI-LINK-AXLE certain countries only and only in conjunction with Code (01R/R31/R55/RQS/RQT/RVG or RVK) only in conjunction with code 459	U ★	○	S	S	S	0,00
U60	Pedestrian protection Certain countries only	○	○	○	○	○	0,00
U64	Full driving school package only in conjunction with Code U63 only LHD	-	-	-	-	-	1260,00
U65	Additional exterior mirror right and left only in conjunction with code U63 only LHD	-	-	-	-	-	126,00
U66	Floormats special model certain countries only not in conjunction with Code U12 or U26 only in conjunction with Code P19	○	○	○	○	○	0,00
U67	230 V socket in the rear certain countries only not in conjunction with code U80	●	●	●	●	●	120,75
U79	BlueTEC diesel emission control system including AdBlue® reservoir certain countries only	○	-	-	-	-	0,00
U80	115 V socket certain countries only	-	●	●	●	-	120,75
U88	AMG Lenkradtasten only in conjunction with code 426/ 429 und L6G, L6J or L6K i.V.m. Code L6G	-	-	-	-	-	367,50
Y05	designo seat belts in red only in conjunction with code 651A	-	-	-	-	-	0,00
Z83	Activation hill-start assist driving school Only in conjunction with Code U64	-	-	-	-	-	0,00
Z97	Electronic interface for remote control certain countries only not in conjunction with code 810 or (550/554)	-	-	-	-	-	399,00