

14/5/2018 Optional extras for the A-Class
Valid from 22.06.2018 (809)

● available at extra charge ○ available at no extra charge U annotations existing
 S standard equipment - not available

A Limousine

177.003 A 180 d

177.084 A 180

177.087 A 200

177.045 A 220 4MATIC

177.046 A 250

177.047 A 250 4MATIC

LLP

L	Left-hand drive	○	○	○	○	○	○	0,00
R	Right-hand drive	●	●	●	●	●	●	1113,00
144U	digital white metallic	●	●	●	●	●	●	619,50
149U	polar white	●	●	●	●	●	●	220,50
	only in conjunction with Code PYF	●	●	●	●	●	●	130,00
191U	cosmos black metallic	●	●	●	●	●	●	619,50
589U	jupiter red	○	○	○	○	○	○	0,00
662U	designo mountain grey magno	●	●	●	●	●	●	1942,50
696U	night black	○	○	○	○	○	○	0,00
775U	iridium silver metallic	●	●	●	●	●	●	619,50
787U	mountain grey metallic	●	●	●	●	●	●	619,50
859U	mojave silver metallic available 4. Quarter 2018	●	●	●	●	●	●	619,50
001A	Tandel fabric black Not in conjunction with Code P27/P59 or 950 only in conjunction with code 7U1	○	○	○	○	○	○	0,00
101A	Black ARTICO man-made leather only in conjunction with Code 7U2 and P27/P59	●	●	●	●	●	●	152,25
105A	ARTICO man-made leather macchiato beige / black Only in conjunction with Code P59 and 7U2	●	●	●	●	●	●	152,25
109A	ARTICO man-made leather neva grey / black Only in conjunction with Code P27 and 7U2	●	●	●	●	●	●	152,25
111A	ARTICO man-made leather black certain countries only only in conjunction with Code 7U3 and (P27/P59) only in conjunction with Code PYF	●	●	●	●	●	●	152,25
		●	●	●	●	●	●	90,00
115A	ARTICO man-made leather, sports seat macchiato beige / black certain countries only only in conjunction with code 7U3 and P59 only in conjunction with Code PYF	●	●	●	●	●	●	152,25
		●	●	●	●	●	●	90,00
119A	ARTICO man-made leather, sports seat neva grey / black only in conjunction with code 7U3 and P27	●	●	●	●	●	●	152,25
159A	Two-tone ARTICO man-made leather neva grey / black only in conjunction with code 7U3 and 950	U ★	U ★	U ★	U ★	U ★	U ★	0,00
201A	Leather black only in conjunction with Code P34 and P59 and 7U2	○	○	○	○	○	○	0,00
204A	Leather bahia brown / black only in conjunction with Code P34 and 7U3	U ★	U ★	U ★	U ★	U ★	U ★	0,00
205A	Leather macchiato beige / black Only in conjunction with Code P34 and P59 and 7U2	○	○	○	○	○	○	0,00
211A	Leather black only in conjunction with code P34 and 7U3	U ★	U ★	U ★	U ★	U ★	U ★	0,00
257A	Two-tone leather classic red / black only in conjunction with code 7U3 and P39	U ★	U ★	U ★	U ★	U ★	U ★	0,00
258A	Two-tone leather titanium grey pearl / black only in conjunction with code 7U3 and P39	U ★	U ★	U ★	U ★	U ★	U ★	0,00
311A	ARTICO man-made leather / Bertrix fabric black only in conjunction with code P27 and 7U2	○	○	○	○	○	○	0,00
321A	ARTICO man-made leather / Fléron fabric black only in conjunction with code P59 and 7U2	○	○	○	○	○	○	0,00
371A	ARTICO man-made leather/ Bertrix fabric, two-tone black / neva grey only in conjunction with Code P27 and 7U2	○	○	○	○	○	○	0,00
372A	ARTICO man-made leather/ Bertrix fabric, two-tone black indigo blue / black only in conjunction with Code P27 and 7U2	○	○	○	○	○	○	0,00
381A	ARTICO man-made leather/ Fléron fabric, two-tone black / Bahia brown only in conjunction with code P59 and 7U2	○	○	○	○	○	○	0,00
411	6-speed manual transmission certain countries only unvalid	S ★	S ★	S ★	-	-	-	0,00
426	9G-DCT AUTOTRONIC transmission	-	-	-	U	U	U	1953,00

● available at extra charge ○ available at no extra charge ◐ annotations existing
S standard equipment - not available

							LLP
L	Left-hand drive certain countries only (code 460/494) not in conjunction with code U63	○	○	○	○	○	0,00
429	7G-DCT	S	-	-	S	S	0,00
		-	●	●	-	-	1848,00
611A	ARTICO man-made leather / DINAMICA microfibre black only in conjunction with code P19 and 7U3	○	○	○	○	○	0,00
651A	ARTICO man-made leather/DINAMICA microfibre upholstery black Only in conjunction with Code 950 and 7U3	⦿	⦿	⦿	⦿	⦿	0,00
		★	★	★	★	★	
22P	Lane Tracking package certain countries only not in conjunction with code 23P or 51B only in conjunction with Code 234 and 243	●	●	●	●	●	819,00
23P	Driving Assistance package available expected 4. Quarter 2018 in conjunction with Code 365 only in conjunction with Code 513 not in conjunction with Code 22P only in conjunction with code 233, 299 and (275/P49) i.V.m. Code 51B	●	●	●	●	●	1995,00
		●	●	●	●	●	1585,50
431	Galvanised steering-wheel gearshift paddles not in conjunction with code 428 only in conjunction with code (426/429) and L5C/L5I	○	○	○	○	○	0,00
950	AMG Line not in conjunction with code P27 or P59 only in conjunction with code (159A/651A/204A/211A/257A/258A/611A) only in conjunction with code Code 310 and (651A/H44/H15/H23/H45) and (677/485/459) and 772 and (RQS/RQT/RVG/RVK)+(U26/U00) and U62 i.V.m. Code P19 i.V.m. Code PYH, only available via PYH	⦿	⦿	⦿	⦿	⦿	3097,50
		★	★	★	★	★	
		★	★	★	★	★	
		○	○	○	○	○	0,00
		○	○	○	○	○	0,00
P19	Edition 1 only in conjunction with code (144U/149U/191U/662U/696U/787U) and 611A and (631/632/640/641/642) and 877, 950, P55, RV1 and U66 i.V.m. Code PYH	⦿	⦿	⦿	⦿	⦿	6195,00
		★	★	★	★	★	
		●	●	●	●	●	2226,00
P27	Style certain countries only Not in conjunction with Code P59 or 950 Only in conjunction with Code 2U5, 310 and (101A/109A/111A/119A/311A/371A/372A) and U62 and R78/76R/643/R00/R11/R30/R31/R55/01R or 72R i.V.m. Code PYB/PYD, only available via PYB or PYD	⦿	●	⦿	⦿	⦿	0,00
		★		★	★	★	
		○		○	○	○	0,00
P34	Leather package Not in conjunction with Code P39 Only in conjunction with Code (401/873), (201A/204A/205A/211A), 950 or P59 i.V.m. Code 950	●	●	●	●	●	1459,50
		●	●	●	●	●	1207,50
P39	AMG Leather package Not in conjunction with Code P34 only in conjunction with code 950, (257A/258A) and (401/873), only available on AMG Line (PYH)	●	●	●	●	●	1207,50
P44	Parking package with reversing camera not in conjunction with P47 only in conjunction with code 235 and 218 i.V.m. Code PYA i.V.m. Code PYM/PYN/PYO	●	●	●	●	●	976,50
		●	●	●	●	●	624,75
		○	○	○	○	○	0,00
P47	Parking Package with 360° camera not in conjunction with code P44 or 218 only in conjunction with code (P27/P59/950) and (233/234) and 235, 501, 270 and 274 only i.V.m. Code PYM/PYN/PYO	⦿	⦿	⦿	⦿	⦿	1407,00
		★	★	★	★	★	
		●	●	●	●	●	430,50
P49	Mirror package Consisting of: Code 249, 500 and U62 i.V.m. Code PYM/PYN/PYO	●	●	●	●	●	383,25
		○	○	○	○	○	0,00
P54	Anti-Theft Protection package certain countries only	●	●	●	●	●	430,50

Valid from 22.06.2018 (809)

● available at extra charge ○ available at no extra charge U annotations existing
 S standard equipment - not available

		A Limousine						LLP
		A 180 d	A 180	A 200	A 220 4MATIC	A 250	A 250 4MATIC	
		177.003	177.084	177.087	177.045	177.046	177.047	
L	Left-hand drive only in conjunction with code 551, 882 and U62 i.V.m. Code 362	○	○	○	○	○	○	0,00
P55	Night package only in conjunction with code P59, and 01R/643/R00/R11/R30/R31/R55/R78/72R/76R/RQT/RVG/RVK or 950 and (RVG/RVK/RVI or (RQT but not with 645) i.V.m. Code 950 i.V.m. Code P19	U	U	U	U	U	U	840,00
		★	★	★	★	★	★	
		●	●	●	●	●	●	409,50
		○	○	○	○	○	○	0,00
P59	Progressive not in conjunction with code P27/950 only in conjunction with code 310 and 2U5 and (101A/105A/111A/115A/201A/205A/211A/321A/381A) and (101A/105A/201A/204A) and 72R/643/R00/R11/R30/R31/R55/R78/01R/76R and (H15/H23/H44/H45/H55/H59) and U62 i.V.m. Code PYF, only available via PYF	U	U	U	U	U	U	1412,25
		-	-	-	-	-	-	1648,50
		★	★	★	★	★	★	
		○	○	○	○	○	○	0,00
PAC	Vorteils-Paket	S	S	S	S	S	S	0,00
PAD	Engineering package only in conjunction with code U29, 459, (641/642) and 889	●	●	●	●	●	●	3108,00
PBF	Navigation Connectivity package certain countries only not in conjunction with code PBG only in conjunction with code 365 and 01U	●	●	●	●	●	●	682,50
PBG	Navigation and Comfort Connectivity package certain countries only not in conjunction with code PBF only in conjunction with code 365, 01U, 02U and 12U only in conjunction with code 859	●	●	●	●	●	●	808,50
PBI	Konnektivitäts-Paket Smartphone certain countries only only in conjunction with code Code 08U, 09U and 14U	●	●	●	●	●	●	420,00
PYA	WEU Standard Equipment certain countries only	●	●	●	●	●	●	0,00
PYB	SE Package certain countries only	●	●	●	-	-	-	0,00
PYD	Style Line Delta due to PYB certain countries only	-	-	-	●	●	●	0,00
		●	●	●	-	-	-	887,00
PYF	Progressive Line Delta due to PYB certain countries only	-	-	-	●	●	●	726,00
		●	●	●	-	-	-	1411,00
PYH	AMG Line Delta due to PYB & U12 certain countries only	-	-	-	●	●	●	1976,00
		●	●	●	-	-	-	2500,00
PYM	Advantage Package certain countries only only in conjunction with Code PYF	●	●	●	●	●	●	1720,00
		●						1335,00
PYN	Premium Package certain countries only	●	●	●	●	●	●	3304,00
PYO	Premium Plus Package certain countries only	●	●	●	●	●	●	4699,00
U59	Seat comfort package not in conjunction with code 7U1	○	○	○	○	○	○	0,00
U62	Light and sight package only in conjunction with Code 543, B18 und (P27/P59 or 950)	○	○	○	○	○	○	0,00
U63	Basic driving school package code U12 or U26 available not in conjunction with code 426/429/840/877/896/897 or 899 only in conjunction with code P27/P59 or 950 and U00, U65 and 931 only LHD (certain countries only) i.V.m. Code U64	●	●	●	●	●	●	572,25
		○	○	○	○	○	○	0,00

14/5/2018 Optional extras for the A-Class
Valid from 22.06.2018 (809)
A Limousine

● available at extra charge ○ available at no extra charge U annotations existing
S standard equipment - not available

177.003

177.084

177.087

177.045

177.046

177.047

LLP

L	Left-hand drive	○	○	○	○	○	○	0,00
498	Japan specification	-	○	-	-	-	-	0,00
00B	Owner's Manual and Service Booklet - Danish	○	○	○	○	○	○	0,00
01B	Owner's Manual and Service Booklet - Dutch	○	○	○	○	○	○	0,00
01R	45.7 cm (18-inch) 5-twin-spoke light-alloy wheels	●	●	●	●	●	●	1312,50
	not in conjunction with code 950	●	●	●	-	-	-	1627,50
	i.V.m. Code P27	●	●	●	-	-	-	1155,00
	i.V.m. Code P55	○	○	○	○	○	○	840,00
	i.V.m. Code P59	●	●	●	●	●	●	0,00
	only available i.V.m. Code PYF	●	●	●	●	●	-	840,00
01U	Navigation services certain countries only only in conjunction with code 362 only in conjunction with code PBG or PBF	○	○	○	○	○	○	0,00
02B	Owner's Manual and Service Booklet - German	○	○	○	○	○	○	0,00
02U	Office function in the vehicle certain countries only only in conjunction with code PBG and 859	○	○	○	○	○	○	0,00
03B	Owner's Manual and Service Booklet - Russian	○	○	○	○	○	○	0,00
04B	Owner's Manual and Service Booklet - Finnish	○	○	○	○	○	○	0,00
05B	Owner's Manual and Service Booklet - English	○	○	○	○	○	○	0,00
06B	Owner's Manual and Service Booklet - Italian	○	○	○	○	○	○	0,00
07B	Owner's Manual and Service Booklet - French	○	○	○	○	○	○	0,00
08B	Owner's Manual and Service Booklet - Spanish	○	○	○	○	○	○	0,00
08U	Vehicle Setup certain countries only only in conjunction with 09U, 362 and (PBI in certain countries only)	○	○	○	○	○	○	0,00
09B	Owner's Manual and Service Booklet - Portuguese	○	○	○	○	○	○	0,00
09U	Vehicle Monitoring certain countries only only in conjunction with 08U, 362 and (PBI in certain countries only)	○	○	○	○	○	○	0,00
10B	Owner's Manual and Service Booklet - Swedish	○	○	○	○	○	○	0,00
11B	Owner's Manual and Service Booklet - Arabic	○	○	○	○	○	○	0,00
12B	Owner's Manual and Service Booklet - Engl. USA/CAN	○	○	○	○	○	○	0,00
12U	Preinstallation for Concierge Service certain countries only only in conjunction with 362 and PBG	○	○	○	○	○	○	0,00
13B	Owner's Manual and Service Booklet - Norwegian	○	○	○	○	○	○	0,00
14B	Owner's Manual and Service Booklet - Greek	○	○	○	○	○	○	0,00
14U	Smartphone integration certain countries only only in conj. With Code 16U and 17U i.V.m. Code PBI	●	●	●	●	●	●	262,50
		○	○	○	○	○	○	0,00
15B	Owner's Manual and Service Booklet - Turkish	○	○	○	○	○	○	0,00
16B	Owner's Manual and Service Booklet - Polish	○	○	○	○	○	○	0,00
16U	Apple CarPlay only in conj. With Code 14U	○	○	○	○	○	○	0,00
17B	Owner's Manual and Service Booklet - Czech	○	○	○	○	○	○	0,00
17U	Android Auto only in conj. with Code 14U	○	○	○	○	○	○	0,00
18B	Owner's Manual and Service Booklet - Engl. S. Am.	○	○	○	○	○	○	0,00
18U	Baidu CarLife certain countries only (China) only in conjunction with code 355 or 859	-	○	○	○	○	○	0,00
19B	Owner's Manual and Service Booklet - French S. Am.	○	○	○	○	○	○	0,00
20B	Owner's Manual and Service Booklet - Spanish S. Am.	○	○	○	○	○	○	0,00
20U	Schlüssellose Vermietung available expected 3. Quarter 2018	●	●	●	●	●	●	52,50

14/5/2018 Optional extras for the A-Class
Valid from 22.06.2018 (809)

● available at extra charge ◯ available at no extra charge ◯ annotations existing
S standard equipment - not available

		A Limousine						LLP
		177.003 A 180 d	177.084 A 180	177.087 A 200	177.045 A 220 4MATIC	177.046 A 250	177.047 A 250 4MATIC	
L	Left-hand drive certain countries only only in conjunction with code 362	○	○	○	○	○	○	0,00
213	Direct-Steer system only in conjunction with code (459/677) or (486 only AMG)	○	○	○	○	○	○	0,00
218	Reversing camera not in conjunction with code 501 i.V.m. Code P44 i.V.m. Code PYA	●	●	●	●	●	●	0,00
		○	○	○	○	○	○	0,00
		○	○	○	○	○	○	0,00
21B	Owner's Manual and Service Booklet - Portug. S. Am.	○	○	○	○	○	○	0,00
228	Auxiliary heater certain countries only in conjunction with code B24 only LHD	●	●	●	●	●	●	1155,00
22B	Owner's Manual and Service Booklet - Japanese	○	○	○	○	○	○	0,00
232	Garage door opener (frequency range 284-390 MHz) Certain countries only (460/494/777L) Only in conjunction with Code U62 or P49	●	●	●	●	●	●	236,25
233	Active Distance Assist DISTRONIC available expected 4. Quarter 2018 certain countries only not in conjunction with Code L3A, 234, 258 or 440 only in conjunction with Code 23P, 266, 270, 273, (426/429)	○	○	○	○	○	○	0,00
234	Blind Spot Assist Certain countries only not in conjunction with code 233 only in conjunction with code 270, 273 and(275 or P49) i.V.m. Code 22P	●	●	●	●	●	●	472,50
		○	○	○	○	○	○	0,00
235	Active Parking Assist with PARKTRONIC i.V.m. Code P44/P47	●	●	●	●	●	●	708,75
		○	○	○	○	○	○	0,00
239	Active Distance Assist DISTRONIC certain countries only Not in conjunction with Code L3A/ 233/258 or 440 Only in conjunction with Code 426 or 429	●	●	●	●	●	●	630,00
23B	Owner's Manual and Service Booklet - simpl. Chinese	○	○	○	○	○	○	0,00
241	Front seat left, electrically adjustable memory switch Only in conjunction with Code 275 Right-hand-drive vehicles only i.V.m. Code PYO	●	●	●	●	●	●	299,25
		○	○	○	○	○	○	0,00
242	Front pass. seat, electrically adj. with memory function LHD version Only in conjunction with Code 275 i.V.m. Code PYO	●	●	●	●	●	●	299,25
		○	○	○	○	○	○	0,00
243	Active Lane Keeping Assist not in conjunction with code 233 i.V.m. Code 22P/51B	●	●	●	●	●	●	0,00
		○	○	○	○	○	○	0,00
249	Interior mirror and driver's exterior mirror automatically dimming Only in conjunction with Code P49	○	○	○	○	○	○	0,00
24B	Owner's Manual and Service Booklet - trad. Chinese	○	○	○	○	○	○	0,00
258	Active Brake Assist Certain countries only not in conjunction with code 233 or 239	○	○	○	○	○	○	0,00
25B	Owner's Manual and Service Booklet - Korean	○	○	○	○	○	○	0,00
260	Omission of model plate on boot lid	○	○	○	○	○	○	0,00
263	Number plate mounting for Asia / Mexico certain countries only and not in conj. With code 968	○	○	○	○	○	○	0,00
264	Number plate mounting for America not in conjunction with Code 968	○	○	○	○	○	○	0,00
266	DISTRONIC PLUS with Cross-Traffic Assist (DTR+Q) certain countries only only in conjunction with code 233	○	○	○	○	○	○	0,00

14/5/2018 Optional extras for the A-Class
Valid from 22.06.2018 (809)

● available at extra charge ○ available at no extra charge U annotations existing
S standard equipment - not available

A Limousine

177.003 A 180 d

177.084 A 180

177.087 A 200

177.045 A 220 4MATIC

177.046 A 250

177.047 A 250 4MATIC

LLP

L	Left-hand drive	○	○	○	○	○	○	0,00
26B	Owner's Manual and Service Booklet - Chinese Taiwan	○	○	○	○	○	○	0,00
26U	Preinstallation for engine remote start	-	-	-	●	●	●	105,00
	certain countries only							
270	Aerial for GPS	○	○	○	○	○	○	0,00
	only in conjunction with Code 501/899/B24/233/234/355/362							
273	Exit Warning Assistant	○	○	○	○	○	○	0,00
	only in conjunction with Code 233 or 234							
274	Aerial for telephone	○	○	○	○	○	○	0,00
	only in conjunction with code 501/899 or B24							
275	Driver's seat, electrically adjustable with memory function	●	●	●	●	●	●	362,25
	only in conjunction with code (U22/409)							
	i.V.m. Code PYO	○	○	○	○	○	○	0,00
286	Luggage net on driver's and front pass. backrest	U	U	U	U	U	U	0,00
	only in conjunction with code 7U2/7U3							
287	Folding rear-seat backrests	U	U	U	U	U	U	0,00
	only in conjunction with code 7U2/7U3							
293	Sidebags in rear	U	U	U	U	U	U	393,75
	certain countries only							
	only in conjunction with code 7U2/7U3							
294	Kneebag	○	○	○	○	○	○	0,00
	Certain countries only							
299	PRE-SAFE® system	●	●	●	●	●	●	346,50
	i.V.m. Code 23P	○	○	○	○	○	○	0,00
2R9	Winter (M+S) wheel and tyre assembly x 4	●	●	●	●	●	●	1417,50
	certain countries only and only in conj. With code 651 or 652							
2U0	car2go pre-installation	●	●	●	●	●	●	178,50
	certain countries only							
	only in conjunction with code (355/859)							
2U5	Painted side skirts	○	○	○	○	○	○	0,00
	only in conjunction with P27/P59							
301	Ashtray insert for cup holder with cigarette lighter	●	●	●	●	●	●	47,25
	certain countries only							
30B	Owner's Manual and Service Booklet - Slovenian	○	○	○	○	○	○	0,00
310	Twin cup holder	●	●	●	●	●	●	0,00
	i.V.m. Code P27/P59/950	○	○	○	○	○	○	0,00
	i.V.m. Code PYA	○	○	○	○	○	○	0,00
31B	Owner's Manual and Service Booklet - Hungarian	○	○	○	○	○	○	0,00
32B	Owner's Manual and Service Booklet - Bulgarian	○	○	○	○	○	○	0,00
33B	Owner's Manual and Service Booklet - Romanian	○	○	○	○	○	○	0,00
345	Windscreen wiper with rain sensor	S	S	S	S	S	S	0,00
34B	Owner's Manual and Service Booklet - Croatian	○	○	○	○	○	○	0,00
351	Mercedes-Benz emergency call system	○	○	○	○	○	○	0,00
	only in conj. With Code 362							
355	Extended MBUX functions	●	●	●	●	●	●	0,00
	certain countries only							
	only in conjunction with Code (548/549) and 270 and 446							
	i.V.m. Code PYA	○	○	○	○	○	○	0,00
35B	Owner's Manual and Service Booklet - Latvian	○	○	○	○	○	○	0,00
362	Communications module (LTE) for the use of Mercedes me connect services	○	○	○	○	○	○	0,00
	cert. Countries only							
	only in conjunction with code 270 and 351							
	Standard in certain countries only							
365	Hard-disc navigation	●	●	●	●	●	●	577,50
	only in conjunction with code 355							
	i.V.m. Code PBF/PBG	○	○	○	○	○	○	0,00
	i.V.m. Code PYM/PYN/PYO	○	○	○	○	○	○	0,00
367	Preinstallation for Live Traffic Information	○	○	○	○	○	○	0,00

Valid from 22.06.2018 (809)

● available at extra charge ○ available at no extra charge U annotations existing
 S standard equipment - not available

		A Limousine						LLP
		177.003 A 180 d	177.084 A 180	177.087 A 200	177.045 A 220 4MATIC	177.046 A 250	177.047 A 250 4MATIC	
L	Left-hand drive only in conj.with Code 355 and 362 and certain countries only i.V.m. Code PYA	○	○	○	○	○	○	0,00
36B	Owner's Manual and Service Booklet - Lithuanian	○	○	○	○	○	○	0,00
37B	Owner's Manual and Service Booklet - Slovakian	○	○	○	○	○	○	0,00
38B	Owner's Manual and Service Booklet - Estonian	○	○	○	○	○	○	0,00
39B	Owner's Manual and Service Booklet - Serbian	○	○	○	○	○	○	0,00
3R1	winter (M+S) wheel and tyre assembly x 4 certain countries only and only in conj. With code 651 or 652 not in conjunction with Code U29	●	●	●	-	-	-	1102,50
400	Rear armrest only in conjunction with Code 287 only available i.V.m. Code PYN/PYO	●	●	●	●	●	●	173,25
401	Climatised front seats certain countries only in conjunction with Sportseat code 7U3 not in conjunction with code 873 only in conjunction with Code 101A/105A/109A/111A/115A/119A/159A/201A/204A/205A/211A/257A/258A or 259A only available i.V.m. Code PYN/PYO	○	○	○	○	○	○	0,00
409	Multicontour seat package certain countries only only in conjunction with code 7U2 but not with code U22	●	●	●	●	●	●	934,50
40B	Owner's Manual and Service Booklet - ukrainian	○	○	○	○	○	○	0,00
413	Panoramic sliding sunroof only in conjunction with Code U62 and 51U i.V.m. Code PYO	○	○	○	○	○	○	0,00
41B	Owner's Manual and Service Booklet - hebrew	○	○	○	○	○	○	0,00
428	Steering wheel shift paddles Only in conjunction with Code 426 or 429 and (L3A/L3B or L3E)	○	○	○	○	○	○	0,00
42B	Owner's Manual and Service Booklet - Indonesian	○	○	○	○	○	○	0,00
43B	Owner's Manual and Service Booklet - Thai	○	○	○	○	○	○	0,00
440	Cruise control Not in conjunction with Code 233 or 239	○	○	○	○	○	○	0,00
443	Heated multifunction steering wheel not in conjunction with code 950 (except with code 460) only in conjunction with code (426/429) and L3B i.V.m. Code P59/950	○	○	○	○	○	○	0,00
446	Touchpad i.V.m. Code PYA	○	○	○	○	○	○	0,00
44B	Owner's Manual and Service Booklet - Vietnamese	○	○	○	○	○	○	0,00
458	All-digital instrument display available i.V.m Code PYM only in conjunction with code 859 und 365 i.V.m. Code PYN/PYO	○	○	○	○	○	○	0,00
459	Suspension with Adaptive Damping system certain countries only only in conjunction with code 213 i.V.m. Code 950 (ohne PYH) i.V.m. Code PAD	○	○	○	○	○	○	0,00
460	Canada specification	-	-	-	-	○	○	0,00
463	Head-up Display only in conjunction with code 355/859 and P59 or 950, only i.V.m Code PYM/PYN/PYO	○	○	○	○	○	○	0,00
474	Diesel particulate filter	○	○	○	○	○	○	0,00
475	Tyre pressure monitoring system Certain countries only i.V.m. S-Code 6P5	○	○	○	○	○	○	0,00
477	Tyre pressure loss warning system Certain countries only	○	○	○	○	○	○	0,00
482	Suspension with higher ground clearance	○	○	○	○	○	○	0,00

● available at extra charge ○ available at no extra charge U annotations existing
 S standard equipment - not available

		A Limousine						LLP
		A 180 d 177.003	A 180 177.084	A 200 177.087	A 220 4MATIC 177.045	A 250 177.046	A 250 4MATIC 177.047	
L	Left-hand drive	○	○	○	○	○	○	0,00
	Certain countries only							
485	Comfort suspension	S	S	S	S	S	S	0,00
	Not in conjunction with Code 950							
500	Electrically folding exterior mirrors	○	○	○	○	○	○	0,00
	Only in conjunction with Code P49							
501	360° camera	U	U	U	U	U	U	0,00
	not in conjunction with code 218							
	only in conjunction with code 270 and 274 and (233/234) and P47	★	★	★	★	★	★	
504	Speed Limit Assist	○	○	○	○	○	○	0,00
	not in conjunction with Code 513, 365 and 233							
	only in conjunction with Code 51B							
513	Traffic Sign Assist	●	●	●	●	●	●	309,75
	not in conjunction with Code 504							
	only in conjunction with Code 365 and certain countries only							
517	HD digital radio standard	○	○	○	○	○	○	0,00
	certain countries only							
518	Media Interface including consumer cable set	●	●	●	●	●	●	52,50
	certain countries only							
51B	Rating Countries EURO-NCAP	○	○	○	○	○	○	0,00
	certain countries only							
	only in conjunction with code (258 or 239) and (243 or 233) and (504 or 513)							
51U	Roof liner in black fabric	○	○	○	○	○	○	0,00
	not available as single option, standard with SE (PYB), Style (PYD), Progressive (PYF) and AMG Line (PYH)							
524	Transport protection	●	●	●	●	●	●	168,00
	certain countries only and only in conj. With code 662U							
	not in conjunction with code 820							
536	Sirius satellite radio	-	-	-	-	●	●	367,50
	certain countries only							
	only in conjunction with code 355/859							
537	Digital radio	●	●	●	●	●	●	210,00
	certain countries only							
	not in conjunction with code 79B							
539	Digital radio standard DRM (Digital Radio Mondial)	●	●	●	●	●	●	210,00
	certain countries only							
543	Sun visor with illuminated vanity mirror	○	○	○	○	○	○	0,00
	Only in conj. with Code U62							
545	MBUX multimedia system	S	S	S	S	S	S	0,00
	certain countries only							
	not in conjunction with code 355/859/PBF or PBG							
546	Automatic speed control	○	○	○	○	○	○	0,00
	certain countries only							
	only in conjunction with code 233 and 513							
548	MBUX multimedia system	U	U	U	U	U	U	0,00
	certain countries only							
	not in conjunction with code 256	★	★	★	★	★	★	
	not in conjunction with code 859							
	only in conjunction with code 355							
549	MBUX multimedia system	○	○	○	○	○	○	0,00
	only in conjunction with code 859 and 355							
550	Trailer coupling with ESP® trailer stabilisation	●	●	●	●	●	●	840,00
	certain countries only							
551	Anti-theft alarm system	●	●	●	●	●	●	262,50
	Only in conjunction with Code P54 or certain countries only							
	i.V.m. Code P54	○	○	○	○	○	○	0,00
552	Anti-theft alarm system	○	○	○	○	○	○	0,00
	Only in conjunction with Code P54 and 513L							
580	THERMATIC automatic climate control	○	○	○	○	○	○	0,00
	certain countries only							

● available at extra charge ○ available at no extra charge U annotations existing
 S standard equipment - not available

		A Limousine						LLP
		177.003 A 180 d	177.084 A 180	177.087 A 200	177.045 A 220 4MATIC	177.046 A 250	177.047 A 250 4MATIC	
L	Left-hand drive	○	○	○	○	○	○	0,00
581	THERMOTRONIC automatic climate control only available i.V.m. Code PYF/PYH	●	●	●	●	●	●	535,50
		○	○	○	○	○	○	0,00
58U	Roof liner in crystal grey fabric not in conjunction with code 105A/109A/115A/119A/159A/205A or 371A Not in conjunction with Code 413	U	U	U	U	U	U	0,00
		★	★	★	★	★	★	
598	Petrol particulate filter certain countries only only in conjunction with code 927	-	○	○	○	○	○	0,00
5U3	AIRPANEL certain countries only	●	●	●	●	●	●	84,00
608	Adaptive Highbeam Assist certain countries only Only in conjunction with Code 631/632 or 640 i.V.m. Code 640	●	●	●	●	●	●	189,00
		-	-	-	○	○	○	0,00
613	Headlamps for RHD vehicles not in conjunction with code PAD Part of standard specification for LHD countries	○	○	○	○	○	○	0,00
620	Halogen headlamps with integrated LED daytime running lamps certain countries only not in conjunction with code PAD standard RHD	○	○	○	○	○	○	0,00
623	Gulf States specification	-	●	●	●	●	●	157,50
625	Australia specification	○	○	○	○	○	○	0,00
628	Adaptive Highbeam Assist Plus not in conjunction with code 608 only in conjunction with Code 641/642	○	○	○	○	○	○	0,00
631	LED High Performance headlamp (RHD) Certain countries only not in conjunction with Code PAD i.V.m. Code P19 i.V.m. Code PYD/PYF/PYH	U	U	U	U	U	U	871,50
		★	★	★	★	★	★	
		○	○	○	○	○	○	0,00
		○	○	○	○	○	○	0,00
632	LED High Performance headlamp for right-hand traffic Certain countries only not in conjunction with code PAD i.V.m. Code P19 i.V.m. Code PYD/PYF/PYH	U	U	U	U	U	U	871,50
		★	★	★	★	★	★	
		○	○	○	○	○	○	0,00
		○	○	○	○	○	○	0,00
634	Omission of first-aid kit certain countries only	○	○	○	○	○	○	0,00
636	Omission of warning triangle certain countries only not in conjunction with code 820	○	○	○	○	○	○	0,00
640	Headlamps, LED, dynamic, SAE, right-side traffic certain countries only only in conjunction with code 608 i.V.m. Code P19	-	-	-	●	●	●	1312,50
		-	-	-	●	●	●	441,00
641	MULTIBEAM LED LV/RL certain countries only only in conjunction with code 628 i.V.m. Code P19 i.V.m. Code PAD i.V.m. Code PYD/PYF/PYH i.V.m. Code PYO	●	●	●	●	●	●	1312,50
		●	●	●	●	●	●	441,00
		○	○	○	○	○	○	0,00
		●	●	●	●	●	●	441,00
		○	○	○	○	○	○	0,00
642	MULTIBEAM LED certain countries only only in conjunction with code 628 i.V.m. Code P19 i.V.m. Code PAD i.V.m. Code PYD/PYF/PYH i.V.m. Code PYO	●	●	●	●	●	●	1312,50
		●	●	●	●	●	●	441,00
		○	○	○	○	○	○	0,00
		●	●	●	●	●	●	441,00
		○	○	○	○	○	○	0,00

14/5/2018 Optional extras for the A-Class
Valid from 22.06.2018 (809)

● available at extra charge ○ available at no extra charge U annotations existing
S standard equipment - not available

		A Limousine						LLP
		177.003 A 180 d	177.084 A 180	177.087 A 200	177.045 A 220 4MATIC	177.046 A 250	177.047 A 250 4MATIC	
L	Left-hand drive	-	○	○	○	○	○	0,00
643	43.2 cm (17-inch) steel wheels with wheel trims	-	○	-	S	S	S	0,00
	certain countries only	●	●	●	-	-	-	315,00
	not in conjunction with code 950	○	○	○	-	-	-	0,00
	i.V.m. Code P59	○	○	○	-	-	-	0,00
645	M+S winter tyres, set of 4	U	U	U	U	U	U	115,50
	Only in conjunction with code R78/72R/RQT/RVG	★	★	★	★	★	★	
651	Winter complete wheels fitted	○	○	○	○	○	○	0,00
	only in conjunction with code 3R1/2R9/8R5/8R2							
652	Summer complete tyres fitted	○	○	○	○	○	○	0,00
	only in conjunction with code 3R1/2R9/8R5/8R2							
666	Freight packaging without tie-down hooks	●	●	●	●	●	●	0,00
	Certain countries only							
	Not in conjunction with Code 820							
	i.V.m. Code 14P/15P/16P	○	○	○	○	○	○	0,00
668	Prod. prot. f. freight pkging with tie-down hooks	●	●	●	●	●	●	26,25
	Certain countries only							
	Not in conjunction with Code 820							
677	Lowered comfort suspension	●	●	●	●	●	●	0,00
	not in conjunction with code 486							
	Only in conjunction with Code 213							
	i.V.m. Code 950	○	○	○	○	○	○	0,00
	i.V.m. Code PYA	○	○	○	○	○	○	0,00
682	Fire extinguisher	●	●	●	●	●	●	0,00
	certain countries only							
687	Type plate with model year	○	○	○	○	○	○	0,00
	certain countries only							
690	Collapsible spare wheel	-	○	○	○	○	○	0,00
	Certain countries only and only in conjunction with Code E76 and B12							
70B	Fluorescent jacket for driver	●	●	●	●	●	●	5,25
	not in conj. With 71B							
71B	Fluorescent jackets for driver and passengers	●	●	●	●	●	●	26,25
	certain countries only							
	not in conj. With 70B							
72R	43.2 cm (17-inch) 10-spoke light-alloy wheels	-	-	-	●	●	●	472,50
	not in conjunction with code 950	●	●	●	-	-	-	787,50
	i.V.m. Code P27	-	-	-	○	○	○	0,00
		●	●	●	-	-	-	315,00
	i.V.m. Code P59	○	○	○	○	○	○	0,00
	only available i.V.m. Code PYF, not with code P55	○	○	○	○	○	○	0,00
73B	Stowage compartment in centre console, with retractable cover	●	●	●	●	●	●	0,00
	certain countries only							
	only in conjunction with code 426/429							
762	Remote control unit	○	○	○	○	○	○	0,00
	certain countries only							
	not in conjunction with code 968/969							
763	Key with Radio remote control with panic switch	○	○	○	○	○	○	0,00
	not in conjunction with code 762/968/969							
	Only in conjunction with Code 551 and Certain countries only							
76R	43.2 cm (17-inch) 5-twin-spoke light-alloy wheels	-	-	-	●	●	●	472,50
	not in conjunction with code 950	●	●	●	-	-	-	787,50
	i.V.m. Code P27	-	-	-	○	○	○	0,00
		●	●	●	-	-	-	315,00
	i.V.m. Code P59	○	○	○	○	○	○	0,00
	only available i.V.m. Code PYD	○	○	○	○	○	○	0,00
772	AMG bodystyling	○	○	○	○	○	○	0,00
	Only in conjunction with Code 950							

● available at extra charge ◯ available at no extra charge U annotations existing
 S standard equipment - not available

		A Limousine						LLP
		177.003 A 180 d	177.084 A 180	177.087 A 200	177.045 A 220 4MATIC	177.046 A 250	177.047 A 250 4MATIC	
L	Left-hand drive	○	○	○	○	○	○	0,00
776	Wider wheel arch for AMG wheels only in conjunction with code RVH/RVL/RTI/RTK/RUS/RSW/RXS/RSY/RSZ	○	○	○	○	○	○	0,00
79B	Preinstallation for digital radio certain countries only not in conjunction with code 537 only in conjunction with code (355/859) and 362	○	○	○	○	○	○	0,00
7U1	Manually adjustable front seats not in conjunction with code 555 only in conjunction with code 001A	○	○	○	○	○	○	0,00
7U2	Luxury front seats only in conjunction with code 101A/105A/109A/201A/205A/311A/321A/371A/372A/381A and U59, 286 und 287	○	○	○	○	○	○	0,00
7U3	Sports front seats only in conjunction with code 111A/115A/119A/159A/204A/211A/257A/258A/259A/611A/651A/671A and U59, 286 and 287	●	●	●	●	●	●	246,75
	i.V.m. Code 950	○	○	○	○	○	○	0,00
	only in conjunction with Code PYF	●						145,00
809	Technical modifications	○	○	○	○	○	○	0,00
810	Burmester® surround sound system not in conjunction with code 853 not in conjunction with code Z97 only in conjunction with code 355/859 only available i.V.m. Code PYN/PYO	U	U	U	U	U	U	698,25
		★	★	★	★	★	★	
		●	●	●	●	●	●	435,75
820	Tourist vehicles not in conjunction with code 634/636/969	○	○	○	○	○	○	0,00
821	Country code Brazil	-	○	○	○	○	○	0,00
822	South Africa specification	○	○	○	○	○	○	0,00
823	Indicator plate fixing Switzerland	○	○	○	○	○	○	0,00
824	Additional parts for cold countries	○	○	○	○	○	○	0,00
829	Taiwan version	○	○	○	○	○	○	0,00
830	China specification	-	○	○	○	-	-	0,00
831	Indicator plate fixing Italia	○	○	○	○	○	○	0,00
835	South Korea specification	-	-	-	○	○	○	0,00
840	Heat-insulating dark-tinted glass Certain countries only not in conjunction with code U63 only in conjunction with code P27/P59/950 i.V.m. Code P55	U	U	U	U	U	U	315,00
		★	★	★	★	★	★	
		○	○	○	○	○	○	0,00
853	Soundsystem certain countries only not in conjunction with code 810 i.V.m. Code PYN/PYO	●	●	●	●	●	●	262,50
		○	○	○	○	○	○	0,00
859	Media-Display in certain countries not with code 362 only in conjunction with code 549 and 446 only available i.V.m. Code PYM/PYN/PYO	●	●	●	●	●	●	682,50
		○	○	○	○	○	○	0,00
873	Heated front seats not in conjunction with code 401 i.V.m. Code PYN/PYO	●	●	●	●	●	●	304,50
		○	○	○	○	○	○	0,00
875	Heated windscreen washer system certain countries only	●	●	●	●	●	●	120,75
877	Ambient lighting only in conj. With Code P27/P59 or 950 i.V.m. Code P19 i.V.m. Code PYN/PYO, not available as single option	●	●	●	●	●	●	278,25
		○	○	○	○	○	○	0,00
		○	○	○	○	○	○	0,00
882	Interior monitoring system certain countries only Only in conjunction with Code P54 and U62	○	○	○	○	○	○	0,00

Valid from 22.06.2018 (809)

● available at extra charge ○ available at no extra charge U annotations existing
 S standard equipment - not available

		A Limousine						LLP
		177.003 A 180 d	177.084 A 180	177.087 A 200	177.045 A 220 4MATIC	177.046 A 250	177.047 A 250 4MATIC	
L	Left-hand drive	○	○	○	○	○	○	0,00
885	Increased anti-theft protection only 537L	○	○	○	○	○	○	0,00
889	KEYLESS-GO only in conj. With Code P27/P59 or 950 i.V.m. Code PAD i.V.m. Code PYN/PYO, not available as single option	●	●	●	●	●	●	420,00
		○	○	○	○	○	○	0,00
		○	○	○	○	○	○	0,00
896	Preinstallation for Digital vehicle key for smartphone certain countries only only in conjunction with code (897/899) and 362	●	●	●	●	●	●	105,00
897	Wireless charging and connection via Bluetooth certain countries only not in conjunction with code 899 only in conjunction with code P27/P59 or 950	●	●	●	●	●	●	210,00
899	Multifunction telephony certain countries only not in conjunction with code 897 only in conjunction with code (P27/P59 or 950) and 270, 274	●	●	●	●	●	●	514,50
8R2	Complete winter (M+S) wheel-and-tyre assembly x 4 certain countries only and only in conj. With code 651 or 652	●	●	●	●	●	●	2467,50
8R5	Complete winter wheel - AMG spoked design, 18" certain countries only and only in conj. With code 651 or 652	●	●	●	●	●	●	2205,00
913	Air conditioning preinstallation for hot countries Certain countries only	○	-	-	-	-	-	0,00
916	Fuel tank with increased capacity	-	-	-	S	-	S	0,00
		-	-	-	-	●	-	52,50
922	Reduced power version certain countries only (524L/528L/810L)	-	-	○	-	-	-	0,00
926	Emission control system with EU4 technology Certain countries only	○	○	○	○	○	○	0,00
927	EU6 emissions standard Certain countries only	○	○	○	○	○	○	0,00
928	EU5 emission standard Certain countries only	-	○	○	○	○	○	0,00
931	Tandem interior mirror Only in conjunction with Code U63 (only LHD)	○	○	○	○	○	○	0,00
933	Add.parts f.telematic alarm identific. certain countries only	-	-	●	-	-	-	315,00
936	Cylinder cut-off certain countries only only in conjunction with Code 429 (cert. Countries only)	-	○	○	-	-	-	0,00
942	Load compartment package certain countries only Only in conjunction with Code U35 Only in conjunction with Code U35 and Code U40	U ★	U ★	U ★	U ★	U ★	U ★	157,50
945	Emission control system China only in conjunction with code 830	-	○	○	○	○	○	0,00
968	COC document EU6 without registration certificate part II Certain countries only	○	○	○	○	○	○	0,00
969	COC document EU6 with registration certificate part II Certain countries only	○	○	○	○	○	○	0,00
981	Omission of vehicle registration document certain countries only	○	○	○	○	○	○	0,00
986	Identification no. (US-VIN) Certain countries only	○	○	○	○	○	○	0,00
989	Identification label under windshield certain countries only	○	○	○	○	○	○	0,00
B08	Fanfares for Asia	○	○	○	○	○	○	0,00
B12	Tyre-change toolkit Certain countries only	●	●	●	●	●	●	31,50

14/5/2018 Optional extras for the A-Class
Valid from 22.06.2018 (809)

● available at extra charge ○ available at no extra charge U annotations existing
S standard equipment - not available

A Limousine

177.003 A 180 d
177.084 A 180
177.087 A 200
177.045 A 220 4MATIC
177.046 A 250
177.047 A 250 4MATIC

LLP

L	Left-hand drive i.c. w. Code 690 or 669	○	○	○	○	○	○	0,00
B18	Spectacles compartment for driver only in conjunction with code U62	○	○	○	○	○	○	0,00
B24	remote control for auxiliary heater Certain countries only Only in conjunction with Code 228, 270 and 274 and in cert. countries with 362	●	●	●	●	●	●	210,00
B51	TIREFIT Certain countries only Not in conjunction with Code R66 i.V.m. Code PYA	●	●	●	●	●	●	0,00
B59	DYNAMIC SELECT	S	S	S	S	S	S	0,00
B63	Sporty engine sound not valid only in conjunction with code 950 and (355 or 859)	-	-	U	○	○	○	0,00
H15	wood linden black open-pored trim only in conjunction with code P59 or (950 but not with P19) i.V.m. Code P39	●	●	●	●	●	●	273,00
H23	Brown open-pore walnut wood trim only in conjunction with code P59/P34	●	●	●	●	●	●	115,50
H44	Light longitudinal-grain aluminium trim only in conjunction with code 950/P59 i.V.m. Code P19 i.V.m. Code P34+950 i.V.m. Code P39 oder 159A	○	○	○	○	○	○	273,00
H45	Light linear-grain aluminium trim only in conjunction with code P59 or (950 but not with P19) i.V.m. Code P39 oder 159A	○	○	○	○	○	○	157,50
H55	Trim in dark carbon-fibre look only in conjunction with code P59	○	○	○	○	○	○	0,00
H59	Carbon-fibre-look trim only in conjunction with code P59	○	○	○	○	○	○	0,00
K32	Active Lane Change Assist certain countries only and only in conjunction with code 266 and 365	○	○	○	○	○	○	0,00
K33	Extended automatic Re-start in traffic jams certain countries only and only in conjunction with code 233, 235 and 365	○	○	○	○	○	○	0,00
K34	Route-based speed adaptation certain countries only and only in conjunction with code 233 and 365	○	○	○	○	○	○	0,00
L3A	Multifunction sports steering wheel not in conjunction with code (P59/950) and 233/239 and 443	S	S	S	S	S	S	0,00
L3B	Multifunction sports steering wheel in nappa leather not in conjunction with code 950 (except with code 460) only in conjunction with code 428 and 443	U	U	U	U	U	U	0,00
L3E	Leather multifunction sports steering wheel not in conjunction with Code 443 or 950 i.V.m. Code P59 i.V.m. Code PYB/PYD	○	○	○	○	○	○	0,00
L5C	Multifunction sports steering wheel in nappa leather not in conjunction with code 443 only in conjunction with code 950	○	○	○	○	○	○	0,00
L51	Multifunction sports steering wheel in nappa leather / DINAMICA microfibre not in conjunction with code 443 only in conjunction with code 950 and (426/429)	●	●	●	●	●	●	241,50
R00	40.6 cm (16-inch) steel wheels with 10-hole trim in certain countries only in conjunction with code R01 or R05 Not in conjunction with Code 950 or U29	S	S	S	-	-	-	0,00
R01	Summer tyres only in conjunction with code 01R/643/R00/R11/R30/R31/R55/R78/643/72R/76R/RQS/RQT/RVG/RVK	○	○	○	○	○	○	0,00
R02	All season tyres certain countries only and only in conjunction with Code (01R/R31/643/72R/76R/R11)	-	-	-	●	●	●	115,50

14/5/2018 Optional extras for the A-Class
Valid from 22.06.2018 (809)

● available at extra charge ○ available at no extra charge U annotations existing
S standard equipment - not available

		A Limousine						LLP
		177.003 A 180 d	177.084 A 180	177.087 A 200	177.045 A 220 4MATIC	177.046 A 250	177.047 A 250 4MATIC	
L	Left-hand drive	○	○	○	○	○	○	0,00
R03	Sports tyres only in conjunction with Code 01R/R31 only in conjunction with Code RQS/RQT	○	○	○	○	○	○	0,00
R05	Tyres with optimised rolling resistance Certain countries only and only in conj. With code (R00/R30/R78)	○	○	○	○	○	○	0,00
R11	43.2 cm (17-inch) 5-twin-spoke light-alloy wheels Not in conjunction with Code 950 i.V.m. Code P27 i.V.m. Code P55 i.V.m. Code P59 i.V.m. Code PYB i.V.m. Code PYD/PYF	- ● - ● ○ ● ● - -	- ● - ● ○ ● ● - -	- ● - ● ○ ● ● - -	● - ● ○ ○ ○ ○ -	● - ● ○ ○ ○ ○ ○	● - ● ○ ○ ○ ○ ○	682,50 997,50 210,00 525,00 0,00 210,00 315,00 0,00 210,00
R30	40.6 cm (16") multi-spoke light-alloy wheels not in conjunction with code 950 i.V.m. Code P27 i.V.m. Code P59 i.V.m. Code PYB	● ● ○ ●	● ● ○ ●	● ● ○ ●	- - - -	- - - -	- - - -	682,50 210,00 0,00 210,00
R31	45.7 cm (18") 5-twin-spoke light-alloy wheels not in conjunction with code 950 i.V.m. Code P27 i.V.m. Code P55 i.V.m. Code P59 i.V.m. Code PYF	- ● ● - ○ ● ●	- ● ● - ○ ● ●	- ● ● - ○ ● ●	● - ● ○ ○ ○ ○	● - ● ○ ○ ○ ○	● - ● ○ ○ ○ ○	1312,50 1627,50 1155,00 840,00 0,00 840,00 840,00
R55	48.3 cm (19-inch) 5-twin-spoke light-alloy wheels not in conjunction with code 950 i.V.m. Code P27 i.V.m. Code P55 i.V.m. Code P59 i.V.m. Code PYF	- ● - ● ● ● ●	- ● - ● ● ● ●	- ● - ● ● ● ●	● - ● ○ ○ ○ ○	● - ● ○ ○ ○ ○	● - ● ○ ○ ○ ○	1785,00 2100,00 1312,50 1627,50 472,50 1312,50 1312,50
R66	Run-flat tyres Not in conjunction with Code R05, B51, 645 only in conjunction with code with 643/72R/76R/R11/01R/R31/RQS or RQT	●	●	●	●	●	●	231,00
R78	40.6 cm (16-inch) 5-twin-spoke light-alloy wheels Not in conjunction with Code 950 i.V.m. Code P27/P59 only available i.V.m. Code PYB	● ○ ○	● ○ ○	● ○ ○	- - -	- - -	- - -	472,50 0,00 0,00
RQS	45.7 cm (18-inch) AMG 5-twin-spoke light-alloy wheels not in conjunction with code P55 i.V.m. Code 950 i.V.m. Code P27 i.V.m. Code P59 only available i.V.m. Code PYH	- ● ○ - ● ○	- ● ○ - ● ○	- ● ○ - ● ○	● - ○ - ○ ○	● - ○ - ○ ○	● - ○ - ○ ○	1575,00 1890,00 0,00 1102,50 1417,50 1102,50 0,00
RQT	45.7 cm (18-inch) AMG 5-twin-spoke light-alloy wheels i.V.m. Code 950 i.V.m. Code P27 i.V.m. Code P55 i.V.m. Code P55+950	- ● - ● ○	- ● - ● ○	- ● - ● ○	● - ○ - ○	● - ○ - ○	● - ○ - ○	1785,00 2100,00 210,00 1312,50 1627,50 472,50 0,00

Valid from 22.06.2018 (809)

● available at extra charge ○ available at no extra charge U annotations existing
 S standard equipment - not available

		A Limousine						LLP
		177.003 A 180 d	177.084 A 180	177.087 A 200	177.045 A 220 4MATIC	177.046 A 250	177.047 A 250 4MATIC	
L	Left-hand drive i.V.m. Code P59 only available i.V.m. Code PYH+P55	●	○	○	○	○	○	0,00
		○	○	○	○	○	-	1312,50
		○	○	○	○	○	-	0,00
RVG	48.3 cm (19-inch) AMG multi-spoke light-alloy wheels not in conjunction with code R66 i.V.m. Code 950 i.V.m. Code P27 Optional wheel for AMG Line (PYH), only with PYH, not icw Night package (P55) i.V.m. Code P55+P59 i.V.m. Code P59	-	●	●	●	●	●	2047,50
		●	●	●	-	-	-	2362,50
		●	●	●	●	●	●	630,00
		-	-	-	●	●	●	1575,00
		●	●	●	-	-	-	1890,00
		●	●	●	●	●	●	735,00
		●	●	●	●	●	●	1575,00
RVI	48.3 cm (19-inch) AMG multi-spoke light-alloy wheels only in conjunction with code P19 and R01	○	○	○	○	○	○	0,00
RVK	48.3 cm (19-inch) AMG multi-spoke light-alloy wheels not in conjunction with code R66 i.V.m. Code 950 i.V.m. Code P27 Optional wheel for AMG Line (PYH) and Night package (P55), only icw PYH+P55 i.V.m. Code P55+P59 i.V.m. Code P59 i.V.m. Code PYH+P55	-	●	●	●	●	●	2415,00
		●	●	●	-	-	-	2730,00
		●	●	●	●	●	●	997,50
		-	-	-	●	●	●	1942,50
		●	●	●	-	-	-	2257,50
		●	●	●	●	●	●	1102,50
		●	●	●	●	●	●	1942,50
		●	●	●	●	●	●	997,50
U00	Velour floor mats for driving instruction vehicles only in conjunction with code U63 only LHD	○	○	○	○	○	○	0,00
U01	Rear belt status indication in the instrument display Certain countries only	○	○	○	○	○	○	0,00
U10	Automatic deactivation of front passenger airbag certain countries only i.V.m. Code 51B	U	U	U	U	U	U	0,00
		★	★	★	★	★	★	0,00
		○	○	○	○	○	○	0,00
U12	Velour floor mats certain countries only Not in conjunction with Code 950 or U26 i.V.m. Code PYA	●	●	●	●	●	●	0,00
		○	○	○	○	○	○	0,00
U19	MBUX augmented reality for navigation certain countries only only in conjunction with code 365, 859 only i.V.m Advantage (PYM), Premium (PYN) or Premium Plus (PYO)	●	●	●	●	●	●	262,50
U22	4-way lumbar support not in conjunction with code 409 Only in conjunction with Code U59 i.V.m. Code PYO	●	●	●	●	●	●	162,75
		○	○	○	○	○	○	0,00
U25	Illuminated door sill panels with "Mercedes-Benz" lettering Only in conjunction with Code U62 i.V.m. Code PYN/PYO, not available as single option	●	●	●	●	●	●	157,50
		○	○	○	○	○	○	0,00
U26	AMG floor mats certain countries only not in conjunction with Code U12 or P19 Only in conjunction with Code 950	○	○	○	○	○	○	0,00
U29	Braking system with larger brake discs on the front axle only in conjunction with code PAD	○	○	○	○	○	○	0,00
U35	12 V socket in load area Only in conjunction with Code 942	○	○	○	○	○	○	0,00
U40	Partition net only i.V.m Code 942 and certain countries only	●	●	●	●	●	●	157,50
U54	TORSION BEAM AXLE certain countries only and only in conjunction with Code (R00/R30/R78/643/72R/76R/R11/01R/R31/RQS or RQT) not in conjunction with code 459	S	○	○	-	-	-	0,00
U55	MULTI-LINK-AXLE	U	○	○	S	S	S	0,00

● available at extra charge ○ available at no extra charge U annotations existing
 S standard equipment - not available

		A Limousine						LLP
		177.003 A 180 d	177.084 A 180	177.087 A 200	177.045 A 220 4MATIC	177.046 A 250	177.047 A 250 4MATIC	
L	Left-hand drive certain countries only and only in conjunction with Code (01R/R31/R55/RQS/RQT/RVG or RVK) only in conjunction with code 459	○	○	○	○	○	○	0,00
U60	Pedestrian protection Certain countries only	○	○	○	○	○	○	0,00
U64	Full driving school package only in conjunction with Code U63 only LHD	●	●	●	●	●	●	1260,00
U65	Additional exterior mirror right and left only in conjunction with code U63 only LHD	●	●	●	●	●	●	126,00
U66	Floormats special model certain countries only not in conjunction with Code U12 or U26 only in conjunction with Code P19	○	○	○	○	○	○	0,00
U67	230 V socket in the rear certain countries only not in conjunction with code U80	●	●	●	●	●	●	120,75
U79	BlueTEC diesel emission control system including AdBlue® reservoir certain countries only	○	-	-	-	-	-	0,00
U80	115 V socket certain countries only	●	-	●	●	●	●	120,75
Z83	Activation hill-start assist driving school Only in conjunction with Code U64	○	○	○	○	○	○	0,00
Z97	Electronic interface for remote control certain countries only not in conjunction with code 810 or (550/554)	●	●	●	●	●	●	399,00