

Standard and special equipment

Model year :

801

Sales Release :

2020-06-03

Production Change :

2020-07-01

Legend

(*) Available at extra cost (○) available without additional charge (S) standard equipment (-) not available (L) Left hand drive only (R) Right hand drive only (NS)

Please note that central restrictions are displayed. Markets may have specific deviation if any. Codes could be valid for certain countries only.

Code	equipment	Restrictions	213004 E 220 d TAXI	LLP
5U6	AMG-specific radiator grille, darkened		-	472,50
			○	0,00
		Not in conjunction with 725		
		Only in conjunction with P60		
		Code at these BM not valid	*	
B28	AMG Exterior Carbon-Fibre package II		-	1.837,50
			-	1.260,00
		Not in conjunction with U47		
		Only in conjunction with U93		
P31	Mercedes-AMG exterior		-	2.940,00
			-	2.467,50
			-	0,00
		Includes codes 725 [720]+772		
		Includes codes 772+U47		
P60	AMG Night package		-	997,50
		Includes codes 720+840 [U50]		
		Includes codes 840 [U50]		
		Not in conjunction with 725		
		i.V.m. Code U50	-	787,50
P60	AMG Night package		-	997,50
U47	AMG spoiler lip		●	367,50
			-	0,00
		Available only as part of (P31)		
		Not in conjunction with 001A/101A	*	
		Not in conjunction with 82R	*	
		Not in conjunction with B28/U93		
		Not in conjunction with H56/P23/P75	*	
		Only in conjunction with [772/P31]	*	
U70	red-painted brake callipers		-	0,00
		Available only as part of (P71)		
		Only in conjunction with P71		
555	AMG Performance seats		-	2.047,50
		Not in conjunction with 23U/292/432/866/902/E02/P20/P68/PBR		
L6G	AMG Performance steering wheel in DINAMICA microfit		-	514,50
		Not in conjunction with 443		
		Only in conjunction with U88		
L6J	AMG Performance steering wheel in nappa leather		-	0,00
L6K	AMG Performance steering wheel in nappa leather / DINAMICA		-	441,00
		Only in conjunction with U88		
P29	Mercedes-AMG interior		-	2.121,00
			-	0,00
		Includes codes 891+U09+U26		
PBX	AMG Performance Seat Package		-	2.047,50
		Includes codes 555+873		
		Not in conjunction with 23U/275/292/401/432/443/61U/65U/866/902/E02/P20/P68/PBR/PBZ/U38		
		Only in conjunction with 51U+621A+P65+U09		
PBZ	AMG Performance Seat package High-End		-	5.848,50
		Includes codes 275+555+873 [401]		
		Not in conjunction with 23U/292/432/866/902/E02/P20/P65/P68/PBR		
		Not in conjunction with 621A/PBX		
		Only in conjunction with P49		
250	AMG Driver's package		-	1.995,00
		Not in conjunction with R05/R06/R66		
		Only in conjunction with R01		
250	AMG Driver's package		-	1.995,00

		Not in conjunction with R05/R06/R66		
		Only in conjunction with R01		
250	AMG Driver's package		–	1.995,00
		Not in conjunction with R05/R06/R66		
		Only in conjunction with R01		
421	AMG SPEEDSHIFT TCT 9G		–	0,00
421	AMG SPEEDSHIFT MCT 9G		–	0,00
B59	AMG DYNAMIC SELECT		–	0,00
P71	AMG DYNAMIC PLUS package		–	1.942,50
		Includes codes L6G [L6J]+U70+U88		
U78	AMG performance exhaust system, selectable		–	1.470,00
		i.V.m. Code PYC	–	0,00
P87	designo interior in macchiato beige / saddle brown		●	5.145,00
		Includes codes 275+287+421+975A+U04+U38	*	
		Not in conjunction with 001A	*	
		Not in conjunction with 101A	*	
		Not in conjunction with 248	*	
		Not in conjunction with 336	*	
		Not in conjunction with 450/601A/811A/824A/837/H73/L5C/P29/U26	*	
		Not in conjunction with 51U/P65/U09	*	
		Not in conjunction with H56	*	
		Not in conjunction with P75	*	
		Not in conjunction with U12	*	
		Only in conjunction with P49	*	
		Only in conjunction with U22	*	
		i.V.m. Code P22	●	3.727,50
P55	Night package		●	1.207,50
			–	472,50
		Includes codes 720+840 [U50]		
		Includes codes 840 [U50]	*	
		Not in conjunction with 001A/101A/H56/P75		
		Not in conjunction with 01R/R32/R97/RVQ/RZl	*	
		Not in conjunction with 15R/645		
		Not in conjunction with 22R	*	
		Not in conjunction with 341/342/725		
		Not in conjunction with 978		
		Not in conjunction with P23	*	
		Not in conjunction with R11	*	
		Not in conjunction with R43	*	
		Not in conjunction with RRD	*	
		Not in conjunction with RSJ		
		Only in conjunction with U29		
		Only in conjunction with [R32/R90/RSK/RSW]		
		i.V.m. Code P15+U50	●	997,50
		i.V.m. Code P31+840	●	787,50
		i.V.m. Code P31+U50	●	577,50
		i.V.m. Code P15+U50	–	262,50
260	Omission of model plate on boot lid		○	0,00
260	Deletion of model plate on boot lid		○	0,00
261	Omission of badge		○	0,00
231	Garage door opener		●	236,25
		Not in conjunction with 337	*	
		Only in conjunction with P49	*	
871	HANDS-FREE ACCESS		○	0,00
		Available only as part of (P17)	*	
		Not in conjunction with 978		
		Only in conjunction with P17	*	
881	Boot lid convenience closing feature		●	551,25
		for certain countries only	*	
		i.V.m. Code P17	○	0,00
882	Interior monitoring system		○	0,00
		Not in conjunction with 336	*	
883	Power closing		●	577,50
		Not in conjunction with 001A	*	
		Not in conjunction with 101A	*	
		Not in conjunction with H56	*	
		Not in conjunction with P75	*	
887	Independent boot locking		●	26,25
		not in conjunction with 830		
889	KEYLESS-GO		●	735,00
		Not in conjunction with 978		
		i.V.m. Code P17	○	0,00

B67	Vehicle key in high-gloss black with ornamental surrou		●	105,00
		Not in conjunction with 934	*	
		Not in conjunction with B68	*	
		Not in conjunction with U32	*	
B68	Vehicle key in high-gloss white with ornamental surrou		●	105,00
		Not in conjunction with 934	*	
		Not in conjunction with B67	*	
		Not in conjunction with U32	*	
P17	KEYLESS-GO Comfort package		●	1.270,50
			–	840,00
		Includes codes 871+881+889	*	
		Includes codes 871+889		
		Not in conjunction with 978		
		Expected to be available from September 2020	*	
		i.V.m. Code PYN	○	0,00
		i.V.m. Code PYO	○	0,00
297U	designo selenite grey magno		●	2.940,00
		Only in conjunction with 524	*	
799U	designo diamond white bright		●	1.732,50
996U	designo hyacinth red metallic		●	1.291,50
197U	obsidian black		●	913,50
831U	graphite grey		●	913,50
859U	Mojave silver		●	913,50
890U	cavansite blue		●	913,50
922U	high-tech silver		●	913,50
992U	selenite grey		●	913,50
040U	black		○	0,00
149U	polar white		●	315,00
413	Panoramic sliding sunroof		●	1.858,50
		Not in conjunction with 001A/101A/H56/P75		
		Not in conjunction with 05Z/06Z/333/336/356	*	
		Not in conjunction with 10Z/11Z/12Z/962/Z30	*	
		Not in conjunction with 19U/334/335/337/341/342/344/450/623U/837/934/938	*	
		Not in conjunction with 248	*	
		Not in conjunction with 24Z/414/50Z/B12	*	
		Not in conjunction with 4R3/844		
		Not in conjunction with 651/652		
		Not in conjunction with 965	*	
		Not in conjunction with 970/974/975	*	
		Not in conjunction with 978		
		Not in conjunction with Z87	*	
		Not in conjunction with Z90	*	
		Only in conjunction with B63		
		Only in conjunction with [965]		
		i.V.m. Code PYO	○	0,00
414	Sliding sunroof		●	1.181,25
		Not in conjunction with 001A/101A/H56/P75		
		Not in conjunction with 10Z/11Z/12Z/962/Z30/Z90	*	
		Not in conjunction with 24Z/413/50Z/B12	*	
		Not in conjunction with 970/974/975	*	
		Not in conjunction with 978		
		Not in conjunction with Z87	*	
		Only in conjunction with [965/B63]		
		Only for left hand drive	*	
720	Roof rails in black		–	0,00
		Available only as part of (P55)		
		Available only as part of (P60)		
		Not in conjunction with 001A/101A/H56/P75		
		Not in conjunction with 15R		
		Not in conjunction with 341/342		
		Not in conjunction with 645		
		Not in conjunction with 725		
		Not in conjunction with P23		
		Not in conjunction with RRD		
		Only in conjunction with P55		
		Only in conjunction with P60		
725	Polished aluminium roof rails		–	0,00
		Available only as part of (P31)		
		Not in conjunction with 5U6/P60		
		Not in conjunction with 720/U50		
		Not in conjunction with P55		
E22	Alustyle Easy-Fix II rail carrier		–	236,25

			●	210,00
632	LED High Performance headlamps		○	0,00
		Not in conjunction with 628/642/P35	*	
E72	Surround lighting with projection of brand logo		●	131,25
		Not in conjunction with 001A	*	
		Not in conjunction with 101A	*	
		Not in conjunction with H56	*	
		Not in conjunction with P75	*	
		Only in conjunction with 891	*	
		Only for left hand drive		
P35	MULTIBEAM LED		●	1.365,00
		Includes codes 628+642	*	
		Not in conjunction with 608/632	*	
		i.V.m. Code PYN/PYO	○	0,00
550	Trailer coupling with ESP[®] trailer stabiliser		●	1.008,00
		Not in conjunction with 489		
		Not in conjunction with 4R3/844		
		Not in conjunction with 601A/811A/824A/H73/L5C/P29/P31/RRD/U26		
		Not in conjunction with 651/652		
		Not in conjunction with 978		
		Only for left hand drive		
P54	URBAN GUARD vehicle protection		●	493,50
		Includes codes 551+882	*	
		Not in conjunction with 336	*	
		Not in conjunction with P82	*	
P82	URBAN GUARD vehicle protection Plus		●	703,50
		Includes codes 551+882	*	
		Not in conjunction with 336	*	
		Not in conjunction with P54	*	
		i.V.m. Code 34U	●	598,50
E16	Rim lock set		●	52,50
645	M+S winter tyres, set of 4		●	204,75
		Not in conjunction with 1R7	*	
		Not in conjunction with 22R	*	
		Not in conjunction with 4R3		
		Not in conjunction with 4R6/P55/U50		
		Not in conjunction with 651	*	
		Not in conjunction with 652	*	
		Not in conjunction with 720		
		Not in conjunction with 776		
		Not in conjunction with R01	*	
		Not in conjunction with R03	*	
		Not in conjunction with R06	*	
		Only in conjunction with 15R+725		
		Only in conjunction with R32		
		Only in conjunction with [R90/RSW/R2I]		
R01	Summer tyres		○	0,00
		Not in conjunction with 645	*	
		Not in conjunction with R03	*	
		Not in conjunction with R05/R66		
		Not in conjunction with R06		
R03	Sports tyres		○	0,00
		Not in conjunction with 645/R01	*	
		Not in conjunction with R32		
		Not in conjunction with R90/RRD		
		Only in conjunction with 22R	*	
		Only in conjunction with U29		
		Only in conjunction with [RSJ/RSK]		
		only in conjunction with R06 and R0K, RQJ, 22R or R32	*	
R06	Noise reduced tyre with foam absorber		○	0,00
		Not in conjunction with 001A/101A/601A/811A/824A/H73/L5C/P29/P75/U26		
		Not in conjunction with 01R/82R/R38		
		Not in conjunction with 19U/248/337/341/342/450/623U/965		
		Not in conjunction with 250/R05		
		Not in conjunction with 645	*	
		Not in conjunction with B51		
		Not in conjunction with H56		
		Not in conjunction with R01		
		Not in conjunction with R32		
		Not in conjunction with R43		
		Not in conjunction with R66		
		Only in conjunction with [22R]	*	

		Only in conjunction with [52R/61R/R48/RVQ/RVR]	*	
		Only for left hand drive		
R66	run-flat tyres		●	294,00
			–	0,00
		Not in conjunction with 250/R01		
		Not in conjunction with 4R3		
		Not in conjunction with 651/652		
		Not in conjunction with 978		
		Not in conjunction with B51	*	
		Not in conjunction with R06		
		Not in conjunction with RSJ/RSK		
		Only in conjunction with R05+RTA		
		i.V.m. Winterkompletträder	●	588,00
		i.V.m. Code R05	–	294,00
		i.V.m. Code PYA	●	241,50
		i.V.m. Code 3R6	○	0,00
		i.V.m. diversen Bereifungen	○	0,00
RRD	48.3 cm (19-inch) AMG 10-spoke light-alloy wheels		●	210,00
		Not in conjunction with 001A	*	
		Not in conjunction with 101A	*	
		Not in conjunction with 1R7		
		Not in conjunction with 248/337/341/342/485/550/623U/811/934/965		
		Not in conjunction with 645		
		Not in conjunction with 651/652		
		Not in conjunction with 720		
		Not in conjunction with 978		
		Not in conjunction with H56	*	
		Not in conjunction with P23/P55/P75/U50	*	
		Not in conjunction with R03	*	
		Not in conjunction with R06	*	
		Only in conjunction with 725		
		Only in conjunction with 776+R01		
		Only in conjunction with 7U0+P31	*	
		Only in conjunction with U29		
RRR	50.8 cm (20-inch) AMG 5-twin-spoke light-alloy wheels		–	1.312,50
		Not in conjunction with 645		
		Only in conjunction with R01		
		i.V.m. Code P55	–	787,50
RSJ	45.7 cm (18-inch) AMG 5-twin-spoke light-alloy wheels		○	0,00
		Not in conjunction with 001A/101A		
		Not in conjunction with 645/P23/P55/P75/U50		
		Not in conjunction with H56		
		Not in conjunction with P15		
		Not in conjunction with R66		
		Only in conjunction with [772]		
		Only in conjunction with [P31]		
RSK	45.7 cm (18-inch) AMG 5-twin-spoke light-alloy wheels		○	0,00
		Not in conjunction with 001A/101A		
		Not in conjunction with 645/P23/P75		
		Not in conjunction with H56		
		Not in conjunction with P15		
		Not in conjunction with R66		
		Only in conjunction with [772]		
		Only in conjunction with [P31]		
		Only in conjunction with (P55)		
RSP	45.7 cm (18-inch) AMG 5-twin-spoke light-alloy wheels		●	315,00
RSW	5-twin-spoke 48.3 cm (19-inch) AMG light-alloy wheels		●	315,00
		Not in conjunction with 001A	*	
		Not in conjunction with 101A	*	
		Not in conjunction with H56	*	
		Not in conjunction with P23/P75	*	
		Not in conjunction with R03	*	
		Not in conjunction with R06	*	
		Only in conjunction with U29		
		Only in conjunction with [772/P31]	*	
		Only for left hand drive		
		i.V.m. Code P31+P55	○	0,00
RTA	48.3 cm (19-inch) AMG 5-twin-spoke light-alloy wheels		–	0,00
		Not in conjunction with R06		
RTG	48.3 cm (19-inch) AMG 5-twin-spoke light-alloy wheels		–	840,00
			–	0,00
		Not in conjunction with 645		

		Only in conjunction with R01		
RVQ	50.8 cm (20-inch) AMG multi-spoke alloy wheels		–	3.885,00
			●	2.887,50
			–	2.152,50
			–	945,00
		Not in conjunction with 19U/248/337/341/342/344/450/623U/934/938/965/B51/P55/U50	*	
		Not in conjunction with 4R3		
		Not in conjunction with 651/652		
		Not in conjunction with 978		
		Not in conjunction with R03	*	
		Not in conjunction with R05/R06/R66		
		Only in conjunction with R01		
		Only in conjunction with R66	*	
		Only in conjunction with U29		
		i.V.m. Code P31	●	945,00
RVR	50.8 cm (20-inch) AMG multi-spoke alloy wheels		–	3.885,00
			●	3.202,50
			–	2.467,50
			–	1.260,00
		Not in conjunction with 19U/248/337/341/342/344/450/623U/934/938/965/B51	*	
		Not in conjunction with 4R3		
		Not in conjunction with 651/652		
		Not in conjunction with 978		
		Not in conjunction with R03	*	
		Not in conjunction with R05/R06/R66		
		Only in conjunction with R01		
		Only in conjunction with R66	*	
		Only in conjunction with U29		
		i.V.m. Code P55	●	2.467,50
		i.V.m. Code P55	–	2.152,50
		i.V.m. Code P31	●	1.260,00
		i.V.m. Code P31+P55	●	945,00
RZI	48.3 cm (19-inch) AMG 5-twin-spoke light-alloy wheels		○	0,00
		Not in conjunction with 001A	*	
		Not in conjunction with 101A	*	
		Not in conjunction with H56	*	
		Not in conjunction with P23/P55/P75/U50	*	
		Not in conjunction with R03	*	
		Not in conjunction with R06	*	
		Only in conjunction with U29		
		Only in conjunction with [772/P31]	*	
		Only for left hand drive		
RZS	50.8 cm (20-inch) AMG 5-twin-spoke light-alloy wheels		–	1.680,00
		Not in conjunction with R05/R06/R66		
		Only in conjunction with R01		
RZT	50.8 cm (20-inch) AMG 5-twin-spoke light-alloy wheels		–	1.155,00
		Not in conjunction with R05/R06/R66		
		Only in conjunction with R01		
01R	45.7 cm (18-inch) 5-twin-spoke light-alloy wheels		●	735,00
			–	210,00
		Not in conjunction with 601A/811A/824A/H73/L5C/P23/P29/P55/R06/U26/U50	*	
		Not in conjunction with R03	*	
		Only in conjunction with P15	*	
		Only in conjunction with U29		
08R	43.2 cm (17-inch) multi-spoke light-alloy wheels		●	210,00
		Not in conjunction with 001A	*	
		Not in conjunction with 101A	*	
		Not in conjunction with 601A/811A/824A/H73/L5C/P15/P29/P75/U26/U29	*	
		Not in conjunction with H56	*	
		Not in conjunction with R03	*	
		Not in conjunction with R06	*	
		Only in conjunction with P23	*	
15R	48.3 cm (19-inch) multi-twin-spoke light-alloy wheels		–	0,00
		Not in conjunction with 720/P55/U50		
		Only in conjunction with 725		
22R	45.7 cm (18-inch) 5-twin-spoke light-alloy wheels		●	892,50
			–	210,00
		Not in conjunction with 645/P55/U50	*	
		Not in conjunction with 776/H73/P29/P31		
		Not in conjunction with R06		
		Only in conjunction with R01		
		Only in conjunction with U29		

		i.V.m. Code P15	–	892,50
		i.V.m. Code P23	–	892,50
22R	45.7 cm (18-inch) 5-twin-spoke light-alloy wheels		●	892,50
			–	210,00
		Not in conjunction with 645/P55/U50	*	
		Not in conjunction with 776/H73/P29/P31		
		Not in conjunction with R06		
		Only in conjunction with R01		
		Only in conjunction with U29		
		i.V.m. Code P15	–	892,50
		i.V.m. Code P23	–	892,50
52R	45.7 cm (18-inch) 5-twin-spoke light-alloy wheels		●	735,00
			–	0,00
		Not in conjunction with 001A	*	
		Not in conjunction with 101A	*	
		Not in conjunction with 601A/811A/824A/H73/L5C/P15/P29/P75/U26	*	
		Not in conjunction with H56	*	
		Not in conjunction with R03	*	
		Only in conjunction with P23	*	
		Only in conjunction with U29		
		for certain countries only		
61R	45.7 cm (18-inch) 10-twin-spoke light-alloy wheels		●	472,50
			–	210,00
		Not in conjunction with 001A	*	
		Not in conjunction with 101A	*	
		Not in conjunction with 601A/811A/824A/H73/L5C/P15/P29/P75/U26	*	
		Not in conjunction with H56	*	
		Not in conjunction with R03	*	
		Only in conjunction with P23	*	
		Only in conjunction with U29		
82R	45.7 cm (18-inch) 5-spoke light-alloy wheels		●	1.732,50
			–	1.155,00
			–	997,50
			–	735,00
			–	210,00
		Not in conjunction with 4R3/844		
		Not in conjunction with 601A/776/811A/824A/H73/L5C/P23/P29/P31/R06/U26	*	
		Not in conjunction with 651/652		
		Not in conjunction with 772		
		Not in conjunction with R03	*	
		Not in conjunction with U47	*	
		Only in conjunction with 7U0+P15	*	
		Only in conjunction with U29		
		i.V.m. Code P15	●	735,00
		i.V.m. Code P15	–	210,00
R10	45.7 cm (18-inch) 5-twin-spoke light-alloy wheels		○	0,00
		Not in conjunction with P23	*	
		Not in conjunction with R03	*	
		Not in conjunction with R06	*	
		Only in conjunction with U29		
R11	43.2 cm (17-inch) 5-twin-spoke light-alloy wheels		○	0,00
		Not in conjunction with 601A/811A/824A/H73/L5C/P23/P29/P55/U26/U29/U50	*	
		Not in conjunction with R03	*	
		Not in conjunction with R06	*	
		Only in conjunction with P15	*	
R32	45.7 cm (18-inch) 5-spoke light-alloy wheels		–	1.890,00
			●	892,50
			–	210,00
			–	0,00
		Not in conjunction with 601A/776/811A/824A/H73/L5C/P29/P31/R06/U26	*	
		Not in conjunction with P55/U50	*	
		Not in conjunction with R03	*	
		Only in conjunction with U29		
R38	45.7 cm (18-inch) 5-twin-spoke light-alloy wheels		●	735,00
			–	0,00
		Not in conjunction with 601A/811A/824A/H73/L5C/P23/P29/R06/U26	*	
		Not in conjunction with R03	*	
		Only in conjunction with P15	*	
		Only in conjunction with U29		
R43	43.2 cm (17-inch) 10-spoke light-alloy wheels		–	997,50
			●	210,00
		Not in conjunction with 459	*	

		Not in conjunction with 4R3/844		
		Not in conjunction with 776/H73/P29/P31/P55/R06/U29/U50	*	
		Not in conjunction with R03	*	
		i.V.m. Code P23	–	262,50
R48	43.2 cm (17-inch) 5-twin-spoke light-alloy wheels		●	210,00
		Not in conjunction with 601A/811A/824A/H73/L5C/P23/P29/U26/U29	*	
		Not in conjunction with R03	*	
		Only in conjunction with P15	*	
R69	43.2 cm (17-inch) 5-spoke light-alloy wheels		○	0,00
		Not in conjunction with 001A	*	
		Not in conjunction with 101A	*	
		Not in conjunction with 601A/811A/824A/H73/L5C/P15/P29/P75/U26/U29	*	
		Not in conjunction with H56	*	
		Not in conjunction with R03	*	
		Not in conjunction with R06	*	
		Only in conjunction with P23	*	
R90	48.3 cm (19-inch) 5-twin-spoke light-alloy wheels		●	1.732,50
			–	997,50
			–	840,00
		Not in conjunction with 601A/811A/824A/H73/L5C/P23/P29/U26	*	
		Not in conjunction with 776		
		Not in conjunction with R03	*	
		Not in conjunction with R06	*	
		Only in conjunction with P15	*	
		Only in conjunction with U29		
		Only in conjunction with P55		
		i.V.m. Code P55	●	997,50
R97	48.3 cm (19") 10-spoke light-alloy wheels		●	1.732,50
			–	997,50
		Not in conjunction with 645/H73/P29/P31		
		Not in conjunction with 978		
		Not in conjunction with P55/U50	*	
		Not in conjunction with R03	*	
		Not in conjunction with R06	*	
		Only in conjunction with R01		
		Only in conjunction with U29		
		Only for left hand drive		
		i.V.m. Code P15	–	1.732,50
		i.V.m. Code P23	–	1.732,50
R97	48.3 cm (19") 10-spoke light-alloy wheels		●	1.732,50
			–	997,50
		Not in conjunction with 645/H73/P29/P31		
		Not in conjunction with 978		
		Not in conjunction with P55/U50	*	
		Not in conjunction with R03	*	
		Not in conjunction with R06	*	
		Only in conjunction with R01		
		Only in conjunction with U29		
		Only for left hand drive		
		i.V.m. Code P15	–	1.732,50
		i.V.m. Code P23	–	1.732,50
B51	TIREFIT		●	52,50
		Not in conjunction with R05		
		Not in conjunction with R06		
		Not in conjunction with R66	*	
		Not in conjunction with RVQ/RVR	*	
		i.V.m. Code PYA	○	0,00
249	interior mirror and driver's exterior mirror automatical		○	0,00
		Available only as part of (P49)	*	
		Only in conjunction with P49	*	
313	Roller sunblinds in left and right rear doors		○	0,00
		Available only as part of (P09)	*	
		Not in conjunction with 840	*	
		Only in conjunction with P09	*	
		for certain countries only		
500	Electrically folding exterior mirrors		○	0,00
		Available only as part of (P49)	*	
		Only in conjunction with P49	*	
540	Electric sunblind for rear window		●	404,25
		Not in conjunction with 840	*	
		i.V.m. Code P09	○	0,00
597	Windscreen, heated		●	609,00

		Not in conjunction with 865/U19	*	
840	Heat-insulating dark-tinted glass		●	409,50
		Not in conjunction with 540/P09	*	
		Not in conjunction with 61U/65U	*	
		Not in conjunction with PAF/U50	*	
		i.V.m. Code P55/P60	○	0,00
		i.V.m. Code PYC/PYG/PYH	○	0,00
875	Heated windscreen washer system		●	178,50
		for certain countries only	*	
P09	Sun Protection package		●	588,00
			■	388,50
		Includes codes 313+540+543	*	
		Includes codes 313+543		
		Not in conjunction with 840	*	
P49	Mirror package		●	577,50
		Includes codes 249+500	*	
		i.V.m. Code PYM/PYN/PYO	○	0,00
PAF	Acoustic Comfort package		●	1.039,50
		Includes codes 596	*	
		Not in conjunction with 840	*	
U50	Omission of heat-insulating dark-tinted glass		○	0,00
		Not in conjunction with 001A/101A/H56/P75		
		Not in conjunction with 01R/R32/R97/RVQ/RZI	*	
		Not in conjunction with 15R/645		
		Not in conjunction with 22R	*	
		Not in conjunction with 341/342		
		Not in conjunction with 725		
		Not in conjunction with 840	*	
		Not in conjunction with 978		
		Not in conjunction with P23	*	
		Not in conjunction with R11	*	
		Not in conjunction with R43	*	
		Not in conjunction with RRD	*	
		Not in conjunction with RSJ		
		Only in conjunction with P55	*	
		Only in conjunction with P60		
		Only in conjunction with U29		
		Only in conjunction with [R32/R90/RSK/RSW]		
518	Media Interface cable kit		●	52,50
		not in conjunction with 460 or 494		
897	Wireless charging system for mobile devices		●	210,00
		Not in conjunction with 274	*	
		Not in conjunction with 301/899	*	
		Not in conjunction with 333	*	
		Not in conjunction with Z30	*	
		for certain countries only	*	
		i.V.m. Code PYB	○	0,00
U82	2 USB ports in the rear		●	47,25
		Not in conjunction with U67	*	
		i.V.m. Code PYA	○	0,00
01U	Preinstallation for Navigation Services		○	0,00
		Only in conjunction with 365	*	
		Only in conjunction with PBF	*	
		for certain countries only	*	
355	Extended MBUX functions		○	0,00
365	Hard-disc navigation		●	577,50
		i.V.m. Code PBF	○	0,00
367	Preinstallation for Live Traffic Information		○	0,00
PBF	Navigation Connectivity package		●	682,50
		Includes codes 362	*	
		Only in conjunction with 01U	*	
		Only in conjunction with 365	*	
		i.V.m. Code PYA	○	0,00
537	Digital radio		○	0,00
79B	Preinstallation for digital radio		○	0,00
865	TV receiver		●	1.039,50
		Not in conjunction with 335	*	
		Not in conjunction with 548	*	
		Not in conjunction with 597	*	
		Not in conjunction with 978		
		Only in conjunction with 549+868	*	
		for certain countries only	*	

866	Preinstallation for entertainment and comfort features		●	178,50
		Not in conjunction with 555/PBX		
		Not in conjunction with PBZ		
810	Burmester® surround sound system		●	892,50
		Not in conjunction with 001A/101A/H56/P75		
		Not in conjunction with 05Z/06Z/333/336/356		
		Not in conjunction with 10Z/11Z/12Z/962/Z30/Z90	*	
		Not in conjunction with 24Z/50Z/B12	*	
		Not in conjunction with 811	*	
		Not in conjunction with 970/974/975	*	
		Not in conjunction with 978		
		Not in conjunction with Z87	*	
		Only in conjunction with [965/B63]		
		i.V.m. Code PYO	○	0,00
811	Burmester® high-end 3D surround sound system		●	5.145,00
		Not in conjunction with 001A/101A	*	
		Not in conjunction with 05Z/06Z/19U/333/334/335/337/341/342/344/356/450/623U/837/934/938/P75	*	
		Not in conjunction with 10Z/11Z/12Z/962/Z30	*	
		Not in conjunction with 248	*	
		Not in conjunction with 24Z/50Z/77B/810/970/974/975/B12	*	
		Not in conjunction with 336/H56	*	
		Not in conjunction with 489		
		Not in conjunction with 601A/811A/824A/H73/L5C/P29/P31/RRD/U26		
		Not in conjunction with 965	*	
		Not in conjunction with Z87	*	
		Not in conjunction with Z90	*	
		Only in conjunction with 287	*	
		Only in conjunction with B63		
		Only for left hand drive		
		i.V.m. Code PYO	●	4.252,50
14U	Smartphone Integration		●	420,00
		Only in conjunction with 16U+17U	*	
		for certain countries only	*	
380	Car telephony		●	619,50
		Only in conjunction with 274		
		Code at these BM not valid	*	
899	Multifunction telephony		●	514,50
		Not in conjunction with 301/897	*	
		Not in conjunction with 333	*	
		Not in conjunction with Z30	*	
		Only in conjunction with 274	*	
		for certain countries only	*	
21U	Dash cam		●	210,00
543	Pull-out sun visor		●	99,75
		Available only as part of (P09)	*	
		Not in conjunction with 840	*	
		Only in conjunction with P09	*	
		only in conjunction with 460 or 494		
		i.V.m. Code P09	○	0,00
730	Centre console in light brown open-pore ash wood		●	157,50
		Not in conjunction with 001A	*	
		Not in conjunction with 101A	*	
		Not in conjunction with 656/728/737/764	*	
		Not in conjunction with 732	*	
		Not in conjunction with 736/H06/H16/H32/H41/H64/H78	*	
		Not in conjunction with 784	*	
		Not in conjunction with H29	*	
		Not in conjunction with H56	*	
		Not in conjunction with H73	*	
		Not in conjunction with L2D	*	
		Not in conjunction with P75	*	
		Only in conjunction with H09	*	
		i.V.m. Code PYC/PYE/PYG/PYH	●	52,50
		i.V.m. Code PYF	○	0,00
U09	Dashboard and door beltlines in ARTICO man-made leat		●	630,00
		Available only as part of (P29)		
		Not in conjunction with 001A	*	
		Not in conjunction with 101A	*	
		Not in conjunction with 975A/P87	*	
		Not in conjunction with H56	*	
		Not in conjunction with P75	*	
		Not in conjunction with U04		

		Not in conjunction with U38		
		Only in conjunction with U12		
		i.V.m. Code P22/P29	○	0,00
U17	Omission of coloured seat belts		—	0,00
		Not in conjunction with Y05		
U38	Dashboard and door beltlines in nappa leather		—	997,50
			○	0,00
		Available only as part of (P87)	*	
		Not in conjunction with 001A	*	
		Not in conjunction with 101A	*	
		Not in conjunction with 248	*	
		Not in conjunction with 336	*	
		Not in conjunction with 450/601A/811A/824A/837/H73/L5C/P29/U26	*	
		Not in conjunction with 51U/P65	*	
		Not in conjunction with H56	*	
		Not in conjunction with P75	*	
		Not in conjunction with PBX		
		Not in conjunction with U09	*	
		Not in conjunction with U12	*	
		Only in conjunction with P49+P87	*	
		Only in conjunction with U22	*	
U67	230 V socket in rear		●	126,00
		Not in conjunction with 301/U82	*	
		for certain countries only		
Y05	designo seat belts in red		—	0,00
		Not in conjunction with 65U/U17		
		Only in conjunction with [62 1A/898A]		
228	Auxiliary heater		●	1.438,50
		Only in conjunction with 916	*	
		Only for left hand drive	*	
		i.V.m. Code 362	●	1.281,00
443	Steering wheel heating		●	273,00
		Not in conjunction with 001A	*	
		Not in conjunction with 101A	*	
		Not in conjunction with H56	*	
		Not in conjunction with L6G		
		Not in conjunction with P65	*	
		Not in conjunction with P75	*	
		Not in conjunction with PBX		
		Only in conjunction with 275	*	
		Only in conjunction with P49	*	
		Only in conjunction with U22	*	
580	THERMATIC automatic climate control		S	0,00
		Not in conjunction with 581	*	
		Not in conjunction with 670	*	
581	THERMOTRONIC automatic climate control		●	892,50
		Not in conjunction with 580	*	
		Only in conjunction with 670	*	
B24	Remote control for auxiliary heating		○	0,00
		Only in conjunction with 228	*	
		Only in conjunction with 916	*	
		Only for left hand drive	*	
		i.V.m. Code 362	●	2 10,00
P21	AIR-BALANCE package		●	351,75
		Not in conjunction with 001A	*	
		Not in conjunction with 101A	*	
		Not in conjunction with 334	*	
		Not in conjunction with H56	*	
		Not in conjunction with P75	*	
		i.V.m. Code PBP/PBR	○	0,00
P68	Warmth Comfort package		●	829,50
			—	451,50
		Includes codes 902+906	*	
		Not in conjunction with 001A	*	
		Not in conjunction with 101A	*	
		Not in conjunction with 555/621A/PBX		
		Not in conjunction with 873/P65	*	
		Not in conjunction with H56	*	
		Not in conjunction with P75	*	
		Not in conjunction with PBZ		
		Only in conjunction with 275	*	
		Only in conjunction with P49	*	

		Only in conjunction with U22	*	
		i.V.m. Code PBP	●	451,50
		i.V.m. Code PYN /PYO	●	451,50
		i.V.m. Code PBR	○	0,00
844	folding bench seat in load compartment		–	1.312,50
		Not in conjunction with 1R7/978/R43		
		Not in conjunction with 413/432/436/550/82R/942/PBR		
890	EASY-PACK tailgate		–	0,00
942	EASY-PACK load securing kit		–	309,75
			–	0,00
		Not in conjunction with 4R3/844		
		Not in conjunction with 651/652		
		Not in conjunction with 978		
E69	EASY-PACK boot box		●	231,00
U35	Socket		–	0,00
656	Centre console in high-gloss brown ash wood		●	157,50
		Not in conjunction with 001A	*	
		Not in conjunction with 101A	*	
		Not in conjunction with 728/730/737/764	*	
		Not in conjunction with 732	*	
		Not in conjunction with 736/H09/H16/H32/H41/H64/H78	*	
		Not in conjunction with 784	*	
		Not in conjunction with H29	*	
		Not in conjunction with H56	*	
		Not in conjunction with H73	*	
		Not in conjunction with L2D	*	
		Not in conjunction with P75	*	
		Only in conjunction with H06	*	
		Only for left hand drive		
		i.V.m.Code PYC/PYE/PYF/PYG/PYH	●	52,50
728	Centre console in black piano-lacquer look		○	0,00
		Not in conjunction with 656/730/737/764	*	
		Not in conjunction with 732	*	
		Not in conjunction with 784	*	
		Not in conjunction with H73	*	
732	AMG carbon-fibre centre console		●	997,50
		Not in conjunction with 001A	*	
		Not in conjunction with 101A	*	
		Not in conjunction with 656/728/730/737/764	*	
		Not in conjunction with 736/H06/H09/H16/H29/H32/H64/H78	*	
		Not in conjunction with 784/P75	*	
		Not in conjunction with 978	*	
		Not in conjunction with H56	*	
		Only in conjunction with 891	*	
		i.V.m.Code PYC/PYE/PYF/PYG/PYH	●	840,00
		i.V.m. Code H73	○	0,00
737	Centre console in black open-pored ash wood		●	157,50
		Not in conjunction with 001A	*	
		Not in conjunction with 101A	*	
		Not in conjunction with 656/728/730/764	*	
		Not in conjunction with 732	*	
		Not in conjunction with 784	*	
		Not in conjunction with H06/H09/H16/H32/H64	*	
		Not in conjunction with H29	*	
		Not in conjunction with H56	*	
		Not in conjunction with H73	*	
		Not in conjunction with P75	*	
		i.V.m. Code PYF	●	52,50
		i.V.m. Code PYC/PYE/PYG/PYH	○	0,00
764	Centre console in grey open-pore ash wood		●	157,50
		Not in conjunction with 001A	*	
		Not in conjunction with 101A	*	
		Not in conjunction with 656/728/730/737	*	
		Not in conjunction with 732	*	
		Not in conjunction with 736/H06/H09/H16/H41/H64/H78	*	
		Not in conjunction with 784	*	
		Not in conjunction with H29	*	
		Not in conjunction with H56	*	
		Not in conjunction with H73	*	
		Not in conjunction with L2D	*	
		Not in conjunction with P75	*	
		Only in conjunction with H32	*	

		i.V.m.Code PYC/PYE/PYF/PYG/PYH	●	52,50
784	Centre console in high-gloss burr walnut wood		●	157,50
		Not in conjunction with 001A	*	
		Not in conjunction with 101A	*	
		Not in conjunction with 656/728/730/736/737/764/H06/H09/H16/H41/H64/H78	*	
		Not in conjunction with 732/H73	*	
		Not in conjunction with H56	*	
		Not in conjunction with P75	*	
		Only in conjunction with H29	*	
		i.V.m.Code PYC/PYE/PYF/PYG/PYH	●	52,50
H16	designo piano lacquer, black flowing lines		●	1.044,75
		Not in conjunction with 001A	*	
		Not in conjunction with 101A	*	
		Not in conjunction with 656/730/737/764	*	
		Not in conjunction with 732	*	
		Not in conjunction with 736/H06/H09/H32/H41/H64/H78	*	
		Not in conjunction with 784	*	
		Not in conjunction with H29	*	
		Not in conjunction with H56	*	
		Not in conjunction with H73	*	
		Not in conjunction with P75	*	
		Only in conjunction with 728	*	
		i.V.m. Code PYC/PYH	●	792,75
PBP	ENERGIZING package		●	939,75
			—	561,75
		Includes codes 355+868+873 [401/902]+891	*	
		Not in conjunction with 001A	*	
		Not in conjunction with 101A	*	
		Not in conjunction with 334	*	
		Not in conjunction with 548	*	
		Not in conjunction with H56	*	
		Not in conjunction with P75	*	
		Not in conjunction with PBR	*	
		Only in conjunction with 549	*	
		Only in conjunction with P21	*	
		i.V.m. Code PYO	○	0,00
PBR	ENERGIZING package Plus		●	4.593,75
			—	4.215,75
		Includes codes 355+401+868+891	*	
		Not in conjunction with 334	*	
		Not in conjunction with 4R3/844	*	
		Not in conjunction with 548	*	
		Not in conjunction with 555/621A/PBX	*	
		Not in conjunction with 651/652	*	
		Not in conjunction with 873/P65/PBP	*	
		Not in conjunction with H56	*	
		Not in conjunction with H73/L5C/P29/U26	*	
		Not in conjunction with P75	*	
		Not in conjunction with PBZ	*	
		Only in conjunction with 275+432+P21+P68	*	
		Only in conjunction with 549+P49	*	
		Only in conjunction with U22	*	
		Only in conjunction with [201A/208A/214A/215A/801A/804A/805A/975A]+436	*	
		i.V.m. Code PYO	●	3.654,00
U12	Velour floor mats		●	99,75
			—	0,00
		Not in conjunction with 450/601A/811A/824A/837/H73/L5C/P29/U26	*	
		Not in conjunction with P87	*	
		Not in conjunction with U04/U38	*	
		i.V.m. Code PYA	○	0,00
U25	Illuminated door sill panels with "Mercedes-Benz" lettering		●	178,50
		Not in conjunction with 978	*	
		i.V.m. Code PYR	●	0,00
		i.V.m.Code PYC/PYE/PYF/PYG/PYH	●	0,00
U25	AMG door sill panels with »AMG« lettering, illuminated		—	178,50
		i.V.m.Code PYC/PYE/PYF/PYG/PYH	—	0,00
U26	AMG floor mats		○	0,00
		Available only as part of (P29)	*	
		Not in conjunction with 01R/52R/61R/82R/R38	*	
		Not in conjunction with 1R7	*	
		Not in conjunction with 248	*	
		Not in conjunction with 337/341/342/485/550/623U/811/934/965	*	

		Not in conjunction with 401/432/436/450/55U/65U/837/88U/H78/L2B/P23/P87/PBR/U12	*	
		Not in conjunction with 651/652		
		Not in conjunction with 978		
		Not in conjunction with R11		
		Not in conjunction with R32		
		Not in conjunction with R90		
		Only in conjunction with 7U0+876+P29+P31	*	
		Only in conjunction with U29		
256	AMG Track Pace		–	262,50
		Not in conjunction with 548		
		Only in conjunction with 365+549		
		i.V.m. Code PYC	–	0,00
463	Head-up Display		●	1.039,50
868	Widescreen cockpit		●	787,50
		i.V.m. Code PYM	○	0,00
		i.V.m. Code PYN/PYO	○	0,00
		i.V.m. S-Code 108	–	0,00
U19	MBUX augmented reality for navigation		●	409,50
		Not in conjunction with 548	*	
		Not in conjunction with 597	*	
		Only in conjunction with 365+549+868	*	
		i.V.m. Code PYN/PYO	○	0,00
891	Ambient lighting		○	0,00
		Available only as part of (P29)		
		Not in conjunction with 001A	*	
		Not in conjunction with 101A	*	
		Not in conjunction with H56	*	
		Not in conjunction with P75	*	
51U	Roof liner in black fabric		●	367,50
			–	0,00
		Not in conjunction with 105A/128A/208A/55U/805A/88U/975A/P87	*	
		Not in conjunction with 336	*	
		Not in conjunction with 61U/65U	*	
		Not in conjunction with U04/U38		
		Only in conjunction with U12		
		i.V.m. Code 554A/555A/561A	○	0,00
		i.V.m. Code 601A	○	0,00
		i.V.m. Code 621A/811A	○	0,00
		i.V.m. Code 824A/851A/854A	○	0,00
		i.V.m. Code 830+(5/6/8*A)	○	0,00
		i.V.m. Code 855A/861A/864A	○	0,00
		i.V.m. Code P29	○	0,00
55U	Roof liner in macchiato beige fabric		○	0,00
		Not in conjunction with 001A	*	
		Not in conjunction with 101A	*	
		Not in conjunction with 121A	*	
		Not in conjunction with 128A/131A/208A/301A/51U/61U/65U/801A/88U	*	
		Not in conjunction with 201A		
		Not in conjunction with 248	*	
		Not in conjunction with 336	*	
		Not in conjunction with 601A/811A/824A/H73/L5C/P29/U26	*	
		Not in conjunction with H56	*	
		Not in conjunction with P75	*	
61U	designo roof lining in black DINAMICA microfibre		●	1.680,00
		Not in conjunction with 001A		
		Not in conjunction with 101A		
		Not in conjunction with 121A		
		Not in conjunction with 124A/125A/128A/208A/214A/215A/301A/314A/315A		
		Not in conjunction with 248	*	
		Not in conjunction with 336	*	
		Not in conjunction with 450/H78	*	
		Not in conjunction with 51U/65U	*	
		Not in conjunction with 55U/88U	*	
		Not in conjunction with 840	*	
		Not in conjunction with H56	*	
		Not in conjunction with P14	*	
		Not in conjunction with P75	*	
		Not in conjunction with PBX		
		Only in conjunction with 540	*	
		Only in conjunction with [105A/131A/801A/804A/805A/975A]	*	
		Only in conjunction with [201A/601A/811A/824A]	*	
		Only in conjunction with [P22]		

65U	designo roof liner in macchiato beige DINAMICA microf		●	1.680,00
		Not in conjunction with 001A	*	
		Not in conjunction with 101A	*	
		Not in conjunction with 121A	*	
		Not in conjunction with 128A/131A/208A/301A/55U/801A/88U	*	
		Not in conjunction with 201A	*	
		Not in conjunction with 248	*	
		Not in conjunction with 336	*	
		Not in conjunction with 450/601A/811A/824A/H73/L5C/P29/U26	*	
		Not in conjunction with 51U/61U	*	
		Not in conjunction with 840	*	
		Not in conjunction with 898A/PBX/Y05		
		Not in conjunction with H56	*	
		Not in conjunction with P75	*	
		Only in conjunction with 540	*	
88U	Roof liner in neva grey fabric		○	0,00
		Not in conjunction with 248		
		Not in conjunction with 51U/55U/61U/65U	*	
		Not in conjunction with 601A/811A/824A/H73/L5C/P29/U26	*	
		Not in conjunction with H56/P75		
P65	Seat Comfort package		○	0,00
		Includes codes U22	*	
		Not in conjunction with 105A/124A/125A/128A/131A/436/L2D/P87	*	
		Not in conjunction with 121A	*	
		Not in conjunction with 275/432/443/902/P68/PBR	*	
		Not in conjunction with PBZ		
		Not in conjunction with U04/U38		
		Only in conjunction with U12		
		i.V.m. Code P75	●	241,50
275	Memory package		●	1.071,00
		Not in conjunction with 001A	*	
		Not in conjunction with 101A	*	
		Not in conjunction with H56	*	
		Not in conjunction with P65	*	
		Not in conjunction with P75	*	
		Not in conjunction with PBX		
		Only in conjunction with P49	*	
		Only in conjunction with U22	*	
		i.V.m. Code 555	–	1.491,00
		i.V.m. Code PBZ	–	0,00
		i.V.m. Code PYO	○	0,00
401	Climatised front seats		●	1.155,00
			–	777,00
		Not in conjunction with 621A/PBX		
		Not in conjunction with 873	*	
		Not in conjunction with H56	*	
		Not in conjunction with H73/L5C/P29/U26	*	
		Not in conjunction with P75	*	
		Only in conjunction with [201A/208A/214A/215A/801A/804A/805A/975A]	*	
		i.V.m. Code P68/432	●	777,00
		i.V.m. Code PBP	●	777,00
		i.V.m. Code PYM/PYN/PYO	●	777,00
		i.V.m. Code PBR	○	0,00
432	Active Multicontour Seat package		●	2.047,50
		Not in conjunction with 001A	*	
		Not in conjunction with 101A	*	
		Not in conjunction with 4R3/844		
		Not in conjunction with 555/621A/PBX		
		Not in conjunction with 601A/811A/824A/H73/L5C/P29/U26	*	
		Not in conjunction with 651/652		
		Not in conjunction with 873/P65	*	
		Not in conjunction with H56	*	
		Not in conjunction with P75	*	
		Not in conjunction with PBZ		
		Only in conjunction with 275+902	*	
		Only in conjunction with 401		
		Only in conjunction with 436	*	
		Only in conjunction with P49	*	
		Only in conjunction with U22	*	
		i.V.m. Code PBP	●	1.669,50
		i.V.m. Code PYN/PYO	●	1.669,50
		i.V.m. Code PBR	○	0,00

436	Comfort front head restraints		○	0,00
		Not in conjunction with 001A	*	
		Not in conjunction with 101A	*	
		Not in conjunction with 4R3/844		
		Not in conjunction with 601A/811A/824A/H73/L5C/P29/U26	*	
		Not in conjunction with 651/652		
		Not in conjunction with 873/P65	*	
		Not in conjunction with H56	*	
		Not in conjunction with P75	*	
		Only in conjunction with 275+432+902+P49	*	
		Only in conjunction with U22	*	
873	Heated front seats		●	378,00
			—	0,00
		Not in conjunction with 401/432/902/P68/PBR	*	
		Not in conjunction with 436	*	
		i.V.m. Code PBR/PBP	○	0,00
		i.V.m. Code PYM/PYN/PYO	○	0,00
902	Seat heating Plus for driver and front passenger seats		○	0,00
		Not in conjunction with 001A	*	
		Not in conjunction with 101A	*	
		Not in conjunction with 555/621A/PBX		
		Not in conjunction with 873/P65	*	
		Not in conjunction with H56	*	
		Not in conjunction with P75	*	
		Not in conjunction with PBZ		
		Only in conjunction with 275	*	
		Only in conjunction with P49	*	
		Only in conjunction with U22	*	
		With 275+(421/P68) added	*	
U10	Automatic front passenger airbag deactivation		○	0,00
U22	4-way lumbar support		○	0,00
		Only in conjunction with P65/275	*	
287	Folding rear seat backrests		●	456,75
			—	0,00
		i.V.m. Code PYB	○	0,00
872	Heated rear seats		●	378,00
		Not in conjunction with 248	*	
		Not in conjunction with 978		
		Only in conjunction with [201A/208A/214A/215A/801A/804A/805A/975A]	*	
		Only in conjunction with [811A/824A]	*	
446	Touchpad without Controller		○	0,00
		Not in conjunction with 448	*	
448	Touchpad with Controller		●	63,00
		Not in conjunction with 446/77B	*	
		i.V.m. Code PYB	○	0,00
77B	MBUX Interior Assistant		●	315,00
		Not in conjunction with 336	*	
		Not in conjunction with 337	*	
		Not in conjunction with 448	*	
		Not in conjunction with 811	*	
		Only in conjunction with 446	*	
L2B	Multifunction steering wheel in nappa leather		○	0,00
		Not in conjunction with 601A/811A/824A/H73/P29/U26	*	
		Not in conjunction with L2D		
L2D	Multifunction steering wheel in wood/leather		●	619,50
		Not in conjunction with 001A	*	
		Not in conjunction with 101A	*	
		Not in conjunction with 656/730/764/H06/H09/H41/H78/P65	*	
		Not in conjunction with 736/H32/H64		
		Not in conjunction with H56	*	
		Not in conjunction with H73	*	
		Not in conjunction with L2B		
		Not in conjunction with P75	*	
		Only in conjunction with 275+443+P49	*	
		Only in conjunction with U22	*	
		Only in conjunction with H18/H29	*	
L5C	Multifunction sports steering wheel in nappa leather		○	0,00
		Not in conjunction with 01R/52R/61R/82R/R38		
		Not in conjunction with 1R7		
		Not in conjunction with 248	*	
		Not in conjunction with 337/341/342/485/550/623U/811/934/965		
		Not in conjunction with 401/432/436/450/55U/65U/837/88U/H78/P23/P75/P87/PBR/U12	*	

		Not in conjunction with 651/652		
		Not in conjunction with 978		
		Not in conjunction with H56	*	
		Not in conjunction with R11		
		Not in conjunction with R32		
		Not in conjunction with R90		
		Only in conjunction with 7U0+876+P29+P31	*	
		Only in conjunction with U29		
U88	AMG steering wheel buttons		—	367,50
301	Front and rear ashtray inserts in the stowage compartment		●	47,25
		Not in conjunction with 274	*	
		Not in conjunction with 333	*	
		Not in conjunction with 336	*	
		Not in conjunction with 897/899/U67	*	
301	Ashtray insert with cigarette lighter in front stowage compartment		●	47,25
		Not in conjunction with 274	*	
		Not in conjunction with 333	*	
		Not in conjunction with 336	*	
		Not in conjunction with 897/899/U67	*	
30P	Stowage facility package		—	183,75
			●	99,75
		Includes codes 309	*	
		Not in conjunction with 333		
		i.V.m. Code PYA	○	0,00
736	Open-pore black ash wood trim		●	252,00
		Not in conjunction with 001A	*	
		Not in conjunction with 101A	*	
		Not in conjunction with 656/730/764	*	
		Not in conjunction with 732	*	
		Not in conjunction with 784	*	
		Not in conjunction with H06/H09/H16/H32/H41/H64/H78	*	
		Not in conjunction with H56	*	
		Not in conjunction with H73	*	
		Not in conjunction with L2D	*	
		Not in conjunction with P75	*	
		Only in conjunction with [728/737]		
		i.V.m. Code P22/P87	●	199,50
		i.V.m. Code PYC/PYH	○	0,00
H06	brown high-gloss ash wood trim		●	252,00
		Not in conjunction with 001A	*	
		Not in conjunction with 101A	*	
		Not in conjunction with 730/737/764	*	
		Not in conjunction with 732	*	
		Not in conjunction with 736/H09/H16/H32/H41/H64/H78	*	
		Not in conjunction with 784	*	
		Not in conjunction with H29	*	
		Not in conjunction with H56	*	
		Not in conjunction with H73	*	
		Not in conjunction with L2D	*	
		Not in conjunction with P75	*	
		Only in conjunction with [656/728]		
		i.V.m. Code P22/P87	●	199,50
		i.V.m. Code PYC/PYH	●	52,50
H09	brown open-pore ash wood trim		●	252,00
		Not in conjunction with 001A	*	
		Not in conjunction with 101A	*	
		Not in conjunction with 656/737/764	*	
		Not in conjunction with 732	*	
		Not in conjunction with 736/H06/H16/H32/H41/H64/H78	*	
		Not in conjunction with 784	*	
		Not in conjunction with H29	*	
		Not in conjunction with H56	*	
		Not in conjunction with H73	*	
		Not in conjunction with L2D	*	
		Not in conjunction with P75	*	
		Only in conjunction with [728/730]		
		i.V.m. Code P87	●	199,50
		i.V.m. Code PYC/PYH	●	52,50
		i.V.m. Code P22	○	0,00
		i.V.m. Code PYF	○	0,00
H29	High-gloss brown burr walnut wood trim		●	252,00
		Not in conjunction with 001A	*	

		Not in conjunction with 101A	*	
		Not in conjunction with 656/730/737/764	*	
		Not in conjunction with 732	*	
		Not in conjunction with H06/H09/H16/H41/H78	*	
		Not in conjunction with H56	*	
		Not in conjunction with H73	*	
		Not in conjunction with P75	*	
		Only in conjunction with 728		
		i.V.m. Code P22	●	199,50
		i.V.m. Code PYC/PYH	●	52,50
		i.V.m. Code P87	○	0,00
H32	Grey open-pore ash wood trim		●	252,00
		Not in conjunction with 001A	*	
		Not in conjunction with 101A	*	
		Not in conjunction with 656/730/737	*	
		Not in conjunction with 732	*	
		Not in conjunction with 736/H06/H09/H16/H41/H64/H78	*	
		Not in conjunction with H56	*	
		Not in conjunction with H73	*	
		Not in conjunction with L2D		
		Not in conjunction with P75	*	
		Only in conjunction with [728/764]		
		i.V.m. Code P22/P87	●	199,50
		i.V.m. Code PYC/PYH	●	52,50
H41	Light longitudinal-grain aluminium trim		●	304,50
		Not in conjunction with 001A	*	
		Not in conjunction with 101A	*	
		Not in conjunction with 656/730/736/764/H06/H09/H16/H32/H64/H78	*	
		Not in conjunction with 784	*	
		Not in conjunction with H29	*	
		Not in conjunction with H56	*	
		Not in conjunction with H73	*	
		Not in conjunction with L2D	*	
		Not in conjunction with P75	*	
		i.V.m. Code PYC/PYH/PYF	●	52,50
		i.V.m. Code P14/P29	○	0,00
		i.V.m. Code P22/P87	○	0,00
		i.V.m. Code PYE/PYG	○	0,00
H56	Silver special-effect paint trim		○	0,00
		Not in conjunction with 08R/R69	*	
		Not in conjunction with 19U/248/337/341/342/344/413/414/720/810/934/938/965/974/975/L2D/P55/U04/U38/U50/Z97		
		Not in conjunction with 23U/275/292/401/432/436/443/55U/61U/656/65U/730/736/737/764/876/883/891/902/E72/H6	*	
		Not in conjunction with 52R/61R/RSW/RZl	*	
		Not in conjunction with 732/H73/P23	*	
		Not in conjunction with 772		
		Not in conjunction with 776		
		Not in conjunction with 784/H29	*	
		Not in conjunction with 811/U47	*	
		Not in conjunction with 88U		
		Not in conjunction with P31	*	
		Not in conjunction with RRD	*	
		Not in conjunction with RSl/RSK		
		Only in conjunction with 725+873+970+P65+U12+Z90		
		Only in conjunction with 728+L2B+P75	*	
		Only in conjunction with 7U0+P15	*	
		Only in conjunction with R32		
H64	Metal-weave trim		●	472,50
		Not in conjunction with 001A	*	
		Not in conjunction with 101A	*	
		Not in conjunction with 656/730/737/764	*	
		Not in conjunction with 732	*	
		Not in conjunction with 736/H06/H09/H16/H32/H41/H78	*	
		Not in conjunction with 784	*	
		Not in conjunction with H56	*	
		Not in conjunction with H73	*	
		Not in conjunction with L2D		
		Not in conjunction with P75	*	
		Only in conjunction with 728	*	
		i.V.m. Code P22/P87	●	420,00
		i.V.m. Code PYC/PYH	●	220,50
H73	AMG carbon-fibre trim		●	3.097,50
		Not in conjunction with 01R/52R/61R/82R/R38		

		Not in conjunction with 1R7		
		Not in conjunction with 22R		
		Not in conjunction with 248	*	
		Not in conjunction with 337/341/342/485/550/623U/811/934/965		
		Not in conjunction with 401/432/436/450/55U/65U/784/837/88U/P23/P75/P87/PBR/U12	*	
		Not in conjunction with 651/652		
		Not in conjunction with 656/728/730/737/764	*	
		Not in conjunction with 736/H06/H09/H16/H29/H32/H41/H64/H78	*	
		Not in conjunction with 978		
		Not in conjunction with H56	*	
		Not in conjunction with R11		
		Not in conjunction with R32		
		Not in conjunction with R43		
		Not in conjunction with R90		
		Not in conjunction with R97		
		Only in conjunction with 732	*	
		Only in conjunction with 7U0+876+P29+P31	*	
		Only in conjunction with U29		
		i.V.m. Code PYC/PYH	●	2.845,50
H78	Light carbon-grain aluminium trim		●	304,50
			—	0,00
		Not in conjunction with 001A	*	
		Not in conjunction with 101A	*	
		Not in conjunction with 105A/131A/601A/61U/801A/804A/805A/811A/824A	*	
		Not in conjunction with 248	*	
		Not in conjunction with 656/730/764	*	
		Not in conjunction with 732	*	
		Not in conjunction with 736/H06/H09/H16/H32/H41/H64	*	
		Not in conjunction with 784	*	
		Not in conjunction with H29	*	
		Not in conjunction with H56	*	
		Not in conjunction with H73	*	
		Not in conjunction with L2D		
		Not in conjunction with P29	*	
		Not in conjunction with P75	*	
		Not in conjunction with U26		
		Only in conjunction with L2B+P14	*	
		Only in conjunction with [728/737]		
		i.V.m. Code PYC/PYE/PYH	●	52,50
		i.V.m. Code PYE/PYG	○	0,00
861A	black		—	2.310,00
		Not in conjunction with PBX/Y05		
		Only in conjunction with U17		
864A	nut brown / black		—	2.520,00
		Not in conjunction with PBX/Y05		
		Only in conjunction with U17		
865A	macchiato beige / black		—	2.520,00
		Not in conjunction with PBX/Y05		
		Only in conjunction with U17		
898A	titanium grey pearl / black		—	2.520,00
		Not in conjunction with 65U/PBX		
101A	black		●	525,00
		Not in conjunction with 08R/R69	*	
		Not in conjunction with 19U/248/337/341/342/344/413/414/720/810/934/938/965/974/975/L2D/P55/U04/U38/U50/Z97		
		Not in conjunction with 23U/275/292/401/432/436/443/55U/61U/656/65U/730/736/737/764/872/876/883/891/902/E	*	
		Not in conjunction with 52R/61R/RRD/RSW/RZi	*	
		Not in conjunction with 732/H73/P23	*	
		Not in conjunction with 772		
		Not in conjunction with 776		
		Not in conjunction with 784/H29	*	
		Not in conjunction with 811	*	
		Not in conjunction with P31	*	
		Not in conjunction with RSI/RSK		
		Not in conjunction with U26		
		Not in conjunction with U47	*	
		Only in conjunction with 725+873+970+P65+U12+Z90		
		Only in conjunction with 728	*	
		Only in conjunction with 7U0+P15	*	
		Only in conjunction with L2B+P75	*	
		Only in conjunction with R32		
		i.V.m. Code 450	○	0,00
105A	macchiato beige / magma grey		●	210,00

		Not in conjunction with 248	*	
		Not in conjunction with 336	*	
		Not in conjunction with 401/51U/872/P65/PBR	*	
		Not in conjunction with 450/H73/H78/L5C	*	
		Not in conjunction with H56	*	
		Not in conjunction with P14		
		Not in conjunction with P29	*	
		Not in conjunction with P75	*	
		Not in conjunction with U26		
		Only in conjunction with 275+P22+P49	*	
		Only in conjunction with 876	*	
		Only in conjunction with U22	*	
131A	black		○	0,00
		Not in conjunction with 248	*	
		Not in conjunction with 401/55U/65U/872/P65/PBR	*	
		Not in conjunction with 450/H73/H78/L5C	*	
		Not in conjunction with H56	*	
		Not in conjunction with P14		
		Not in conjunction with P29	*	
		Not in conjunction with P75	*	
		Not in conjunction with U26		
		Only in conjunction with 275+P22+P49	*	
		Only in conjunction with 876	*	
		Only in conjunction with U22	*	
134A	nut brown / black		●	210,00
		Not in conjunction with 248	*	
		Not in conjunction with 336	*	
		Not in conjunction with 401/51U/872/P65/PBR	*	
		Not in conjunction with 450/H73/H78/L5C	*	
		Not in conjunction with H56	*	
		Not in conjunction with P14		
		Not in conjunction with P29	*	
		Not in conjunction with P75	*	
		Not in conjunction with U26		
		Only in conjunction with 275+P22+P49	*	
		Only in conjunction with 876	*	
308A	neva grey / magma grey	Only in conjunction with U22	*	#VALUE!
		Only in conjunction with P14+300A+88U		
601A	black		○	0,00
		Not in conjunction with 01R/52R/61R/82R/R38		
		Not in conjunction with 1R7		
		Not in conjunction with 248	*	
		Not in conjunction with 336	*	
		Not in conjunction with 337/341/342/485/550/623U/811/934/965		
		Not in conjunction with 401/432/436/450/55U/65U/837/872/88U/H78/L2B/P23/P75/P87/PBR/U12	*	
		Not in conjunction with 651/652		
		Not in conjunction with 978		
		Not in conjunction with H56	*	
		Not in conjunction with R11		
		Not in conjunction with R32		
		Not in conjunction with R90		
		Only in conjunction with 7U0+876+P29+P31	*	
		Only in conjunction with U29		
621A	black		—	0,00
		Not in conjunction with 401/432/902/P68/PBR/PBZ		
		Only in conjunction with 873		
301A	black		○	0,00
		Not in conjunction with 248	*	
		Not in conjunction with 401/55U/61U/65U/872/PBR	*	
		Not in conjunction with 450/H73/L5C	*	
		Not in conjunction with H56	*	
		Not in conjunction with P22		
		Not in conjunction with P29	*	
		Not in conjunction with P75	*	
		Not in conjunction with U26		
		Only in conjunction with P14	*	
314A	nut brown / black		●	210,00
		Not in conjunction with 248	*	
		Not in conjunction with 336	*	
		Not in conjunction with 401/61U/872/PBR	*	
		Not in conjunction with 450/H73/L5C	*	
		Not in conjunction with H56	*	

		Not in conjunction with P22		
		Not in conjunction with P29	*	
		Not in conjunction with P75	*	
		Not in conjunction with U26		
		Only in conjunction with P14	*	
315A	macchiato beige / black		●	210,00
		Not in conjunction with 248	*	
		Not in conjunction with 336	*	
		Not in conjunction with 401/61U/872/PBR	*	
		Not in conjunction with 450/H73/L5C	*	
		Not in conjunction with H56	*	
		Not in conjunction with P22		
		Not in conjunction with P29	*	
		Not in conjunction with P75	*	
		Not in conjunction with U26		
		Only in conjunction with P14	*	
975A	macchiato beige / saddle brown		○	0,00
		Not in conjunction with 248	*	
		Not in conjunction with 336	*	
		Not in conjunction with 450/H73/L5C/P29/U26	*	
		Not in conjunction with 51U/U09	*	
		Not in conjunction with H56	*	
		Not in conjunction with P75	*	
201A	black		●	1.816,50
		Not in conjunction with 248	*	
		Not in conjunction with 55U/61U/65U		
		Not in conjunction with H56	*	
		Not in conjunction with P22	*	
		Not in conjunction with P75	*	
		Only in conjunction with P14		
208A	neva grey / magma grey		●	2.026,50
		Not in conjunction with 248	*	
		Not in conjunction with 450/H73/L5C	*	
		Not in conjunction with 51U/55U/61U/65U	*	
		Not in conjunction with H56	*	
		Not in conjunction with P22		
		Not in conjunction with P29	*	
		Not in conjunction with P75	*	
		Not in conjunction with U26		
		Only in conjunction with 88U+P14	*	
214A	nut brown / black		●	2.026,50
		Not in conjunction with 248	*	
		Not in conjunction with 336	*	
		Not in conjunction with 61U	*	
		Not in conjunction with H56	*	
		Not in conjunction with H73/L5C	*	
		Not in conjunction with P22		
		Not in conjunction with P29	*	
		Not in conjunction with P75	*	
		Not in conjunction with U26		
		Only in conjunction with P14	*	
215A	macchiato beige / black		●	2.026,50
		Not in conjunction with 248	*	
		Not in conjunction with 336	*	
		Not in conjunction with 61U	*	
		Not in conjunction with H56	*	
		Not in conjunction with H73/L5C	*	
		Not in conjunction with P22		
		Not in conjunction with P29	*	
		Not in conjunction with P75	*	
		Not in conjunction with U26		
		Only in conjunction with P14	*	
001A	black		○	0,00
		Not in conjunction with 08R/R69	*	
		Not in conjunction with 19U/337/341/342/344/413/414/720/810/934/938/965/974/975/L2D/P55/U04/U38/U50/Z97		
		Not in conjunction with 23U/248/275/292/401/432/436/443/55U/61U/656/65U/730/736/737/764/872/876/883/891/90	*	
		Not in conjunction with 450/732/H73/P23	*	
		Not in conjunction with 52R/61R/RRD/RSW/RZI	*	
		Not in conjunction with 772		
		Not in conjunction with 776		
		Not in conjunction with 784/H29	*	
		Not in conjunction with 811	*	

		Not in conjunction with P31	*	
		Not in conjunction with RS/RSK		
		Not in conjunction with U47	*	
		Only in conjunction with 725+873+970+P65+U12+Z90		
		Only in conjunction with 728	*	
		Only in conjunction with 7U0+P15	*	
		Only in conjunction with L2B+P75	*	
		Only in conjunction with R32		
801A	black		●	2.310,00
		Not in conjunction with 248	*	
		Not in conjunction with 450/H73/H78/L5C	*	
		Not in conjunction with 55U/65U	*	
		Not in conjunction with H56	*	
		Not in conjunction with P14		
		Not in conjunction with P29	*	
		Not in conjunction with P75	*	
		Not in conjunction with U26		
		Only in conjunction with 876	*	
		Only in conjunction with P22	*	
804A	nut brown / black		●	2.520,00
		Not in conjunction with 248	*	
		Not in conjunction with 336	*	
		Not in conjunction with 450/H73/H78/L5C	*	
		Not in conjunction with H56	*	
		Not in conjunction with P14		
		Not in conjunction with P29	*	
		Not in conjunction with P75	*	
		Not in conjunction with U26		
		Only in conjunction with 876	*	
		Only in conjunction with P22	*	
805A	macchiato beige / magma grey		●	2.520,00
		Not in conjunction with 248	*	
		Not in conjunction with 336	*	
		Not in conjunction with 450/H73/H78/L5C	*	
		Not in conjunction with 51U	*	
		Not in conjunction with H56	*	
		Not in conjunction with P14		
		Not in conjunction with P29	*	
		Not in conjunction with P75	*	
		Not in conjunction with U26		
		Only in conjunction with 876	*	
		Only in conjunction with P22	*	
811A	black		●	2.310,00
		Not in conjunction with 01R/52R/61R/82R/R38		
		Not in conjunction with 1R7		
		Not in conjunction with 248	*	
		Not in conjunction with 336	*	
		Not in conjunction with 337/341/342/485/550/623U/811/934/965		
		Not in conjunction with 401/432/436/450/55U/65U/837/88U/H78/L2B/P23/P75/P87/PBR/U12	*	
		Not in conjunction with 651/652		
		Not in conjunction with 978		
		Not in conjunction with H56	*	
		Not in conjunction with R11		
		Not in conjunction with R32		
		Not in conjunction with R90		
		Only in conjunction with 7U0+876+P29+P31	*	
		Only in conjunction with U29		
824A	saddle brown / black		●	2.520,00
		Not in conjunction with 01R/52R/61R/82R/R38		
		Not in conjunction with 1R7		
		Not in conjunction with 248	*	
		Not in conjunction with 336	*	
		Not in conjunction with 337/341/342/485/550/623U/811/934/965		
		Not in conjunction with 401/432/436/450/55U/65U/837/88U/H78/L2B/P23/P75/P87/PBR/U12	*	
		Not in conjunction with 651/652		
		Not in conjunction with 978		
		Not in conjunction with H56	*	
		Not in conjunction with R11		
		Not in conjunction with R32		
		Not in conjunction with R90		
		Only in conjunction with 7U0+876+P29+P31	*	
		Only in conjunction with U29		

P14	AVANTGARDE interior		●	1.386,00
			–	0,00
		Includes codes 876+891+H78 [736/H06/H09/H16/H64]		
		Includes codes 876+891	*	
		Not in conjunction with 001A	*	
		Not in conjunction with 101A	*	
		Not in conjunction with 105A/131A/61U/801A/804A/805A	*	
		Not in conjunction with 248	*	
		Not in conjunction with 601A/811A/824A/H73/L5C	*	
		Not in conjunction with P22		
		i.V.m. Code PYE/PYG	○	0,00
P15	AVANTGARDE exterior		–	1.155,00
			○	0,00
		Includes codes 15R [RRR/RTG]+489+725 [720]		
		Includes codes 485 [489]		
		Includes codes 485+725 [720]		
		Includes codes 677 [459/482/485/489]	*	
		Includes codes 677 [459/485/489]		
		Includes codes 677 [485/489]+725 [720]		
		Not in conjunction with 08R/R69	*	
		Not in conjunction with 52R/61R/RSW/RZl	*	
		Not in conjunction with 601A/811A/824A/H73/L5C/P29/U26	*	
		Not in conjunction with 776		
		Not in conjunction with RRD	*	
		Not in conjunction with RSJ/RSK		
		Not in conjunction with U47	*	
		Only in conjunction with 7U0	*	
		Only in conjunction with [22R/R90/R97]		
		Only in conjunction with [R32]		
P22	EXCLUSIVE interior		–	2.803,50
			●	2.289,00
			–	1.081,50
		Includes codes 891+H09 [736/H06/H09/H16/H64]+U09	*	
		Includes codes 891+H78 [736/H06/H09/H16/H64]+U09		
		Includes codes 891+U09		
		Not in conjunction with 450/H73/H78/L5C	*	
		Not in conjunction with P14		
		Only in conjunction with 876	*	
		Only in conjunction with [105A/131A/801A/804A/805A/975A]	*	
		i.V.m. Code PYF	○	0,00
P23	EXCLUSIVE exterior		–	1.155,00
			●	210,00
		Includes codes 485 [459/482/489/677]	*	
		Includes codes 485 [459/489/677]		
		Includes codes 485 [489/677]+725		
		Includes codes 485 [489]		
		Includes codes 485+725		
		Not in conjunction with 001A	*	
		Not in conjunction with 01R/R10/R38/R90/RRD/RSW/RZl	*	
		Not in conjunction with 101A	*	
		Not in conjunction with 601A/7U0/811A/824A/H73/L5C/P29/P55/P75/U26/U50	*	
		Not in conjunction with 720		
		Not in conjunction with 776		
		Not in conjunction with 82R	*	
		Not in conjunction with H56	*	
		Not in conjunction with R11/R48	*	
		Not in conjunction with RSJ/RSK		
		Not in conjunction with U47	*	
		Only in conjunction with U29		
		Only in conjunction with [22R/R97]		
		Only in conjunction with [52R/61R/RVQ/RVR]		
		Only in conjunction with [R32]		
		i.V.m. Code PYF	○	0,00
P29	AMG Line interior		●	2.121,00
		Includes codes 891+L5C+U09+U26	*	
		Not in conjunction with 01R/52R/61R/82R/R38		
		Not in conjunction with 1R7		
		Not in conjunction with 22R		
		Not in conjunction with 248	*	
		Not in conjunction with 337/341/342/485/550/623U/811/934/965		
		Not in conjunction with 401/432/436/450/55U/65U/837/88U/H78/L2B/P23/P87/PBR/U12	*	
		Not in conjunction with 651/652		

		Not in conjunction with 978		
		Not in conjunction with R11		
		Not in conjunction with R32		
		Not in conjunction with R43		
		Not in conjunction with R90		
		Not in conjunction with R97		
		Only in conjunction with 7U0+876+P31	*	
		Only in conjunction with U29		
		i.V.m. Code PWS ohne 498	●	1.779,75
		i.V.m. Code PYH	●	0,00
P31	AMG Line exterior		●	2.940,00
			–	2.467,50
		Includes codes 485 [489]+772		
		Includes codes 677 [459/482/485/489]+772	*	
		Includes codes 677 [459/485/489]+772		
		Includes codes 677 [485/489]+725 [720]+772		
		Includes codes 725 [720]+772		
		Includes codes 772		
		Not in conjunction with 001A	*	
		Not in conjunction with 01R/52R/61R/82R/R38		
		Not in conjunction with 101A	*	
		Not in conjunction with 1R7		
		Not in conjunction with 22R		
		Not in conjunction with 248/337/341/342/485/550/623U/811/934/965		
		Not in conjunction with 651/652		
		Not in conjunction with 978		
		Not in conjunction with H56	*	
		Not in conjunction with P75	*	
		Not in conjunction with R11		
		Not in conjunction with R32		
		Not in conjunction with R43		
		Not in conjunction with R90		
		Not in conjunction with R97		
		Only in conjunction with 7U0	*	
		Only in conjunction with U29		
		Only in conjunction with [22R/R10/R97/RRD/RSW/RVQ/RVR/RZl]	*	
		i.V.m. Code RSK/RSP	●	2.887,50
		i.V.m. Code RSJ /RSN	●	2.572,50
		i.V.m. Code RSK/RSP	–	2.415,00
		i.V.m. Code RSJ /RSN	–	2.100,00
		i.V.m. Code PYG/PYH	●	0,00
P75	Standard interior equipment and appointments		S	0,00
		Includes codes H56	*	
		Not in conjunction with 08R/R69	*	
		Not in conjunction with 19U/248/337/341/342/344/413/414/720/810/934/938/965/974/975/L2D/P55/U04/U38/U50/Z97		
		Not in conjunction with 23U/275/292/401/432/436/443/55U/61U/656/65U/730/736/737/764/876/883/891/902/E72/H6	*	
		Not in conjunction with 52R/61R/RSW/RZl	*	
		Not in conjunction with 732/H73/P23	*	
		Not in conjunction with 772		
		Not in conjunction with 776		
		Not in conjunction with 784/H29	*	
		Not in conjunction with 811	*	
		Not in conjunction with 88U		
		Not in conjunction with P31	*	
		Not in conjunction with RRD	*	
		Not in conjunction with RSJ/RSK		
		Not in conjunction with U47	*	
		Only in conjunction with 725+873+970+P65+U12+Z90		
		Only in conjunction with 728	*	
		Only in conjunction with 7U0+P15	*	
		Only in conjunction with L2B	*	
		Only in conjunction with R32		
362	Communications module (LTE) for the use of Mercedes		○	0,00
362	Communications module (LTE) for the use of Mercedes		○	0,00
13U	Preinstallation for Remote and Navigation Services		–	0,00
20U	Pre-installation for car sharing		●	52,50
		i.V.m. Code PYA	○	0,00
33U	Remote Services Plus		●	157,50
		Not in conjunction with 34U	*	
		Not in conjunction with 38U		
		i.V.m. Code PYA	–	0,00
34U	Remote Services Premium		●	262,50

		Not in conjunction with 33U	*	
351	Mercedes-Benz emergency call system		○	0,00
37U	Advanced connectivity Plus		●	262,50
38U	Remote and Charging Services Plus		●	252,00
		Not in conjunction with 33U		
		Only in conjunction with 365		
		i.V.m. Code PYA	–	94,50
00B	Owner's Manual and Service Booklet - Danish		○	0,00
		Not in conjunction with 01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/13B/14B/15B/16B/17B/30B/31B/32B/33B/34	*	
		Not in conjunction with 22B	*	
01B	Owner's Manual and Service Booklet - Dutch		○	0,00
		Not in conjunction with 00B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/13B/14B/15B/16B/17B/30B/31B/32B/33B/34	*	
		Not in conjunction with 22B	*	
02B	Owner's Manual and Service Booklet - German		○	0,00
		Not in conjunction with 00B/01B/03B/04B/05B/06B/07B/08B/09B/10B/11B/13B/14B/15B/16B/17B/30B/31B/32B/33B/34	*	
		Not in conjunction with 22B	*	
03B	Owner's Manual and Service Booklet - Russian		○	0,00
		Not in conjunction with 00B/01B/02B/04B/05B/06B/07B/08B/09B/10B/11B/13B/14B/15B/16B/17B/30B/31B/32B/33B/34	*	
		Not in conjunction with 22B	*	
04B	Owner's Manual and Service Booklet - Finnish		○	0,00
		Not in conjunction with 00B/01B/02B/03B/05B/06B/07B/08B/09B/10B/11B/13B/14B/15B/16B/17B/30B/31B/32B/33B/34	*	
		Not in conjunction with 22B	*	
05B	Owner's Manual and Service Booklet - English		○	0,00
		Not in conjunction with 00B/01B/02B/03B/04B/06B/07B/08B/09B/10B/11B/13B/14B/15B/16B/17B/30B/31B/32B/33B/34	*	
		Not in conjunction with 22B	*	
05Z	Run-on times MPM 4 hours		○	0,00
		Not in conjunction with 06Z	*	
		Not in conjunction with 413	*	
		Not in conjunction with 810		
		Not in conjunction with 811	*	
		Not in conjunction with B63		
		Not in conjunction with Z97	*	
06B	Owner's Manual and Service Booklet - Italian		○	0,00
		Not in conjunction with 00B/01B/02B/03B/04B/05B/07B/08B/09B/10B/11B/13B/14B/15B/16B/17B/30B/31B/32B/33B/34	*	
		Not in conjunction with 22B	*	
06Z	Run-on times MPM w/o time limit		○	0,00
		Not in conjunction with 05Z	*	
		Not in conjunction with 413	*	
		Not in conjunction with 810		
		Not in conjunction with 811	*	
		Not in conjunction with B63		
		Not in conjunction with Z97	*	
07B	Owner's Manual and Service Booklet - French		○	0,00
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/08B/09B/10B/11B/13B/14B/15B/16B/17B/30B/31B/32B/33B/34	*	
		Not in conjunction with 22B	*	
08B	Owner's Manual and Service Booklet - Spanish		○	0,00
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/09B/10B/11B/13B/14B/15B/16B/17B/30B/31B/32B/33B/34	*	
		Not in conjunction with 22B	*	
09B	Owner's Manual and Service Booklet - Portuguese		○	0,00
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/10B/11B/13B/14B/15B/16B/17B/30B/31B/32B/33B/34	*	
		Not in conjunction with 22B	*	
10B	Owner's Manual and Service Booklet - Swedish		○	0,00
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/11B/13B/14B/15B/16B/17B/30B/31B/32B/33B/34	*	
		Not in conjunction with 22B	*	
10Z	High-beam flashing, daytime, for emerg. vehicle		○	0,00
		Not in conjunction with 19U/337/341/342/344/934/938/965	*	
		Not in conjunction with 19U/965		
		Not in conjunction with 248/344/450/934/938		
		Not in conjunction with 248	*	
		Not in conjunction with 337/341/342/623U		
		Not in conjunction with 413/414/810/Z97		
		Not in conjunction with 413/414/810	*	
		Not in conjunction with 450/623U	*	
		Not in conjunction with 811	*	
		Not in conjunction with 837		
		Not in conjunction with B63		
		Not in conjunction with Z97	*	
		Only in conjunction with Z90	*	
11B	Owner's Manual and Service Booklet - Arabic		○	0,00
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/13B/14B/15B/16B/17B/30B/31B/32B/33B/34	*	
		Not in conjunction with 22B	*	
11Z	Dayt. run. lamps flashing, daytime, emerg. veh.		○	0,00

		Not in conjunction with 19U/337/341/342/344/934/938/965	*	
		Not in conjunction with 19U/965		
		Not in conjunction with 248/344/450/934/938		
		Not in conjunction with 248	*	
		Not in conjunction with 337/341/342/623U		
		Not in conjunction with 413/414/810/297		
		Not in conjunction with 413/414/810	*	
		Not in conjunction with 450/623U	*	
		Not in conjunction with 811	*	
		Not in conjunction with 837		
		Not in conjunction with B63		
		Not in conjunction with Z97	*	
		Only in conjunction with Z90	*	
121A	black ARTICO man-made leather		●	262,50
			—	0,00
		Not in conjunction with 248	*	
		Not in conjunction with 401/55U/61U/65U/872/P65/PBR	*	
		Not in conjunction with 450/H73/L5C	*	
		Not in conjunction with H56	*	
		Not in conjunction with P22		
		Not in conjunction with P29	*	
		Not in conjunction with P75	*	
		Not in conjunction with U26		
		Only in conjunction with 275+P14+P49	*	
		Only in conjunction with U22	*	
124A	ARTICO man-made leather hazelnut brown / black		●	472,50
			—	0,00
		Not in conjunction with 248	*	
		Not in conjunction with 336	*	
		Not in conjunction with 401/61U/872/P65/PBR	*	
		Not in conjunction with 450/H73/L5C	*	
		Not in conjunction with H56	*	
		Not in conjunction with P22		
		Not in conjunction with P29	*	
		Not in conjunction with P75	*	
		Not in conjunction with U26		
		Only in conjunction with 275+P14+P49	*	
		Only in conjunction with U22	*	
125A	ARTICO man-made leather macchiato beige / black		●	472,50
			—	0,00
		Not in conjunction with 248	*	
		Not in conjunction with 336	*	
		Not in conjunction with 401/61U/872/P65/PBR	*	
		Not in conjunction with 450/H73/L5C	*	
		Not in conjunction with H56	*	
		Not in conjunction with P22		
		Not in conjunction with P29	*	
		Not in conjunction with P75	*	
		Not in conjunction with U26		
		Only in conjunction with 275+P14+P49	*	
		Only in conjunction with U22	*	
128A	ARTICO man-made leather alpaca grey		●	472,50
		Not in conjunction with 248	*	
		Not in conjunction with 401/51U/55U/61U/65U/872/P65/PBR	*	
		Not in conjunction with 450/H73/L5C	*	
		Not in conjunction with H56	*	
		Not in conjunction with P22		
		Not in conjunction with P29	*	
		Not in conjunction with P75	*	
		Not in conjunction with U26		
		Only in conjunction with 275+88U+P14+P49	*	
		Only in conjunction with U22	*	
12B	Owner's Manual and Service Booklet - Engl. USA/CAN		○	0,00
12U	Preinstallation for Concierge Service		●	105,00
12Z	Dayt. run. lamps flashing, night-time, emerg. veh.		○	0,00
		Not in conjunction with 19U/337/341/342/344/934/938/965	*	
		Not in conjunction with 19U/965		
		Not in conjunction with 248/344/450/934/938		
		Not in conjunction with 248	*	
		Not in conjunction with 337/341/342/623U		
		Not in conjunction with 413/414/810/297		
		Not in conjunction with 413/414/810	*	

		Not in conjunction with 450/623U	*	
		Not in conjunction with 811	*	
		Not in conjunction with 837		
		Not in conjunction with B63		
		Not in conjunction with Z97	*	
		Only in conjunction with Z90	*	
13B	Owner's Manual and Service Booklet - Norwegian		○	0,00
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/14B/15B/16B/17B/30B/31B/32B/33B/34	*	
		Not in conjunction with 22B	*	
14B	Owner's Manual and Service Booklet - Greek		○	0,00
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/13B/15B/16B/17B/30B/31B/32B/33B/34	*	
		Not in conjunction with 22B	*	
15B	Owner's Manual and Service Booklet - Turkish		○	0,00
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/13B/14B/16B/17B/30B/31B/32B/33B/34	*	
		Not in conjunction with 22B	*	
15U	Preinstallation for Mercedes-Benz Link		S	0,00
16B	Owner's Manual and Service Booklet - Polish		○	0,00
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/13B/14B/15B/17B/30B/31B/32B/33B/34	*	
		Not in conjunction with 22B	*	
16U	Smartphone integration (Apple CarPlay™)		○	0,00
		Only in conjunction with 14U+17U	*	
17B	Owner's Manual and Service Booklet - Czech		○	0,00
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/13B/14B/15B/16B/30B/31B/32B/33B/34	*	
		Not in conjunction with 22B	*	
17U	Smartphone integration (Android Auto)		○	0,00
		Only in conjunction with 14U+16U	*	
18B	Owner's Manual and Service Booklet - Engl. S. Am.		○	0,00
18U	Baidu Carlife		-	0,00
19B	Owner's Manual and Service Booklet - French S. Am.		○	0,00
19U	Smartphone integration mirrorlink (Mercedes-Benz Link)		●	157,50
		Not in conjunction with 001A/101A/H56/P75		
		Not in conjunction with 10Z/11Z/12Z/24Z/50Z/96Z/970/974/975/B12/Z30	*	
		Not in conjunction with 356	*	
		Not in conjunction with 413	*	
		Not in conjunction with 489		
		Not in conjunction with 811	*	
		Not in conjunction with 978		
		Not in conjunction with R06		
		Not in conjunction with RVO/RVR	*	
		Not in conjunction with Z87	*	
		Not in conjunction with Z90	*	
		Not in conjunction with Z97	*	
		Only in conjunction with 965	*	
		Only for left hand drive		
1R7	7-twin-spoke alloy wheel w. winter tyre 43.2 cm (17")		●	1.837,50
		Not in conjunction with 459	*	
		Not in conjunction with 4R3/844/978		
		Not in conjunction with 601A/811A/B24A/H73/L5C/P29/P31/RRD/U26		
		Not in conjunction with 645/U29	*	
20B	Owner's Manual and Service Booklet - Spanish S. Am.		○	0,00
21B	Owner's Manual and Service Booklet - Portug. S. Am.		○	0,00
22B	Owner's Manual and Service Booklet - Japanese		○	0,00
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/13B/14B/15B/16B/17B/30B/31B/32B/33	*	
		Only for right hand drive		
233	DISTRONIC PLUS		○	0,00
		Not in conjunction with 22P/234	*	
		Not in conjunction with 258	*	
		Only in conjunction with P49	*	
23B	Owner's Manual and Service Booklet - simpl. Chinese		-	0,00
23U	Active traffic-assist		○	0,00
		Not in conjunction with 001A	*	
		Not in conjunction with 101A	*	
		Not in conjunction with 220	*	
		Not in conjunction with 22P/234	*	
		Not in conjunction with 258	*	
		Not in conjunction with 555/PBX		
		Not in conjunction with H56	*	
		Not in conjunction with P75	*	
		Not in conjunction with PBZ		
		Only in conjunction with 235+513+546+K33+K34+P20	*	
		Only in conjunction with 365+P49	*	
24B	Rear seats with integrated child seats		●	819,00

		Not in conjunction with 10Z/11Z/12Z/55U/61U/65U/872/970/974/975/P87	*	
		Not in conjunction with 24Z/96Z/Z30		
		Not in conjunction with 356	*	
		Not in conjunction with 413	*	
		Not in conjunction with 489		
		Not in conjunction with 50Z/B12	*	
		Not in conjunction with 811	*	
		Not in conjunction with 88U		
		Not in conjunction with 978		
		Not in conjunction with H56/P75		
		Not in conjunction with H73/H78/L5C/P29/U26	*	
		Not in conjunction with P14	*	
		Not in conjunction with P31/RRD		
		Not in conjunction with R06		
		Not in conjunction with RVQ/RVR	*	
		Not in conjunction with U04/U38		
		Not in conjunction with Z87	*	
		Not in conjunction with Z90	*	
		Not in conjunction with Z97	*	
		Only in conjunction with 101A	*	
		Only in conjunction with 876		
		Only in conjunction with P22		
		Only in conjunction with [965]		
		Only for left hand drive		
24B	Owner's Manual and Service Booklet - trad. Chinese		○	0,00
24Z	Pre-installation for TETRA mobile radio, Sepura		●	147,00
		Not in conjunction with 19U/341/342/934/965	*	
		Not in conjunction with 248		
		Not in conjunction with 337		
		Not in conjunction with 344/938		
		Not in conjunction with 413/414/810	*	
		Not in conjunction with 450	*	
		Not in conjunction with 623U		
		Not in conjunction with 811	*	
		Not in conjunction with 837		
		Not in conjunction with B63		
		Not in conjunction with Z97	*	
		Only in conjunction with Z90		
		Only for left hand drive	*	
251	Increase in top speed, USA		—	0,00
25B	Owner's Manual and Service Booklet - Korean		○	0,00
263	Number plate mounting for Asia / Mexico		○	0,00
264	Number plate mounting for America		○	0,00
26B	Owner's Manual and Service Booklet - Chinese Taiwan		○	0,00
26U	Preinstallation for engine remote start		●	105,00
		i.V.m. S-Code PZG	—	52,50
270	Aerial for GPS		○	0,00
274	Telephone aerial		○	0,00
		Not in conjunction with 301/333/897	*	
		Not in conjunction with Z30		
27B	Owner's Manual and Service Booklet - Spanish Mexico		—	0,00
309	Double cup holder		○	0,00
		Available only as part of (30P)	*	
		Not in conjunction with 333/938	*	
		Only in conjunction with 30P	*	
30B	Owner's Manual and Service Booklet - Slovenian		○	0,00
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/13B/14B/15B/16B/17B/31B/32B/33B/34	*	
		Not in conjunction with 22B	*	
31B	Owner's Manual and Service Booklet - Hungarian		○	0,00
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/13B/14B/15B/16B/17B/30B/32B/33B/34	*	
		Not in conjunction with 22B	*	
32B	Owner's Manual and Service Booklet - Bulgarian		○	0,00
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/13B/14B/15B/16B/17B/30B/31B/33B/34	*	
		Not in conjunction with 22B	*	
333	Special instrument panel		●	84,00
		Not in conjunction with 274	*	
		Not in conjunction with 301/309/897/899	*	
		Not in conjunction with 30P/810		
		Not in conjunction with 413	*	
		Not in conjunction with 811	*	
		Not in conjunction with B63		
		Not in conjunction with Z97	*	

334	Preinstallation for two-way radio in glove compartment		●	94,50
		Not in conjunction with 335/P21/PBP/PBR	*	
		Not in conjunction with 413	*	
		Not in conjunction with 811	*	
		Not in conjunction with B63		
		Not in conjunction with Z97	*	
		Only for left hand drive	*	
		i.V.m. Code 450	○	0,00
335	Preinstallation for two-way radio in boot		●	94,50
		Not in conjunction with 334/B65	*	
		Not in conjunction with 413	*	
		Not in conjunction with 811	*	
		Not in conjunction with B63		
		Not in conjunction with Z97	*	
		Only for left hand drive	*	
		i.V.m. Code 450	○	0,00
336	Preinstallation for taximeter		●	57,75
		Not in conjunction with 301/51U/551/55U/61U/65U/77B/882/P54/P82/P87	*	
		Not in conjunction with 413	*	
		Not in conjunction with 810	*	
		Not in conjunction with 811	*	
		Not in conjunction with B63		
		Not in conjunction with U04/U38		
		Not in conjunction with Z97	*	
		Only in conjunction with [001A]	*	
		Only in conjunction with [101A]	*	
		Only in conjunction with [121A]	*	
		Only in conjunction with [128A/131A/201A/208A/301A/801A]	*	
		i.V.m. Code 450	○	0,00
337	Taximeter integrated in the rear-view mirror		●	1.039,50
		Not in conjunction with 001A/101A/H56/P75		
		Not in conjunction with 10Z/11Z/12Z/231/77B/970/974/975	*	
		Not in conjunction with 24Z/96Z/Z30		
		Not in conjunction with 356	*	
		Not in conjunction with 413	*	
		Not in conjunction with 489		
		Not in conjunction with 50Z/B12	*	
		Not in conjunction with 601A/811A/824A/H73/L5C/P29/P31/RRD/U26		
		Not in conjunction with 811	*	
		Not in conjunction with 978		
		Not in conjunction with R06		
		Not in conjunction with RVQ/RVR	*	
		Not in conjunction with Z87	*	
		Not in conjunction with Z90	*	
		Not in conjunction with Z97	*	
		Only in conjunction with 965		
		Only for left hand drive		
338	Owner's Manual and Service Booklet - Romanian		○	0,00
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/13B/14B/15B/16B/17B/30B/31B/32B/34	*	
		Not in conjunction with 22B	*	
341	Taxi single arm roof sign		●	257,25
		Not in conjunction with 001A/101A/H56/P75		
		Not in conjunction with 10Z/11Z/12Z/24Z/50Z/96Z/970/974/975/B12/Z30	*	
		Not in conjunction with 356	*	
		Not in conjunction with 413	*	
		Not in conjunction with 489		
		Not in conjunction with 601A/811A/824A/H73/L5C/P29/P31/RRD/U26		
		Not in conjunction with 720/P55/U50		
		Not in conjunction with 811	*	
		Not in conjunction with 978		
		Not in conjunction with R06		
		Not in conjunction with RVQ/RVR	*	
		Not in conjunction with Z87	*	
		Not in conjunction with Z90	*	
		Not in conjunction with Z97	*	
		Only in conjunction with 342	*	
		Only in conjunction with 725		
		Only in conjunction with 965		
		Only for left hand drive		
342	Connection, taxi roof sign		●	73,50
		Not in conjunction with 001A/101A/H56/P75		
		Not in conjunction with 10Z/11Z/12Z/24Z/50Z/96Z/970/974/975/B12/Z30	*	

		Not in conjunction with 356	*	
		Not in conjunction with 413	*	
		Not in conjunction with 489		
		Not in conjunction with 601A/811A/824A/H73/L5C/P29/P31/RRD/U26		
		Not in conjunction with 720/P55/U50		
		Not in conjunction with 811	*	
		Not in conjunction with 978		
		Not in conjunction with R06		
		Not in conjunction with RVQ/RVR	*	
		Not in conjunction with Z87	*	
		Not in conjunction with Z90	*	
		Not in conjunction with Z97	*	
		Only in conjunction with 725		
		Only in conjunction with 965		
		Only for left hand drive		
344	Antenna pre-installation for taxi		●	162,75
		Not in conjunction with 001A/101A/H56/P75		
		Not in conjunction with 10Z/11Z/12Z/356/970/974/975	*	
		Not in conjunction with 24Z/50Z/96Z/B12/Z30		
		Not in conjunction with 413	*	
		Not in conjunction with 489		
		Not in conjunction with 811	*	
		Not in conjunction with 978		
		Not in conjunction with RVQ/RVR	*	
		Not in conjunction with Z87	*	
		Not in conjunction with Z90	*	
		Not in conjunction with Z97	*	
		Only in conjunction with 274	*	
		Only in conjunction with 965		
		Only for left hand drive	*	
34B	Owner's Manual and Service Booklet - Croatian		○	0,00
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/13B/14B/15B/16B/17B/30B/31B/32B/33	*	
		Not in conjunction with 22B	*	
356	Roof-mounted radio aerial		●	204,75
		Not in conjunction with 19U	*	
		Not in conjunction with 248	*	
		Not in conjunction with 337/341/342/965	*	
		Not in conjunction with 344	*	
		Not in conjunction with 413	*	
		Not in conjunction with 623U	*	
		Not in conjunction with 810		
		Not in conjunction with 811	*	
		Not in conjunction with 934		
		Not in conjunction with B63		
		Not in conjunction with Z97	*	
35B	Owner's Manual and Service Booklet - Latvian		○	0,00
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/13B/14B/15B/16B/17B/30B/31B/32B/33	*	
		Not in conjunction with 22B	*	
36B	Owner's Manual and Service Booklet - Lithuanian		○	0,00
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/13B/14B/15B/16B/17B/30B/31B/32B/33	*	
		Not in conjunction with 22B	*	
37B	Owner's Manual and Service Booklet - Slovakian		○	0,00
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/13B/14B/15B/16B/17B/30B/31B/32B/33	*	
		Not in conjunction with 22B	*	
38B	Owner's Manual and Service Booklet - Estonian		○	0,00
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/13B/14B/15B/16B/17B/30B/31B/32B/33	*	
		Not in conjunction with 22B	*	
39B	Owner's Manual and Service Booklet - Serbian		○	0,00
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/13B/14B/15B/16B/17B/30B/31B/32B/33	*	
		Not in conjunction with 22B	*	
3R6	10-spoke alloy wheel w. winter tyre 48.3 cm (19")		●	2.992,50
40B	Owner's Manual and Service Booklet - ukrainian		○	0,00
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/13B/14B/15B/16B/17B/30B/31B/32B/33	*	
		Not in conjunction with 22B	*	
41B	Owner's Manual and Service Booklet - hebrew		○	0,00
42B	Owner's Manual and Service Booklet - Indonesian		○	0,00
431	Galvanised steering-wheel gearshift paddles		○	0,00
43B	Owner's Manual and Service Booklet - Thai		○	0,00
450	Taxi version, international		●	0,00
450		Not in conjunction with 10Z/11Z/12Z/24Z/50Z/61U/65U/960/962/970/974/975/B12/H73/L5C/P22/P29/P87/U12/U26/Z3	*	
450		Not in conjunction with 413	*	
450		Not in conjunction with 489		

450		Not in conjunction with 811	*	
450		Not in conjunction with 978		
450		Not in conjunction with R06		
450		Not in conjunction with RVQ/RVR	*	
450		Not in conjunction with Z87	*	
450		Not in conjunction with Z90	*	
450		Not in conjunction with Z97	*	
450		Only in conjunction with 670+837+965	*	
450		Only in conjunction with [101A]	*	
450		Only in conjunction with [201A/214A/215A]	*	
450		Only for left hand drive	*	
460	Canada specification		-	0,00
461	Instrument cluster with display in miles and English let		○	0,00
472	Petrol particulate filter		-	0,00
477	Tyre pressure loss warning system		○	0,00
494	USA specification		-	0,00
498	Japan specification		○	0,00
4R3	18" 5-spoke light-alloy wheel painted in black with a hi		-	2.520,00
		Not in conjunction with 1R7/R43		
		Not in conjunction with 413/432/436/550/82R/942/PBR/RVQ/RVR		
		Not in conjunction with 645		
		Not in conjunction with 978		
		Not in conjunction with R66		
		Only in conjunction with 844		
4R6	complete winter (M+S) wheel-and-tyre assembly x 4		-	2.625,00
		Not in conjunction with 645		
4R7	Complete winter wheel, 5-spoke, 18-inch, light-alloy		●	2.362,50
501	360° camera		○	0,00
		Available only as part of (P47)	*	
		Not in conjunction with Z18	*	
		Not in conjunction with Z20	*	
		Not in conjunction with 978		
		Not in conjunction with P44	*	
		Only in conjunction with P47	*	
		Only in conjunction with P49	*	
50Z	Conversion parts for emergency vehicles		○	0,00
		Not in conjunction with 19U/341/342/934/965	*	
		Not in conjunction with Z48	*	
		Not in conjunction with 337	*	
		Not in conjunction with 344/938		
		Not in conjunction with 413/414/810	*	
		Not in conjunction with 450	*	
		Not in conjunction with 623U	*	
		Not in conjunction with 811	*	
		Not in conjunction with 837		
		Not in conjunction with B63		
		Not in conjunction with Z97	*	
		Only in conjunction with Z90		
517	HD digital radio standard		○	0,00
524	Transport protection (full body cover)		●	168,00
		with 000U, 044U, 049U, Z01, Z02 or Z98 added	*	
536	Sirius satellite radio		-	708,75
548	CONNECT 20 MID (NTG6)		○	0,00
		Not in conjunction with Z56		
		Not in conjunction with 549/865/PBP/PBR/U19	*	
549	MBUX multimedia system		○	0,00
		Not in conjunction with 548	*	
551	Anti-theft alarm system with preinstallation for collisio		○	0,00
		Not in conjunction with 336	*	
552	Anti-theft alarm system with preinstallation for collisio		○	0,00
596	Tinted and IR-reflecting laminated glass		○	0,00
		Available only as part of (PAF)	*	
		Not in conjunction with 840	*	
		Only in conjunction with PAF	*	
602	CKD vehicles for Russia		-	0,00
608	Adaptive Highbeam Assist		●	189,00
		Not in conjunction with 628/642/P35	*	
		Only in conjunction with 632	*	
		i.V.m. Code PYA	○	0,00
623	Gulf States specification		-	0,00
623U	light ivory		○	0,00
		Not in conjunction with 10Z/11Z/12Z/970/974/975	*	

		Not in conjunction with 24Z/601A/811A/824A/962/H73/L5C/P29/P31/RRD/U26/Z30		
		Not in conjunction with 356/50Z/B12	*	
		Not in conjunction with 413	*	
		Not in conjunction with 489		
		Not in conjunction with 811	*	
		Not in conjunction with 978		
		Not in conjunction with R06		
		Not in conjunction with RVQ/RVR	*	
		Not in conjunction with Z87	*	
		Not in conjunction with Z90	*	
		Not in conjunction with Z97	*	
		Only in conjunction with 965		
		Only for left hand drive		
625	Australia specification		○	0,00
628	Adaptive Highbeam Assist Plus		○	0,00
		Available only as part of (P35)	*	
		Not in conjunction with 608/632	*	
		Only in conjunction with P35	*	
631	LED High Performance headlamps		○	0,00
		only Left hand drive	*	
634	Omission of first-aid kit		○	0,00
636	Omission of warning triangle		○	0,00
63B	Charging socket for electric and plug-in hybrid vehicles		–	0,00
640	LED Intelligent Light System (LHD)		–	0,00
641	LED Intelligent Light System (RHD)		○	0,00
642	LED Intelligent Light System (LHD)		○	0,00
		Available only as part of (P35)	*	
		Not in conjunction with 608/632	*	
		Only in conjunction with P35	*	
64B	Vehicle socket		–	0,00
651	Winter complete wheels fitted		○	0,00
		Not in conjunction with 413/432/436/550/82R/942/PBR/RVQ/RVR		
		Not in conjunction with 459/U29	*	
		Not in conjunction with 601A/811A/824A/H73/L5C/P29/P31/RRD/U26		
		Not in conjunction with 645	*	
		Not in conjunction with 652	*	
		Not in conjunction with 978		
		Not in conjunction with R66		
		Only in conjunction with 1R7	*	
		Only in conjunction with 4R3		
		Only in conjunction with 4R6		
		Only in conjunction with 844		
		Only in conjunction with 9R2		
652	Summer complete tyres fitted		○	0,00
		Not in conjunction with 413/432/436/550/82R/942/PBR/RVQ/RVR		
		Not in conjunction with 459/U29	*	
		Not in conjunction with 601A/811A/824A/H73/L5C/P29/P31/RRD/U26		
		Not in conjunction with 645	*	
		Not in conjunction with 651	*	
		Not in conjunction with 978		
		Not in conjunction with R66		
		Only in conjunction with 1R7	*	
		Only in conjunction with 4R3		
		Only in conjunction with 4R6		
		Only in conjunction with 844		
		Only in conjunction with 9R2		
65B	FAHRZEUGS. XEV-LADEDÖSE CHINA STANDARD GB/T		–	0,00
666	Freight packaging without tie-down hooks		●	0,00
668	Prod. prot. f. freight pkging with tie-down hooks		●	26,25
66B	Charging socket		–	0,00
66R	45.7 cm (18-inch) 5-twin-spoke light-alloy wheels		–	735,00
			–	0,00
		i.V.m. Code P15	–	210,00
670	Residual engine heat utilisation		○	0,00
		Not in conjunction with 580	*	
		Only in conjunction with 581		
687	Type plate with model year		○	0,00
690	Pre-installation for the spare wheel		○	0,00
6U7	BlueTEC diesel emission control system including gene		○	0,00
6U8	Location and tracking system		–	336,00
701	CKD vehicles, Thailand		○	0,00
717	CKD vehicles for Vietnam		–	0,00

718	CKD vehicles for Malaysia		-	0,00
719	Indonesia SKD		-	1,05
762	Key with radio remote control		○	0,00
763	Key with Radio remote control with panic switch		○	0,00
768	Alternating current charging system (AC charging)		-	0,00
772	AMG bodystyling		○	0,00
		Available only as part of (P31)		
		Not in conjunction with 001A	*	
		Not in conjunction with 101A	*	
		Not in conjunction with 82R	*	
		Not in conjunction with 978		
		Not in conjunction with H56	*	
		Not in conjunction with P75	*	
775U	iridium silver metallic		●	913,50
776	Wider wheel arch for AMG wheels		○	0,00
		Not in conjunction with 001A/101A		
		Not in conjunction with 22R		
		Not in conjunction with 645		
		Not in conjunction with 82R	*	
		Not in conjunction with H56		
		Not in conjunction with P15		
		Not in conjunction with P23/P75		
		Not in conjunction with R32	*	
		Not in conjunction with R43	*	
		Not in conjunction with R90		
		Only in conjunction with [772]		
		Only in conjunction with [P31]		
7U0	Powerdome on bonnet		○	0,00
		Not in conjunction with P23	*	
801	Technical modifications		○	0,00
817	Encapsulation for ATA alarm siren		○	0,00
820	Tourist vehicle		○	0,00
821	Country code Brazil		-	0,00
822	South Africa specification		○	0,00
823	Indicator plate fixing Switzerland		○	0,00
824	Additional parts for cold countries		○	0,00
829	Taiwan version		○	0,00
830	China specification		-	0,00
831	Indicator plate fixing Italia		○	0,00
834	New Zealand specification		○	0,00
835	South Korea specification		○	0,00
837	Boot liner - rubber mat		●	189,00
		Not in conjunction with 001A/101A/H56/P75		
		Not in conjunction with 10Z/11Z/12Z/24Z/50Z/96Z/970/974/975/B1Z/Z30/Z87/Z90		
		Not in conjunction with 413	*	
		Not in conjunction with 601A/811A/824A/H73/L5C/P29/P87/U12/U26	*	
		Not in conjunction with 811	*	
		Not in conjunction with B63		
		Not in conjunction with Z97	*	
		Only in conjunction with 965		
		Only for left hand drive	*	
		i.V.m. Code 450	○	0,00
838	Direct current charging system (DC charging)		-	525,00
852	Sensor system for anti-theft alarm system		-	0,00
876	Interior Light package		○	0,00
		Not in conjunction with 001A	*	
		Not in conjunction with 101A	*	
		Not in conjunction with H56	*	
		Not in conjunction with P75	*	
879	Removable ashtray insert		○	0,00
885	Increased anti-theft protection		●	63,00
896U	brilliant blue metallic		-	913,50
8R4	Complete winter wheel - AMG twin-spoke design, 19"		-	3.675,00
906	Armrest heating for driver and front passenger		○	0,00
		Available only as part of (P68)	*	
		Not in conjunction with 001A	*	
		Not in conjunction with 101A	*	
		Not in conjunction with 555/621A/PBX		
		Not in conjunction with 873/P65	*	
		Not in conjunction with H56	*	
		Not in conjunction with P75	*	
		Not in conjunction with PBZ		

		Only in conjunction with 275+P68	*	
		Only in conjunction with P49	*	
		Only in conjunction with U22	*	
913	Engine pre-installation for climate control system		○	0,00
922	Reduced power version		○	0,00
926	Emission control system with EU4 technology		○	0,00
927	EU6 emissions standard		○	0,00
		Only in conjunction with 961		
934	Taxi/hire car emergency alarm system		●	257,25
		Not in conjunction with 001A/101A/H56/P75		
		Not in conjunction with 10Z/11Z/12Z/24Z/50Z/96Z/970/974/975/B12/B67/B68/Z30	*	
		Not in conjunction with 356/601A/811A/824A/H73/L5C/P29/P31/RRD/U26		
		Not in conjunction with 413	*	
		Not in conjunction with 489		
		Not in conjunction with 811	*	
		Not in conjunction with 978		
		Not in conjunction with RVQ/RVR	*	
		Not in conjunction with Z87	*	
		Not in conjunction with Z90	*	
		Not in conjunction with Z97	*	
		Only in conjunction with 965		
		Only for left hand drive	*	
937	Reinforcement package		–	556,50
			○	0,00
938	Preinst. for 2-way radio hands-free system		●	157,50
		Not in conjunction with 001A/101A/H56/P75		
		Not in conjunction with 10Z/11Z/12Z/309/970/974/975	*	
		Not in conjunction with 24Z/50Z/96Z/B12/Z30		
		Not in conjunction with 413	*	
		Not in conjunction with 489		
		Not in conjunction with 811	*	
		Not in conjunction with 978		
		Not in conjunction with RVQ/RVR	*	
		Not in conjunction with Z87	*	
		Not in conjunction with Z90	*	
		Not in conjunction with Z97	*	
		Only in conjunction with 965		
		Only for left hand drive	*	
943	Payment system for tolls		●	210,00
945	Emission Control China Stage 6B		–	0,00
947	Pennant holder and pennant staff left		●	997,50
948	Pennant holder and pennant staff right		●	997,50
960	Government version		○	0,00
		Not in conjunction with 450	*	
		Not in conjunction with 974/975	*	
		Only for left hand drive	*	
961	Petrol particulate filter		–	0,00
962	Preparation for signal unit (light bar)		●	168,00
		Not in conjunction with 19U/341/342/934/965	*	
		Not in conjunction with 248		
		Not in conjunction with 337		
		Not in conjunction with 344/938		
		Not in conjunction with 413/414/810	*	
		Not in conjunction with 450	*	
		Not in conjunction with 623U		
		Not in conjunction with 811	*	
		Not in conjunction with 837		
		Not in conjunction with B63		
		Not in conjunction with Z97	*	
		Only in conjunction with 260	*	
		Only in conjunction with Z90		
		Only for left hand drive	*	
965	Taxi and hire car		●	519,75
965		Not in conjunction with 001A/101A/H56/P75		
965		Not in conjunction with 10Z/11Z/12Z/24Z/50Z/96Z/B12/Z30	*	
965		Not in conjunction with 356	*	
965		Not in conjunction with 413	*	
965		Not in conjunction with 489		
965		Not in conjunction with 601A/811A/824A/H73/L5C/P29/P31/RRD/U26		
965		Not in conjunction with 811	*	
965		Not in conjunction with 970/974/975/Z90	*	
965		Not in conjunction with 978		

965		Not in conjunction with R06		
965		Not in conjunction with RVQ/RVR	*	
965		Not in conjunction with Z87	*	
965		Not in conjunction with Z97	*	
965		Only for left hand drive		
966		I.V.m. Code 450	○	0,00
968	COC document EU6 without registration certificate part I		○	0,00
		only in conjunction with 927, U60 and 16U or 2U8	*	
969	COC document EU6 with registration certificate part II		○	0,00
970	Preparation for police vehicle		●	656,25
		Not in conjunction with 19U/337/341/342/344/934/938	*	
		Not in conjunction with 248	*	
		Not in conjunction with 413/414/810	*	
		Not in conjunction with 450/623U	*	
		Not in conjunction with 811	*	
		Not in conjunction with 837		
		Not in conjunction with 965	*	
		Not in conjunction with 974/975	*	
		Not in conjunction with Z97	*	
		Only in conjunction with Z90	*	
971	Diesel particulate filter		○	0,00
			-	#VALUE!
972	Exhaust system with DPF Generation 2.0		○	0,00
973	Designation as owner-driver rental vehicle		○	0,00
974	Preparation for fire service command vehicle		●	656,25
		Not in conjunction with 001A/101A/H56/P75		
		Not in conjunction with 19U/337/341/342/344/934/938	*	
		Not in conjunction with 248	*	
		Not in conjunction with 413/414/810/960	*	
		Not in conjunction with 450/623U	*	
		Not in conjunction with 811	*	
		Not in conjunction with 837		
		Not in conjunction with 965	*	
		Not in conjunction with 970/975	*	
		Not in conjunction with Z97	*	
		Only in conjunction with Z90	*	
975	Preparation for emergency doctor vehicle		●	656,25
		Not in conjunction with 001A/101A/H56/P75		
		Not in conjunction with 19U/337/341/342/344/934/938	*	
		Not in conjunction with 248	*	
		Not in conjunction with 413/414/810/960	*	
		Not in conjunction with 450/623U	*	
		Not in conjunction with 811	*	
		Not in conjunction with 837		
		Not in conjunction with 965	*	
		Not in conjunction with 970/974	*	
		Not in conjunction with Z97	*	
		Only in conjunction with Z90	*	
978	Vehicle for bodybuilder		-	0,00
		Not in conjunction with 19U/22P/234/235/23U/248/266/293/337/341/342/344/413/414/450/546/550/601A/623U/732/733/734/735/736/737/738/739/740/741/742/743/744/745/746/747/748/749/750/751/752/753/754/755/756/757/758/759/760/761/762/763/764/765/766/767/768/769/770/771/772/773/774/775/776/777/778/779/780/781/782/783/784/785/786/787/788/789/790/791/792/793/794/795/796/797/798/799/800/801/802/803/804/805/806/807/808/809/810/811/812/813/814/815/816/817/818/819/820/821/822/823/824/825/826/827/828/829/830/831/832/833/834/835/836/837/838/839/840/841/842/843/844/845/846/847/848/849/850/851/852/853/854/855/856/857/858/859/860/861/862/863/864/865/866/867/868/869/870/871/872/873/874/875/876/877/878/879/880/881/882/883/884/885/886/887/888/889/890/891/892/893/894/895/896/897/898/899/900/901/902/903/904/905/906/907/908/909/910/911/912/913/914/915/916/917/918/919/920/921/922/923/924/925/926/927/928/929/930/931/932/933/934/935/936/937/938/939/940/941/942/943/944/945/946/947/948/949/950/951/952/953/954/955/956/957/958/959/960/961/962/963/964/965/966/967/968/969/970/971/972/973/974/975/976/977/978/979/980/981/982/983/984/985/986/987/988/989/990/991/992/993/994/995/996/997/998/999/1000		
		Not in conjunction with 1R7/844		
		Not in conjunction with 4R3/652		
		Not in conjunction with 651		
		Not in conjunction with 942		
		Not in conjunction with R66/R97/RVQ/RVR		
		Not in conjunction with RRD		
981	Omission of vehicle registration document		○	0,00
986	Identification no. (US-VIN)		○	0,00
989	Identification label under windshield		○	0,00
997	Exhibition vehicle		○	0,00
9R2	Complete winter (M+S) wheel-and-tyre assembly x 4		-	3.675,00
B01	EQ Boost starter-alternator		○	0,00
B08	Electronic fanfare		○	0,00
B21	Charging cable for domestic socket, 5 m, straight		-	0,00
B34	Charging cable for wallbox and public charging stations		-	283,50
B39	Charging cable for domestic socket, 5 m, straight		-	0,00
B40	Charging cable for domestic socket, 4 m, straight		-	0,00
B41	Charging cable for domestic socket, 5 m, straight		-	0,00
B44	Charging cable for domestic socket, 5 m, straight		-	0,00
B47	Charging cable for domestic socket, 5 m, straight		-	0,00
B48	Charging cable for domestic socket, 5 m, straight		-	0,00
B70	Charging cable for domestic socket, 5 m, straight		-	0,00

B71	Charging cable for domestic socket, 5 m, straight		-	0,00
B73	Charging cable for domestic socket, 5 m, straight		-	0,00
B75	Charging cable for domestic socket, 8 m, straight		-	73,50
B77	Charging cable for domestic socket, 8 m, straight		-	73,50
B78	Charging cable for domestic socket, 8 m, straight		-	73,50
B84	Charging cable for domestic socket, 8 m, straight		-	73,50
B85	Charging cable for domestic socket, 8 m, straight		-	73,50
B86	Charging cable for domestic socket, 8 m, straight		-	0,00
B88	Charging cable for domestic socket, 8 m, straight		-	73,50
B89	Charging cable for domestic socket, 8 m, straight		-	73,50
B96	Charging cable for domestic socket, 8 m, straight		-	73,50
B98	Charging cable for domestic socket, 8 m, straight		-	73,50
B99	Charging cable for domestic socket, 8 m, straight		-	73,50
E02	Kleiderbügel		○	0,00
		Not in conjunction with 555/PBX		
		Not in conjunction with PBZ		
		Only in conjunction with 866	*	
		Only for left hand drive		
E07	Positioning and Tracking System		-	336,00
E76	Spare wheel		●	315,00
E79	iPod Interface Kit		-	0,00
		Only for left hand drive		
K11	Adaptive brake lights		S	0,00
K32	Active Lane Change Assist		○	0,00
K33	Extended automatic Re-start in traffic jams		○	0,00
		Not in conjunction with 220	*	
		Not in conjunction with 22P/234/258	*	
		Not in conjunction with 978	*	
		Only in conjunction with 233+235+513+546+K34	*	
		Only in conjunction with 365+P49	*	
K34	Route-based speed adaptation		○	0,00
		Not in conjunction with 22P/234/258	*	
		Not in conjunction with 978	*	
		Only in conjunction with 233+513+546	*	
		Only in conjunction with 365+P49	*	
L	Left-hand drive		○	0,00
P53	Fine particle sensor		-	0,00
PYA	Base package		●	0,00
PYB	SE Package		●	0,00
PYC	SE Plus Package		-	0,00
PYE	Avantgarde Line		●	1.470,00
PYF	EXCLUSIVE Line		●	2.530,00
PYG	AMG/AVANTGARDE Line		●	4.560,00
			-	4.110,00
PYJ	AMG/Avantgarde Line Light		-	0,00
PYH	AMG Line		●	5.440,00
			-	4.990,00
PYM	Advantage Package		●	2.342,00
PYN	Premium Package		●	4.832,00
PYO	Premium Plus package		●	7.661,00
R	Right-hand drive		●	1.905,75
R02	All-season tyres		-	0,00
R05	Summer tyres		-	0,00
		Not in conjunction with 250/B51/R01/R06		
		Only in conjunction with R66+RTA		
R26	48.3 cm (19") 10-spoke light-alloy wheels		-	1.575,00
			-	840,00
U01	Status display for rear seat belts in instrument cluster		○	0,00
U04	designo floor mats		○	0,00
		Available only as part of (P87)	*	
		Not in conjunction with 001A	*	
		Not in conjunction with 101A	*	
		Not in conjunction with 248	*	
		Not in conjunction with 336	*	
		Not in conjunction with 450/601A/811A/824A/837/H73/L5C/P29/U26	*	
		Not in conjunction with 51U/P65/U09	*	
		Not in conjunction with H56	*	
		Not in conjunction with P75	*	
		Not in conjunction with U12	*	
		Only in conjunction with P49+P87	*	
		Only in conjunction with U22	*	
U13	Badge for special model		○	0,00

U16	Exhaust system with acoustic flap		–	0,00
U32	Two additional master keys		●	157,50
		Not in conjunction with B67/B68	*	
		Only for left hand drive	*	
U41	Fuel/water separator and lubrication package		○	0,00
U60	Pedestrian protection		○	0,00
U66	Floormats special model		○	0,00
U79	BlueTEC diesel emission control system including AdBlue		●	0,00
U80	115 V socket		–	126,00
U90	Low-Line package China		–	0,00
U91	Mid-Line-package China		–	0,00
		Only for left hand drive		
U93	AMG spoiler lip in carbon fibre on boot lid		–	0,00
		Not in conjunction with U47		
		Only in conjunction with B28		
Z01	Paint not feat.on standard sample card		○	0,00
		Not in conjunction with Z02/Z98	*	
		Only in conjunction with 524	*	
Z02	Paint not feat.on standard sample card		○	0,00
		Not in conjunction with Z01/Z98	*	
		Only in conjunction with 524	*	
Z30	Motor continuity circuit		○	0,00
		Not in conjunction with 19U/341/342/934/965	*	
		Not in conjunction with 248		
		Not in conjunction with 274		
		Not in conjunction with 337		
		Not in conjunction with 344/938		
		Not in conjunction with 413/414/810/897/899	*	
		Not in conjunction with 450	*	
		Not in conjunction with 623U		
		Not in conjunction with 811	*	
		Not in conjunction with 837		
		Not in conjunction with B63		
		Not in conjunction with Z97	*	
		Only in conjunction with Z90		
		Only for left hand drive	*	
Z87	Monitor activation in special-purpose vehicles		●	63,00
		Not in conjunction with 19U/337/341/342/344/938/965	*	
		Not in conjunction with 248	*	
		Not in conjunction with 413/414/810	*	
		Not in conjunction with 450/623U	*	
		Not in conjunction with 811	*	
		Not in conjunction with 837		
		Not in conjunction with B63		
		Not in conjunction with Z97	*	
		Only in conjunction with Z90	*	
Z88	Deactivation of ext. lights, sp-purpose vehicles		○	0,00
Z90	Multifunction control unit for special functions		●	399,00
		Not in conjunction with 19U/337/341/342/344/934/938	*	
		Not in conjunction with 248	*	
		Not in conjunction with 413/414/810	*	
		Not in conjunction with 450/623U	*	
		Not in conjunction with 811	*	
		Not in conjunction with 837		
		Not in conjunction with 965	*	
		Not in conjunction with B63		
		Not in conjunction with Z97	*	
Z97	Electronic interface for remote control		●	399,00
		Not in conjunction with 001A/101A/H56/P75		
		Not in conjunction with 05Z/06Z/19U/333/334/335/337/341/342/344/356/934/938	*	
		Not in conjunction with 10Z/11Z/12Z/962/Z30	*	
		Not in conjunction with 248	*	
		Not in conjunction with 24Z/50Z/970/974/975/B12	*	
		Not in conjunction with 336	*	
		Not in conjunction with 450/623U	*	
		Not in conjunction with 837	*	
		Not in conjunction with 965	*	
		Not in conjunction with Z87	*	
		Not in conjunction with Z90	*	
		Only in conjunction with B63		
		Only for left hand drive	*	
Z98	Paint not feat.on standard sample card		○	0,00

		Not in conjunction with Z01/Z02	*	
		Only in conjunction with 524	*	
B12	Tyre-change toolkit		○	0,00
		Not in conjunction with 19U/341/342/934/965	*	
		Not in conjunction with 248	*	
		Not in conjunction with 337	*	
		Not in conjunction with 344/938		
		Not in conjunction with 413/414/810	*	
		Not in conjunction with 450	*	
		Not in conjunction with 623U	*	
		Not in conjunction with 811	*	
		Not in conjunction with 837		
		Not in conjunction with B63		
		Not in conjunction with Z97	*	
		Only in conjunction with Z90		
		i.V.m. Code 970/974/975	●	31,50
682	Fire extinguisher		●	0,00
70B	Fluorescent jacket for driver		●	5,25
		Not in conjunction with 71B	*	
71B	Safety vests for driver and passengers		●	26,25
		Not in conjunction with 70B	*	
293	Sidebags in rear		●	399,00
		Not in conjunction with 978		
294	Kneebag		S	0,00
258	Active Brake Assist		○	0,00
258		Not in conjunction with 233	*	
258		Not in conjunction with 23U/266/546/K33/K34	*	
292	PRE-SAFE® impulse side		○	0,00
		Available only as part of (P20)	*	
		Not in conjunction with 001A	*	
		Not in conjunction with 101A	*	
		Not in conjunction with 22P/234	*	
		Not in conjunction with 555/PBX		
		Not in conjunction with H56	*	
		Not in conjunction with P75	*	
		Not in conjunction with PBZ		
		Only in conjunction with P20	*	
		Only in conjunction with P49	*	
299	PRE-SAFE® system		S	0,00
266	Active Steering Assist		○	0,00
		Not in conjunction with 22P/234/258	*	
		Not in conjunction with 978		
		Only in conjunction with 233		
546	Active Speed Limit Assist		○	0,00
		Not in conjunction with 22P/234/258	*	
		Not in conjunction with 978		
		Only in conjunction with 233	*	
		Only in conjunction with P49	*	
22P	Lane Tracking package		●	819,00
		Includes codes 234+243	*	
		Not in conjunction with 233	*	
		Not in conjunction with 23P		
		Not in conjunction with 23U/266/546/K33/K34/P20	*	
		Only in conjunction with 258	*	
		Only in conjunction with P49	*	
		i.V.m. Code PYM/PYN/PYO	●	346,50
234	Blind Spot Assist		●	472,50
		Not in conjunction with 233	*	
		Not in conjunction with 23P		
		Not in conjunction with 23U/266/546/K33/K34/P20	*	
		Only in conjunction with 258	*	
		Only in conjunction with P49	*	
		i.V.m. Code 22P	○	0,00
		i.V.m. Code PYM/PYN/PYO	○	0,00
23P	Driving Assistance package		●	2.026,50
		Includes codes 233+266	*	
		Not in conjunction with 22P/234/23U	*	
		Only in conjunction with P49	*	
		i.V.m. Code PYM/PYN/PYO	●	1.554,00
243	Active Lane Keeping Assist		○	0,00
		Available only as part of (22P)	*	
		Not in conjunction with 233	*	

		Not in conjunction with 23P		
		Not in conjunction with 23U/266/546/K33/K34/P20	*	
		Only in conjunction with 22P+258	*	
		Only in conjunction with P49	*	
475	Tyre pressure monitoring system		●	320,25
			—	0,00
		i.V.m. S-Code 6P5	○	0,00
513	Traffic Sign Assist		●	309,75
		Only in conjunction with 365	*	
		i.V.m. Code PYA	○	0,00
P20	Driving Assistance package Plus		●	2.551,50
		Includes codes 233+266+292	*	
		Not in conjunction with 001A	*	
		Not in conjunction with 101A	*	
		Not in conjunction with 22P/234	*	
		Not in conjunction with 555/PBX	*	
		Not in conjunction with H56	*	
		Not in conjunction with P75	*	
		Not in conjunction with PBZ	*	
		Only in conjunction with P49	*	
		i.V.m. Code PYM/PYN/PYO	●	2.079,00
		i.V.m. Code PYM/PYN/PYO	—	2.047,50
218	Reversing camera		●	420,00
		Not in conjunction with 220	*	
		Not in conjunction with P47	*	
		i.V.m. Code P44	○	0,00
		i.V.m. Code PYA	—	0,00
220	Parking Assist PARKTRONIC		●	682,50
		Not in conjunction with 218/P47	*	
		Not in conjunction with 235/23U/K33/P44	*	
235	Active Parking Assist with PARKTRONIC		○	0,00
		Not in conjunction with 220	*	
		Not in conjunction with 978	*	
P44	Parking package with reversing camera		●	1.097,25
		Includes codes 218+235	*	
		Not in conjunction with 220	*	
		Not in conjunction with 978	*	
		Not in conjunction with P47	*	
		i.V.m. Code PYM	○	0,00
P47	Parking Package with 360-degree camera		●	1.580,25
		Includes codes 235+501	*	
		Not in conjunction with 218	*	
		Not in conjunction with 220	*	
		Not in conjunction with 978	*	
		Not in conjunction with P44	*	
		Only in conjunction with P49	*	
		for certain countries only	*	
		i.V.m. Code PYM	●	483,00
		i.V.m. Code PYN/PYO	○	0,00
915	Fuel tank with a capacity of 80 litres		—	105,00
		Not in conjunction with 916	*	
		i.V.m. Code PYA	—	0,00
916	Fuel tank with a capacity of 60 litres		—	52,50
			—	0,00
		i.V.m. Code PYA	—	0,00
916	Fuel tank with a capacity of 66 litres		●	52,50
			—	0,00
		Not in conjunction with 915	*	
		i.V.m. Code PYA	●	0,00
B59	DYNAMIC SELECT		○	0,00
B63	Sporty engine sound		—	0,00
		Not in conjunction with 05Z/06Z/10Z/11Z/12Z/19U/24Z/333/334/335/337/341/342/344/356/50Z/934/938/962/B12/Z30	*	
		Not in conjunction with 248/336/450/623U/837	*	
		Not in conjunction with Z87	*	
		Not in conjunction with Z90	*	
U29	Braking system with larger brake discs on the front axle		●	262,50
			—	0,00
		Not in conjunction with 08R/1R7/R48/R69	*	
		Not in conjunction with 651/652	*	
		Not in conjunction with R11	*	
		Not in conjunction with R43	*	
		i.V.m. Code PYG/PYH	○	0,00

U85	AdBlue® tank with 23.5-litre capacity		○	0,00
			–	#VALUE!
B30	Charging cable for domestic socket, 5 m, straight		–	0,00
		Not in conjunction with B80		
B32	Charging cable for industrial socket, 5 m, straight		–	252,00
		Not in conjunction with B82		
B33	Charging cable for wallbox and public charging stations		–	252,00
		Not in conjunction with B83		
		i.V.m. Code PYC	–	0,00
B80	Charging cable for domestic socket, 8 m, straight		–	73,50
		Not in conjunction with B30		
B82	Charging cable for industrial socket, 8 m, straight		–	283,50
		Not in conjunction with B32		
B83	Charging cable for wallbox and public charging stations		–	283,50
		Not in conjunction with B33		
459	DYNAMIC BODY CONTROL suspension with adjustable damping		●	997,50
		Not in conjunction with 1R7/651/652/R43	*	
		Only for left hand drive		
482	Suspension with higher ground clearance		○	0,00
485	AGILITY CONTROL suspension with selective damping		○	0,00
		Not in conjunction with 489		
		Not in conjunction with 601A/811A/824A/H73/L5C/P29/P31/RRD/U26		
		Only for left hand drive		
489	AMG RIDE CONTROL+		–	1.575,00
			–	0,00
489	AIR BODY CONTROL		●	1.995,00
			–	0,00
		Not in conjunction with 19U/337/341/342/344/450/485/550/623U/811/934/938/965		
		Not in conjunction with 248		
		Not in conjunction with 677		
489	AIR BODY CONTROL		●	1.995,00
			–	1.575,00
			–	0,00
		Not in conjunction with 19U/337/341/342/344/450/485/550/623U/811/934/938/965		
		Not in conjunction with 248		
		Not in conjunction with 677		
677	AGILITY CONTROL suspension with selective damping		○	0,00
		Not in conjunction with 489		
		i.V.m. Code P23	●	441,00
481	Underguard		★	0,00
421	9G-TRONIC		\$	0,00
B53	Acoustic ambient protection		–	0,00