

Valid from 15.10.2019 - MY 800+050 - update: 07.10.2019

[illegible]

[illegible]

[illegible]

[illegible]

13U	Additional services for electric and plug-in hybrid vehicles only in conjunction with code 360/362	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	0,00
14B	Owner's Manual and Service Booklet - Greek	o	o	o	o	-	o	o	o	o	o	o	o	o	o	o	o	o	o	o	o	o	0,00
14U	Smartphone integration incl. Code 15U, 16U, 17U only for certain countries I.V.m. Code PYN/PYO	367,50
15B	Owner's Manual and Service Booklet - Turkish	o	o	o	o	-	o	o	o	o	o	o	o	o	o	o	o	o	o	o	o	o	0,00
15R	48.3 cm (19-inch) multi-twin-spoke light-alloy wheels I.V.m. Code P76+P55 I.V.m. Code PYB I.V.m. Code U89	1260,00 315,00 787,50 157,50 525,00 525,00
15U	Preinstallation for Mercedes-Benz Link	o	o	o	o	-	o	o	o	o	o	o	o	o	o	o	o	o	o	o	o	o	0,00
16B	Owner's Manual and Service Booklet - Polish	o	o	o	o	-	o	o	o	o	o	o	o	o	o	o	o	o	o	o	o	o	0,00
16U	Apple CarPlay only in conjunction with code 14U	o	o	o	o	-	o	o	o	o	o	o	o	o	o	o	o	o	o	o	o	o	0,00
17B	Owner's Manual and Service Booklet - Czech	o	o	o	o	-	o	o	o	o	o	o	o	o	o	o	o	o	o	o	o	o	0,00
17U	Android Auto only in conjunction with code 14U	o	o	o	o	-	o	o	o	o	o	o	o	o	o	o	o	o	o	o	o	o	0,00
18B	Owner's Manual and Service Booklet - Engl. S. Am.	o	o	o	o	-	o	o	o	o	o	o	o	o	o	o	o	o	o	o	o	o	0,00
18U	Baidu Carlife only for certain countries only in conjunction with code 14U																						0,00
19B	Owner's Manual and Service Booklet - French S. Am.	o	o	o	o	-	o	o	o	o	o	o	o	o	o	o	o	o	o	o	o	o	0,00
20B	Owner's Manual and Service Booklet - Spanish S. Am.	o	o	o	o	-	o	o	o	o	o	o	o	o	o	o	o	o	o	o	o	o	0,00
218	Reversing camera not in conjunction with code 501 I.c.w. Code P44 I.V.m. Code PYA	.	-	.	-	.	-	.	-	.	-	.	s	s	s	s	s	s	s	s	s	s	0,00 420,00 0,00 0,00
21B	Owner's Manual and Service Booklet - Portug. S. Am.	o	o	o	o	-	o	o	o	o	o	o	o	o	o	o	o	o	o	o	o	o	0,00
21U	Dashcam only for certain countries only in conjunction with code U19	210,00
228	Auxiliary heater for certain countries only in conjunction with code B24 only for LHD only in conjunction with code 916 I.V.m. Code 360/362	.	-	.	-	.	-	.	-	.	-	1281,00 1438,50 1281,00
22B	Owner's Manual and Service Booklet - Japanese	o	o	o	o	-	o	o	o	o	o	o	o	o	o	o	o	o	o	o	o	o	0,00
231	Garage door opener only for certain countries only in conjunction with code 249	236,25
232	Garage door opener (frequency range 284-390 MHz) only for certain countries only in conjunction with code P49	236,25
233	Active Distance Assist DISTRONIC included with code 23P including code: U10 not in conjunction with code 440 only for certain countries	o	o	o	o	-	o	o	o	o	o	o	o	o	o	o	o	o	o	o	o	o	0,00
234	Blind Spot Assist only for certain countries only in conjunction with code P49 I.c.w. code 22P	472,50 0,00
235	Active Parking Assist with PARKTRONIC I.V.m. Code 25P I.V.m. Code P44/P47 I.V.m. Code PYM/PYN	.	-	.	-	.	-	.	-	.	-	.	o	o	o	o	o	o	o	o	o	o	766,50 0,00 0,00 0,00
239	Active Distance Assist DISTRONIC not in conjunction with code 23P, 258 and 440 only for certain countries	630,00
23B	Owner's Manual and Service Booklet - simpl. Chinese	o	o	o	o	-	o	o	o	o	o	o	o	o	o	o	o	o	o	o	o	o	0,00
23Z	Pre-installation for TETRA mobile radio, Motorola only in conjunction with code 290	147,00
241	Electrically adjustable front passenger seat with memory for left-hand traffic only for RHD only in conjunction with code 275 and U22 I.V.m. Code 555 I.V.m. Code PBY/PBZ	525,00 735,00 0,00
242	Power front right seat with memory function only for LHD only in conjunction with code 275 and U22 I.V.m. Code 555 I.V.m. Code P57 I.V.m. Code PBY/PBZ	525,00 735,00 0,00 0,00
243	Active Lane Keeping Assist not in conjunction with code 233	o	o	o	o	-	o	o	o	o	o	o	o	o	o	o	o	o	o	o	o	o	0,00
249	Interior mirror and driver's exterior mirror automatically dimming included with code P49	o	o	o	o	-	o	o	o	o	o	o	o	o	o	o	o	o	o	o	o	o	0,00
24B	Owner's Manual and Service Booklet - trad. Chinese	o	o	o	o	-	o	o	o	o	o	o	o	o	o	o	o	o	o	o	o	o	0,00
24Z	Pre-installation for TETRA mobile radio, Sepura only in conjunction with code 290	147,00
250	AMG Driver's package	-	-	-	-	-	-	-	-	-	o	-	-	-	-	-	-	-	-	-	o	-	0,00 1995,00
251	Increase in top speed, USA	-	-	-	-	-	-	-	-	o	-	-	-	-	-	-	-	-	-	o	-	-	0,00 2310,00
256	AMG Track Pace only in conjunction with code 549, 365 and 859	-	-	-	-	-	-	-	-	-	o	-	-	-	-	-	-	-	-	-	o	-	0,00 262,50
258	Active Brake Assist only for certain countries	0,00
25B	Owner's Manual and Service Booklet - Korean	o	o	o	o	-	o	o	o	o	o	o	o	o	o	o	o	o	o	o	o	o	0,00
25R	43.2 cm (17-inch) 10-spoke light-alloy wheels included with code P76 not in conjunction with code R66	s	s	s	s	s	-	s	s	s	s	-	-	-	-	-	-	-	-	-	-	-	0,00
260	Omission of model plate on boot lid	o	o	o	o	-	o	o	o	o	o	o	o	o	o	o	o	o	o	o	o	o	0,00
261	Omission of badge	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	0,00
263	Number plate mounting for Asia / Mexico	o	o	o	o	-	o	o	o	o	o	o	o	o	o	o	o	o	o	o	o	o	0,00

[illegible]

[illegible]

[illegible]

[illegible]

	I.V.m. Code P17		O	O	O	O	O	O	O	O	O	O	O	O	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	0,00		
	I.V.m. Code PYB		S	S	S	S	S	S	S	S	S	S	S	S	S	S	S	S	S	S	S	S	S	S	S	S	S	S	S	S	S	S	0,00	
893	KEYLESS GO starting function		S	S	S	S	S	S	S	S	S	S	S	S	S	S	S	S	S	S	S	S	S	S	S	S	S	S	S	S	S	S	0,00	
895	Telescope stack only for certain countries		157,50
896	Preinstallation for Digital vehicle key for smartphone only for certain countries only in conjunction with code 897/899 and 362		105,00
897	Wireless charging and connection via Bluetooth not in conjunction with code 899 I.V.m. Code PYN/PYO		210,00
			O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	0,00	
899	Multifunction telephony only for certain countries only in conjunction with code 270 and 274 I.V.m. Code PYN/PYO		514,50
			304,50
8R0	Winter (M+S) wheel and tyre assembly x 4 only available for Germany		-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	3990,00		
8R3	Complete set of 4 M+S winter wheels not in conjunction with code R66 or RZT only available for Germany		-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	3990,-		
913	Air conditioning preinstallation for hot countries only for certain countries		O	O	O	O	O	-	-	-	-	-	-	O	O	O	O	O	-	-	-	-	-	-	-	-	-	-	-	-	-	-	0,00	
916	Fuel tank included with code 228 I.V.m. Code PYA/PYB		.	-	-	-	O	O	O	-	S	S	S	-	O	O	O	O	O	-	S	S	S	-	-	-	-	-	-	0,00
			O	O	O	O	-	-	-	-	-	-	-	O	O	O	O	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	0,00	
919	Air Conditioning Enhancement package/improved cooling performance only for certain countries		O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	0,00	
922	Reduced power version only for certain countries		-	-	-	-	-	-	-	O	-	-	-	-	-	-	-	-	-	-	-	O	-	-	-	-	-	-	-	-	-	-	0,00	
926	Emission control system with EU4 technology		O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	0,00	
927	EU6 emissions standard		O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	0,00	
928	EU5 emission standard		O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	0,00	
92R	50.8 cm (20-inch) AMG light-alloy wheels only in conjunction with code P31		892,50
			945,00
93R	50.8 cm (20-inch) AMG light-alloy wheels only in conjunction with code P31 I.V.m. Code P31+P55		.	-	-	-	.	-	-	-	-	-	-	-	1102,50
			1155,00
			892,50
942	Protection and Care set		99,75
945	Emission control system China		O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	0,00	
961	Petrol particulate filter only for certain countries only in conjunction with code 927		-	-	-	-	-	O	O	O	O	O	O	O	-	-	-	-	O	O	O	O	O	O	O	O	O	O	O	O	O	O	0,00	
962	Preparation for signal unit (light bar) only in conjunction with code 290		168,00
968	COC document EU6 without registration certificate part II		O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	0,00	
969	COC document EU6 with registration certificate part II		O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	0,00	
970	Preparation for police vehicle only in conjunction with code 290		656,25
971	Exhaust system with DPF Generation 1.5 for certain countries only in conjunction with code 927		O	O	O	O	O	-	-	-	-	-	O	O	O	O	O	-	-	-	-	-	-	-	-	-	-	-	-	-	-	0,00		
974	Preparation for fire service command vehicle only in conjunction with code 290		656,25
975	Preparation for emergency doctor vehicle only in conjunction with code 290		656,25
97R	45.7 cm (18-inch) 5-twin-spoke light-alloy wheels I.V.m. Code PYB I.V.m. Code U89		-	-	-	-	.	-	-	-	-	-	-	262,50	
			-	735,00
			-	210,00
			-	157,50
981	Omission of vehicle registration document		O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	0,00	
986	Identification no. (US-VIN)		O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	0,00	
989	Identification label under windshield		O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	0,00	
997	Exhibition vehicle		O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	0,00	
B01	EQ Boost starter-alternator not in conjunction with code U87 only for certain countries		-	-	-	-	-	420,00
B06	AMG high-performance braking system		-	-	-	-	-	-	-	-	-	-	S	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	S	-	0,00		
B07	AMG high-performance ceramic composite braking system		-	-	-	-	-	-	-	-	-	-	.	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	.	4410,00		
B08	Fanfares for Asia only for certain countries		O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	0,00	
B12	Tyre-change toolkit only for certain countries		O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	0,00	
B21	Charging cable for domestic plug socket, 4 m, coiled only for certain countries		-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	0,00		
B24	Remote control for auxiliary heating only in conjunction with code 228 I.V.m. Code 360/362		O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	O	0,00	
			-	-	-	-	-	-	-	-	-	-	-	210,00	
B28	AMG Carbon-fibre exterior mirror AMG carbon-fibre exterior mirrors		-	-	-	-	-	-	-	-	-	-	210,00	
B30	Charging cable for domestic plug socket, 4m, coiled only for certain countries		-	-	-	-	-	-	-	-	-	-	.	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	0,00		
B31	Charging cable for domestic socket, 4 m, coiled only for certain countries		-	-	-	-	-	-	-	-	-	-	.	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	0,00		
B32	Charging cable for industrial plug socket, 4m, coiled only for certain countries		-	-	-	-	-	-	-	-	-	-	.	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	252,00		
B33	Charging cable for wallbox and public charging stations, 4m, coiled only for certain countries I.V.m. Code PYA		-	-	-	-	-	-	-	-	-	-	.	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	252,00		
B35	Charging cable for domestic socket, 4 m, coiled only for certain countries		-	-	-	-	-	-	-	-	-	-	.	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	0,00		
B36	Charging cable for domestic socket, 4 m, coiled only for certain countries		-	-	-	-	-	-	-	-	-	-	.	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	0,00		
B38	Charging cable for domestic socket, 4 m, coiled only for certain countries		-	-	-	-	-	-	-	-	-	-	.	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	0,00		
B39	Charging cable for domestic socket, 4 m, coiled only for certain countries		-	-	-	-	-	-	-	-	-	-	.	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	0,00		
B40	Charging cable for domestic socket, 4 m, coiled only for certain countries		-	-	-	-	-	-	-	-	-	-	.	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	0,00		

[illegible]

[illegible]

[illegible]

[illegible]