

## Standard and special equipment

Model year :

801

Sales Release :

2020-05-06

Production Change :

2020-07-11

Legend

(\*) Available at extra cost (○) available without additional charge (S) standard equipment (-) not available (L) Left hand drive only (R) Right hand drive only (NS) National Standard "+" AND (code A and Please note that central restrictions are displayed. Markets may have specific deviation if any. Codes could be valid for certain countries only.

			GLS Class						LLP
Code	equipment	Restrictions	167921 GLS 350 d 4MATIC	167923 GLS 400 d 4MATIC	167959 GLS 450 4MATIC (L)	167986 GLS 580 4MATIC (L)	167987 Mercedes-Maybach GLS 600 4MATIC	167989 Mercedes-AMG GLS 63 4MATIC+	
B14	AMG carbon-fibre engine cover		-	-	-	-	-	●	787,50
P60	AMG Night package		-	-	-	-	-	●	997,50
		Includes codes 840 [U50]						*	
		i.V.m. Code PYB	-	-	-	-	-	●	588,00
L6G	AMG Performance steering wheel in DINAMICA microf		-	-	-	-	-	●	514,50
		Not in conjunction with 443/L6H/L6J/L6K						*	
		Only in conjunction with U88						*	
L6H	AMG Performance steering wheel in carbon fibre / DIN		-	-	-	-	-	●	861,00
		Not in conjunction with H18/H22/H34/H46/H64/L6G/L6J/L6K						*	
L6J	AMG Performance steering wheel in nappa leather		-	-	-	-	-	S	0,00
		Not in conjunction with L6G/L6H/L6K						*	
L6K	AMG Performance steering wheel in nappa leather / DIN		-	-	-	-	-	●	441,00
		Not in conjunction with L6G/L6H/L6J						*	
250	AMG Driver's package		-	-	-	-	-	●	1.995,00
421	AMG SPEEDSHIFT TCT 9G		-	-	-	-	-	S	0,00
465	AMG ACTIVE RIDE CONTROL		-	-	-	-	-	S	0,00
467	AMG electronic rear-axle limited-slip differential		-	-	-	-	-	S	0,00
B06	AMG high-performance compound braking system		-	-	-	-	-	S	0,00
		Not in conjunction with B07/U70						*	
B07	AMG high-performance ceramic composite braking system		-	-	-	-	-	●	4.410,00
		Not in conjunction with 669/B06/B12/U70						*	
U70	AMG high-performance composite braking system		-	-	-	-	-	●	630,00
		Not in conjunction with B06/B07						*	
U78	AMG performance exhaust system, selectable		-	-	-	-	-	●	1.470,00
		i.V.m. Code PYB	-	-	-	-	-	○	0,00
PBE	designo Exclusive Leather package		-	-	-	-	-	●	6.300,00
		Only in conjunction with U61					*	-	
U61	designo Leather package		-	-	-	-	-	●	13.125,00
901	Interior Chrome package		S	S	S	S	S	S	0,00
		Only for left hand drive				*			
P55	Night package		●	●	●	●	-	-	829,50
		Includes codes 840 [U50]+RWH [RPB/RPO]	*	*	*	*			
		Not in conjunction with 36R/65R	*	*	*				
		Not in conjunction with 690/94R/95R/R33/R66/R76/RPA/U12	*	*	*	*			
		Not in conjunction with R02	*	*					
		Only in conjunction with P31+U26	*	*	*	*			
		Only for left hand drive				*			
		i.V.m. Code PYH	●	●	●	●	-	-	420,00
260	Deletion of model plate on boot lid		○	○	○	○	○	○	0,00
		Only for left hand drive				*			
261	Omission of badge		-	-	-	-	○	○	0,00
846	Aluminium-look, illuminated running boards with rubber		●	●	●	●	-	●	656,25
		Only for left hand drive				*			
E03	External door handle recesses in high-gloss chrome		●	●	●	●	●	●	110,25
E03		Only for left hand drive				*			
E54	Design side wall trim		●	●	●	●	●	●	462,00
E54		Only for left hand drive				*			
231	Garage door opener		●	●	●	●	●	●	236,25
		Only for left hand drive				*			
551	Anti-theft alarm system with preinstallation for collision		●	●	●	●	●	●	288,75
		Only for left hand drive				*			
		i.V.m. Code P54	○	○	○	○	○	○	0,00
883	Power closing		●	●	●	●	●	●	577,50
		Only for left hand drive				*			
		i.V.m. Code PYB	-	-	-	-	○	-	0,00
		i.V.m. Code PYN/PYO	○	○	○	○	-	○	0,00
896	Preinstallation for NFC key card		●	●	●	●	●	●	105,00
867	Vehicle key in high-gloss black with ornamental surround		●	●	●	●	-	●	0,00
867	Vehicle key in high-gloss black with ornamental surround		-	-	-	-	S	-	0,00

B67		Not in conjunction with B68	*	*	*	*	*	*		
B67		Only for left hand drive				*				
B67		standard equipment for certain countries	*	*	*	*				
B68	Vehicle key in high-gloss white with ornamental surro		●	●	●	●	-	●		105,00
			-	-	-	-	○	-		0,00
		Not in conjunction with B67	*	*	*	*	*	*		
		Only for left hand drive				*				
P17	KEYLESS-GO Comfort package		●	●	●	-	-	-		0,00
P17	KEYLESS-GO Comfort package		-	-	-	S	S	S		0,00
P17		Includes codes 871+889	*	*	*	*	*	*		
P17		Only for left hand drive				*				
C19	cavansite blue / Iridium silver		-	-	-	-	●	-		18.375,00
		Only in conjunction with 524+890U					*			
C21	obsidian black / rubellite red		-	-	-	-	●	-		18.375,00
		Not in conjunction with C24/C30					*			
		Only in conjunction with 197U+524					*			
C22	designo diamond white bright / obsidian black		-	-	-	-	●	-		18.375,00
		Only in conjunction with 524+799U					*			
C23	obsidian black / designo Kalahari gold		-	-	-	-	●	-		18.375,00
		Only in conjunction with 197U+524					*			
C24	emerald green / mojave silver		-	-	-	-	●	-		18.375,00
		Not in conjunction with C21/C30					*			
		Only in conjunction with 524+989U					*			
C25	Iridium silver / designo diamond white bright		-	-	-	-	●	-		18.375,00
		Only in conjunction with 524+775U					*			
C30	Iridium silver / selenite grey		-	-	-	-	●	-		18.375,00
		Not in conjunction with C21/C24					*			
		Only in conjunction with 775U					*			
413	Panoramic sliding sunroof		●	●	●	●	-	●		735,00
			-	-	-	-	S	-		0,00
		Not in conjunction with 414	*	*	*	*		*		
		Only for left hand drive				*				
		i.V.m. Code PYN/PYO	○	○	○	○	-	○		0,00
414	Sliding sunroof		S	S	S	S	-	S		0,00
		Not in conjunction with 413	*	*	*	*		*		
		Only for left hand drive				*				
E22	Alustyle Easy-Fix II rail carrier		●	●	●	●	●	●		294,00
E22		Only for left hand drive				*				
608	Adaptive Highbeam Assist		-	-	●	●	●	●		189,00
		for certain countries only			*	*	*	*		
		i.V.m. Code 640	-	-	○	○	○	○		0,00
628	Adaptive Highbeam Assist Plus		○	○	○	○	○	○		0,00
		Only for left hand drive				*				
642	MULTIBEAM LED		●	●	●	-	-	-		0,00
642	MULTIBEAM LED		-	-	-	S	S	S		0,00
642		Only for left hand drive				*				
642		standard equipment in certain countries	*	*	*	*				
550	Trailer coupling with ESP<sup>®</sup> trailer stabilis		●	●	●	●	●	●		1.008,00
		Only in conjunction with 557	*	*	*	*	*	*		
		Only for left hand drive				*				
		for certain countries only	*	*	*	*	*	*		
557	Increased towing capacity		○	○	○	○	○	○		0,00
		Only in conjunction with 550	*	*	*	*	*	*		
		Only for left hand drive				*				
P54	URBAN GUARD vehicle protection		●	●	●	●	●	●		493,50
		Includes codes 551+882	*	*	*	*	*	*		
		Not in conjunction with P82	*	*	*	*	*	*		
		Only for left hand drive				*				
		i.V.m. Code 362	●	●	●	●	●	●		525,00
		i.V.m. Code PYB	○	○	○	○	-	○		0,00
P82	URBAN GUARD vehicle protection Plus		●	●	●	●	●	●		703,50
		Not in conjunction with P54	*	*	*	*	*	*		
		Only in conjunction with 551+882	*	*	*	*	*	*		
		Only for left hand drive				*				
		i.V.m. Code PYB	●	●	●	●	-	●		210,00
		i.V.m. Code PYB	-	-	-	-	○	-		0,00
E16	Rim lock set		●	●	●	●	●	●		57,75
		Only for left hand drive				*				
R02	All-season tyres		○	○	○	○	-	-		0,00
		Not in conjunction with 94R/95R/L5C/P31/P55/R01/R06/R33/R76/RPA/RPB/RPQ/RWF/RWH/U26/U28/U	*	*						
		for certain countries only	*	*	*	*				
R66	run-flat tyres		●	●	●	●	-	-		367,50
		Not in conjunction with 36R/65R	*	*	*					
		Not in conjunction with 95R/B51/L5C/P31/P55/R06/R76/RPA/RPB/RPQ/RWF/RWH/U26/U50	*	*	*	*				
		Only for left hand drive				*				

RPA	55.9 cm (22-inch) AMG multi-spoke light-alloy wheels		●	●	●	●	-	-	1.207,50
		Not in conjunction with 36R/65R	*	*	*				
		Not in conjunction with 690/94R/95R/P55/R33/R66/R76/RPB/RPQ/RWF/RWH/U12/U50	*	*	*	*			
		Not in conjunction with R02	*	*					
		Only in conjunction with P31+U26	*	*	*	*			
		Only in conjunction with R01	*	*					
		Only for left hand drive				*			
RPB	55.9 cm (22-inch) AMG multi-spoke light-alloy wheels		●	●	●	●	-	-	1.522,50
		Not in conjunction with 36R/65R	*	*	*				
		Not in conjunction with 690/94R/95R/R33/R66/R76/RPA/RPB/RPQ/RWF/RWH/U12	*	*	*	*			
		Not in conjunction with R02	*	*					
		Only in conjunction with P31+U26	*	*	*	*			
		Only in conjunction with R01	*	*					
		Only for left hand drive				*			
		i.V.m. Code P55	●	●	●	●	-	-	1.207,50
RPC	55.9 cm (22-inch) AMG multi-spoke light-alloy wheels		-	-	-	-	-	●	1.890,00
		Not in conjunction with RPR/RPS/RWI/RXW/RXX/RXY						*	
RPQ	58.4 cm (23-inch) AMG 5-twin-spoke light-alloy wheels		●	●	●	●	-	-	2.625,00
		Not in conjunction with 36R/65R	*	*	*				
		Not in conjunction with 690/94R/95R/R33/R66/R76/RPA/RPB/RPQ/RWF/RWH/U12	*	*	*	*			
		Not in conjunction with R02	*	*					
		Only in conjunction with P31+U26	*	*	*	*			
		Only in conjunction with R01	*	*					
		Only for left hand drive				*			
		i.V.m. Code P55	●	●	●	●	-	-	2.310,00
RPR	58.4 cm (23-inch) AMG 5-hole forged wheels		-	-	-	-	-	●	3.360,00
		Not in conjunction with RPC/RWI/RXW/RXX/RXY						*	
RPS	58.4 cm (23-inch) AMG 5-hole forged wheels		-	-	-	-	-	●	4.042,50
		Not in conjunction with RPC/RWI/RXW/RXX/RXY						*	
RWF	53.3 cm (21-inch) AMG 5-twin-spoke light-alloy wheels		○	○	○	○	-	-	0,00
		Available only as part of (P31)	*	*	*	*			
		Not in conjunction with 36R/65R	*	*	*				
		Not in conjunction with 690/94R/95R/R33/R66/R76/RPA/RPB/RPQ/RWF/RWH/U12	*	*	*	*			
		Not in conjunction with R02	*	*					
		Only in conjunction with P31+U26	*	*	*	*			
		Only in conjunction with R01	*	*					
		Only for left hand drive				*			
RWH	53.3 cm (21-inch) AMG 5-twin-spoke light-alloy wheels		●	●	●	●	-	-	315,00
		Not in conjunction with 36R/65R	*	*	*				
		Not in conjunction with 690/94R/95R/R33/R66/R76/RPA/RPB/RPQ/RWF/U12	*	*	*	*			
		Not in conjunction with R02	*	*					
		Only in conjunction with P31+U26	*	*	*	*			
		Only in conjunction with R01	*	*					
		Only for left hand drive				*			
		in conjunction with R02, only for certain countries	*	*	*	*			
		only in conjunction with P31+R01	*	*	*	*			
		i.V.m. Code P55	○	○	○	○	-	-	0,00
RWI	53.3 cm (21-inch) AMG 10-spoke light-alloy wheels		-	-	-	-	-	S	0,00
		Not in conjunction with RPC/RPR/RPS/RXW/RXX/RXY						*	
RXW	55.9 cm (22-inch) AMG multi-spoke light-alloy wheels		-	-	-	-	-	●	1.207,50
		Not in conjunction with RPC/RPR/RPS/RWI/RXX/RXY						*	
RXX	58.4 cm (23-inch) AMG multi-spoke forged wheels		-	-	-	-	-	●	3.150,00
		Not in conjunction with RPC/RPR/RPS/RWI/RXW/RXY						*	
RXY	58.4 cm (23-inch) AMG multi-spoke forged wheels		-	-	-	-	-	●	3.832,50
		Not in conjunction with RPC/RPR/RPS/RWI/RXW/RXX						*	
36R	48.3 cm (19-inch) 6-twin-spoke light-alloy wheels		●	●	●	-	-	-	315,00
		Not in conjunction with 65R/669/94R/95R/L5C/P31/P55/R06/R33/R66/R76/RPA/RPB/RPQ/RWF/RWH/U	*	*	*				
		i.V.m. Code PYB	○	○	○	-	-	-	0,00
65R	48.3 cm (19-inch) 5-twin-spoke light-alloy wheels		S	S	S	-	-	-	0,00
		Not in conjunction with 36R/669/94R/95R/L5C/P31/P55/R06/R33/R66/R76/RPA/RPB/RPQ/RWF/RWH/U	*	*	*				
94R	50.8 cm (20-inch) 8-spoke light-alloy wheels		●	●	●	-	-	-	945,00
			-	-	-	S	-	-	0,00
		Not in conjunction with 36R/65R	*	*	*				
		Not in conjunction with 669/95R/L5C/P31/P55/R33/R66/R76/RPA/RPB/RPQ/RWF/RWH/U26/U50	*	*	*	*			
		Not in conjunction with R02	*	*					
		Only in conjunction with R01	*	*					
		Only for left hand drive				*			
		i.V.m. Code PYB	●	●	●	-	-	-	630,00
95R	53.3 cm (21-inch) 5-triple-spoke light-alloy wheels		-	●	●	-	-	-	1.837,50
			-	-	-	●	-	-	892,50
		Not in conjunction with 36R/65R	*	*	*				
		Not in conjunction with 669/94R/L5C/P31/P55/R33/R66/R76/RPA/RPB/RPQ/RWF/RWH/U26/U50	*	*	*	*			
		Not in conjunction with R02	*	*					
		Only in conjunction with R01	*	*					
		Only for left hand drive				*			

		i.V.m. Code PYB	●	●	●	-	-	-	1.522,50
96R	50.8 cm (20-inch) 5-spoke light-alloy wheels		-	-	-	-	-	-	0,00
R33	50.8 cm (20-inch) 5-twin-spoke light-alloy wheels		●	●	●	-	-	-	945,00
			-	-	-	○	-	-	0,00
		Not in conjunction with 36R/65R	*	*	*				
		Not in conjunction with 669/94R/95R/L5C/P31/P55/R76/RPA/RPB/RPQ/RWF/RWH/U26/U50	*	*	*	*			
		Not in conjunction with R02	*	*					
		Only in conjunction with R01	*	*					
		Only for left hand drive				*			
		i.V.m. Code PYB	●	●	●	-	-	-	630,00
R76	53.3 cm (21-inch) 5-spoke light-alloy wheels		●	●	●	-	-	-	1.837,50
			-	-	-	●	-	-	892,50
		Not in conjunction with 36R/65R	*	*	*				
		Not in conjunction with 669/94R/95R/L5C/P31/P55/R33/R66/RPA/RPB/RPQ/RWF/RWH/U26/U50	*	*	*	*			
		Not in conjunction with R02	*	*					
		Only in conjunction with R01	*	*					
		Only for left hand drive				*			
		i.V.m. Code PYB	●	●	●	-	-	-	1.522,50
		i.V.m. Code PYB	-	-	-	●	-	-	577,50
R63	55.9 cm (22-inch) Maybach multi-spoke light-alloy wheels		-	-	-	-	S	-	0,00
		Not in conjunction with R65					*		
R65	58.4 cm (23-inch) MAYBACH multi-spoke forged wheels		-	-	-	-	●	-	6.300,00
		Not in conjunction with R63					*		
		Only in conjunction with R01+R06					*		
669	Collapsible spare wheel		●	●	●	●	-	-	367,50
			-	-	-	-	-	●	210,00
			-	-	-	-	○	-	0,00
		Not in conjunction with 36R/65R	*	*	*				
		Not in conjunction with 690/94R/95R/R33/R76/U12/U68	*	*	*	*			
		Not in conjunction with 811/B51	*	*	*	*		*	
		Not in conjunction with B07						*	
		Not in conjunction with B16			*				
		Only in conjunction with 810						*	
		Only in conjunction with B12	*	*	*	*		*	
		Only for left hand drive				*			
		i.V.m. Code PYB	●	●	●	●	-	-	315,00
		i.V.m. Code PYB	-	-	-	-	-	●	157,50
690	Emergency spare wheel		●	●	●	●	-	-	136,50
		Not in conjunction with 669/811/B51/L5C/P31/P55/RPA/RPB/RPQ/RWF/RWH/U26/U28/U50/U68	*	*	*	*			
		Not in conjunction with B16			*				
		Only in conjunction with B12	*	*	*	*			
		Only for left hand drive				*			
		included in configuration: code B12	*	*	*	*			
		not in conjunction with P31/U29	*	*	*	*			
		standard equipment in certain countries	*	*	*	*			
		i.V.m. Code PYB	●	●	●	●	-	-	84,00
B51	TIREFIT		●	●	●	●	●	●	52,50
			-	-	-	-	-	-	0,00
		Not in conjunction with 669/B12	*	*	*	*		*	
		Not in conjunction with 690/R66	*	*	*	*			
		Only for left hand drive				*			
		standard equipment in certain countries							
		i.V.m. Code PYB	○	○	○	○	○	○	0,00
297	electric sunblinds in rear doors, left and right		●	●	●	●	-	●	682,50
			-	-	-	-	S	-	0,00
		Only for left hand drive				*			
597	Windscreen, heated		-	-	●	●	●	●	609,00
		Only for left hand drive				*			
840	Heat-insulating dark-tinted glass		●	●	●	●	-	●	409,50
			-	-	-	-	○	-	0,00
		Not in conjunction with U50	*	*	*	*		*	
		Only for left hand drive				*			
		standard equipment in certain countries					*		
		i.V.m. Code P55	○	○	○	○	-	-	0,00
		i.V.m. Code P60	-	-	-	-	-	○	0,00
		i.V.m. Code PYB	○	○	○	○	-	○	0,00
874	MAGIC VISION CONTROL		●	●	●	●	●	-	409,50
			-	-	-	-	-	●	231,00
		Not in conjunction with 875	*	*	*	*	*	*	
		Only for left hand drive				*			
		i.V.m. Code PYB	○	○	○	○	○	○	0,00
875	Heated windscreen washer system		●	●	●	●	●	-	178,50
875	Heated windscreen washer system		-	-	-	-	-	S	0,00
875		Not in conjunction with 874	*	*	*	*	*	*	
875		Only for left hand drive				*			

P49	Mirror package		●	●	●	●	-	●	0,00
P49	Mirror package		-	-	-	-	S	-	0,00
P49		Includes codes 249+500+587	*	*	*	*	*	*	
P49		Only for left hand drive				*			
P49		standard equipment in certain countries	*	*	*	*		*	
PAF	Acoustic Comfort package		●	●	●	●	-	●	1.260,00
			-	-	-	-	S	-	0,00
		Includes codes 596	*	*	*	*	*	*	
		Only for left hand drive				*			
U50	Omission of heat-insulating dark-tinted glass		○	○	○	○	-	○	0,00
		Not in conjunction with 36R/65R	*	*	*				
		Not in conjunction with 690/94R/95R/R33/R66/R76/RPA/U12	*	*	*	*			
		Not in conjunction with 840	*	*	*	*		*	
		Not in conjunction with R02	*	*					
		Only in conjunction with P31+P55+U26	*	*	*	*			
		Only in conjunction with P60						*	
		Only for left hand drive				*			
518	Media Interface cable kit		●	●	●	●	●	●	52,50
518		Only for left hand drive				*			
72B	Additional USB ports		S	S	S	S	S	S	0,00
		Only for left hand drive				*			
897	Wireless charging system for mobile devices		●	●	●	●	-	●	0,00
897	Wireless charging system for mobile devices		-	-	-	-	S	-	0,00
897		Not in conjunction with 899	*	*	*	*	*	*	
897		Only for left hand drive				*			
897		for certain countries only	*	*	*	*			
897		standard equipment in certain countries	*	*	*	*			
943	Toll payment system		●	●	●	●	●	●	262,50
01U	Preinstallation for Navigation Services		●	●	●	●	●	●	105,00
		Only for left hand drive				*			
		i.V.m. Code PYB	○	○	○	○	○	○	0,00
355	Extended MBUX functions		S	S	S	S	S	S	0,00
		Only for left hand drive				*			
365	Hard-disc navigation		S	S	S	S	S	S	0,00
		Only for left hand drive				*			
537	Digital radio		○	○	○	○	○	○	0,00
		Only for left hand drive				*			
		includes code 79B	*	*	*	*	*	*	
		standard equipment in certain countries	*	*	*	*	*	*	
PAU	MBUX Innovation package		●	●	●	●	●	●	1.375,50
		Includes codes 463+77B	*	*	*	*	*	*	
		Not in conjunction with 548	*	*	*	*	*	*	
		Not in conjunction with 811	*	*	*	*	*	*	
		Only in conjunction with 256						*	
		Only in conjunction with 549+U19	*	*	*	*	*	*	
		Only in conjunction with 810					*	*	
		Only for left hand drive				*			
		i.V.m. Code U19	●	●	●	●	●	●	1.785,00
		i.V.m. Code PYB	-	-	-	-	●	-	231,00
447	MBUX rear tablet		○	○	○	○	S	○	0,00
		Available only as part of (P11)	*	*	*	*		*	
		Not in conjunction with 224	*	*	*	*		*	
		Only in conjunction with P08+P11	*	*	*	*		*	
		Only for left hand drive				*			
864	MBUX Rear Seat Entertainment System		●	●	●	●	●	●	2.467,50
		Not in conjunction with 254	*	*	*				
		Not in conjunction with 548	*	*	*	*	*		
		Only in conjunction with 256						*	
		Only in conjunction with 549+866	*	*	*	*	*	*	
		Only in conjunction with P64	*	*	*				
		Only for left hand drive				*			
865	TV receiver		●	●	●	●	●	●	1.039,50
		Not in conjunction with 548	*	*	*	*	*		
		Only in conjunction with 256						*	
		Only in conjunction with 549	*	*	*	*	*	*	
		Only for left hand drive				*			
		for certain countries only	*	*	*	*			
866	Preinstallation for entertainment and comfort features		●	●	●	●	●	●	178,50
		Only for left hand drive				*			
		standard equipment in certain countries					*		
		i.V.m. Code 864	○	○	○	○	○	○	0,00
U31	1 wireless head set		●	●	●	●	●	●	210,00
U31		Not in conjunction with U58	*	*	*	*	*	*	
U31		Only for left hand drive				*			
U58	2 wireless head sets		●	●	●	●	●	●	420,00

U58		Not in conjunction with U31	*	*	*	*	*	*	
U58		Only for left hand drive				*			
810	Burmester® surround sound system		●	●	●	●	-	-	892,50
			-	-	-	-	S	S	0,00
		Not in conjunction with 811	*	*	*	*	*	*	
		Only for left hand drive				*			
		i.V.m. Code PYN/PYO	○	○	○	○	-	-	0,00
811	Burmester® high-end 3D surround sound system		●	●	●	●	-	-	5.145,00
			-	-	-	-	●	●	4.252,50
		Not in conjunction with 669/B12	*	*	*	*		*	
		Not in conjunction with 690/U68	*	*	*	*			
		Not in conjunction with 77B/810/PAU	*	*	*	*	*	*	
		Not in conjunction with B16			*				
		Only in conjunction with 582	*	*	*	*		*	
		Only for left hand drive				*			
		i.V.m. Code PYN/PYO	●	●	●	●	-	-	4.252,50
14U	Smartphone integration		●	●	●	●	●	●	0,00
14U		Only for left hand drive				*			
14U		only in conjunction with 18U	*	*	*	*			
14U		standard equipment in certain countries	*	*	*	*	*	*	
380	Car telephony		●	●	●	●	●	●	619,50
380		Only in conjunction with 274	*	*	*	*	*	*	
380		Only for left hand drive				*			
856	Business Telephony in the rear		-	-	-	-	●	-	997,50
856		Only in conjunction with 224+274+380+898					*		
856		for certain countries only					*		
899	Multifunction telephony		●	●	●	●	-	●	514,50
			-	-	-	-	●	-	304,50
		Not in conjunction with 897	*	*	*	*	*	*	
		Only in conjunction with 274	*	*	*	*	*	*	
		Only for left hand drive				*			
21U	Dash cam		●	●	●	●	●	●	210,00
543	Double sunblind		●	●	●	●	-	●	99,75
			-	-	-	-	S	-	0,00
		Only for left hand drive				*			
U09	Dashboard and door beltlines in ARTICO man-made leather		●	●	●	●	-	-	472,50
			-	-	-	-	-	S	0,00
		Not in conjunction with 551A/554A/561A/565A						*	
		Not in conjunction with U08	*	*	*	*			
		Not in conjunction with U38	*	*	*	*		*	
		Only for left hand drive				*			
		i.V.m. Code P22	○	○	○	○	-	-	0,00
U38	Dashboard and door beltlines in nappa leather		●	●	●	●	-	-	1.102,50
			-	-	-	-	S	○	0,00
		Not in conjunction with 135A/873	*	*	*	*			
		Not in conjunction with 215A/55U/58U/U08	*	*	*	*			
		Not in conjunction with U09	*	*	*	*		*	
		Only in conjunction with 293+951A	*	*	*	*			
		Only in conjunction with 902	*	*	*	*			
		Only for left hand drive				*			
U67	230 V socket in rear		●	●	●	●	●	●	126,00
		Only for left hand drive				*			
		standard equipment in certain countries					*		
Y05	Red seat belts		-	-	-	-	-	●	315,00
		Not in conjunction with 55U						*	
		only in conjunction with 851A/551A/561A						*	
228	Auxiliary heater		●	●	●	●	●	●	1.281,00
		Only for left hand drive		*		*	*	*	
443	Steering wheel heating		●	●	●	●	●	●	273,00
		Not in conjunction with L5C	*	*	*	*			
		Not in conjunction with L6G/U88						*	
		Only for left hand drive				*			
		only in conjunction with L3D					*		
		i.V.m. Code PYB	-	-	-	-	○	-	0,00
580	THERMATIC automatic climate control		S	S	S	-	-	-	0,00
581	THERMOTRONIC automatic climate control		●	●	●	-	-	-	0,00
581	THERMOTRONIC automatic climate control		-	-	-	S	S	S	0,00
581		Only for left hand drive				*			
581		standard equipment in certain countries	*	*	*	*			
582	THERMOTRONIC automatic climate control in the rear		●	●	●	●	-	●	724,50
			-	-	-	-	S	-	0,00
		Only for left hand drive				*			
		i.V.m. Code PYQ	○	○	○	○	-	○	0,00
B24	Remote control for auxiliary heating		●	●	●	●	●	●	210,00
		Only in conjunction with 228+274	*	*	*	*	*	*	

		Only for left hand drive	*	*		*	*	*	
P21	AIR BALANCE package		●	●	●	●	●	●	351,75
		Only for left hand drive				*			
		i.V.m. Code PBP/PBR	○	○	○	○	○	○	0,00
		i.V.m. Code PYN/PYO	○	○	○	○	-	○	0,00
P69	Warmth Comfort package		●	●	●	-	-	-	1.522,50
			-	-	-	●	●	●	766,50
		Includes codes 872 [402]+902+906+907	*	*	*	*		*	
		Includes codes 902+906+907					*		
		Not in conjunction with 873	*	*	*				
		Only for left hand drive				*			
		i.V.m. Code PBR	○	○	○	○	○	○	0,00
		i.V.m. Code PYO	○	○	○	○	-	○	0,00
723	EASY-PACK load compartment cover		S	S	S	S	-	S	0,00
		Only for left hand drive				*			
890	EASY-PACK tailgate		S	S	S	S	S	S	0,00
		Only for left hand drive				*			
892	Lockable load compartment floor		●	●	●	●	-	●	73,50
		Only for left hand drive				*			
E80	Rear sill protector		●	●	●	●	-	●	162,75
E80		Only for left hand drive				*			
E82	Protection and Care set		●	●	●	●	-	●	120,75
E82		Only for left hand drive				*			
U40	Dividing net for luggage compartment partitioning and		●	●	●	●	-	●	115,50
		Not in conjunction with 224	*	*	*	*		*	
		Only in conjunction with 226	*	*	*	*		*	
		Only for left hand drive				*			
H11	designo high-gloss black flowing lines piano lacquer		-	-	-	-	●	-	603,75
		Not in conjunction with H22/H31/H34/H35					*		
H34	designo high-gloss brown lightlines lime wood		●	●	●	●	-	●	771,75
			-	-	-	-	●	-	603,75
		Not in conjunction with H11					*		
		Not in conjunction with H18/H46/H64/H86	*	*	*	*		*	
		Not in conjunction with H22/H31/H35	*	*	*	*	*	*	
		Not in conjunction with L6H						*	
		Only for left hand drive				*			
		only in conjunction with 876	*	*	*	*			
		i.V.m. Code P22	●	●	●	●	-	-	603,75
H35	designo black flamed open-pore ash wood		●	●	●	●	-	●	462,00
			-	-	-	-	●	-	294,00
		Not in conjunction with H11					*		
		Not in conjunction with H18/H46/H64/H86	*	*	*	*		*	
		Not in conjunction with H22/H31/H34	*	*	*	*	*	*	
		Not in conjunction with L3D	*	*	*	*	*		
		Only in conjunction with L3B					*		
		Only for left hand drive				*			
		only in conjunction with 876	*	*	*	*			
		i.V.m. Code P22	●	●	●	●	-	-	294,00
PBP	ENERGIZING package		●	●	●	●	-	-	729,75
			-	-	-	●	●	●	351,75
		Includes codes 873 [401/902]+876	*	*	*				
		Includes codes 876				*	*	*	
		Not in conjunction with 548	*	*	*	*	*		
		Not in conjunction with PBR	*	*	*	*	*	*	
		Only in conjunction with 256						*	
		Only in conjunction with 549	*	*	*	*	*	*	
		Only in conjunction with P21	*	*	*	*			
		Only for left hand drive				*			
		i.V.m. Code PYN	○	○	○	○	-	○	0,00
PBR	ENERGIZING package Plus		●	●	●	-	-	-	4.184,25
			-	-	-	●	-	-	1.874,25
			-	-	-	-	●	●	1.118,25
		Includes codes 399+876	*	*	*	*	*	*	
		Not in conjunction with 548	*	*	*	*	*		
		Not in conjunction with 873/U22	*	*	*				
		Not in conjunction with PBP	*	*	*	*	*	*	
		Only in conjunction with 256						*	
		Only in conjunction with 549+P69	*	*	*	*	*	*	
		Only in conjunction with P21	*	*	*	*			
		Only for left hand drive				*			
		i.V.m. Code PYB	-	-	-	-	○	-	0,00
		i.V.m. Code PYO	○	○	○	○	-	○	0,00
U12	Velour floor mats		●	●	●	●	-	-	94,50
			-	-	-	-	S	-	0,00
		Not in conjunction with 669/L5C/P31/P55/RPA/RPB/RPQ/RWF/RWH/U26/U50	*	*	*	*			

		Not in conjunction with U14						*		
		Only for left hand drive					*			
		standard equipment for certain countries	*	*	*	*	*			
		i.V.m. Code P22	○	○	○	○	-	-		0,00
		i.V.m. Code PYB	○	○	○	○	-	-		0,00
U14	High-pile floor mats		-	-	-	-	●	-		273,00
		Not in conjunction with U12					*			
		i.V.m. Code PYB	-	-	-	-	○	-		0,00
U25	Illuminated AMG door sill panels with »AMG« lettering		-	-	-	-	-	S		0,00
U26	AMG floor mats		○	○	○	○	-	S		0,00
		Not in conjunction with 36R/65R	*	*	*					
		Not in conjunction with 690/94R/95R/R33/R66/R76/U12	*	*	*	*				
		Not in conjunction with R02	*	*						
		Only in conjunction with P31	*	*	*	*				
		Only for left hand drive				*				
256	AMG TRACK PACE		-	-	-	-	-	●		262,50
		Only in conjunction with 549						*		
463	Head-up Display		●	●	●	●	●	●		1.144,50
		Only for left hand drive				*				
		i.V.m. Code PAU	○	○	○	○	○	○		0,00
		i.V.m. Code PYB	-	-	-	-	○	-		0,00
		i.V.m. Code PYO	○	○	○	○	-	○		0,00
868	Widescreen cockpit		S	S	S	S	S	S		0,00
		Only for left hand drive				*				
U19	MBUX augmented reality for navigation		●	●	●	●	●	●		409,50
		Not in conjunction with 548	*	*	*	*	*			
		Only in conjunction with 256						*		
		Only in conjunction with 549	*	*	*	*	*	*		
		Only for left hand drive				*				
		i.V.m. Code PYB	-	-	-	-	○	-		0,00
		i.V.m. Code PYO	○	○	○	○	-	○		0,00
876	Ambient lighting		S	S	S	S	S	S		0,00
		Only for left hand drive				*				
51U	Roof liner in black fabric		●	●	●	●	-	-		367,50
			-	-	-	-	-	S		0,00
		Not in conjunction with 134A/135A	*	*	*					
		Not in conjunction with 214A/215A	*	*	*	*				
		Not in conjunction with 55U/58U/61U	*	*	*	*		*		
		Not in conjunction with 565A						*		
		Only for left hand drive				*				
		i.V.m. Code 284A	○	○	○	○	-	-		0,00
55U	Roof liner in macchiato beige fabric		○	○	○	○	-	○		0,00
		Not in conjunction with 111A/134A	*	*	*					
		Not in conjunction with 201A/214A/284A/951A/U38	*	*	*	*				
		Not in conjunction with 51U/58U/61U	*	*	*	*		*		
		Not in conjunction with 551A/554A/561A/851A/854A/Y05						*		
		Only for left hand drive				*				
58U	Roof liner in crystal grey fabric		○	○	○	○	-	○		0,00
		Not in conjunction with 135A	*	*	*					
		Not in conjunction with 215A/951A/U38	*	*	*	*				
		Not in conjunction with 51U/55U/61U	*	*	*	*		*		
		Not in conjunction with 565A						*		
		Only for left hand drive				*				
61U	Roof lining in black DINAMICA microfibre		●	●	●	●	-	●		1.680,00
			-	-	-	-	S	-		0,00
		Not in conjunction with 135A	*	*	*					
		Not in conjunction with 215A	*	*	*	*				
		Not in conjunction with 51U/55U/58U	*	*	*	*		*		
		Not in conjunction with 65U/71U/75U/79U/954A/959A					*			
		Only in conjunction with 543	*	*	*	*	*	*		
		Only for left hand drive				*				
65U	designo roof liner in macchiato beige DINAMICA microfibre		-	-	-	-	○	-		0,00
		Not in conjunction with 51U/61U/71U/75U/79U								
		Not in conjunction with 61U/71U/75U/79U/951A/959A					*			
		Only in conjunction with 543					*			
71U	designo roof liner in black nappa leather		-	-	-	-	○	-		0,00
		Not in conjunction with 51U/61U/65U/75U/79U								
		Not in conjunction with 61U/65U/75U/79U/954A/959A					*			
		Only in conjunction with 543					*			
		available only as part of (U61)					*			
75U	designo roof liner in porcelain nappa leather		-	-	-	-	○	-		0,00
		Not in conjunction with 51U/61U/65U/71U/79U								
		Not in conjunction with 61U/65U/71U/79U/951A/959A					*			
		Only in conjunction with 543+954A								
		Only in conjunction with 543					*			



79U	designo roof liner in crystal white nappa leather		-	-	-	-	○	-	0,00
		Not in conjunction with 51U/61U/65U/71U/75U							
		Not in conjunction with 61U/65U/71U/75U/951A/954A					*		
		Only in conjunction with 543					*		
		available only as part of (U61)					*		
254	Electrically adjustable seat cushion depth and head re		○	○	○	○	-	○	0,00
		Not in conjunction with 111A/134A/135A/864/P64	*	*	*				
		Not in conjunction with 241	*	*					
		included in configuration of code 201A/204A/205A/284A	*	*	*	*			
		not in conjunction with code 275/P64	*	*	*	*			
		standard equipment in certain countries						*	
275	Driver's seat, electrically adjustable with memory func		●	●	●	-	-	-	845,25
			-	-	-	S	S	S	0,00
		Available only as part of (P64)	*	*	*				
		Not in conjunction with 254	*	*	*				
		Only in conjunction with P64	*	*	*				
		Only for left hand drive				*			
		only in conjunction with P49	*	*	*	*			
		i.V.m. Code P64	○	○	○	-	-	-	0,00
399	multicontour front seats		●	●	●	-	-	-	2.310,00
			-	-	-	S	S	S	0,00
		Not in conjunction with 873/U22	*	*	*				
		Only in conjunction with 401+436+902	*	*	*				
		Only for left hand drive				*			
		included in configuration: code 401 902 436	*	*	*	*			
		only in conjunction with code 201A/204A/205A/284A/958A	*	*	*	*			
		i.V.m. Code PBP	●	●	●	-	-	-	1.932,00
		i.V.m. Code PBR	○	○	○	-	-	-	0,00
		i.V.m. Code PYO	○	○	○	-	-	-	0,00
401	Climatised front seats		●	●	●	-	-	-	1.155,00
			-	-	-	S	S	S	0,00
		Not in conjunction with 873	*	*	*				
		Only for left hand drive				*			
		i.V.m. Code P69	●	●	●	-	-	-	777,00
		i.V.m. Code PBP	●	●	●	-	-	-	777,00
		i.V.m. Code 399	○	○	○	-	-	-	0,00
		i.V.m. Code PYO	○	○	○	-	-	-	0,00
452	Seat on front passenger side electrically adjustable fr		●	●	●	●	-	●	210,00
			-	-	-	-	S	-	0,00
		Not in conjunction with 224	*	*	*	*		*	
		Only in conjunction with P08+P11	*	*	*	*		*	
		Only for left hand drive				*			
		standard equipment in certain countries	*	*	*	*		*	
873	Heated front seats		●	●	●	-	-	-	0,00
873	Heated front seats		-	-	-	-	-	S	0,00
873		Not in conjunction with 399/401/402/406/436/902/951A/P69/PBR/U38	*	*	*				
873		not valid						*	
873		standard equipment in certain countries	*	*	*				
873		i.V.m. Code PBP	○	○	○	-	-	-	0,00
P64	Memory package		●	●	●	-	-	-	1.092,00
			-	-	-	S	S	S	0,00
		Includes codes 242+275	*	*	*	*	*	*	
		Not in conjunction with 254	*	*	*				
		Only for left hand drive				*			
		includes codes 241/242 + 275	*	*	*	*	*	*	
		only in conjunction with P49	*	*	*	*	*	*	
		standard equipment in certain countries	*	*	*	*	*	*	
		i.V.m. Code 201A	●	●	●	-	-	-	934,50
		i.V.m. Code PYM/PYN/PYO	○	○	○	-	-	-	0,00
U10	Automatic front passenger airbag deactivation		S	S	S	S	S	S	0,00
		Only for left hand drive				*			
224	luxury individual seats		-	-	-	-	●	-	3.937,50
			●	●	●	●	-	●	525,00
		Not in conjunction with 226/307/402/406/452/P08/P11/U40	*	*	*	*		*	
		Only in conjunction with 872						*	
		Only for left hand drive	*	*	*	*		*	
226	5+2-seater		S	S	S	S	-	S	0,00
		Not in conjunction with 224	*	*	*	*		*	
		Only for left hand drive				*			
308	Refrigerated compartment		-	-	-	-	●	-	1.155,00
402	Climatised rear seats		●	●	●	-	-	-	1.155,00
			-	-	-	●	-	●	777,00
			-	-	-	-	S	-	0,00
		Not in conjunction with 111A/873	*	*	*				
		Not in conjunction with 224/872	*	*	*	*		*	

		Only in conjunction with 401	*	*	*				
		Only in conjunction with 406+P08+P11	*	*	*	*		*	
		Only for left hand drive				*			
		i.V.m. Code P69	●	●	●	-	-	-	777,00
		i.V.m. Code 406	○	○	○	○	-	○	0,00
		i.V.m. Code PYQ	○	○	○	○	-	○	0,00
406	Multicontour rear seats		●	●	●	●	-	●	2.310,00
			-	-	-	-	S	-	0,00
		Not in conjunction with 111A/873	*	*	*				
		Not in conjunction with 224/872	*	*	*	*		*	
		Only in conjunction with 401	*	*	*				
		Only in conjunction with 402+P08+P11	*	*	*	*		*	
		Only for left hand drive				*			
		i.V.m. Code PYQ	○	○	○	○	-	○	0,00
437	Luxury rear head restraints		○	○	○	○	S	○	0,00
		Available only as part of (P08)	*	*	*	*		*	
		Not in conjunction with 224	*	*	*	*		*	
		Only in conjunction with P08+P11	*	*	*	*		*	
		Only for left hand drive				*			
449	folding tables in the rear		-	-	-	-	●	-	1.890,00
		Only in conjunction with 224					*		
453	Executive seats		-	-	-	-	S	-	0,00
845	3rd seat row		S	S	S	S	-	S	0,00
		Only for left hand drive				*			
872	Heated rear seats		●	●	●	-	-	-	378,00
			-	-	-	○	-	○	0,00
		Not in conjunction with 402/406	*	*	*	*		*	
		Only for left hand drive				*			
		standard equipment in certain countries						*	
		i.V.m. Code P69	○	○	○	-	-	-	0,00
886	Seat heating for the 3rd seat row		●	●	●	●	-	●	378,00
		Only in conjunction with 582	*	*	*	*		*	
		Only for left hand drive				*			
903	seat heating Plus for outer rear seats		-	-	-	-	S	-	0,00
P08	Rear Comfort package		○	○	○	○	-	○	0,00
		Includes codes 201A [111A/284A]+226+293+437+72B	*	*	*				
		Includes codes 201A [284A]+226+293+437+72B				*			
		Includes codes 226+293+437+72B						*	
		Not in conjunction with 224	*	*	*	*		*	
		Only in conjunction with P11	*	*	*	*		*	
		Only for left hand drive				*			
P11	Rear Comfort package Plus		●	●	●	●	-	●	1.869,00
		Includes codes 447+898	*	*	*	*		*	
		Not in conjunction with 224	*	*	*	*		*	
		Only in conjunction with P08	*	*	*	*		*	
		Only for left hand drive				*			
		i.V.m. Code PYQ	○	○	○	○	-	○	0,00
77B	MBUX Interior Assistant		●	●	●	●	●	●	315,00
		Not in conjunction with 811	*	*	*	*	*	*	
		Only in conjunction with 810					*	*	
		Only for left hand drive				*			
		i.V.m. Code PAU	○	○	○	○	○	○	0,00
L3B	Multifunction sports steering wheel in nappa leather		S	S	S	○	S	-	0,00
		Not in conjunction with L3D	*	*	*	*	*		
		Not in conjunction with L5C	*	*	*	*			
		Only for left hand drive				*			
		standard equipment in certain countries				*			
L3D	Wood/leather multifunction steering wheel		●	●	●	●	●	-	619,50
		Not in conjunction with H18/H46/H64/H86/L5C	*	*	*	*			
		Not in conjunction with H31/H35/L3B				*			
		Not in conjunction with H31					*		
		Not in conjunction with H35/L3B	*	*	*	*	*		
		Only for left hand drive				*			
L5C	Multifunction sports steering wheel in nappa leather		○	○	○	○	-	-	0,00
		Available only as part of (P31)	*	*	*	*			
		Not in conjunction with 36R/65R	*	*	*				
		Not in conjunction with 443/690/94R/95R/L3B/L3D/R33/R66/R76/U12	*	*	*	*			
		Not in conjunction with R02	*	*					
		Only in conjunction with P31+U26	*	*	*	*			
		Only for left hand drive				*			
U88	AMG steering wheel buttons		-	-	-	-	-	●	367,50
		Not in conjunction with 443						*	
		i.V.m. Code PYB	-	-	-	-	-	○	0,00
301	Smoker package		●	●	●	●	●	●	47,25
		Only for left hand drive				*			

		for certain countries only	*	*	*	*			
307	Temperature-controlled cup holder in the rear		●	●	●	●	-	●	220,50
			-	-	-	-	S	-	0,00
		Not in conjunction with 224	*	*	*	*		*	
		Only in conjunction with P08+P11	*	*	*	*		*	
		Only for left hand drive				*			
		standard equipment in certain countries						*	
311	Temperature-controlled cup holder		●	●	●	●	●	●	220,50
			-	-	-	-	-	-	0,00
		Only for left hand drive				*			
		standard equipment in certain countries							
		i.V.m. Code PYB	-	-	-	-	○	-	0,00
		i.V.m. Code PYO	○	○	○	○	-	○	0,00
B65	Holder for champagne flutes		-	-	-	-	●	-	840,00
		Only in conjunction with 224+308					*		
735	Exclusive trim package		●	●	●	●	-	●	472,50
			-	-	-	-	S	-	0,00
		Not in conjunction with H46/H64	*	*	*	*		*	
		Only for left hand drive				*			
H18	High-gloss anthracite lime wood trim		S	S	S	S	-	S	0,00
		Not in conjunction with H22/H31/H34/H35/H46/H64/H86	*	*	*	*		*	
		Not in conjunction with L3D	*	*	*	*			
		Not in conjunction with L6H						*	
		Only for left hand drive				*			
H22	Brown open-pore walnut wood trim		●	●	●	●	-	●	168,00
			-	-	-	-	○	-	0,00
		Not in conjunction with H11					*		
		Not in conjunction with H18/H46/H64/H86	*	*	*	*		*	
		Not in conjunction with H31/H34/H35	*	*	*	*	*	*	
		Not in conjunction with L6H						*	
		Only for left hand drive				*			
		i.V.m. Code P22	○	○	○	○	-	-	0,00
H31	Anthracite open-pore oak wood trim elements		●	●	●	●	-	●	168,00
			-	-	-	-	S	-	0,00
		Not in conjunction with H11/L3D					*		
		Not in conjunction with H18/H46/H64/H86	*	*	*	*		*	
		Not in conjunction with H22/H34/H35	*	*	*	*	*	*	
		Only in conjunction with L3B					*		
		Only for left hand drive				*			
		i.V.m. Code P22	○	○	○	○	-	-	0,00
H46	Brushed aluminium trim with light longitudinal grain		○	○	○	○	-	○	0,00
		Not in conjunction with 735/H18/H22/H31/H34/H35/H64/H86	*	*	*	*		*	
		Not in conjunction with L3D	*	*	*	*			
		Not in conjunction with L6H						*	
		Only for left hand drive				*			
H86	AMG carbon-fibre trim		●	●	●	●	-	●	1.837,50
		Not in conjunction with H18/H22/H31/H34/H35/H46/H64	*	*	*	*		*	
		Not in conjunction with L3D	*	*	*	*			
		Only for left hand drive				*			
P22	EXCLUSIVE interior		●	●	●	-	-	-	2.598,75
			-	-	-	●	-	-	708,75
		Includes codes 201A [215A/284A]+876+901+H22 [H18/H31/H34/H35/H46/H64/H86]+U09+U12	*	*	*	*			
		Not in conjunction with 111A/134A/135A	*	*	*				
		Not in conjunction with U08	*	*	*	*			
		Only for left hand drive				*			
		i.V.m. Code PYB	●	●	●	●	-	-	903,00
P31	AMG Line		●	●	●	-	-	-	3.780,00
			-	-	-	●	-	-	3.412,50
		Includes codes 772+L5C [L3B/L3D]+RWF [RPA/RPB/RPQ/RWH]	*	*	*	*			
		Not in conjunction with 36R/65R	*	*	*				
		Not in conjunction with 690/94R/95R/R33/R66/R76/U12	*	*	*	*			
		Not in conjunction with R02	*	*					
		Only in conjunction with U26	*	*	*	*			
		Only for left hand drive				*			
		i.V.m. Code PYH	○	○	○	○	-	-	0,00
362	Communications module (LTE) for the use of Mercedes		○	○	○	○	○	○	0,00
		Only for left hand drive				*			
08U	Preinstallation for Vehicle Set-Up		●	●	●	●	●	●	0,00
08U		Only for left hand drive				*			
08U		standard equipment in certain countries	*	*	*	*	*	*	
09U	Preinstallation for Vehicle Monitoring		●	●	●	●	●	●	0,00
09U		Only for left hand drive				*			
20U	Pre-installation for car sharing		●	●	●	●	●	●	52,50
		Only for left hand drive				*			
		i.V.m. Code PYB	○	○	○	○	○	○	0,00

351	Mercedes-Benz emergency call system		○	○	○	○	○	○	0,00
		Only for left hand drive				*			
00B	Owner's Manual and Service Booklet - Danish		○	○	○	○	○	○	0,00
		Not in conjunction with 01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/13B/14B/15B/16B/17B/30B	*	*	*	*	*	*	
		Only for left hand drive				*			
01B	Owner's Manual and Service Booklet - Dutch		○	○	○	○	○	○	0,00
		Not in conjunction with 00B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/13B/14B/15B/16B/17B/30B	*	*	*	*	*	*	
		Only for left hand drive				*			
02B	Owner's Manual and Service Booklet - German		○	○	○	○	○	○	0,00
		Not in conjunction with 00B/01B/03B/04B/05B/06B/07B/08B/09B/10B/11B/13B/14B/15B/16B/17B/30B	*	*	*	*	*	*	
		Only for left hand drive				*			
03B	Owner's Manual and Service Booklet - Russian		○	○	○	○	○	○	0,00
		Not in conjunction with 00B/01B/02B/04B/05B/06B/07B/08B/09B/10B/11B/13B/14B/15B/16B/17B/30B	*	*	*	*	*	*	
		Only for left hand drive				*			
040U	black		○	○	○	○	○	○	0,00
		Only for left hand drive				*			
04B	Owner's Manual and Service Booklet - Finnish		○	○	○	○	○	○	0,00
		Not in conjunction with 00B/01B/02B/03B/05B/06B/07B/08B/09B/10B/11B/13B/14B/15B/16B/17B/30B	*	*	*	*	*	*	
		Only for left hand drive				*			
05B	Owner's Manual and Service Booklet - English		○	○	○	○	○	○	0,00
		Not in conjunction with 00B/01B/02B/03B/04B/06B/07B/08B/09B/10B/11B/13B/14B/15B/16B/17B/30B	*	*	*	*	*	*	
		Only for left hand drive				*			
06B	Owner's Manual and Service Booklet - Italian		○	○	○	○	○	○	0,00
		Not in conjunction with 00B/01B/02B/03B/04B/05B/07B/08B/09B/10B/11B/13B/14B/15B/16B/17B/30B	*	*	*	*	*	*	
		Only for left hand drive				*			
07B	Owner's Manual and Service Booklet - French		○	○	○	○	○	○	0,00
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/08B/09B/10B/11B/13B/14B/15B/16B/17B/30B	*	*	*	*	*	*	
		Only for left hand drive				*			
08B	Owner's Manual and Service Booklet - Spanish		○	○	○	○	○	○	0,00
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/09B/10B/11B/13B/14B/15B/16B/17B/30B	*	*	*	*	*	*	
		Only for left hand drive				*			
09B	Owner's Manual and Service Booklet - Portuguese		○	○	○	○	○	○	0,00
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/10B/11B/13B/14B/15B/16B/17B/30B	*	*	*	*	*	*	
		Only for left hand drive				*			
10B	Owner's Manual and Service Booklet - Swedish		○	○	○	○	○	○	0,00
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/11B/13B/14B/15B/16B/17B/30B	*	*	*	*	*	*	
		Only for left hand drive				*			
111A	ARTICO man-made leather black		S	S	S	-	-	-	0,00
		Not in conjunction with 135A/215A/231U/254/292/402/406/55U/P22	*	*	*				
11B	Owner's Manual and Service Booklet - Arabic		○	○	○	○	○	○	0,00
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/13B/14B/15B/16B/17B/30B	*	*	*	*	*	*	
		Only for left hand drive				*			
12B	Owner's Manual and Service Booklet - Engl. USA/CAN		-	-	○	○	○	○	0,00
12U	Preinstallation for Concierge Service		○	○	○	○	○	○	0,00
		for certain countries only	*	*	*	*	*	*	
		only in conjunction with 362	*	*	*	*	*	*	
		standard equipment in certain countries	*	*	*	*	*	*	
134A	ARTICO man-made leather espresso brown / black		●	●	●	-	-	-	367,50
		Not in conjunction with 135A/215A/231U/254/292/51U/55U/P22	*	*	*				
135A	ARTICO man-made leather macchiato beige / black		●	●	●	-	-	-	367,50
		Not in conjunction with 111A/134A/201A/214A/231U/254/284A/292/51U/58U/61U/951A/P22/U38	*	*	*				
		Only in conjunction with 55U	*	*	*				
13B	Owner's Manual and Service Booklet - Norwegian		○	○	○	○	○	○	0,00
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/13B/14B/15B/16B/17B/30B	*	*	*	*	*	*	
		Only for left hand drive				*			
149U	polar white		●	●	●	●	●	●	315,00
		Only for left hand drive				*			
14B	Owner's Manual and Service Booklet - Greek		○	○	○	○	○	○	0,00
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/13B/14B/15B/16B/17B/30B	*	*	*	*	*	*	
		Only for left hand drive				*			
15B	Owner's Manual and Service Booklet - Turkish		○	○	○	○	○	○	0,00
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/13B/14B/15B/16B/17B/30B	*	*	*	*	*	*	
		Only for left hand drive				*			
15U	Preinstallation for Mercedes-Benz Link		○	○	○	○	○	○	0,00
16B	Owner's Manual and Service Booklet - Polish		○	○	○	○	○	○	0,00
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/13B/14B/15B/17B/30B	*	*	*	*	*	*	
		Only for left hand drive				*			
16U	Apple CarPlay		○	○	○	○	○	○	0,00
		Only for left hand drive				*			
		included in configuration of 14U	*	*	*	*			
17B	Owner's Manual and Service Booklet - Czech		○	○	○	○	○	○	0,00
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/13B/14B/15B/16B/30B	*	*	*	*	*	*	
		Only for left hand drive				*			
17U	Android Auto		○	○	○	○	○	○	0,00
		Only for left hand drive				*			

		included in configuration of 14U	*	*	*	*				
18B	Owner's Manual and Service Booklet - Engl. S. Am.		○	○	○	○	○	○		0,00
18U	Baidu Carlife		-	-	○	○	○	○		0,00
		for certain countries only			*	*	*	*		
		only in conjunction with 14U			*	*	*	*		
197U	obsidian black metallic		●	●	●	●	●	●		924,00
		Only for left hand drive				*				
		i.V.m. Code C21/C23	-	-	-	-	○	-		0,00
		i.V.m. Code PYB	-	-	-	-	○	-		0,00
19B	Owner's Manual and Service Booklet - French S. Am.		○	○	○	○	○	○		0,00
201A	Rough leather / leather black		●	●	●	-	-	-		0,00
201A	Rough leather / leather black		-	-	-	S	-	-		0,00
201A		Not in conjunction with 135A	*	*	*					
201A		Not in conjunction with 215A/55U	*	*	*	*				
201A		Only for left hand drive				*				
201A		standard equipment in certain countries	*	*	*	*				
201A		i.V.m. Code P22	○	○	○	-	-	-		0,00
20B	Owner's Manual and Service Booklet - Spanish S. Am.		○	○	○	○	○	○		0,00
214A	Rough leather / leather espresso brown / black	Delta due to 201A	●	●	●	-	-	-		367,50
214A	Rough leather / leather espresso brown / black		-	-	-	●	-	-		367,50
214A		Not in conjunction with 135A	*	*	*					
214A		Not in conjunction with 215A/51U/55U	*	*	*	*				
214A		Only for left hand drive				*				
215	Suspension with adaptive damping system		S	S	S	S	S	S		0,00
		Not in conjunction with 490	*	*	*	*	*			
		Not in conjunction with B01	*	*						
		Only for left hand drive				*				
		for certain countries only	*	*	*	*	*	*		
215A	Leather, two-tone macchiato beige / black	Delta due to 201A	●	●	●	-	-	-		367,50
215A	Leather, two-tone macchiato beige / black		-	-	-	●	-	-		367,50
215A		Not in conjunction with 111A/134A	*	*	*					
215A		Not in conjunction with 201A/214A/284A/51U/58U/61U/951A/U38	*	*	*	*				
215A		Only in conjunction with 55U	*	*	*	*				
215A		Only for left hand drive				*				
21B	Owner's Manual and Service Booklet - Portug. S. Am.		○	○	○	○	○	○		0,00
22B	Owner's Manual and Service Booklet - Japanese		○	○	○	○	○	○		0,00
22P	Lane Tracking package		●	●	●	●	-	●		819,00
		for certain countries only	*	*	*	*	*	*		
		includes Codes 234+243	*	*	*	*		*		
		only in conjunction with P49	*	*	*	*		*		
232	Garage door opener (frequency range 284-390 MHz)		-	-	●	●	●	●		236,25
		for certain countries only			*	*	*	*		
		only in conjunction with P49			*	*	*	*		
233	Active Distance Assist DISTRONIC		○	○	○	○	○	○		0,00
		Not in conjunction with 234/239/243/258/504	*	*	*	*		*		
		Only in conjunction with 266+273+513+546+K32+K34	*	*	*	*		*		
		Only in conjunction with K33				*		*		
		Only for left hand drive				*				
		for certain countries only	*	*	*	*				
		included in configuration of P20/23P	*	*	*	*				
235	Active Parking Assist with PARKTRONIC		○	○	○	○	S	○		0,00
		Only for left hand drive				*				
		included in configuration of P44/P47	*	*	*	*	*	*		
23B	Owner's Manual and Service Booklet - simpl. Chinese		-	-	○	○	○	○		0,00
241	Power front left seat with memory function		○	○	○	○	○	○		0,00
		Not in conjunction with 254	*	*						
		Only for right hand drive	*	*			*	*		
		only available as part of (P64)	*	*	*	*	*	*		
242	Power front right seat with memory function		○	○	○	○	S	○		0,00
		Available only as part of (P64)	*	*	*					
		Not in conjunction with 254	*	*	*					
		Only for left hand drive	*	*		*	*	*		
249	Interior mirror and driver's exterior mirror automatic		○	○	○	○	S	○		0,00
		Only for left hand drive				*				
		only available as part of (P49)	*	*	*	*	*	*		
24B	Owner's Manual and Service Booklet - trad. Chinese		○	○	○	○	○	○		0,00
25B	Owner's Manual and Service Booklet - Korean		○	○	○	○	○	-		0,00
263	Number plate mounting for Asia / Mexico		○	○	○	○	○	○		0,00
264	Number plate mounting for USA/CAN		-	○	○	○	○	○		0,00
		standard equipment in certain countries		*	*	*	*	*		
266	Active Steering Assist		○	○	○	○	○	○		0,00
		Not in conjunction with 234/239/243/258/504	*	*	*	*		*		
		Only in conjunction with K32	*	*	*	*		*		
		Only for left hand drive				*				
		for certain countries only	*	*	*	*				

		included in configuration of P20/23P	*	*	*	*	*			
26B	Owner's Manual and Service Booklet - Chinese Taiwan		○	○	○	-	○	○		0,00
26U	Preinstallation for engine remote start		●	●	●	●	●	●		105,00
		for certain countries only	*	*	*	*	*	*		
		only in conjunction with 362	*	*	*					
		i.V.m. S-Code PZG	●	●	●	●	●	●		52,50
270	GPS aerial		S	S	S	S	S	S		0,00
		Only for left hand drive				*				
273	Exit warning function		○	○	○	○	○	○		0,00
		Only for left hand drive				*				
		included in configuration of 233/234	*	*	*	*				
274	Telephone aerial		○	○	○	○	○	○		0,00
		Only for left hand drive				*				
		included in configuration of 380/899/B24	*	*	*	*				
27B	Owner's Manual and Service Booklet - Spanish Mexico		-	-	-	○	○	-		0,00
284A	Rough leather / two-tone leather truffle brown / black	Delta due to 201A	●	●	●	-	-	-		367,50
284A	Rough leather / two-tone leather truffle brown / black		-	-	-	●	-	-		367,50
284A		Not in conjunction with 135A	*	*	*					
284A		Not in conjunction with 215A/55U	*	*	*	*				
284A		Only for left hand drive				*				
284A		i.V.m. Code P22	●	●	●	-	-	-		367,50
30B	Owner's Manual and Service Booklet - Slovenian		○	○	○	○	○	○		0,00
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/13B/14B/15B/16B/17B	*	*	*	*	*	*		
		Only for left hand drive				*				
31B	Owner's Manual and Service Booklet - Hungarian		○	○	○	○	○	○		0,00
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/13B/14B/15B/16B/17B	*	*	*	*	*	*		
		Only for left hand drive				*				
32B	Owner's Manual and Service Booklet - Bulgarian		○	○	○	○	○	○		0,00
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/13B/14B/15B/16B/17B	*	*	*	*	*	*		
		Only for left hand drive				*				
33B	Owner's Manual and Service Booklet - Romanian		○	○	○	○	○	○		0,00
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/13B/14B/15B/16B/17B	*	*	*	*	*	*		
		Only for left hand drive				*				
34B	Owner's Manual and Service Booklet - Croatian		○	○	○	○	○	○		0,00
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/13B/14B/15B/16B/17B	*	*	*	*	*	*		
		Only for left hand drive				*				
35B	Owner's Manual and Service Booklet - Latvian		○	○	○	○	○	○		0,00
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/13B/14B/15B/16B/17B	*	*	*	*	*	*		
		Only for left hand drive				*				
367	Preinstallation for Live Traffic Information		○	○	○	○	○	○		0,00
		Only for left hand drive				*				
		for certain countries only	*	*	*	*				
		only in conjunction with 362	*	*	*	*				
36B	Owner's Manual and Service Booklet - Lithuanian		○	○	○	○	○	○		0,00
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/13B/14B/15B/16B/17B	*	*	*	*	*	*		
		Only for left hand drive				*				
37B	Owner's Manual and Service Booklet - Slovakian		○	○	○	○	○	○		0,00
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/13B/14B/15B/16B/17B	*	*	*	*	*	*		
		Only for left hand drive				*				
38B	Owner's Manual and Service Booklet - Estonian		○	○	○	○	○	○		0,00
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/13B/14B/15B/16B/17B	*	*	*	*	*	*		
		Only for left hand drive				*				
39B	Owner's Manual and Service Booklet - Serbian		○	○	○	○	○	○		0,00
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/13B/14B/15B/16B/17B	*	*	*	*	*	*		
		Only for left hand drive				*				
40B	Owner's Manual and Service Booklet - ukrainian		○	○	○	○	○	○		0,00
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/13B/14B/15B/16B/17B	*	*	*	*	*	*		
		Only for left hand drive				*				
41B	Owner's Manual and Service Booklet - hebrew		○	○	○	○	○	○		0,00
		Not in conjunction with 00B/01B/02B/03B/04B/05B/06B/07B/08B/09B/10B/11B/13B/14B/15B/16B/17B	*	*	*	*	*	*		
		Only for left hand drive				*				
42B	Owner's Manual and Service Booklet - Indonesian		○	○	○	○	○	○		0,00
436	Comfort front head restraints		○	○	○	○	○	○		0,00
		Not in conjunction with 873/U22	*	*	*					
		Only in conjunction with 399+401+902	*	*	*					
		Only for left hand drive				*				
		included within: 399	*	*	*	*				
43B	Owner's Manual and Service Booklet - Thai		○	○	○	○	○	○		0,00
44B	Owner's Manual and Service Booklet - Vietnamese		○	○	○	○	○	○		0,00
460	Canada specification		-	-	○	○	○	○		0,00
461	Instrument display in miles with English lettering		○	○	○	○	○	○		0,00
		Only for left hand drive				*				
		standard equipment in certain countries	*	*	*	*	*	*		
477	Tyre pressure loss warning system		○	○	○	○	○	-		0,00
494	USA specification		-	-	○	○	○	○		0,00

496	Mexico version		-	-	○	○	○	-	0,00
498	Japan specification		○	○	-	○	○	○	0,00
500	Electrically folding exterior mirrors		○	○	○	○	○	○	0,00
		Only for left hand drive				*			
		included in configuration of P49	*	*	*	*			
501	360° camera		○	○	○	○	S	○	0,00
		Available only as part of (P47)	*	*	*				
		Not in conjunction with P44	*	*	*				
		Only in conjunction with P47	*	*	*				
		Only for left hand drive				*			
		included in configuration of P47	*	*	*	*			
		only in conjunction with 249	*	*	*	*			
517	HD digital radio standard		-	-	○	○	○	○	0,00
		standard equipment in certain countries			*	*	*	*	
524	Transport protection (full body cover)		●	●	●	●	●	●	168,00
		for certain countries only	*	*	*	*			
536	Radio: SIRIUS/SDARS ex factory		-	-	●	●	●	●	462,00
		for certain countries only			*	*	*	*	
546	Active Speed Limit Assist		○	○	○	○	○	○	0,00
		Not in conjunction with 234/239/243/258/504	*	*	*	*		*	
		Only in conjunction with 233+266+273+513+K32+K34	*	*	*	*		*	
		Only in conjunction with K33				*		*	
		Only for left hand drive				*			
		for certain countries only	*	*	*	*			
		included in configuration of (P20/23P)+513	*	*	*	*			
548	MBUX multimedia system		S	S	S	S	S	S	0,00
		Not in conjunction with 549/864/865/PAU/PBP/PBR/U19	*	*	*	*	*		
		Only for left hand drive				*			
		not in conjunction with 21U	*	*	*	*			
549	MBUX multimedia system		○	○	○	○	○	○	0,00
		Not in conjunction with 548	*	*	*	*	*		
		Only in conjunction with 256						*	
		Only for left hand drive				*			
		only in conjunction with U19/864/865/21U/PBP/PBR	*	*	*	*			
		standard equipment in certain countries	*	*	*	*			
551A	AMG Exclusive nappa leather black		-	-	-	-	-	●	2.100,00
		Not in conjunction with 55U/U09						*	
		Only in conjunction with U38						*	
552	Anti-theft alarm system		○	○	○	○	○	○	0,00
		for certain countries only	*	*	*	*	*	*	
		only in conjunction with P54/P82	*	*	*	*	*	*	
554A	Two-tone exclusive nappa AMG leather truffle brown /		-	-	-	-	-	●	2.467,50
		Not in conjunction with 55U/U09						*	
		Only in conjunction with U38						*	
561A	AMG Style Exclusive nappa leather black		-	-	-	-	-	●	2.730,00
		Not in conjunction with 55U/U09						*	
		Only in conjunction with U38						*	
565A	AMG Style Exclusive nappa leather macchiato beige /		-	-	-	-	-	●	2.730,00
		Not in conjunction with 51U/58U/U09						*	
		Only in conjunction with U38						*	
587	Ambient lighting with projection of brand logo		○	○	○	○	S	○	0,00
		Only for left hand drive				*			
		included in configuration of P49	*	*	*	*			
596	Heat-insulating, noise-insulating and infrared-reflectin		○	○	○	○	S	○	0,00
		Available only as part of (PAF)	*	*	*	*		*	
		Only in conjunction with PAF	*	*	*	*		*	
		Only for left hand drive				*			
598	Petrol particulate filter		-	-	-	○	-	-	0,00
		Only for left hand drive				*			
		only in conjunction with code 927				*			
		standard equipment in certain countries				*			
602	CKD vehicles for Russia		-	○	○	-	-	-	0,00
623	Gulf States specification		-	-	○	○	○	○	0,00
625	Australia specification		-	○	○	○	○	○	0,00
631	LED High Performance headlamp		○	○	○	-	-	-	0,00
632	LED High Performance headlamps		○	○	○	-	-	-	0,00
		standard equipment in certain countries	*	*	*				
634	Omission of first-aid kit		○	○	○	○	○	○	0,00
		for certain countries only	*	*	*	*	*	*	
636	Omission of hazard warning triangle		-	-	○	○	○	○	0,00
		for certain countries only			*	*	*	*	
640	LED High Performance headlamps with active light fun		-	-	○	S	○	○	0,00
		for certain countries only			*	*	*	*	
		included in configuration: 608			*	*	*	*	
		standard equipment in certain countries			*		*	*	

641	MULTIBEAM LED		●	●	●	-	-	-	1.365,00
			-	-	-	S	S	○	0,00
		for certain countries only	*	*	*	*	*	*	
		included in configuration: 628	*	*	*			*	
		standard equipment in certain countries	*	*	*			*	
666	Freight packaging without tie-down hooks		○	○	○	○	○	○	0,00
		for certain countries only	*	*	*	*	*	*	
668	Freight packaging with tie-down hooks		●	●	●	●	●	●	0,00
668		Only for left hand drive				*			
668		for certain countries only	*	*	*	*	*	*	
668		not in conjunction with 666	*	*	*	*	*	*	
687	Model year on model plate		○	○	○	○	○	○	0,00
		Only for left hand drive				*			
		standard equipment in certain countries	*	*	*	*			
695	Product protection rim		-	-	-	-	○	-	0,00
6U8	Location and tracking system		-	●	●	-	-	-	336,00
		for certain countries only		*	*				
		only in conjunction with code P54		*	*				
708	CKD vehicles for India		-	○	○	-	-	-	0,00
708	Fluorescent jacket for driver		●	●	●	●	●	●	5,25
		Not in conjunction with 71B	*	*	*	*	*	*	
		Only for left hand drive				*			
		standard equipment in certain countries	*	*	*	*			
714	Omission of CKD parts Brazil		○	○	○	-	-	-	0,00
719	Indonesia SKD		-	-	○	-	-	-	0,00
762	Remote control unit		○	○	○	○	○	○	0,00
		standard equipment in certain countries	*	*	*	*	*	*	
763	Radio remote control with panic switch		○	○	○	○	○	○	0,00
		for certain countries only	*	*	*	*	*	*	
		only in conjunction with 551	*	*	*	*	*	*	
772	AMG bodystyling		○	○	○	○	-	S	0,00
		Available only as part of (P31)	*	*	*	*			
		Not in conjunction with 36R/65R	*	*	*				
		Not in conjunction with 690/94R/95R/R33/R66/R76/U12	*	*	*	*			
		Not in conjunction with R02	*	*					
		Only in conjunction with P31+U26	*	*	*	*			
		Only for left hand drive				*			
775U	Iridium silver metallic		●	●	●	●	●	●	924,00
		Only for left hand drive				*			
		i.V.m. Code C25/C30	-	-	-	-	○	-	0,00
		i.V.m. Code PYB	-	-	-	-	○	-	0,00
799U	designo diamond white bright		●	●	●	●	●	●	1.743,00
		Only for left hand drive				*			
		i.V.m. Code PYB	-	-	-	-	●	-	819,00
		i.V.m. Code C22	-	-	-	-	○	-	0,00
79B	Preinstallation for digital radio		○	○	○	○	○	○	0,00
		Only for left hand drive				*			
		included in configuration of code 537	*	*	*	*	*	*	
		standard equipment in certain countries	*	*	*	*	*	*	
801	Technical modifications		○	○	○	○	○	○	0,00
		Only for left hand drive				*			
820	Tourist vehicle		○	○	○	○	○	○	0,00
821	Country code Brazil		-	○	○	-	○	○	0,00
822	South Africa specification		○	○	○	○	○	○	0,00
823	Indicator plate fixing Switzerland		○	○	○	○	○	○	0,00
824	Additional parts for cold countries (engine air intake s		○	○	○	-	-	-	0,00
		for certain countries only	*	*	*				
829	Taiwan version		○	○	○	-	○	○	0,00
830	China specification		-	-	○	○	○	○	0,00
831	Italy specification		○	○	○	○	○	○	0,00
834	New Zealand specification		-	○	-	○	○	○	0,00
835	South Korea specification		○	○	○	○	○	-	0,00
851A	AMG nappa leather black		-	-	-	-	-	S	0,00
		Not in conjunction with 55U						*	
852	Sensor system for anti-theft alarm system		-	-	●	●	●	●	147,00
		for certain countries only			*	*	*	*	
		only in conjunction with code 551			*	*	*	*	
854A	Two-tone AMG nappa leather truffle brown / black		-	-	-	-	-	●	367,50
		Not in conjunction with 55U						*	
855	Telephony in the rear		●	●	●	-	●	●	997,50
859U	mojave silver metallic		●	●	●	●	●	●	924,00
		Only for left hand drive				*			
		i.V.m. Code PYB	-	-	-	-	○	-	0,00
871	HANDS-FREE ACCESS		○	○	○	○	○	○	0,00
		Only for left hand drive				*			



		included in configuration of P17	*	*	*	*	*	*		
882	Interior monitoring system		○	○	○	○	○	○		0,00
		Only for left hand drive				*				
		for certain countries only	*	*	*	*				
		included in configuration of P54	*	*	*	*				
885	Increased anti-theft protection		●	●	●	—	●	●		63,00
		for certain countries only	*	*	*		*	*		
889	KEYLESS-GO		○	○	○	S	S	S		0,00
		Only for left hand drive				*				
		included in configuration of P17	*	*	*	*	*	*		
890U	cavansite blue metallic		●	●	●	●	●	●		924,00
		Only for left hand drive				*				
		i.V.m. Code C19	—	—	—	—	○	—		0,00
		i.V.m. Code PYB	—	—	—	—	○	—		0,00
896U	brilliant blue metallic		●	●	●	●	●	●		924,00
		Only for left hand drive				*				
		i.V.m. Code PYB	—	—	—	—	○	—		0,00
898	Wireless charging for mobile phones in the rear		—	—	—	—	●	—		294,00
			○	○	○	○	—	○		0,00
		Available only as part of (P11)	*	*	*	*		*		
		Not in conjunction with 224	*	*	*	*		*		
		Only in conjunction with P08+P11	*	*	*	*		*		
		Only for left hand drive				*				
		only in conjunction with P11+447	*	*	*	*				
902	Seat heating Plus for driver and front passenger seats		○	○	○	○	○	○		0,00
		Not in conjunction with 873	*	*	*					
		Only for left hand drive				*				
		included in configuration of P69/399	*	*	*	*				
906	Armrest heating for driver and front passenger		○	○	○	○	○	○		0,00
		Available only as part of (P69)	*	*	*	*	*	*		
		Not in conjunction with 873	*	*	*					
		Only in conjunction with P69	*	*	*	*	*	*		
		Only for left hand drive				*				
907	Cushions in rear heated		○	○	○	○	○	○		0,00
		Available only as part of (P69)	*	*	*	*	*	*		
		Not in conjunction with 873	*	*	*					
		Only in conjunction with P69	*	*	*	*	*	*		
		Only for left hand drive				*				
913	Air conditioning preinstallation for hot countries		○	○	○	○	○	○		0,00
		standard equipment in certain countries	*	*	*	*	*	*		
926	Emission control system with EU4 technology		—	—	○	○	○	○		0,00
		for certain countries only			*	*				
927	EU6 emissions standard		○	○	○	○	○	○		0,00
		Only for left hand drive				*				
		for certain countries only	*	*	*	*				
93B	Integrated Starter Generator Generation 1		—	—	S	S	S	S		0,00
		Only for left hand drive				*				
945	Emission control system China		—	—	○	—	○	—		0,00
94B	Integrated Starter Generator Generation 2		—	—	○	—	—	—		0,00
951A	Nappa leather black		●	●	●	●	●	—		3.360,00
		Not in conjunction with 135A/873	*	*	*					
		Not in conjunction with 215A/55U/58U/U08	*	*	*	*				
		Not in conjunction with 65U/75U/79U/959A					*			
		Only in conjunction with 293	*	*	*	*	*			
		Only in conjunction with 902	*	*	*					
		Only in conjunction with U38					*			
		Only for left hand drive				*				
954A	designo Exclusive nappa leather mahogany brown / m		—	—	—	—	●	—		367,50
		Not in conjunction with 61U/71U/79U/959A					*			
		Only in conjunction with 293+U38					*			
959A	crystal white / silver grey pearl		—	—	—	—	●	—		14.175,00
		Not in conjunction with 61U/65U/71U/75U/951A/954A					*			
		Only in conjunction with 293+543+79U+U38+U61					*			
961	Petrol particulate filter		—	—	○	—	○	○		0,00
		standard equipment in certain countries			*		*	*		
968	COC document EU6 without registration certificate pa		○	○	○	○	○	○		0,00
		standard equipment in certain countries	*	*	*	*	*			
969	COC document EU6 with registration certificate part 2		○	○	○	○	○	○		0,00
		standard equipment in certain countries	*	*	*	*	*	*		
973	Designation as owner-driver rental vehicle		○	○	○	○	○	○		0,00
981	Omission of vehicle registration document		○	○	○	○	○	○		0,00
989	Identification label under windshield		○	○	○	○	○	○		0,00
		Only for left hand drive				*				
989U	emerald green metallic		●	●	●	●	●	●		924,00
		Only for left hand drive				*				

		i.V.m. Code C24	-	-	-	-	○	-	0,00
		i.V.m. Code PYB	-	-	-	-	○	-	0,00
992U	selenite grey metallic		●	●	●	●	●	●	924,00
		Only for left hand drive				*			
		i.V.m. Code PYB	-	-	-	-	○	-	0,00
996U	designo hyacinth red metallic		●	●	●	●	●	●	1.302,00
		Only for left hand drive				*			
		i.V.m. Code PYB	-	-	-	-	●	-	378,00
997	Exhibition vehicle		○	○	○	○	○	○	0,00
B01	EQ Boost starter-alternator		○	○	S	S	S	S	0,00
		Not in conjunction with 215	*	*					
		Only in conjunction with 481+490	*	*					
		Only for left hand drive				*			
		48V Technology	*	*					
B08	Fanfare horn Asia		○	○	○	○	○	○	0,00
		standard equipment in certain countries	*	*	*	*	*	*	
E07	Positioning and Tracking System		-	●	●	●	●	●	336,00
		for certain countries only		*	*	*	*	*	
		only in conjunction with P54/P82		*	*	*	*	*	
H64	Metal-weave trim		●	●	●	●	-	●	199,50
		Not in conjunction with 735/H18/H22/H31/H34/H35/H46/H86	*	*	*	*		*	
		Not in conjunction with L3D	*	*	*	*			
		Not in conjunction with L6H						*	
		Only for left hand drive				*			
		only in conjunction with 876	*	*	*	*			
		i.V.m. Code P22	○	○	○	○	-	-	0,00
K32	Active Lane Change Assist		○	○	○	○	○	○	0,00
		Not in conjunction with 234/239/243/258/504	*	*	*	*		*	
		Only in conjunction with 266	*	*	*	*		*	
		Only for left hand drive				*			
		for certain countries only	*	*	*	*		*	
		included in configuration of P20/23P	*	*	*	*	*	*	
K33	Extended automatic Re-start in traffic jams		○	○	○	○	○	○	0,00
		Not in conjunction with 234/239/243/258/504	*	*	*	*		*	
		Only in conjunction with 233+266+273+513+546+K32+K34	*	*	*	*		*	
		Only for left hand drive				*			
		for certain countries only	*	*	*	*		*	
		included in configuration of P20/23P	*	*	*	*	*	*	
K34	Route-based speed adaptation		○	○	○	○	○	○	0,00
		Not in conjunction with 234/239/243/258/504	*	*	*	*		*	
		Only in conjunction with 233+266+273+513+546+K32	*	*	*	*		*	
		Only in conjunction with K33				*		*	
		Only for left hand drive				*			
		for certain countries only	*	*	*	*		*	
		included in configuration of P20/23P	*	*	*	*	*	*	
L	Left-hand drive		○	○	○	○	○	○	0,00
P53	Fine particle sensor		-	-	●	●	●	●	157,50
		standard equipment in certain countries			*	*	*	*	
PYB	SE Package		-	-	-	-	●	-	0,00
PYB	SE Package		-	-	-	-	-	●	0,00
PYB	SE Package		●	●	●	-	-	-	0,00
PYB	SE Package		-	-	-	●	-	-	0,00
PYH	AMG Line		●	●	●	-	-	-	3.760,00
			-	-	-	●	-	-	3.410,00
PYM	Advantage Package		●	●	●	-	-	-	1.573,00
PYN	Premium Package		●	●	●	-	-	-	4.804,00
			-	-	-	●	-	-	3.324,00
			-	-	-	-	-	●	2.644,00
PVO	Premium Plus package		●	●	●	-	-	-	8.591,00
			-	-	-	●	-	-	5.554,00
			-	-	-	-	-	●	4.376,00
PYQ	Executive Rear Package		●	●	●	-	-	-	4.225,00
			-	-	-	●	-	●	3.919,00
R	Right-hand drive		●	●	●	●	●	●	1.811,25
R01	Summer tyres		○	○	○	○	○	○	0,00
		Not in conjunction with R02	*	*					
		Only for left hand drive				*			
		for certain countries only	*	*	*	*			
R06	Noise reduced tyre with foam absorber		○	○	○	○	S	-	0,00
		Not in conjunction with 36R/65R	*	*	*				
		Not in conjunction with R02	*	*					
		Not in conjunction with R66	*	*	*	*			
		Only for left hand drive				*			
		only in conjunction with PAF+R01+(94R/95R/R33/R76/RPA/RPB/RPO/RWF/RWH)	*	*	*	*			
U01	Rear belt status indication in the instrument display		○	○	○	○	○	○	0,00

		Only for left hand drive					*				
		for certain countries only	*	*	*	*	*			*	
		standard equipment in certain countries	*	*	*	*	*			*	
U08	Upper part of dashboard in ARTICO man-made leather		S	S	S	S	-	-			0,00
		Not in conjunction with 951A/P22/U09/U38	*	*	*	*					
		Only for left hand drive				*					
U22	4-way lumbar support		S	S	S	S	S	S			0,00
		Not in conjunction with 23U/399/436/PBR	*	*	*						
U79	BlueTEC diesel emission control system including AdBlue		S	S	-	-	-	-			0,00
U80	115 V socket		-	-	●	●	-	●			115,50
			-	-	-	-	○	-			0,00
		for certain countries only				*	*	*	*		
		standard equipment in certain countries				*	*	*	*		
B12	Tyre-change toolkit		○	○	○	○	○	○			0,00
		Not in conjunction with 811/B51	*	*	*	*				*	
		Not in conjunction with B07								*	
		Not in conjunction with B16				*					
		Not in conjunction with U68	*	*	*	*					
		Only in conjunction with 669+810								*	
		Only for left hand drive					*				
682	Fire extinguisher		●	●	●	●	●	●			0,00
682		Only for left hand drive					*				
71B	Safety vests for driver and passengers		●	●	●	●	●	●			36,75
		Not in conjunction with 70B	*	*	*	*	*	*		*	
		Only for left hand drive					*				
293	Sidebags in rear		●	●	●	●	-	●			357,00
			-	-	-	-	S	-			0,00
		Only for left hand drive					*				
		standard equipment in certain countries	*	*	*	*				*	
		i.V.m. Code PYQ	○	○	○	○	-	○			0,00
294	Kneebag		○	○	○	○	○	○			0,00
		Only for left hand drive					*				
256	Active Brake Assist		●	●	●	●	-	●			0,00
256		Not in conjunction with 233/239/23P/23U/266/292/546/K32/K33/K34/P20	*	*	*	*	*	*		*	
256		Only in conjunction with 243	*	*	*	*	*	*		*	
256		Only for left hand drive					*				
292	PRE-SAFE® impulse side		○	○	○	○	○	○			0,00
		Not in conjunction with 111A/134A/135A	*	*	*						
		Not in conjunction with 234/239/243/258/504	*	*	*	*				*	
		Not in conjunction with 23P	*	*	*	*	*	*		*	
		Only in conjunction with 23U					*	*		*	
		Only in conjunction with 266+273+513+546+K32+K34	*	*	*	*	*	*		*	
		Only in conjunction with K33				*		*		*	
		Only in conjunction with P20	*	*	*	*	*	*		*	
		Only for left hand drive					*				
23U	Active Stop-and-Go Assist		○	○	○	○	○	○			0,00
		Not in conjunction with 111A/134A/135A/U22	*	*	*						
		Not in conjunction with 234/239/243/258/504	*	*	*	*				*	
		Not in conjunction with 23P	*	*	*	*	*	*		*	
		Only in conjunction with 266+273+513+546+K32+K33+K34	*	*	*	*	*	*		*	
		Only in conjunction with 292+P20	*	*	*	*	*	*		*	
		Only for left hand drive					*				
		for certain countries only	*	*	*	*					
		included in configuration of P20	*	*	*	*					
		only in conjunction with 233 292	*	*	*	*					
234	Blind Spot Assist		●	●	●	●	-	●			472,50
			-	-	-	-	○	-			0,00
		Not in conjunction with 233/23P/23U/266/292/546/K32/K33/K34/P20	*	*	*	*	*	*		*	
		Only in conjunction with 243+273	*	*	*	*	*	*		*	
		Only for left hand drive					*				
		i.V.m. Code 22P	○	○	○	○	-	○			0,00
		i.V.m. Code PYB	-	-	-	-	-	○			0,00
		i.V.m. Code PYM	○	○	○	○	-	-			0,00
239	Active Distance Assist DISTRONIC		●	●	●	●	-	●			945,00
239	Active Distance Assist DISTRONIC		-	-	-	-	○	-			0,00
239		Not in conjunction with 233/23P/23U/258/266/292/546/K32/K33/K34/P20	*	*	*	*	*	*		*	
239		Only in conjunction with 243	*	*	*	*	*	*		*	
239		Only for left hand drive					*				
23P	Driving Assistance package		●	●	●	●	-	●			2.026,50
			-	-	-	-	S	-			0,00
		Includes codes 233	*	*	*	*	*	*		*	
		Not in conjunction with 234/239/243/258/504	*	*	*	*	*	*		*	
		Not in conjunction with 23U/292/P20	*	*	*	*	*	*		*	
		Only in conjunction with 266+273+513+546+K32+K34	*	*	*	*	*	*		*	
		Only in conjunction with K33				*		*		*	

		Only for left hand drive					*			
		standard equipment for certain countries								
		i.V.m. Code PYM	●	●	●	●	-	-		1.396,50
		i.V.m. Code PYN	○	○	○	○	-	○		0,00
243	Active Lane Keeping Assist		●	●	●	●	-	●		0,00
243	Active Lane Keeping Assist		-	-	-	-	○	-		0,00
243		Not in conjunction with 233/23P/23U/266/292/546/K32/K33/K34/P20	*	*	*	*		*		
243		Only for left hand drive				*				
243		i.V.m. Code 22P	○	○	○	○	-	○		0,00
475	Tyre pressure monitoring system		●	●	●	●	●	●		320,25
		Only for left hand drive				*				
		i.V.m. S-Code 6P5	○	○	○	○	○	○		0,00
504	Speed Limit Assist		○	○	○	○	○	○		0,00
		Not in conjunction with 233/23P/23U/266/292/513/546/K32/K33/K34/P20	*	*	*	*		*		
		Only in conjunction with 243	*	*	*	*		*		
		Only for left hand drive				*				
513	Traffic Sign Assist		●	●	●	●	●	●		309,75
			-	-	-	-	-	-		0,00
		Not in conjunction with 504	*	*	*	*		*		
		Only for left hand drive				*				
		for certain countries only	*	*	*	*				
		standard equipment in certain countries								
		i.V.m. S-Code 51B	●	●	●	●	●	●		157,50
		i.V.m. Code 23P	○	○	○	○	○	○		0,00
		i.V.m. Code 546	○	○	○	○	○	○		0,00
		i.V.m. Code P20	○	○	○	○	○	○		0,00
		i.V.m. Code PYB	○	○	○	○	○	○		0,00
P20	Driving Assistance package Plus		●	●	●	●	-	●		2.551,50
			-	-	-	-	●	-		525,00
		Includes codes 233	*	*	*	*	*	*		
		Not in conjunction with 234/239/243/258/504	*	*	*	*		*		
		Not in conjunction with 23P	*	*	*	*	*	*		
		Only in conjunction with 23U+292				*	*	*		
		Only in conjunction with 266+273+513+546+K32+K34	*	*	*	*	*	*		
		Only in conjunction with K33				*		*		
		Only for left hand drive				*				
		i.V.m. Code PYB	-	-	-	-	○	-		0,00
		i.V.m. Code PYO	○	○	○	○	-	○		0,00
218	Reversing camera		S	S	S	S	-	S		0,00
		Available only as part of (P44)	*	*	*					
		Not in conjunction with 553/P47	*	*	*					
		Only in conjunction with P44	*	*	*					
553	Trailer Manoeuvring Assist		●	●	●	●	●	●		367,50
		Not in conjunction with P44	*	*	*					
		Only in conjunction with 550+557	*	*	*	*	*	*		
		Only in conjunction with P47	*	*	*					
		Only for left hand drive				*				
		for certain countries only	*	*	*	*				
P44	Parking package		●	●	●	-	-	-		0,00
P44	Parking package		-	-	-	○	-	○		0,00
P44		Includes codes 218+235	*	*	*					
P44		Not in conjunction with 553/P47	*	*	*					
P47	Parking Package with 360-degree camera		●	●	●	-	-	-		1.144,50
P47	Parking Package with 360-degree camera		-	-	-	●	-	●		0,00
			-	-	-	-	S	-		0,00
		Includes codes 235+501	*	*	*	*	*	*		
		Not in conjunction with P44	*	*	*					
		Only for left hand drive				*				
		standard equipment in certain countries	*	*	*	*		*		
		i.V.m. Code PYB	-	-	-	-	-	○		0,00
		i.V.m. Code PYM/PYN/PYO	○	○	○	○	-	-		0,00
915	Fuel tank with a capacity of 90 litres		S	S	S	S	S	S		0,00
		Only for left hand drive				*				
B16	Two-pipe exhaust system		-	-	○	S	S	S		0,00
		Not in conjunction with 669/690/811/B12				*				
		Only in conjunction with U68				*				
		Only for left hand drive				*				
		included in configuration of U68				*				
U28	Braking system with larger brake disks on the front ax		●	●	●	●	-	-		262,50
		Not in conjunction with 36R/65R	*	*	*					
		Not in conjunction with 690	*	*	*	*				
		Not in conjunction with R02	*	*						
		Only for left hand drive				*				
		i.V.m. Code PYH	○	○	○	○	-	-		0,00
U68	Sporty engine sound		●	●	●	●	-	-		367,50

		Not in conjunction with 669/690/811/812	*	*	*	*			
		Only in conjunction with B16			*				
		Only for left hand drive				*			
489	AMG RIDE CONTROL+		S	S	-	S	S	S	0,00
		Only for left hand drive				*			
		AIRMATIC package	*	*		*	*		
490	E-ACTIVE BODY CONTROL		●	●	●	●	●	-	6.825,00
		Not in conjunction with 215	*	*	*	*	*		
		Only in conjunction with 481	*	*	*	*	*		
		Only in conjunction with B01	*	*					
		Only for left hand drive				*			
		for certain countries only	*	*	*	*	*		
		includes code 481	*	*	*	*	*		
971	Diesel particulate filter		○	○	-	-	-	-	0,00
430	Off-Road Engineering package		●	●	●	●	-	-	1.995,00
		Includes codes 481	*	*	*	*			
		Only for left hand drive				*			
481	Underguard		●	●	●	●	●	-	136,50
		Only for left hand drive				*			
		i.V.m. Code 430/490	○	○	○	○	○	-	0,00
421	9G-TRONIC		S	S	S	S	S	-	0,00
		Only for left hand drive				*			